

Oracle® VM Server for SPARC 3.3 Release Notes

Copyright © 2007, 2015, Oracle and/or its affiliates. All rights reserved.

This software and related documentation are provided under a license agreement containing restrictions on use and disclosure and are protected by intellectual property laws. Except as expressly permitted in your license agreement or allowed by law, you may not use, copy, reproduce, translate, broadcast, modify, license, transmit, distribute, exhibit, perform, publish, or display any part, in any form, or by any means. Reverse engineering, disassembly, or decompilation of this software, unless required by law for interoperability, is prohibited.

The information contained herein is subject to change without notice and is not warranted to be error-free. If you find any errors, please report them to us in writing.

If this is software or related documentation that is delivered to the U.S. Government or anyone licensing it on behalf of the U.S. Government, then the following notice is applicable:

U.S. GOVERNMENT END USERS. Oracle programs, including any operating system, integrated software, any programs installed on the hardware, and/or documentation, delivered to U.S. Government end users are "commercial computer software" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, use, duplication, disclosure, modification, and adaptation of the programs, including any operating system, integrated software, any programs installed on the hardware, and/or documentation, shall be subject to license terms and license restrictions applicable to the programs. No other rights are granted to the U.S. Government.

This software or hardware is developed for general use in a variety of information management applications. It is not developed or intended for use in any inherently dangerous applications, including applications that may create a risk of personal injury. If you use this software or hardware in dangerous applications, then you shall be responsible to take all appropriate fail-safe, backup, redundancy, and other measures to ensure its safe use. Oracle Corporation and its affiliates disclaim any liability for any damages caused by use of this software or hardware in dangerous applications.

Oracle and Java are registered trademarks of Oracle and/or its affiliates. Other names may be trademarks of their respective owners.

Intel and Intel Xeon are trademarks or registered trademarks of Intel Corporation. All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. AMD, Opteron, the AMD logo, and the AMD Opteron logo are trademarks or registered trademarks of Advanced Micro Devices. UNIX is a registered trademark of The Open Group.

This software or hardware and documentation may provide access to or information about content, products, and services from third parties. Oracle Corporation and its affiliates are not responsible for and expressly disclaim all warranties of any kind with respect to third-party content, products, and services unless otherwise set forth in an applicable agreement between you and Oracle. Oracle Corporation and its affiliates will not be responsible for any loss, costs, or damages incurred due to your access to or use of third-party content, products, or services, except as set forth in an applicable agreement between you and Oracle.

Documentation Accessibility

For information about Oracle's commitment to accessibility, visit the Oracle Accessibility Program website at <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=docacc>.

Access to Oracle Support

Oracle customers that have purchased support have access to electronic support through My Oracle Support. For information, visit <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=info> or visit <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=trs> if you are hearing impaired.

Ce logiciel et la documentation qui l'accompagne sont protégés par les lois sur la propriété intellectuelle. Ils sont concédés sous licence et soumis à des restrictions d'utilisation et de divulgation. Sauf stipulation expresse de votre contrat de licence ou de la loi, vous ne pouvez pas copier, reproduire, traduire, diffuser, modifier, breveter, transmettre, distribuer, exposer, exécuter, publier ou afficher le logiciel, même partiellement, sous quelque forme et par quelque procédé que ce soit. Par ailleurs, il est interdit de procéder à toute ingénierie inverse du logiciel, de le désassembler ou de le décompiler, excepté à des fins d'interopérabilité avec des logiciels tiers ou tel que prescrit par la loi.

Les informations fournies dans ce document sont susceptibles de modification sans préavis. Par ailleurs, Oracle Corporation ne garantit pas qu'elles soient exemptes d'erreurs et vous invite, le cas échéant, à lui en faire part par écrit.

Si ce logiciel, ou la documentation qui l'accompagne, est concédé sous licence au Gouvernement des Etats-Unis, ou à toute entité qui délivre la licence de ce logiciel ou l'utilise pour le compte du Gouvernement des Etats-Unis, la notice suivante s'applique:

U.S. GOVERNMENT END USERS. Oracle programs, including any operating system, integrated software, any programs installed on the hardware, and/or documentation, delivered to U.S. Government end users are "commercial computer software" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, use, duplication, disclosure, modification, and adaptation of the programs, including any operating system, integrated software, any programs installed on the hardware, and/or documentation, shall be subject to license terms and license restrictions applicable to the programs. No other rights are granted to the U.S. Government.

Ce logiciel ou matériel a été développé pour un usage général dans le cadre d'applications de gestion des informations. Ce logiciel ou matériel n'est pas conçu ni n'est destiné à être utilisé dans des applications à risque, notamment dans des applications pouvant causer des dommages corporels. Si vous utilisez ce logiciel ou matériel dans le cadre d'applications dangereuses, il est de votre responsabilité de prendre toutes les mesures de secours, de sauvegarde, de redondance et autres mesures nécessaires à son utilisation dans des conditions optimales de sécurité. Oracle Corporation et ses affiliés déclinent toute responsabilité quant aux dommages causés par l'utilisation de ce logiciel ou matériel pour ce type d'applications.

Oracle et Java sont des marques déposées d'Oracle Corporation et/ou de ses affiliés. Tout autre nom mentionné peut correspondre à des marques appartenant à d'autres propriétaires qu'Oracle.

Intel et Intel Xeon sont des marques ou des marques déposées d'Intel Corporation. Toutes les marques SPARC sont utilisées sous licence et sont des marques ou des marques déposées de SPARC International, Inc. AMD, Opteron, le logo AMD et le logo AMD Opteron sont des marques ou des marques déposées d'Advanced Micro Devices. UNIX est une marque déposée d'The Open Group.

Ce logiciel ou matériel et la documentation qui l'accompagne peuvent fournir des informations ou des liens donnant accès à des contenus, des produits et des services émanant de tiers. Oracle Corporation et ses affiliés déclinent toute responsabilité ou garantie expresse quant aux contenus, produits ou services émanant de tiers, sauf mention contraire stipulée dans un contrat entre vous et Oracle. En aucun cas, Oracle Corporation et ses affiliés ne sauraient être tenus pour responsables des pertes subies, des coûts occasionnés ou des dommages causés par l'accès à des contenus, produits ou services tiers, ou à leur utilisation, sauf mention contraire stipulée dans un contrat entre vous et Oracle.

Accessibilité de la documentation

Pour plus d'informations sur l'engagement d'Oracle pour l'accessibilité à la documentation, visitez le site Web Oracle Accessibility Program, à l'adresse <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=docacc>.

Accès au support électronique

Les clients Oracle qui ont souscrit un contrat de support ont accès au support électronique via My Oracle Support. Pour plus d'informations, visitez le site <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=info> ou le site <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=trs> si vous êtes malentendant.

Contents

Preface	7
1 Oracle VM Server for SPARC 3.3 Release Notes	9
What's New in This Release	10
Features That Depend on System Firmware, the Oracle Solaris OS, Or Both	12
Oracle VM Server for SPARC 3.3 System Requirements	12
Deprecated and Removed Oracle VM Server for SPARC Features	13
Known Issues	14
Installation Issues	14
General Issues	14
Migration Issues	21
SR-IOV Issues	28
Bugs Affecting the Oracle VM Server for SPARC Software	31
Resolved Issues	60

Preface

- **Overview** – Includes information about this release of the Oracle VM Server for SPARC software, such as changes for this release, supported platforms, a matrix of required software and patches, and bugs affecting this software.
- **Audience** – System administrators who manage virtualization on SPARC servers
- **Required knowledge** – System administrators on these servers must have a working knowledge of UNIX systems and the Oracle Solaris operating system (Oracle Solaris OS)

Product Documentation Library

Documentation and resources for this product and related products are available at <http://www.oracle.com/technetwork/documentation/vm-sparc-194287.html>.

Feedback

Provide feedback about this documentation at <http://www.oracle.com/goto/docfeedback>.

◆ ◆ ◆ 1
CHAPTER 1

Oracle VM Server for SPARC 3.3 Release Notes

These release notes include information about issues that you might encounter if you are running the fully qualified versions of the Oracle Solaris OS, system firmware for a supported platform, and the Oracle VM Server for SPARC 3.3 software. If you are not running these qualified versions, you might encounter a larger set of issues.

Note – Ensure that you install and run the Oracle VM Server for SPARC 3.3 software with the fully qualified system firmware versions on the supported hardware platforms. All domains on the system must run the latest Support Repository Update (SRU) of an Oracle Solaris 11 OS or the latest patch for the Oracle Solaris 10 1/13 OS.

For issues that you should address before you install the Oracle VM Server for SPARC 3.3 software, see [“Installation Issues” on page 14](#).

These release notes might include some known issues that exist with older versions of the software.

For information about the supported hardware and fully qualified software and system firmware, see [Chapter 1, “Oracle VM Server for SPARC 3.3 System Requirements,” in *Oracle VM Server for SPARC 3.3 Installation Guide*](#).

Note – Oracle VM Server for SPARC features are added and maintained on the supported hardware platforms listed in “[Supported Platforms](#)” in *Oracle VM Server for SPARC 3.3 Installation Guide*. However, new features will not be added and existing features will not be maintained on hardware platforms that have been removed from the list.

As a rule, new Oracle VM Server for SPARC features and functionality are made available for all price-listed, supported T-Series and M-Series servers from Oracle and Fujitsu M10 servers at the time that the Oracle VM Server for SPARC software is released and not for SPARC based systems that have already passed their last-order date.

Note – The features that are described in this book can be used with all of the supported system software and hardware platforms that are listed in *Oracle VM Server for SPARC 3.3 Installation Guide*. However, some features are only available on a subset of the supported system software and hardware platforms. For information about these exceptions, see “[What's New in This Release](#)” on page 10 and [What's New in Oracle VM Server for SPARC Software](#) (<http://www.oracle.com/technetwork/server-storage/vm/documentation/sparc-whatsnew-330281.html>).

- “[What's New in This Release](#)” on page 10
- “[Features That Depend on System Firmware, the Oracle Solaris OS, Or Both](#)” on page 12
- “[Oracle VM Server for SPARC 3.3 System Requirements](#)” on page 12
- “[Deprecated and Removed Oracle VM Server for SPARC Features](#)” on page 13
- “[Known Issues](#)” on page 14

What's New in This Release

For information about the features introduced in all versions of the Oracle VM Server for SPARC (Logical Domains) software, see [What's New in Oracle VM Server for SPARC Software](#) (<http://www.oracle.com/technetwork/server-storage/vm/documentation/sparc-whatsnew-330281.html>).

The major changes for the Oracle VM Server for SPARC 3.3 software are as follows. Note that each feature is available on all supported platforms except UltraSPARC T2, UltraSPARC T2 Plus, and SPARC T3 unless otherwise stated. For the list of supported platforms, see “[Supported Platforms](#)” in *Oracle VM Server for SPARC 3.3 Installation Guide*.

- Support the virtual SCSI host bus adapter (vHBA) feature, which enables you to virtualize any type of SCSI device (such as disk, tape, CD, or DVD). The virtualized SCSI device is accessible from a guest domain.

The vHBA feature is compatible with other I/O interfaces such as MPxIO multipathing, which enables a virtual LUN to have the same behavior as a physical LUN. vHBA also enables you to easily configure virtual SANs, which can contain an unbounded number of

SCSI devices. See “Introduction to Virtual SCSI Host Bus Adapters” in *Oracle VM Server for SPARC 3.3 Administration Guide* and the `ldm(1M)` man page.

This feature is supported on UltraSPARC T2, UltraSPARC T2 Plus, and SPARC T3 systems as well.

- Enable recovery mode by default. See “Recovering Domains After Detecting Faulty or Missing Resources” in *Oracle VM Server for SPARC 3.3 Administration Guide*.

This feature is not supported on SPARC T4 systems.

- Add Oracle VM Templates commands to create, deploy, and configure Oracle VM templates for SPARC systems. See Chapter 18, “Using Oracle VM Server for SPARC Templates,” in *Oracle VM Server for SPARC 3.3 Administration Guide*.

This feature is supported on UltraSPARC T2, UltraSPARC T2 Plus, and SPARC T3 systems as well.

- Support whole-core dynamic resource management (DRM). See “Using Dynamic Resource Management” in *Oracle VM Server for SPARC 3.3 Administration Guide*.
- Add support for CPU socket constraints. See *Fujitsu M10/SPARC M10 Systems System Operation and Administration Guide*.

This feature is supported only on Fujitsu M10 servers.

- Enhance the live migration feature to enable memory block splitting. Memory block splitting eliminates the requirement to have sufficient free contiguous memory regions on the target machine for each memory block that is assigned to the guest domain. The migration can split up memory blocks in the guest domain to fit into available free regions on the target machine.

This feature requires that you run the Oracle Solaris 11.3 OS on the guest domain being migrated.

This feature is supported on UltraSPARC T2, UltraSPARC T2 Plus, and SPARC T3 systems as well.

- Enable autoreplacement of faulty CPUs with bound processes and faulty CPUs in single-core domains. See *Fujitsu M10/SPARC M10 Systems System Operation and Administration Guide*.

This feature is supported only on Fujitsu M10 servers.

- Dynamically update the `net - dev` property value by using the `ldm set - vsw` command.
- Expand cross-CPU migration to include the SPARC T7 series servers and SPARC M7 series servers. See “Domain Migration Requirements for CPUs” in *Oracle VM Server for SPARC 3.3 Administration Guide* and “Cross-CPU Restrictions for Migration” in *Oracle VM Server for SPARC 3.3 Administration Guide*.

- Provide support for Ethernet over USB to enable the `ldmd` daemon to communicate with the SP and provide support for an `ldmd` connection check. See “How to Verify the ILOM Interconnect Configuration” in *Oracle VM Server for SPARC 3.3 Administration Guide*.

This feature is supported only on SPARC T7 series servers and SPARC M7 series servers.

- Bug fixes.

Features That Depend on System Firmware, the Oracle Solaris OS, Or Both

Some of the Oracle VM Server for SPARC 3.3 features are available only when the fully qualified system firmware and Oracle Solaris OS are installed. Note that the control domain must already be running the fully qualified Oracle Solaris OS.

For information about the supported hardware, system firmware, and Oracle Solaris OS, see [Chapter 1, “Oracle VM Server for SPARC 3.3 System Requirements,”](#) in *Oracle VM Server for SPARC 3.3 Installation Guide*. For Fujitsu M10 servers, see the latest *Fujitsu M10/SPARC M10 Systems Product Notes*.

For Oracle VM Server for SPARC 3.3, all new features are available even if the system does not run the fully qualified system firmware.

If a guest domain, an I/O domain, or a root domain does not run the fully qualified Oracle Solaris OS version, the following Oracle VM Server for SPARC 3.3 features are not available:

- Virtual SCSI HBA, which requires the Oracle Solaris 11.3 OS
- Memory block splitting, which requires the Oracle Solaris 11.3 OS on the guest domain to be migrated

Oracle VM Server for SPARC 3.3 System Requirements

You can find information about the recommended and minimum software component versions to use with the Oracle VM Server for SPARC 3.3 release in [Chapter 1, “Oracle VM Server for SPARC 3.3 System Requirements,”](#) in *Oracle VM Server for SPARC 3.3 Installation Guide*.

Deprecated and Removed Oracle VM Server for SPARC Features

The following Oracle VM Server for SPARC features have been removed from this release of the software:

- The Oracle VM Server for SPARC 3.3 produce no longer supports the running of the Oracle Solaris 10 OS in control domains. You can continue to run the Oracle Solaris 10 OS in guest domains, root domains, and I/O domains when using future releases. Oracle Solaris 10 patches will continue to be provided for Oracle VM Server for SPARC based on the documented support policy.
- Setting the `threading` property to manage single-thread workloads on SPARC T4 platforms has been deprecated previously. By default, domains are created for maximum throughput, and the Oracle Solaris OS automatically uses the critical thread API to optimize for single-thread workloads. This feature has been removed from the Oracle VM Server for SPARC 3.3 release.

Before you install or upgrade to the Oracle VM Server for SPARC 3.3 software, ensure that all domains have the `threading` property set to `max-throughput`.

- Using the `-c` option of the `add-vcpu`, `set-vcpu`, and `rm-vcpu` subcommands to manage hard partitioning has been deprecated previously. Instead, use the `add-core`, `set-core`, or `rm-core` subcommand to assign whole cores. Also, use the `add-domain` or `set-domain` subcommand to specify the CPU cap (`max-cores`). This feature has been removed from the Oracle VM Server for SPARC 3.3 release.
- This Oracle VM Server for SPARC release no longer includes the `ldmconfig` utility as it runs only on Oracle Solaris 10 control domains. This utility will no longer be updated to address bug fix or enhancement requests.
- The network interface functionality of an Oracle VM Server for SPARC `vsw` driver was deprecated in Oracle Solaris 11.1. The Oracle VM Server for SPARC `vsw` driver continues to provide virtual network switching functionality for guest domains. See [“Oracle Solaris 11 Networking Overview”](#) in *Oracle VM Server for SPARC 3.3 Administration Guide*.
- The SR-IOV feature is no longer supported on a control domain that runs the Oracle Solaris 10 OS.

The following Oracle VM Server for SPARC features are deprecated in this release of the software and might be removed from the product in a future release:

- Using the Hybrid I/O feature is deprecated in favor of using the single-root I/O virtualization (SR-IOV) feature.
- The Netra Data Plane software suite, which includes the `vdpc` and `vdpc`s virtual devices, is no longer supported by Oracle VM Server for SPARC.

- The `ldmp2v` utility will no longer be updated to address bug fix or enhancement requests. This utility will no longer be supported, but will continue to be included and documented as part of the Oracle VM Server for SPARC software.
- Using the `ldm migrate-domain -p filename` command to initiate a non-interactive migration operation is deprecated. Instead, use SSL certificate-based authentication. See “Configuring SSL Certificates for Migration” in *Oracle VM Server for SPARC 3.3 Administration Guide*.
- The Logical Domains Manager auditing implementation is deprecated pending replacement and is turned off by default.

Known Issues

This section contains general issues and specific bugs concerning the Oracle VM Server for SPARC 3.3 software.

Installation Issues

threading Property Removal Requires That You Remove the `threading=max-ipc` Setting

The `threading` property has been removed from the Oracle VM Server for SPARC 3.3 release. Therefore, before you update your system to use the Oracle VM Server for SPARC 3.3 software, remove the `threading=max-ipc` property setting from all domains:

```
primary# ldm set-dom threading=max-throughput domain-name
```

If you do not remove this property setting, only one virtual CPU per core remains after the `ldmd` daemon is restarted and the whole-core constraint is lost.

Use the `ldm set-core` command to restore the whole-core constraint.

```
primary# ldm set-core n domain-name
```

General Issues

This section describes general known issues about this release of the Oracle VM Server for SPARC software that are broader than a specific bug number. Workarounds are provided where available.

After Canceling a Migration, ldm Commands That Are Run on the Target System Are Temporarily Unresponsive

If you cancel a live migration, the memory contents of the domain instance that is created on the target machine must be “scrubbed” by the hypervisor. This scrubbing process is performed for security reasons and must be complete before the memory can be returned to the pool of free memory. While this scrubbing is in progress, ldm commands become unresponsive. As a result, the Logical Domains Manager appears to be hung.

Recovery: You must wait for this scrubbing request to finish before you attempt to run other ldm commands. This process might take a long time. For example, a guest domain that has 500 Gbytes of memory might complete this process in up to 7 minutes on a SPARC T4 server or up to 25 minutes on a SPARC T3 server.

SPARC M5-32 and SPARC M6-32: Issue With Disks That Are Accessible Through Multiple Direct I/O Paths

When using the ldm add -vcpu command to assign CPUs to a domain, the Oracle Solaris OS might panic with the following message:

```
panic[cpu16]/thread=c4012102c860: mpo_cpu_add: Cannot read MD
```

This panic occurs if the following conditions exist:

- Additional DCUs have been assigned to a host
- The host is started by using a previously saved SP configuration that does not contain all the hardware that is assigned to the host

The target domain of the ldm add -vcpu operation is the domain that panics. The domain recovers with the additional CPUs when it reboots.

Workaround: Do not use configurations that are generated with fewer hardware resources than are assigned to the host.

To avoid the problem, do not add CPUs as described in the problem description. Or, perform the following steps:

1. Generate a new SP configuration after the DCUs have been added.
For example, the following command creates a configuration called new-config-more-dcus:


```
primary# ldm add-config new-config-more-dcus
```
2. Shutdown the domain.
3. Stop the host.
-> stop /HOST
4. Start the host.

```
-> start /HOST
```

Destroying All Virtual Functions and Returning the Slots to the Root Domain Does Not Restore the Root Complex Resources

The resources on the root complex are not restored after you destroy all the virtual functions and return the slots to the root domain.

Recovery: Return all the virtual I/O resources that are associated with the root complex to its root domain.

First, put the control domain in delayed reconfiguration..

```
primary# ldm start-reconf primary
```

Return all child PCIe slots to the root domain that owns the pci_0 bus. Then, remove all of the child virtual functions on the pci_0 bus and destroy them.

Finally, set iov=off for the pci_0 bus and reboot the root domain.

```
primary# ldm set-io iov=off pci_0
primary# shutdown -y -g 10
```

Workaround: Set the iov option to off for the specific PCIe bus.

```
primary# ldm start-reconf primary
primary# ldm set-io iov=off pci_0
```

init-system Does Not Restore Named Core Constraints for Guest Domains From Saved XML Files

The ldm init-system command fails to restore the named CPU core constraints for guest domains from a saved XML file.

Workaround: Perform the following steps:

1. Create an XML file for the primary domain.

```
# ldm ls-constraints -x primary > primary.xml
```

2. Create an XML file for the guest domain or domains.

```
# ldm ls-constraints -x domain-name[,domain-name][,...] > guest.xml
```

3. Power cycle the system and boot a factory default configuration.
4. Apply the XML configuration to the primary domain.

```
# ldm init-system -r -i primary.xml
```

5. Apply the XML configuration to the guest domain or domains.

```
# ldm init-system -f -i guest.xml
```

Removing a Large Number of CPUs From a Domain Might Fail

You might see the following error message when you attempt to remove a large number of CPUs from a guest domain:

```
Request to remove cpu(s) sent, but no valid response received
VCPU(s) will remain allocated to the domain, but might
not be available to the guest OS
Resource modification failed
```

Workaround: Stop the guest domain before you remove more than 100 CPUs from the domain.

Newly Added NIU/XAUI Adapters Are Not Visible to the Host OS If Logical Domains Is Configured

When Logical Domains is configured on a system and you add another XAUI network card, the card is not visible after the machine has undergone a power cycle.

Recovery: To make the newly added XAUI visible in the control domain, perform the following steps:

1. Set and clear a dummy variable in the control domain.

The following commands use a dummy variable called `fix-xaui`:

```
# ldm set-var fix-xaui=yes primary
# ldm rm-var fix-xaui primary
```

2. Save the modified configuration to the SP, replacing the current configuration.

The following commands use a configuration name of `config1`:

```
# ldm rm-sponfig config1
# ldm add-sponfig config1
```

3. Perform a reconfiguration reboot of the control domain.

```
# reboot -- -r
```

At this time, you can configure the newly available network or networks for use by Logical Domains.

LSI SAS 2008 Cannot Be Added by Dynamic Bus or PCI-Box Hotplug Operations

If you attempt to remove a PCIe bus that hosts LSI SAS HBA devices, you cannot later add the devices by using dynamic bus or PCI-box hotplug operations.

In Certain Conditions, a Guest Domain's Solaris Volume Manager Configuration or Metadevices Can Be Lost

If a service domain is running a version of Oracle Solaris 10 OS prior to Oracle Solaris 10 1/13 OS and is exporting a physical disk slice as a virtual disk to a guest domain, then this virtual disk will appear in the guest domain with an inappropriate device ID. If that service domain is then upgraded to Oracle Solaris 10 1/13 OS, the physical disk slice exported as a virtual disk will appear in the guest domain with no device ID.

This removal of the device ID of the virtual disk can cause problems to applications attempting to reference the device ID of virtual disks. In particular, Solaris Volume Manager might be unable to find its configuration or to access its metadevices.

Workaround: After upgrading a service domain to Oracle Solaris 10 1/13 OS, if a guest domain is unable to find its Solaris Volume Manager configuration or its metadevices, perform the following procedure.

▼ How to Find a Guest Domain's Solaris Volume Manager Configuration or Metadevices

- 1 **Boot the guest domain.**
- 2 **Disable the `devid` feature of Solaris Volume Manager by adding the following lines to the `/kernel/drv/md.conf` file:**

```
md_devid_destroy=1;
md_keep_repl_state=1;
```
- 3 **Reboot the guest domain.**

After the domain has booted, the Solaris Volume Manager configuration and metadevices should be available.

- 4 **Check the Solaris Volume Manager configuration and ensure that it is correct.**
- 5 **Re-enable the Solaris Volume Manager `devid` feature by removing from the `/kernel/drv/md.conf` file the two lines that you added in Step 2.**
- 6 **Reboot the guest domain.**

During the reboot, you will see messages similar to this:

```
NOTICE: mddb: unable to get devid for 'vdc', 0x10
```

These messages are normal and do not report any problems.

Oracle Solaris Boot Disk Compatibility

Historically, the Oracle Solaris OS has been installed on a boot disk configured with an SMI VTOC disk label. Starting with the Oracle Solaris 11.1 OS, the OS is installed on a boot disk that is configured with an extensible firmware interface (EFI) GUID partition table (GPT) disk label by default. If the firmware does not support EFI, the disk is configured with an SMI VTOC disk label instead. This situation applies only to SPARC T4 servers that run at least system firmware version 8.4.0, to SPARC T5, SPARC M5, SPARC M6 servers that run at least system firmware version 9.1.0, and to Fujitsu M10 servers that run at least XCP version 2230.

The following servers cannot boot from a disk that has an EFI GPT disk label:

- UltraSPARC T2, UltraSPARC T2 Plus, and SPARC T3 servers no matter which system firmware version is used
- SPARC T4 servers that run system firmware versions prior to 8.4.0
- SPARC T5, SPARC M5, and SPARC M6 servers that run system firmware versions prior to 9.1.0
- Fujitsu M10 servers that run XCP versions prior to 2230

So, an Oracle Solaris 11.1 boot disk that is created on an up-to-date SPARC T4, SPARC T5, SPARC M5, SPARC M6, Fujitsu M10 server cannot be used on older servers or on servers that run older firmware.

This limitation restrains the ability to use either cold or live migration to move a domain from a recent server to an older server. This limitation also prevents you from using an EFI GPT boot disk image on an older server.

To determine whether an Oracle Solaris 11.1 boot disk is compatible with your server and its firmware, ensure that the Oracle Solaris 11.1 OS is installed on a disk that is configured with an SMI VTOC disk label.

To maintain backward compatibility with systems that run older firmware, use one of the following procedures. Otherwise, the boot disk uses the EFI GPT disk label by default. These procedures show how to ensure that the Oracle Solaris 11.1 OS is installed on a boot disk with an SMI VTOC disk label on a SPARC T4 server with at least system firmware version 8.4.0, on a SPARC T5, SPARC M5, or SPARC M6 server with at least system firmware version 9.1.0, and on a Fujitsu M10 server with at least XCP version 2230.

- **Solution 1:** Remove the `gpt` property so that the firmware does not report that it supports EFI.
 1. From the OpenBoot PROM prompt, disable automatic booting and reset the system to be installed.

```
ok setenv auto-boot? false
ok reset-all
```

After the system resets, it returns to the ok prompt.

- Change to the `/packages/disk-label` directory and remove the `gpt` property.

```
ok cd /packages/disk-label
ok " gpt" delete-property
```

- Begin the Oracle Solaris 11.1 OS installation.

For example, perform a network installation:

```
ok boot net - install
```

- Solution 2:** Use the `format -e` command to write an SMI VTOC label on the disk to be installed with the Oracle Solaris 11.1 OS.

- Write an SMI VTOC label on the disk.

For example, select the `label` option and specify the SMI label:

```
# format -e c1d0
format> label
[0] SMI Label
[1] EFI Label
Specify Label type[1]: 0
```

- Configure the disk with a slice 0 and slice 2 that cover the entire disk.

The disk should have no other partitions. For example:

```
format> partition
```

```
partition> print
Current partition table (unnamed):
Total disk cylinders available: 14087 + 2 (reserved cylinders)
```

Part	Tag	Flag	Cylinders	Size	Blocks
0	root	wm	0 - 14086	136.71GB	(14087/0/0) 286698624
1	unassigned	wu	0	0	(0/0/0) 0
2	backup	wu	0 - 14086	136.71GB	(14087/0/0) 286698624
3	unassigned	wm	0	0	(0/0/0) 0
4	unassigned	wm	0	0	(0/0/0) 0
5	unassigned	wm	0	0	(0/0/0) 0
6	unassigned	wm	0	0	(0/0/0) 0
7	unassigned	wm	0	0	(0/0/0) 0

- Re-write the SMI VTOC disk label.

```
partition> label
[0] SMI Label
[1] EFI Label
Specify Label type[0]: 0
Ready to label disk, continue? y
```

- Configure your Oracle Solaris Automatic Installer (AI) to install the Oracle Solaris OS on slice 0 of the boot disk.

Change the `<disk>` excerpt in the AI manifest as follows:

```
<target>
  <disk whole_disk="true">
    <disk_keyword key="boot_disk"/>
    <slice name="0" in_zpool="rpool"/>
  </disk>
```

```
[...]
</target>
```

5. Perform the installation of the Oracle Solaris 11.1 OS.

Sometimes a Block of Dynamically Added Memory Can Be Dynamically Removed Only as a Whole

Due to the way in which the Oracle Solaris OS handles the metadata for managing dynamically added memory, you might later be able to remove only the entire block of memory that was previously dynamically added rather than a proper subset of that memory.

This situation could occur if a domain with a small memory size is dynamically grown to a much larger size, as shown in the following example.

```
primary# ldm list ldom1
NAME STATE FLAGS   CONS VCPU MEMORY UTIL UPTIME
ldom1 active -n--   5000 2    2G    0.4% 23h

primary# ldm add-mem 16G ldom1

primary# ldm rm-mem 8G ldom1
Memory removal failed because all of the memory is in use.

primary# ldm rm-mem 16G ldom1

primary# ldm list ldom1
NAME STATE FLAGS   CONS VCPU MEMORY UTIL UPTIME
ldom1 active -n--   5000 2    2G    0.4% 23h
```

Workaround: Use the `ldm add-mem` command to sequentially add memory in smaller chunks rather than in chunks larger than you might want to remove in the future.

Recovery: Perform one of the following actions:

- Stop the domain, remove the memory, and then restart the domain.
- Reboot the domain, which causes the Oracle Solaris OS to reallocate its memory management metadata such that the previously added memory can now be removed dynamically in smaller chunks.

Migration Issues

Migration of a Domain Between SPARC T7 Series Servers With Fragmented Memory Might Cause `ldmd` to Crash

Bug ID 21554591: During a live migration, the `ldmd` service on the target machine might dump core then restart.

This problem might occur when the memory on the domain to be migrated is highly fragmented into multiple memory segments and the target machine's free memory layout is not compatible. The problem is more likely to occur if you use memory DR to remove memory from the domain prior to live migration.

The stack trace of the core dump is similar to the following:

```
restore_lpgg_mblk+0x398(17bbc88, 16c39c8, 80000000, 80000000, 0, 40000000)
rgrp_restore_lpgg+0x39c(0, 0, 1733948, 1711598, 0, 20000000)
mem_allocate_real+0x92c(0, 20000000, ffbff868, 13aec88, 80808080, 373cd8)
affinity_bind_resources+0x9f4(17bbc88, ffbff948, 13aec88, 3a10c000, 3a10c000, 1010101)
mem_bind_real+0x468(17bbc88, ffbff9d4, 13aec88, 3a10c000, 3a10c000, 1010101)
mem_bind_real_check+0xf4(17bbc88, 12ee338, 13aec88, 0, 376468, ff29fd80)
mig_tgt_bound_feasibility_check+0x168(164be08, ff000000, ff, 1, 0, 0)
i_tgt_do_feasibility_check+0x168(164be08, 0, 12390, 1, f960d244, ffffff)
sequence+0x4a4(0, ff000000, ff322a40, 1, f960d244, ffffff)
main+0xb54(5, ffbffc64, ffbffc7c, f960a900, 0, ff320200)
_start+0x108(0, 0, 0, 0, 0, 370b60)
```

When this problem occurs, the guest domain continues to run. If the `ldmd` services restarts successfully, no further recovery is needed.

If the `ldmd` service fails to restart and goes into maintenance mode due to Bug 21569507, you must perform a power cycle of the host or applicable physical domain before you can restart `ldmd`.

Workaround: Stop and unbind the guest domain and then perform a cold migration. Do not use memory DR to remove memory from the guest domains to be migrated.

Kernel Zones Block Live Migration of Guest Domains

Bug ID 21289174: On a SPARC system, a running kernel zone within an Oracle VM Server for SPARC domain will block live migration of the guest domain. The following error message is shown:

```
Guest suspension failed because Kernel Zones are active.
Stop Kernel Zones and retry.
```

Workaround: Choose one of the following workarounds:

- Stop running the kernel zone.

```
# zoneadm -z zonename shutdown
```
- Suspend the kernel zone.

```
# zoneadm -z zonename suspend
```
- Perform a live migration of the kernel zone to another system before migrating the guest domain.

See Chapter 3, “Migrating an Oracle Solaris Kernel Zone,” in *Creating and Using Oracle Solaris Kernel Zones*.

Cross-CPU Live Migrations Between SPARC T7 Series Servers and SPARC M7 Series Servers and Older Platforms Require at Least the Oracle VM Server for SPARC 3.2 Software on the Source Machine and the Target Machine

Bug ID 20606773: Cross-CPU live migrations between a SPARC T7 series server or a SPARC M7 series server and an older platform require that you run at least Oracle VM Server for SPARC 3.2 software on the source and target machines.

For example, live migration between a SPARC T5 system and a SPARC T7 series server requires that at least Oracle VM Server for SPARC 3.2 software is installed on the SPARC T5 system.

Domain Migration Might Fail Even Though Sufficient Memory in a Valid Layout Is Available on the Target System

Bug ID 20453206: A migration operation might fail even if sufficient memory in a valid layout is available on the target system. Memory DR operations might make it more difficult to migrate a guest domain.

Workaround: None.

Oracle Solaris 10 Guest Domains That Have Only One Virtual CPU Assigned Might Panic During a Live Migration

Bug ID 17285751: Migrating an Oracle Solaris 10 guest domain that has only one virtual CPU assigned to it might cause a panic on the guest domain in the function `pg_cmt_cpu_fini()`.

Workaround: Assign at least two virtual CPUs to the guest domain before you perform the live migration. For example, use the `ldm add-vcpu number-of-virtual-CPUs domain-name` command to increase the number of virtual CPUs assigned to the guest domain.

Domain Migrations From SPARC T4 Systems That Run System Firmware 8.3 to SPARC T5, SPARC M5, or SPARC M6 Systems Are Erroneously Permitted

Bug ID 17027275: Domain migrations from SPARC T4 systems that run system firmware 8.3 to SPARC T5, SPARC M5, or SPARC M6 systems are not permitted. Although the migration succeeds, a subsequent memory DR operation causes a panic.

Workaround: Update the system firmware on the SPARC T4 system to version 8.4. See the workaround for “[Guest Domain Panics at `lgrp_lineage_add\(mutex_enter: bad mutex, lp=10351178\)`”](#) on page 47.

ldm migrate -n Should Fail When Performing a Cross-CPU Migration From SPARC T5, SPARC M5, or SPARC M6 System to UltraSPARC T2 or SPARC T3 System

Bug ID 16864417: The `ldm migrate -n` command does not report failure when attempting to migrate between a SPARC T5, SPARC M5, or SPARC M6 machine and an UltraSPARC T2 or SPARC T3 machine.

Workaround: None.

ldm list -o status on Target Control Domain Reports Bogus Migration Progress

Bug ID 15819714: In rare circumstances, the `ldm list -o status` command reports a bogus completion percentage when used to observe the status of a migration on a control domain.

This problem has no impact on the domain that is being migrated or on the `ldmd` daemons on the source or target control domains.

Workaround: Run the `ldm list -o status` command on the other control domain that is involved in the migration to observe the progress.

Guest Domain Panics When Running the cputrack Command During a Migration to a SPARC T4 System

Bug ID 15776123: If the `cputrack` command is run on a guest domain while that domain is migrated to a SPARC T4 system, the guest domain might panic on the target machine after it has been migrated.

Workaround: Do not run the `cputrack` command during the migration of a guest domain to a SPARC T4 system.

Guest Domain That Uses Cross-CPU Migration Reports Random Uptimes After the Migration Completes

Bug ID 15775055: After a domain is migrated between two machines that have different CPU frequencies, the uptime reports by the `ldm list` command might be incorrect. These incorrect results occur because uptime is calculated relative to the `STICK` frequency of the machine on which the domain runs. If the `STICK` frequency differs between the source and target machines, the uptime appears to be scaled incorrectly.

This issue only applies to UltraSPARC T2, UltraSPARC T2 Plus and SPARC T3 systems.

The uptime reported and shown by the guest domain itself is correct. Also, any accounting that is performed by the Oracle Solaris OS in the guest domain is correct.

nxge Panics When Migrating a Guest Domain That Has Hybrid I/O and Virtual I/O Virtual Network Devices

Bug ID 15710957: When a heavily loaded guest domain has a hybrid I/O configuration and you attempt to migrate it, you might see an nxge panic.

Workaround: Add the following line to the `/etc/system` file on the primary domain and on any service domain that is part of the hybrid I/O configuration for the domain:

```
set vsw:vsw_hio_max_cleanup_retries = 0x200
```

Live Migration of a Domain That Depends on an Inactive Master Domain on the Target Machine Causes `ldmd` to Fault With a Segmentation Fault

Bug ID 15701865: If you attempt a live migration of a domain that depends on an inactive domain on the target machine, the `ldmd` daemon faults with a segmentation fault, and the domain on the target machine restarts. Although you can still perform a migration, it will not be a live migration.

Workaround: Perform one of the following actions before you attempt the live migration:

- Remove the guest dependency from the domain to be migrated.
- Start the master domain on the target machine.

DRM Fails to Restore the Default Number of Virtual CPUs for a Migrated Domain When the Policy Is Removed or Expired

Bug ID 15701853: After you perform a domain migration while a DRM policy is in effect, if the DRM policy expires or is removed from the migrated domain, DRM fails to restore the original number of virtual CPUs to the domain.

Workaround: If a domain is migrated while a DRM policy is active and the DRM policy is subsequently expired or removed, reset the number of virtual CPUs. Use the `ldm set -vcpu` command to set the number of virtual CPUs to the original value on the domain.

Migration Failure Reason Not Reported When the System MAC Address Clashes With Another MAC Address

Bug ID 15699763: A domain cannot be migrated if it contains a duplicate MAC address. Typically, when a migration fails for this reason, the failure message shows the duplicate MAC address. However in rare circumstances, this failure message might not report the duplicate MAC address.

```
# ldm migrate ldg2 system2
Target Password:
Domain Migration of LDom ldg2 failed
```

Workaround: Ensure that the MAC addresses on the target machine are unique.

Simultaneous Migration Operations in “Opposite Direction” Might Cause `ldm` to Hang

Bug ID 15696986: If two `ldm migrate` commands are issued between the same two systems simultaneously in the “opposite direction,” the two commands might hang and never complete. An opposite direction situation occurs when you simultaneously start a migration on machine A to machine B and a migration on machine B to machine A.

The hang occurs even if the migration processes are initiated as dry runs by using the `-n` option. When this problem occurs, all other `ldm` commands might hang.

Workaround: None.

Migration of a Domain That Has an Enabled Default DRM Policy Results in a Target Domain Being Assigned All Available CPUs

Bug ID 15655513: Following the migration of an active domain, CPU utilization in the migrated domain can increase dramatically for a short period of time. If a dynamic resource management (DRM) policy is in effect for the domain at the time of the migration, the Logical Domains Manager might begin to add CPUs. In particular, if the `vcpu-max` and `at tack` properties were not specified when the policy was added, the default value of `unlimited` causes all the unbound CPUs in the target machine to be added to the migrated domain.

Recovery: No recovery is necessary. After the CPU utilization drops below the upper limit that is specified by the DRM policy, the Logical Domains Manager automatically removes the CPUs.

Explicit Console Group and Port Bindings Are Not Migrated

Bug ID 15527921: During a migration, any explicitly assigned console group and port are ignored, and a console with default properties is created for the target domain. This console is created using the target domain name as the console group and using any available port on the first virtual console concentrator (`vcc`) device in the control domain. If there is a conflict with the default group name, the migration fails.

Recovery: To restore the explicit console properties following a migration, unbind the target domain and manually set the desired properties using the `ldm set -vcons` command.

Migration Can Fail to Bind Memory Even If the Target Has Enough Available

Bug ID 15523120: In certain situations, a migration fails and `ldmd` reports that it was not possible to bind the memory needed for the source domain. This situation can occur even if the total amount of available memory on the target machine is greater than the amount of memory being used by the source domain.

This failure occurs because migrating the specific memory ranges in use by the source domain requires that compatible memory ranges are available on the target as well. When no such compatible memory range is found for any memory range in the source, the migration cannot proceed. See “[Migration Requirements for Memory](#)” in *Oracle VM Server for SPARC 3.3 Administration Guide*.

Recovery: If this condition is encountered, you might be able to migrate the domain if you modify the memory usage on the target machine. To do this, unbind any bound or active logical domain on the target.

Use the `ldm list-devices -a mem` command to see what memory is available and how it is used. You might also need to reduce the amount of memory that is assigned to another domain.

Cannot Connect to Migrated Domain's Console Unless vntsd Is Restarted

Bug ID 15513998: Occasionally, after a domain has been migrated, it is not possible to connect to the console for that domain.

Workaround: Restart the vntsd SMF service to enable connections to the console:

```
# svcadm restart vntsd
```

Note – This command will disconnect all active console connections.

Cannot Migrate a Domain Between a System That Has EFI GPT Disk Labels and a System That Does Not Have EFI GPT Disk Labels

System firmware versions 8.4, 9.1, and XCP2230 introduced support for EFI GPT disk labels. By default, virtual disks that are installed when running at least the Oracle Solaris 11.1 OS on those systems have an EFI GPT disk label. You cannot read this disk label on older versions of firmware (such as 9.0.x, 8.3, 7.x, or XCP2221). This situation precludes you from performing a live migration or a cold migration to a system that runs a system firmware version without EFI GPT support. Note that a cold migration also fails in this situation, which is different than the previous limitations.

To determine whether your virtual disk has an EFI GPT disk label, run the `devinfo -i` command on the raw device. The following examples show whether the virtual disk has an SMI VTOC or an EFI GPT disk label.

- **SMI VTOC disk label.** When your virtual disk has an SMI VTOC, you can perform a migration to firmware regardless of whether it supports EFI.

This example indicates that the device has a VTOC label because the `devinfo -i` command reports device-specific information.

```
# devinfo -i /dev/rdisk/c2d0s2
/dev/rdisk/c2d0s2      0      0      73728  512      2
```

- **EFI GPT disk label.** When your virtual disk has an EFI GPT disk label, you can perform a migration only to firmware that has EFI support.

This example indicates that the device has an EFI GPT disk label because the `devinfo -i` command reports an error.

```
# devinfo -i /dev/rdisk/c1d0s0
devinfo: /dev/rdisk/c1d0s0: This operation is not supported on EFI
labeled devices
```

SR-IOV Issues

SPARC M5 and SPARC M6: Virtual Function Add Operation Triggers a PCIe Fabric Error Panic When Attempting to Enable SR-IOV on the PCIe Bus That Hosts rKVMs Devices

Bug ID 21548747: If you use any SR-IOV devices on a SPARC M5 or SPARC M6 system on a PCIe bus that hosts rKVMs devices, attempting to enable SR-IOV after a dynamic bus add DBUS operation triggers an FMA error panic.

Workaround: Restrict the use of a PCIe bus that hosts rKVMs devices to the primary domain. Only use the static PCIe bus assignment method to remove and add this bus to the primary domain.

Fibre Channel Physical Function Configuration Changes Require Several Minutes to Complete

Bug ID 21299683: After you create or destroy virtual functions, it might take up to five minutes before you can attempt to create or destroy more virtual functions from the Fibre Channel physical function.

If you attempt to perform these operations before five minutes elapse, the operations fail with a message similar to the following:

```
The attempt to offline the pf /SYS/PCI-EM4/IOVFC.PF0 in domain
primary failed.
Error message from svc:/ldoms/agents in domain primary:
CMD_OFFLINE Failed. ERROR: devices or resources are busy.
```

Sometimes the states of the physical function, the virtual function, or both appear as INV in `ldm list-io` output. For example, in the following sample output, physical function 0 and its child virtual functions have an INV status.

```
primary# ldm list-io pci_5
NAME                                     TYPE  BUS      DOMAIN  STATUS
----                                     -
pci_5                                    BUS   pci_5    primary  IOV
```

/SYS/RCSA/PCIE5	PCIE	pci_5	primary	OCC
/SYS/RCSA/PCIE6	PCIE	pci_5	primary	OCC
/SYS/RCSA/PCIE5/IOVFC.PF0	PF	pci_5	primary	INV
/SYS/RCSA/PCIE5/IOVFC.PF1	PF	pci_5	primary	
/SYS/RCSA/PCIE5/IOVFC.PF0.VF0	VF	pci_5		INV
/SYS/RCSA/PCIE5/IOVFC.PF0.VF1	VF	pci_5		INV
/SYS/RCSA/PCIE5/IOVFC.PF0.VF2	VF	pci_5		INV
/SYS/RCSA/PCIE5/IOVFC.PF0.VF3	VF	pci_5		INV
/SYS/RCSA/PCIE5/IOVFC.PF0.VF4	VF	pci_5		INV
/SYS/RCSA/PCIE5/IOVFC.PF0.VF5	VF	pci_5		INV
/SYS/RCSA/PCIE5/IOVFC.PF0.VF6	VF	pci_5		INV

Workaround: To clear the INV status on the physical and virtual functions, perform the following steps:

1. Wait five minutes.
2. Retry the IOV operation to create or destroy the virtual function on the Fibre Channel physical function.

You can perform all necessary IOV configurations for the Fibre Channel physical function in a single command by using the `ldm create-vf -n max` or `ldm destroy-vf -n max` command.

Ldm remove-io Command Reports a Timeout and Fails to Remove the Last SR-IOV Virtual Function From an I/O Domain

Bug ID 20731016: When you use the `ldm remove-io` command to remove the last SR-IOV virtual function from an I/O domain, the command might report a timeout and fail to remove the virtual function.

Workaround: If this problem occurs, perform the following steps:

1. Verify that the `system/management/hwmgmt` package is installed on the system.

```
# pkg info system/management/hwmgmt
```

2. Disable the `svc:/system/sp/management` service.

```
# svcadm disable -st svc:/system/sp/management
```

3. Retry the `ldm remove-io` command.

4. When the SR-IOV virtual function is successfully removed, enable the `svc:/system/sp/management` service.

```
# svcadm enable svc:/system/sp/management
```

Fibre Channel Physical Function Is Faulted by FMA and Disabled

Bug IDs 18168525 and 18156291: You must connect the Fibre Channel PCIe card to a Fibre Channel switch that supports NPIV and that is compatible with the PCIe card. If you do not use this configuration, using the `format` command, or creating or destroying a virtual function might cause the physical function to be faulted by FMA and disabled. If this fault occurs, the message is similar to the following:

SUNW-MSG-ID: PCIEX-8000-0A, TYPE: Fault, VER: 1, SEVERITY: Critical
EVENT-TIME: *event-time*
PLATFORM: *platform-type*
SOURCE: eft, REV: 1.16
EVENT-ID: *event-ID*
DESC: A problem was detected for a PCIEX device.
AUTO_RESPONSE: One or more device instances may be disabled
IMPACT: Loss of services provided by the device instances associated with this fault
REC-ACTION: Use 'fmadm faulty' to provide a more detailed view of this event. Please refer to the associated reference document at <http://support.oracle.com/msg/PCIEX-8000-0A> for the latest service procedures and policies regarding this diagnosis.

Workaround: If the card has been faulted by FMA, first check its connections and ensure that the card is not directly connected to storage. Then, perform the step that matches your configuration:

- **Card is directly connected to storage** – Correctly configure the Fibre Channel PCIe card by connecting it to a Fibre Channel switch that supports NPIV and is compatible with the PCIe card. Then, run the `fmadm repair` command to override the FMA diagnosis.
- **Card is not directly connected to storage** – Replace the card.

Warnings Appear on Console When Creating Fibre Channel Virtual Functions

Bug ID 17623156: When you create Fibre Channel virtual functions, you might see the following warnings:

```
WARNING: kmem_cache_destroy: 'px0_emlxs3_3_cache2'  
(3000383e030) not empty  
WARNING: vmem_destroy('px0_emlxs3_3_vmem_top'):  
leaked 262144 identifiers
```

These messages do not affect the normal operation of the system and you can ignore them.

Workaround: None.

Fujitsu M10 Server Has Different SR-IOV Feature Limitations

On a Fujitsu M10 server you can assign PCIe endpoint devices and SR-IOV virtual functions from a particular PCIe bus to a maximum of 24 domains. The maximum is 15 domains for supported SPARC T-Series and SPARC M-Series platforms.

Bugs Affecting the Oracle VM Server for SPARC Software

This section summarizes the bugs that you might encounter when using this version of the software. The most recent bugs are described first. Workarounds and recovery procedures are specified, if available.

Oracle Solaris OS Bugs Affecting the Oracle VM Server for SPARC 3.3 Software

The following Oracle Solaris OS bugs have been fixed in the fully qualified Oracle Solaris OS releases. These bugs might still be present in Oracle Solaris 10 OS versions. To avoid these problems, ensure that you run one of the Oracle Solaris OS versions that is associated with the bug ID.

To obtain details about the bugs in this table, review the bug reports.

TABLE 1-1 Resolved Oracle Solaris OS Bugs

Bug ID	Bug Description	Resolved in Oracle Solaris OS Versions
15707426	Logical Domains agent service does not come online if the system log service does not come online	Oracle Solaris 11 Oracle Solaris 10 1/13 with at least ID 147147-26
15701258	Virtual CPU timeout failures during DR	Oracle Solaris 11 Oracle Solaris 10 1/13 with at least ID 147147-26
15560811	Oracle Solaris 11: zones configured with an automatic network interface might fail to start	Oracle Solaris 11
15422900	Guest domain with too many virtual networks on the same network using DHCP can become unresponsive	Oracle Solaris 11

Bugs Affecting the Oracle VM Server for SPARC 3.3 Software

IOV Information Update Might Take Four Minutes After Running the `cfgadm configure` or `cfgadm unconfigure` Command

Bug ID 21953704: The `ldm list -io` command might not show the most up-to-date IOV information immediately after running a `cfgadm` command. You might have to wait as long as four minutes for the updated information to be available.

Workaround: None.

ovmtcreate Generates Incorrect OVF File If the Locale Is Not C

Bug ID 21780045: The ovmtcreate utility generates a NULL string for the Version information in the OVF file if the locale is not the C locale (non-English locale environment).

The values for the Version and FullVersion properties are null as shown by the XML lines that appear in bold in this example:

```
<ovf:VirtualSystem ovf:id="templates">
  <ovf:Info>Oracle VM Template</ovf:Info>
  <ovf:ProductSection ovf:class="com.oracle.ovmt">
    <ovf:Info>Oracle VM Template</ovf:Info>
    <ovf:Product>Oracle VM Template</ovf:Product>
    <ovf:Version></ovf:Version>
    <ovf:FullVersion></ovf:FullVersion>
```

When the ovmtdeploy utility uses the templates that you created by using the ovmtcreate utility in the non-C locale environment, a Java exception occurs because the templates include the NULL strings.

```
# /opt/ovmtutils/bin/ovmtdeploy -d guest10 -o /export/home/ovm \
/export/home/templates.ova
```

```
Oracle Virtual Machine for SPARC Deployment Utility
ovmtdeploy Version
Copyright (c) 2014, 2015, Oracle and/or its affiliates. All rights reserved.
```

STAGE 1 - EXAMINING SYSTEM AND ENVIRONMENT

```
-----
Checking user privilege
Performing platform & prerequisite checks
Checking for required services
Named resourced available
```

2 - ANALYZING ARCHIVE & RESOURCE REQUIREMENTS

```
-----
Checking .ova format and contents
Validating archive configuration
Exception in thread "main" java.lang.NullPointerException
  at ovfparse.OvfParse.getTagValue(OvfParse.java:233)
  at ovfparse.VmProduct.<init>(VmProduct.java:33)
  at ovfparse.VmSys.<init>(VmSys.java:72)
  at ovfparse.OvfParse.parseOVFByDOM(OvfParse.java:371)
  at ovfparse.OvfParse.<init>(OvfParse.java:56)
  at ovmtdeploy.Ovmtdeploy.exec(Ovmtdeploy.java:1841)
  at ovmtdeploy.Ovmtdeploy.main(Ovmtdeploy.java:1946)
```

Workaround: Perform the following steps:

1. Edit the OVF file to add the version numbers to the contents of the Version and FullVersion properties.
2. Re-archive the template ova by using the gtar command.

For example:

```
# /usr/bin/gtar -cf templates.ova templates.ovf templates.mf System.img.gz
```

3. Run the `ovmtdploy` utility with `-k` option to skip checksum verification.

`ldm add-vsan` Fails After Replacing the PCIe Card

Bug ID 21674282: When you replace a PCIe card in the same slot, using the `ldm add-vsan` command that specifies an alias for the physical SCSI HBA device (`/SYS`) might fail.

Workaround: Do not specify the device name alias. Instead, specify the full device path name (`/pci`) for the `ldm add-vsan` command.

`ovmtdcreate` Fails If the Service Domain Has Multiple Virtual Disk Servers

Bug ID 21635033: When a service domain has more than one virtual disk server (`vds`), running the `ovmtdcreate` utility for a guest domain might fail because the utility checks only the first `vds` instance in the service domain.

For example, running the `ovmtdcreate` utility for the `gdom3` domain fails if the virtual disk is configured as follows:

- The primary domain has four virtual disk servers (`vds`)
- The virtual disk server device that corresponds to the virtual disk on the `gdom3` domain is associated with `vds3`

In the following sample output, the lines in bold show that `vds0` is the first virtual disk server and virtual disk server device for the `gdom3` virtual disk is not `vds0`.

```
primary# ldm list -l -p -o disk
VERSION 1.15

DOMAIN|name=primary|
VDS|name=vds0|nclients=1
|vol=vol0|opts=|dev=/export/home/ovm/gdom0.img|mpgroup=
VDS|name=vds1|nclients=1
|vol=vol0|opts=|dev=/export/home/ovm/gdom1.img|mpgroup=
VDS|name=vds2|nclients=1
|vol=vol0|opts=|dev=/export/home/ovm/gdom2.img|mpgroup=
VDS|name=cdrom|nclients=3
|vol=1|opts=|dev=/export/home/ovm/sol-113_1.iso|mpgroup=
|vol=2|opts=|dev=/export/home/ovm/sol-113_2.iso|mpgroup=
|vol=3|opts=|dev=/export/home/ovm/sol-113_3.iso|mpgroup=
|vol=4|opts=|dev=/export/home/ovm/sol-113_4.iso|mpgroup=
VDS|name=vds3|nclients=1
|vol=disk0|opts=|dev=/export/home/ovm/gdom3.img|mpgroup=
DOMAIN|name=gdom0|
VDISK|name=vdisk0|vol=vol0@vds0|timeout=|dev=disk@0|server=primary|mpgroup=|id=0
VDISK|name=cdrom|vol=1@cdrom|timeout=|dev=disk@1|server=primary|mpgroup=|id=1
DOMAIN|name=gdom1|
VDISK|name=vdisk0|vol=vol0@vds1|timeout=|dev=disk@0|server=primary|mpgroup=|id=0
VDISK|name=cdrom|vol=2@cdrom|timeout=|dev=disk@1|server=primary|mpgroup=|id=1
DOMAIN|name=gdom2|
VDISK|name=vdisk0|vol=vol0@vds2|timeout=|dev=disk@0|server=primary|mpgroup=|id=0
```

```

VDISK|name=cdrom|vol=3@cdrom|timeout=|dev=disk@1|server=primary|mpgroup=|id=1
DOMAIN|name=gdom3|
VDISK|name=vdisk0|vol=disk0@vds3|timeout=|dev=disk@0|server=primary|mpgroup=|id=0

```

The following `ldm list` command shows the `gdom3` domain status:

```

primary# ldm list
NAME          STATE      FLAGS  CONS  VCPU  MEMORY  UTIL  NORM  UPTIME
primary      active    -n-cv-  UART   32    46848M  0.3%  0.3%  1d 51m
gdom0        active    -n----  5000   24    24G     0.0%  0.0%  1d 35m
gdom1        active    -n----  5001   24    24G     0.0%  0.0%  8d 18h 21m
gdom2        active    -n----  5002   24    24G     0.0%  0.0%  8d 17h 43m
gdom3        bound     ------  5003   24    24G

```

The following command shows the error you receive when running the `ovmtcreate` command for the `gdom3` domain:

```

# /opt/ovmtutils/bin/ovmtcreate -d gdom3 -o /export/home/ovmt
STAGE 1 - EXAMINING SYSTEM AND ENVIRONMENT
-----
Performing platform & prerequisite checks
Checking user permissions
Checking for required packages
Checking for required services
Checking directory permissions

STAGE 2 - ANALYZING DOMAIN
-----
Retrieving and processing attributes
Checking domain state
Getting domain resource settings
Discovering network topology
Discovering disk topology
ERROR: VDS Device does not exist or not readable

```

Workaround: Ensure that the service domain has only one virtual disk server before you run the `ovmtcreate` utility.

A Domain That Has Socket Constraints Cannot Be Re-Created From an XML File

Bug ID 21616429: The Oracle VM Server for SPARC 3.3 software introduced socket support for Fujitsu M10 servers only.

Software running on Oracle SPARC systems and Oracle VM Server for SPARC versions older than 3.3 cannot re-create a domain with socket constraints from an XML file.

Attempting to re-create a domain with socket constraints from an XML file with an older version of the Oracle VM Server for SPARC software or on an Oracle SPARC system fails with the following message:

```

primary# ldm add-domain -i ovm3.3_socket_ovm11.xml
socket not a known resource

```

If Oracle VM Server for SPARC 3.2 is running on a Fujitsu M10 server and you attempt to re-create a domain with socket constraints from an XML file, the command fails with various error messages, such as the following:

```
primary# ldm add-domain -i ovm3.3_socket_ovm11.xml
Unknown property: vcpus
```

```
primary# ldm add-domain -i ovm3.3_socket_ovm11.xml
perf-counters property not supported, platform does not have
performance register access capability, ignoring constraint setting.
```

Workaround: Edit the XML file to remove any sections that reference the socket resource type.

DRM Is Unresponsive When a Domain Has Only a Few Virtual CPUs

Bug ID 21561834: If the number of virtual CPUs in a domain drops below four, DRM might fail to add virtual CPUs to the domain even when utilization significantly exceeds the upper utilization level. If the `util-upper` property value is greater than the default value of 70, DRM might fail to add virtual CPUs even if the domain has more than four virtual CPUs.

Workaround: Set the DRM policy's `elastic-margin` property value to at least 15.

```
primary# ldm set-policy elastic-margin=15 name=policy-name domain-name
```

If the `util-upper` property value is greater than 70, set the DRM policy's `elastic-margin` property value to at least 20.

```
primary# ldm set-policy elastic-margin=20 name=policy-name domain-name
```

Note – Ensure that the `elastic-margin` property value is lower than the `util-upper` property value.

Fujitsu M10 servers: Running `ldm set-socket` on an Active Domain Might Cause Unstable Operation of the Logical Domains Manager

Bug ID 21527087: In rare cases, using the `ldm set-socket` command to specify sockets for a running domain might cause the following unexpected behavior:

- The Logical Domains Manager might crash
- The `ldm set-socket` command completes but not all of the domain's CPUs and memory are remapped to the specified sockets

However, if the physical partition (PPAR) has more than 12 sockets, do not use the `ldm set-socket --restored-degraded` and `ldm set-socket socket_id=id` commands while the domain is running. If you do run these commands on a running domain, the `ldmd` state might become corrupted.

Workaround: Stop the domain before executing an `ldm set-socket` command.

It is always safe to clear an active domain's socket constraints by using the `ldm set -socket` command to set the `socket_id` property to a NULL value.

Random device busy or `ldm remove-io` Command Failures While Removing One or More PCIe Buses

Bug ID 21510615: Sometimes, you might get a persistent device busy or `ldm remove-io` failures while removing one or more PCIe buses.

Workaround: Check the `gdm` service, disable manually (or check and kill `Xorg`) and retry the `ldm remove-io` operation.

```
# svcs | grep gdm
# svcadm disable -st svc:/application/graphical-login/gdm:default
```

Or:

```
# ps -ef | grep Xorg
# pkill Xorg
```

Fujitsu M10 servers: Inconsistent Socket Constraints Might Cause the Logical Domains Manager to Crash During CPU Removal

Bug ID 21367043: In rare circumstances, socket constraints might become out of synchronization with the bound CPU and memory resources of a domain. The `ldm rm-vcpu`, `ldm set-vcpu`, `ldm rm-core`, and `ldm set-core` commands might cause the Logical Domains Manager to crash with the following error message in the `ldmd` SMF log:

```
fatal error: xcalloc(0,4) : one of number or size is <= 0 at line 1183
of affinity_core.c
```

Workaround: Clear the domain's socket constraints by using the following commands:

```
primary# ldm list-socket domain-name
primary# ldm set-socket socket_id= domain-name
```

`ldmpower` Causes a Segmentation Fault of `ldmd`

Bug ID 21369897: While administering a guest domain, running the `ldmpower` command causes a segmentation fault of the `ldmd` daemon.

Workaround: Do not execute the `ldmpower` command while performing addition or removal operations on a guest domain.

Fatal Error in the PCIe Fabric Causes a Root Domain to Panic

Bug IDs 21352084, 21861284, and 21861327: In rare circumstances, a root domain might panic if it receives an I/O error and starts to analyze the error while an I/O domain is reset.

The panic message is similar to the following:

```
panic[cpu15]/thread=2a1017d3c20:
Fatal error has occurred in: PCIe fabric.(0x2)(0x245)
```

The ereports are dumped to the console at the time of the panic. The ereports show that some status register values, including the `pcie_ue_status` value, are all FFs. After the panic, the root domain reboots itself and recovers.

Workaround: None.

Slow I/O on Virtual SCSI HBA Guest Domain When One of the Service Domains is Down With a Virtual SCSI HBA Timeout Set

Bug ID 21321166: I/O throughput is sometimes slower when using a virtual SCSI HBA MPxIO path to an offline service domain.

Workaround: Disable the path to the offline service domain by using the `mpathadm disable path` command until the service domain is returned to service.

Fujitsu M10 servers: ldm shrink-socket Command Removes Additional Memory If the Memory Block Is Unaligned

Bug ID 21299404: If you use the `ldm shrink-socket` command to perform a memory DR operation and one of the domain's memory blocks is not 256-Mbyte aligned, the command might remove an additional 256 Mbytes of memory from the active domain. If the domain's memory is fragmented, the `ldmd` daemon might attempt to further remove additional memory.

Workaround: None.

ldm list-group Shows the Same Memory and I/O In Both the /SYS/MB and Other Resource Groups

Bug ID 21283102: The `ldm list-rsrc-group` command might show the same memory and I/O resource information under both the `/SYS/MB` (motherboard) and other resource groups. For example:

```
primary# ldm list-group
NAME                                CORE  MEMORY  IO
/SYS/PM0                            32    64G     4
/SYS/PM1                            32   256G     4
/SYS/PM2                            32   128G     4
```

```

/SYS/PM3                32    128G    4
/SYS/MB                 0     576G    16

```

primary# ldm list-group -a -l

```

NAME                    CORE  MEMORY  IO
/SYS/PM0                32    64G     4

```

CORE

```

CID                    BOUND
0, 1                  primary
2, 3, 4, 5, 6, 7, 8, 9
10, 11, 12, 13, 14, 15, 16, 17
18, 19, 20, 21, 22, 23, 24, 25
26, 27, 28, 29, 30, 31

```

MEMORY

```

PA          SIZE          BOUND
0x0         57M           _sys_
0x39000000  32M           _sys_
0x59000000  94M           _sys_
0xb7000000  393M          _sys_
0x24000000  192M          _sys_
0x30000000  31488M        _sys_
0x7e000000  64M           _sys_
0x7e400000  64M           _sys_
0x7e800000  384M          _sys_
0x800000000000  32G

```

IO

```

DEVICE          PSEUDONYM      BOUND
pci@300         pci_0          primary
pci@340         pci_1          primary
pci@380         pci_2          primary
pci@3c0         pci_3          primary

```

```

NAME                    CORE  MEMORY  IO
/SYS/PM1                32    256G    4

```

CORE

```

CID                    BOUND
32, 33, 34, 35, 36, 37, 38, 39
40, 41, 42, 43, 44, 45, 46, 47
48, 49, 50, 51, 52, 53, 54, 55
56, 57, 58, 59, 60, 61, 62, 63

```

MEMORY

```

PA          SIZE          BOUND
0x1000000000000  768M
0x1000300000000  24G           primary
0x1006300000000  105728M
0x1800000000000  128G

```

IO

```

DEVICE          PSEUDONYM      BOUND
pci@400         pci_4          primary
pci@440         pci_5          primary
pci@480         pci_6          primary
pci@4c0         pci_7          primary

```

```

-----
NAME                                CORE MEMORY IO
/SYS/PM2                            32  128G  4

CORE
  CID                                BOUND
  64, 65, 66, 67, 68, 69, 70, 71
  72, 73, 74, 75, 76, 77, 78, 79
  80, 81, 82, 83, 84, 85, 86, 87
  88, 89, 90, 91, 92, 93, 94, 95

MEMORY
  PA                                SIZE          BOUND
  0x2000000000000000             64G
  0x2800000000000000             64G

IO
  DEVICE                            PSEUDONYM      BOUND
  pci@500                           pci_8           primary
  pci@540                           pci_9           primary
  pci@580                           pci_10          primary
  pci@5c0                           pci_11          primary

```

```

-----
NAME                                CORE MEMORY IO
/SYS/PM3                            32  128G  4

CORE
  CID                                BOUND
  96, 97, 98, 99, 100, 101, 102, 103
  104, 105, 106, 107, 108, 109, 110, 111
  112, 113, 114, 115, 116, 117, 118, 119
  120, 121, 122, 123, 124, 125, 126, 127

MEMORY
  PA                                SIZE          BOUND
  0x3000000000000000             64G
  0x3800000000000000             64G

IO
  DEVICE                            PSEUDONYM      BOUND
  pci@600                           pci_12          primary
  pci@640                           pci_13          primary
  pci@680                           pci_14          primary
  pci@6c0                           pci_15          primary

```

```

-----
NAME                                CORE MEMORY IO
/SYS/MB                              0    576G  16

MEMORY
  PA                                SIZE          BOUND
  0x0                               57M           _sys_
  0x39000000                        32M           _sys_
  0x59000000                        94M           _sys_
  0xb7000000                        393M          _sys_
  0x24000000                        192M          _sys_
  0x30000000                        31488M

```

0x7e0000000	64M	_sys_
0x7e4000000	64M	_sys_
0x7e8000000	384M	_sys_
0x80000000000	32G	
0x100000000000	768M	
0x100030000000	24G	primary
0x100630000000	105728M	
0x180000000000	128G	
0x200000000000	64G	
0x280000000000	64G	
0x300000000000	64G	
0x380000000000	64G	

IO

DEVICE	PSEUDONYM	BOUND
pci@300	pci_0	primary
pci@340	pci_1	primary
pci@380	pci_2	primary
pci@3c0	pci_3	primary
pci@400	pci_4	primary
pci@440	pci_5	primary
pci@480	pci_6	primary
pci@4c0	pci_7	primary
pci@500	pci_8	primary
pci@540	pci_9	primary
pci@580	pci_10	primary
pci@5c0	pci_11	primary
pci@600	pci_12	primary
pci@640	pci_13	primary
pci@680	pci_14	primary
pci@6c0	pci_15	primary

Workaround: See the detailed information for memory and I/O in the following columns to determine whether the same resource information is shown:

- **Memory:** PA, SIZE and BOUND
- **I/O:** DEVICE, PSEUDONYM and BOUND

Virtual SCSI HBA Does Not See Dynamic LUN Changes Without a Reboot

Bug ID 21188211: If LUNs are added to or removed from a virtual SAN after a virtual SCSI HBA is configured, the `ldm rescan -vhba` command sometimes does not show the new LUN view.

Workaround: Remove the virtual SCSI HBA and then re-add it. Check to see whether the LUNs are seen. If the removal and re-add operations are unsuccessful, you must reboot the guest domain.

Logical Domains Manager Should Not Rely on Polling to Obtain Configuration Status From the DIO Agent

Bug ID 21114622: When you execute the `ldm create -vf` or `ldm destroy -vf` command, the associated physical function driver is detached and re-attached, which can take a significant but

unquantifiable amount of time. The amount of time depends the number of virtual functions that are involved and the complexity of the target hardware device.

Running the `ldm list -io` command might show that the physical function (and its child virtual functions) have the INV (invalid) status.

Currently, the Logical Domains Manager polls the agent for a period of time and then stops polling. If the polling period is too short, the device might show the INV status indefinitely.

Note – The fix for bug 20772410 should reduce the occurrence of this problem.

Workaround: From the root domain that owns the physical function device, restart the `ldoms/agents` service.

```
primary# svcadm restart ldoms/agents
```

Run this command if the INV status persists for at least six minutes after issuing the `ldm create -vf` or `ldm destroy -vf` command.

vhba Should Support SCSI HBAs When MPxIO Is Enabled in the Service Domain

Bug ID 20951004: `vhba` should support SCSI HBAs when MPxIO is enabled in the service domain.

Workaround: Disable MPxIO for all the initiator ports on the service domain by running the following command:

```
# stmsboot -d
```

Suppress FRU-Monitor Alerts When PCI Bus Is Re-Assigned From the primary Domain to a Guest Domain

Bug ID 20882700: When a PCIe device (or an SR-IOV virtual function) is removed from or added to a domain, the Oracle Solaris 11.3 `fmd` fault management daemon reports the event in exactly the same way as if an FRU had been physically removed or added.

You might see console messages and messages in the `/var/adm/messages` file similar to the following:

■

```
SUNW-MSG-ID: FMD-8000-A0, TYPE: Alert, VER: 1, SEVERITY: Minor
EVENT-TIME: Tue May 19 18:39:41 PDT 2015
PLATFORM: unknown, CSN: unknown, HOSTNAME: starbuck
SOURCE: software-diagnosis, REV: 0.1
EVENT-ID: 5077e6c3-6a15-457e-a55b-cb72ea5f9728
DESC: FRU has been added to the system.
```

AUTO-RESPONSE: FMD topology will be updated.
 IMPACT: System impact depends on the type of FRU.
 REC-ACTION: Use `fmadm faulty` to provide a more detailed view of this event.
 Please refer to the associated reference document at
<http://support.oracle.com/msg/FMD-8000-A0> for the latest service procedures
 and policies regarding this diagnosis.

■
fmadm faulty

```
-----
TIME                EVENT-ID                MSG-ID                SEVERITY
-----
Apr 14 10:04:00    2d981602-975c-4861-9f26-e37360eca697  FMD-8000-CV  Minor
```

```
Problem Status      : open
Diag Engine         : software-diagnosis / 0.1
System
  Manufacturer      : Oracle Corporation
  Name              : SPARC T7-2
  Part_Number       : T7_2
  Serial_Number     : T7_2
  Host_ID           : 86582a8c
```

```
-----
Suspect 1 of 1 :
  Problem class : alert.oracle.solaris.fmd.fru-monitor.fru-remove
  Certainty    : 100%
```

```
FRU
  Status          : active/not present
  Location        : "/SYS/MB/PCIE1"
  Manufacturer    : unknown
  Name            : unknown
  Part_Number     : unknown
  Revision        : unknown
  Serial_Number   : unknown
  Chassis
    Manufacturer  : Oracle-Corporation
    Name          : SPARC-T7-2
    Part_Number   : T7_2
    Serial_Number : T7_2
```

```
Resource
  Status          : active/not present
```

Description : FRU '/SYS/MB/PCIE1' has been removed from the system.

Response : FMD topology will be updated.

Impact : System impact depends on the type of FRU.

Action : Use '`fmadm faulty`' to provide a more detailed view of this event.
 Please refer to the associated reference document at
<http://support.oracle.com/msg/FMD-8000-CV> for the latest service
 procedures and policies regarding this diagnosis.

Workaround: You can ignore these alerts as long as they were generated by explicit administrator actions to add or remove an I/O device from a domain.

mpathadm Shows Incorrect Path State Output for a Virtual SCSI HBA When a Fibre Channel Cable Is Pulled

Bug ID 20876502: Pulling the SAN cable from a service domain that is part of a virtual SCSI HBA MPxIO guest domain configuration causes the Path State column of the `mpathadm` output to show incorrect values. In addition, pulling the cable leads to I/O operation failures in the guest domain.

Workaround: Plug in the SAN cable and run the `ldm rescan -vhba` command for all the virtual SCSI HBAs to the service domain that has the cable attached. After performing this workaround, the guest domain should resume performing I/O operations.

device busy Error When Attempting to Remove a PCIe Bus That Hosts an SES-Enabled Storage Device

Bug ID 20774477: If you use SES-enabled storage devices, you might see a device busy error when you attempt to remove a PCIe bus that hosts these devices. To determine whether you are using this type of storage device, search for the `ses` or `enclosure` string in the `ldm list-io -l` output for the PCIe bus.

Workaround: Perform one of the following workarounds to remove the PCIe bus:

- **Dynamically remove the PCIe bus.**

1. Disable the FMD service.

```
primary# svcadm disable -st svc:/system/fmd
```

2. Remove the PCIe bus.

```
primary# ldm remove-io bus
```

3. Re-enable the FMD service.

```
primary# svcadm enable svc:/system/fmd
```

- **Statically remove the PCIe bus.**

1. Place the root domain that has the PCIe bus in a delayed reconfiguration.

```
primary# ldm start-reconf root-domain
```

2. Remove the PCIe bus.

```
primary# ldm remove-io bus
```

3. Perform a reboot from the root domain console.

```
root-domain# reboot
```

rcm_daemon Might Emit a Message on the Console During an ldm remove-io Operation

Bug ID 20619894: If the `system/management/hwmgmt` package is not installed, a dynamic bus remove operation causes the `rcm_daemon` to print the following message on the console:

```
rcm_daemon[839]: rcm script ORCL,pcie_rc_rcm.pl: svcs: Pattern 'sp/management'  
doesn't match any instances
```

Workaround: You can safely ignore this message.

Dynamic Bus Removal Should be Aware of Virtual SAN Devices Prior to Removing a PCIe Bus

Bug ID 20532270: Be aware of any direct I/O or dynamic bus removal operations that attempt to remove the physical SCSI HBA from the virtual SAN's control.

If you perform an `ldm remove-io` operation on a PCIe resource that is referenced by a virtual SAN device, that device is unusable if it has never been referenced by an `ldm add-vhba` command. If the `ldm remove-io` operation occurs after you run the `ldm add-vhba` command, the `vsan` module prevents the PCIe resource from being removed.

Workaround: Delete the virtual SAN.

After Dropping Into factory-default, Recovery Mode Fails If the System Boots From a Different Device Than the One Booted in the Previously Active Configuration

Bug ID 20425271: While triggering a recovery after dropping into `factory-default`, recovery mode fails if the system boots from a different device than the one booted in the previously active configuration. This failure might occur if the active configuration uses a boot device other than the `factory-default` boot device.

Workaround: Perform the following steps any time you want to save a new configuration to the SP:

1. Determine the full PCI path to the boot device for the primary domain.
Use this path for the `ldm set-var` command in Step 4.
2. Remove any currently set `boot-device` property from the primary domain.
Performing this step is necessary only if the `boot-device` property has a value set. If the property does not have a value set, an attempt to remove the `boot-device` property results in the `boot-device not found` message.

```
primary# ldm rm-var boot-device primary
```

3. Save the current configuration to the SP.

```
primary# ldm add-spconfig config-name
```

4. Explicitly set the `boot-device` property for the primary domain.

```
primary# ldm set-var boot-device=value primary
```

If you set the `boot-device` property after saving the configuration to the SP as described, the specified boot device is booted when recovery mode is triggered.

Recovery: If recovery mode has already failed as described, perform the following steps:

1. Explicitly set the boot device to the one used in the last running configuration.

```
primary# ldm set-var boot-device=value primary
```

2. Reboot the primary domain.

```
primary# reboot
```

The reboot enables the recovery to proceed.

Panic When Using the `ldm rm-io virtual-function` Command to MPxIO That Contains a Virtual SCSI HBA

Bug ID 20046234: When a virtual SCSI HBA and a Fibre Channel SR-IOV device can view the same LUNs in a guest domain when MPxIO is enabled, a panic might occur. The panic occurs if the Fibre Channel SR-IOV card is removed from the guest domain and then re-added.

Workaround: Do not configure a guest domain with Fibre Channel SR-IOV and a virtual SCSI HBA when both have MPxIO enabled.

ixgbev Nodes on an I/O Domain Are Reported as Disabled By the `ipadm` Command and Non-Existent By the `ifconfig` Command

Bug ID 20004281: When a primary domain is power cycled, `ixgbev` nodes on the I/O domain might be reported as disabled by the `ipadm` command, and as nonexistent by the `ifconfig` command.

Workaround: Re-enable the IP interfaces:

```
# svcadm restart network/physical:default
```

HGXE Interfaces Are Unusable If Assigned by Using Direct I/O to an I/O Domain

Bug ID 19943809: The `hxge` driver cannot use interfaces inside an I/O domain when the card is assigned by using the direct I/O feature.

The following warning is issued to the system log file:

```
WARNING: hxge0 : <== hxge_setup_mutexes: failed 0x1
```

Workaround: Add the following line to the `/etc/system` and reboot:

```
set px:px_force_intx_support=1
```

Guest Domain eeprom Updates Are Lost if an ldm add-spconfig Operation Is Not Complete

Bug ID 19932842: An attempt to set an OBP variable from a guest domain might fail if you use the eeprom or the OBP command before one of the following commands is completed:

- `ldm add-spconfig`
- `ldm remove-spconfig`
- `ldm set-spconfig`
- `ldm bind`

This problem might occur when these commands take more than 15 seconds to complete.

```
# /usr/sbin/eeprom boot-file\=-k
promif_ldom_setprop: promif_ldom_setprop: ds response timeout
eeprom: OPROMSETOPT: Invalid argument
boot-file: invalid property
```

Recovery: Retry the eeprom or OBP command after the ldm operation has completed.

Workaround: Retry the eeprom or OBP command on the affected guest domain. You might be able to avoid the problem by using the `ldm set-var` command on the primary domain.

Rebooting a Guest Domain With More Than 1000 Virtual Network Devices Results in a Panic

Bug ID 19449221: A domain can have no more than 999 virtual network devices (vnets).

Workaround: Limit the number of vnets on a domain to 999.

Oracle VM Server for SPARC No Longer Keeps Track of Freed MAC Addresses

Bug ID 19078763: Oracle VM Server for SPARC no longer keeps track of freed MAC addresses. MAC addresses are now allocated by randomly selecting an address and then confirming that address is not used by any logical domains on the local network.

Sun Storage 16 Gb Fibre Channel Universal HBA Firmware Does Not Support Bandwidth Controls

Bug ID 18083904: The firmware for Sun Storage 16 Gb Fibre Channel Universal HBA, Emulex cards does not support setting bandwidth controls. The HBA firmware ignores any value that you specify for the `bw-percent` property.

Workaround: None.

Incorrect Device Path for Fibre Channel Virtual Functions in a Root Domain

Bug ID 18001028: In the root domain, the Oracle Solaris device path for a Fibre Channel virtual function is incorrect.

For example, the incorrect path name is `pci@380/pci@1/pci@0/pci@6/fibre-channel@0,2` while it should be `pci@380/pci@1/pci@0/pci@6/SUNW,emlxs@0,2`.

The `ldm list-io -l` output shows the correct device path for the Fibre Channel virtual functions.

Workaround: None.

Issues Might Arise When FMA Detects Faulty Memory

Bug ID 17576087: Performing a power cycle of the system to a saved configuration might not restore the memory after the faulty memory has been replaced.

Workaround: After you replace the faulty memory, perform a power cycle of the system to the `factory-default` configuration. Then, perform a power cycle of the system to the configuration that you want to use.

DLMP Does Not Work in a Guest Domain on Top of a Virtual Network Device or an SR-IOV Virtual Function

You cannot configure a DLMP aggregation on an SR-IOV NIC virtual function or a virtual network device in a guest domain.

Cannot Install the Oracle Solaris 11.1 OS Using an EFI GPT Disk Label on Single-Slice Virtual Disk

Bug ID 17422973: The installation of the Oracle Solaris 11.1 OS on a single-slice disk might fail with the following error on a SPARC T4 server that runs at least system firmware version 8.4.0, a SPARC T5, SPARC M5, or SPARC M6 server that runs at least system firmware version 9.1.0, and a Fujitsu M10 server that runs at least XCP version 2230:

```
cannot label 'c1d0': try using fdisk(1M) and then provide a specific slice
Unable to build pool from specified devices: invalid vdev configuration
```

Workaround: Relabel the disk with an SMI label.

Guest Domain Panics at `lgrp_lineage_add(mutex_enter: bad mutex, lp=10351178)`

Bug ID 17020950: After migrating an active domain from a SPARC T4 platform to a SPARC T5, SPARC M5, or SPARC M6 platform that was bound using firmware version 8.3, performing a memory dynamic reconfiguration might result in a guest domain panic.

Workaround: Before you perform the migration, update the SPARC T4 system with version 8.4 of the system firmware. Then, rebind the domain.

Misleading Messages Shown For InfiniBand SR-IOV Remove Operations

Bug ID 16979993: An attempt to use a dynamic SR-IOV remove operation on an InfiniBand device results in confusing and inappropriate error messages.

Dynamic SR-IOV remove operations are not supported for InfiniBand devices.

Workaround: Remove InfiniBand virtual functions by performing one of the following procedures:

- “How to Remove an InfiniBand Virtual Function From an I/O Domain” in *Oracle VM Server for SPARC 3.3 Administration Guide*
- “How to Remove an InfiniBand Virtual Function From a Root Domain” in *Oracle VM Server for SPARC 3.3 Administration Guide*

Resilient I/O Domain Should Support PCI Device Configuration Changes After the Root Domain Is Rebooted

Bug ID 16691046: If virtual functions are assigned from the root domain, an I/O domain might fail to provide resiliency in the following hotplug situations:

- You add a root complex (PCIe bus) dynamically to the root domain, and then you create the virtual functions and assign them to the I/O domain.
- You hot-add an SR-IOV card to the root domain that owns the root complex, and then you create the virtual functions and assign them to the I/O domain.
- You replace or add any PCIe card to an empty slot (either through hotplug or when the root domain is down) on the root complex that is owned by the root domain. This root domain provides virtual functions from the root complex to the I/O domain.

Workaround: Perform one of the following steps:

- If the root complex already provides virtual functions to the I/O domain and you add, remove, or replace any PCIe card on that root complex (through hotplug or when the root domain is down), you must reboot both the root domain and the I/O domain.
- If the root complex does not have virtual functions currently assigned to the I/O domain and you add an SR-IOV card or any other PCIe card to the root complex, you must stop the root domain to add the PCIe card. After the root domain reboots, you can assign virtual functions from that root complex to the I/O domain.
- If you want to add a new PCIe bus to the root domain and then create and assign virtual functions from that bus to the I/O domain, perform one of the following steps and then reboot the root domain:
 - Add the bus during a delayed reconfiguration
 - Add the bus dynamically

Guest Domains in Transition State After Reboot of the primary Domain

Bug ID 16659506: A guest domain is in transition state (t) after a reboot of the primary domain. This problem arises when a large number of virtual functions are configured on the system.

Workaround: To avoid this problem, retry the OBP disk boot command several times to avoid a boot from the network.

Perform the following steps on each domain:

1. Access the console of the domain.

```
primary# telnet localhost 5000
```

2. Set the boot-device property.

```
ok> setenv boot-device disk disk disk disk disk disk disk disk disk net
```

The number of disk entries that you specify as the value of the boot-device property depends on the number of virtual functions that are configured on the system. On smaller systems, you might be able to include fewer instances of disk in the property value.

3. Verify that the boot-device property is set correctly by using the printenv.

```
ok> printenv
```

4. Return to the primary domain console.
5. Repeat Steps 1-4 for each domain on the system.
6. Reboot the primary domain.

```
primary# shutdown -i6 -g0 -y
```

Subdevices Under a PCIe Device Revert to an Unassigned Name

Bug ID 16299053: After disabling a PCIe device, you might experience unexpected behavior. The subdevices that are under the disabled PCIe device revert to the non-assigned names while the PCIe device is still owned by the domain.

Workaround: If you decide to disable a PCIe slot on the ILOM, ensure that the PCIe slot is not assigned to a domain by means of the direct I/O (DIO) feature. That is, first ensure that the PCIe slot is assigned to the corresponding root domain before disabling the slot on the ILOM.

If you disable the PCIe slot on the ILOM while the PCIe slot is assigned to a domain with DIO, stop that domain and reassign the device to the root domain for the correct behavior.

WARNING: ddi_intr_alloc: cannot fit into interrupt pool Means That Interrupt Supply Is Exhausted While Attaching I/O Device Drivers

Bug ID 16284767: This warning on the Oracle Solaris console means the interrupt supply was exhausted while attaching I/O device drivers:

WARNING: ddi_intr_alloc: cannot fit into interrupt pool

The hardware provides a finite number of interrupts, so Oracle Solaris limits how many each device can use. A default limit is designed to match the needs of typical system configurations, however this limit may need adjustment for certain system configurations.

Specifically, the limit may need adjustment if the system is partitioned into multiple logical domains and if too many I/O devices are assigned to any guest domain. Oracle VM Server for SPARC divides the total interrupts into smaller sets given to guest domains. If too many I/O devices are assigned to a guest domain, its supply might be too small to give each device the default limit of interrupts. Thus, it exhausts its supply before it completely attaches all the drivers.

Some drivers provide an optional callback routine which allows Oracle Solaris to automatically adjust their interrupts. The default limit does not apply to these drivers.

Workaround: Use the `::irmools` and `::irmreqs` MDB macros to determine how interrupts are used. The `::irmools` macro shows the overall supply of interrupts divided into pools. The `::irmreqs` macro shows which devices are mapped to each pool. For each device, `::irmreqs` shows whether the default limit is enforced by an optional callback routine, how many interrupts each driver requested, and how many interrupts the driver is given.

The macros do not show information about drivers that failed to attach. However, the information that is shown helps calculate the extent to which you can adjust the default limit. Any device that uses more than one interrupt without providing a callback routine can be forced to use fewer interrupts by adjusting the default limit. Reducing the default limit below the amount that is used by such a device results in freeing of interrupts for use by other devices.

To adjust the default limit, set the `ddi_msix_alloc_limit` property to a value from 1 to 8 in the `/etc/system` file. Then, reboot the system for the change to take effect.

To maximize performance, start by assigning larger values and decrease the values in small increments until the system boots successfully without any warnings. Use the `::irmools` and `::irmreqs` macros to measure the adjustment's impact on all attached drivers.

For example, suppose the following warnings are issued while booting the Oracle Solaris OS in a guest domain:

```
WARNING: emlxs3: interrupt pool too full.
WARNING: ddi_intr_alloc: cannot fit into interrupt pool
```

The `::irmools` and `::irmreqs` macros show the following information:

```
# echo "::irmools" | mdb -k
ADDR      OWNER      TYPE      SIZE  REQUESTED  RESERVED
00000400016be970 px#0      MSI/X    36    36         36

# echo "00000400016be970::irmreqs" | mdb -k
```

ADDR	OWNER	TYPE	CALLBACK	NINTRS	NREQ	NAVAIL
00001000143acaa8	emLxs#0	MSI-X	No	32	8	8
00001000170199f8	emLxs#1	MSI-X	No	32	8	8
000010001400ca28	emLxs#2	MSI-X	No	32	8	8
0000100016151328	igb#3	MSI-X	No	10	3	3
0000100019549d30	igb#2	MSI-X	No	10	3	3
0000040000e0f878	igb#1	MSI-X	No	10	3	3
000010001955a5c8	igb#0	MSI-X	No	10	3	3

The default limit in this example is eight interrupts per device, which is not enough interrupts to accommodate the attachment of the final emLxs3 device to the system. Assuming that all emLxs instances behave in the same way, emLxs3 probably requested 8 interrupts.

By subtracting the 12 interrupts used by all of the igb devices from the total pool size of 36 interrupts, 24 interrupts are available for the emLxs devices. Dividing the 24 interrupts by 4 suggests that 6 interrupts per device would enable all emLxs devices to attach with equal performance. So, the following adjustment is added to the /etc/system file:

```
set ddi_msix_alloc_limit = 6
```

When the system successfully boots without warnings, the ::irmpools and ::irmreqs macros show the following updated information:

```
# echo "::irmpools" | mdb -k
ADDR          OWNER      TYPE      SIZE  REQUESTED  RESERVED
00000400018ca868  px#0      MSI/X     36    36         36

# echo "00000400018ca868::irmreqs" | mdb -k
ADDR          OWNER      TYPE      CALLBACK  NINTRS  NREQ  NAVAIL
0000100016143218  emLxs#0  MSI-X    No        32      8     6
0000100014269920  emLxs#1  MSI-X    No        32      8     6
000010001540be30  emLxs#2  MSI-X    No        32      8     6
00001000140cbe10  emLxs#3  MSI-X    No        32      8     6
00001000141210c0  igb#3    MSI-X    No        10      3     3
0000100017549d38  igb#2    MSI-X    No        10      3     3
0000040001ceac40  igb#1    MSI-X    No        10      3     3
000010001acc3480  igb#0    MSI-X    No        10      3     3
```

ixgbevf Device in SR-IOV Domains Might Become Disabled When Rebooting the primary Domain

Bug ID 16224353: After rebooting the primary domain, ixgbevf instances in primary domain might not work.

Workaround: None.

SPARC M5-32 and SPARC M6-32: LSI-SAS Controller Is Incorrectly Exported With SR-IOV

Bug ID 16071170: On a SPARC M5-32 or a SPARC M6-32 system, the internal SAS controllers are exported as SR-IOV-enabled controllers even though these cards do not support SR-IOV.

The Oracle VM Server for SPARC log shows the following messages when attempting to create the physical function on these cards:

```
Dec 11 04:27:54 warning: Dropping pf
pci@d00/pci@1/pci@0/pci@0/pci@0/pci@4/LSI,sas@0: no IOV capable driver
Dec 11 04:27:54 warning: Dropping pf
pci@d80/pci@1/pci@0/pci@c/pci@0/pci@4/LSI,sas@0: no IOV capable driver
Dec 11 04:27:54 warning: Dropping pf
pci@c00/pci@1/pci@0/pci@c/pci@0/pci@4/LSI,sas@0: no IOV capable driver
Dec 11 04:27:54 warning: Dropping pf
pci@e00/pci@1/pci@0/pci@0/pci@0/pci@4/LSI,sas@0: no IOV capable driver
```

The system has four LSI SAS controller ports, each in one IOU of the SPARC M5-32 and SPARC M6-32 assembly. This error is reported for each port.

Workaround: You can ignore these messages. These messages indicate only that the LSI-SAS controller devices on the system are capable of SR-IOV but no SR-IOV support is available for this hardware.

SPARC T5-8: Uptime Data Shows a Value of 0 for Some ldm List Commands

Bug ID 16068376: On a T5-8 with approximately 128 domains, some `ldm list` commands such as `ldm list` might show 0 seconds as the uptime for all domains.

Workaround: Log in to the domain and use the `uptime` command to determine the domain's uptime.

No Error Message When a Memory DR Add is Partially Successful

Bug ID 15812823: In low free-memory situations, not all memory blocks can be used as part of a memory DR operation due to size. However, these memory blocks are included in the amount of free memory. This situation might lead to a smaller amount of memory being added to the domain than expected. No error message is shown if this situation occurs.

Workaround: None.

ldm init-system Command Might Not Correctly Restore a Domain Configuration on Which Physical I/O Changes Have Been Made

Bug ID 15783031: You might experience problems when you use the `ldm init-system` command to restore a domain configuration that has used direct I/O or SR-IOV operations.

A problem arises if one or more of the following operations have been performed on the configuration to be restored:

- A slot has been removed from a bus that is still owned by the primary domain.
- A virtual function has been created from a physical function that is owned by the primary domain.

- A virtual function has been assigned to the primary domain, to other guest domains, or to both.
- A root complex has been removed from the primary domain and assigned to a guest domain, and that root complex is used as the basis for further I/O virtualization operations. In other words, you created a non-primary root domain and performed any of the previous operations.

To ensure that the system remains in a state in which none of the previous actions have taken place, see [Using the `ldm init-system` Command to Restore Domains on Which Physical I/O Changes Have Been Made](https://support.oracle.com/epmos/faces/DocumentDisplay?id=1575852.1) (<https://support.oracle.com/epmos/faces/DocumentDisplay?id=1575852.1>).

Control Domain Requires the Lowest Core in the System

Bug ID 15778392: The control domain requires the lowest core in the system. So, if core ID 0 is the lowest core, it cannot be shared with any other domain if you want to apply the whole-core constraint to the control domain.

For example, if the lowest core in the system is core ID 0, the control domain should look similar to the following output:

```
# ldm ls -o cpu primary
NAME
primary

VCPUs
VID  PID  CID  UTIL  STRAND
0    0    0    0.4%  100%
1    1    0    0.2%  100%
2    2    0    0.1%  100%
3    3    0    0.2%  100%
4    4    0    0.3%  100%
5    5    0    0.2%  100%
6    6    0    0.1%  100%
7    7    0    0.1%  100%
```

Limit the Maximum Number of Virtual Functions That Can be Assigned to a Domain

Bug ID 15775637: An I/O domain has a limit on the number of interrupt resources that are available per root complex.

On SPARC T3 and SPARC T4 systems, the limit is approximately 63 MSI/X vectors. Each `igb` virtual function uses three interrupts. The `ixgbe` virtual function uses two interrupts.

If you assign a large number of virtual functions to a domain, the domain runs out of system resources to support these devices. You might see messages similar to the following:

```
WARNING: ixgbev32: interrupt pool too full.
WARNING: ddi_intr_alloc: cannot fit into interrupt pool
```

Trying to Connect to Guest Domain Console While It Is Being Bound Might Cause Input to be Blocked

Bug ID 15771384: A domain's guest console might freeze if repeated attempts are made to connect to the console before and during the time the console is bound. For example, this might occur if you use an automated script to grab the console as a domain is being migrated onto the machine.

Workaround: To unfreeze console, perform the following commands on the domain that hosts the domain's console concentrator (usually the control domain):

```
primary# svcadm disable vntsd
primary# svcadm enable vntsd
```

ldm remove-io of PCIe Cards That Have PCIe-to-PCI Bridges Should Be Disallowed

Bug ID 15761509: Use only the PCIe cards that support the Direct I/O (DIO) feature, which are listed in this [support document \(https://support.us.oracle.com/oip/faces/secure/km/DocumentDisplay.jspx?id=1325454.1\)](https://support.us.oracle.com/oip/faces/secure/km/DocumentDisplay.jspx?id=1325454.1).

Workaround: Use the `ldm add-io` command to add the card to the primary domain again.

ldm stop Command Might Fail If Issued Immediately After an ldm start Command

Bug ID 15759601: If you issue an `ldm stop` command immediately after an `ldm start` command, the `ldm stop` command might fail with the following error:

```
LDom domain-name stop notification failed
```

Workaround: Reissue the `ldm stop` command.

System Panics When Rebooting a primary Domain That Has a Very Large Number of Virtual Functions Assigned

Bug ID 15750727: A system might panic when you reboot a primary domain that has a very large number of virtual functions assigned to it.

Workaround: Perform one of the following workarounds:

- Decrease the virtual function number to reduce the number of failed virtual functions. This change might keep the chip responsive.
- Create more Interrupt Resource Management (IRM) pools for the `ixgbe` virtual function because only one IRM pool is created by default for all the `ixgbe` virtual functions on the system.

Partial Core primary Fails to Permit Whole-Core DR Transitions

Bug ID 15748348: When the primary domain shares the lowest physical core (usually 0) with another domain, attempts to set the whole-core constraint for the primary domain fail.

Workaround: Perform the following steps:

1. Determine the lowest bound core that is shared by the domains.

```
# ldm list -o cpu
```

2. Unbind all the CPU threads of the lowest core from all domains other than the primary domain.

As a result, CPU threads of the lowest core are not shared and are free for binding to the primary domain.

3. Set the whole-core constraint by doing one of the following:

- Bind the CPU threads to the primary domain, and set the whole-core constraint by using the `ldm set -vcpu -c` command.
- Use the `ldm set -core` command to bind the CPU threads and set the whole-core constraint in a single step.

Cannot Use Oracle Solaris Hot-Plug Operations to Hot-Remove a PCIe Endpoint Device

Bug ID 15721872: You cannot use Oracle Solaris hot-plug operations to hot-remove a PCIe endpoint device after that device is removed from the primary domain by using the `ldm rm-io` command. For information about replacing or removing a PCIe endpoint device, see [“Making PCIe Hardware Changes” in Oracle VM Server for SPARC 3.3 Administration Guide](#).

DRM and ldm list Output Shows a Different Number of Virtual CPUs Than Are Actually in the Guest Domain

Bug ID 15701853: A No response message might appear in the Oracle VM Server for SPARC log when a loaded domain's DRM policy expires after the CPU count has been substantially reduced. The `ldm list` output shows that more CPU resources are allocated to the domain than is shown in the `psrinfo` output.

Workaround: Use the `ldm set -vcpu` command to reset the number of CPUs on the domain to the value that is shown in the `psrinfo` output.

SPARC T3-1: Issue With Disks That Are Accessible Through Multiple Direct I/O Paths

Bug ID 15668368: A SPARC T3-1 system can be installed with dual-ported disks, which can be accessed by two different direct I/O devices. In this case, assigning these two direct I/O devices to different domains can cause the disks to be used by both domains and affect each other based on the actual usage of those disks.

Workaround: Do not assign direct I/O devices that have access to the same set of disks to different I/O domains. To determine whether you have dual-ported disks on a SPARC T3-1 system, run the following command on the SP:

```
-> show /SYS/SASBP
```

If the output includes the following `fru_description` value, the corresponding system has dual-ported disks:

```
fru_description = BD,SAS2,16DSK,LOUISE
```

If dual disks are found to be present in the system, ensure that both of the following direct I/O devices are always assigned to the same domain:

```
pci@400/pci@1/pci@0/pci@4 /SYS/MB/SASHBA0  
pci@400/pci@2/pci@0/pci@4 /SYS/MB/SASHBA1
```

Guest Domains Running Oracle Solaris 10: Memory DR Removal Operations With Multiple Plumbed NIU nxge Instances Can Hang Indefinitely and Never Complete

Bug ID 15667770: When multiple NIU nxge instances are plumbed on a domain, the `ldm rm-mem` and `ldm set-mem` commands, which are used to remove memory from the domain, might never complete. To determine whether the problem has occurred during a memory removal operation, monitor the progress of the operation with the `ldm list -o status` command. You might have encountered this problem if the progress percentage remains constant for several minutes.

Workaround: Cancel the `ldm rm-mem` or `ldm set-mem` command, and check whether a sufficient amount of memory was removed. If not, a subsequent memory removal command to remove a smaller amount of memory might complete successfully.

If the problem has occurred on the primary domain, do the following:

1. Start a delayed reconfiguration operation on the primary domain.

```
# ldm start-reconf primary
```

2. Assign the desired amount of memory to the domain.
3. Reboot the primary domain.

If the problem occurred on another domain, stop the domain before adjusting the amount of memory that is assigned to the domain.

Using the `ldm stop -a` Command on Domains in a Master-Slave Relationship Leaves the Slave With the Stopping Flag Set

Bug ID 15664666: When a reset dependency is created, an `ldm stop -a` command might result in a domain with a reset dependency being restarted instead of only stopped.

Workaround: First, issue the `ldm stop` command to the master domain. Then, issue the `ldm stop` command to the slave domain. If the initial stop of the slave domain results in a failure, issue the `ldm stop -f` command to the slave domain.

Dynamic Reconfiguration of MTU Values of Virtual Network Devices Sometimes Fails

Bug ID 15631119: If you modify the maximum transmission unit (MTU) of a virtual network device on the control domain, a delayed reconfiguration operation is triggered. If you subsequently cancel the delayed reconfiguration, the MTU value for the device is not restored to the original value.

Recovery: Rerun the `ldm set -vnet` command to set the MTU to the original value. Resetting the MTU value puts the control domain into delayed reconfiguration mode, which you need to cancel. The resulting MTU value is now the original, correct MTU value.

```
# ldm set-vnet mtu=orig-value vnet1 primary
# ldm cancel-op reconf primary
```

Dynamically Removing All the Cryptographic Units From a Domain Causes SSH to Terminate

Bug ID 15600969: If all the hardware cryptographic units are dynamically removed from a running domain, the cryptographic framework fails to seamlessly switch to the software cryptographic providers, and kills all the ssh connections.

Recovery: Re-establish the ssh connections after all the cryptographic units are removed from the domain.

Workaround: Set `UseOpenSSLEngine=no` in the `/etc/ssh/sshd_config` file on the server side, and run the `svcadm restart ssh` command.

All ssh connections will no longer use the hardware cryptographic units (and thus not benefit from the associated performance improvements), and ssh connections will not be disconnected when the cryptographic units are removed.

PCI Express Dual 10-Gigabit Ethernet Fiber Card Shows Four Subdevices in `ldm list-io -l` Output

Bug ID 15597025: When you run the `ldm ls -io -l` command on a system that has a PCI Express Dual 10-Gigabit Ethernet Fiber card (X1027A-Z) installed, the output might show the following:

```
primary# ldm ls -io -l
...
pci@500/pci@0/pci@c PCIE5 OCC primary
```

```
network@0
network@0,1
ethernet
ethernet
```

The output shows four subdevices even though this Ethernet card has only two ports. This anomaly occurs because this card has four PCI functions. Two of these functions are disabled internally and appear as ethernet in the `ldm ls-io -l` output.

Workaround: You can ignore the ethernet entries in the `ldm ls-io -l` output.

ldm Commands Are Slow to Respond When Several Domains Are Booting

Bug ID 15572184: An `ldm` command might be slow to respond when several domains are booting. If you issue an `ldm` command at this stage, the command might appear to hang. Note that the `ldm` command will return after performing the expected task. After the command returns, the system should respond normally to `ldm` commands.

Workaround: Avoid booting many domains simultaneously. However, if you must boot several domains at once, refrain from issuing further `ldm` commands until the system returns to normal. For instance, wait for about two minutes on Sun SPARC Enterprise T5140 and T5240 servers and for about four minutes on the Sun SPARC Enterprise T5440 server or Sun Netra T5440 server.

Oracle Solaris 11: Zones Configured With an Automatic Network Interface Might Fail to Start

Bug ID 15560811: In Oracle Solaris 11, zones that are configured with an automatic network interface (`anet`) might fail to start in a domain that has Logical Domains virtual network devices only.

- **Workaround 1:** Assign one or more physical network devices to the guest domain. Use PCIe bus assignment, the Direct I/O (DIO), or the SR-IOV feature to assign a physical NIC to the domain.
- **Workaround 2:** If the zones configuration requirement is to have interzone communication only within the domain, create an `etherstub` device. Use the `etherstub` device as the “lower link” in the zones configuration so that virtual NICs are created on the `etherstub` device.
- **Workaround 3:** Use exclusive link assignment to assign a Logical Domains virtual network device to a zone. Assign virtual network devices, as needed, to the domain. You might also choose to disable inter-vnet links to be able to create a large number of virtual network devices.

Logical Domains Manager Does Not Start If the Machine Is Not Networked and an NIS Client Is Running

Bug ID 15518409: If you do not have a network configured on your machine and have a Network Information Services (NIS) client running, the Logical Domains Manager will not start on your system.

Workaround: Disable the NIS client on your non-networked machine:

```
# svcadm disable nis/client
```

Sometimes, Executing the uadmin 1 0 Command From a Logical Domains System Does Not Return the System to the OK Prompt

Bug ID 15511551: Sometimes, executing the `uadmin 1 0` command from the command line of a Logical Domains system does not leave the system at the ok prompt after the subsequent reset. This incorrect behavior is seen only when the Logical Domains variable `auto-reboot?` is set to `true`. If `auto-reboot?` is set to `false`, the expected behavior occurs.

Workaround: Use this command instead:

```
uadmin 2 0
```

Or, always run with `auto-reboot?` set to `false`.

Simultaneous Net Installation of Multiple Domains Fails When in a Common Console Group

Bug ID 15453968: Simultaneous net installation of multiple guest domains fails on systems that have a common console group.

Workaround: Only net-install on guest domains that each have their own console group. This failure is seen only on domains with a common console group shared among multiple net-installing domains.

OpenBoot PROM Variables Cannot be Modified by the eeprom Command When the Logical Domains Manager Is Running

Bug ID 15387338: This issue is summarized in [“Logical Domains Variable Persistence” in Oracle VM Server for SPARC 3.3 Administration Guide](#) and affects only the control domain.

Cannot Set Security Keys With Logical Domains Running

Bug ID 15370442: The Logical Domains environment does not support setting or deleting wide-area network (WAN) boot keys from within the Oracle Solaris OS by using the `ickey(1M)` command. All `ickey` operations fail with the following error:

```
ickey: setkey: ioctl: I/O error
```

In addition, WAN boot keys that are set using OpenBoot firmware in logical domains other than the control domain are not remembered across reboots of the domain. In these domains, the keys set from the OpenBoot firmware are valid only for a single use.

Behavior of the `ldm stop-domain` Command Can Be Confusing

Bug ID 15368170: In some cases, the behavior of the `ldm stop-domain` command is confusing.

```
# ldm stop-domain -f domain-name
```

If the domain is at the kernel module debugger, `kmdb(1)`, prompt, then the `ldm stop-domain` command fails with the following error message:

```
LDom <domain-name> stop notification failed
```

Resolved Issues

The following enhancement requests and bugs have been fixed for the Oracle VM Server for SPARC 3.3 software release:

- 21446603 Fix suspended reconfiguration with mblock splitting
- 21439137 Unbound constrained domains vanish post ldmd crash on reconf cancellation
- 21438526 PCIe slot status remains EMP after successful hotplug enable of the connector
- 21434726 Ldom migration fails with Ldoms 3.3 Integration 15 and target ldmd cores
- 21427171 Disable unsupported 'dr-pdom' domain service messages
- 21427137 Disable move-core and move-memory commands
- 21419747 Problem in PAPL/M10
- 21367340 LDOMs: auto changing physical-bindings constraint
- 21366945 Recovery Mode messages should indicate recovery is ongoing
- 21350128 Fix for 21240346 breaks DTrace probes in ldmd
- 21342706 PCIe slots stuck in UNK status following DBUS add operation
- 21328933 vhba timeout value does not persist across guest domain migration
- 21313658 Fujitsu socket remapping requires latest firmware
- 21306352 Board DR causes ldmd abort after ldmd changes in S11.2 SRU9
- 21296317 ldomMIB.so gets issues with athena_skip_cpu_memory and fj_force_flag symbols

- 21258580 Migration failed with DRM policy enabled
- 21258063 Memory operation block by "A memory blacklist operation is being processed"
- 21251095 Migrated guest domain panics on resumption on target machine
- 21249867 Migration results in hung ldmd on the target machine
- 21248066 mem_bind_real() reports "Cannot move memory" warning during a failed migration
- 21240346 Domains with Kernel Zones should emit meaningful output for migration failure
- 21239682 Add ovmtutils to ldoms-incorporation
- 21234461 FC SRIOV: "set-io port-wwn=<> node-wwn=<> VF" succeeding when not in delay-reconf
- 21209454 rgrp_get_split_mblk_cap_info: referenced symbol not found
- 21203360 CPU autoreplacement breaks CMI multi-instance
- 21202779 Domains left suspended if suspend fails but HV is reconfigured
- 21196845 Live Service on M10 removes memory other than specified resource group
- 21195903 Possible migration failures and memory corruption
- 21193823 Assertion failure on rm-memory -g as do_mem_dr() called while not on sequencer
- 21191079 The LDOMs smf service on the newly deployed sparc system goes to maintenance
- 21189304 Assertion failure when CMI nop attempted for active domain
- 21181793 ovmtconfig fails to set the auto-boot property
- 21174268 Recovery with Fujitsu sockets may calculate resources incorrectly
- 21174261 init-system -f should ignore Fujitsu sockets
- 21174256 Recovery should ignore degraded sockets saved in bootset
- 21174253 Degraded Fujitsu sockets not reset to current bound resources
- 21174250 M10-specific code breaks recovery on non-M10 platforms
- 21173437 Board DR move failures if domains do not support mblock splitting
- 21173038 Board DR move failure with bound domain causes SEGV
- 21165224 add-domain -i fails with socket not a known resource
- 21164944 Blacklisting and board evacuation can run at the same time as DRM
- 21151265 /SYS/MB is rejected as invalid to resource group move and remove CLIs

- 21150868 ovmcreate retains domain name in XML even when alternate specified
- 21150415 M10 specific code breaks remap CLIs on non-M10 platforms
- 21138802 Migration does not take advantage of mblock splitting support
- 21134659 set-vcpu of domain with physical-bindings tries to set incorrect number of CPUs
- 21129227 Disable evacuate-io/restore-io code for LDoms 3.3
- 21123013 Live migration pre-suspend API group check should be removed
- 21117019 Properties files should include other settings such as allowing NIS and LDAP
- 21116899 ldm list-group only shows partial memory on T5-2
- 21116432 ovmutils: remove the standalone ovfparse script from /opt/ovmutils/bin
- 21116138 Incorrect total memory size in ldm list-group -a -l command for /SYS/MB
- 21109812 ovmtprop -h should include banner and copyright message
- 21109793 Solaris boilerplate should not contain default values
- 21109771 ovmconfig properties files should not contain default values
- 21093569 ovmutils: ovmutility should not set a limit on property description
- 21092364 Incorrect format strings in ldomcli/policy.c and rgrp_mem.c, nvlist lint errors
- 21092307 No error messages for XMPP commands in Recovery Mode
- 21084406 Out of sequence 'dr-pdom' progress messages sent to GM
- 21082758 Missing HOSTID in "ldm ls-constraints -x <guest>"
- 21081832 Logic error in SDIO NPRD recovery
- 21077022 "PRI component node has no topo-hc-name" warning in ldmd service log
- 21072214 Policy active does not set to vcpu-max when domain is loaded and has >vcpu-max
- 21070377 init-system reports Malformed XML Document
- 21060914 Illegal recovery_mode_boot_timeout values should be handled gracefully
- 21057594 Better policy checks between PM and SP policy needed
- 20996572 'core -g' commands should not run at the same time as DRM
- 20995171 Heartbeat thread parameters may be clobbered
- 20991993 Guest Live migration from T5-8 to T5-2 fails: API group 0x1 v1.5 is not supported
- 20976838 Assertion failed: ildp->rgrp_mem.ildom_sel_mblks == 0, file rgrp_mem.c:1746

-
- 20975146 Need a way to force full reconfig
 - 20974426 Disable changes to autosave made by 18746688
 - 20970759 ldomTable output shows 'Wrong Types' from LDoms 3.3 Integration 05
 - 20960651 Wholecore DRM continues in off state after migration from LDoms 3.2 to 3.3
 - 20957412 Assert failure in platsvc.c:domain_suspend_data_handler()
 - 20938662 ovmtcreate should not rely on ldoms package verification, but presence only
 - 20938619 Suspend attempts wait when a prior suspend is in progress
 - 20937100 ldm list-group should improve how the SPARC T7 motherboard is handled
 - 20927881 Whole core DRM policy goes to OFF state after live migration
 - 20927189 set-core command fails if existing number CPUs is not multiple of core-size
 - 20925389 Fatal in pri_get_cmis() if all strands in chip degraded
 - 20905098 Assertion fail during migration on OVM3.3
 - 20898641 Update move-core to be consistent with move-memory
 - 20891044 A panic/reboot during suspend leaves a guest 'suspending'
 - 20890579 Remove ovmtutils from ldoms-incorporation
 - 20888305 set-core in delayed reconfig allows exceeding max-cores limit - LDoms 3.3_b05
 - 20886229 'move-mem_sys_' should only be allowed on certain platforms
 - 20885337 Only attempt memory or core remap with compatible firmware
 - 20885286 Add debug command to allocate RKEY table memory
 - 20884770 Don't suspend a guest with physical IO if it is not supported
 - 20881247 Addition of VCPUs does not happen when weighted mean util > Util upper value
 - 20880305 Restore unlimited attack/decay
 - 20878254 Support Live Service on Fujitsu M10
 - 20868341 Min binding size for real memory should be 4MB not 256MB
 - 20868330 Binding real address should allow 4MB granularity instead of 256MB
 - 20868325 bind_real_status() returns incorrect offset if a mblock needs to be split
 - 20868319 PA range selected by best_suitable_mblks() may not be optimal
 - 20862729 Solaris expects nmblk=1 not 0 for requesting a memory map

- 20862661 Logical Domains Manager should retry failed mem allocation for multiple mblocks on the same LGPG
- 20854392 Support for Fujitsu socket constraints
- 20854350 Enhance Board DR memory processing
- 20854296 Fujitsu CPU autoreplacement should use CPU remapping
- 20849084 Unable to clear the vnet maxbw using XML interface
- 20848996 LDoms 3.1: vnet maxbw is sent in Mbps instead of bps
- 20826013 Recovery Mode: boot timeout handling needs improvement
- 20822568 set-vnet does not detect dup mac addrs between auto generated alt-mac-addrs
- 20811827 timed_read() in sptok_init_virtual_channel() doesn't timeout
- 20811467 LDoms deployment on zfs filesystem is taking too long to install
- 20799692 OVMT utilities: ovmtlibrary -c list -i 1 -o causes sqlite3 error: syntax error
- 20796786 MIB missing ldomVdsdevTable, ldomVnetTable, ldomVdiskTable from LDoms 3.2 b13
- 20772407 NPRD: ldm loses track of PFs, reporting not-found on ldm ls-io -l <PF> cmds
- 20765597 OVMT utilities: ovmtutils build cleanup
- 20765043 OVMT utilities: add the ovmtutils build generated files to .hgignore
- 20764954 OVMT utilities: remove xindent python code which is not written by Oracle
- 20752170 Assertion failed: ldp->rgrp_mem.ildom_sel_mblks != 0 in rgrp_mem_remove()
- 20742183 Build updates hg controlled file after 18714584
- 20738497 OVMT utilities: add fortify rules for ovmtutils java code
- 20704924 Mblocks should not be split if it is not supported by a guest
- 20704724 Defer retained memory API group check
- 20704064 A DR memory query hangs when sent to a hung domain
- 20694418 list-dependencies does not handle mpgroups correctly
- 20692005 mem_allocate_real assert hit during migrate.py
- 20690717 migrate.py cannot move memory because there is no suitable free memory
- 20688980 Ldom 3.1.1.2/M5-32/ldmd coredumps while doing a live migration
- 20687207 Releasing a resource that is not held should return success
- 20680100 Assertion failed in function debug_chk_mem_align_page()

-
- 20648386 Held resources do not persist across a restart
 - 20630625 `disable_self()` in `ldmd_include.sh` SMF helper function can drop S10 support
 - 20604908 `get_ldom_by_rc_name()` does not always return the correct root domain
 - 20586961 Problem with `mgmtldmgr/ldommgr-mgmt`
 - 20586857 `ldmd` dumps core at `complete_pending_evac_memory` subsequent to core fault
 - 20581427 Failed `ldm move-mem` may pass after `add-mem`
 - 20570207 Recovery Mode hangs primary domain if Elastic PM
 - 20540894 VHBA: `ldm ls -o san,hba` not implemented properly
 - 20537580 Parfait 1.6 detects some null pointer dereferences and memory leaks
 - 20532612 vHBA Logical Domains Manager integration
 - 20514062 Remove support for Logical Domains Manager on Oracle Solaris 10 primary domain
 - 20508772 Domains still suspended after failure in BDR sequence
 - 20506186 Failed suspended reconfig can lead to inconsistent HV MD
 - 20496285 Restore partial move failed to preserve PA LGPG
 - 20487202 Enable Recovery Mode by default
 - 20475338 Move memory failed to handle `free memory = 0`
 - 20458698 3.2 fix for 19513561 is incomplete
 - 20458388 `ovmtconfig` should supply timestamps in debug mode
 - 20457740 Logical Domains Manager should support enabling trusted mode for VNETs
 - 20432421 Fujitsu socket commands behave unexpectedly in delayed reconfiguration
 - 20427316 `vpci` port destroyed after `remove-io` from one `px`
 - 20426593 `ldm list-rsrc-group` incorrectly displays PCIE bus for `CMIOU10` under `CMIOU1`
 - 20416951 Disable generation of LDOMs audit records
 - 20399591 Migration bind should not split mblocks
 - 20395425 Update `LDM_RELEASE_NUM` in `Makefile.master`
 - 20373163 Assertion failed: `'tgt_num > 0'` in `core_remap_restore()`
 - 20372917 Logical Domains Manager should check DS channel state before suspending guests
 - 20372132 `cpu-arch=(migration-class1|generic)` should not include DAX in the MDs

- 20365522 SPARC T7 domain cannot migrate back after it is migrated to another system
- 20340446 ovmtcreate fails to read correct number of CPU assigned to guest domain dax1
- 20321459 Recovery fails when service domain missing virtual disk back end
- 20305752 Add memory using mblock option fails after memory evacuation
- 20305649 SPARC M7 After SP reset, Solaris does not reflect policy change in ILOM
- 20288350 mdprint.py should be able to print the PRI and save PRI/guest MD's
- 20257979 PF/VF stuck in INV state when in delayed reconf & ldomsmanager is restarted
- 20245881 ldmd dumps core at mem_unconfigure_range() when system memory is faulted
- 20245294 Impacted domain memory removal does not use MEMDR_MINSIZE
- 20244972 All mblocks in a large page must be remapped together
- 20232511 Unable to migrate vcpu resource state T41 to T42 ldoms3.1 / 8.7.0 build 23
- 20215998 move-memory should pass a board structure to subroutines
- 20215712 dr_mem get-map needs to handle timeout case
- 20207846 Memory DR add should break large requests at 16G RA boundary
- 20207824 Fatal error when res ids run out due to memory fragmentation
- 20199059 Logical Domains Manager frees an arg pointer twice in add memory failure path
- 20187335 Crash in SSL_write() returning from a resource group operation
- 20187197 CPUs are not resumed after power cap under the limit
- 20157499 Memory DR silently adds less memory than requested
- 20124236 ldmd should log HVMDs, error info after failing to reconfigure the HV
- 20095724 "channel-endpoint" is missing "back" arc to "channel-endpoints"
- 20047766 Warning: Attempt to reset hvmem@0xb700000:0x18900000 to 0x40000b700000:0x18900000
- 20035182 Enable move-core and move-memory commands for Live Service
- 20034433 "channel %s has been restored" message is misleading
- 20027321 mv-mem does not allow _sys_ to be moved
- 20011636 TestFailure Not all resource pmstates were lowered from the previous state of 1
- 20005608 list-group output should sort resource groups numerically
- 20003817 move-mem with -s option needs to be revisited

-
- 19976062 Panic, assertion failed, file: cpu_idle.c, line: 737
 - 19926799 move-mem should only do one suspend/resume
 - 19914686 Missing memory info from ldm list-group -a -l on T7-2 or T5-2
 - 19905790 DR DS requests can timeout when stalled by a CLI command
 - 19898359 Logical Domains Manager error sending SET_HEARTBEAT message: Invalid argument
 - 19887895 Broken link /var/opt/SUNWldm after installation from Unified Archive
 - 19883744 move-memory error handling needs to be cleaned up
 - 19880888 Logical Domains Manager unable to bring resources to initial power states on SPARC_T5-2
 - 19723743 Dynamic device specific property support
 - 19679858 ldm ls-constraints lose the configured hypervisor mpgroup function
 - 19430230 Non-existent resources should be ignored during evacuation
 - 19365876 IO Resource Group information is missing
 - 18714584 Support for ovmt_utilities
 - 18402532 Support SPARC M7 and SPARC T7 coprocessor interrupt bindings
 - 18168555 Evacuate and restore support for PCIe buses and SR-IOV cards
 - 18043073 set-core returns 0, but the domain is not whole-core constrained
 - 17834232 DRM support for whole-core constrained domains
 - 17563489 mem_add_in_sequencer() duplicates code in mem_add()
 - 16713362 Recovery Mode should support PCI slot removal in non-primary root domains
 - 15811513 ldm set-vcpu -c syntax should be deprecated
 - 15694181 Remove obsolete code and deprecate max-ipc

