



# Sun SPARC® Enterprise M4000/M5000 Servers Product Notes

---

For XCP Version 1080

Sun Microsystems, Inc.  
[www.sun.com](http://www.sun.com)

Part No. 820-6020-10  
November 2008, Revision A

Submit comments about this document at: <http://www.sun.com/hwdocs/feedback>

Copyright 2008 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, California 95054, U.S.A. and FUJITSU LIMITED, 1-1, Kamikodanaka 4-chome, Nakahara-ku, Kawasaki-shi, Kanagawa-ken 211-8588, Japan. All rights reserved.

Sun Microsystems, Inc. and Fujitsu Limited each own or control intellectual property rights relating to products and technology described in this document, and such products, technology and this document are protected by copyright laws, patents and other intellectual property laws and international treaties. The intellectual property rights of Sun Microsystems, Inc. and Fujitsu Limited in such products, technology and this document include, without limitation, one or more of the United States patents listed at <http://www.sun.com/patents> and one or more additional patents or patent applications in the United States or other countries.

This document and the product and technology to which it pertains are distributed under licenses restricting their use, copying, distribution, and decompilation. No part of such product or technology, or of this document, may be reproduced in any form by any means without prior written authorization of Fujitsu Limited and Sun Microsystems, Inc., and their applicable licensors, if any. The furnishing of this document to you does not give you any rights or licenses, express or implied, with respect to the product or technology to which it pertains, and this document does not contain or represent any commitment of any kind on the part of Fujitsu Limited or Sun Microsystems, Inc., or any affiliate of either of them.

This document and the product and technology described in this document may incorporate third-party intellectual property copyrighted by and/or licensed from suppliers to Fujitsu Limited and/or Sun Microsystems, Inc., including software and font technology.

Per the terms of the GPL or LGPL, a copy of the source code governed by the GPL or LGPL, as applicable, is available upon request by the End User. Please contact Fujitsu Limited or Sun Microsystems, Inc.

This distribution may include materials developed by third parties.

Parts of the product may be derived from Berkeley BSD systems, licensed from the University of California. UNIX is a registered trademark in the U.S. and in other countries, exclusively licensed through X/Open Company, Ltd.

Sun, Sun Microsystems, the Sun logo, Java, Netra, Solaris, Sun Ray, docs.sun.com, OpenBoot, and Sun Fire are trademarks or registered trademarks of Sun Microsystems, Inc., or its subsidiaries, in the U.S. and other countries.

Fujitsu and the Fujitsu logo are registered trademarks of Fujitsu Limited.

All SPARC trademarks are used under license and are registered trademarks of SPARC International, Inc. in the U.S. and other countries. Products bearing SPARC trademarks are based upon architecture developed by Sun Microsystems, Inc.

SPARC64 is a trademark of SPARC International, Inc., used under license by Fujitsu Microelectronics, Inc. and Fujitsu Limited.

The OPEN LOOK and Sun™ Graphical User Interface was developed by Sun Microsystems, Inc. for its users and licensees. Sun acknowledges the pioneering efforts of Xerox in researching and developing the concept of visual or graphical user interfaces for the computer industry. Sun holds a non-exclusive license from Xerox to the Xerox Graphical User Interface, which license also covers Sun's licensees who implement OPEN LOOK GUIs and otherwise comply with Sun's written license agreements.

United States Government Rights - Commercial use. U.S. Government users are subject to the standard government user license agreements of Sun Microsystems, Inc. and Fujitsu Limited and the applicable provisions of the FAR and its supplements.

Disclaimer: The only warranties granted by Fujitsu Limited, Sun Microsystems, Inc. or any affiliate of either of them in connection with this document or any product or technology described herein are those expressly set forth in the license agreement pursuant to which the product or technology is provided. EXCEPT AS EXPRESSLY SET FORTH IN SUCH AGREEMENT, FUJITSU LIMITED, SUN MICROSYSTEMS, INC. AND THEIR AFFILIATES MAKE NO REPRESENTATIONS OR WARRANTIES OF ANY KIND (EXPRESS OR IMPLIED) REGARDING SUCH PRODUCT OR TECHNOLOGY OR THIS DOCUMENT, WHICH ARE ALL PROVIDED AS IS, AND ALL EXPRESS OR IMPLIED CONDITIONS, REPRESENTATIONS AND WARRANTIES, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT, ARE DISCLAIMED, EXCEPT TO THE EXTENT THAT SUCH DISCLAIMERS ARE HELD TO BE LEGALLY INVALID. Unless otherwise expressly set forth in such agreement, to the extent allowed by applicable law, in no event shall Fujitsu Limited, Sun Microsystems, Inc. or any of their affiliates have any liability to any third party under any legal theory for any loss of revenues or profits, loss of use or data, or business interruptions, or for any indirect, special, incidental or consequential damages, even if advised of the possibility of such damages.

DOCUMENTATION IS PROVIDED "AS IS" AND ALL EXPRESS OR IMPLIED CONDITIONS, REPRESENTATIONS AND WARRANTIES, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT, ARE DISCLAIMED, EXCEPT TO THE EXTENT THAT SUCH DISCLAIMERS ARE HELD TO BE LEGALLY INVALID.



Adobe PostScript

Copyright 2008 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, California 95054, U.S.A. et FUJITSU LIMITED, 1-1, Kamikodanaka 4-chome, Nakahara-ku, Kawasaki-shi, Kanagawa-ken 211-8588, Japon. Tous droits réservés.

Entrée et revue tecnica fournies par Fujitsu Limited sur des parties de ce matériel.

Sun Microsystems, Inc. et Fujitsu Limited détiennent et contrôlent toutes deux des droits de propriété intellectuelle relatifs aux produits et technologies décrits dans ce document. De même, ces produits, technologies et ce document sont protégés par des lois sur le copyright, des brevets, d'autres lois sur la propriété intellectuelle et des traités internationaux. Les droits de propriété intellectuelle de Sun Microsystems, Inc. et Fujitsu Limited concernant ces produits, ces technologies et ce document comprennent, sans que cette liste soit exhaustive, un ou plusieurs des brevets déposés aux États-Unis et indiqués à l'adresse <http://www.sun.com/patents> de même qu'un ou plusieurs brevets ou applications brevetées supplémentaires aux États-Unis et dans d'autres pays.

Ce document, le produit et les technologies afférents sont exclusivement distribués avec des licences qui en restreignent l'utilisation, la copie, la distribution et la décompilation. Aucune partie de ce produit, de ces technologies ou de ce document ne peut être reproduite sous quelque forme que ce soit, par quelque moyen que ce soit, sans l'autorisation écrite préalable de Fujitsu Limited et de Sun Microsystems, Inc., et de leurs éventuels bailleurs de licence. Ce document, bien qu'il vous ait été fourni, ne vous confère aucun droit et aucune licence, expresses ou tacites, concernant le produit ou la technologie auxquels il se rapporte. Par ailleurs, il ne contient ni ne représente aucun engagement, de quelque type que ce soit, de la part de Fujitsu Limited ou de Sun Microsystems, Inc., ou des sociétés affiliées.

Ce document, et le produit et les technologies qu'il décrit, peuvent inclure des droits de propriété intellectuelle de parties tierces protégés par copyright et/ou cédés sous licence par des fournisseurs à Fujitsu Limited et/ou Sun Microsystems, Inc., y compris des logiciels et des technologies relatives aux polices de caractères.

Par limites du GPL ou du LGPL, une copie du code source régi par le GPL ou LGPL, comme applicable, est sur demande vers la fin utilisateur disponible; veuillez contacter Fujitsu Limited ou Sun Microsystems, Inc.

Cette distribution peut comprendre des composants développés par des tierces parties.

Des parties de ce produit pourront être dérivées des systèmes Berkeley BSD licenciés par l'Université de Californie. UNIX est une marque déposée aux États-Unis et dans d'autres pays et licenciée exclusivement par X/Open Company, Ltd.

Sun, Sun Microsystems, le logo Sun, Java, Netra, Solaris, Sun Ray, Answerbook2, docs.sun.com, OpenBoot, et Sun Fire sont des marques de fabrique ou des marques enregistrées de Sun Microsystems, Inc. ou ses filiales, aux États-Unis et dans d'autres pays.

Fujitsu et le logo Fujitsu sont des marques déposées de Fujitsu Limited.

Toutes les marques SPARC sont utilisées sous licence et sont des marques de fabrique ou des marques déposées de SPARC International, Inc. aux États-Unis et dans d'autres pays. Les produits portant les marques SPARC sont basés sur une architecture développée par Sun Microsystems, Inc.

SPARC64 est une marque déposée de SPARC International, Inc., utilisée sous le permis par Fujitsu Microelectronics, Inc. et Fujitsu Limited.

L'interface d'utilisation graphique OPEN LOOK et Sun™ a été développée par Sun Microsystems, Inc. pour ses utilisateurs et licenciés. Sun reconnaît les efforts de pionniers de Xerox pour la recherche et le développement du concept des interfaces d'utilisation visuelle ou graphique pour l'industrie de l'informatique. Sun détient une licence non exclusive de Xerox sur l'interface d'utilisation graphique Xerox, cette licence couvrant également les licenciés de Sun qui mettent en place l'interface d'utilisation graphique OPEN LOOK et qui, en outre, se conforment aux licences écrites de Sun.

Droits du gouvernement américain - logiciel commercial. Les utilisateurs du gouvernement américain sont soumis aux contrats de licence standard de Sun Microsystems, Inc. et de Fujitsu Limited ainsi qu'aux clauses applicables stipulées dans le FAR et ses suppléments.

Avis de non-responsabilité: les seules garanties octroyées par Fujitsu Limited, Sun Microsystems, Inc. ou toute société affiliée de l'une ou l'autre entité en rapport avec ce document ou tout produit ou toute technologie décrit(e) dans les présentes correspondent aux garanties expressément stipulées dans le contrat de licence régissant le produit ou la technologie fourni(e). SAUF MENTION CONTRAIRE EXPRESSEMENT STIPULÉE DANS CE CONTRAT, FUJITSU LIMITED, SUN MICROSYSTEMS, INC. ET LES SOCIÉTÉS AFFILIÉES REJETTENT TOUTE REPRÉSENTATION OU TOUTE GARANTIE, QUELLE QU'EN SOIT LA NATURE (EXPRESSE OU IMPLICITE) CONCERNANT CE PRODUIT, CETTE TECHNOLOGIE OU CE DOCUMENT, LESQUELS SONT FOURNIS EN L'ÉTAT. EN OUTRE, TOUTES LES CONDITIONS, REPRÉSENTATIONS ET GARANTIES EXPRESSES OU TACITES, Y COMPRIS NOTAMMENT TOUTE GARANTIE IMPLICITE RELATIVE À LA QUALITÉ MARCHANDE, À L'APTITUDE À UNE UTILISATION PARTICULIÈRE OU À L'ABSENCE DE CONTREFAÇON, SONT EXCLUES, DANS LA MESURE AUTORISÉE PAR LA LOI APPLICABLE. Sauf mention contraire expressément stipulée dans ce contrat, dans la mesure autorisée par la loi applicable, en aucun cas Fujitsu Limited, Sun Microsystems, Inc. ou l'une de leurs filiales ne sauraient être tenues responsables envers une quelconque partie tierce, sous quelque théorie juridique que ce soit, de tout manque à gagner ou de perte de profit, de problèmes d'utilisation ou de perte de données, ou d'interruptions d'activités, ou de tout dommage indirect, spécial, secondaire ou consécutif, même si ces entités ont été préalablement informées d'une telle éventualité.

LA DOCUMENTATION EST FOURNIE "EN L'ÉTAT" ET TOUTES AUTRES CONDITIONS, DECLARATIONS ET GARANTIES EXPRESSES OU TACITES SONT FORMELLEMENT EXCLUES, DANS LA MESURE AUTORISÉE PAR LA LOI APPLICABLE, Y COMPRIS NOTAMMENT TOUTE GARANTIE IMPLICITE RELATIVE A LA QUALITE MARCHANDE, A L'APTITUDE A UNE UTILISATION PARTICULIERE OU A L'ABSENCE DE CONTREFAÇON.



# Contents

---

## **Product Notes 1**

### **General Information About XCP 1080 3**

What's New in XCP 1080 3

Supported Firmware and Operating System 4

Solaris Patch Information 5

Patches for Solaris 10 10/08 5

Patches for Solaris 10 5/08 5

Patches for Solaris 10 8/07 6

Patches for Solaris 10 11/06 6

Patches for Emulex PCI Express (PCIe) Cards 7

Patches for QLogic PCIe Cards 7

Obtaining Solaris Patches 7

Using the Update Manager GUI to Obtain Patches 8

Using the `smpatch` CLI to Obtain Patches 9

Upgrading to XCP 1080 11

Resetting the XSCF Firmware 11

Updating the OpenBoot PROM Firmware 11

Updating From a Version Earlier Than XCP 1050 11

Updating From a Version Earlier Than XCP 1080 12

Functionality Issues and Limitations	12
Limitations for SPARC64 VII Processors	12
General Functionality Issues and Limitations	12
Additional Information and Procedures	14
Logging Into the System	14
Sun Crypto Accelerator 6000 Cards	15
U320 PCIe SCSI Card	15
Sun Java Enterprise Server	15
XSCF Web Browser Issues	16
Booting From a WAN Boot Server	16
Identifying System Memory	17
▼ Identifying Degraded Memory in a System	17
▼ Using the <code>showdevices</code> Command to Identify Memory Size	17
▼ Using the <code>prtdiag</code> Command to Identify Memory Size	18
▼ Identifying Permanent Memory in a Target Board	19
CPU Upgrade (Service Representatives Only)	20
SPARC64 VII CPU Modules Added to a New Domain	20
SPARC64 VII Processors Added to an Existing Domain	23
▼ Preparing to Add SPARC64 VII Processors to an Existing Domain	24
▼ Adding a SPARC64 VII CPU Module to a Domain Configured With SPARC64 VI	26
▼ Upgrading a SPARC64 VI CPU Module to SPARC64 VII on an Existing Domain	27
<b>Information About Software</b>	<b>29</b>
XCP Issues and Workarounds	29
Solaris OS Issues and Workarounds	31
Solaris Issues for All Supported Releases	31
Solaris Issues Fixed in Solaris 10 10/08	36
Solaris Issues Fixed in Solaris 10 5/08	38

Solaris Issues Fixed in Solaris 10 8/07	42
Documentation Updates	46





# Product Notes

---

These product notes contain important and late-breaking information about the Sun SPARC® Enterprise M4000/M5000 servers hardware, software, and documentation.

---

## Software Resources

The Solaris™ Operating System and Sun Java™ Enterprise System software are preinstalled on your Sun SPARC Enterprise M4000/M5000.

## Latest Solaris Patches

Mandatory Solaris patches for the SPARC Enterprise M4000/M5000 servers should be preinstalled on your system. See “[Solaris Patch Information](#)” on page 5 for the list of patches required on your version of the Solaris OS.

## Additional Information

For additional information, see the release notes for the version of the Solaris OS that you are using, as well as the Big Admin web site:

<http://www.bigadmin.com>



# General Information About XCP 1080

---

This section includes the following sections:

- “What’s New in XCP 1080” on page 3
- “Supported Firmware and Operating System” on page 4
- “Solaris Patch Information” on page 5
- “Obtaining Solaris Patches” on page 7
- “Upgrading to XCP 1080” on page 11
- “Functionality Issues and Limitations” on page 12
- “Additional Information and Procedures” on page 14

---

## What’s New in XCP 1080

In XCP Version 1080, the following new XSCF commands are supported:

- `dumpconfig(8)`
- `ping(8)`
- `restoreconfig(8)`
- `traceroute(8)`

For detail, see the *Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF Reference Manual* or the manual pages for each command.

---

# Supported Firmware and Operating System

**TABLE 1** lists the firmware and operating system (OS) versions that are supported in this release.

**TABLE 1** Firmware and Operating System Versions

Software or Firmware	Version
XSCF Control Package	1080
SPARC64™ VII processors:	XCP 1071
Capacity on Demand (COD) support:	XCP 1050
Solaris Operating System	
SPARC64 VI processors:	Solaris 10 11/06 or later, with required patches
SPARC64 VII processors:	Solaris 10 8/07 or later, with required patches*

\* See “[Solaris Patch Information](#)” on page 5 for information about patches. Check <http://sunsolve.sun.com> for the latest patch revision

---

**Note** – You cannot boot a domain mounted with the SPARC64 VII processors using the Solaris 10 8/07 installation DVD. Use the Solaris 10 5/08 installation DVD to boot a domain mounted with the SPARC64 VII processors.

---

Many web browsers support the XSCF Web. The browsers in [TABLE 2](#) have demonstrated compatibility with the XSCF Web through testing.

**TABLE 2** Tested Web Browser Versions

Web Browser Application	Version
Firefox	2.0 and 3.0
Microsoft Internet Explorer	6.0 and 7.0

---

# Solaris Patch Information

This section lists mandatory patches for the M4000/M5000 servers.

Always refer to the patch README for information about patch requirements and special installation instructions.

The patch identifiers listed in this section represent the *minimum* level of the patches that must be installed. The two-digit suffix represents the minimum revision level of the patch.

Check <http://sunsolve.sun.com> for the latest patch revision.

Apply patches in the order listed. For the procedures of CPU upgrade including the patches, see “[CPU Upgrade \(Service Representatives Only\)](#)” on page 20.

For additional Solaris OS information see “[Solaris OS Issues and Workarounds](#)” on page 31.

## Patches for Solaris 10 10/08

Patches are not required for servers running Solaris 10 10/08 OS or later.

## Patches for Solaris 10 5/08

The following patch is required for all M4000/M5000 servers running Solaris 10 5/08:

- 137137-09

Solaris 10 5/08 OS might panic/trap during normal domain operation (CR 6720261). To prevent this you must set the following parameter in the system specification file (`/etc/system`):

```
set heaplp_use_stlb=0
```

Then reboot the domain.

## Patches for Solaris 10 8/07

The following patches are required for Solaris 10 8/07 OS only on servers containing SPARC64 VII CPUs. Install them in the order in which they are listed:

1. 119254-51 - SunOS 5.10: Install and Patch Utilities Patch
2. 125891-01 - SunOS 5.10: libc\_psr\_hwcap.so.1 patch
3. 127755-01 - SunOS 5.10: Fault Manager patch
4. 127127-11 - SunOS 5.10: kernel patch

Solaris 10 8/07 OS with patch 127127-11 might panic/trap during normal domain operation (CR 6720261). To prevent this you must set the following parameter in the system specification file (`/etc/system`):

```
set heaplp_use_stlb=0
```

Then reboot the domain.

## Patches for Solaris 10 11/06

The following patches are required for Solaris 10 11/06 OS. Note that Solaris 10 11/06 does *not* support SPARC64 VII processors, even with these required patches. Install the patches in the order in which they are listed:

1. 118833-36 – Reboot your domain before proceeding.
2. 125100-10 – See the patch README file for a list of other patch requirements.
3. 123839-07
4. 120068-03
5. 125424-01
6. 118918-24
7. 120222-21
8. 125127-01 – Reboot your domain before proceeding.
9. 125670-02
10. 125166-05

## Patches for Emulex PCI Express (PCIe) Cards

The following Emulex cards require drivers supplied in patch 120222-26:

- Sun StorageTek™ Enterprise Class 4-gigabit Dual-Port Fibre Channel PCIe HBA (part SG-XPCIE2FC-EM4)
- Sun StorageTek Enterprise Class 4-gigabit Single-Port Fibre Channel PCIe HBA (part SG-XPCIE1FC-EM4)

## Patches for QLogic PCIe Cards

The following QLogic cards require drivers supplied in patch 125166-10:

- Sun StorageTek Enterprise Class 4-gigabit Dual-Port Fibre Channel PCIe HBA (part SG-XPCIE2FC-QF4)
- Sun StorageTek Enterprise Class 4-gigabit Single-Port Fibre Channel PCIe HBA (part SG-XPCIE1FC-QF4)

---

## Obtaining Solaris Patches

The Sun<sup>SM</sup> Connection Update Manager can be used to reinstall the patches if necessary or to update the system with the latest set of mandatory patches. For more information about the Sun Connection Update Manager, refer to the *Sun Update Connection System Administration Guide* at:

<http://docs.sun.com/app/docs/prod/updconn.sys>

Or visit:

<http://wikis.sun.com/display/SunConnection/Update+Manager>

There are two options available to register your system and to use the Sun Connection Update Manager to obtain the latest Solaris OS patches:

- [“Using the Update Manager GUI to Obtain Patches” on page 8](#)
- [“Using the smpatch CLI to Obtain Patches” on page 9](#)

Installation information and README files are included in the patch downloads.



---

**Caution** – For Sun SPARC Enterprise M4000/M5000 servers running Solaris 10 11/06 OS, patches 123003-03 and 124171-06 must be installed on your system prior to using Sun Connection Update Manager. These patches can be downloaded from <http://sunsolve.sun.com/> if needed. These patches are not required for servers running later versions of Solaris 10 OS.

---

## Using the Update Manager GUI to Obtain Patches

### 1. As root, launch the Update Manager from either of the following:

- From JDS Launch menu:  
Click **Launch->Applications->System Tools->Update Manager**
- From a terminal window:  
Type `/usr/bin/updatemanager`

### 2. Complete the registration.

- If you have already registered, proceed to [Step 3](#).
- If you have not yet registered, the Update Manager interface guides you through the registration process. Follow the onscreen instructions.

---

**Note** – If you are unable to complete registration using the Sun Connection Update Manager GUI, use the command-line interface (CLI) option to obtain patches. See [“Using the `smpatch` CLI to Obtain Patches” on page 9](#).

---

### 3. In the Available tab in the Update Manager, open the Update Collection dropdown menu and select Sun SPARC Enterprise M4000/M5000/M8000/M9000 Servers.

Update Manager analyzes your system for any patches that are needed.

### 4. If a kernel patch is recommended, select it by clicking the box to the left of the patch ID, then click the Install button.

The patch is downloaded to `/var/sadm/spool`.

---

**Note** – Kernel patches (such as patch 118833-xx, for example) require special instructions for installation (see the patch README for specifics). They are often download-only (interactive) patches, requiring manual installation. You must install kernel patches before any others in order for any remaining patches in the patch set to be installed.

---



5. For a kernel patch, continue by typing:

```
# cd /var/sadm/spool
# unzip patchid-xx.jar
```

6. Follow the installation instructions in the file

`/var/sadm/spool/patchid-xx/README.patchid-xx`.

7. After installing `patchid-xx`, restart the system with the `shutdown` command.

Using the `reboot` command does not complete installations of patches that require a restart. You must use the Update Manager or the `shutdown` command.

```
# shutdown -i6
```

8. Launch the Update Manager again, and select the collection, as in [Step 3](#).

9. If the Update Manager does not automatically start a new analysis, click the Check for Updates button.

10. Select any patches that are listed by checking the boxes to the left of the patch IDs.

11. Click the Install button.

Update Manager downloads and installs the patches.

12. If any of the patches require a system restart, follow the instructions in [Step 7](#).

If any patches are installed that require restart, Update Manager offers to restart the system. Alternatively, you can use the `shutdown` command, as described in [Step 7](#). For patches that require restart, you must perform the restart in order for the installation to take effect.

The patch installation is now complete.

## Using the `smpatch` CLI to Obtain Patches

1. Copy the file `/usr/lib/breg/data/RegistrationProfile.properties` to your `/tmp` directory.

2. Edit the file `/tmp/RegistrationProfile.properties` to add your user name, password, network proxy (if necessary), and port (if required).

---

**Note** – The user name and password is a Sun Online Account. To create an account, go to <http://sunsolve.sun.com>.

---

### 3. Register your system.

```
# sconadm register -a -r /tmp/RegistrationProfile.properties
```

### 4. Obtain the correct patches.

```
# smpatch set patchpro.patchset=sem4k5k8k9k
```

### 5. Install any kernel patches.

Kernel patches, such as 118833-xx, can be downloaded through the Sun Connection Update Manager.

#### a. Download the patch to your `/var/sadm/spool` directory.

```
# smpatch update -i patchid-xx
```

#### b. Unzip the patch.

```
# cd /var/sadm/spool  
# unzip patchid-xx.jar
```

#### c. Install the patch by following the installation instructions in the file: `/var/sadm/spool/patchid-xx/README.patchid-xx`.

### 6. Restart the system

Using the `reboot` command does not complete installation of patches that require a restart. You must use the Update Manager or the `shutdown` command.

```
# shutdown -i6
```

### 7. Display a list of patches.

```
# smpatch analyse
```

### 8. Download and install the patches.

```
# smpatch update
```

9. If any of the patches requires a system restart, see [Step 6](#).

If any patches are installed that require restart, Update Manager offers to restart the system. Alternatively, you can use the `shutdown` command, as described in [Step 6](#). For patches that require restart, you must perform the restart in order for the installation to take effect.

The patch installation is now complete.

---

## Upgrading to XCP 1080

You can upgrade to XCP 1080 from XCP version 1050 or higher. Refer to the *Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF User's Guide* for instructions.

## Resetting the XSCF Firmware

After updating the XCP firmware to 1080 or later use the `rebootxscf(8)` command to reset the XSCF.

## Updating the OpenBoot PROM Firmware

To complete updating the OpenBoot™ PROM (OBP) firmware in the target domain, be sure to restart the domain. You should restart the domain as soon as possible after completing the update.

## Updating From a Version Earlier Than XCP 1050

- You cannot directly update to XCP 1080 or later. If you are currently running a version earlier than XCP 1050, you must first update to an interim version of XCP (between 1050 and 1061 inclusive) before updating to XCP 1080 or later. Refer to the product notes document for the interim version for instructions.
- Use the `deleteuser(8)` command to delete any accounts named `admin` prior to updating to XCP 1050 or later. The `admin` account name is reserved in XCP 1050 and higher.

# Updating From a Version Earlier Than XCP 1080

On a domain that has been in operation during the XCP update to XCP 1080 or later, when you perform dynamic reconfiguration (DR) to add or replace the SPARC64 VII processors, you need to update the OpenBoot PROM firmware. The OpenBoot PROM firmware is updated as you update the XCP and restart the domain. For this reason, restart all the domains after you update the firmware to XCP 1080 or later, regardless of whether you added or replaced the SPARC64 VII processors.

---

## Functionality Issues and Limitations

This section describes known issues in this release.

### Limitations for SPARC64 VII Processors



---

**Caution** – You must complete the upgrades to the XCP firmware and to the Solaris OS before inserting SPARC 64 VII processors into the chassis.

---

### General Functionality Issues and Limitations



---

**Caution** – For dynamic reconfiguration (DR) and hot-plug issues, see [“Solaris OS Issues and Workarounds”](#) on page 31.

---

---

**Note** – For power-on after power-off, wait at least 30 seconds before turning the system power back on, by using the main line switch or the circuit breakers on the distribution panel.

---

- You cannot use the following user account names, as they are reserved for system use: `root`, `bin`, `daemon`, `adm`, `operator`, `nobody`, `sshd`, `rpc`, `rpcuser`, `ldap`, `apache`, `ntp`, `admin`, and `default`.

- Do not use the Service Processor (SP) as the Network Time Protocol (NTP) server. Using an independent NTP server provides optimal reliability in maintaining consistent time on the SP and the domains. For more information about NTP, see the Sun BluePrints™ document, *Using NTP to Control and Synchronize System Clocks*: <http://www.sun.com/blueprints/0701/NTP.pdf>
- When you use the external power control interface of the external power controller, the following notification signals are not supported:
  - The OS panic or the server hardware error signal (\*CPUN/RTNU)
  - The server hardware error signal (power fail, temperature error, and fan error) (\*ALARM)
- When you import XCP or update the firmware using the XSCF you might see Web session ID errors displayed on the web browser. When you specify the timeout period as over 30 minutes in the Autologout setting Internal Server Errors might be displayed. To reconnect to the XSCF Web, close the current browser and open the new browser.
- For this XCP release, the XSCF browser user interface (XSCF Web) does not support the External I/O Expansion Unit Manager feature.
- Disable pop-up blocking and remove any plug-ins such as the search tool installed with the browser when you use the XSCF Web.
- To use XSCF Web, disable the cache function of your browser. If you leave the browser cache function enabled, the old cached data might be displayed. To disable the cache function:
  - Internet Explorer 6 & 7  
Tools->Internet Options...->Advanced tab and check the "Do not save encrypted pages to disk" box.
  - Firefox 2 & 3  
Type about:config in the address box, and then type cache in filter box.  
Change the Browser.Cache.Check.Doc.Frequency settings value to 1.
- XSCF-LAN is compliant with autonegotiation. Set the network device which connects with XSCF-LAN to the autonegotiation mode. Otherwise when you connect the XSCF-LAN and the network device (fixed to the full-duplex mode, according to the IEEE 802.3 rule) the XSCF-LAN communicates in half-duplex mode and network communication speed might slow down or communication errors occur.
- Domains using the ZFS file system cannot use dynamic reconfiguration (DR).
- The M4000/M5000 servers are cold service machines. Hot-swapping of the CPU module (CPUM), memory board (MEMB), I/O unit (IOU), or XSCF unit is not supported.
- For 1027A-Z/X1027A-Z, PCIe Dual 10-Gigabit Ethernet Fiber XFP cards, these limits apply:
  - Do not use more than two cards per domain.

- Do not use these cards in an External I/O Expansion Unit.
  - For 4447A-Z/X4447A-Z, PCIe Quad-port Gigabit Ethernet Adapter UTP cards, these maximum limits apply:
    - No more than four cards in an External I/O Expansion Unit (two per PCIe I/O boat).
    - No more than four cards in a M4000 server domain.
    - No more than eight cards in a M5000 server domain.
  - Do not use the CD-RW/DVD-RW drive unit and the TAPE drive unit at the same time.
  - The use of the External I/O Expansion Unit to connect the host server to an external boot disk drive is not supported.
  - DR is not compatible with XSCF failover or XSCF reset. Do not start an XSCF failover or reset while a DR operation is running. Wait for a DR operation to finish before starting the failover or reset. If you start the failover or reset first, wait for the failover or reset to finish before starting the DR operation.
- 

## Additional Information and Procedures

This section describes additional known issues and limitations at the time of this release.

### Logging Into the System

In addition to the standard *default* login, the servers is delivered with a temporary login called `admin` to enable remote initial login, through a serial port. The server's privileges are fixed to `useradm` and cannot be changed. You cannot log in as temporary `admin` using the standard UNIX user name and password authentication or SSH public key authentication. The temporary `admin` account has no password, and one cannot be added for it.

The temporary `admin` account is disabled after someone logs in as the default user, or after someone logged in as temporary `admin` has successfully added the first user with valid password and privileges.

If, before the default login is used, you cannot log in as temporary `admin`, you can determine if someone else has done so by executing the `showuser -l` command.

## Sun Crypto Accelerator 6000 Cards

If you are not using the correct version of the Sun Crypto Accelerator (SCA) 6000 card driver, hot-plug operations on SCA 6000 cards can cause M4000/M5000 servers to panic or hang. Version 1.1 of the SCA6000 driver and firmware supports hot-plug operations after the required bootstrap firmware upgrade has been performed. Version 1.0 of the SCA6000 driver does not support hot-plug and should not be used.

## U320 PCIe SCSI Card

U320 PCIe SCSI card, part numbers 375-3357-01/02, is not supported in PCI cassettes for Sun SPARC Enterprise M4000/M5000 servers. Customers must use 375-3357-03 or later.

## Sun Java Enterprise Server

The Sun Java Enterprise Server is a comprehensive set of software and life cycle services that make the most of your software investment. For an overview and documentation, go to:

<http://www.sun.com/service/javaes/index.xml>

---

**Note** – Due to an issue that arises from the installation of the Java Enterprise System 5 Update 1 on your system (CR 6644798), it might be necessary to enable the Web Console SMF service.

---

### ▼ Enabling the Web Console SMF Service

- **Log in to a terminal as `root`, then enable the service.**

```
# svcadm enable svc:/system/webconsole:console
```

If you have to reload the software, go to the following web site for download and installation instructions:

<http://www.sun.com/software/preinstall>

If you download a fresh copy of software, that software might not include patches that are mandatory for your server. After installing the software, refer to “Solaris

[Patch Information](#) on page 5 for information about checking for and installing required patches.

## XSCF Web Browser Issues

The XSCF Web browser interface occasionally truncates output. For example when you select SSH on the snapshot screen, the maximum number of character input for Host, Directory, ID, and Password does not correspond to the maximum number of character input on the XSCF Shell. The Panic Log page only displays the last 50 lines of the panic message (CR 6756052). The browser interface displays only the last two digits of the non-audit log size limit (CR 6742502).

To see the full output use the XSCF Shell command-line interface (CLI).

## Booting From a WAN Boot Server

The WAN boot installation method enables you to boot and install software over a wide area network (WAN) by using HTTP. To support booting the M4000/M5000 servers from a WAN boot server, you must have the appropriate `wanboot` executable installed and OpenBoot™ version 4.24 or above to provide the needed hardware support.

For information about WAN boot servers, refer to the *Solaris 10 Installation Guide: Network-Based Installations* for the version of Solaris 10 OS that you are using. You can find Solaris 10 OS documentation here:

<http://docs.sun.com/app/docs/prod/solaris.10>

If you do not upgrade the `wanboot` executable, the M3000 server will panic, with messages similar to the following:

```
krtld: load_exec: fail to expand cpu/$CPU
krtld: error during initial load/link phase
panic - boot: exitto64 returned from client program
```



# Identifying System Memory

## ▼ Identifying Degraded Memory in a System

- Log in to XSCF and show the system status.

```
XSCF> showstatus
```

The following example identifies DIMM number 0A on Memory Board #5 has degraded memory.

```
XSCF> showstatus
      MBU_B Status:Normal;
      MEMB#5 Status:Normal;
*     MEM#0A Status:Degraded;
```

## ▼ Using the showdevices Command to Identify Memory Size

- Log in to XSCF and show the devices.

```
XSCF> showdevices -d domain_id
```

The following example shows a display of the showdevices -d command, where 0 is the *domain\_id*.

```
XSCF> showdevices -d 0

...

Memory:
-----

```

DID	XSB	board mem MB	perm mem MB	base address	domain mem MB	target XSB	deleted mem MB	remaining mem MB
00	00-0	65536	2402	0x0000000000000000	131072			
00	01-0	16384	0	0x000003c000000000	131072			
00	01-1	16384	0	0x0000038000000000	131072			
00	01-2	16384	0	0x0000034000000000	131072			
00	01-3	16384	0	0x0000030000000000	131072			

```
...
```

This example shows that 00-0 has 64 Gbytes of memory, while the other system boards have 16 Gbytes.

## ▼ Using the prtdiag Command to Identify Memory Size

- In the domain, display system diagnosis information.

```
# prtdiag
```

The following example shows a display of the prtdiag command.

```
# prtdiag
...
===== Memory Configuration =====
Memory   Available      Memory   DIMM   # of  Mirror Interleave
LSB      Group    Size      Status  Size  DIMMs Mode Factor
-----  -
00      A        32768MB  okay    2048MB  16 no    8-way
00      B        32768MB  okay    2048MB  16 no    8-way
01      A        8192MB   okay    2048MB  4 no    2-way
01      B        8192MB   okay    2048MB  4 no    2-way
02      A        8192MB   okay    2048MB  4 no    2-way
02      B        8192MB   okay    2048MB  4 no    2-way
03      A        8192MB   okay    2048MB  4 no    2-way
03      B        8192MB   okay    2048MB  4 no    2-way
04      A        8192MB   okay    2048MB  4 no    2-way
04      B        8192MB   okay    2048MB  4 no    2-way
...

```

This example displays varying memory sizes.

## ▼ Identifying Permanent Memory in a Target Board

- Log in to XSCF and show the devices.

```
XSCF> showdevices -d domain_id
```

The following example shows a display of the `showdevices -d` command, where 0 is the `domain_id`.

```
XSCF> showdevices -d 0

...

Memory:
-----

  board      perm      base      domain  target  deleted  remaining
DID XSB  mem MB  mem MB  address  mem MB  XSB   mem MB  mem MB
00 00-0   65536   2402   0x0000000000000000  131072
00 01-0   16384     0   0x000003c000000000  131072
00 01-1   16384     0   0x0000038000000000  131072
00 01-2   16384     0   0x0000034000000000  131072
00 01-3   16384     0   0x0000030000000000  131072

...
```

The entry for column 4, `perm mem MB`, indicates the presence of permanent memory if the value is not zero.

The example shows permanent memory on 00-0, with 2402 Mbytes.

If the board includes permanent memory, when you execute the `deleteboard` command or the `moveboard` command, the following notice is displayed:

```
System may be temporarily suspended, proceed? [y|n]:
```

# CPU Upgrade (Service Representatives Only)

---

**Note** – You must be an authorized service representative to install SPARC64 VII processors in your server.

---

This section describes procedures for installing SPARC64 VII processors in SPARC Enterprise M4000/M5000 servers:

- [“SPARC64 VII CPU Modules Added to a New Domain” on page 20](#)
- [“SPARC64 VII Processors Added to an Existing Domain” on page 23](#)

---

**Note** – Before upgrading firmware to XCP 1071, refer to [“Upgrading to XCP 1080” on page 11](#).

---



---

**Caution** – You must complete the upgrades to the XCP firmware and to Solaris before inserting SPARC 64 VII processors into the chassis.

---

For more information about configuring combinations of processors in domains, refer to Section 2.2.13, “Domain Mode Configuration,” in the *Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF User’s Guide*. In particular, see the section “SPARC64 VI and SPARC64 VII Processors and CPU Operational Modes.”

## SPARC64 VII CPU Modules Added to a New Domain

### ▼ Adding a SPARC64 VII CPU Module to a New Domain

---

**Note** – If you want to install Solaris 10 8/07 on the new domain, you must install from a patched image on the installation server. (See [Step 20](#).)

---

1. **Log in to the XSCF using an account with `platadm` privileges.**
2. **Confirm that no FRU is currently listed in `Faulted` or `Deconfigured` status.**

```
XSCF> showstatus
```

3. Turn off the power to all domains.

```
XSCF> poweroff -a
```

4. Confirm that all domains have stopped.

```
XSCF> showlogs power
```

5. Change the key position on the operator panel from Locked to Service.

6. Collect an XSCF snapshot to archive system status prior to upgrade.

If a problem should occur during the upgrade procedure, a snapshot of the system status might be helpful.

```
XSCF> snapshot -t user@host:directory
```

7. Update the XCP version to 1080.

Before updating firmware to XCP 1080, refer to [“Upgrading to XCP 1080” on page 11](#). For instructions for updating the firmware, refer to the *Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF User’s Guide*.

8. Install the CPU module (CPUM) in the server.

For instructions, refer to Chapter 12, “CPU Module Replacement,” in the *Sun SPARC Enterprise M4000/M5000 Servers Service Manual*. Note that this procedure involves powering down the entire server.



---

**Caution** – After installing the CPU module, you must reconnect the power cable to the power supply.

---

9. Log in to the XSCF again, using an account with `platadm` or `fieldeng` privileges.

10. Perform an initial diagnosis of the newly installed CPU module.

```
XSCF> testsb 01
```

The following example shows a test after adding PSB#01 to a SPARC Enterprise M5000 server:

```
XSCF> testsb 01
Initial diagnosis is about to start. Continue? [y|n] : y
Initial diagnosis is executing.
Initial diagnosis has completed.
XSB Test Fault
-----
01 Passed Normal
```

11. Confirm that the installed CPU module is recognized by the server and that the error indicator asterisk (\*) is not displayed.

```
XSCF> showhardconf -M
```

12. Confirm that no abnormality has occurred.

```
XSCF> showlogs error -v
XSCF> showstatus
```

13. Change the key position on the operator panel from Service to Locked.

14. Power on the existing domains.

```
XSCF> poweron -a
```

15. Set the following for the added CPU module:

- Set up XSB for the added CPU module.
- Set up the domain.
- Set up the CPU operational mode on the domain.

Refer to Chapter 2, "Setting Up XSCF," in the *Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF User's Guide* for information about these settings.

16. Use the `setdomainmode(8)` command to disable the autoboot function of the domain.

Refer to the *Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF User's Guide* and the `setdomainmode(8)` man page for more information.

17. Power on the new domain.

```
XSCF> poweron -d domain_id
```

**18. Confirm that the target domain has been correctly started.**

```
XSCF> showlogs power
```

**19. Confirm that no abnormality has occurred.**

```
XSCF> showlogs error -v
XSCF> showstatus
```

**20. Install a version of Solaris OS that supports SPARC64 VII processors.**

Refer to [“Supported Firmware and Operating System” on page 4](#) for information about supported software versions.

If you are installing Solaris 10 8/07 on the new domain, you must install from a patched image on the installation server. For information about patches, refer to [“Solaris Patch Information” on page 5](#). For information about network-based installations, refer to *Solaris 10 8/07 Installation Guide: Network-Based Installations* (part 820-0177).

**21. Use the `setdomainmode(8)` command to enable the autoboot function of the domain.**

The autoboot function is applied by a domain reboot. For more information, refer to the *Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF User’s Guide* and the `setdomainmode(8)` man page.

## SPARC64 VII Processors Added to an Existing Domain

Adding SPARC64 VII Processors to an existing domain is a two step process. First you must prepare the system (see [“Preparing to Add SPARC64 VII Processors to an Existing Domain” on page 24](#)) and then you must install the Processors using the instructions that correspond to your installation scenario.

- [“Adding a SPARC64 VII CPU Module to a Domain Configured With SPARC64 VI” on page 26.](#)
- [“Upgrading a SPARC64 VI CPU Module to SPARC64 VII on an Existing Domain” on page 27](#)

## ▼ Preparing to Add SPARC64 VII Processors to an Existing Domain

1. If necessary, upgrade to a version of Solaris OS that supports SPARC64 VII processors.

Refer to [“Supported Firmware and Operating System” on page 4](#) for information about supported software versions. Apply any required patches.

2. Log in to the XSCF using an account with `platadm` privileges.
3. Confirm that no FRU is currently listed in `Faulted` or `Deconfigured` status.

```
XSCF> showstatus
```

4. Turn off the power for all the domains.

```
XSCF> poweroff -a
```

5. Confirm that the power is off for the domains.

```
XSCF> showlogs power
```

6. Change the key position on the operator panel from `Locked` to `Service`.
7. Collect an XSCF snapshot to archive system status prior to upgrade.

If a problem should occur during the upgrade procedure, a snapshot of the system status might be helpful.

```
XSCF> snapshot -t user@host:directory
```

8. Update the XCP version to 1080.

Before updating firmware to XCP 1080, refer to [“Upgrading to XCP 1080” on page 11](#). For instructions for updating the firmware, refer to the *Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF User’s Guide*.

9. Log in to the XSCF again, using an account with `platadm` or `fieldeng` privileges.
10. Power on all the domains, and apply OpenBoot PROM firmware.

```
XSCF> poweron -a
```

The `ok` prompt is displayed. You do not need to start the Solaris OS.



## 11. Check the updated OpenBoot PROM version.

```
XSCF> version -c cmu -v
```

For XCP 1080, the version of OpenBoot PROM is 02.07.0000. Your output should look similar to the following:

```
XSCF> version -c cmu -v  
DomainID 0: 02.07.0000  
DomainID 1: 02.07.0000  
DomainID 2: 02.07.0000  
DomainID 3: 02.07.0000  
XSB#00-0: 02.07.0000 (Current)      02.03.0000 (Reserve)  
XSB#00-1: 02.07.0000 (Current)      02.03.0000 (Reserve)  
XSB#00-2: 02.07.0000 (Current)      02.03.0000 (Reserve)  
XSB#00-3: 02.07.0000 (Current)      02.03.0000 (Reserve)  
XSB#01-0: 02.07.0000 (Current)      02.03.0000 (Reserve)  
XSB#01-1: 02.07.0000 (Current)      02.03.0000 (Reserve)  
XSB#01-2: 02.07.0000 (Current)      02.03.0000 (Reserve)  
XSB#01-3: 02.07.0000 (Current)      02.03.0000 (Reserve)  
...
```

## 12. Turn off the power to all the domains.

```
XSCF> poweroff -a
```

## 13. Continue with the appropriate installation procedure:

- If you are adding a new SPARC64 VII-equipped CPU module to a domain configured with SPARC64 VI processors, continue with [“Adding a SPARC64 VII CPU Module to a Domain Configured With SPARC64 VI”](#) on page 26.
- If you are upgrading an existing SPARC64 VI CPU module in an existing domain to SPARC64 VII processors, continue with [“Upgrading a SPARC64 VI CPU Module to SPARC64 VII on an Existing Domain”](#) on page 27.

## ▼ Adding a SPARC64 VII CPU Module to a Domain Configured With SPARC64 VI

This procedure must be preceded by [“Preparing to Add SPARC64 VII Processors to an Existing Domain” on page 24](#). If you have not completed that procedure, do so before continuing.

### 1. Install the CPUM in the server.

For instructions, refer to the “CPU Module Replacement,” chapter in the *Sun SPARC Enterprise M4000/M5000 Servers Service Manual*. Note that this procedure involves powering down the entire server.



---

**Caution** – After installing the CPU module, you must reconnect the power cable to the power supply.

---

### 2. Log in to the XSCF again, using an account with `platadm` or `fieldeng` privileges.

Perform an initial diagnosis of the newly installed CPU module.

```
XSCF> testsb 01
```

The following example shows a test after adding PSB#01:

```
XSCF> testsb 01
Initial diagnosis is about to start. Continue? [y|n] : y
Initial diagnosis is executing.
Initial diagnosis has completed.
XSB Test Fault
-----
01 Passed Normal
```

### 3. Confirm that the installed CPU module is recognized by the server and that the error indicator asterisk (\*) is not displayed.

```
XSCF> showhardconf -M
```

### 4. Confirm that no abnormality has occurred.

```
XSCF> showlogs error -v
XSCF> showstatus
```

### 5. Change the key position on the operator panel from Service to Locked.

6. Set the following for the CPU module:

- Set up XSB.
- Set up the LSB.
- Add the XSB to the domain.
- Set up the CPU operational mode on the domain.

Refer to Chapter 2, “Setting Up XSCF,” in the *Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF User’s Guide* for information about these settings.

7. Power on all the domains.

```
XSCF> poweron -a
```

8. Confirm that all the domains have been correctly started.

```
XSCF> showlogs power
```

9. Confirm that no abnormality has occurred.

```
XSCF> showlogs error -v  
XSCF> showstatus
```

## ▼ Upgrading a SPARC64 VI CPU Module to SPARC64 VII on an Existing Domain

This procedure must be preceded by [“Preparing to Add SPARC64 VII Processors to an Existing Domain” on page 24](#). If you have not completed that procedure please do so before continuing.

1. Replace the SPARC64 VI CPU module with the SPARC64 VII CPU module.

For instructions, refer to Chapter 12, “CPU Module Replacement,” in the *Sun SPARC Enterprise M4000/M5000 Servers Service Manual*. Note that this procedure involves powering down the entire server.



---

**Caution** – After installing the CPU module, you must reconnect the power cable to the power supply.

---

2. Log in to the XSCF again, using an account with `platadm` or `fieldeng` privileges.

3. Perform an initial diagnosis of the newly installed CPU module.

```
XSCF> testsb 01
```

The following example shows a test after adding PSB#01 to a SPARC Enterprise M5000 server:

```
XSCF> testsb 01  
Initial diagnosis is about to start. Continue? [y|n] : y  
Initial diagnosis is executing.  
Initial diagnosis has completed.  
XSB Test Fault  
-----  
01 Passed Normal
```

4. Confirm that the installed CPU module is recognized by the server and that the error indicator asterisk (\*) is not displayed.

```
XSCF> showhardconf -M
```

5. Confirm that no abnormality has occurred.

```
XSCF> showlogs error -v  
XSCF> showstatus
```

6. Change the key position on the operator panel from Service to Locked.

7. Set up and confirm the CPU operational mode of the domain.

For more information, refer to Chapter 2, "Setting Up XSCF," in the *Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF User's Guide*.

8. Power on all the domains.

```
XSCF> poweron -a
```

9. Confirm that the target domain has been correctly started.

```
XSCF> showlogs power
```

10. Confirm that no abnormality has occurred.

```
XSCF> showlogs error -v  
XSCF> showstatus
```

# Information About Software

---

This section includes the following sections:

- “XCP Issues and Workarounds” on page 29
- “Solaris OS Issues and Workarounds” on page 31
- “Documentation Updates” on page 46

This section describes specific software and firmware issues and workarounds. To obtain patches and to check for availability of new patches that fix these issues, go to:

<http://sunsolve.sun.com>

---

## XCP Issues and Workarounds

TABLE 3 lists XCP issues and possible workarounds.

**TABLE 3** XCP Issues and Workarounds (1 of 3)

ID	Description	Workaround
6714765	The <code>setsnmp(8)</code> and <code>showsnmp(8)</code> commands do not notify the user of authorization failure.	There is no workaround. Confirm that the SNMP trap host is working and re-execute the command using the correct user name.
6723305	The XSCF Web does not show the correct daylight saving time.	There is no workaround. Use the <code>showlogs(8)</code> command to determine time during daylight savings time.
6726679	SNMP trap is not sent after XSCF watchdog time out. This occurs intermittently. SNMP traps will not be notified after the watchdog timeout occurs in XSCF and XSCF reset.	Reset the XSCF.
6735711	<code>setemailreport(8)</code> command cannot handle recipient email addresses that are longer than 255 characters	Use email address with fewer than 255 characters

---

**TABLE 3** XCP Issues and Workarounds (2 of 3)

ID	Description	Workaround
6741770	SNMP trap host configuration changes are not valid until <code>setsnmp disable</code> and <code>setsnmp enable</code> .	When you have modified the SNMP setting: XSCF> <code>setsnmp disable</code> XSCF> <code>setsnmp enable</code>
6742502	The browser interface displays only the last two digits of the non-audit log size limit.	Do not set Archive Log limit to '0'. Use the <code>showarchiving(8)</code> command to determine log size limit.
6742951	The <code>setlogarchiving(8)</code> command accepts '-1' for the Audit log limit and then sets the limit as "Unlimited".	No workaround is available
6743842	The <code>password</code> command indicates that the <code>[user]</code> operand is optional but will fail if a <code>[user]</code> operand is not included when other options are specified.	No workaround is available.  Specify the <code>[user]</code> operand to use the <code>password</code> command when you specify other options.
6744772	Logs will not be archived when <code>logarchiving</code> limits are exceeded, and there is no warning message to indicate that logs are no longer being archived.	Periodically, run the <code>showarchiving(8)</code> command and adjust limits as needed.  Or, as the used log archiving space approaches the defined limit manually rotate the existing logs on the log archiving host.
6755113	XSCF panic might occur during <code>flashupdate(8)</code> .	Use the <code>flashupdate(8)</code> command again.
6755986	In Internet Explorer 6 or 7, clicking on the [Reset] button then the [OK] button from the Settings->Audit->Add Policy pop-up screen will log the user out with message: Error Session Error Session ID has been expired	Log back into the browser interface and use the backspace key to clear text in the 'User' text box of the popup screen instead of using the Reset button.
6756052	The panic log on the XSCF Web might not be displayed from the top of the message.	When the output is insufficient, execute the <code>showlogs panic</code> command on the XSCF shell.
6757064	Firmware update might fail with "XSCF FMEM write error".	Power off (AC OFF) the system, and power on (AC ON) again. Then, re-execute the firmware update.
6757614	The network configuration on the XSCF Web does not support the function equivalent to the <code>setnetwork -r</code> option. And when you specified localhost or localdomain to the host name or the domain name, the error message "SessionID has expired" appears	Use the <code>setnetwork -r</code> command on the XSCF shell.

**TABLE 3** XCP Issues and Workarounds (3 of 3)

ID	Description	Workaround
6765468	When the timezone value is not three characters, the error logs cannot be displayed on the XSCF Web “Error Log” page. In addition, XSCF Web “Panic Log” and “IPPL Message Log” pages display the date on the table with “---”.	Use the <code>showlogs(8)</code> command on the XSCF shell.

---

## Solaris OS Issues and Workarounds

This section contains information about Solaris OS issues. [TABLE 4](#), [TABLE 5](#), [TABLE 6](#), and [TABLE 7](#) list issues you might encounter, depending upon which Solaris OS release you are using.

### Solaris Issues for All Supported Releases

[TABLE 4](#) lists Solaris OS issues that you might encounter in any supported release of Solaris OS.

**TABLE 4** Solaris OS Issues and Workarounds for All Supported Releases (1 of 4)

CR ID	Description	Workaround
6459540	The DAT72 internal tape drive might time out during tape operations. The device might also be identified by the system as a QIC drive.	Add the following definition to /kernel/drv/st.conf:  <pre>tape-config-list= "SEAGATE DAT DAT72-000", "SEAGATE_DAT DAT72-000", "SEAGATE_DAT DAT72-000"; SEAGATE_DAT DAT72-000= 1,0x34,0,0x9639,4,0x00,0x8c,0x8c, 0x8c,3;</pre> There are four spaces between SEAGATE DAT and DAT72-000.
6522017	Domains using the ZFS file system cannot use DR.	Set the maximum size of the ZFS ARC lower. For detailed assistance, contact your authorized service representative.
6531036	The error message network initialization failed appears repeatedly after a boot net installation.	There is no workaround.
6531668	System hangs when executing parallel hot-plug operation with SP DR in suspend phase.	There is no workaround.
6532215	volfs or dscpl services might fail when a domain is booted.	Restart the service. To avoid the problem, issue the following commands. <pre># svccfg -s dscpl setprop start/timeout_seconds=count: 300 # svccfg -s volfs setprop start/timeout_seconds=count: 300 # svcadm refresh dscpl # svcadm refresh volfs</pre>
6565553 6674266	DR deleteboard(8) and moveboard(8) operations might fail. Example for messages on domain: <pre>drmach: WARNING: Device driver failure: /pci dcs: &lt;xxxx&gt; config_change_state: Hardware specific failure: unconfigure SB1: Device driver failure: /pci</pre>	There is no workaround. Try DR operations again.



**TABLE 4** Solaris OS Issues and Workarounds for All Supported Releases (2 of 4)

CR ID	Description	Workaround
6572827	The <code>prtdiag -v</code> command reports PCI bus types incorrectly. It reports "PCI" for PCI-X leaf devices and "UNKN" for legacy PCI devices.	There is no workaround.
6575970	DR and XSCF failover are not compatible.	
6588555	Resetting the XSCF during a DR operation on permanent memory might cause domain panic.	Do not start an XSCF reset while a DR operation is underway. Wait for the DR operation to complete before starting the reset.
6592302	Unsuccessful DR operation leaves memory partially configured.	It might be possible to recover by adding the board back to the domain with an <code>addboard -d</code> command.
6619344	The Sun Crypto Accelerator (SCA) 6000 card might not work if hot-plug configured into slot 1.	To avoid the defect, do not hot-plug this card in slot 1.
6623226	The Solaris command <code>lockstat(1M)</code> or the <code>dtrace lockstat</code> provider might cause a system panic.	Do not use the Solaris <code>lockstat(1M)</code> command or the <code>dtrace lockstat</code> provider.
6625734	Systems with large number of processors in a single domain environment may have suboptimal performance with certain workloads.	Use processor sets to bind application processes or LWPs to groups of processors. Refer to the <code>psrset(1M)</code> man page for more information.
6660168	If a <code>ubc.piowbeue-cpu</code> error occurs on a domain, the Solaris Fault Management <code>cpumem-diagnosis</code> module might fail, causing an interruption in FMA service. If this happens, you will see output similar to the following sample in the console log:	If <code>fmd</code> service fails, issue the following command on the domain to recover: # <code>svcadm clear fmd</code> Then restart <code>cpumem-diagnosis</code> : # <code>fmadm restart cpumem-diagnosis</code>

**TABLE 4** Solaris OS Issues and Workarounds for All Supported Releases (3 of 4)

CR ID	Description	Workaround
	<p>SUNW-MSG-ID: FMD-8000-2K, TYPE: Defect, VER: 1, SEVERITY: Minor  EVENT-TIME: Fri Apr 4 21:41:57 PDT 2008  PLATFORM: SUNW,SPARC-Enterprise, CSN: 2020642002, HOSTNAME: &lt;hostname&gt;  SOURCE: fmd-self-diagnosis, REV: 1.0  EVENT-ID: 6b2e15d7-aa65-6bcc-bcb1-cb03a7dd77e3  DESC: A Solaris Fault Manager component has experienced an error that required the module to be disabled. Refer to <a href="http://sun.com/msg/FMD-8000-2K">http://sun.com/msg/FMD-8000-2K</a> for more information.  AUTO-RESPONSE: The module has been disabled. Events destined for the module will be saved for manual diagnosis.  IMPACT: Automated diagnosis and response for subsequent events associated with this module will not occur.  REC-ACTION: Use <code>fmdump -v -u &lt;EVENT-ID&gt;</code> to locate the module. Use <code>fmadm reset &lt;module&gt;</code> to reset the module.</p>	
6668237	After DIMMs are replaced, the corresponding DIMM faults are not cleared on the domain.	Use the <code>fmadm repair <i>fmri uuid</i> Suzie</code> to record the repair. Then use the <code>fmadm rotate</code> command to clear out any leftover events.
6679370	<p>The following message may be output on the console during the system booting, the External I/O Expansion Unit adding by hotplug, or the FMEMA operating by DR.  SUNW-MSG-ID: SUN4-8000-75, TYPE: Fault, VER: 1, SEVERITY: Critical  ...  DESC:  A problem was detected in the PCIEExpress subsystem.  Refer to <a href="http://sun.com/msg/SUN4-8000-75">http://sun.com/msg/SUN4-8000-75</a> for more information.  ...</p>	<p>Add the following to <code>/etc/system</code> and then reboot the domain.  <code>set pcie_expected_ce_mask = 0x2001</code></p>

**TABLE 4** Solaris OS Issues and Workarounds for All Supported Releases (4 of 4)

CR ID	Description	Workaround
6680733	Sun Quad-port Gigabit Ethernet Adapter UTP (QGC) & Sun Dual 10 GigE Fiber XFP Low Profile Adapter (XGF) NICs might panic under high load conditions.	Check for the availability of a patch for this defect.
6689757	Sun Dual 10 GigE Fiber XFP Low Profile Adapter (XGF) with a single or improperly installed XFP optical transceivers might cause the following error to show on the console: The XFP optical transceiver is broken or missing.	Check and make sure that both XFP optical transceivers are firmly seated in the housing. Do not mix INTEL and Sun XFP optical transceivers in the same Adapter. Do NOT plumb a port with the <code>ifconfig</code> command if the port does not contain an XFP optical transceiver or it contains one but the transceiver is not in use.
6745410	Boot program ignores the <code>kadb</code> option which causes the system not to boot.	Use <code>kmdb</code> instead of <code>kadb</code> .

# Solaris Issues Fixed in Solaris 10 10/08

TABLE 5 lists issues that have been fixed in Solaris 10 10/08 OS. You might encounter them in supported releases earlier than Solaris 10 10/08.

**TABLE 5** Solaris OS Issues and Workarounds Fixed in Solaris 10 10/08 (1 of 2)

CR ID	Description	Workaround
6511374	Memory translation warning messages might appear during boot if memory banks were disabled due to excessive errors.	After the system is rebooted, the <code>fmadm repair</code> command can be used to prevent a recurrence of the problem on the next boot.
6533686	When XSCF is low on system resources, DR <code>deleteboard</code> or <code>moveboard</code> operations that relocate permanent memory might fail with one or more of these errors: <code>SCF busy</code> <code>DR parallel copy timeout</code> This applies only to Quad-XSB configured System Boards hosting multiple domains.	This has been fixed in patch 138397-01.  Retry the DR operation at a later time.
6556742	The system panics when DiskSuite cannot read the <code>metaadb</code> during DR. This bug affects the following cards: <ul style="list-style-type: none"> <li>• SG-XPCIE2FC-QF4, 4Gb PCI-e Dual-Port Fibre Channel HBA</li> <li>• SG-XPCIE1FC-QF4, 4Gb PCI-e Single-Port Fibre Channel HBA</li> <li>• SG-XPCI2FC-QF4, 4Gb PCI-X Dual-Port Fibre Channel HBA</li> <li>• SG-XPCI1FC-QF4, 4Gb PCI-X Single-Port Fibre Channel HBA</li> </ul>	Panic can be avoided when a duplicated copy of the <code>metaadb</code> is accessible via another Host Bus Adaptor.
6589833	The DR <code>addboard</code> command might cause a system hang if you are adding a Sun StorageTek Enterprise Class 4Gb Dual-Port Fibre Channel PCI-E HBA card (SG-XPCIE2FC-QF4) at the same time that an SAP process is attempting to access storage devices attached to this card. The chance of a system hang is increased if the following cards are used for heavy network traffic: <ul style="list-style-type: none"> <li>• X4447A-Z, PCI-e Quad-port Gigabit Ethernet Adapter UTP</li> <li>• X1027A-Z1, PCI-e Dual 10 Gigabit Ethernet Fiber XFP Low profile Adapter</li> </ul>	There is no workaround.
6608404	Hot-plug of the X4447A-Z, PCI-e Quad-port Gigabit Ethernet Adapter UTP card in slot 1 might cause other network devices to fail.	To avoid the defect, do not install this card in slot 1.

**TABLE 5** Solaris OS Issues and Workarounds Fixed in Solaris 10 10/08 (2 of 2)

CR ID	Description	Workaround
6614737	<p>The DR <code>deleteboard(8)</code> and <code>moveboard(8)</code> operations might hang if any of the following conditions exist:</p> <ul style="list-style-type: none"> <li>A DIMM has been degraded.</li> <li>The domain contains system boards with different memory size.</li> </ul>	<p>For Solaris 10 5/08 or earlier, this has been fixed in patch 137111-01.</p> <p>Avoid performing DR operations if any of the following conditions exist:</p> <ul style="list-style-type: none"> <li>• <i>Degraded memory</i> – To determine whether the system contains degraded memory, use the XSCF command <code>showstatus</code>. For sample output see <a href="#">“Identifying System Memory” on page 17</a>.</li> <li>• <i>Differing memory sizes</i> – To determine whether the domain contains system boards with different memory sizes, display the list of memory sizes using the XSCF command <code>showdevices</code> or the <code>prtdiag</code> command on the domain. For sample output, see <a href="#">“Identifying System Memory” on page 17</a>.</li> </ul> <p>If a DR command hangs, reboot the domain to recover.</p>
6632549	<p><code>cmd</code> service on domain might fail to maintenance mode after DR operations.</p>	<p>This has been fixed in patch 138050-01.</p> <p>Issue the following command on the domain:</p> <pre># svcadm clear cmd</pre>
6660197	<p>DR might cause the domain to hang if either of the following conditions exist:</p> <ul style="list-style-type: none"> <li>• A domain contains 256 or more CPUs.</li> <li>• Memory error occurred and the DIMM has been degraded.</li> </ul>	<p>This has been fixed in patch 138397-01.</p> <ol style="list-style-type: none"> <li>1. Set the following parameter in the system specification file (<code>/etc/system</code>):  <pre>set drmach:drmach_disable_mcopy = 1</pre> </li> <li>2. Reboot the domain.</li> </ol>
6663570	<p>DR operations involving the lowest number CPU might cause the domain to panic.</p>	<p>Do not use DR to remove the system board that hosts the CPU with the lowest CPU ID. Use the Solaris <code>prtdiag</code> command to identify the CPU with the lowest CPU ID.</p>
6718173	<p>If your domain is running one of the following versions of Solaris OS, the system might panic/trap during normal operation:</p> <ul style="list-style-type: none"> <li>• Solaris 10 5/08 OS</li> <li>• An earlier version of Solaris 10 OS with patch ID 127127-11</li> </ul>	<p>Set the following parameter in the system specification file (<code>/etc/system</code>):  <pre>set heaplp_use_stlb=0</pre> Then reboot the domain.</p>

# Solaris Issues Fixed in Solaris 10 5/08

TABLE 6 lists issues that have been fixed in Solaris 10 5/08 OS. You might encounter them in supported releases earlier than Solaris 10 5/08.

**TABLE 6** Solaris OS Issues and Workarounds Fixed in Solaris 10 5/08 (1 of 4)

CR ID	Description	Workaround
6348554	Using the <code>cfgadm -c disconnect</code> command on the following cards might hang the command: <ul style="list-style-type: none"> <li>• SG-XPCIE2FC-QF4 Sun StorageTek Enterprise Class 4Gb Dual-Port Fibre Channel PCI-E HBA</li> <li>• SG-XPCIE1FC-QF4 Sun StorageTek Enterprise Class 4Gb Single-Port Fibre Channel PCI-E HBA</li> <li>• SG-XPCI2FC-QF4 Sun StorageTek Enterprise Class 4Gb Dual-Port Fibre Channel PCI-X HBA</li> <li>• SG-XPCI1FC-QF4 Sun StorageTek Enterprise Class 4Gb Single-Port Fibre Channel PCI-X HBA</li> </ul>	Do not perform <code>cfgadm -c disconnect</code> operation on the affected cards.
6472153	If you create a Solaris Flash archive on a non-Sun SPARC Enterprise M4000/M5000 sun4u server and install it on a Sun SPARC Enterprise M4000/M5000 sun4u server, the console's TTY flags will not be set correctly. This can cause the console to lose characters during stress.	For Solaris 10 8/07 or earlier, this has been fixed in patch 137046-01.  Just after installing Solaris OS from a Solaris Flash archive, telnet into the Sun SPARC Enterprise M4000/M5000 server to reset the console's TTY flags as follows: <pre># sttydefs -r console # sttydefs -a console -i "9600 hupcl opost onlcr crtscts" -f "9600"</pre> This procedure is required only once.
6522433	The incorrect motherboard might be identified by <code>fmddump</code> for cpu faults after reboot.	For Solaris 10 8/07 or earlier, this has been fixed in patch 127127-11.  Check system status on XSCF.
6527811	The <code>showhardconf(8)</code> command on the XSCF cannot display PCI card information that is installed in the External I/O Expansion Unit, if the External I/O Expansion Unit is configured using PCI hot-plug.	For Solaris 10 8/07 or earlier, this has been fixed in patch 128346-01.  There is no workaround. When each PCI card in the External I/O Expansion Unit is configured using PCI hot-plug, the PCI card information is displayed correctly.

**TABLE 6** Solaris OS Issues and Workarounds Fixed in Solaris 10 5/08 (2 of 4)

CR ID	Description	Workaround
6536564	showlogs(8) and showstatus(8) command might report wrong I/O component.	<p>For Solaris 10 8/07 or earlier, this has been fixed in patch 125369-05.</p> <p>To avoid this problem, issue the following commands on the domain.</p> <pre># cd /usr/platform/SUNW,SPARCEnterprise/ lib/fm/topo/plugins # mv ioboard.so ioboard.so.orig # svcadm restart fmd</pre> <p>Contact a service engineer if the following messages are displayed:  SUNW-MSG-ID: SUNOS-8000-1L, TYPE: Defect, VER: 1, SEVERITY: Minor  EVENT-TIME: Sun May 6 18:22:24 PDT 2007  PLATFORM: SUNW,SPARC-Enterprise,  CSN: BE80601007, HOSTNAME: sparc</p>
6545143	There is a low probability that a system panic can occur during trap processing of a TLB miss for a user stack address. The problem can occur if the user stack is unmapped concurrently with the user process executing a flush windows trap (ta 3). The panic message will contain the following string: bad kernel MMU trap at TL 2	<p>For Solaris 10 8/07 or earlier, this has been fixed in patch 127111-08.</p> <p>There is no workaround.</p>
6545685	If the system has detected Correctable MemoryErrors (CE) at power-on self-test (POST), the domains might incorrectly degrade 4 or 8 DIMMs.	<p>For Solaris 10 8/07 or earlier, this has been fixed in patch 127111-08.</p> <p>Increase the memory patrol timeout values used via the following setting in /etc/system and reboot the system:</p> <pre>set mc-opl:mc_max_rewrite_loop = 20000</pre>
6546188	<p>The system panics when running hot-plug (cfgadm) and DR operations (addboard and deleteboard) on the following cards:</p> <ul style="list-style-type: none"> <li>• X4447A-Z, PCI-e Quad-port Gigabit Ethernet Adapter UTP</li> <li>• X1027A-Z1, PCI-e Dual 10 Gigabit Ethernet Fiber XFP Low profile Adapter</li> </ul>	<p>For Solaris 10 8/07, this has been fixed in patch 127741-01.</p> <p>There is no workaround.</p>

**TABLE 6** Solaris OS Issues and Workarounds Fixed in Solaris 10 5/08 (3 of 4)

CR ID	Description	Workaround
6551356	<p>The system panics when running hot-plug (<code>cfgadm</code>) to configure a previously unconfigured card. The message “WARNING: PCI Expansion ROM is not accessible” will be seen on the console shortly before the system panic. The following cards are affected by this defect:</p> <ul style="list-style-type: none"> <li>• X4447A-Z, PCI-e Quad-port Gigabit Ethernet Adapter UTP</li> <li>• X1027A-Z1, PCI-e Dual 10 Gigabit Ethernet Fiber XFP Low profile Adapter</li> </ul>	<p>For Solaris 10 8/07, this has been fixed in patch 127741-01.</p> <p><b>Note</b> - Do not use <code>cfgadm -c unconfigure</code> to disconnect the I/O card.</p> <p>Use <code>cfgadm -c disconnect</code> to completely remove the card. After waiting at least 10 seconds, the card might be configured back into the domain using the <code>cfgadm -c configure</code> command.</p>
6559504	<p>Messages of the form <code>nxge: NOTICE: nxge_ipp_eccue_valid_check: rd_ptr = nnn wr_ptr = nnn</code> will be observed on the console with the following cards:</p> <ul style="list-style-type: none"> <li>• X4447A-Z, PCI-e Quad-port Gigabit Ethernet Adapter UTP</li> <li>• X1027A-Z1, PCI-e Dual 10 Gigabit Ethernet Fiber XFP Low profile Adapter</li> </ul>	<p>These messages can be safely ignored.</p>
6563785	<p>Hot-plug operation with the following cards might fail if a card is disconnected and then immediately reconnected:</p> <ul style="list-style-type: none"> <li>• SG-XPCIE2SCSIU320Z Sun StorageTek PCI-E Dual-Port Ultra320 SCSI HBA</li> <li>• SGXPCI2SCSILM320-Z Sun StorageTek PCI Dual-Port Ultra320 SCSI HBA</li> </ul>	<p>After disconnecting a card, wait for a few seconds before re-connecting.</p>
6564934	<p>Performing a DR <code>deleteboard</code> operation on a board which includes Permanent Memory when using the following network cards results in broken connections:</p> <ul style="list-style-type: none"> <li>• X4447A-Z, PCI-e Quad-port Gigabit Ethernet Adapter UTP</li> <li>• X1027A-Z1, PCI-e Dual 10 Gigabit Ethernet Fiber XFP Low profile Adapter</li> </ul>	<p>For Solaris 10 8/07, this has been fixed in patch 127741-01.</p> <p>Reconfigure the affected network interfaces after the completion of the DR operation. For basic network configuration procedures, refer to the <code>ifconfig</code> man page for more information.</p>
6568417	<p>After a successful CPU DR <code>deleteboard</code> operation, the system panics when the following network interfaces are in use:</p> <ul style="list-style-type: none"> <li>• X4447A-Z, PCI-e Quad-port Gigabit Ethernet Adapter UTP</li> <li>• X1027A-Z1, PCI-e Dual 10 Gigabit Ethernet Fiber XFP Low profile Adapter</li> </ul>	<p>For Solaris 10 8/07 or earlier, this has been fixed in patch 127111-02.</p> <p>Add the following line to <code>/etc/system</code> and reboot the system:</p> <pre>set ip:ip_soft_rings_cnt=0</pre>



**TABLE 6** Solaris OS Issues and Workarounds Fixed in Solaris 10 5/08 (4 of 4)

CR ID	Description	Workaround
6571370	Use of the following cards have been observed to cause data corruption in stress test under laboratory conditions: <ul style="list-style-type: none"><li>• X4447A-Z, PCI-e Quad-port Gigabit Ethernet Adapter UTP</li><li>• X1027A-Z1, PCI-e Dual 10 Gigabit Ethernet Fiber XFP Low profile Adapter</li></ul>	For Solaris 10 8/07, this has been fixed in patch 127741-01.  Add the following line in <code>/etc/system</code> and reboot the system: <code>set nxge:nxge_rx_threshold_hi=0</code>
6589546	<code>prtdiag</code> does not show all IO devices of the following cards: <ul style="list-style-type: none"><li>• SG-XPCIE2FC-EM4 Sun StorageTek Enterprise Class 4Gb Dual-Port Fibre Channel PCI-E HBA</li><li>• SG-XPCIE1FC-EM4 Sun StorageTek Enterprise Class 4Gb Single-Port Fibre Channel PCI-E HBA</li></ul>	For Solaris 10 8/07 or earlier, this has been fixed in patch 127127-11.  Use <code>prtdiag -v</code> for full output.
6663570	DR operations involving the lowest number CPU might cause the domain to panic.	Do not use DR to remove the system board that hosts the CPU with the lowest CPU ID. Use the Solaris <code>prtdiag</code> command to identify the CPU with the lowest CPU ID.

## Solaris Issues Fixed in Solaris 10 8/07

TABLE 7 lists issues that have been fixed in Solaris 10 8/07 OS. You might encounter them in Solaris 10 11/06.



---

**Caution** – ICR ID #6534471: Improper handling of large page in kernel memory may cause random panics. Implement the workaround for CR ID #6534471 or check for the availability of a patch and install it immediately. This bug has been fixed by 125100-06 and Solaris 10 8/07.

---

**TABLE 7** Solaris OS Issues and Workarounds Fixed in Solaris 10 8/07 (1 of 4)

CR ID	Description	Workaround
6416224	System performance can degrade using a single NIC card with more than 5,000 connections.	For Solaris 10 11/06, this has been fixed in patch 120011-08.  Use multiple NIC cards to split network connections.
6441349	I/O error can hang the system.	For Solaris 10 11/06, this has been fixed in patch 120011-07.  There is no workaround.
6485555	On-board Gigabit Ethernet NVRAM corruption could occur due to a race condition. The window of opportunity for this race condition is very small.	For Solaris 10 11/06, this has been fixed in patch 120011-08.  There is no workaround.

**TABLE 7** Solaris OS Issues and Workarounds Fixed in Solaris 10 8/07 (2 of 4)

CR ID	Description	Workaround
6496337	<p>The “cpumem-diagnosis” module may fail to load after uncorrectable error(UE) panic. Systems will function correctly but events normally automatically diagnosed by FMA using this module will require manual diagnosis.</p> <p>Example:  SUNW-MSG-ID: FMD-8000-2K, TYPE: Defect, VER: 1, SEVERITY: Minor  EVENT-TIME: Thu Feb 15 15:46:57 JST 2007  PLATFORM: SUNW,SPARC-Enterprise,  CSN: BE80601007, HOSTNAME: col2-ffem7-d0</p>	<p>For Solaris 10 11/06, this has been fixed in patch 125369-05.</p> <p>If the problem has already occurred:  workaround:  1. Remove the cpumemdiagnosis file.  <pre># rm /var/fm/fmd/ckpt/cpumemdiagnosis/cpumem-diagnosis</pre> 2. Restart fmd service.  <pre># svcadm restart fmd</pre> <p>To avoid this problem in advance, add “rm -f /var/fm/fmd/ckpt/cpumemdiagnosis/cpumem-diagnosis” in the /lib/svc/method/svc-dumpadm file as below.  <pre># savedev=none rm -f /var/fm/fmd/ckpt/cpumemdiagnosis/cpumem-diagnosis #</pre> </p> </p>
6495303	<p>The use of a PCIe Dual-Port Ultra320 SCSI controller card (SG-(X)PCIE2SCSIU320Z) in IOU Slot 1 on a Sun SPARC Enterprise M4000/M5000 server might result in a system panic.</p>	<p>Do not use this card in IOU Slot 1.</p>
6499304	<p>Unexpected message is displayed on console and CPU isn’t offlined when numerous correctable error(CE) occur.</p> <p>Example:  SUNW-MSG-ID: FMD-8000-11, TYPE: Defect, VER: 1, SEVERITY: Minor  EVENT-TIME: Fri Feb 2 18:31:07 JST 2007  PLATFORM: SPARC-Enterprise, CSN: BE80601035, HOSTNAME: FF2-35-0</p>	<p>For Solaris 10 11/06, this has been fixed in patch 125369-05.</p> <p>Check CPU status on XSCF.</p>

**TABLE 7** Solaris OS Issues and Workarounds Fixed in Solaris 10 8/07 (3 of 4)

CR ID	Description	Workaround
6502204	<p>Unexpected error messages may be displayed on console on booting after CPU UE panic.</p> <p>Example:  SUNW-MSG-ID: FMD-8000-11, TYPE: Defect, VER: 1, SEVERITY: Minor  EVENT-TIME: Tue Jan 9 20:45:08 JST 2007  PLATFORM: SUNW,SPARC-Enterprise, CSN: 2030636002, HOSTNAME: P2-DC1-16-d0</p>	<p>For Solaris 10 11/06, this has been fixed in patch 125369-05.</p> <p>If you see unexpected messages, use the <code>showdomainstatus(8)</code> command to check system status on XSCF.</p>
6502750	<p>Inserted or removed hotplugged PCI card may not output notification message.</p>	<p>For Solaris 10 11/06, this has been fixed in patch 120011-08.</p> <p>There is no workaround.</p>
6508432	<p>A large number of spurious PCIe correctable errors can be recorded in the FMA error log.</p>	<p>For Solaris 10 11/06, this has been fixed in patch 120011-08.</p> <p>To mask these errors, add the following entry to <code>/etc/system</code> and reboot the system:  <pre>set pcie:pcie_aer_ce_mask = 0x2001</pre></p>
6508434	<p>The domain may panic when an additional PCI-X card is installed or a PCI-X card is replaced using PCI hot-plug.</p>	<p>For Solaris 10 11/06, this has been fixed in patch 120011-08.</p> <p>Do not insert a different type of PCI-X card on the same PCI slot by using PCI hot-plug.</p>
6510861	<p>When using the PCIe Dual-Port Ultra320 SCSI controller card (SG-(X)PCIE2SCSIU320Z), a PCIe correctable error causes a Solaris panic.</p>	<p>For Solaris 10 11/06, this has been fixed in patch 120011-08.</p> <p>Add the following entry to <code>/etc/system</code> to prevent the problem:  <pre>set pcie:pcie_aer_ce_mask = 0x31c1</pre></p>
6520990	<p>When a domain reboots, SCF might not be able to service other domains that share the same physical board. DR operation can exceed the default timeout period and panic can occur.</p>	<p>Increase the DR timeout period by setting the following statement in <code>/etc/system</code> and reboot your system.:</p> <pre>set drmach:fmem_timeout = 30</pre>
6530178	<p>DR <code>addboard</code> command can hang. Once the problem is observed, further DR operations are blocked. Recovery requires reboot of the domain.</p>	<p>For Solaris 10 11/06, this has been fixed in patch 120011-07.</p> <p>There is no workaround.</p>

**TABLE 7** Solaris OS Issues and Workarounds Fixed in Solaris 10 8/07 (4 of 4)

CR ID	Description	Workaround
6530288	<code>cfgadm(1M)</code> command may not correctly show <code>Ap_Id</code> format.	For Solaris 10 11/06, this has been fixed in patch 120011-07.  There is no workaround.
6534471	Systems might panic/trap during normal operation.	This bug has been fixed in Solaris 10 8/07. Check for the availability of a patch for this bug.  If a patch is not available, disable the kernel large page sTLB programming. In the file <code>/etc/system</code> , change the <code>heaplp_use_stlb</code> variable to 0: <code>set heaplp_use_stlb=0</code>
6535564	PCI hot-plug to PCI slot #0, #1 or External I/O Expansion Unit may fail on XSB added by DR.	For Solaris 10 11/06, this has been fixed in patch 120011-08.  Use DR instead of PCI hot plug if need to add or remove PCI card on the XSB.
6539084	There is a low probability of a domain panic during reboot when the Sun Quad GbE UTP x8 PCIe (X4447A-Z) card is present in a domain.	A fix is available in patch 125670-01.
6539909	Do not use the following I/O cards for network access when you are using the <code>boot net install</code> command to install the Solaris OS: <ul style="list-style-type: none"> <li>• X4447A-Z/X4447A-Z, PCIe Quad-port Gigabit Ethernet Adapter UTP</li> <li>• X1027A-Z/X1027A-Z, PCIe Dual 10 Gigabit Ethernet Fiber XFP</li> </ul>	Use an alternative type of network card or onboard network device to install the Solaris OS via the network.
6542632	Memory leak in PCIe module if driver attach fails.	For Solaris 10 11/06, this has been fixed in patch 120011-09.  There is no workaround.

---

# Documentation Updates

This section contains late-breaking information that became known after the documentation set was published.

The corrections for *Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF Reference Manual*, if not otherwise specified, also apply to the man pages, which XSCF provides. And these corrections supersede the information on the man pages.

TABLE 8 lists known documentation corrections.

**TABLE 8** Documentation Corrections

Document	Issue	Change
<i>Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Servers XSCF Reference Manual</i> and XSCF man pages	<code>traceroute(8)</code> command	The following description appears under Privileges but is incorrect: <ul style="list-style-type: none"><li>To execute the command to DSCP address: <code>fieldeng</code></li></ul> The following description should appear under OPERANDS but does not: When used to specify DSCP address to host, an error occurs.
<i>Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 XSCF User's Guide</i>	<code>setloginlockout(8)</code> <code>showloginlockout(8)</code> command	These commands are not available in this XCP release.
<i>Sun SPARC Enterprise M3000/M4000/M5000/M8000/M9000 Administration Guide</i>	<code>setloginlockout(8)</code> <code>showloginlockout(8)</code> command	These commands are not available in this XCP release.