



StorageTek™ Host Software Component (HSC)

MVS software

Messages and Code Guide

Part Number: 312597402

Revision: E

Version: 6.1

Host Software Component (MVS Implementation)

Messages and Codes Guide

Release 6.1

312597402

Copyright 2008 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, California 95054, U.S.A. All rights reserved.

Sun Microsystems, Inc. has intellectual property rights relating to technology that is described in this document. In particular, and without limitation, these intellectual property rights may include one or more of the U.S. patents listed at <http://www.sun.com/patents> and one or more additional patents or pending patent applications in the U.S. and in other countries.

This document and the product to which it pertains are distributed under licenses restricting their use, copying, distribution, and decompilation. No part of the product or of this document may be reproduced in any form by any means without prior written authorization of Sun and its licensors, if any.

Third-party software, including font technology, is copyrighted and licensed from Sun suppliers.

Parts of the product may be derived from Berkeley BSD systems, licensed from the University of California. UNIX is a registered trademark in the U.S. and in other countries, exclusively licensed through X/Open Company, Ltd.

Sun, Sun Microsystems, the Sun logo, Java, AnswerBook2, docs.sun.com, and Solaris are trademarks or registered trademarks of Sun Microsystems, Inc. in the U.S. and in other countries.

All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. in the U.S. and in other countries. Products bearing SPARC trademarks are based upon an architecture developed by Sun Microsystems, Inc.

The OPEN LOOK and Sun™ Graphical User Interface was developed by Sun Microsystems, Inc. for its users and licensees. Sun acknowledges the pioneering efforts of Xerox in researching and developing the concept of visual or graphical user interfaces for the computer industry. Sun holds a non-exclusive license from Xerox to the Xerox Graphical User Interface, which license also covers Sun's licensees who implement OPEN LOOK GUIs and otherwise comply with Sun's written license agreements.

U.S. Government Rights—Commercial use. Government users are subject to the Sun Microsystems, Inc. standard license agreement and applicable provisions of the FAR and its supplements.

DOCUMENTATION IS PROVIDED "AS IS" AND ALL EXPRESS OR IMPLIED CONDITIONS, REPRESENTATIONS AND WARRANTIES, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT, ARE DISCLAIMED, EXCEPT TO THE EXTENT THAT SUCH DISCLAIMERS ARE HELD TO BE LEGALLY INVALID.

Copyright 2008 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, Californie 95054, Etats-Unis. Tous droits réservés.

Sun Microsystems, Inc. a les droits de propriété intellectuels relatants à la technologie qui est décrit dans ce document. En particulier, et sans la limitation, ces droits de propriété intellectuels peuvent inclure un ou plus des brevets américains énumérés à <http://www.sun.com/patents> et un ou les brevets plus supplémentaires ou les applications de brevet en attente dans les Etats-Unis et dans les autres pays.

Ce produit ou document est protégé par un copyright et distribué avec des licences qui en restreignent l'utilisation, la copie, la distribution, et la décompilation. Aucune partie de ce produit ou document ne peut être reproduite sous aucune forme, par quelque moyen que ce soit, sans l'autorisation préalable et écrite de Sun et de ses bailleurs de licence, s'il y en a.

Le logiciel détenu par des tiers, et qui comprend la technologie relative aux polices de caractères, est protégé par un copyright et licencié par des fournisseurs de Sun.

Des parties de ce produit pourront être dérivées des systèmes Berkeley BSD licenciés par l'Université de Californie. UNIX est une marque déposée aux Etats-Unis et dans d'autres pays et licenciée exclusivement par X/Open Company, Ltd.

Sun, Sun Microsystems, le logo Sun, Java, AnswerBook2, docs.sun.com, et Solaris sont des marques de fabrique ou des marques déposées de Sun Microsystems, Inc. aux Etats-Unis et dans d'autres pays.

Toutes les marques SPARC sont utilisées sous licence et sont des marques de fabrique ou des marques déposées de SPARC International, Inc. aux Etats-Unis et dans d'autres pays. Les produits portant les marques SPARC sont basés sur une architecture développée par Sun Microsystems, Inc.

L'interface d'utilisation graphique OPEN LOOK et Sun™ a été développée par Sun Microsystems, Inc. pour ses utilisateurs et licenciés. Sun reconnaît les efforts de pionniers de Xerox pour la recherche et le développement du concept des interfaces d'utilisation visuelle ou graphique pour l'industrie de l'informatique. Sun détient une licence non exclusive de Xerox sur l'interface d'utilisation graphique Xerox, cette licence couvrant également les licenciées de Sun qui mettent en place l'interface d'utilisation graphique OPEN LOOK et qui en outre se conforment aux licences écrites de Sun.

LA DOCUMENTATION EST FOURNIE "EN L'ÉTAT" ET TOUTES AUTRES CONDITIONS, DECLARATIONS ET GARANTIES EXPRESSES OU TACITES SONT FORMELLEMENT EXCLUES, DANS LA MESURE AUTORISEE PAR LA LOI APPLICABLE, Y COMPRIS NOTAMMENT TOUTE GARANTIE IMPLICITE RELATIVE A LA QUALITE MARCHANDE, A L'APTITUDE A UNE UTILISATION PARTICULIERE OU A L'ABSENCE DE CONTREFAÇON.

We welcome your feedback. Please contact the Sun Learning Services Feedback System at:

SLSFS@Sun.com

or

Sun Learning Services
Sun Microsystems Inc.
One StorageTek Drive
Louisville, CO 80028-3256
USA

Document Effectivity

EC Number	Date	Doc Kit Number	Type	Effectivity
132084	February, 2005	---	First Edition	This document applies to the Host Software Component for MVS (MVS/HSC), Version 6.1.
132553	February, 2006	---	Revision B	
132581	June, 2006	---	Revision C	
---	April, 2008	---	Revision D	
---	September, 2008	---	Revision E	

Contents

Preface	ix
Scope	ix
Intended Audience	ix
About the Software	ix
How this Manual is Organized	x
References to HSC Product Releases	x
Related Publications	xi
Sun StorageTek Publications	xi
Additional Information	xii
Sun's External Web Site	xii
Customer Resource Center	xii
Partners Site	xii
Hardcopy Publications	xii
Customer Support	xiii
Customer-initiated Maintenance	xiii
Sun's Worldwide Offices	xiv
Chapter 1. General Information	1
Introduction	1
Message Formats	1
Message Descriptions	2
Message Number	2
Message Text	2
Message Explanation	2
System Action	2
User Response	2
Variable Definitions	3
Chapter 2. HSC System Messages	5
Introduction	5
Message Listings and Descriptions	5
Chapter 3. Abend Reason Code Listings and Descriptions	401
Introduction	401
Reason Codes Issued by Operator Command	402
Reason Codes Issued by Mount/Dismount	404
Reason Codes Issued by Utilities	406

Reason Codes Issued By CAP Common	409
Reason Codes Issued by Subsystem Allocation Modules	410
Reason Codes Issued by Volume/Cell	411
Reason Codes Issued by Configuration Control	412
Reason Codes Issued by Initialization/Termination	413
Reason Codes Issued by Installation Component	414
Reason Codes Issued by TMS/User Interface	415
Reason Codes Issued by LMU Driver	416
Reason Codes Issued by Subsystem Data Base Modules	418
Reason Codes Issued by WTO Server	420
Reason Codes Issued by ASCOMM	421
Reason Codes Issued by Subsystem Services Modules	422
Reason Codes Issued by Recovery Component	425
Reason Codes Issued by Host Communications	427
Chapter 4. HSC Return Codes	429
Introduction	429
Return Code Listings and Descriptions	430
Appendix A. Message Route Codes and Descriptor Codes	451
Appendix B. Message Change Summary - HSC 6.1	473
Message Modifications	474
Messages Added	474
Messages Deleted	476
Messages Changed	476
Messages Replaced	476
Glossary	477
Index	493

Tables

Table 1.	Variable Data Definitions	3
Table 2.	Return Codes for Operator Commands	430
Table 3.	Return Codes for Initialization/Termination	430
Table 4.	Return Codes for Mount/Dismount	430
Table 5.	Return Codes for Utilities	431
Table 6.	Audit Utility Return Codes	433
Table 7.	Return Codes for CAP Processing	433
Table 8.	Volume/Cell Return Codes -- No Parameter List	435
Table 9.	Volume/Cell Return Codes -- With Parameter List	436
Table 10.	Configuration Return Codes	437
Table 11.	LMU Server Return Codes	439
Table 12.	Data Base Server Return Codes	442
Table 13.	Address Space Communications Return Codes	444
Table 14.	Address Space Communication Function Codes	444
Table 15.	Recovery Return Codes	445
Table 16.	Service Component Return Codes	446
Table 17.	Host Communications Services Return Codes	449
Table 18.	Message Route Codes & Descriptor Codes	451

Preface

Scope

This manual describes messages and codes issued by the Sun StorageTek™ Automated Cartridge System (ACS) Host Software Component (HSC).

Intended Audience

This manual is intended for all users of the HSC including operators, system programmers, system analysts, storage administrators, system specialists, and operations specialists who are responsible for one or more of the following tasks:

- initializing the HSC
- monitoring daily HSC activity
- diagnosing and correcting system problems
- keeping the HSC up and running properly.

About the Software

HSC 6.1 is supported by this guide.

How this Manual is Organized

This manual is divided into the chapters and appendices described below. Also, a glossary of terms relevant to Sun StorageTek products, and an index are included.

- **Chapter 1, “General Information”** — Provides a general overview of the message format used in this manual including message numbers, descriptions, explanations, system actions, operator responses and symbols used.
- **Chapter 2, “HSC System Messages”** — Describes each HSC message in detail.
- **Chapter 3, “Abend Reason Code Listings and Descriptions”** — Describes the HSC ABEND codes.
- **Chapter 4, “HSC Return Codes”** — Describes the HSC return codes.
- **Appendix A, “Message Route Codes and Descriptor Codes”** — Provides a cross-reference list for message numbers to route codes and descriptor codes.
- **Appendix B, “Message Change Summary - HSC 6.1”** — Provides a list of message changes, additions, and deletions for HSC Release 6.1.

References to HSC Product Releases

The HSC Release 6.1.0 product is referred to as HSC 6.1.

Related Publications

The following publications contain information about specific topics relating to the use of HSC.

Sun StorageTek Publications

The following documents are available for the MVS operating system and related miscellaneous topics.

Nearline Control Solution Publications

- *Nearline Control Solution (MVS/HSC, LibraryStation, MVS/CSC) Installation Guide*
- *NCS User Exit Guide*
- *SMC Configuration and Administration Guide*

HSC MVS Publications

- *HSC Configuration Guide*
- *HSC Operator's Guide*
- *HSC System Programmer's Guide*
- *HSC Messages and Codes Guide*
- *HSC Reference Summary*

Additional Information

Sun Microsystems, Inc. (Sun) offers several methods for you to obtain additional information.

Sun's External Web Site

Sun's external Web site provides marketing, product, event, corporate, and service information. The external Web site is accessible to anyone with a Web browser and an Internet connection.

The URL for the Sun external Web site is: <http://www.sun.com>

The URL for Sun StorageTek™ brand-specific information is:
<http://www.sun.com/storagetek>

Customer Resource Center

The Sun StorageTek product Customer Resource Center (CRC) is a Web site that enables members to resolve technical issues by searching code fixes and technical documentation for StorageTek brand products. CRC membership entitles you to other proactive services, such as HIPER subscriptions, technical tips, answers to frequently asked questions, addenda to product documentation books, and online product support contact information. Customers who have a current warranty or a current maintenance service agreement may apply for membership by clicking on the Request Password button on the CRC home page. Sun employees may enter the CRC through the SunWeb PowerPort.

The URL for the CRC is <http://www.support.storagetek.com>

Partners Site

The Sun StorageTek Partners site is a Web site for partners with a Sun StorageTek Partner Agreement. This site provides information about products, services, customer support, upcoming events, training programs, and sales tools to support Sun StorageTek Partners. Access to this site, beyond the Partners Login page, is restricted. On the Partners Login page, Sun employees and current partners who do not have access can request a login ID and password and prospective partners can apply to become Sun StorageTek resellers.

The URL for the Sun StorageTek Partners site is:
<http://members.storagetek.com>

The URL for partners with a Sun Partner Agreement is:
<http://www.sun.com/partners/>

Hardcopy Publications

Contact a Sun sales or marketing representative to order additional paper copies of this publication or to order other StorageTek brand product customer publications in paper format.

Sun's Worldwide Offices

You may contact any of Sun's worldwide offices to discuss complete storage, service, and support solutions for your organization. You can find address and telephone number information on Sun's external Web site at:
<http://www.sun.com/worldwide/>

Chapter 1. General Information

Introduction

This chapter describes, in general terms, HSC message formats, variable definitions and numbering conventions.

The information in this manual is provided to help system programmers and operators:

- keep HSC up and running correctly
- monitor HSC activity
- diagnose and correct HSC problems.

This information is NOT to be used as programming interface information.

Message Formats

HSC system messages help you interpret and respond to the informational, diagnostic, and error messages issued by the HSC during operation.

Each message consists of:

- a three-letter prefix identifying the component producing the message; a four character message serial number identifying individual messages; and a one character message identifier.
- message text used to provide information, describe an error, or request an operator action.

Messages are in the traditional MVS style of *SLSNNNX*

where

- *SLS* identifies the host software component
- *NNNN* is a four character numeric
- *X* is a message type identifier

and

- A = action
- D = decision
- E = eventual action
- I = information

Each message contains a description and additional information such as explanation, system action and user response (depending upon the message type).

Message Descriptions

Each message description contains five parts:

- Message Number
- Message Text
- Message Explanation
- System Action
- User Response.

Message Number

SLS message numbers differentiate HSC messages from other messages that may be received. The message number for HSC messages has a “SLS” prefix followed by a four-digit number and a one character message type identifier.

Message Text

The Message Text is the message as actually displayed on the console. Words or terms in *italics* are variables which are replaced by actual values when the message is displayed.

Message Explanation

This section of the message documentation explains the meaning and significance of each message.

System Action

This section of the message documentation describes what the HSC software does, or what happens, when the event triggering the message occurs.

User Response

This section of the message documentation describes what you should do in response to the message. In many cases, no response is required.

Variable Definitions

Message specific information is symbolized by the following:

Table 1. Variable Data Definitions

Variable Data	Definition
<i>AA</i>	ACSid
<i>AA:LL</i>	LSMid
<i>AA:LL:CC</i>	CAPid
<i>AA:LL:PP:NN</i>	DRIVEid (<i>PP</i> is the panel number [01-10] associated with an LSM, and <i>NN</i> is the drive number [0-19] on the panel)
<i>AA:LL:PP:RR:CC</i>	Cartridge location (LSMid, panel, row and column)
<i>D</i>	Indicates a decimal value
<i>LL</i>	LSM number
<i>volser</i>	Volume Serial Number
<i>X</i>	Indicates a hexadecimal value
various letters (see note below)	Variable information (character data)
{ }	Indicates available choices
[]	Indicates an optional field (might not appear in message)
Note: Various letters represent variable character data...including <i>C, S, N, L, P, Y, F, O, Z</i> , etc.	

Chapter 2. HSC System Messages

Introduction

This chapter lists the messages issued by the HSC. The information contained in this chapter helps you interpret and respond to these informational, diagnostic, and error messages.

Each message is listed in numeric order. The description for each message:

- explains why the component issued the message
- describes the system's or component's action
- suggests (if applicable) what action the user should take in response to the message.

Message Listings and Descriptions

SLS0000I	command string
	Explanation: This message echoes the command string entered by the operator.
	System Action: HSC processing continues.
	User Response: None.
SLS0001I	Invalid Command CCCCCCCC
	Explanation: An attempt was made to enter a command (CCCCCCCC) that was not a valid subsystem command.
	System Action: The command is not executed.
	User Response: Enter the correct command.
SLS0002I	Keyword CCCCCCCC1 must have a value for CCCCCCCC2 command
	Explanation: Keyword CCCCCCCC1 was entered without a value for the CCCCCCCC2 command.
	System Action: The command is not executed.
	User Response: Re-enter the command specifying a value for the keyword.

SLS0003I No value allowed for keyword *CCCCCCCC1* on *CCCCCCCC2* command

Explanation: Keyword *CCCCCCCC1* for command *CCCCCCCC2* does not allow a value, but a value was entered.

System Action: The command is not executed.

User Response: Re-enter the command keyword without a value.

SLS0004I *CCCCCCCC1* mutually exclusive with *CCCCCCCC2* for *CCCCCCCC3* command

Explanation: Two mutually exclusive parameters (*CCCCCCCC1*, *CCCCCCCC2*) were entered for the *CCCCCCCC3* command. Positional parameters are identified as POS xx where xx is the position of the parameter. Keyword parameters are identified by their names.

System Action: The command is not executed.

User Response: Re-enter the command eliminating one of the parameters.

SLS0005I Parameter error on *CCCCCCCC1* for *CCCCCCCC2* command

Explanation: The positional parameter denoted by *CCCCCCCC1* had an invalid syntax for the command.

System Action: The command is not executed.

User Response: Re-enter the correct parameter.

SLS0006I Syntax error at parm offset *DDDDDDDD* for *CCCCCCCC1* command-----*CCCCCCCCCCCCC2*

Explanation: A syntax error was detected for the *CCCCCCCC1* command at parameter offset *DDDDDDDD* for the *CCCCCCCCCCCCC2* reason.

System Action: The command is not executed.

User Response: Re-enter the command without the syntax error.

SLS0007I Data Base Status:

Data Set	Configured	Current
Primary.....	{ONLINE OFFLINE}	{ONLINE OFFLINE}
Secondary.....	{ONLINE OFFLINE}	{ONLINE OFFLINE}
Standby.....	{ONLINE OFFLINE}	{ONLINE OFFLINE}
Journal.....	{ONLINE OFFLINE}	{ONLINE OFFLINE}

Explanation: The configured recovery techniques and current recovery techniques are listed. If conflicts between current and configured exist, they are due to an I/O error or the CDs Enable/Disable command.

System Action: HSC processing continues.

User Response: None.

SLS0008I *CCCCCCCC1* name changed from *CCCCCCCC2* to *CCCCCCCC3*

Explanation: The name of a CDS object (record) has been changed.

- *CCCCCCCC1* can be one of the following:
 - ACS
 - LSM
 - CAP
- *CCCCCCCC2* shows the old name
- *CCCCCCCC3* shows the new name

System Action: No action, processing continues.

User Response: Informational message, no action required.

SLS0009I NULL is a reserved word and can not be used

Explanation: An attempt was made to use the reserved word 'NULL' where it is not allowed

System Action: The command is rejected

User Response: Choose a different word and resubmit the command

SLS0010I - SLS0015I

SLS0010I Invalid value for CCCCCCCC1 on CCCCCCCC2 command

Explanation: The data entered for the specified parameter (CCCCCCCC1) is invalid on the CCCCCCCC2 command.

System Action: The command is not executed.

User Response: Re-enter the command with valid data.

SLS0011I Mandatory parameter CCCCCCCC1 missing for CCCCCCCC2 command

Explanation: A command (CCCCCCCC2) was entered without a mandatory parameter (CCCCCCCC1).

System Action: The command is not executed.

User Response: Re-enter the command with the mandatory parameter.

SLS0012I LIST ID NAME

Explanation: Output from the NAME LIST command

System Action: No action, processing continues.

User Response: Informational message, no action required.

SLS0013I Command CCCCCCCC not implemented

Explanation: A valid subsystem command was entered, but the command has not been installed.

System Action: The command is not executed.

User Response: Contact Sun StorageTek Software Support.

SLS0015I Host to Host Broadcast failed for MODIFY command; RC=XXXXXXXX

Explanation: An attempt was made to broadcast a command to all online hosts. The broadcast failed.

System Action: The command is not executed.

User Response: Save the return code (XXXXXXXX) printed in the message, and contact StorageTek Software Support.

SLS0016I ACS subsystem command rejected; ASCOMM RC=XXXXXXXX

Explanation: An attempt to enter an ACS subsystem command was not processed due to a failure in the address space communication component of the HSC.

System Action: The command is not executed.

User Response: Save the return code (XXXXXXXX) printed in the message, and contact StorageTek Software Support.

SLS0017I MODIFY command failed; LSM lock not available

Explanation: The LSM lock is a software construct used to serialize changes to the state of an LSM. There is one LSM lock for each LSM defined in the LIBGEN.

The LSM lock is held by the HSC “MODify lsm” command during ONLINE/OFFLINE processing, and by the Configuration Control initialization task during HSC subsystem startup.

Message SLS0017I is issued when another MODify command for the same LSM is already in process, either on this host or on some other host in the system. The previous MODify command may be active, or it may be queued waiting for the LSM to become ready.

This message may also be issued if Configuration Control initialization is in process on another host in the system.

System Action: The command is not executed.

User Response: Wait a few seconds for any queued commands to complete, or for HSC subsystem initialization to complete on any other hosts in the system, and then reissue the command.

If the problem persists, issue the HSC Display Request command. If the command output indicates any requests with a type of “Vary lsm” and a status of “WAITING” or “TEMP OUT”, there may be a hardware problem with the LSM. Investigate the LSM to ensure that it is in a ready state and communicating with the HSC.

If the hardware problem cannot be corrected immediately, you may need to issue the HSC command “MODify lsm OFFline FORCE”. After the hardware problem has been corrected, you may issue another MODify command to bring the LSM online.

Following a MODify lsm OFFline FORCE command, message SLS0057I may be displayed, indicating return code 45344534 from SLSFCONF. This message is issued because the LSM lock held by an active or queued MODify command was “stolen” by the MODify FORCE command; the message may be ignored.



Note: Use the MODify lsm OFFline FORCE command with extreme caution. If an LSM is forced offline, all outstanding requests to the LSM are purged, and the LSM may need to be IMLed.

SLS0018I - SLS0022I

SLS0018I Invalid keyword *CCCCCCCC1* for *CCCCCCCC2* command

Explanation: The keyword (*CCCCCCCC1*) entered for the specified command (*CCCCCCCC2*) was either invalid or greater than eight characters in length.

System Action: The command is not executed.

User Response: Re-enter the command with the correct keyword.

SLS0019I DISPLAY data unavailable; database I/O error

Explanation: An attempt was made to enter a Display command, but a control data set error occurred while gathering information.

System Action: The command is rejected. However, some information may be displayed if available.

User Response: Determine the cause of the control data set error and correct it. Then re-enter the command.

SLS0020I *CCCCCCCC1* co-requisite *CCCCCCCC2* missing for *CCCCCCCC3* command

Explanation: A parameter (*CCCCCCCC1*) co-requisite with another parameter (*CCCCCCCC2*) was not entered on the *CCCCCCCC3* command.

System Action: The command is not executed.

User Response: Re-enter the command with the correct co-requisite parameters.

SLS0021I Value for *CCCCCCCC1* parameter contained invalid data for *CCCCCCCC2* command

Explanation: The value entered for this parameter (*CCCCCCCC1*) was invalid (e.g., HEX rather than NUMERIC) for the *CCCCCCCC2* command.

System Action: The command is not executed.

User Response: Re-enter the command with the correct value.

SLS0022I Invalid value length for *CCCCCCCC1* parameter on the *CCCCCCCC2* command

Explanation: The value entered for this parameter (*CCCCCCCC1*) exceeded its length specification for the *CCCCCCCC2* command.

System Action: The command is not executed.

User Response: Re-enter the command with the correct value.

SLS0023I Invalid {CCCCCCC} range (CCCCCC-CCCCCC) for {CCCCCCCC} command

Explanation: An attempt was made to enter the CCCCCCCC command with an invalid range. The second element was not greater than the first, or, in the case of a CAP range, a PCAP was specified.

System Action: The command may not be executed in some cases. In other cases, the command is executed, ignoring the invalid portion.

User Response: Re-enter the command specifying a valid range where the second element is greater than the first; and, if a CAP range, neither CAPid specifies a PCAP.

SLS0024I EJECT volser *volser* ignored; volume is {SELECTED|ERRANT|NOT FOUND|NOT in ACS|in OFFLINE LSM|INVALID}

Explanation: An Eject command was entered for a volume which was SELECTED|ERRANT|NOT FOUND|NOT IN ACS|in OFFLINE LSM|INVALID and could not be recovered.

SELECTED	indicates that the volume was in use when an eject was attempted, e.g. the volume could have been mounted. If the volume is erroneously selected, run the UNSElect utility prior to re-entering the command (see the <i>HSC System Programmer's Guide</i> for more information on the UNSElect utility).
ERRANT	indicates that a volume was being moved from one location to another when an error occurred. The location of the volume is unknown. Since the volume was errant, it may be necessary to take other actions such as (1) running an audit against the cell location, (2) checking the CAP and previous MVS SYSLOGs/SCP CONSLOGs to find reasons for the volume becoming errant, (3) investigating the various locations with the View command relating to the actions being taken.
NOT FOUND	indicates that the volume does not reside within any LSM. Check other non-library storage locations.
NOT in ACS	indicates that the volume does not reside in the same ACS as the CAP. Enter an Eject command specifying a CAP in appropriate ACS. Determine the location of the volume by using the Display Volume command.
OFFLINE LSM	indicates that the volume resides in an LSM that is offline.
INVALID	indicates that the volume has an invalid volume serial label or media label. The eject continues.

System Action: An INVALID volume is ejected. For all other conditions, the volume is not ejected.

User Response: If the volume is:

SELECTED	wait until volume becomes unselected, and re-enter the command.
ERRANT	invoke errant recovery to locate the volume, and re-enter the command.
NOT FOUND	no response.
NOT in ACS	determine what ACS contains the volume, and re-enter the Eject command specifying the correct CAPid.
OFFLINE	bring the LSM online, and re-enter the command.
INVALID	no response.

SLS0028I Volume *volser* {ENTER|EJECT} error; {ACS IN PATH OFFLINE| LSM IN PATH OFFLINE|CAP IN PATH OFFLINE|CAP IN PATH INVALID| CARTRIDGE MADE ERRANT}

Explanation: Volume *volser* encountered a command {ENter|Eject} error due to either a CAP IN PATH OFFLINE or an LSM IN PATH OFFLINE or a CAP IN PATH OFFLINE or A CAP IN PATH INVALID or a CARTRIDGE MADE ERRANT situation.

System Action: The command continues without operating on volume *volser*.

User Response: Correct the cause of the error.

SLS0029I CAP preference value for CAPid *AA:LL:CC = D*

Explanation: The CAPPref command has completed execution. Preference value is set as shown.

System Action: HSC processing continues.

User Response: None.

SLS0030I Message ID *DDDD* Help Info: {NO HELP AVAILABLE|help text}

Explanation: A Display command Msg parameter was entered. The data following the control (first) line is information about the message ID entered on the Display Msg command.

System Action: HSC processing continues.

User Response: None.

- SLS0031D** *CCCCCCCC* command in progress; to continue termination reply DRAIN, else reply WAIT
- Explanation:** Operator command termination discovered one or more active tasks using a CAP. These were identified in previous SLS2628E messages. You can reply DRAIN to cause HSC to DRAIN all these tasks immediately, or WAIT to allow them to finish normally.
- If you respond WAIT, this message reappears in three minutes, along with SLS2628E messages describing tasks still active. If you respond DRAIN, HSC acts as if you had entered a DRAIN command for each task. SLS2628E messages describing active tasks appear every three minutes, but no more SLS0031D messages are issued.
- An Eject stops after processing the current tape for each CAP, and the task ends once the CAPs are opened, emptied and closed. An ENter stops only when it has processed all cartridges in the CAP.
- System Action:** The task waits for you to reply DRAIN or WAIT.
- User Response:** Issue a Display Status command to determine any outstanding actions. Reply DRAIN or WAIT.
- SLS0032I** Operator Command Termination in progress
- Explanation:** Operator Command Termination is waiting for a command to terminate before continuing.
- System Action:** Termination waits for the operator command to complete.
- User Response:** Also, issue the Display Status command to determine any outstanding actions.
- SLS0033A** Enter password for EJECT command
- Explanation:** An attempt was made to enter the Eject command, and the "EJCTPAS=" parameter was specified on the SLILIBRY macro in the HSC LIBGEN. A password must be entered to continue processing.
- System Action:** The command waits for a reply. If the password is verified, the command continues.
- User Response:** Enter the correct password.
- SLS0034I** Password not accepted; *CCCCCCCC* command rejected
- Explanation:** A command was rejected after an invalid password was entered.
- System Action:** The command is rejected.
- User Response:** Re-enter the command specifying the correct password.

SLS0035A ENTER scheduled on CAPid AA:LL:CC

Explanation: A SENter command was entered for CAPid AA:LL:CC. The ENter was scheduled. The message is highlighted and remains on the screen until the Eject in progress on the CAP is interrupted and the ENter attempted.

System Action: Unlock the CAP after the next Eject to allow user to enter a cartridge.

User Response: Place the cartridge required in the first slot of the CAP the next time the CAP is opened for ejecting.

SLS0036I {ENTER|EJECT} ended on CAPid AA:LL:CC

Explanation: The command released control of CAPid AA:LL:CC.

System Action: The CAP is made available for other operations.

User Response: None.

SLS0037I CAPid AA:LL:CC has been allocated to the {ENTER|EJECT} command

Explanation: The specified CAPid AA:LL:CC was allocated to either the ENter or Eject command.

System Action: The CAP is allocated to perform the operation indicated.

User Response: None.

SLS0040I {ENTER|EJECT|MODIFY|RELEASE} command rejected; CAPid AA:LL:CC is busy

Explanation: The HSC attempted to execute an ENter, Eject, MODify, or RElease command for a specific CAPid (AA:LL:CC), but the CAP was busy.

System Action: The Eject, ENter, MODify, or RElease command is rejected.

User Response: When the command specified is Eject, ENter, or MODify, another process is actively using the CAP. Re-enter the command when the CAP becomes available or re-enter the command specifying a different CAPid.

When the command specified is RElease, another RElease command is active or another process is releasing the CAP.

SLS0041I Command *CCCCCC* Help Info:

Explanation: A Display CMd was entered. The data following the control (first) line is information about the specified command (*CCCCCC*).

System Action: HSC processing continues.

User Response: None.

SLS0042I {ENTER|EJECT} *volser* failed; LMU/LSM error (*XXXX*)

Explanation: An attempt to ENter or EJect volume *volser* failed. Possible LMU/LSM errors are:

6510 - No pass-thru port for transfer
 6511 - LMU offline
 6512 - Lost communication with LMU
 6514 - LSM hardware error
 6515 - LMU hardware error
 6528 - LMU Server Dead
 6592 - LSM is offline
 65FF - Request purged

System Action: The action in progress (ENter, EJect) will not complete. The cartridge may be made errant depending on the point at which the failure occurred.

User Response: Determine cause of error, correct it, and retry.

SLS0045I *CCCCCCCC* command ignored; subsystem is shutting down

Explanation: Command *CCCCCCCC* was not executed due to subsystem termination in progress.

System Action: The command is ignored.

User Response: Once the HSC is operational, re-enter the command.

SLS0046I RECOVER *CCCCCCCC* ignored; recovery already active for specified host

Explanation: A RECover command was entered for a host that is currently being recovered by another host.

System Action: The RECover command is ignored.

User Response: None.

SLS0047I - SLS0050I

SLS0047I ONLINE or OFFLINE required on {VARY|MODIFY} command

Explanation: The Vary or MODify command was entered without specifying ONline or OFFline.

System Action: The command is not executed.

User Response: Re-enter the desired command specifying ONline or OFFline.

SLS0048I Vary {ACS AA|station C...C} {ONLINE|OFFLINE} failed; command timed out

Explanation: The Vary Station command timed out, or Vary ACS command timed out for all stations. Most likely a hardware or communication error occurred.

System Action: The Vary command failed.

User Response: Correct communication problems with the hardware (LMU) and retry the command.

SLS0049I CCCCCCCC1 set to CCCCCCCC2

Explanation: The function specified on the command has been set to the indicated value. CCCCCCCC1 is the function entered on the command. CCCCCCCC2 is the value entered on the command.

System Action: HSC processing continues.

User Response: None.

SLS0050I Invalid {DEVICE XXXX|UNIT XXXX|STATION XXXX|LSMID AA:LL|
ACSID AA|CAPID AA:LL:CC|DISPLAY TYPE CCCCCCCC|HOSTID CCCCCCCC} for
{ACS|CAPREF|CLEAN|DISMOUNT|DISPLAY|DRAIN|LSM|MODIFY|MOUNT|MNTD|
RECOVER|RELEASE|SENDER|VARY} command

Explanation: The command entered contained an invalid ID.

System Action: The command is not executed.

User Response: Re-enter the command specifying the correct ID.

SLS0053I {MODIFY|VARY|ENABLE|DISABLE|JOURNAL} rejected; {LSMid AA:LL|ACS AA|STation C...C|DATA SET DSNNAME|EVERY CDS COPY|ABEND OPTION|CONTINUE OPTION}is already {ONLINE|OFFLINE|ENABLED|DISABLED|ON}

Explanation: An attempt was made to enter a MODify|Vary|Enable|Disable|Journal request for a LSMid|ACS|STation|CDs|OPTion that was already ONline|OFFline|Enabled|Disabled|ON.

System Action: The command is rejected.

User Response: None.

SLS0054I CC..CC1 CC..CC2 now CC..CC3

Explanation: This message displays connected/disconnected, online/offline, unallocated, or standby status of an ACS, LSM, Station, or CAP.

CC..CC1 ACS, LSM, STATION, or CAP

CC..CC2 ACSid, LSMid, Station Number, or CAPid

CC..CC3 CONNECTED means at least one station is online to the ACS indicated. DISCONNECTED means that no stations are online to the ACS indicated. ONLINE means that a station can be used for transmitting work to the LMU or that an LSM can be requested to perform work for the HSC or that a CAP is now available for ENter or Eject processing. STANDBY means that a station is connected to the slave LMU in a Dual LMU configuration. OFFLINE means that a station or an LSM cannot be used for productive work. An UNALLOCATED ACS means the ACS is a place holder ACS. The ACS is added back into the HSC configuration with the F CONFIG ADD ACSType(SL8500 or SL3000) command. An UNALLOCATED CAP means the CAP is either not physically installed or it is dedicated to another partition.

System Action: An operator command caused the named component to assume the state indicated.

User Response: None.

SLS0055I {ENTER|MODIFY|EJECT|DISPLAY LSM} rejected; ACSid AA is not CONNECTED

Explanation: An attempt was made to enter a command to an offline ACS (AA).

System Action: The command is rejected.

User Response: Issue a Vary command to bring the ACS online and re-enter the command.

SLS0056I - SLS0059I

SLS0056I {ENTER|SEnTER|EJECT} rejected; {ACSid AA}|{LSMid AA:LL}|{CAPid AA:LL:CC}|{TLsM AA:LL} is {OFFLINE|INVALID|UNAVAILABLE|NOT EJECTING|RELEASING}

Explanation: The ENter, SENter, or Eject command could not complete the requested operation.

System Action: The command is rejected.

User Response: When the message indicates the ACSid, LSMid, or CAPid is offline, vary the element online and then re-enter the command.

When the message indicates the ACSid, LSMid, or CAPid is invalid, re-enter the command specifying the correct identifier.

When the message indicates the ACSid, LSMid, or CAPid is unavailable, verify that the CAP is drained before re-entering the ENter or Eject command.

When the message indicates the CAPid is not ejecting, cartridges may be entered into the ACS by issuing the ENter command.

When the message indicates the CAPid is releasing, wait until the RElease command has completed before re-issuing the ENter, SENter, or Eject command.

SLS0057I Unknown RC XXXXXXXX from {SLSFCNF SLSFATHS SLSFLSMV LMURQST MRQST CAPRQST}

Explanation: The HSC COMPONENT that is active received a return code from a lower component and was unable to translate it to a message.

System Action: The request is rejected.

User Response: Refer to the *4400 HSC Messages and Codes Manual*, Chapter 4 - HSC Return Codes, for additional information and explanations of the return code(s).

SLS0059I Cleaning {HAS BEEN|WAS NOT} scheduled for drive DDD

Explanation: The CLean command was entered for device number DDD. If cleaning WAS NOT scheduled, message SLS0069I is also issued to indicate the reason the cleaning request failed.

System Action: HSC processing continues.

User Response: None.

SLS0060I Error parsing *CCCCCCCC* command; SLSSPARS RC=*XXXXXXXX*

Explanation: Parse return codes that are not syntax errors are reported this way.

RC = 4 the length of the string passed to the parser to be parsed was 0.

RC = 12 the parameter list passed to the parser had an invalid format.

RC = 16 the parse table passed to the parser had an invalid format.

System Action: The command is not executed. An internal reason code should generate an additional message.

User Response: Retry the command. If it continues to fail, contact StorageTek Software Support.

SLS0061I Structure *CCCCCCCC1* not allocated; *CCCCCCCC2* command rejected

Explanation: An attempt was made to enter a command (*CCCCCCCC2*) that needed addressability to the specified structure (*CCCCCCCC1*). The structure (data area) pointer was zero. Therefore, no access was possible.

System Action: The command is rejected.

User Response: Re-enter the command with the correct structure name.

SLS0062I Invalid structure or equate name *CCCCCCCC1;CCCCCCCC2* command rejected

Explanation: An attempt was made to enter a command (*CCCCCCCC2*) requiring access to a specific data area. The data area name (*CCCCCCCC1*) was not found in the symbol table.

System Action: The command is rejected.

User Response: Re-enter the command with a correct structure or equate name.

SLS0063I LIST {*CCCCCCCC|XXXXXXXX*} accepted

Explanation: A LIST command was entered for the address or data area named.

System Action: The command lists the data at the address or structure name listed.

User Response: None.

SLS0068I Current TRACE Status:
ALLOCATION DATA {Traced|NOT Traced}
ALLOCATION {Traced|NOT Traced}
ASCOMM {Traced|NOT Traced}
CAP {Traced|NOT Traced}
CONFIGURATION {Traced|NOT Traced}
DATABASE {Traced|NOT Traced}
INIT/TERM {Traced|NOT Traced}
JOB PROCESSING {Traced|NOT Traced}
LMU DRIVER {Traced|NOT Traced}
MOUNT/DISMOUNT {Traced|NOT Traced}
OPERATOR {Traced|NOT Traced}
RECOVERY {Traced|NOT Traced}
UTILITIES {Traced|NOT Traced}
VOLUME/CELL {Traced|NOT Traced}
WTO SERVER {Traced|NOT Traced}
HOST COMMUNICATIONS {Traced|NOT Traced}
LIBRARY STATION {Traced|NOT Traced}
JES3 DIR/ALLOC {Traced|NOT Traced}
JES3 MESSAGE/PROC {Traced|NOT Traced}
JES3 DEVICE/SEP {Traced|NOT Traced}
JES3 DYNALLOC {Traced|NOT Traced}
SERVICES {Traced|NOT Traced}

Explanation: The TRace command successfully completed. A list of ACS subsystem components and their tracing status is displayed.

System Action: HSC processing continues.

User Response: None.

SLS0069I Host to Host Broadcast failed: CCCCCCCC

Explanation: An LMU Server host to host broadcast request was issued as a result of a CLean drive command. The request failed. CCCCCCCC is descriptive text indicating the nature of the failure.

System Action: If the failure is recoverable, message SLS0059I is issued to indicate cleaning was not scheduled for the requested device, and CLean command processing continues. If the failure is not recoverable, the CLean command abends with the reason code 0018.

User Response: None.

SLS0070I {ENTER|EJECT} rejected; CAPid AA:LL:CC recovery failed, RC XXXXXXXX

Explanation: An attempt was made to enter either an ENter or EJect command, but the command was rejected because the specified CAP (AA:LL:CC) required recovery. The recovery failed with a return code of XXXXXXXX.

System Action: The command is rejected.

User Response: Use the RELease CAPid command to regain the CAP. After the release, use the ENter command to open the CAP to check for cartridges. Remove cartridges, if any, from the CAP, and re-enter the previous command (ENter|EJect).

SLS0071I Unexpected RC XXXXXXXX from CCCCCCCC

Explanation: An unexpected return code, XXXXXXXX, was returned from component CCCCCCCC.

System Action: The request is not executed.

User Response: Contact StorageTek Software Support.

SLS0072I EJECT failed; unable to recover errant volume *volser*

Explanation: During EJect processing an errant volume could not be recovered.

System Action: The volume is not ejected.

User Response: Investigate MVS SYSLOGs/SCP CONSLOGs to find the cause of the errant condition. Use the VIEw command to look at home and destination locations. Run the AUDIt and/or the UNSElect utility as needed to recover the volume.

SLS0073I Length LLLL is greater than the 4096 byte limit

Explanation: An attempt was made to dump more than the limit of 4096 bytes. LLLL is the invalid length. The command is terminated.

System Action: Re-enter the LIST command with a valid length

User Response: None.

SLS0076I - SLS0078I

SLS0076I SLS - software failure - *XXXXXXXX volser*

Explanation: The HSC has detected a software error. The specified error occurred.

If three hexadecimal digits are displayed for *XXXXXXXX*, the code is a system abend code.

If eight hexadecimal digits are displayed for *XXXXXXXX*, the code is an HSC abend reason code.

If *volser* is displayed, it contains the volser being processed. If a ? is displayed, the volser is unknown.

System Action: An ERDS entry is created, and a dump is produced. Processing of the affected volume stops.

User Response: Save the dump. Contact StorageTek Software Support.

SLS0077I Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Volume is selected

Explanation: An attempt was made to dismount volume *volser* from transport {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN* = driveid, but the volume was already selected.

System Action: The dismount is not executed.

User Response: Issue a library DISMount from the host that mounted the volume, or perform cross-host recovery and issue library DISMount from host that does the recovery.

SLS0078I Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Volume is errant

Explanation: An attempt was made to locate errant volume *volser* during processing of a dismount request for transport {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN* = driveid. Volume *volser* could not be located.

System Action: The dismount ends.

User Response: None.

SLS0080I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Volume at *AA:LL:PP:RR:CC*

Explanation: The volume *volser* to be mounted on {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN* = driveid, was located at *AA:LL:PP:RR:CC* (LSMid:panel number:row number:column number).

System Action: The mount continues.

User Response: None.

SLS0081I Volume *volser* found mounted on {drive *XXXX*|driveid *AA:LL:PP:NN*} - attempting dismount

Explanation: The HSC found volume *volser* mounted on transport {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN* = driveid, when it attempted to mount another volume. If the volume on the drive has an unreadable label, *volser* is displayed as a question mark.

System Action: The mount continues. The HSC attempts to dismount the mounted volume.

User Response: None.

SLS0082I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - LSMid *AA:LL* is in manual mode; manual mount is required

Explanation: An attempt was made to mount volume *volser* on transport {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN* = driveid, but the specified LSM *AA:LL* was in manual mode. A manual mount is required.

System Action: The mount fails.

User Response: Manually mount the volume.

SLS0083I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - ACS *AA* is disconnected; library mount is required

Explanation: An attempt was made to mount volume *volser* on transport {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN* = driveid, but the specified ACS *AA* was disconnected.

System Action: The mount fails.

User Response: Enter the library Mount command from a host that is connected to the ACS.

SLS0085I Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - ACS *AA* is disconnected; library dismount command is required

Explanation: An attempt was made to dismount volume *volser* from transport {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN* = driveid, but the specified ACS *AA* was disconnected.

System Action: The dismount fails.

User Response: Enter the library DISMount command from a host that is connected to the ACS.

SLS0086I Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - LSMid *AA:LL* is in manual mode; manual dismount is required

Explanation: An attempt was made to dismount volume *volser* from transport {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN* = driveid, but the specified LSM *AA:LL* was in manual mode. A manual dismount is required.

System Action: The dismount fails.

User Response: Manually dismount the volume, and remove it from the LSM.

SLS0087I Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Volume is not on drive

Explanation: The HSC attempted to dismount a volume *volser* from transport {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN* = driveid, but either the drive is empty or a different cartridge is mounted.

System Action: The dismount fails.

User Response: Issue the Display DRives command to determine what volume, if any, is currently mounted on the drive. If the current volume is to be dismounted, issue the HSC DISMount command.

SLS0088D Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Intervention required; Mount or Ignore (M/I)

Explanation: An attempt was made to mount volume *volser* on transport {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN* = driveid, but operator intervention was required (e.g., IEC512I I/O ERR on this drive).

System Action: The mount waits until you reply M or I.

User Response: Reply with one of the following:

M If the mount is to continue.

I If the mount is to be ignored. The HSC leaves the mount pending.

- SLS0089E** Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Unable to allocate cell in ACS *AA*
- Explanation:** An attempt was made to dismount volume *volser* from specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = driveid, but there were no free cells in ACS *AA*.
- System Action:** The dismount fails.
- User Response:** Free a cell (via Eject), and re-enter the DISMount command.
- SLS0090I** Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Unable to insert volume in the database
- Explanation:** An attempt to dismount volume *volser* from specified transport{*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = *DRIVE* id failed because the volume could not be inserted in the control data set.
- System Action:** The dismount fails.
- User Response:** Verify that there is not a duplicate in the control data set, and re-enter the DISMount command.
- SLS0091I** Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Complete
- Explanation:** The dismount of *volser* from specified transport{*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = *DRIVE*id is complete. Receiving this message does not necessarily indicate that the dismount was successful.
- System Action:** Normal processing continues.
- User Response:** None.
- SLS0092I** Swap of *volser* to {drive *XXXX*|driveid *AA:LL:PP:NN*} - LSMid *AA:LL* is in manual mode; manual mount is required
- Explanation:** An attempt was made to swap volume *volser* to specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = *DRIVE*id, but LSM *AA:LL* was in manual mode. Therefore, a manual mount is required.
- System Action:** The swap fails.
- User Response:** Manually swap the volume.

SLS0093I Swap of *volser* to {drive *XXXX*|driveid *AA:LL:PP:NN*} - ACS *AA* is disconnected; library dismount command is required

Explanation: An attempt was made to swap volume *volser* on specified transport {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN* = driveid, but ACS *AA* was disconnected. Therefore, a library DISMOUNT command is required.

System Action: The swap fails.

User Response: To perform the swap, enter library DISMOUNT command from a host that is connected to the ACS.

SLS0094E Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - DRIVEid is *AA:LL:PP:NN*

System Action: transport (drive)The DISMOUNT command is not executed.

User Response: Manually dismount the volume from the transport, and remove the volume from the LSM.

SLS0096I Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - volume not dismounted

Explanation: An attempt was made to dismount volume *volser* from transport{*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN*= driveid, but an error occurred.

System Action: The dismount fails.

User Response: Correct the error, and re-enter the DISMOUNT command.

SLS0098A Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - No non-zero priority CAPs in ACS *AA*; reply C to cancel wait

Explanation: An attempt to permanently or temporarily enter and mount volume *volser* on {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN*= driveid, was made when no non-zero priority CAPs were available in ACS *AA*.

System Action: The mount waits until you reply "C" or a CAP becomes available.

User Response: Make a CAP available using the CAPPref command or DRAIN an active CAP. If the mount need not be processed, reply "C".

SLS0099I Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Volume at *AA:LL:PP:RR:CC*

Explanation: The volume *volser* being dismounted from {*XXXX*|*AA:LL:PP:NN*}, where *XXXX* = drive and *AA:LL:PP:NN*= driveid, is now at location *AA:LL:PP:RR:CC*.

System Action: The dismount continues.

User Response: None.

SLS0101I *CCCCCCCC* invalid reply

Explanation: *CCCCCCCC* is an invalid reply to a WTOR.

System Action: The WTOR is reissued.

User Response: Respond with a valid reply.

SLS0103E Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Drive unload error

Explanation: An attempt to dismount volume *volser* from transport *XXXX*|*AA:LL:PP:NN* encountered a drive unload error.

System Action: The dismount fails.

User Response: Correct the error, and enter a library DISMount command for the specified transport and Volser.

SLS0104D Dismount of {drive *XXXX*|driveid *AA:LL:PP:NN*} - cartridge has no *volser*; reply U,*volser* or I to Use or Ignore

Explanation: The HSC attempted to determine the volume serial number for a dismount. However, one of the following is true: 1) the cartridge has no external label, 2) the external label is unreadable, 3) the external label does not have a valid volume serial number, 4) the volume serial number entered in response to the previous SLS0104D message is invalid or 5) the volume serial number entered in response to the previous SLS0104D message is already in the library.

System Action: The dismount waits for you to reply “U, *volser*” with a valid volume serial number, or “I”.

User Response: Reply with one of the following:

U,*volser* (Use)

Supply a *volser* where “*volser*” is the volume serial number to use. The specified *volser* must contain only valid characters and must not already exist in the library.

I (Ignore)

If the dismount is to be ignored.

SLS0105A Dismount of {drive XXXX|driveid AA:LL:PP:NN} - drive is loaded;
reply I to cancel wait

Explanation: An attempt was made to determine the volume serial number for a dismount but the cartridge was loaded on the transport.

System Action: The dismount waits for you to reply.

User Response: If the dismount is to be ignored, reply "I". If the volume is known to be on the drive and not allocated to a job on any processor, unload the volume from the drive. (To unload a drive in MVS, issue an UNLOAD command. To unload a drive in VM, ATTACH the drive to some virtual machine and then DETACH it.) If the drive is in use, let the job finish processing the volume on the drive. If the drive cannot be unloaded due to a malfunction, place the drive offline, contact StorageTek Hardware Support and reply "I" to this message.

SLS0107D Dismount of *volser* from {drive XXXX|driveid AA:LL:PP:NN} - drive has
loaded cartridge; reply Dismount, Retry or Ignore (D/R/I)

Explanation: A request was made to dismount a volume. However, the volume has not been rewound and unloaded. The dismount waits for you to reply either "D" (dismount), "R" (retry), or "I" (ignore), or for the drive to be rewound and unloaded.

System Action:

User Response: Wait for the rewind and unload to complete or reply with one of the following:

D

If the volume is to be rewound and unloaded.

R

If the dismount is to be retried without forcing the rewind.

I

If the request is to be ignored.



Note: Replying "D" can cause intervention required messages for the transport and cause jobs to abend if the transport is in use. In MVS, you must issue an UNLOAD command for the transport; and if it is online, the UNLOAD command delays unloading the device until it is no longer allocated. In VM, if the device is ATTACHED to the tape management virtual machine (such as VMTAPE), reply "D". If the device is not ATTACHED to any virtual machine, you should attempt to ATTACH the device to some virtual machine and then DETACH it which unloads the tape. If the transport is assigned to another system, the ATTACH fails.

Replying “R” reissues the dismount request without first attempting to rewind the volume.

Replying “T” allows the mounted cartridge to stay on the transport. In MVS, if the system wants to use the mounted cartridge, the transport is allocated without a mount request. If the transport is required for a different cartridge, a dismount request is followed by a new mount request. In VM, if the device is ATTACHed to a virtual machine other than the tape management system, it is unloaded when it is DETACHed.

SLS0108D Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - External label is unreadable; reply Mount, Bypass, or Ignore (M/B/I)

Explanation: An attempt was made to mount volume *volser* on transport *XXXX|AA:LL:PP:NN*, but the external label was unreadable.

System Action: The mount waits until you reply either Mount, Bypass, or Ignore.

User Response: Reply with one of the following:

- M If the volume is to be mounted. External label checking is temporarily bypassed for the duration of this mount.
- B If the volume is to be mounted and it is to be permanently marked as having an unreadable external label.
- I If the request is to be ignored. If necessary, an Eject command can be issued to eject the volume.

SLS0109D Swap of *XXXX1* to *XXXX2* - Volume *volser* is in the library; reply Eject, Dismount, or Ignore (E/D/I)

Explanation: An attempt was made to swap a volume to a transport outside the library.

System Action: The swap waits until you reply either Eject, Dismount, or Ignore.

User Response: Reply with one of the following:

Eject (E)

If the volume is to be ejected.

Dismount (D)

If the volume is to be dismounted and retained in the library.

Ignore (I)

If the request is to be ignored.

SLS0110I Eject of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Unable to eject, volume errant

Explanation: An attempt was made to eject volume *volser* from transport *XXXX|AA:LL:PP:NN*, but an error occurred causing the volume to become errant.

System Action: HSC processing continues.

User Response: Determine why the volume became errant, and make the appropriate correction.

SLS0112E Swap of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - LMU error
XXXXXXXX ACS AA

Explanation: When attempting to swap volume *volser* from *XXXX|AA:LL:PP:NN*, an LMU error *XXXXXXXX* was received.

System Action: The swap fails.

User Response: Enter a library DISMount and Mount command for the volume. If the problem recurs, contact StorageTek Software Support.

SLS0113D Mount of *volser1* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - OCR *volser* mismatch (*volser2*); Retry, Eject, or Ignore (R,E,I)

Explanation: An attempt was made to mount volume *volser1* on specified transport {*XXXX|AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but the LMU found a *volser* with a different external label (*volser2*).

System Action: The mount waits for you to reply Retry, Eject or Ignore.

User Response: Reply with one of the following:

- R If the mount is to be retried.
- E If the volume is to be ejected. Volume *volser1* will be deleted from the control data set. Additionally, if *volser2* is not in the control data set, it will be physically ejected.
- I If the mount is to be ignored.

SLS0114D Enter of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - *volser* invalid; reply E,*volser* or I to Enter a different volume, or Ignore

Explanation: An attempt was made to ENter volume *volser* on specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but the *volser* was unacceptable.

System Action: The mount waits for you to reply “E,*volser*” or “I”.

User Response: Reply with one of the following:

E,*volser*

If a different *volser* is to be entered.

I

If the mount is to be ignored.

SLS0115I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Overridden by a dismount request

Explanation: An attempt was made to mount volume *volser* on specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but the mount was overridden by a dismount request (a mount and dismount request had been made for the same transport).

System Action: Neither the Mount nor the DISMount command is executed.

User Response: None.

SLS0116I Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Newly unreadable *volser*; Ejecting

Explanation: When dismounting *volser*, the LMU indicated that a formerly readable external label is now unreadable.

System Action: The volume is ejected from the library.

User Response: None.

SLS0117E Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - LMU error *XXXXXXXX ACS AA*

Explanation: An attempt was made to dismount volume *volser* from specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but LMU error *XXXXXXXX* occurred.

System Action: The dismount fails.

User Response: Enter a library DISMount command for the volume. If the problem reoccurs immediately, contact StorageTek Software Support.

SLS0118D Enter of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*}; bad CAPid *AA:LL:CC*; reply "T,capid","U", or "I" - Try another/Use any/Ignore

Explanation: An attempt was made to enter volume *volser* on transport {*XXXX*|*AA:LL:PP:NN*}, but a bad CAPid (*AA:LL:CC*) was specified. Either the CAPid is not defined, or the CAP is in use.

System Action: The ENter waits for you to reply T,capid; U; or I.

User Response: Reply with one of the following:

T,capid (Try another CAP)

If the entry of the volume is to proceed, where CAPid is the CAP to use.

U (Use any CAP)

To allow the subsystem to select a CAP.

I (Ignore)

If the entry of the volume is to be ignored.

SLS0119D Enter of *volume* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - volume already in database; reply "M,volser", or "I" to Mount or Ignore

Explanation: An attempt was made to enter volume *volser* on transport *XXXX*|*AA:LL:PP:NN*, but *volser* was already included in the control data set.

System Action: The ENter waits for you to reply "M,volser" or "I".

User Response: Reply with one of the following:

M,volser (Mount)

If the entry of the volume is to proceed, specify a Volser which is not in the control data set.

I (Ignore)

If the entry of the volume is to be ignored.

SLS0120E Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - LMU error *XXXXXXXX ACS AA*

Explanation: An attempt was made to mount volume *volser* on specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but an LMU error *XXXXXXXX* occurred for ACS *AA*.

System Action: The mount fails. If the volume is not in its cell, it is made errant.

User Response: Correct the problem, and enter a library Mount for the volume.

SLS0121I Invalid library {drive XXXX|driveid AA:LL:PP:NN}

Explanation: An attempt was made to mount or dismount a volume via operator command specifying an invalid library transport.

System Action: The mount or dismount fails.

User Response: Re-enter the command with a valid transport.

SLS0122D Enter of *volser* on {drive XXXX|driveid AA:LL:PP:NN} - no cell space available in ACS AA; Retry or Ignore (R/I)

Explanation: An attempt was made to enter volume *volser* on specified transport {XXXX|AA:LL:PP:NN} where XXXX = drive and AA:LL:PP:NN = DRIVEid, but there was no cell space available in the ACS.

System Action: The ENter waits for you to reply Retry or Ignore.

User Response: Reply with one of the following:

R If the entry of the volume is to proceed, eject some volumes prior to replying "R".

I If the entry of the volume is to be ignored.

SLS0123I Dismount of *volser* from {drive XXXX|driveid AA:LL:PP:NN} - Suppressed; mount was not initiated

Explanation: The dismount of *volser* was suppressed because the preceding mount was suppressed, and the volume had not been placed in the transport.

System Action: The dismount is not executed.

User Response: None.

SLS0124I Mount of *volser* on {drive XXXX|driveid AA:LL:PP:NN} - Complete

Explanation: In response to a mount request, volume *volser* was mounted on specified transport {XXXX|AA:LL:PP:NN} where XXXX = drive and AA:LL:PP:NN = DRIVEid.

System Action: Normal processing continues.

User Response: None.

SLS0125D Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Volume not in cell *AA:LL:PP:RR:CC*; Retry, Eject, or Ignore (R,E,I)

Explanation: An attempt was made to mount volume *volser*, but no volume was found in cell *AA:LL:PP:RR:CC*.

System Action: The Mount waits for you to reply Retry, Eject, or Ignore.

User Response: Reply with one of the following:

- R If the Mount is to be retried..
- E If the volume found is to be deleted from the control data set. If the volume is outside the ACS and needs to be entered, reply Eject. Then use HSC operator commands to enter and mount the volume.
- I If the Mount is to be ignored and the volume is NOT to be deleted from the control data set.

SLS0127I Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Error doing scan

Explanation: An attempt was made to dismount volume *volser* from transport *XXXX|AA:LL:PP:NN* which required a scan of either the drive or home location. However, the LMU indicated a move error occurred, or it could not communicate with the drive.

System Action: The dismount is not executed.

User Response: If needed, re-enter the command.

SLS0128A Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Waiting for volume; reply "I" to cancel wait

Explanation: An attempt was made to mount volume *volser* on transport *XXXX|AA:LL:PP:NN*, but the volume was in use.

System Action: The Mount waits until the volume becomes available.

User Response: Reply "I" if the Mount is to be ignored.

SLS0129I Non-zero Return Code From STIMERM - *XXXX*

Explanation: A macro was used to set a particular time interval and wait (STIMERM), and a non-zero return code (*XXXX*) was received.

System Action: The system will not wait for the volume to become available. It will wait for an operator response.

User Response: Reply to the associated WTOR as appropriate.

SLS0130I {Drive XXXX|Driveid AA:LL:PP:NN} found full while attempting mount of *volser*

Explanation: An attempt was made to mount volume *volser* on specified transport {XXXX|AA:LL:PP:NN} where XXXX = drive and AA:LL:PP:NN = DRIVEid, but the transport was full.

System Action: The system attempts to dismount the cartridge on the transport and retry the mount. If the dismount is unsuccessful, the mount may be aborted, or SLS0105A may be issued.

User Response: None.

SLS0131I Mount of *volser* on {drive XXXX|driveid AA:LL:PP:NN} - Error doing scan

Explanation: An attempt was made to mount volume *volser* on transport XXXX|AA:LL:PP:NN which required a scan of either the drive or home location. However, the LMU indicated that a move error occurred or that it could not communicate with the drive.

System Action: The mount is not executed.

User Response: If needed, re-enter the command.

SLS0132I Dismount of *volser* from {drive XXXX|driveid AA:LL:PP:NN} - Suppressed; prior dismount queued or active

Explanation: An attempt was made to dismount volume *volser* from transport XXXX|AA:LL:PP:NN, but the dismount was suppressed because there was a preceding dismount active or queued for the drive.

System Action: The dismount is not executed.

User Response: None.

SLS0133I Dismount of *volser* from {drive XXXX|driveid AA:LL:PP:NN} - Mount active; attempting suppression

Explanation: An attempt was made to dismount volume *volser* from transport XXXX|AA:LL:PP:NN, but a mount request was already active for volume *volser* on that drive.

System Action: The system attempts to suppress the mount. If the mount is successfully suppressed, the dismount is also suppressed.

User Response: None.

SLS0134D Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Volume and drive are in different ACSs; Eject, Retry, or Ignore (E,R,I)

Explanation: An attempt was made to mount volume *volser* on transport *XXXX|AA:LL:PP:NN*, but the mount requires a volume in a different ACS.

System Action: The mount waits for you to reply Eject, Retry or Ignore.

User Response: Reply with one of the following:

- E If the volume required is to be ejected.
- R If the mount is to be retried.
- I If the mount is to be ignored.

SLS0136D Eject of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - bad CAPid *AA:LL:CC*; reply "T,capid", "U", or "I"; Try another/Use any/Ignore

Explanation: An attempt was made to eject volume *volser* and dismount it from transport *XXXX|AA:LL:PP:NN*, but a bad CAPid was specified. Either the CAPid is not defined or the CAP is in use.

System Action: The Eject waits for you to reply T,capid; U; or I.

User Response: Reply with one of the following:

T,capid (Try another CAP)

If the Eject is to proceed, where CAPid is the CAP to use.

U (Use any CAP)

In order to have the subsystem pick a CAP.

I (Ignore)

If the dismount is to be ignored.

SLS0137E Eject of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - LMU error *XXXXXXXX ACS AA*

Explanation: An attempt was made to eject volume *volser* from specified transport {*XXXX|AA:LL:PP: NN*} where *XXXX*= drive and *AA:LL:PP: NN* = driveid, but an LMU error (*XXXXXXXX*) was received.

System Action: The eject fails.

User Response: Enter a library DISMount command for the volume and retry the Eject command. If the problem recurs immediately, contact StorageTek Software Support.

SLS0138D Eject of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - No non-zero priority CAPs in ACS *AA*; reply C to cancel wait

Explanation: An attempt was made to eject volume *volser* from specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but there were not any non-zero priority CAPs available.

System Action: The dismount waits for you to reply C or until a CAP becomes available.

User Response: Enter the CAPPref command or DRA in an active CAP to make a CAP available. If the eject does not need to be processed, reply C.

SLS0140I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Suppressed

Explanation: An attempt was made to mount volume *volser* on specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but it was suppressed by a dismount.

System Action: The mount is not executed.

User Response: None.

SLS0141I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Suppressed; prior scratch request active or queued

Explanation: An attempt was made to mount volume *volser* for a scratch request, but a prior nonspecific request was queued or active for that drive.

System Action: The second mount request is not executed.

User Response: None.

SLS0142I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Unable to recover volume - *XX*

Explanation: An attempt was made to mount errant volume *volser*, but it could not be located. *XX* indicates possible reasons for not finding the volume as follows:

04 - Recovery could not locate the volume
 08 - A control data set error occurred
 0C - Recovery abended
 10 - An LMU error occurred

System Action: The mount terminates.

User Response: None.

SLS0143I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Cancelled due to operator request

Explanation: An attempt was made to mount volume *volser* on specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but the mount was cancelled due to operator request.

System Action: The mount processing terminates.

User Response: None.

SLS0144I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Overriding a mount scratch request

Explanation: When starting to mount *volser* on specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, the system detected a Mount SCRTCH request made for that drive and overrode the request.

System Action: The Mount SCRTCH is not executed.

User Response: None.

SLS0145I Mount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Mount scratch active; attempting suppression

Explanation: An attempt was made to mount volume *volser* on specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but a Mount SCRTCH request was active for that drive.

System Action: The system attempts to suppress the Mount SCRTCH.

User Response: None.

SLS0147I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} suppressed - prior mount request queued

Explanation: An attempt was made to mount volume *volser* on specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but a prior mount request for that volume was queued for that drive.

System Action: The second mount request is not executed.

User Response: None.

SLS0148I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Cancelled by overdue response handler

Explanation: An attempt was made to mount volume *volser* on specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but the overdue response handler determined that this request had taken too long and received permission from you to flush the request.

System Action: The mount request is cancelled.

User Response: Re-enter the mount request if necessary.

SLS0149I Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Cancelled by overdue response handler

Explanation: An attempt was made to dismount volume *volser* from specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but the overdue response handler determined that this request had taken too long and received permission from you to flush the request.

System Action: The dismount request is cancelled.

User Response: Re-enter the dismount request if necessary.

SLS0150I Missing or invalid SLSIN DD statement

Explanation: The SLUADMIN utility program was not able to successfully OPEN the required utility control statements file (DD name SLSIN).

System Action: The utility function is terminated.

User Response: Supply the SLSIN data set containing 80 byte card-image control statements, and resubmit the SLUADMIN utility job.

SLS0151I Value in JCL PARM field is invalid

Explanation: A SLUADMIN utility job was submitted with a PARM= value that was invalid. The allowable values are:

MIXED, NOHDR, LINECNT=*nn* and DATE=4YR|2YR

where *nn* is a value between 10 and 99. NOHDR and LINECNT are mutually exclusive.

System Action: The utility function is terminated.

User Response: Correct the value in the JCL PARM field or eliminate PARM value altogether and resubmit the job.

SLS0152I - SLS0154A

SLS0152I SLUCON__must be authorized when specifying "LIBONLY" parameter

Explanation: The indicated Scratch Conversion utility **MUST** execute in an APF-authorized mode when the "LIBONLY" execution-time parameter is specified.

System Action: The utility is terminated with a return code of 8.

User Response: Ensure that the library that the utility resides in is APF-authorized and resubmit the job.

SLS0153I Conflicting utility is currently active on the system -- try again later

Explanation: Another SLUADMIN utility job was active on the system and was running a utility function that conflicted with the utility function requested in this SLUADMIN utility job.

System Action: The utility function terminates.

User Response: Wait until the other SLUADMIN utility job finishes, and resubmit this SLUADMIN utility job.

SLS0154A A CCCCCCCCCCCCCC library utility active during termination; waiting for completion

Explanation: An attempt was made to terminate one or both HSC service levels but a CCCCCCCCCCCCCC SLUADMIN utility job requiring active Library Software on the system

System Action: Termination waits until the utility function ends.

User Response: Execute one of the following actions based on your current situation:

- Wait until the SLUADMIN utility job ends, and the library software termination continues
- Cancel the SLUADMIN utility job, and allow the library termination to continue
- Cancel the library software, and it terminates abnormally

SLS0155I Condition code for utility function is *DD*

Explanation: A utility function represented by a single control statement in a SLUADMIN utility job has completed with the specified condition code. Possible condition codes are:

- 0 Utility function completed successfully
- 4 Error detected, but utility function was able to complete
- 8 Error detected, and utility function was cancelled
- 12 Error detected, and utility program (all utility functions) was cancelled

System Action: The utility function terminated as indicated.

User Response: If the condition code is other than zero (0), refer to other utility message(s) to resolve the exact reason for the error and determine if the SLUADMIN utility job needs to be resubmitted.

SLS0156I No qualifying SMF records found

Explanation: A SLUADMIN ACTivities Report utility read all of the SMF records but found none in the specified date/time period.

System Action: The Activities Report utility terminates.

User Response: Check the supplied SMF data (DD name SLSSMF) and/or the requested reporting period (BEGIN and END parameters on the control statement), fix the error, and resubmit the SLUADMIN utility job.

SLS0157I Host Software Component not active or an NCO event has temporarily disabled utilities

Explanation: A SLUADMIN utility function requiring the library software was attempted, but the library software was not active or Dynamic Reconfiguration (NCO) is active and has temporarily disabled utilities.

System Action: The utility function is not executed.

User Response:

1. Start the host library software if not active, and resubmit the SLUADMIN utility job.
2. Or if an NCO event occurred then inspect the utility joblog to determine at what point to re-submit the SLUADMIN utility.

SLS0158I - SLS0161I

SLS0158I Conflicting audit in progress on this Host

Explanation: A SLUADMIN AUDIt utility was attempted against library components that were already being audited by another SLUADMIN AUDIt utility, or there was an attempt to simultaneously execute an “active” AUDIt utility (parameter APPLy(YES)) with a “report-only” AUDIt utility (parameter APPLy(NO)).

System Action: The requested utility function is not executed.

User Response: Wait until the other AUDIt utility job is finished and resubmit this SLUADMIN audit job, or change the parameters on this AUDIt control statement to not conflict with the other AUDIt utility.

SLS0159I Conflicting audit in progress within the LSM

Explanation: A SLUADMIN AUDIt utility is in process within the same LSM(s) as those in the current AUDIt utility, initialize cartridge utility (MVS), or ENTER cartridges utility (VM).

System Action: The utility function terminates.

User Response: Wait until the SLUADMIN AUDIt utility or series of concurrent AUDIt utilities complete, and then resubmit this SLUADMIN utility.

SLS0160I All DD journals are successfully sorted

Explanation: This is a checkpoint message from a SLUADMIN RESTore utility indicating that all journal records from DD (the number of active journals) files have been successfully sorted.

System Action: HSC processing continues.

User Response: None.

SLS0161I Control database is successfully copied from the backup copy

Explanation: This is a checkpoint message from the SLUADMIN RESTore utility indicating that the control data set is successfully replaced by the control data set from the backup data set.

System Action: HSC processing continues.

User Response: None.

SLS0162I P P P P P P P P parameter value V V V V V V V V V V invalid

Explanation: The VOLRpt parameter value shown was specified with an invalid parameter value.

System Action: The VOLRpt utility terminates with a return code of 8.

User Response: Correct the indicated parameter on the volume report (VOLRpt) control statement, and resubmit the SLUADMIN utility job.

SLS0163I Volume *volser* not in library

Explanation: A SLUADMIN utility function was supplied a specific volume serial number (*volser*) in the Volser parameter that was not defined in the library; the utility function could not process that volume serial number. This message can also appear without supplying a specific volume serial number, if an internal module requests specific volume serial number information. Rather than ignore this condition, this message is issued to inform the user of an unusual condition.

System Action: The utility continues processing.

User Response: This error does not cancel the utility function, but you may want to check the specified volume serial number, correct it, and resubmit the SLUADMIN utility job.

SLS0164I Volume *volser* already defined in library as scratch

Explanation: A SLUADMIN SCRATCH update utility attempted to add a specified volume serial number (*volser*) to the library scratch pool, but the volume was already defined as scratch.

System Action: The utility continues processing.

User Response: The error does not cancel the SCRATCH update utility, but you may want to check the specified volume serial number, correct it, and resubmit the SLUADMIN SCRATCH update job.

SLS0165I Control database is successfully restored by applying sorted journals

Explanation: This is a checkpoint message from the SLUADMIN RESTORE utility indicating that the control data set, that was replaced from a backup, has been updated with records from all active journal files.

System Action: HSC processing continues.

User Response: None.

SLS0166I Volume *volser* not defined in library as scratch

Explanation: A SLUADMIN SCRATCH update utility attempted to remove a specified volume serial number (*volser*) from the library scratch pool, but the volume was not defined as a scratch volume.

System Action: The utility continues functioning.

User Response: This error does not cancel the SCRATCH update utility, but you may want to check the specified volume serial number and resubmit the SLUADMIN scratch update job.

SLS0167I Volume *volser* successfully added to library as scratch

Explanation: A SLUADMIN SCRATCH update utility has added the specified volume serial number (*volser*) to the library scratch pool.

System Action: HSC processing continues.

User Response: None.

SLS0168I Volume *volser* successfully deleted from library scratch pool

Explanation: A SLUADMIN SCRATCH update utility has deleted the specified volume serial number (*volser*) from the library scratch pool.

System Action: HSC processing continues.

User Response: None.

SLS0169I Secondary is successfully copied from the restored control database

Explanation: This is a checkpoint message from the SLUADMIN RESTORE utility indicating that the secondary copy of the control data set has been successfully replaced by the contents of the restored control data set.

System Action: HSC processing continues.

User Response: None.

SLS0170I Volume *volser* in use; unavailable for processing

Explanation: A SLUADMIN utility function was attempting to perform utility-specific processing against a specific volume serial number (*volser*), but the volume was either currently selected by another process or had been used before it could be scratched. The utility process could not be performed.

System Action: The process continues, but this volume has been ignored.

User Response: This is not considered an error, but you may want to resubmit the SLUADMIN utility job after the competing process/job releases the volume.

SLS0171I CAPid *AA:LL:CC* is invalid

Explanation: A SLUADMIN utility function requiring a Cartridge Access Port (CAP) specified a particular CAPid (*AA:LL:CC*) in the utility control statement, but the CAPid was invalid.

System Action: The utility terminates.

User Response: Change the specification of the CAPid, and resubmit the SLUADMIN utility job.

SLS0172I CAP could not be successfully allocated

Explanation: A SLUADMIN utility function requiring a CAP either could not allocate the specific CAP (if a CAP parameter was specified on the utility control statement) because that CAP was in use by another process, or no unreserved CAPs with a non-zero priority exist in the ACS where the CAP is required.

System Action: The utility terminates without performing the CAP operation.

User Response: Either specify a different CAPid, or wait for the process using the specific CAP to complete and resubmit the SLUADMIN utility job. If no CAP is specified, display the preference priorities for CAPs in the ACS, and set an available CAP preference to non-zero (see Display and CAPPref library commands) and resubmit the SLUADMIN utility job.

SLS0173I Missing or invalid SLSTAPE DD statement

Explanation: A SLUADMIN initialize cartridge utility either could not locate an SLSTAPE DD statement, or the SLSTAPE DD statement did not represent a transport.

System Action: The utility terminates processing.

User Response: Make sure the JCL contains an SLSTAPE DD statement representing a valid library transport; and, if requesting a specific CAP, make sure the CAP is in the same ACS as the library transport represented by the SLSTAPE DD statement. Then resubmit the SLUADMIN utility job.

SLS0174I Volume *volser* successfully ejected from library

Explanation: A SLUADMIN utility function that involves cartridge ejection has successfully moved the identified volume serial number (*volser*) to a Cartridge Access Port (CAP).

System Action: The cartridge is ejected from the control data set.

User Response: None. (The operator is informed of the cartridge ejection and is required to empty the CAP either when the CAP is full or when the SLUADMIN utility function completes.)

SLS0175I - SLS0179I

SLS0175I Missing or invalid SLSCNTL DD statement

Explanation: A SLUADMIN BACKUp or RESTore utility could not successfully open the control data set represented by the SLSCNTL DD statement.

System Action: The utility terminates processing.

User Response: Supply the SLSCNTL DD statement to properly reference the control data set for the SLUADMIN utility function, and resubmit the SLUADMIN utility job.

SLS0176I Missing or invalid SLSBKUP DD statement

Explanation: A SLUADMIN BACKUp or RESTore utility could not successfully open the backup data set represented by the SLSBKUP DD statement.

System Action: The utility terminates processing.

User Response: Supply the SLSBKUP DD statement to properly reference the backup data set for the SLUADMIN utility function and, resubmit the SLUADMIN utility job.

SLS0177I Missing or invalid SLSJRNnn DD statement

Explanation: A SLUADMIN BACKUp utility could not successfully open the journal represented by the SLSJRNnn statement (*nn* = 01 - 32).

System Action: The utility terminates processing.

User Response: Supply the SLSJRNnn statements to properly reference all active journal files for the SLUADMIN BACKUp utility, and resubmit the SLUADMIN utility job.

SLS0178I APPLY(YES) specified or defaulted, but journaling not active

Explanation: A SLUADMIN RESTore utility was submitted with a specified or implied APPLY(YES) parameter meaning that journal records were to be applied to the restored control data set, but journaling was not in effect for the library software.

System Action: The utility terminates processing.

User Response: If the control data set should really be restored to the state of the referenced backup data set (SLSBKUP DD statement), supply APPLY(NO) on the RESTore utility (RESTore) control statement, and resubmit the SLUADMIN utility job.

SLS0179I I/O error reading backup file specified by SLSBKUP DD statement

Explanation: An I/O error occurred for the CDS backup data set.

System Action: The utility terminates. The CDS is not affected.

User Response: Re-establish another backup data set, and rerun the CDS BACKUp utility.

SLS0180I I/O error processing control database

Explanation: An I/O error on the control data set occurred during processing of a SLUADMIN utility function.

System Action: The utility terminates without completing the requested function.

User Response: Determine the cause of the I/O error. Resubmit the utility after the control data set problem is corrected.

SLS0181I I/O error reading journal specified by SLSJRNnn DD statement

Explanation: An I/O error occurred, during a SLUADMIN BACKUp or RESTore utility, reading the journal file represented by the SLSJRNnn statement. (nn = 01 - 32 for BACKUp, 01 - 99 for RESTore).

System Action: The utility terminates prematurely.

User Response: Refer to local recovery procedures.

If BACKUp had a journal I/O error, use SLICREAT to create new (reset) journal file(s).

If RESTore had a journal I/O error, determine if another copy of the journal file exists and use the copy.

If no copy exists, you are either left with an incomplete restore or with auditing your whole library.

SLS0182I I/O error writing journal specified by SLSJRNnn DD statement

Explanation: An I/O error occurred during a SLUADMIN BACKUp or OFFLoad utility, writing the journal file represented by the SLSJRNnn statement. (nn = 01 - 02 for OFFLoad, 01 - 32 for BACKUp.)

System Action: The utility terminates without resetting the journal file(s).

User Response: If OFFLoad had the I/O error, IMMEDIATELY take a BACKUp. If BACKUp had the I/O error, use SLICREAT to create (reset) the journal files.

SLS0184I DD1 hosts defined, but only DD2 SLSJRNnn DD statements supplied

Explanation: A SLUADMIN RESTore utility determined that the DD1 number of hosts defined showed that there was an insufficient number of SLSJRNnn statements. DD2 expresses how many SLSJRNnn statements were present. Each host attached to the library must have two journal files. (= 01 - 32 for BACKUp, 01 - 99 for RESTore.)

System Action: The RESTore utility terminates processing.

User Response: Supply two SLSJRNnn statements for each host attached to the library, and resubmit the SLUADMIN RESTore utility job.

SLS0191I - SLS0196I

- SLS0191I** Journal specified by SLSJRNnn DD statement successfully reset
- Explanation:** A checkpoint message issued by a SLUADMIN BACKup or OFFLoad utility indicated that one of the journal files represented by the SLSJRNnn (nn = 01 - 02 for OFFLoad, 01 - 32 for BACKup) DD statement was successfully reset.
- System Action:** HSC processing continues.
- User Response:** None.
- SLS0194I** I/O error writing to control database specified by SLSCNTL DD statement
- Explanation:** A SLUADMIN RESTore utility encountered an I/O error while copying the backup or applying the journal to the control data set (DD name SLSCNTL).
- System Action:** The utility terminates processing.
- User Response:** Recreate the control data set, identify the new control data set on the SLSCNTL DD statement, and resubmit the SLUADMIN utility job.
- SLS0195I** I/O error reading from data set specified by SLSDELTA DD statement
- Explanation:** A SLUADMIN RESTore utility encountered an I/O error reading back the sorted journal records on the temporary work file (DD name SLSDELTA).
- System Action:** The utility terminates processing.
- User Response:** Reallocate the temporary sorted journal records file represented by the SLSDELTA DD statement, and resubmit the SLUADMIN utility job.
- SLS0196I** LSM LL is invalid
- Explanation:** The LSMid (LL) obtained through the “LSM” parameter on a SLUADMIN utility function control statement was invalid.
- System Action:** The utility terminates processing.
- User Response:** Check the configuration of the library, respecify the “LSM”parameter, and resubmit the SLUADMIN utility job.

SLS0197I LSMid *AA:LL* is offline or unallocated

Explanation: A SLUADMIN utility function required a functional path to a specific LSMid (*AA:LL*) but found the LSM offline or not allocated to the host where the utility was executed.

System Action: The utility terminates processing.

User Response: If the LSM is offline, bring the LSM online to this host (see MODify command) and resubmit the SLUADMIN utility job. If the LSM is unallocated, remove the LSM from the utility control statements and resubmit the SLUADMIN utility job.

SLS0198I Panel index *DD* is invalid

Explanation: A SLUADMIN AUDIt utility encountered an invalid panel index (*DD*) specified in the PANel parameter of the AUDIt control statement.

System Action: The utility terminates processing.

User Response: Respecify the panel index in the PANel parameter and, resubmit the SLUADMIN utility job.

SLS0199I Volume *volser* in cell *AA:LL:PP:RR:CC* is in control database at cell *AA:LL:PP:RR:CC*

Explanation: A SLUADMIN AUDIt utility function has encountered a library cartridge with the specified volume serial number (*volser*) that was in a different library location than the control data set (first cell is observed location, second is control data set location). If the audit was “active” (APPLY(YES) specified or defaulted on the control statement), the data set was updated.

System Action: Depending on the APPLY parameter, the audit will change the location of the volume in the control data set.

User Response: None.

SLS0200I Volume *volser* in cell *AA:LL:PP:RR:CC* is not in control database

Explanation: A SLUADMIN AUDIt utility function has encountered a library cartridge with the specified volume serial number (*volser*) at the specified location (*AA:LL:PP:RR:CC*) that is not in the control data set. If the audit is “active” (APPLY(YES) specified or defaulted on the control statement), the volume is added to the control data set.

System Action: Depending on the APPLY parameter specification, the volume may be added to the control data set.

User Response: None.

SLS0201I Cartridge in cell *AA:LL:PP:RR:CC* has an unreadable or illegal external label

Explanation: A SLUADMIN AUDIt utility encountered an unlabeled cartridge, a cartridge with an unreadable external label, or a cartridge with a label containing illegal characters in the defined location (*AA:LL:PP:RR:CC*). If the audit is “active” (APPLY(YES) specified or defaulted), the cartridge is ejected.

System Action: The cartridge is physically ejected from the library if APPLY(YES) is specified.

User Response: If APPLY(YES) is specified, take the cartridge out of the CAP, determine its Volser, and re-enter the cartridge. If APPLY(NO) is specified, you may have to invoke errant recovery on the original volume to have the cartridge logically ejected (deleted from the control data set). Errant recovery can be invoked by issuing a Mount or Eject command for the volume.

SLS0202I Volume *volser* in cell *AA:LL:PP:RR:CC* is a duplicate with volume in cell *AA:LL:PP:RR:CC*

Explanation: A SLUADMIN AUDIt utility function encountered more than one library cartridge with the specified volume serial number (*volser*). The first specified location (*AA:LL:PP:RR:CC*) refers to the duplicate, while the second refers to the original. If the audit is “active” (APPLY(YES) specified or defaulted on the control statement), the volume is ejected.

System Action: The duplicate volume is physically ejected from the library if the audit is active.

User Response: Depending on which one is supposed to be in the library, the volume left in the library may have to be ejected and the other one re-entered.

SLS0203I ACS *AA* is invalid

Explanation: A SLUADMIN utility function encountered an invalid specification of the ACS parameter on the utility control statement.

System Action: The utility function is terminated.

User Response: Respecify the ACS, and resubmit the SLUADMIN utility job.

SLS0204I ACS AA is disconnected

Explanation: A SLUADMIN utility function required a functional path to a specific ACS (AA), but found the ACS disconnected to the host where the utility was executed.

System Action: The utility function is terminated.

User Response: Connect the ACS to this host (see Vary command), and resubmit the SLUADMIN utility job.

SLS0205I Missing or invalid SLSINIT DD statement

Explanation: A SLUADMIN INITIALize cartridge utility could not successfully open the required prototype initialization control statement file (DD name SLSINIT).

System Action: The utility function is terminated.

User Response: Supply the SLSINIT DD statement with 80-byte card-image control statement records with a 6-character substitution field for the volume serial number (“*****”), and resubmit the SLUADMIN utility job.

SLS0206I Missing or invalid initialization control statement (CCCCCCCC DD statement)

Explanation: A SLUADMIN INITIALize cartridge utility could not successfully open the required initialization control statement file (DD name = CCCCCCCC; for IEHINITT this is SYSIN).

System Action: The utility function is terminated.

User Response: Supply the DD statement specified by the CNTLDD parameter of the initialize cartridge control statement (default DDname = SYSIN), and resubmit the SLUADMIN utility job.

SLS0207I Invalid SLSINIT prototype initialization control statement

Explanation: A SLUADMIN INITIALize cartridge utility encountered an invalid prototype initialization control statement in the SLSINIT file. Either the file is null (contains no card-image records), or there are more than six card-image records, or there is no six-character volume serial number substitution field (“*****”).

System Action: The utility function is terminated.

User Response: Supply the SLSINIT DD statement with 80-byte card-image control statement records and a six-character substitution field for the volume serial number (“*****”), and resubmit the SLUADMIN utility job.

SLS0208I OPTION parameter value invalid; must be SCRatch or EJEct

Explanation: A SLUADMIN INITIALize cartridge utility encountered an invalid value in the initialize cartridge (INITialize) control statement OPTion parameter.

System Action: The utility function terminates.

User Response: Respecify or remove the OPTion parameter from the initialize cartridge control statement, and resubmit the SLUADMIN utility job.

SLS0209I Initialize cartridge program CCCCCCCC not found

Explanation: A SLUADMIN INITIALize cartridge utility attempted to load the initialization program (CCCCCCCC) either specified on the PROGram parameter of the initialize cartridge control statement or defaulted to IEHINITT.

System Action: The utility function is terminated.

User Response: Check the specification of the initialization program in the PROGRAM parameter and/or make sure it is accessible to the SLUADMIN link list.

SLS0210I Library scratch list deletion completed successfully

Explanation: This is a checkpoint message issued by a SLUADMIN SCRAtch update utility with a REPLaceall control statement indicating that all scratch volumes are deleted from the current scratch list.

System Action: Normal operations continue.

User Response: None.

SLS0211I Volume *volser* successfully entered into library

Explanation: A SLUADMIN INITIALize cartridge utility (MVS) or ENTER cartridges utility (VM) has entered a cartridge with an external label (*volser*) into the library. The MVS initialize cartridge utility issues this message prior to invoking the initialization program.

System Action: The cartridge has been entered into the library.

User Response: None.

SLS0212I Missing or invalid SLSSMF DD statement

Explanation: A SLUADMIN ACTIvities Report utility could not successfully open the required SMF records file (DD name SLSSMF).

System Action: The utility terminates processing.

User Response: Supply the SLSSMF DD statement, and resubmit the SLUADMIN utility job.

SLS0213I Volume *volser* not located by Audit

Explanation: A SLUADMIN AUDIt utility did not find the specified volume serial number (*volser*) in the audited library elements, but the control data set contained that volume with a location within the audited library elements. If the audit is “active” (APPLY(YES) specified or defaulted), the volume is deleted from the database.

System Action: The volume is logically ejected (deleted from control data set) if APPLY(YES) is specified.

User Response: If the volume is suspected to be in the library still, increase the library items being audited to include the whole LSM or its ACS. If the volume still cannot be found inside the ACS, examine SMF data and MVS SYSLOG/SCP CONSLOG to determine if the volume has been ejected or perhaps manually mounted and taken out of the library.

SLS0214I 'APPLY' parameter value invalid; must be 'YES' or 'NO'

Explanation: A SLUADMIN utility function specified an APPLY parameter with a value other than YES or NO.

System Action: The utility terminates.

User Response: Correct the APPLY parameter on the utility control statement, and resubmit the SLUADMIN utility job.

SLS0215I An error occurred in the initialize cartridge program CCCCCCCC

Explanation: A SLUADMIN INITialize cartridge utility invoked the initialize cartridge program (CCCCCCC) and received a non-zero return code.

System Action: The utility terminates.

User Response: Check for an error message from the initialize cartridge program and correct the cause. Then eject the cartridges, and resubmit the SLUADMIN utility job.

SLS0216I Invalid date and/or time specified on SLSIN control statement

Explanation: A SLUADMIN ACTivities Report utility encountered a date and/or time on the BEGIN or END parameter of the ACTivities control statement that was not in the proper format.

System Action: The utility terminates.

User Response: Respecify the BEGIN and/or END parameters on the ACTivities control statement in the format “MM/DD/YY” or “YYYYMMDD” (01 =< MM =< 12, 01 =< DD =< 31) for date, and “HH:MM:SS” (00 =< HH =< 23, 00 =< MM,SS =< 59) for time, and resubmit the SLUADMIN utility job.

SLS0217I BEGIN date and/or time is the same or later than END date and/or time

Explanation: A SLUADMIN ACTivities Report utility encountered a date/time on the BEGIN parameter that was not earlier than the date/time parameter on the END parameter of the ACTivities control statement.

System Action: The utility terminates.

User Response: Respecify the BEGIN and/or END parameters on the Activities control statement, and resubmit the SLUADMIN utility job.

SLS0218I Invalid date specified in PARM parameter of JCL statement

Explanation: The date specified in the PARM field for the Scratch Conversion utility was not a valid date value.

System Action: The utility terminates.

User Response: Correct the date value, and resubmit the Scratch Conversion utility.

SLS0219I Missing or invalid SLSTMS DD statement

Explanation: The SLUCONDB Scratch Conversion utility program was not able to successfully open the required utility control statements file (DD name SLSTMS).

System Action: The utility terminates.

User Response: Supply the SLSTMS data set containing the tape management system database to be processed. Resubmit the SLUCONDB utility.

SLS0220I Invalid command

Explanation: A SLUADMIN utility encountered an unrecognized command on a SLSIN control statement.

System Action: The command statement is ignored.

User Response: Correct the command on the control statement, and resubmit the SLUADMIN utility job.

SLS0221I CCCCCCCC1 parameter mutually exclusive with CCCCCCCC2 parameter

Explanation: A SLUADMIN utility encountered a SLSIN control statement with two mutually exclusive parameters (CCCCCCCC1 and CCCCCCCC2).

System Action: The control statement is ignored.

User Response: Correct the control statement by removing one of the referenced parameters, and resubmit the SLUADMIN utility job.

SLS0222I CCCCCCCC1 parameter requires corequisite parameter CCCCCCCC2

Explanation: A SLUADMIN utility encountered a SLSIN control statement with a parameter (CCCCCCCC1) that required specification of another parameter (CCCCCCCC2) which was not present on the control statement.

System Action: The control statement is ignored.

User Response: Correct the control statement by supplying the required parameter, and resubmit the SLUADMIN utility job. This error could be associated with an invalid continuation.

Please note that the requested missing parameter may not be the only one acceptable. In some parameters, several corequisite parameters may satisfy the requirement and the message will only show one of them.

SLS0223I Parameter CCCCCCCC is an unknown parameter

Explanation: A SLUADMIN utility function encountered a SLSIN control statement with either a parameter (CCCCCCCC) that was not allowed for the command or a parameter greater than eight characters in length.

System Action: The control statement is ignored.

User Response: Correct the control statement by either removing the invalid parameter or correcting the spelling of the valid parameter, and resubmitting the SLUADMIN utility job.

SLS0224I CCCCCCCC parameter has a value with a length error

Explanation: A SLUADMIN utility encountered a SLSIN control statement with a parameter (CCCCCCCC) whose value was longer or shorter than permitted.

System Action: The control statement is ignored.

User Response: Correct the parameter value on the control statement, and resubmit the SLUADMIN utility job.

SLS0225I CCCCCCCC parameter requires a value

Explanation: A SLUADMIN utility encountered a SLSIN control statement with a parameter (CCCCCCCC) without a value, but the parameter required a value.

System Action: The control statement is ignored.

User Response: Supply a value for the parameter on the control statement, and resubmit the SLUADMIN utility job.

SLS0226I Value not allowed with CCCCCCCC parameter

Explanation: A SLUADMIN utility encountered a SLSIN control statement with a parameter (CCCCCCCC) having a value, but the parameter does not allow a value.

System Action: The control statement is ignored.

User Response: Remove the value on the parameter on the control statement, and resubmit the SLUADMIN utility job.

SLS0227I Parameter CCCCCCCC has an illegal value

Explanation: A SLUADMIN utility encountered a SLSIN control statement with a parameter (CCCCCCCC) with an illegal value; either there is a list when a list is not allowed or the value type (i.e. hex, numeric, alpha) is of a different type than allowed.

System Action: The control statement is ignored.

User Response: Correct the value on the parameter on the control statement, and resubmit the SLUADMIN utility job.

SLS0228I CCCCCCCC parameter has too many values

Explanation: A SLUADMIN utility encountered a SLSIN control statement with a parameter (CCCCCCCC) that had too many values in the value list. For example, a maximum of 20 panel indexes on a PANel parameter.

System Action: The control statement is ignored.

User Response: Correct the value list on the parameter of the control statement, and resubmit the SLUADMIN utility job.

SLS0229I PANEL parameter not allowed with LSM value list parameter

Explanation: A SLUADMIN AUDIt utility encountered a control statement with a PANel parameter and an LSM parameter that had a value list (more than one LSM index). There can only be one LSM identified on the AUDIt control statement if the PANel parameter is supplied.

System Action: The control statement is ignored.

User Response: Correct the parameters on the control statement, and resubmit the SLUADMIN utility job.

SLS0230I Parameter ALL or ACS required

Explanation: A SLUADMIN utility function encountered a control statement that required one of the two listed parameters (ALL or ACS).

System Action: The control statement is ignored.

User Response: Supply one of the parameters on the control statement, and resubmit the SLUADMIN utility job.

SLS0231I Audit phase 1 (Registration) completed

Explanation: This is a SLUADMIN AUDIt utility checkpoint message indicating the audit has completed the Registration phase. It has been verified that the requested audit is legal and does not conflict with any other library utilities; also a Cartridge Access Port (CAP) is reserved for the ACS encountering the error.

System Action: Audit processing continues.

User Response: None.

SLS0232I Audit phase 2 (Volumes Check) completed

Explanation: This is a SLUADMIN AUDIt utility checkpoint message indicating the audit has completed the Volumes Check phase. All volume records in the control data set have been read and an entry built in the Audited Volume Table for those volumes in an audited library element; at the completion of the last active audit, all unlocated volumes are deleted from the control data set.

System Action: Audit processing continues.

User Response: None.

SLS0233I Audit phase 3 (Cell Scan) completed

Explanation: This is a SLUADMIN AUDIt utility checkpoint message indicating the audit has completed the Cell Scan phase. All library elements to be audited have been scanned by the LSM camera, and if this is an “active” audit (APPLY(YES) specified or defaulted), the control data set has been updated to reflect the actual contents of those elements. Also, any cartridges with duplicate or unreadable labels have been ejected.

System Action: Audit processing continues.

User Response: None.

SLS0234I Audit phase 4 (Finish) completed

Explanation: This is a SLUADMIN AUDIt utility checkpoint message indicating the audit has completed the final phase. All Cartridge Access Ports (CAPs) reserved by this audit have been released, and if this is the last “active” audit (APPLY(YES) specified or defaulted), the Audited Volume Table has been scanned and any volumes not located by the audit have been deleted from the control data set.

System Action: If this is (Final) started, audit processing continues; otherwise, audit processing is ended, and a termination return code message is issued (SLS0155I).

User Response: None.

SLS0235I Audited volume *volser* is errant (lost)

Explanation: A SLUADMIN AUDIt utility has discovered a volume record in the control data set that has been marked “errant” (lost) for a volume in an audited library element. If this is an “active” audit (APPLY(YES) specified or defaulted), the volume record is updated if the volume is found in the cell scan phase.

System Action: If APPLY(YES) is specified and the volume is found during the LSM cell scan phase, the volume is removed from the errant set.

User Response: If the volume cannot be found, display the volume to determine its last known location. Use the VIEW command to examine the last known location. If the volume still cannot be found inside the library, examine MVS SYSLOG/SCP CONSLOG and SMF data to determine if the volume was ejected or manually mounted and taken out of the ACS. Increase the scope of the audit.

SLS0236I Audited volume *volser* has a cell index mismatch

Explanation: A SLUADMIN AUDIt utility has discovered a volume record in the control data set that has a home location in an audited library element, but the cell index for that location reflects a different or no volume serial number. If this is an “active” audit (APPLY(YES) specified or defaulted), the cell index record is updated if it reflects no volume serial number, the volume serial number contained does not exist, or the volume record has a different home location.

System Action: The cell index portion of the control data set will be updated if APPLY(YES) is specified.

User Response: If APPLY(NO) is specified, a cell index mismatch occurs which can only be fixed if audited or if the volume actually in the cell is ejected or floated out of the LSM. Executing a location (specify ACS or LSM parameters) volume report will show the cell index mismatch.

SLS0237I Audited volume *volser* is errant (lost) and has a cell index mismatch

Explanation: A SLUADMIN AUDIt utility has discovered a volume record in the control data set that is marked errant (lost) and the cell index for its home location reflected a different or no volume serial number. If this is an “active” audit (APPLY(YES) specified or defaulted), the cell index record is updated if it reflects no volume serial number, the volume serial number contained does not exist, or the volume record has a different home location. Also, if the volume is located in the cell scan phase of the audit, the control data set is updated and the volume made non-errant.

System Action: The cell index is updated if active audit. If the volume is found during the LSM cell scan and this is an active audit, the volume is removed from errant state.

User Response: If the volume cannot be found, attempt to increase the scope of the audit. If the volume still cannot be found, examine MVS SYSLOG/SCP CONSLOG and SMF data to determine when the volume was ejected or manually mounted.

SLS0238I Audit scan for LSMid *AA:LL*, panel *DD* has completed

This is a checkpoint message issued by a SLUADMIN AUDIt utility indicating the physical cell scan for the specified LSMid (*AA:LL*) and panel (*DD*) has completed.

System Action: HSC processing continues.

User Response: None.

SLS0239I Audit scan for panels in LSMid *AA:LL* has terminated

Explanation: This is a checkpoint message issued by a SLUADMIN AUDIt utility indicating the physical cell scan for the specified LSMid has either completed normally or was terminated early due to an error identified by another message in the SLSPRINT output.

System Action: HSC processing continues.

User Response: None.

SLS0240I Control data set configuration does not match the hardware configuration

Explanation: A SLUADMIN AUDIt utility has encountered a difference in the control data set configuration and the hardware configuration as discovered by the physical cell scan.

System Action: The AUDIt utility is cancelled.

User Response: Either change the control data set configuration via LIBGEN or have the CSE alter the ACS configuration stored in the LMU.

SLS0241I Invalid utility control statement

Explanation: A SLUADMIN utility has encountered a continuation or other general syntax error (e.g. unmatched parentheses) on a utility control statement, or the concatenated control statement exceeds the maximum length of 32767 characters.

System Action: The control statement is ignored.

User Response: Correct the syntax error, and resubmit the SLUADMIN utility job.

SLS0242I Required parameter CCCCCCCC is missing

Explanation: A SLUADMIN utility function has encountered a control statement with a missing required parameter (CCCCCCCC).

System Action: The control statement is ignored.

User Response: Supply the missing parameter, and resubmit the SLUADMIN utility job.

SLS0243I LMU or LSM failure during operation in LSMid AA:LL, RC=XXXXXXXX

Explanation: A SLUADMIN utility has encountered an error returned from a directed LMU or LSM operation.

System Action: The utility terminates processing.

User Response: Record the approximate time of failure, and contact StorageTek Software Support. After repair/adjustment actions have been performed, resubmit the SLUADMIN utility job.

SLS0244I Scratch Redistribution completed successfully for ACS AA

Explanation: A SLUADMIN SCREdist (scratch redistribution) utility has completed balancing the scratch volumes (within the tolerance defined for the installation) for the specified ACS (AA).

System Action: HSC processing continues.

User Response: None.

SLS0245I Specified ACS has fewer than two LSMs online; Scratch Redistribution will not run

Explanation: A SLUADMIN SCREdist (scratch redistribution) utility has determined that fewer than two online LSMs exist within the ACS being scratch balanced. Scratch redistribution cannot redistribute scratch volumes in this configuration.

System Action: The redistribution terminates without moving scratch cartridges.

User Response: If more than one LSM exists within the specified ACS, bring at least two LSMs online (see MODify command), and resubmit the scratch redistribution utility job.

SLS0246I No scratch volumes exist; Scratch Redistribution will not run

Explanation: A SLUADMIN SCREdist (scratch redistribution) utility has determined no scratch volumes exist within the ACS being scratch balanced.

System Action: The utility terminates without moving scratch cartridges.

User Response: Use the SCRAatch update utility to define scratch volumes in the ACS, then resubmit the SLUADMIN utility job.

SLS0247I Offline LSM in path for ejecting volume *volser*

Explanation: A SLUADMIN EJECT utility attempted to eject a cartridge, but the cartridge resides in, or needed to pass-thru, an offline LSM.

System Action: The utility continues without ejecting the cartridge.

User Response: Resubmit the SLUADMIN utility job when all LSMs are online.

SLS0248I CAP is in offline LSM (LSMid AA:LL); eject utility terminating

Explanation: A SLUADMIN EJECT utility attempted to eject a cartridge, but the CAP, from which the cartridge was to be ejected, was in an offline LSM.

System Action: The utility terminates.

User Response: Resubmit the SLUADMIN utility job when all LSMs are online.

SLS0249I Invalid scratch pool specified in PARM parameter of JCL statement

Explanation: The scratch pool specified is not one that is recognized by the SLUADMIN utility.

System Action: The utility terminates processing.

User Response: Specify AL, SL, NL, or NSL for the scratch pool, and resubmit the utility.

SLS0250D Unnamed Cartridge in CAP cell *AA:LL:CC:RR:C*; reply "V,*volser*" or "Eject"

Explanation: A cartridge with no optical label has been found in CAP cell *AA:LL:CC:RR:C* where *RR* is a CAP row and *C* is a CAP column. The operator is requested to provide a volume serial number for the cartridge. The cartridge is "known" by this volume serial number.

System Action: Cartridge entry waits for the operator to respond to the query. If the volume serial number is not a duplicate of another librarycartridge, it is entered into the library.

If an invalid response is entered, message SLS0926I is issued, then message SLS0250D is reissued.

User Response: Respond with one of the following:

V,*volser*

Where *volser* is the appropriate volume serial number for the cartridge in question.

Eject

If the cartridge is to be ejected.

SLS0251E Cartridge *volser* in CAP cell *AA:LL:CC:RR:C* is a duplicate and cannot be entered

Explanation: A duplicate cartridge *volser* was found in CAP cell *AA:LL:CC:RR:C* where *RR* is a CAP row and *C* is a CAP column. Duplicate cartridges are not allowed to be entered into the library.

System Action: Cartridge entry leaves the cartridge in the CAP cell in which it is found and continues with the next cartridge in the CAP.

User Response: Remove the duplicate cartridge from the CAP. If the cartridge must be entered, eject the other cartridge with the same volume serial number and attempt the cartridge entry again.

SLS0252I Cartridge *volser* entered into LSMid *AA:LL*

Explanation: Volume serial number *volser* is entered into the library. Its location is within the specified ACS and LSM.

System Action: The cartridge is entered, its volume serial number optically verified, and it is moved to its new location.

User Response: None.

SLS0254I Cartridge *volser* ejected to CAP cell *AA:LL:CC:RR:C*

Explanation: Volume serial number *volser* has been ejected and can now be found in the identified CAP.

System Action: The cartridge is ejected, and its volume serial number is deleted from the control data set.

User Response: Manually remove the cartridge from the CAP.

SLS0255E Cartridge *volser* in CAP cell *AA:LL:CC:RR:C* has an invalid *volser* and cannot be entered

Explanation: Volume serial number *volser* contains an invalid character and will not be allowed in the ACS.

System Action: The cartridge is left in the CAP and should be removed when the CAP is opened.

User Response: Remove the cartridge from the CAP.

SLS0256I Scheduled Enter (SEnTER) cancelled

Explanation: A SEnTER command was entered for a CAP which was ejecting. No cartridge was entered, and the EJECT completed without a cartridge being entered.

System Action: None.

User Response: The operator may want to start an ENter on the CAP in order to enter the cartridge needed.

SLS0257I {ENTER|EJECT|END|BEGIN} failed; CAPid AA:LL:CC; DDDD1-DDDD2, CCC...CCC

Explanation: ENTER|EJECT|END|BEGIN failed on specified CAPid (AA:LL:CC) due to an LMU error. DDDD1 is the LMU return code followed by DDDD2, the LMU error category and code. CCC...CCC is a 32-byte description of the error. Possible LMU return codes are:

LMU/LSM Error	Description
6500	- Source is invalid
6501	- Source is empty
6502	- Source volser does not match
6503	- Source volser is not readable
6504	- Unexpected volser on source
6505	- Target is invalid
6506	- Target is full
6507	- Source/target not in same ACS
6508	- Source/target not in same LSM
6509	- Source/target not the same type
6510	- Connecting LSM path unavailable
6511	- LMU is not online
6512	- Lost communications with LMU
6513	- Ended - Overdue Response Handler
6514	- LSM hardware error
6515	- LMU error
6516	- CAP in maintenance mode
6517	- CAP door is open
6518	- Enter request pending
6519	- Eject request pending
6520	- CAP catalog pending
6521	- Drive load error
6522	- Drive unload error
6524	- CAP already resvd to this host
6525	- CAP reserved to another host
6526	- CAP not reserved to this host
6527	- Move is pending to/from CAP
6528	- LMU is dead
6529	- Invalid option flag specified
6530	- Option code is invalid
6532	- Volser unexpectedly readable
6541	- LMU listener attach failed
6542	- LMU timer attach failed
6543	- LMU station driver attach failed
6544	- LMU station simulator attach failed
6545	- LMU simulator attach failed
6546	- LMU worker attach failed
6548	- No HCT address was found in LVT

6549 - Offline rqst already in progress
6550 - Station is not offline
6551 - Station is not online
6552 - LMU does not exist
6553 - Station does not exist
6554 - Source/target not in same panel
6555 - Station is offline
6558 - Invalid function
6568 - No broadcast message present
6574 - Invalid character in volser
6575 - Invalid character in message
6578 - No seq-no on vary station online
6579 - Timeout to vary station online
6582 - Volume motion is complete
6584 - Invalid broadcast id
6586 - Drive active or not rewind
6587 - Drive load failed for special use cartridge
6590 - Unable to allocate station
6591 - Open failed for station
6592 - LSM is offline
6593 - Set host path group failed
6595 - Enter operations terminated
6596 - Cannot cancel enter on rel rqst.
6598 - Invalid response recd from LMU
65A0 - LSM is online
65A1 - LSM is pending online
65A2 - LSM is pending offline
65A3 - LSM is not ready
65A4 - LSM not offline
65A5 - LSM is in maintenance mode
65A6 - LMU I/O error
65A7 - Invalid cancel request
65A8 - Request was canceled
65A9 - Rqst to be canceled not active
65AA - Too late to cancel rqst spec.
65AC - Media miscompare
65AD - Media and volser miscompare
65AE - Incompatible media/drive
65AF - Missing CAP magazine
65FF - Request purged

System Action: The action in progress (ENTER, EJECT, END, or BEGIN) will not complete. The cartridge may be made errant depending on the point at which the failure occurred. This message may be followed by an SDUMP or SVC Dump.

User Response: Attempt to resolve the problem. If this is not possible, retain the dump, a copy of the MVS SYSLOG/SCP CONSLOG, and contact StorageTek Software Support.

SLS0258I Request allowed selection of CAPid AA:LL:CC

Explanation: An ENter or EJect request defaulted to a system-selected CAP (AA:LL:CC). The message indicates the CAP chosen by the system for the request.

System Action: The cartridges requested are ejected/entered via the CAP indicated.

User Response: None.

SLS0261A Open CAPid AA:LL:CC for entering when unlocked

Explanation: CAP processing is attempting to enter cartridges through CAP AA:LL:CC. The CAP door is unlocked when the LSM indicator lights so that the operator may open the door to enter cartridges. The CAP is identified by AA:LL:CC where AA is the ACSid, LL is the LSMid, and CC is the specific CAP number within the LSM.

System Action: The system waits until the operator opens and closes the CAP door at which time the system examines the CAP and attempts to enter cartridges found in the CAP.

User Response: Open the CAP door, place cartridges to be entered in the CAP, and close the CAP door.

SLS0262I Volume *volser* made errant

Explanation: The current location of the volume could not be verified.

System Action: The volume is made errant.

User Response: None.

SLS0263D No storage space available for enter; reply Retry or Abort (R,A)

Explanation: An enter request cannot complete due to one of the following conditions:

- The TLSM parameter was specified on the ENter command, but the requested LSM has insufficient storage space, or is offline or pending offline.
- The requested ACS has insufficient storage space, or all LSMs in the ACS are offline or pending offline.

Note: If an audit is in progress, allocation of new cells is temporarily suspended.

System Action: The cartridge(s) remains in the CAP until the user responds.

User Response: Free the necessary storage space and retry the request, or abort the request and remove the cartridges from the CAP.

If LSM(s) are pending offline, abort the enter request to allow the LSM(s) to go offline. If the cartridges must be entered, modify the LSM(s) online temporarily and retry the enter.

SLS0265A More than one cartridge in CAPid AA:LL:CC; expected only cartridge *volser*

Explanation: Transport enter processing accepts only a single cartridge at a time to be entered and mounted. The referenced CAP contained more than one cartridge when scanned by the LSM.

System Action: Transport entry leaves all cartridges in the CAP and unlocks the door so that all cartridges except the one specified can be removed.

User Response: Open the CAP door, remove all cartridges except *volser*, and close the CAP door.

SLS0266I Invalid function code (XX) passed in parm list

Explanation: An invalid function code (XX) was passed to the CAP error handler program, SLSCASET. Valid function codes are:

- 01 - ENTER
- 02 - EJECT
- 03 - END
- 04 - BEGIN

System Action: This message precedes a user abend U1096, RC=262.

User Response: Retain the SDUMP and a copy of the MVS SYSLOG/SCP CONSLOG. Contact StorageTek Software Support.

SLS0267A CAP processing {ejecting|terminating}; empty CAPid AA:LL:CC

Explanation: Either a CAP eject process has loaded cartridges into the CAP for removal or a CAP enter process was unable to enter volumes from the CAP into the library. The operator can now open the CAP door and remove the cartridges from the indicated CAP.

System Action: The system waits until the operator opens and closes the CAP door at which time the robotics examines the CAP to ensure it is empty. After the system verifies that the CAP is empty, if the CAP process is not terminating, the enter or eject process continues. The system may reissue this message if cartridges are left in the CAP.

User Response: Open the CAP door, remove all cartridges, and close the CAP door. To continue a CAP enter process, wait until the system verifies the CAP is empty and unlocks the CAP door before placing cartridges in the CAP.

SLS0268I UNSELECT failed for *volser*, RC=XXXX; volume is still selected

Explanation: The source location was found empty on an Eject, and the operator requested the operation be ignored. An attempt was made to unselect the volume (*volser*), but that request failed with the specified return code (XXXX).

System Action: The volume remains selected, and a control data set entry still exists because the volume was not fully ejected.

User Response: Determine the appropriate course of action from the return code.

SLS0269I CAP termination found CAPid AA:LL:CC still active; will attempt Drain

Explanation: The HSC is attempting to terminate. CAP processing detects an active CAP for this host and attempts to stop its CAP processing.

System Action: The system invokes an internal end CAP which may cause all cartridges in the CAP to be ejected.

User Response: Wait for further messages which may request operator actions.

SLS0270I Attempt to enter duplicate volume *volser* rejected

Explanation: A SLUADMIN INITIALize cartridge utility (MVS) or ENTER cartridges utility (VM) encountered an attempted entry of a volume (*volser*) that was already in the library.

System Action: The SLUADMIN utility job continues with other volumes.

User Response: If the particular volume is required to be entered, relabel the cartridge, and resubmit the SLUADMIN utility job.

SLS0271I Specified CAPid is not within ACS of Audit

Explanation: A SLUADMIN AUDIt utility requested a specific CAPid for an audit within a specified ACS, but the CAP was in a different ACS than the specified ACS of the audit.

System Action: The audit terminates processing.

User Response: Check the AUDIt utility control statement. Make sure that the specified ACS is actually the ACS containing the elements in which the audit is to be performed; and, if so, either change the CAP parameter to refer to a CAPid within the ACS, or do not specify the CAP parameter, allowing the utility to choose the highest priority CAP available. Then resubmit the SLUADMIN utility job.

SLS0272I Volume *volser* is not in same ACS as CAP

Explanation: A SLUADMIN EJECT cartridge utility specified the Volser of a cartridge which resides in an ACS other than the ACS whose CAP was chosen for ejection.

System Action: The volume is not ejected; the utility continues with the next volume specified.

User Response: Resubmit the SLUADMIN utility job, specifying a CAP from the ACS in which the requested Volser resides.

SLS0273I Attempt to enter unlabeled cartridge rejected

Explanation: A SLUADMIN INITIALize cartridge utility (MVS) or ENTER cartridges utility (VM) encountered an attempted entry of an unlabeled cartridge into the library, and the operator has aborted the entry.

System Action: The SLUADMIN utility job continues with other volumes.

User Response: If the particular cartridge is required to be entered, either label the cartridge with an external volume label, or instruct the operator to reply to the operator message with an acceptable Volser. Then resubmit the SLUADMIN utility job.

SLS0274I Attempt to enter cartridge with invalid label *volser* rejected

Explanation: A SLUADMIN INITIALize cartridge utility (MVS) or ENTER cartridges utility (VM) encountered an attempted entry of a cartridge with an invalid volser or media label.

System Action: The utility job continues with other volumes.

User Response: If the particular volume is required to be entered, relabel the cartridge with an acceptable external label and resubmit the utility job.

SLS0275I One or more requested volumes not in library

Explanation: A SLUADMIN utility function was supplied a specific volume serial number in the Volser parameter that was not defined in the library; the utility function could not process that volume serial number. Rather than ignore this condition, this message is issued to inform the user of an unusual condition.

Note that virtual volumes are not found in the library until VTCS has completed initialization.

System Action: The utility continues processing.

User Response: This error does not cancel the utility function, but you may want to check the utility output to determine if you need to resubmit the SLUADMIN utility job.

SLS0276I HSC server task abend; completion code *XXXXXX*

Explanation: A SLUADMIN utility function encountered an abend in its associated server task running in the HSC address space and terminated. The completion code (*XXXXXX*) indicates the abend code; either System (first three hex digits) or User (last three hex digits).

System Action: The utility terminates processing.

User Response: Contact StorageTek Software Support. There is also an SVC dump from the associated server task abend labeled "UTILITIES ESTAE ROUTINE"; save a copy of this dump to aid in diagnosing the problem.

SLS0277I All journals are logically empty

Explanation: The specified journals had no deltas written to them since the last backup, and, so, were not applied to the control data set during restore processing. This occurred when the restore was performed immediately following a backup and simply means that no journal application to the control database is necessary.

System Action: None.

User Response: None.

SLS0278I LSM server subtask servicing LSMid *AA:LL* abended

Explanation: A SLUADMIN AUDIt utility has detected an LSM server subtask abend in the HSC Address Space and has terminated the audit.

System Action: The utility terminates processing.

User Response: Contact StorageTek Software Support. There will also be an SVC dump from the associated server task abend labeled "AUDIT LSM SERVER ESTAE ROUTINE"; save a copy of this dump to aid in diagnosing the problem.

SLS0279I - SLS0282I

- SLS0279I** An empty but allocated cell detected at cell *AA:LL:PP:RR:CC*
- Explanation:** A SLUADMIN utility function encountered an allocated cell in the control data set. If the utility is VOLRpt, no volume is assigned to the cell. If the utility is AUDIt, the physical cell scan found the cell to be empty.
- System Action:** The utility continues processing.
- User Response:** If this message is issued from an audit with APPLY(YES) specified, the cell is freed. Otherwise, free the cell by running an audit with APPLY(YES) against the panel in which the cell is located.
- SLS0280I** Journaling is not active; journal offload is not performed
- Explanation:** A SLUADMIN Journal OFFLoad utility was attempted against the HSC journals for the installation, but the control data set indicated that journaling was not selected as a LIBGEN option for this installation.
- System Action:** The journal offload cannot be performed.
- User Response:** Refer to the *4400 Automated Cartridge System HSC System Programmer's Guide* (utilities chapter) to determine if a regular BACKup utility should be executed or if the SET utility should be executed to change the recovery technique.
- SLS0281I** Missing or invalid SLSOFF*dd* DD statement
- Explanation:** A SLUADMIN Journal OFFLoad utility could not successfully open the offload file represented by the SLSOFF*dd* DD statement (*dd* = 01 - 02).
- System Action:** The utility terminates processing.
- User Response:** Supply a correct SLSOFF*dd* DD statement to properly reference an offload file, and resubmit the SLUADMIN utility job.
- SLS0282I** Journal at DDname SLSJRN*nn1* successfully off-loaded to data set defined by SLSOFF*nn2* DD statement
- Explanation:** A checkpoint message issued by the SLUADMIN Journal OFFLoad utility indicated that the identified journal file was successfully offloaded to the identified offload file (*nn1* = 01 - 02; *nn2* = 01 - 02).
- System Action:** None.
- User Response:** None.

SLS0283I Offload of journal at DDname SLSJRNnn failed

Explanation: A SLUADMIN Journal OFFLoad utility could not successfully copy the contents of the identified journal file to an offload data set.

System Action: The utility terminates.

User Response: Look at the preceding message to determine the cause of the error, and refer to the explanation and action for it.

SLS0284I SLSOFF02 DD statement specified, but no corresponding SLSJRN02 DD statement

Explanation: A SLUADMIN Journal OFFLoad utility encountered the identified offload file but could not find a corresponding journal file.

System Action: The utility terminates processing.

User Response: Specify corresponding offload and journal file DD statements in the SLUADMIN job JCL, and resubmit the SLUADMIN utility job.

SLS0285I SORT failure; No records were selected for sorting

Explanation: A SLUADMIN utility function requiring the SORT program noticed that there were no records to SORT.

System Action: The utility terminates processing. RC=4.

User Response: Re-evaluate your report selection criteria and re-submit the report request.

SLS0286I DDDDD volumes have been selected for scratching

Explanation: The number printed represents the total number of volumes selected for scratching.

System Action: None.

User Response: None.

SLS0287I VOLSER parameter has a range value error

Explanation: A SLUADMIN utility encountered a SLSIN control statement with a VOLser parameter that had a value in a range format, but the range was illegal. Either the lengths of the low and high values were not equal, the non-incremental portion of the low and high values were not the same, or the incremental portion of the low range was not less than the incremental portion of the high range.

System Action: The utility terminates processing.

User Response: Correct the range value on the VOLser parameter of the control statement and resubmit the SLUADMIN utility job.

SLS0288I User not authorized to use this utility function

Explanation: A SLUADMIN utility function that required execution out of an authorized library detected that it was invoked out of an unauthorized library. Either there has been an attempt to use a SLUADMIN utility function by an unauthorized user, or the utility software was improperly installed.

System Action: The utility terminates processing.

User Response: You should check with your local systems programming staff to clarify your requirements for needing the StorageTek automated library utility function. System programming should assure that the library software is properly installed in an authorized library.

SLS0289I SORT failure; refer to the sort message data set or job log

Explanation: A SLUADMIN utility function requiring the SORT program encountered an error return code from SORT.

System Action: The utility terminates processing.

User Response: Refer to the sort message data set (SYSOUT DD) or job log (if there is no SYSOUT DD) for a message from SORT, correct the problem, and resubmit the SLUADMIN utility job.

SLS0290I Subsystem is active on this host; restore terminated

Explanation: The RESTore utility detected that the HSC software subsystem was active on the host on which the restore operation was running. A restore operation requires that the subsystem not be running.

System Action: The utility terminates processing.

User Response: Bring down the subsystem, and rerun the RESTore utility.

SLS0291I Volume *volser* is currently errant; unavailable for processing

Explanation: A SLUADMIN utility function was attempting to perform utility-specific processing against a specific volume serial number (*volser*), but the volume was errant (lost) at that time and the utility process could not be performed.

System Action: The utility continues processing with the next volume serial number.

User Response: This is not considered an error, but you may want to resubmit the SLUADMIN utility job after the next HSC subsystem initialization has been performed or after errant recovery for the volume has been accomplished.

SLS0292I Scratch Redistribution failed - target LSM AA:LL has no available cells

Explanation: A SLUADMIN utility function was attempting to perform SCREdist (scratch redistribution), but the LSM specified had no available cells in which to move a scratch volume. There must be at least one free cell in every target LSM for scratch redistribution to take place.

System Action: The utility terminates processing.

User Response: Attempt to free a cell within the specified LSM, and resubmit the utility job or reduce the scope of the redistribution to LSMs which have at least one free cell.

SLS0293I SLSTAPE DD statement does not identify a library transport

Explanation: A SLUADMIN INITIALize cartridge utility encountered an SLSTAPE DD statement that did not represent a library transport.

System Action: The utility terminates processing.

User Response: Change the JCL so that the SLSTAPE DD statement identifies a valid library transport. Then resubmit the SLUADMIN utility job.

SLS0294I SLSTAPE DD statement identifies a library transport in a different ACS than the specified CAPid

Explanation: A SLUADMIN INITIALize cartridge utility requesting a specific CAP encountered an SLSTAPE DD statement that allocated a library transport in a different ACS than the specified CAPid.

System Action: The utility terminates processing.

User Response: Either change the JCL so that the SLSTAPE DD statement identifies a specific library transport in the same ACS as the specified CAP, or change the initialize cartridge utility control statement CAP parameter. Then resubmit the SLUADMIN utility job.

SLS0295I Scratch Redistribution failed; too many LSMids specified

Explanation: More LSMids were used as a parameter to the SCREdist (scratch redistribution utility) than were defined in the LIBGEN.

System Action: The utility terminates processing.

User Response: Resubmit the utility with the correct number of LSMids specified.

SLS0296I Scratch Redistribution prematurely ended; even distribution may not have occurred

Explanation: Prior to termination of the SCREdist (scratch redistribution) utility, it was determined that the number of scratch volumes in a particular LSM was greater than the expected value.

System Action: The utility completes processing.

User Response: Evaluate the spread of scratch volumes across LSMs within the given ACS and determine if the spread is sufficient. If sufficient, do nothing further. If not sufficient, try to determine why the spread of volumes was not as expected (average number of scratch volumes per LSM, plus or minus the scratch tolerance level). Resubmit the utility, if necessary, to complete process.

SLS0297I VOLSER parameter not present with SCRATCH or UNSCRATCH option

Explanation: A SLUADMIN SCRATCH update utility encountered a SCRATCH or UNSCRATCH control statement without the required VOLSER parameter identifying which volumes to scratch or unscratch.

System Action: The utility terminates processing.

User Response: Supply a VOLSER parameter on the SCRATCH or UNSCRATCH control statement, and resubmit the SLUADMIN utility job.

SLS0298I Missing or invalid SLSSOUT DD statement

Explanation: A utility function could not locate the required output file in which to put selected transactions.

System Action: The utility terminates processing.

User Response: Supply the SLSSOUT DD statement, and resubmit the utility job.

SLS0299I Unexpected return code; RC=XXXXXXXX

Explanation: A SLUADMIN utility received an unexpected return code from an HSC address space component.

System Action: Utility processing continues, and a final condition code of 4 is returned.

User Response: Contact StorageTek Software Support.

SLS0303I All nonlibrary drives are offline or allocated

Explanation: A swap message was issued, but all non-library drives were unavailable for the swap.

System Action: This message is issued, and a library drive is selected for the swap to complete.

User Response: Follow the instructions of the messages to follow.

SLS0306I Swap to nonlibrary: XXXX1 {XXXX2 XXXX3 XXXX4 XXXX5 XXXX6 XXXX7
XXXX8}

Explanation: A swap has been requested. The from-transport is not a library transport so the library has presented a list of non-library to-transport (XXXX1 - XXXX8).

System Action: The system waits until you respond to the swap message.

User Response: You can either elect to specify one of the non-library transports or elect some other transport on which to perform the swap.

SLS0308I Swap to library: XXXX1 {XXXX2 XXXX3 XXXX4 XXXX5 XXXX6 XXXX7
XXXX8}

Explanation: A swap has been requested. The from-transport is a library transport so the library has presented a list of library to-transport (XXXX1 - XXXX8).

System Action: The system waits until you respond to the swap message.

User Response: You can either elect to specify one of the library transports or elect some other transport on which to perform the swap.

SLS0310I Swap will be automated

Explanation: A swap has been requested. Both the from-transport and the to-transport are in the same ACS. The swap will be processed automatically by the library system.

System Action: When the SWAP PROCEEDING (IGF502E) message appears, the library system performs the swap.

User Response: None.

SLS0312D Allow mount of *volser* on *XXXX*; Reply 'Y' or 'N'

Explanation: A dynamic allocation request was received to mount *volser* on transport *XXXX*. Y=yes; N=no.

System Action: The job waits.

User Response: If the dynamic allocation is to be permitted for the job, reply Y; otherwise, reply N.

SLS0313E SLS WTO intercept not enabled; Code - *D*

Explanation: The subsystem could not enable the WTO subsystem request. *D* describes the problem:

4 - No available slots in the SSVT.

System Action: Processing continues. Automated cartridge handling is disabled.

User Response: Contact StorageTek Software Support.

SLS0315I Job Processing user exit function code invalid; code = *XX*

Explanation: Probable user error. The function code returned from Job Processing user exit was not one of the following:

C"1" - UX01MNT - Mount function

C"2" - UX01DMNT - Dismount function

C"3" - UX01SWAP - Swap drive

C"4" - UX01RPLY - Reply to message

C"5" - UX01NOP - No operation to be performed.

System Action: Validate and correct function code in user exit.

User Response: Enable user exit, and verify that the function code is correct.

SLS0316I Job Processing user exit return code invalid; RC = *XX*

Explanation: Control was returned to Job Processing, and it was determined that the return code in register 15 from the Job Processing user exit was invalid.

System Action: Probable user error. Return code from Job Processing user exit was not one of the following:

- 0 HSC to interpret message.
- 4 Message interpreted by user exit. HSC acts per user exit direction.
- 64 User exit not operational. Messages to be interpreted by HSC.

User exit SLSUX01 has been DISABLED.

User Response: Correct user error. Enable user exit again and determine if user exit functions successfully.

SLS0317I Mount of library volume *volser* on nonlibrary device *XXXX*

Explanation: An attempt was made to mount a library volume on a non-library transport.

System Action: None.

User Response: You may eject the volume to satisfy the mount request.

SLS0318I Subpool *CCCCCCCCCCCC* invalid in User Exit 01; subpool not defined

Explanation: Control was returned to Job Processing. The Subpool returned from User Exit 01 could not be found in the system and, therefore, is invalid.

System Action: Probable user error. The Subpool returned from User Exit 01 was not found in the system, and the user exit was marked unusable. No further calls to User Exit 01 will be made until the problem has been corrected and the User Exit has been enabled.

User Response: Correct user error. Enable user exit again and determine if user exit functions successfully.

SLS0319I Invalid Drive ID *XXXX* from User Exit 01

Explanation: The drive address returned by User Exit 01 to Job Processing was considered invalid, since no matching UCB could be found in the system.

System Action: Probable user error. The HSC will attempt to handle the message that caused User Exit 01 to return the bad drive address. If the HSC is able to handle the message and if a scratch subpool was picked by User Exit 01, the HSC will attempt to honor that subpool.

User Response: Notify the Systems Programmer responsible for maintaining User Exit 01. Retain the console log from the time of the error. If possible, keep a copy of the JCL for the job which caused the error. StorageTek Software Support may be called for advice in setting up a GTF trace of the User Exit 01 parameter list, to assist the Systems Programmer in debugging.

SLS0320I Parse error RC *NN* on message *CCCCCCC* for job *JJJJJJJJ*

Explanation: The HSC received an error while trying to parse message *CCCCCCC*, which was issued from job *JJJJJJJJ*. The parse return code was *NN*.

System Action: The HSC will take no further action based on the message. Processing will continue, although the HSC may not be performing desired functions (for example, Mounts and Dismounts) for job *JJJJJJJJ*.

User Response: This is a warning of a serious error in either the operating system or the HSC. Retain the console log from the time of the error. If possible, keep a copy of the JCL for the job which caused the error. Contact StorageTek Software Support.

SLS0350I Invalid TMS specified in PARM parameter of JCL

Explanation: The name specified in the PARM field for the Scratch Conversion utility of the SCRATCH update function is not TMS, TLMS or RMM.

System Action: The utility terminates processing.

User Response: Correct the value, and resubmit the Scratch Conversion utility of the SCRATCH update function.

SLS0351I Scratch cartridges are within scratch tolerance level - Scratch Redistribution completed successfully

Explanation: A SCREdist (scratch redistribution) utility function completed successfully, and LSMs involved in the process contain the number of scratch cartridges that fall within the scratch tolerance level.

System Action: None.

User Response: None.

SLS0352I Audit unable to physically scan cell *AA:LL:PP:RR:CC*

Explanation: A SLUADMIN AUDIt utility function was unable to perform a physical scan of the specified cell (*AA:LL:PP:RR:CC*). If the audit is “active” (APPLY(YES) specified or defaulted on the control statement), corrective action could not be performed for that cell.

System Action: The situation is treated as a condition code 4 error; the audit job continues.

User Response: Depending on the cell contents and condition of the control data set, a secondary audit may have to be run against a library element containing the identified cell.

SLS0353I Audit unable to eject volume *volser* at cell *AA:LL:PP:RR:CC* which is a duplicate with volume in cell *AA:LL:PP:RR:CC*

Explanation: A SLUADMIN AUDIt utility function has encountered more than one library cartridge with the specified volume serial number (*volume*). The first specified location (*AA:LL:PP:RR:CC*) refers to the duplicate, and the second refers to the original. An attempt was made to eject the duplicate, but the audit encountered an LMU error and was unable to successfully eject the duplicate volume.

System Action: The situation is treated as a condition code 4 error; the audit job continues.

User Response: If an error persists, contact your local StorageTek CSE. Depending on which volume should be in the library, the volume left in the library may have to be ejected, the duplicate located, and re-entered.

SLS0354I Audit unable to eject cartridge at cell *AA:LL:PP:RR:CC* which has an unreadable or illegal external label

Explanation: A SLUADMIN AUDIt utility encountered an unlabeled cartridge, a cartridge with an unreadable external label, or a cartridge with a label containing illegal characters in the defined location (*AA:LL:PP:RR:CC*). An attempt was made to eject the cartridge, but the audit encountered an LMU error and was unable to successfully eject the cartridge.

System Action: The situation is treated as a condition code 4 error; the audit job continues.

User Response: If an error persists, contact your local StorageTek CSE. The cartridge should be located, and the label examined. If the label is destroyed, it should be relabeled and re-entered into the library or replaced in its original location and another audit performed on a library element containing its cell location.

SLS0355I ROW parameter not allowed with PANEL value list parameter

Explanation: A SLUADMIN AUDIt utility encountered a control statement with a ROW parameter and a PANel parameter that has a value list (more than one Panel id). There can only be one panel identified on the AUDIt control statement if the ROW parameter is supplied.

System Action: The control statement is ignored.

User Response: Correct the parameters on the control statement, and resubmit the SLUADMIN utility job.

SLS0356I COLUMN parameter not allowed with ROW value list parameter

Explanation: A SLUADMIN AUDIt utility encountered a control statement with a COLumn parameter and an ROW parameter that has a value list (more than one ROW id). There can only be one ROW identified on the AUDIt control statement if the COLumn parameter is supplied.

System Action: The control statement is ignored.

User Response: Correct the parameters on the control statement, and resubmit the SLUADMIN utility job.

SLS0357I Row index XX is invalid

Explanation: The row number (XX) obtained through the ROW parameter on a SLUADMIN AUDIt utility function control statement is invalid.

System Action: The utility terminates processing.

User Response: Respecify the ROW parameter, and resubmit the SLUADMIN utility job.

SLS0358I Column index XX is invalid

Explanation: The column number (XX) obtained through the COLumn parameter on a SLUADMIN AUDIt utility function control statement is invalid.

System Action: The utility terminates processing.

User Response: Respecify the COLumn parameter, and resubmit the SLUADMIN utility job.

SLS0359I Volume *volser* successfully ejected from library via CAPid *AA:LL:CC*

Explanation: A SLUADMIN utility function involving cartridge ejection has successfully moved the identified volume serial number (*volser*) to the specified Cartridge Access Port (CAP).

System Action: The cartridge is ejected from the control data set.

User Response: None. (The operator is informed that the cartridge has been ejected and is required to empty the CAP either when the CAP is full or when the SLUADMIN utility function completes.)

SLS0360E {EJECT|AUDIT} Utility unable to reserve CAPid *AA:LL:CC*; utility waiting

Explanation: A SLUADMIN utility function requiring a Cartridge Access Port (CAP) either could not allocate the specific CAP (if a CAP parameter was specified on the utility control statement) because that CAP was in use by another process, or no unreserved CAPs with a non-zero preference priority exist in the ACS where the CAP is required.

System Action: The utility waits until either a non-zero priority CAP becomes available or until the specific CAP is available.

User Response: Either cancel the utility and specify a different CAPid, or wait for the process using the specific CAP to complete. The utility continually attempts to acquire the CAP. If no CAP was specified, display the preference priorities for CAPs in the ACS, and set an available CAP preference to non-zero (see Display and CAPPref library commands), and resubmit the SLUADMIN utility job.

SLS0361I Duplicate CAPid *AA:LL:CC* specified; duplicate is ignored

Explanation: A SLUADMIN EJECT cartridges utility specified the same CAPid (*AA:LL:CC*) multiple times on the utility control statement.

System Action: The SLUADMIN utility job continues, while ignoring multiple occurrences of previously specified CAPids.

User Response: Remove the duplicate CAPid specification on the utility control statement.

SLS0362I HSC server task abended for CAPid AA:LL:CC; remaining ejects for this CAPid not performed

Explanation: A SLUADMIN EJECT cartridges utility has encountered an abend in its associated Server Task running in the HSC address space and has terminated the eject process for the CAPid (AA:LL:CC).

System Action: The utility terminates processing for this CAPid. Any other active CAPids associated with this EJECT cartridges utility continues.

User Response: Contact StorageTek Software Support. An SDUMP from the associated Server Task abend labeled "MULTI-CAP EJECT SUBTASK; ESTAE ROUTINE" is produced. Save a copy of this dump to aid in diagnosing the problem.

SLS0363I Invalid specification of MIXED in PARM field of JCL statement

Explanation: The name specified in the PARM field for Mixed case report headings and messages is invalid.

System Action: The utility is terminated.

User Response: Specify Mixed correctly, and resubmit the SCRATCH update conversion program.

SLS0364I Volume *volser* not ejected from library due to HSC server abend

Explanation: A SLUADMIN EJECT cartridges utility has encountered an abend in its associated Server Task running in the HSC address space and has terminated with volume (*volser*) still remaining to be ejected. This message is issued in association with error message SLS0362I.

System Action: Volume (*volser*) is not ejected.

User Response: A SLUADMIN EJECT cartridges utility will need to be executed for the volume (*volser*).

SLS0365I An audit of LSM AA:LL, panel *PP* is recommended

Explanation: While running the SCREDIST (scratch redistribution) utility, a discrepancy was found between the control data set location and the physical location in the library.

System Action: None.

User Response: It is recommended that an audit of at least the specified panel be run to correct the discrepancy.

- SLS0366I** Volume *volser* not found in location (*AA:LL:PP:RR:CC*) specified in Control Data Set
- Explanation:** During the process of verifying a volume and its location, the volume did not match the location specified in the control data set.
- System Action:** The volume was not moved during this operation.
- User Response:** An attempt should be made to locate the volume in question. If necessary, perform an audit of the panel where the volume resided.
- SLS0367I** External label on volume *volser* is unreadable
- Explanation:** While running the SCREdist (scratch redistribution) utility, the label on the referenced volume was not readable.
- System Action:** The volume was not moved during this operation. The control data set has been marked to reflect this condition.
- User Response:** The referenced volume should be ejected from the library and its external label examined to determine why the label is not readable. If this condition exists on several volumes, report this condition to a StorageTek CSE.
- SLS0368I** Cell *AA:LL:PP:RR:CC* is empty - found during Scratch Redistribution
- Explanation:** While running the SCREdist (scratch redistribution) utility, the cell in question was found to be empty. The control data set indicated the cell contained a scratch volume and was attempting to move it when this condition was discovered.
- System Action:** None.
- User Response:** Audit the specified cell to correct this condition.
- SLS0369I** Volume *volser* is a cleaning cartridge; labelling ignored
- Explanation:** While running the initialize cartridge utility, a cartridge was entered whose Volser matches that of the cleaning cartridges. The tape is not initialized but is entered into the LSM.
- System Action:** None.
- User Response:** If the cleaning cartridge was intended to be entered, do nothing. If the cleaning cartridge was unintentionally entered, you may wish to eject the cartridge.

SLS0370I Volume *volser* is a cleaning cartridge; cannot be entered into Scratch List

Explanation: A SLUADMIN SCRAtch update utility attempted to add a specified volume serial number (*volser*) to the library scratch pool, but the Volser qualifies as a library cleaning cartridge and cannot be treated as a scratch volume.

System Action: The utility continues processing.

User Response: The error does not cancel the SCRAtch update utility, but you may want to check the specified volume serial number, correct it, and resubmit the SLUADMIN SCRAtch update job.

SLS0373I DDname *CCCCCCCC* failed to open

Explanation: An attempt to open the specified file was not successful.

System Action: Refer to operating system messages and codes for appropriate action.

User Response: Make the necessary correction, and run the utility again.

SLS0374I Cleaning cartridge prefix has been set to *CCC*

Explanation: The Auto-Clean conversion utility ran successfully, and the prefix for the auto-clean cartridges was set to *CCC*.

System Action: None.

User Response: None.

SLS0375I Duplicate Data Set names have been found

Explanation: An attempt was made to run a utility, and it was found during execution that duplicate data set names existed for multiple DD statements.

System Action: Verify data set names on all DD statements.

User Response: Make the necessary corrections, and run the utility again.

SLS0376I Volume *volser* is now unselected; owning host was *CCCCCCCC*

Explanation: The UNSElect utility ran successfully, and the specified volume is now unselected. The host owning the volume is specified.

System Action: None.

User Response: None.

SLS0377I Volume *volser* was not selected

Explanation: The UNSElect utility found that the specified volume was not selected.

System Action: None.

User Response: None.

SLS0378I *volser* not ejected, not found in cell; IGNORED

Explanation: During EJECT processing, a volume to be ejected was not found in its cell. The following messages may also be issued by HSC at the console: SLS0698I, SLS0699I, and SLS0925D. The operator replied "I" in response to SLS0925D.

System Action: EJECT continues without ejecting the cartridge. Condition code 4 is set.

User Response: None necessary; however, it may be desirable to run the AUDIt utility in an attempt to locate the volume.

SLS0379I *volser* not ejected, not found in cell; DELETED FROM CONTROL DATA SET

Explanation: During EJECT processing, a volume to be ejected was not found in its cell.

System Action: EJECT continues without ejecting the cartridge. The corresponding volume record is deleted from the control data set.

User Response: None necessary; however, it may be desirable to run the AUDIt utility in an attempt to locate the volume.

SLS0380I Unable to communicate with *CCCCCCCC* to unselect *volser*

Explanation: The UNSElect utility attempted to route the unselect request to the specified host in order to ensure that some in-memory tables were updated was unsuccessful.

System Action: The utility terminates.

User Response: Re-establish communication with the specified host, or run the UNSElect utility on the specified host.

SLS0381A {AUDIt|EJect|INITialize} Utility unable to reserve a CAP in ACS AA;
utility waiting

Explanation: A SLUADMIN utility function could not allocate a required CAP in the specified ACS because all CAPs were in use by another process, or no unreserved CAPs with a non-zero preference priority exist in the ACS where the CAP is required.

System Action: The utility waits until a non-zero priority CAP becomes available or until a zero priority CAP in the specified ACS is made non-zero.

User Response: Display the preference priorities for CAPs in the ACS, and set the preference of an available CAP to non-zero (see Display and CAPPref library commands). The utility continually attempts to acquire a CAP, so the newly preferred CAP is selected.

SLS0382I SMF input file is not sorted by SMF record type, Date and Time;
utility terminated

Explanation: A request to run the HSC Activities Report utility was made, but the SMF input data was not sorted by SMF record type, date and time.

System Action: The utility terminates.

User Response: Sort the SMF input data specifying the sort control statements as follows:

```
INCLUDE COND=(6,1,BI,EQ,'FF')
SORT FIELDS=(15,4,CH,A,11,4,PD,A,7,4,BI,A)
SUM FIELDS=NONE
```



Note: X'FF' is the SMFid default of 255. SMFid range can be from 00-FF and should match SMFid you are using.

After sorting the SMF data, change Activities Report JCL to point to the newly sorted file, if necessary, and rerun the job.

SLS0383I I/O error CCCCCCCC

Explanation: An I/O error occurred against one of the utility data sets. CCCCCCCC is message information describing the error. This could include the jobname, unit address, DD name, a hex dump of the DECB ECB, and the relative block number.

System Action: The utility terminates.

User Response: Correct the problem, and rerun the utility.

SLS0384I CCCCCCCC parameter changed from DDDDDDDD to EEEEEEEE

Explanation: The SET utility successfully changed the CCCCCCCC parameter from DDDDDDDD to EEEEEEEE.

System Action: None.

User Response: None.

SLS0385I Hostid CCCCCCCC is active

Explanation: The utility has determined that the specified host is active; however, the requested function requires the specified host to be down.

System Action: The utility terminates.

User Response: Ensure the specified host is inactive, and rerun the utility.

SLS0386I HOSTid CCCCCCCC is active

Explanation: The SET utility has determined that the specified host is active; however, the requested function requires the specified host to be inactive.

System Action: The utility terminates.

User Response: Rerun the utility specifying an inactive HOSTid.

SLS0387I Parameter CCCCCCCC1 would create duplicate values of CCCCCCCC2

Explanation: The SET utility has determined that a parameter specified duplicate values.

System Action: The utility terminates.

User Response: Rerun the utility, but do not specify duplicate parameters.

SLS0388I Hostid CCCCCCCC not found.

Explanation: The Hostid CCCCCCCC was not found in database.

System Action: The utility terminates processing.

User Response: Correct the Hostid to be a valid CDS host and resubmit the job.

SLS0389I Database not formatted for dynamic Host addition.

Explanation: The Database must be at HSC Release 2.1.0 or above to add a new Host to the database.

System Action: The utility terminates processing.

User Response: Install the current release of HSC and rerun the utility job.

SLS0390I Database already contains maximum number of Hostids.

Explanation: The database already contains 16 Hostids.

System Action: The utility terminates processing.

User Response: Verify all Host in database are required by your installation. If so, you may not add another Host to this configuration. If not, rerun LIBGEN to delete the inactive Host and add the new Host.

SLS0391I All host DHBEFLAGS reset in CDS

Explanation: During execution of the SLUADMIN RESTore utility, after primary CDS is reconstructed, but before it is copied to the secondary copy, all DHBEFLAGS for all hosts were reset to null. This insures all hosts start normal with no residual status information.

System Action: None.

User Response: None.

SLS0392I Option CCC...CCC is invalid

Explanation: The option specified (CCC...CCC) is invalid.

System Action: The utility terminates processing.

User Response: Respecify the option, and resubmit the utility job.

SLS0393I Cell location parameter contains non-hex value

Explanation: A value in the cell location parameter does not contain valid hex data.

System Action: The utility terminates processing.

User Response: Correct the cell location parameter, and resubmit the utility job.

SLS0394I Audit at ROW or COLUMN level of non-existent cell *AA:LL:PP:RR:CC*

Explanation: A SLUADMIN AUDIt utility function was unable to perform a ROW or COLumn level audit of the specified cell (*AA:LL:PP:RR:CC*). This is due to the cell location specified being a non-existent cell.

System Action: No corrective action is required; however, you may wish to modify the AUDIt control statement to exclude non-existent cell(s). This is treated as a condition code 4 error, and the audit job continues.

User Response: None necessary; however, it may be desirable to modify similar AUDIt utility control statements to exclude non-existent cells when the audit is at the ROW or COLumn level.

SLS0395I Panel free-cell count corrected for LSMid *AA:LL*, panel *PP*

Explanation: A SLUADMIN AUDIt utility function found that the free-cell count for the panel *PP* in LSM *AA:LL* disagreed with the actual number of free cells found by the audit. This message is only issued when audits are performed at the panel level or higher (i.e., LSM or ACS). The count was corrected to agree with the actual number of free cells detected.

System Action: No corrective action is required. The audit job continues.

User Response: None.

SLS0396I LSM free-cell count corrected for LSMid *AA:LL*

Explanation: A SLUADMIN AUDIt utility function found that the free-cell count in LSM *AA:LL* disagreed with the actual number of free cells found by the audit. This message is only issued when audits are performed at the LSM or ACS level. The count was corrected to agree with the actual number of free cells detected.

System Action: No corrective action is required. The audit job continues.

User Response: None.

SLS0397I Volume *volser* not found in library; not ejected

Explanation: A SLUADMIN INIT utility function was attempting to perform EJECT processing against a specific volume serial number (*volser*), but the *volser* was no longer in the library.

System Action: This is the result of the *volser* (*volser*) being ejected through another CAP before the INIT job has completed. A return code of 4 is set, and processing continues with any other EJECT requests that may be present.

User Response: None.

SLS0398I - SLS0411I

SLS0398I Host *CCCCCCCC* added to database.

Explanation: The Newhost *CCCCCCCC* was added to the database.

System Action: The utility terminates processing.

User Response: No action required.

SLS0399I Parameter *CCCCCCCC* has an invalid syntax

Explanation: A SLUADMIN utility encountered a SLSIN control statement containing a parameter (*CCCCCCCC*) with invalid syntax such as a missing closing parenthesis.

System Action: The control statement is ignored.

User Response: Correct the syntax of the parameter on the control statement, and resubmit the SLUADMIN utility job.

SLS0404I Volume Serial *volser* found selected at HSC Termination

Explanation: A library volume (*volser*) was found selected during termination of the Host Software Component. This indicates the volume is still in use, or a Host Software Component (HSC) function abended while “owning” that volume, i.e., had it selected, and the operator then stopped the HSC.

System Action: HSC Termination unselects the volume.

User Response: None.

SLS0410I Free-Cell count error detected for LSM *AA:LL*, Panel *PP*

Explanation: The record in the HSC Control Data Set (CDS) which tracks available Free Cells for LSM *AA:LL* has an error for Panel *PP*. The HSC attempts to allocate a free cell in another panel in this LSM.

System Action: There is no immediate action to be taken. However, an audit for the specified panel *PP* in LSM *AA:LL* should be scheduled to correct the CDS error.

User Response: None.

SLS0411I Free-Cell count error detected for LSM *AA:LL*

Explanation: The record in the HSC Control Data Set (CDS) which tracks available free cells for LSM *AA:LL* has an error. The LSM free cell count was non-zero, but there were no free cells available in any of the panel free cell maps. The HSC will zero the LSM free cell count.

System Action: There is no immediate action to be taken. However, an audit for LSM *AA:LL* should be scheduled to verify the CDS cell allocation information.

User Response: None.

SLS0451I No matching HOSTid

Explanation: The host identifier found in the LVT does not match any host identifier found in the LCT. Configuration initialization could not complete.

System Action: The HSC terminates processing.

User Response: Possible LIBGEN error or execution of the HSC on a non-LIBGENed host is being attempted. Check the input on the LIBGEN macros; if an error is found, regenerate the control data set with another LIBGEN.

SLS0452I Attach failed for module SLSFLSMC

Explanation: Configuration Control initialization received an error return code from ATTACH when attaching SLSFLSMC (the LSM Change Function Listener Task) load module.

System Action: The HSC terminates processing.

User Response: Make sure that the SLSFLSMC load module is in a library available to the HSC through its JOBLIB or link list.

SLS0453I LMU error XXXXXXXX varying {ACS AA|station C...C} online

Explanation: A Configuration Control function received an error from the LMU driver (return code = XXXXXXXX) when attempting to vary station (device address C...C)|ACS AA online.

System Action: The Configuration Control function is aborted. This may cause other higher level functions to be aborted as well.

User Response: Examine MVS SYSLOG for LMU I/O errors which occurred during the same time frame to determine if it is an LMU device error, or a software problem. If a software problem is suspected, contact StorageTek Software Support.

SLS0454I Error reading LMU configuration

Explanation: A Configuration Control function received an error from the LMU driver when attempting to read the LMU configuration.

System Action: Configuration verification is aborted and causes the ACS to remain disconnected.

User Response: Examine MVS SYSLOG/SCP CONSLOG to determine if the problem is an LMU I/O error or a software problem. If a software problem is suspected, contact StorageTek Software Support.

SLS0456I Station XXX varied offline

Explanation: Due to a previously reported error in a Configuration Control function, the specified station (XXX) had to be varied offline.

System Action: The HSC varies the station offline.

User Response: Check for previous Configuration Control and LMU error message(s) to determine why the station had to be varied offline. If the problem persists, contact StorageTek Software Support.

SLS0457I LMU error XXXXXXXX modifying LSMid AA:LL online

Explanation: A Configuration Control function received an error return code (XXXXXXXX) from the LMU driver when attempting to modify a specific LSM (AA:LL) online.

System Action: The LSM remains offline.

User Response: Ensure the LMU is in communication with the host, is online, and the LSM is ready, and reissue the command.

SLS0458I LMU error XXXXXXXX modifying LSMid AA:LL offline

Explanation: A Configuration Control function received an error return code (XXXXXXXX) from the LMU driver when attempting to modify a specific LSM (AA:LL) offline, possibly even after issuing operator command MODify lsm OFFline with the FORCE option.

System Action: The modify request is aborted. The LSM is left in its prior state.

User Response: Ensure the LMU is in communication with the host, is online, and the LSM is ready, and reissue the command. If that is unsuccessful, vary the LMU stations offline and reissue the command.

SLS0460I LSM AA:LL Mismatch - LMU Value *T* CDS Value *T*

Explanation: The Configuration Control verification function detected a mismatch between the LSM configuration defined in the LMU and that found in the control data set for LSM AA:LL. Each *T* will be replaced by one of the following values:

X - the LSM is defined as a 4410 or 9310
 3 - the LSM is defined as a 9360
 6 - the LSM is defined as a 9740
 7 - the LSM is defined as a SL8500
 . - the LSM is not defined

System Action: Configuration Control verification continues in order to report on all mismatches. The HSC remains up, but the station (LMU) will stay offline.

User Response: A comparison of the two LSM type values shows where the differences in LSM configurations are. Based on the actual physical configuration, (1) change the LIBGEN parameters to correspond to the LMU configuration and regenerate the control data set with another LIBGEN or (2) have the Sun Microsystems CSE change the LMU configuration to match the LIBGEN parameters.

SLS0500I LICENSED/SECRET/UNPUBLISHED WORK/COPYRIGHT (YYYY-YYYY) STORAGETEK

Explanation: This message is issued during host software initialization.

System Action: None.

User Response: None.

SLS0501I Module CCCCCCCC return code XXXXXXXX

Explanation: The module called completed with a return code of XXXXXXXX during initialization or termination list processing.

System Action: For most errors, the HSC terminates to the next level when an error is encountered during initialization. For certain severe errors, the HSC terminates. When an error is encountered during termination, the HSC continues termination processing.

User Response: If the problem occurs consistently during initialization or termination and the return code does not give sufficient information to point to the problem, contact StorageTek Software Support.

SLS0503I SMF subtype *XX* is invalid and is ignored

Explanation: The SUBPARM parameter for this subsystem specified an invalid subtype. The allowed values are between "1" and the documented maximum value.

System Action: The value was ignored, and processing continues with the next subtype value, if any.

User Response: If the installation wishes to change the subtypes being recorded, edit the appropriate SMFPRMxx member in "SYS1.PARMLIB" specifying SUBPARM(ssnx(SUBTYPE(a,b,c...))) with the correct subtypes. Then issue a SET SMF to place those subtypes into effect.

SLS0504I Error processing *CCCCCCCC1*; abend *CCCC2 RCXXXXXXXX*

Explanation: The call to module *CCCCCCCC1* completed with either a user or a system abend (*CCCC2*) and reason code *RCXXXXXXXX* during initialization or termination list processing.

System Action: Depending on the type of abend, initialization/termination may continue.

User Response: Look for any related messages in the SYSLOG and the Job Log. If the problem is a system abend, consult the IBM MVS Extended Architecture Message Library: System Codes Manual. If the problem is a user abend, consult Chapter 3 of the StorageTek 4400 ACS *HSC Messages and Codes Manual* for the MVS environment and the *SCP Messages and Codes Manual* for the VM environment. If you are unable to solve the problem using these manuals, contact StorageTek Software Support.

SLS0505I SSCVT *CCCC* not allocated for HSC subsystem

Explanation: During initialization, the HSC subsystem detected that no SSCVT had been created for this invocation of the subsystem.

System Action: The HSC terminates processing.

User Response: Ensure that the HSC subsystem is properly defined in the IEFSSNxx member of SYS1.PARMLIB and that module SLSBPRES is present in a library in the system linklist.

SLS0506I Modify commands not supported by *CCCC* HSC subsystem

Explanation: A MODify (F) command was directed to the HSC subsystem. The modify interface is not supported at this time.

System Action: The command is rejected.

User Response: None.

SLS0507I HSC preinitialization failure

Explanation: During initialization, the HSC subsystem detected an error in preinitialization.

System Action: The HSC terminates processing.

User Response: Contact StorageTek Software Support.

SLS0508I Multiple subsystem start not allowed; ACS CCCC
{ACTIVE|TERMINATING|INITIALIZING| RECONFIGURING|INVALID FLAG} in
single mode

Explanation: An attempt to start an additional HSC subsystem was rejected because another HSC subsystem is running in single mode.

System Action: The new subsystem terminates processing and the running subsystem continues processing.

User Response: Determine which subsystems are to be running and start or stop the correct subsystems.

SLS0509I Single mode HSC start rejected; another HSC subsystem is active

Explanation: An attempt to start an HSC subsystem was rejected because another HSC subsystem was running.

System Action: The new subsystem terminates processing, and the running subsystem continues processing.

User Response: Determine which subsystems are to be running, and start or stop the correct subsystems.

SLS0510I Multiple SSCVTs exist for HSC subsystem CCCC

Explanation: During subsystem initialization, the subsystem detected the presence of two HSC SSCVTs having the same SSCTSNAM field.

System Action: The HSC terminates processing.

User Response: Ensure that the subsystem name table only has one entry for the HSC subsystem. Re-IPL to recreate the SSCVT chain.

SLS0511I All keywords following error are ignored

Explanation: The EXECParm statement contained invalid keywords. Parsing stopped at the keyword displayed in the previous message, and the subsystem continues to initialize.

System Action: HSC initialization continues with only a portion of the PARM string parsed.

User Response: Restart the subsystem correcting the error displayed in the previous error message.

SLS0512E HSC subsystem CCCC is {ACTIVE|TERMINATING|INITIALIZING|RECONFIGURING|INVALID FLAG|NOT ALLOWED}

Explanation: The subsystem was started and it determined that another HSC subsystem with the name CCCC was ACTIVE|TERMINATING|INITIALIZING|RECONFIGURING. The new subsystem terminates processing. Alternatively, the other HSC subsystem turned on an INVALID FLAG in the HSC's SSCVT control block, or corrupted the SSCVT contents such that initialization was NOT ALLOWED.

System Action: The new subsystem terminates processing.

User Response: In cases of ACTIVE, TERMINATING, INITIALIZING, or RECONFIGURING, wait for that activity to finish before attempting to start HSC again. If the operator determines that the message was issued in error (i.e., there is no other active HSC), then restart the subsystem specifying the RESET option on the start parameter.

The cases of INVALID FLAG or NOT ALLOWED indicate that the HSC's SSCVT control block has been corrupted and the HSC is unable to complete its subsystem initialization. This is a more serious situation, and will require careful circumvention. HSC will have to be started as a differently named subsystem. This can be accomplished through the use of the MVS operator SETSSI command and by changing the HSC startup parameter SSYS. Contact Sun Support for more information.

SLS0516I License Key definition not found; trial period processing begins

Explanation: During the initialization of the HSC, it was determined that no Software License Key definition exists. Either the LKEYDEF control statement was missing from the HSC parameter file, or an error occurred during the LKEYDEF processing. In either event the HSC begins trial period processing. A subsequent message, either SLS4800I or SLS4801I reflects the status of the trial period.

System Action: Product trial period processing begins.

User Response: The customer must obtain a valid license key from StorageTek prior to the end of the 75 day trial period.

- SLS0518D** *WARNING* The HSC subsystem is not in key 1-7; results may be unpredictable; reply YES to continue or NO to terminate execution
- Explanation:** The HSC protect key was found to be other than 1-7. The HSC subsystem should have a key of 1-7 to operate properly.
- System Action:** Initialization waits for a reply.
- User Response:** A reply of "NO" results in termination of the HSC. If you reply "YES," initialization continues and the HSC executes in a limited capacity. Several unpredictable events can occur. As an example, HSC may generate an abnormal amount of SLS0107D messages or the EDL (eligible device list) may not be modified properly. Contact your local systems programmer or StorageTek Software Support. Further information regarding the program properties table (PPT) may be found in the *NCS Installation Guide*.
- SLS0519I** HSC subsystem CCCC terminating abnormally
- Explanation:** The subsystem is going through abnormal termination as a result of an abend or an operator CANCEL.
- System Action:** The HSC terminates processing.
- User Response:** If the termination was not the result of an operator CANCEL, contact StorageTek Software Support.
- SLS0520I** {GTF EID|GTF FID} invalid or not provided, defaulting to XXXX
- Explanation:** The GTF EID, or GTF FID, was not specified or was incorrectly specified as a parameter on the EXEC statement of the procedure used to start HSC or the EXECParm control statement within PARMLIB.
- System Action:** The default EID or FID XXXX is used.
- User Response:** Correct GTF EID or GTF FID values on either the HSC EXECParm control statement or as EXEC statement parameter of the start procedure. During the next HSC startup the new values will be picked up.
- SLS0521I** CCCCCCCC failed to open; no automatic commands issued
- Explanation:** The HSC automatic command component requires a SLSSYScc member or DD name to be provided. cc refers to the suffix of a member or DD statement name. CCCCCCCC - data set name plus member or the DD statement name.
- System Action:** The HSC starts with no automatic command list.
- User Response:** If the installation wishes to issue automatic commands on subsystem startup, create a SYS1.PARMLIB member SLSSYScc, or a SLSSYScc DD statement and specify the suffix (cc) on the MEMBER parameter for the startup procedure.

SLS0522I - SLS0525I

SLS0522I Allocation of SYS1.PARMLIB(SLSSYScc) failed; no automatic commands issued; RC=XXXX

Explanation: The HSC automatic command component requires an issuing SLSSYScc member to be provided, or the member name on the EXEC parameter was incorrectly specified. cc refers to the suffix of a member or DD statement name. XXXX is the dynamic allocation error reason code (S99ERROR).

System Action: The system starts with no automatic command list.

User Response: If the installation wishes to issue automatic commands on subsystem startup, create a SYS1.PARMLIB member SLSSYScc, and specify the suffix on the MEMBER parameter for the startup procedure, or specify a SLSSYScc DD statement.

SLS0523I Volume volser found errant during reconfiguration, home location is AA:LL:PP:RR:CC

Explanation: The reconfiguration function encountered an errant volume (volser) in the old control data set whose home location is AA:LL:PP:RR:CC.

System Action: The errant volume detected was copied to the new control data set and marked errant (in the new control data set).

User Response: An audit of the specified cell should be performed on the new control data set in an attempt to clean up the above status.

SLS0524I Volume volser found selected during reconfiguration, home location is AA:LL:PP:RR:CC

Explanation: The reconfiguration function encountered a selected volume (volser) in the old control data set whose home location is AA:LL:PP:RR:CC.

System Action: The selected volume was copied to the new control data set and marked unselected (in the new control data set).

User Response: An audit of the specified cell should be performed on the new control data set to verify the volume status. Further verify that no other HSC subsystem was active on another host during the time reconfiguration was running. If HSC was active on another host, the newly created control data set may be corrupted. If HSC was not active on another host, the newly created control data set can be assumed to be correct.

SLS0525I Reconfiguration completed successfully

Explanation: The reconfiguration function has completed successfully.

System Action: None.

User Response: The subsystem must be brought up pointing to the newly created control data sets. Then run the VOLRpt (Volume Report) utility function, and analyze the contents of the report.

SLS0527I Reconfiguration function is currently executing; DO NOT START other HSC subsystems

Explanation: The reconfiguration function is currently running. To prevent modifications and possible out of sync conditions, no other HSC subsystem should be running or started on any host sharing the same CDS.

System Action: Reconfiguration processing continues.

User Response: None.

SLS0529I An empty but allocated cell detected at cell *AA:LL:PP:RR:CC*

Explanation: The reconfiguration function was running and detected that a cell was allocated but empty.

System Action: The reconfiguration function continues processing.

User Response: As long as no error messages were issued by the reconfiguration function, the new data set is considered to be good. To clean up the empty but allocated cell condition, bring the HSC software up with the newly configured data set(s) and run an audit against the above mentioned cells.

SLS0530I Reconfiguration completed having found the above control data set conditions

Explanation: Reconfiguration completed. However, conditions were encountered during the function which may have resulted in the corruption of the control data set.

System Action: Examine other output messages from reconfiguration and determine the severity of the message.

User Response: Audit the cells in the newly created control data set for which messages were generated to correct any possible error conditions.

SLS0531E Database mismatch; Volume *volser*, Cell Index *AA:LL:PP:RR:CC*, VAR Location *AA:LL:PP:RR:CC*

Explanation: The reconfiguration function detected a mismatch when comparing the Cell Index location and the Volume home location.

System Action: None.

User Response: Audit the cells in the newly created control data set for the generated message to correct any possible error conditions.

SLS0539I Unknown volume found, review prior SLS0874A Messages; 'Y' to acknowledge

Explanation: During HSC startup, message SLS0874A was issued to indicate an unknown (to HSC) volume was found and must be removed manually from the LSM. This message will be issued at each startup of HSC until the volume has been removed. Response to this message simply indicates you have seen the message. Leaving the cartridge in the LSM will not prevent the HSC from normal function.

System Action: Processing continues normally following response. The cartridge is left where it was found.

User Response: Open the LSM and remove the cartridge from the library as indicated in message SLS0874A. This message will be issued at each startup of the HSC and each time the HSC Service Level is brought from Base to Full.

SLS0545I HSC subsystem CCCC STOP (P) command received

Explanation: An operator STOP (P) command was directed to the specified subsystem.

System Action: The subsystem begins termination.

User Response: None.

SLS0548I LMURQST error XXXXXXXX for Read ACS statistics

Explanation: The performance monitor issued a READ ACS STATISTICS command and received the displayed return code.

System Action: No SMF statistical record is written.

User Response: Contact StorageTek Software Support.

SLS0551I {SMF|COMPRFX|MAJNAME|EJCTPAS| HOSTID(CCCCCCCC)|NNLBDRV(CCCCCCCC)| ADJACNT(CCC)} parameter outside valid range

Explanation: LIBGEN parameter SMF|COMPRFX|MAJNAME|EJCTPAS| HOSTID(CCCCCCCC)|NNLBDRV(CCCCCCCC)| ADJACNT(CCC) is outside the valid range.

System Action: Processing continues. A return code of 12 is set.

User Response: Correct the error, and resubmit the LIBGEN assembly.

SLS0552I STATION(XXXX1)|LSM(AA:LL)|SYSLIST(CCCCCCCC1)|
 HOSTDRV(CCCCCCCC2)|HOSTID| PASTHRU(D)|LSMDRV(CCCCCCCC3)|
 ADJACNT(CCCCCCCC4)|DRIVE(DD)| DRVELST(CCCCCCCC5)| ADDRESS(XXXX2)|
 ACSDRV(CCCCCCCC6) parameter not found

Explanation: Required LIBGEN parameter

STATION(XXXX1)|LSM(AA:LL)|SYSLIST(CCCCCCCC1)|
 HOSTDRV(CCCCCCCC2)|HOSTID| PASTHRU(D)|LSMDRV(CCCCCCCC3)|
 ADJACNT(CCCCCCCC4)|DRIVE(DD)|
 DRVELST(CCCCCCCC5)|ADDRESS(XXXX2)|ACSDRV(CCCCCCCC6) was not
 specified.

System Action: Processing continues. A return code of 12 is set.

User Response: Correct the error, and resubmit the LIBGEN assembly.

SLS0553I {ACSDRV=(CCCCCCC1)|ADDRESS| LSMDRV=(CCCCCCC2)|PASTHRU=(D)|
 DRIVE=(CCCCCCC3)|TYPE/WINDOW|
 WINDOW=(D)|TYPE=(CCC4)|DELDISP|SCRLABL|TCHNIQE|DOOR=(CCC5)|
 VSMONLY=CCCCCCC6|FUTRACS=(DD,DD)|FUTRLSM=(8500,CCC7)FUTURLSM=(8500
 ,CCC7)} parameter invalid value

Explanation: The value specified for LIBGEN parameter

{ACSDRV=(CCCCCCC1)|ADDRESS| LSMDRV=(CCCCCCC2)|PASTHRU(D)|
 DRIVE=(CCCCCCC3)|TYPE/WINDOW|
 WINDOW=(D)|TYPE=(CCC4)|DELDISP|SCRLABL|
 TCHNIQE|DOOR=(CCC5)|VSMONLY=CCCCCCC6|FUTRACS=(DD,DD)|FUTRLSM
 (8500,CCC7)|FUTURLSM=(8500,CCC7)} parameter is invalid.

System Action: Processing continues. A return code of 12 is set.

User Response: Correct the error, and resubmit the LIBGEN assembly.



Note: FUTURLSM is being phased out and replaced by FUTRLSM.

SLS0554I TOO MANY {ACSDRV|LSM|LSM=(CCCCCCCC1)|ADDRESS|
ADDRESS=(XXXX1)|HOSTID(CCCCCCCC2)|NNLBDRV|
LSMDRV|DRIVE|PASTHRU|'PASTHRU=(D)'|'ADJACNT=(CCCCCCCC3)'|SYSLIST|
DRIVE=(CCCCCCCC4)|'DRVELST=(CCCCCCCC5)'|
HOSTID|ADDRESS(XXXX2)|WINDOW=(D)|SYSLIST(CCCCCCCC6)} values
specified

Explanation: Too many ACSDRV|LSM|LSM=(CCCCCCCC1)|ADDRESS|
ADDRESS=(XXXX1)|HOSTID(CCCCCCCC2)|NNLBDRV|
LSMDRV|DRIVE|PASTHRU|PASTHRU=(D)|
ADJACNT=(CCCCCCCC3)|SYSLIST|DRIVE=(CCCCCCCC4)|
DRVELST=(CCCCCCCC5)|HOSTID|ADDRESS(XXXX2)|
WINDOW=(D)|SYSLIST(CCCCCCCC6) values specified.

System Action: Processing continues. A return code of 12 is set.

User Response: Correct the error, and rerun the job

SLS0555I Too many CCCCCCCC macros specified

Explanation: Too many CCCCCCCC macros were specified for the LIBGEN.

System Action: Processing continues. A return code of 12 is set.

User Response: Correct the error, and resubmit the LIBGEN assembly.

SLS0556I CCCCCCCC macro missing or out of sequence

Explanation: CCCCCCCC was not specified or was specified out of sequence in the LIBGEN.

System Action: Processing continues. A return code of 12 is set.

User Response: Correct the error, and resubmit the LIBGEN assembly.

SLS0557I Database successfully initialized; total cartridge capacity:
DDDDDDDDDDDD volumes

Explanation: All copies of the control database and/or journals have been successfully initialized. DDDDDDDDDDDDD indicates the total cartridge capacity for this database. When doing a LIBGEN for the SL3000 or SL8500, DDDDDDDDDDDDD is the maximum cartridge capacity for the library and not the actual capacity of your library. After varying the LSM online, use the Display ACS or Display LSM operator command to display the actual capacity.

System Action: None.

User Response: None.

SLS0558I CLNPRFX operand must be three VOLSER characters, Valid values are (A-Z, 0-9, and \$#@)

Explanation: The CLNPRFX operand is not three characters consisting of A-Z, 0-9, \$, #, or @.

System Action: Processing continues. A return code of 12 is set.

User Response: Correct the error, and rerun the job.

SLS0559I DRIVE PANEL numbers must be in ascending order

Explanation: DRIVE PANEL numbers were not specified in ascending order

System Action: Processing continues. A return code of 12 is set.

User Response: Correct the error, and resubmit the LIBGEN assembly.

SLS0560E CCCCCCCC errors encountered

Explanation: The CCCCCCCC function encountered errors.

System Action: The utility terminates with a non-zero return code.

User Response: Correct the errors, and resubmit the job.

SLS0562I CCCCCCCC - Installation verified

Explanation: The installation was verified by CCCCCCCC, where CCCCCCCC is the IVP that was executing.

System Action: The utility terminates with a 00 return code.

User Response: None.

SLS0563E Host SID CCCCCCCC, UNITNAME CCCCCCCC is not in EDT or has no supported tape devices

Explanation: The utility (executing on host SID CCCCCCCC) determined that the unitname specified in either the SLILIBRY macro>NNLBDRV parameter, or the SLIACS macro ACSDRV parameter was not in the EDT for this host, or the unitname existed but contained no supported tape devices.

System Action: Processing continues. A return code of 08 is set.

User Response: Perform one of the following actions:

- Repeat the LIBGEN to change the unitname
- Use the SET utility
- Perform an EDTGEN for the host to add the unitname.

SLS0564E - SLS0566E

SLS0564E Host SID *CCCCCCCC* was not defined in LIBGEN

Explanation: The utility (executing on host SID *CCCCCCCC*) determined that host SID *CCCCCCCC* was not specified in the LIBGEN.

System Action: Processing terminates. A return code of 08 is set.

User Response: Perform one of the following actions:

- Repeat the LIBGEN and specify *CCCCCCCC* in the SLILBRY macro HOSTID parameter
- Use the SET utility
- Run the job on a host that is defined to LIBGEN.

SLS0565E HOSTid *CCCCCCCC*; Device number *XXXX* is not a supported tape device

Explanation: The HOSTid (*CCCCCCCC*) has determined that device number *XXXX* is not a supported tape device as specified in the SLIDRIVS macro ADDRESS parameter.

System Action: Processing continues.

User Response: Perform one of the following actions:

- Repeat the LIBGEN and delete *XXXX* from the SLIDRIVS macro ADDRESS parameter
- Use the SET utility
- Use HCD to define the unit as a supported tape device.

SLS0566E HOSTid *CCCCCCCC*; Device number *XXXX* is not a 3278

Explanation: The HOSTid (*CCCCCCCC*) determined that device number *XXXX* was not a 3278 as specified in the SLISTATN macro ADDRESS parameter.

System Action: Processing continues.

User Response: Perform one of the following actions:

- Repeat the LIBGEN and delete *XXXX* from the SLISTATN macro ADDRESS parameter
- Use the SET utility
- Perform an IOGEN or MVSCP to make the device number a 3278.

- SLS0567E** Unable to allocate drive *XXXX1*; SVC 99 = *XXXX2*, *XXXX3*
- Explanation:** The utility was unable to allocate device number *XXXX1*. *XXXX2* is the information reason code, and *XXXX3* is the error reason code.
- System Action:** Processing continues.
- User Response:** Correct the reason for the dynamic allocation failure, and resubmit the job.
- SLS0568I** Message *DDDD* does not exist
- Explanation:** The LIBGEN macros requested message *DDDD* be issued.
- System Action:** Processing continues. A return code of 14 is set.
- User Response:** Contact StorageTek Software Support.
- SLS0569E** Invalid LIBGEN load module specified
- Explanation:** A Load macro issued for the LIBGEN load module was unsuccessful.
- System Action:** Processing terminates.
- User Response:** Ensure the LIBGEN load module is available.
- SLS0570I** Macro *CCCCCCCC* already specified
- Explanation:** The specified LIBGEN macro has already been issued.
- System Action:** Processing continues. A return code of 12 is set.
- User Response:** Correct the label, and resubmit the job.
- SLS0571I** Number of values for {STATION|HOSTDRV} parameter must equal number of hosts
- Explanation:** The specified LIBGEN parameter must have a number of values specified that equals the number of host identifiers specified on the SLILIBRY macro HOSTID parameter.
- System Action:** Processing continues. A return code of 12 is set.
- User Response:** Correct the number of parameters, and resubmit the job.

SLS0572I - SLS0576E

SLS0572I Number of values for {PASTHRU|DRIVE} parameter must equal number of values for {ADJACNT|DRVELST} parameter

Explanation: The specified LIBGEN parameter pair must have the same number of values specified.

System Action: Processing continues. A return code of 12 is set.

User Response: Correct the number of parameters, and resubmit the job.

SLS0573E Parameter list is missing or invalid

Explanation: The utility has determined that the parameter specified to the utility is missing or invalid.

System Action: Processing continues.

User Response: Specify a set of parameters.

SLS0574E CCCCCCCC program not permitted to do Dynamic Allocation

Explanation: The utility was not permitted to do dynamic allocation by the installation validation routine (IEFDB401).

System Action: Processing stops.

User Response: Authorize the program to perform dynamic allocation, and resubmit the job.

SLS0575E CCCCCCCC DD statement missing

Explanation: The specified DD statement could not be found.

System Action: Processing continues.

User Response: Define the specified DD statement, and resubmit the job.

SLS0576E Unable to load LIBGEN module CCCCCCCC (XXXX1 - XXXX2)

Explanation: The specified load module CCCCCCCC could not be loaded. XXXX1 - XXXX2 are the abend code and reason code issued by the system.

System Action: Processing stops.

User Response: Make sure there is a STEPLIB to the library containing CCCCCCCC, and resubmit the job.

SLS0577I Panel number 10 must be specified as the last operand for the DRIVE= parameter

Explanation: DRIVE= parameter of SLILSM macro MUST specify panel 10 as a drive panel. It is either missing from the DRIVE= operands, or it is not specified as the last operand for the DRIVE= parameter.

System Action: Processing continues. A return code of 12 is set.

User Response: Correct the error, and rerun the job.

SLS0578E Invalid ACSid

Explanation: The ACSid specified on the PARM= parameter of the EXEC statement for the SLIEXERS program is invalid - out of range.

System Action: Processing stops.

User Response: Specify the correct ACSid, and resubmit the job

SLS0579I Number of CCCCCC values specified is less than the number of hosts

Explanation: The macro parameter named by CCCCCC must contain as many operands as the number of hosts specified on the SLILIBRY HOSTID parameter. If an operand is intentionally omitted for a host, a comma must be used as a place holder.

System Action: LIBGEN assembly continues, and the assembly return code is set to 04.

User Response: Correct the number of parameters, and resubmit the job.

SLS0580I The RESERVE= parameter has been discontinued and is ignored; it should be removed

Explanation: The RESERVE= parameter was removed in an earlier maintenance cycle and is no longer used.

System Action: LIBGEN assembly continues normally and the resultant LIBGEN module is not affected.

User Response: Remove the RESERVE= parameter from the SLIRCVRY macro when convenient. It is not necessary to rerun the LIBGEN assembly.

SLS0581I SLIPTPCK - PASTHRU parameter #*N* of *BBB* does not have a corresponding ADJACENT parameter specified

Explanation: The *N*th PASTHRU parameter defined on the SLILSM macro labelled *BBB* does not have a matching ADJACNT parameter entry.

System Action: LIBGEN assembly continues, and the assembly return code is set to 12.

User Response: Add an ADJACNT parameter entry which corresponds to the other LSM for which the pass-thru-port is being defined. Rerun the LIBGEN assembly.

SLS0582I SLIPTPCK - *AAA* is adjacent to *BBB*, but *BBB* is not adjacent to *AAA*

Explanation: LSM *AAA* is defined in the SLILSM macro for LSM *BBB* as being adjacent, yet *BBB* is not defined in the SLILSM macro for LSM *AAA* as being adjacent.

System Action: LIBGEN assembly continues, and the assembly return code is set to 12.

User Response: Place an entry for LSM *BBB* in the ADJACNT parameter of the SLILSM macro for *AAA*. Rerun the LIBGEN assembly.

SLS0583I SLIPTPCK - Adjacent parameter *N* (*VVV*) of *AAA* does not have a corresponding PASTHRU parameter specified

Explanation: The *N*th parameter in the ADJACNT keyword for the SLILSM macro labelled *AAA*, which contains the value *VVV*, has no corresponding PASTHRU parameter.

System Action: LIBGEN assembly continues and the assembly return code is set to 12.

User Response: Insert a value into the PASTHRU parameter which corresponds to the *N*th ADJACNT parameter for LSM *AAA*. Rerun the LIBGEN assembly.

SLS0584I SLIPTPCK - PASTHRU parameter *N* of *AAA* and PASTHRU parameter *O* of *BBB* are both defined as type *TTT*

Explanation: The corresponding PASTHRU parameters *N* of LSM *AAA* and *O* of LSM *BBB* are both defined as the same PTP type *TTT* (MASTER/SLAVE).

System Action: LIBGEN assembly continues, and the assembly return code is set to 12.

User Response: Change either conflicting PASTHRU parameter to be of the opposite type.

SLS0585I SLILSM - SLILSM macro labeled *CCCCCCC* has a drive/pasthru port/window assigned to number *NN*

Explanation: The macro labeled *CCCCCCC* has the same panel number assigned to a drive, pasthru port or window.

System Action: LIBGEN assembly continues, and the assembly return code is set to 12.

User Response: Change either PASTHRU, DRIVE or WINDOW parameter to the correct panel number.

SLS0586I SLISTATN ADDRESS *dddd* WILL NOT BE USED BY HSC

Explanation: The SLISTATN Macro defined a Station Address of zero. HSC assumes a Station with an address of zero is a “dummy” one and will not use it.

System Action: LIBGEN assembly continues, and the assembly return code is set to 8.

User Response: If the Station is to be used, change it to a non-zero address.

SLS0587I PASTHRU PARAMETER REQUIRED WHEN DEFINING AN ACS WITH MULTIPLE LSMS

Explanation: The SLIACS Macro defined more than one LSM. The SLILSM macro must define the pass-thru ports between adjacent LSMs by coding the PASTHRU parameter.

System Action: LIBGEN assembly continues, and the assembly return code is set to 12.

User Response: Define the pass-thru ports between adjacent LSMs by coding the PASTHRU parameter on the SLILSM macro.

SLS0600I Volume *volser*; *AA:LL:PP:RR:CC*, {Selected|Unselected},
{Scratch|Nonscratch}<, Mounted>

Explanation: A Display Volume command was issued for volume *volser*. The home cell for the volume is *AA:LL:PP:RR:CC*, where *AA* is the ACSid, *LL* is the LSMid, *PP* is the panel number in decimal, *RR* is the row number in decimal, and *CC* is the column number in decimal. The display indicates whether the volume is currently selected or unselected. The scratch status of the volume is also displayed. "Mounted" appears in the message only when the volume is mounted on a drive.

System Action: None.

User Response: None.

SLS0601I Volume *volser* - detail:

```
Home cell:AA:LL:PP:RR:CC
Scratch:{YES|NO}
Selected:{YES|NO}
<Mounted:{drive DDDD|driveid AA:LL:PP:NN}>
<Owning host:CCCCCCCC>
External label:{YES|NO}
<Label readable:{YES|NO}>
Inserted:YYYY-MM-DD HH:MM:SS
Last selected:YYYY-MM-DD HH:MM:SS
Select count:DDDD
Media type:MMMMMMMM
Rectech:RRRRRRRR
Media Label:LLLLLLLL
Media Match:{YES|NO|VOLATTR Only|Label Only|Undefined}
<Not usable>
<Not eligible for SCRATCH>
```

Explanation: A Display Volume command with the DETail operand was issued for volume *volser*. All available information about the volume is displayed in a multi-line WTO.

In the "home cell" line, *AA* is the ACSid, *LL* is the LSMid, *PP* is the panel number in decimal, *RR* is the row number in decimal, and *CC* is the column number in decimal.

The "Mounted" line is displayed only if the volume is mounted. drive *DDDD*|driveid *AA:LL:PP:NN* indicates the drive on which the volume is mounted.

The "Owning host" (*CCCCCCCC*) line is displayed only if the volume is selected.

The "Label readable" line is displayed only if the volume has an external label.

The "Inserted" and "Last Selected" lines respectively show the date and time at which the volume entered the library and was last selected. The date is in YYYY-MM-DD format.

MMMMMMMM and *RRRRRRRR* are the media type and recording technique of the volume. *LLLLLLLL* indicates if the media type on the external label was readable or not. The value *N/A*, not applicable, appears if the media value shown was not read from the LMU.

The Media Match values indicate how the Media-type value was determined for the volume:

YES	The LMU read a media label, and there is a VOLATTR defined for the volume. The media label and VOLATTR agree with respect to the media type.
NO	The LMU read a media label, and there is a VOLATTR defined for the volume. The media label and VOLATTR do not agree with respect to the media type.
VOLATTR Only	A VOLATTR exists for the volume, but the LMU has not determined the media type. This is valid when a VOLATTR is defined for a volume outside the library.
Label Only	The LMU has determined the media type, but no VOLATTR exists for the volume.
Undefined	The LMU has not determined the media type, and no VOLATTR exists for the volume.

A value of “No”, “Label Only”, or “Undefined” indicates an error in VOLATTR statements. A value of “VOLATTR Only” for a volume inside the library also indicates an error in the VOLATTR statements. Either condition can cause invalid scratch counts to occur for the Display SCRATCH command.

“Not usable” indicates a non-authorized request attempted to mount a cleaning cartridge or diagnostic cartridge.

The “Not eligible for SCRATCH” is displayed if the volume is a VSM MVC and is an indication that the volume cannot be scratched.

System Action: None.

User Response: None.

```

SLS0602I  Volume volser - errant:
Scratch:                                {YES|NO}
Selected:                               {YES|NO}
<Owning Host:                          CCCCCCCC>

Last known locations:
Home:                                    CELL AA:LL:PP:RR:CC
Source:                                  {CELL AA:LL:PP:RR:CC |
CAP AA:LL:RR:CC |
DRIVE XXXX
DRIVEID AA:LL:PP:NN}
Destination:                             {CELL AA:LL:PP:RR:CC |
CAP AA:LL:RR:CC |
DRIVE XXXX
DRIVEID AA:LL:PP:NN}
<Lost in:                                LSM AA:LL>

```

Explanation: A Display Volume command was issued for volume *volser*. The volume was found to be errant. The last known locations of the volume are listed. In the volume location lines, *AA* is the ACSid, *LL* is the LSMid, *PP* is the panel number in decimal, *RR* is the row number in decimal, *CC* is the column number in decimal, *NN* is the drive number in decimal, and *XXXX* is a device unit address. The “owning host” line is only displayed if the volume is selected. The “Lost in” line is only displayed if the volume is lost in an LSM.

System Action: The volume continues to be errant until processed by errant recovery or logically ejected from the library.

User Response: Invoke errant recovery for the volume. Some methods that can be used to invoke errant recovery are mounting the volume or modifying the LSM online.

```

SLS0603I  Volume(s) volser1<-volser2> not in ACS

```

Explanation: One or more of the volumes requested on a Display Volume command were not found in the ACS. If a volume range was specified on the command and a sequential series of volumes within that range was not found, a single message will be displayed for the series.

System Action: None.

User Response: None.

SLS0604I Invalid volser range (*volser1-volser2*) for DISPLAY VOLUME command, CC=XX

Explanation: A range of volumes (*volser1-volser2*) was specified on a Display Volume command, but the range was syntactically invalid. XX is a condition code indicating the nature of the syntax error:

- 08 Overflow occurred when incrementing the volser. The result is larger than the incremental portion of the volser.
- 12 One of the volsers in the specified range has no incrementable portion
- 16 One of the volsers in the specified range contains invalid characters.
- 20 The second volser in the specified range is less than or equal to the first volser in the range.
- 24 The incrementable portions of the volsers specified in the range are not compatible.

System Action: None.

User Response: Re-enter the Display Volume command, specifying a valid volser range.

SLS0605I Volser range (*volser1-volser2*) for DISPLAY VOLUME command exceeds 100 volumes

Explanation: A range of volumes (*volser1-volser2*) was specified on a Display Volume command. The specified range contains more than 100 volumes. Volume ranges for the Display Volume command are limited to a maximum of 100 volumes.

System Action: None.

User Response: Enter multiple Display Volume commands specifying ranges of 100 volumes or less, or run the batch HSC VOLRpt (Volume Report) utility, which has no limit on volser ranges.

SLS0607I Invalid CCCCCCCC1 option - CCCCCCCC2

Explanation: An invalid option was specified for a keyword on a given command. CCCCCCCC1 is the keyword entered. CCCCCCCC2 is the option for the CCCCCCCC1 keyword.

System Action: Command processing terminates.

User Response: Refer to the *HSC Operator's Guide*, or issue the HSC "Display CMd" command, to determine the supported options for the specified command keyword.

SLS0609I Invalid {OPTION} CCCCCCCC1 CCCCCCCC2 value - DDDDDDDDD1; value must be within range DDDDDDDDD2-DDDDDDDD3

Explanation: A numeric value was specified for the OPTion command option. The specified value is either less than the minimum value allowed for the option, or greater than the maximum value allowed for the option. CCCCCCCC1 is the function entered on the OPTion command. CCCCCCCC2 is the option entered on the OPTion command. DDDDDDDDD1 is the value entered on the OPTion command. DDDDDDDDD2 is the minimum value allowed for the option. DDDDDDDDD3 is the maximum value allowed for the option.

System Action: OPTion command processing terminates.

User Response: Refer to the *HSC Operator's Guide*, or issue the HSC "Display CMD OPTion" command, to determine the supported values for the specified function.

SLS0612I The CCCCCCCC1 command is at a command Service Level unknown to the HSC

Explanation: An operator command was entered, but the HSC did not recognize the Service Level of the command. CCCCCCCC1 is the operator command entered.

System Action: The command is not executed.

User Response: This is an HSC internal error and should be reported to StorageTek Software Support.

SLS0613I The CCCCCCCC1 command cannot be processed at the current HSC Service Level

Explanation: An operator command was entered, but the HSC was not at a Service Level that could execute the command. CCCCCCCC1 is the operator command entered.

System Action: The command is not executed.

User Response: Re-enter the CCCCCCCC1 command when the HSC is at the appropriate Service Level.

SLS0651I Allocation of station device XXXX failed - XX1, XX2

Explanation: An error occurred while attempting to allocate the specified station. XX1 contains the SVC 99 error code, and XX2 contains the info code.

System Action: The station is not varied online.

User Response: Correct the problem, and reissue the Vary Station command. If the problem persists, contact StorageTek Software Support

- SLS0652I** Open of station device *XXXX* failed
- Explanation:** An error occurred attempting to OPEN the specified station.
- System Action:** The station is not varied online.
- User Response:** Correct the problem, and reissue the Vary Station command. If the problem persists, contact StorageTek Software Support.
- SLS0653I** SHPG of station *C...C* failed -*CCCCCCCC*
- Explanation:** The Set Host Path Group (SHPG) for the specified station has failed.
- System Action:** The station is marked offline.
- User Response:** Verify the LMU connection and status. Ensure that HSC full initialization is complete, and then vary the station or ACS online. If the last 4 characters of the error (CCCCCCCC) is "A214", then HSC is not compatible with the ACS. Update your HSC to release 6.1 or above in order to connect to this ACS. If the problem persists, contact StorageTek Software Support.
- SLS0655I** ACS AA station *C...C* communicating
- Explanation:** The specified station started communicating.
- System Action:** All requests waiting for the LMU are reissued.
- User Response:** None.
- SLS0657E** ACS AA station *C...C* not communicating
- Explanation:** The station cannot be used to communicate with ACS AA.
- System Action:** All requests are routed to another station (if available).
- User Response:** Diagnose and correct the problem. If I/O error messages are generated for a 3270 station, it may be necessary to vary the station offline.
- SLS0660I** ERR BCST - *CCCCCCCC*
- Explanation:** An invalid broadcast was received. This message describes the broadcast.
- System Action:** Processing continues. The broadcast is ignored.
- User Response:** Contact StorageTek Software Support.

SLS0661E ACS AA not communicating

Explanation: All the stations used to communicate with ACS AA are not responding.

System Action: All requests are returned with an LMU hardware error (6515).

User Response: Use the Vary command to vary the stations offline, then online. If the stations do not come online, then contact StorageTek Hardware Support.

SLS0662I LMU Response error - AA, XXXX, XX, DD

Explanation: A response was received that was in error. AA represents the ACSid of the ACS the block was being sent to or received from.

XXXX represents the station device number being used.

XX represents an error code:

- 04 - Invalid multiple response type
- 08 - Sequence number not numeric
- 0C - Response not expected
- 10 - Invalid response (see reason code)
- 14 - Non-numeric response type
- 18 - Error response received
- 20 - Unknown broadcast type
- 28 - Invalid broadcast (see reason code)

DD represents a reason code:

- 00 - N/A
- 01 - Invalid response code
- 02 - Invalid response size
- 03 - Invalid HOSTid
- 04 - Invalid slave id
- 05 - Invalid LSM vary status found
- 06 - Invalid passthru port count
- 08 - Invalid response len - too small
- 09 - Invalid response len - not evenly divisible
- 0A - Invalid month
- 0B - Invalid day
- 0C - Invalid hour
- 0D - Invalid minute
- 0E - Invalid second
- 0F - Invalid arm utilization
- 10 - Invalid passthru count
- 11 - Invalid response len - too large
- 12 - Missing response for LRQ
- 13 - Invalid LSM
- 14 - Invalid drive panel

15 - Invalid drive row
 17 - Invalid softfail recovered count
 80 - Invalid configuration status
 81 - Invalid master LSM
 82 - Invalid master panel
 83 - Invalid slave LSM
 84 - Invalid slave panel
 90 - Invalid LSM count

System Action: Processing continues.

User Response: Contact StorageTek Software Support.

SLS0663I LMU Block error - *AA,XXXX,XX,DDD*

Explanation: A block was received or sent that was in error.

AA represents the ACSid of the ACS the block was being sent to or received from.

XXXX represents the station device number being used.

XX represents an error code:

1C - Deblocking error; LMU sent bad block

24 - ACK error; LMU or HSC sent bad block

DDD represents a reason code:

1 Valid block indicator not received

2 Start of transmission not found

3 End of transmission not found

4 Start of transaction not found

5 End of transaction not found

6 Interface not grouped to any host

7 Illegal HOSTid

8 Illegal set host path group option

9 Interface joined to another host

10 HOSTid does not agree with owning host

11 Non-numeric data in block header

12 Standby LMU cannot accept block of requests

13 Switchover already active

14 Can't join, unsupported compatibility level

SLS0664I - SLS0665E

15	Can't join, Partition ID non-zero, library not partitioned
16	Can't join, Partition ID zero, library is partitioned
17	Partition ID not defined to library
18	SHPG Transmission header does not match host compatibility level
50	Bad block seq. no. on unexpected ACK
51	Illegal ACK of request block from Standby LMU
52	ACK error type not numeric
124	Non-numeric block length on ACK from LMU
136	Bad block seq. no. on ACK from LMU

System Action: Processing continues.

User Response: Send the MVS SYSLOG/SCP CONSLOG and PM2 ACS deblocking report to your StorageTek Customer Service Representative.

SLS0664I ACS AA Busy; station *C...C* offline pending

Explanation: A Vary OFFline was issued for the specified station or ACS. Station *C...C* was the last station online to the LMU, and there was work active for the LMU.

System Action: The request waits until active work for the LMU is complete.

User Response: None.

SLS0665E ACS AA Degraded; LSM AA:*LL*, Condition *D*, FSC *XXXX*

Explanation: A message was received from ACS AA that a failure occurred that causes degraded performance. The ACS can continue normal functioning.

LL is the LSM. If "FF", the failing device is the LMU.

D is the condition code. If "1", device inoperative. A "2" indicates performance is degraded.

XXXX is the fault symptom code (FSC). See fault symptom code dictionary for specific error codes.

System Action: Processing continues.

User Response: Contact StorageTek Hardware Support. Have the FSC (*XXXX*) available.

SLS0666A LSM AA:LL access door has been opened

Explanation: The specified LSM access door has been opened.

System Action: All requests involving the LSM wait until the door is closed, made ready, or the LSM is forced offline.

User Response: Close the LSM door, force the LSM offline to go into manual mode.

SLS0667I LSM AA:LL access door has been closed

Explanation: The specified LSM access door has been closed.

System Action: Processing continues.

User Response: None.

SLS0668I LSM AA:LL CCC...CCC

Explanation: The LSM has been brought successfully online or offline according to the variable text portion of the message.

If the text for CCC...CCC reads

Is Offline; Temp Outage Queue has been purged.

The LSM already was offline and no MODify lsm ONline was found on the Temp Outage Queue.

Ready; Temp Outage Queue Will Be Re-Driven.

Either a MODify lsm ONline command, an LSM Ready event, or an LMU Ready event has been successfully processed and any pending requests on the Temp Outage Queue will be re-queued to the Waiting Request Queue.

System Action: The system processes the Temp Outage Queue as indicated in the text of the message.

User Response: None.

SLS0669A - SLS0671I

SLS0669A LSM AA:LL not ready (C)

Explanation: The specified LSM is not ready. C represents the reason the LSM is not ready. Reasons include:

- 0 - Response indicates LSM not ready
- 1 - Configuration mismatch
- 2 - Failed initialization
- 3 - Lost Communication
- 4 - Mechanism failure
- 5 - LSM Cannot initialize - CAP door open
- 6 - LSM Cannot initialize - playground requires emptying
- 7 - LSM has capacity mismatch
- 8 - Key door has been opened

System Action: All requests involving the LSM wait until the LSM is made ready or the LSM is forced offline.

User Response: Ready the LSM. If this cannot be done, force the LSM offline to go into manual mode.

SLS0670I Modify of LSM AA:LL pending (DDDDDDDD)

Explanation: The MODify lsm request was issued while another modify for that LSM was active. The pending queue is now DDDDDDDD deep.

System Action: The modify waits.

User Response: None.

SLS0671I Vary of ACS {AA/AA station C...C} pending (DDDDDDDD)

Explanation: The Vary STation or Vary ACS request was issued while another Vary for that ACS was active. The Vary pending queue is now DDDDDDDD deep.

System Action: The vary waits until it reaches the top of the queue.

User Response: None.

SLS0672E LSM AA:LL {Drive XXXX|Driveid AA:LL:PP:NN} - needs cleaning

Explanation: The specified drive needs to have a cleaning cartridge inserted. The transport is identified either by the unit address (XXXX) or, when the drive is not defined to this host, by the driveid (acs, lsm, panel and number of drive AA:LL:PP:NN).

System Action: Processing continues.

User Response: Mount a cleaning cartridge in the transport.



Note: The automated clean function of the HSC is set to off. To prevent this message from being issued, turn the HSC automated clean function on via the HSC MNTD AUtocln(ON) command.

SLS0673I LSM AA:LL pending offline

Explanation: A MODify lsm OFFline request was issued for the specified LSM; however, the LSM was in use. Either a request (e.g. Mount, DISMount) was active, or the CAP was reserved.

System Action: The offline request waits. When no longer in use, the MODify lsm OFFline request will complete. If necessary, issue a MODify lsm OFFline with the FORCE option to bring the LSM offline regardless of activity.

User Response: None.

SLS0674I ACS AA Station C...C driver cannot run without ESTAE

Explanation: This station failed three times to establish an ESTAE environment. Normally recoverable errors cannot be recovered without an ESTAE routine to schedule the retry routine. Schedule a recycle of the HSC if this station stops working.

AA is the ACS number.

C...C is the station address.

System Action: Processing continues for the HSC, but the station remains inactive.

User Response: This problem may be corrected by varying the ACS offline and back online.

SLS0675E LSM AA:LL CCC...CCC

Explanation: The indicated LSM failure or partial failure has been detected according to the variable text portion of the message.

If the text for CCC...CCC reads:

Try MODIFY Again; Config Request Failed.

SLSLCLSM failed three times to obtain the current status of the LSM from the database. Even though the database may show the LSM to be in automatic mode, the LSM is still logically offline.

Try MODIFY Again; Read LSM Status Failed.

SLSLCLSM failed three times to obtain the current status of the LSM from the LMU. Even though the database shows the LSM to be in automatic mode, the LSM is still logically offline.

Try Modify Again When LSM Is Ready.

SLSLCLSM detected that the LSM is not ready, so the LSM cannot be brought logically online in its current state. Even though the database shows the LSM to be in the automatic mode, the LSM is still logically offline.

Try MODIFY Again; Modify LSM Online Failed.

SLSLCLSM failed three times to bring the LSM online even though the LSM was detected to be in a ready status. Even though the database shows the LSM to be in automatic mode, the LSM is still logically offline.

Is Online, But CAP Query Failed.

The LSM is now online, but the Configuration query for all CAP records of the LSM failed. CAP reserve/release handling cannot take place.

Is Online, But Failed To Re-Reserve CAP CC.

The LSM is now online, but CAP CC is active. The LMU thinks that this host owns it, and SLSLCLSM failed three times in trying to re-reserve CAP CC to this host.

Is Online, But Failed To Lock CAP CC.

The LSM is now online, but CAP CC is active. The LMU thinks that this host owns it, and SLSLCLSM failed three times in trying to lock CAP CC.

Is Online, But Failed To Unlock CAP CC.

The LSM is now online, but CAP CC is active. The LMU thinks that this host owns it, and SLSLCLSM failed three times in trying to unlock CAP CC.

Is Online, But Failed To Release CAP CC.

The LSM is now online, but CAP CC is not active. The LMU thinks that this host owns it, and SLSLCLSM failed three times in trying to release it.

Is Online, But Carts. In Motion Not Resolved.

The LSM is now online, but SLSLCLSM failed three times in trying to read the in-transit set. There may still be cartridges lost in this LSM.

System Action: The system takes no immediate action, but errant recovery may be automatically invoked later for cartridges not found in their home cells.

User Response: Depends on the variable portion of the message text.

If the text for CCC...CCC reads:

Try MODIFY Again ...

then either open and close the LSM door or MODify lsm ONline. If that fails, has already failed, or yields LSM Lock Not Available, then MODify lsm OFFline (possibly FORCE) and MODify lsm ONline are necessary, assuming that the hardware is working.

Is Online, But ...

The LSM is online but either the CAP was not properly reinitialized or we could not read the in-transit set. Errant recovery may automatically locate the unrecovered volumes. It does not have to be scheduled immediately, but the operator should eventually get the LSM offline and online again without any errors.

SLS0676I

Can't process requests; LMU server is terminating

Explanation: The LMU server is not available to process requests. Yet due to timing, some task tried to queue a request for the LMU. This request will not be accepted.

System Action: Termination continues.

User Response: None.

SLS0677I LMU I/O Error *XXXX*, *XX1*, *XX2*, *XX3*, *XX4*, *XX5*

Explanation: An I/O error occurred doing I/O to an LMU

<i>XXXX</i>	Station device number
<i>XX1</i>	CCW that was issued
<i>XX2</i>	Unit status
<i>XX3</i>	Channel status
<i>XX4</i>	Sense byte 0
<i>XX5</i>	Sense byte 1

System Action: Processing continues.

User Response: Contact StorageTek Hardware Support, if necessary.

SLS0678I LMU Attention Error *DDD*, *SS*

Explanation: Device *DDD* returned Channel/Device status *SS* during LMU attention interrupt processing.

System Action: If the status contains an attention indicator, the attention will be processed.

User Response: It is possible there is a device problem. Contact a StorageTek customer service representative.

SLS0679E Restart HSC sometime; an LMU server subtask has abended

Explanation: A non-critical resource has abended, and a restart of the HSC should be scheduled for a convenient time.

System Action: None.

User Response: Vary offline the station that is incurring the problem and then vary it back online. If the problem persists report this abend to StorageTek, and schedule a restart of the HSC for a convenient time.

SLS0680I ABEND *XXX1*, *CCC1*, *XXX2*, *XXX3*, *CCC2*

Explanation: An LMU Server task has abended.

XXX1 is the abend code

CCC1 is the name of the CSECT that abended

XXX2 is the starting address of the CSECT that abended

XXX3 is the address of the TCB that abended

CCC2 is the name of the PRB that abended at the address of the RB that abended.

System Action: Terminates the failing task.

User Response: This message is generated for abends that occur within the LMU server. Another HSC message will depict the criticality of this *XXX1* abend.

SLS0681I ORH interval expired: ACS *AA*, SEQNO *BBCCC*, *CCC1*, *CCCCCCCCCCCCCCCC*

Explanation: The response wait time interval for a request has expired.

AA ACSid

BB HOSTid

CCC the request sequence number is missing if not on the Active Request Queue

CCC1 the queue name where the request has been waiting:
ACT stands for the Active Request Queue,
WTG stands for the Waiting Request Queue,
TMP stands for the Temp Outage Queue.

CCCCCCCCCCCCCCCC the LMU request data in EBCDIC format.

System Action: Processing continues.

User Response: None.

SLS0682D ORH: ABORT/EXTEND/REDRIVE? ACS AA, SEQNO BBCCC, CCC1, CCC2, volser

Explanation: The HSC is asking the system operator what to do with a request whose response wait time interval has expired. Message SLS0681I was previously issued for this request.

AA ACSid
BB HOSTid
CCC the request sequence number
CCC1 the queue the request is waiting on:
ACT stands for the Active Request Queue,
WTG stands for the Waiting Request Queue,
TMP stands for the Temp Outage Queue.
CCC2 the type of request:
DMT Dismount
MNT Mount
MOV Move
SWP Swap
volser is the volume serial number of the cartridge.

System Action: Task waits for operator to enter a reply.

User Response: Answer can be one or more letters of one of the following words:

ABORT HSC will free the selected volume so that the operator can enter manual override commands to move the cartridge.
EXTEND HSC will extend the response wait time interval another increment to let the LMU finish working on this request.
REDRIVE HSC will move the request from the Temp Outage Queue to the Waiting Request Queue so it can be driven again. If the request is not in the Temp Outage Queue, the HSC will extend the response wait time interval, and you should receive a SLS0684I message.

SLS0683I ORH aborted request: ACS AA, SEQNO BBCCC, {ACT|WTG|TMP}

Explanation: Request has been aborted by the Overdue Response Handler.

AA ACSid

BB HOSTid

CCC the request sequence number is missing if not on the Active Request Queue
ACT stands for the Active Request Queue,
WTG stands for the Waiting Request Queue,
TMP stands for the Temp Outage Queue.

System Action: HSC frees the selected volume and makes it errant.

User Response: Operator can enter override commands if desired.

SLS0684I ORH interval extended: ACS AA, SEQNO BBCCC, {ACT|WTG|TMP}

Explanation: The response wait time interval for a request has been extended by the Overdue Response Handler.

AA ACSid

BB HOSTid

CCC the request sequence number is missing if not on the Active Request Queue
ACT stands for the Active Request Queue,
WTG stands for the Waiting Request Queue,
TMP stands for the Temp Outage Queue.

System Action: HSC gives the LMU more time to finish working on this request.

User Response: None.

SLS0685I ORH completed request: ACS AA, SEQNO BBCCC, {ACT|WTG|TMP}

Explanation: Request has been marked completed by the Overdue Response Handler.

AA ACSid

BB HOSTid

CCC the request sequence number is missing if not on the Active REquest Queue
ACT stands for the Active Request Queue,
WTG stands for the Waiting Request Queue,
TMP stands for the Temp Outage Queue.

System Action: HSC marks the request as having been completed.

User Response: None.

SLS0686I ORH redrive request: ACS AA, SEQNO BBCCC, {ACT|WTG|TMP}

Explanation: Request was redriven by the Overdue Response Handler.

AA ACSid

BB HOSTid

CCC the request sequence number is missing if not on the Active REquest Queue
ACT stands for the Active Request Queue,
WTG stands for the Waiting Request Queue,
TMP stands for the Temp Outage Queue.

System Action: If the request ends up on the Temp Outage Queue again, the required station (path), LMU, or LSM is not ready.

User Response: Take the appropriate action to ready the required station, LMU or LSM.

SLS0687I Invalid reply <CCCCCCCC>

Explanation: A character string was not recognized by the HSC.

CCCCCCCC is the character string that was not recognized.

System Action: None.

User Response: None.

SLS0688I Invalid broadcast message received - *XX* (ignored)

Explanation: A Broadcast was received that was invalid.

XX defines what in the broadcast was invalid:

- 04 - An invalid type was received.
- 08 - An invalid number was received.
- 0C - An invalid ACS was received.
- 10 - An invalid ACS was received.
- 14 - An invalid drive number was received.

System Action: Processing continues.

User Response: Contact StorageTek Software Support.

SLS0689I ORH request not on queue: ACS *AA*, SEQNO *BBCCC*, {ACT|WTG|TMP}

Explanation: Request is no longer on the indicated queue. Overdue response was received while SLS0682D was outstanding.

<i>AA</i>	ACSid
<i>BB</i>	HOSTid
<i>CCC</i>	the request sequence number is missing if not on the Active Request Queue
	ACT stands for the Active Request Queue,
	WTG stands for the Waiting Request Queue,
	TMP stands for the Temp Outage Queue.

System Action: None.

User Response: None.

SLS0690E ORH: no stations ready for redrive: ACS *AA*

Explanation: Operator responded "REDRIVE" to message SLS0682D. In looking for an available station driver to POST, HSC determined that all stations are not ready.

System Action: Processing continues.

User Response: Operator should investigate status of stations. HSC requires one ready station for communication with the LMU.

SLS0691I Invalid UCB for station XXXX

Explanation: An invalid device type was provided by OPEN. In an SMS installation, ACS routines may have improperly altered the OPEN request.

System Action: The station is not varied online.

User Response: Ensure that ACS routines exclude the station devices from device preferencing schemes. If no ACS routines exist, call StorageTek Software Support.

SLS0695I CAPid AA:LL:CC CAP reserve overridden by the CLI/SLC

Explanation: The cap reserve for specified CAP has been taken away via the CLI or the SLConsole by the site administrator.

System Action: The activity for this cap is terminated.

User Response: The cap will be available for new requests when the cap is again available.

SLS0696I CAPid AA:LL:CC CAP door opened

Explanation: The specified CAP has been opened.

System Action: The ENter or Eject waits.

User Response: Empty or fill the CAP, and close it.

SLS0697I CAPid AA:LL:CC CAP door closed

Explanation: The specified CAP has been closed.

System Action: The ENter or Eject continues.

User Response: None.

SLS0698I Req ACS AA SEQ DD/DDD REQ CC CCCCCCCCCC Basic info.

```

LSM LL CCCCCC          A suffix
VOL volser SRC LL/PP:RR:CC CCC XXX
TGT LL/PP:RR:CC CCC XXX      B C D E suffix
LSM LL START PP:RR:CC END PP:RR:CC CCC
                                K suffix
VOL volser                M suffix
TXT CCCCCC....(X53)....CCCCC P suffix
HST DD CCCCCC            Q suffix
LSM LL                    R S ZG suffix
SEQ DD/DDD                V W suffix
LSM LL CAP CC             ZA ZB ZC ZD ZE suffix
LSM LL PNL PP             ZH suffix

```

Explanation: This message describes a failing request. The LMU was unable to complete this request. The associated SLS0699I message describes the error response including the reason for the failure. The basic information is given for every type of request. A suffix is appended for some types of requests. Some request types do not require an additional suffix.

Basic information (all requests):

Req ACS AA SEQ DD/DDD REQ CC CCCCCCCCCC

AA	ACSid
DD/DDD	HOSTid/Request Sequence Number
CC	Request Code (see table below)
CCCCCCCCC	Request Functional Description (see table below)

Request Code Request Function:

A	Vary LSM
B	Mount
C	Dismount
D	Swap
E	Move
K	Catalog
L	Read Configuration
M	Read Volser Status
N	ACS Statistics
P	Host-to-Host Broadcast
Q	Quiesce Host
R	Read Transition Cartridge
S	LSM Status
T	LMU Status

V	Query Request Status
W	Cancel Request
X	View Request
ZA	CAP Reserve
ZB	CAP Release
ZC	CAP Unlock
ZD	CAP Lock
ZE	CAP Status
ZG	LSM PTP Status
ZH	LSM Transport Status by Panel
-	Unknown Req

Type A Suffix (MODify LSM):

“LSM *LL* *CCCCCCC*”

<i>LL</i>	LSM Number (decimal)
<i>CCCCCCC</i>	ONline/OFFline/FORCE

Type B, C, D E Suffix (Mount, DISMount, Swap, MOVE):

“VOL *volser* SRC *LL/PP:RR:CC* *CCC* *XXX*
TGT *LL/PP:RR:CC* *CCC* *XXX*”

<i>volser</i>	Volume Serial Number
<i>LL/PP:RR:CC</i>	Source/Target LSM No.(decimal)/Panel/CAPid:Row:Column
<i>CCC</i>	CAP/CEL/DRV/RDO
CAP	CAP Cell
CEL	Normal Storage Cell
DRV	Writable Drive
RDO	Read Only Drive
<i>XXXX</i>	Drive channel/unit address (DRV/RDO only)

Type K Suffix (Catalog/Cell Scan):

“LSM *LL* START *PP:RR:CC* END *PP:RR:CC* *CCC*”

<i>LL</i>	LSM Number (decimal)
<i>PP:RR:CC</i>	Starting/Ending Panel:Row:Column
<i>CCC</i>	CAP/CEL/DGN/DRV/PNL
CAP	CAP Scan
CEL	Cell Scan
DGN	Diagnostic Cell
DRV	Drive Scan
PNL	Full Panel Scan

Type M Suffix (Read *volser* Status):

“VOL *volser*”

<i>volser</i>	Volume Serial Number
---------------	----------------------

Type P Suffix (Host-to-Host Broadcast):

“TXT CCCCCC.....(x53).....CCCCC”

CCC...CCC Up to 53 character broadcast message

Type Q Suffix (Quiesce Host):

“HST DD CCCCCCCC”

DD HOSTid
CCCCCCCC Normal/Override

Type R,S,ZG Suffix (Read Transition Cartridges, LSM Status, LSM PTP Status):

“LSM LL”

LL LSM Number (decimal)

Type V, W Suffix (Query Request Status, Cancel):

“SEQ DD/DDD”

DD/DDD HOSTid/Request Sequence Number

Type ZA, ZB, ZC, ZD, ZE Suffix (CAP Reserve, RELease, Lock, Unlock, CAP Status):

“LSM LL CAP CC”

LL LSM Number
CC CAP Number

Type ZH Suffix (LSM Transport Status by Panel)

“LSM LL PNL PP”

LL LSM Number (decimal)
PP Panel Number (decimal)

System Action: See SLS0699I error response for types of errors that cause requests to be automatically retried. Otherwise, no further action is automatically taken by the HSC.

User Response: Response depends on the type of failure. See the subsequent message SLS0699I for the same ACS, HOSTid, and Request Sequence Number to determine the type of response necessary to recover from this error.

SLS0699I Response ACS AA SEQ DD/DDD ERR DD/DD CCC...(x28)...CCC CCCCCCCCCCCC
 LSM LL Cartridge Status Suffix
 CCC DD/D Manual Recovery Suffix

Explanation: This message describes the error preventing the completion of a request that is described in message SLS0698I issued previously. The basic information is given for all types of errors. The “Cartridge Status” suffix is added for failing cartridge movement requests. The “Manual Recovery” suffix is added if a cartridge is stuck in a mechanism in an LSM.

Basic Information (for all error types):

AA	ACSid
DD/DDD	HOSTid/Request Sequence Number
DD/DD	Error Category/Error Code (see below)
CCC...(x28)..CCC	Error Descriptive Text (see below)

Error Cat/Code	Descriptive Error Text
-------------------	------------------------

01/xx - Invalid Parameter Error Codes

01/01	Bad Primary LSM
01/02	Bad Secondary LSM
01/05	Undefined Option Or Modifier
01/06	Invalid LSM
01/07	Invalid Panel
01/08	Invalid Row
01/09	Invalid Column
01/10	Invalid Drive
01/11	Invalid CAP Row
01/12	Invalid CAP Column
01/13	Invalid Cell Address
01/14	Invalid Label Modifier
01/15	Invalid Source Modifier
01/16	Illegal Source Type
01/17	Illegal Destination Type
01/18	Illegal Catalog Cell Range
01/19	Illegal Characters In Volser
01/20	Invalid Request Code
01/21	Invalid Transaction Length
01/22	Invalid HOSTid
01/23	Illegal Character In Request
01/24	HOSTid Does not Match
01/25	Duplicate Sequence Number

01/26 Expected Request Or Msg Ack.
01/27 Bad Cancel Request

02/xx - Configuration Error Codes

02/01 LSM Not In LMU Configuration
02/02 Drive Does Not Exist

03/xx - CAP Procedural Error Codes

03/01 CAP Not Reserved
03/02 CAP Already Reserved
03/03 CAP In ENTER Mode
03/04 CAP In EJECT Mode
03/05 CAP Move Active
03/06 CAP Door Open
03/07 CAP Catalog In Progress
03/08 Cannot Kill ENTER On REL Req.
03/09 Cannot free CAP, Door is open
(Door may not be fully closed)
03/10 Cannot cancel ENTER
03/11 CAP magazine not present

04/xx - General Procedural Error Codes

04/01 LSM Is Not Ready
04/02 LSM In Maintenance Mode
04/03 LSM Offline Pending
04/04 LSM Is Offline
04/05 Drive Is Full
04/06 Connecting LSM Not Available
04/07 Mult LSM Requests In Maint.
04/08 Path rej., full PTP deadlock
04/10 Bad Recov. Cartridge Volser
04/11 Maximum Requests Exceeded
04/12 Quiesce Host Already Active
04/13 Quiesce Host Over-Ridden
04/14 Max Read Volser Req/s Active
04/15 Cancel Pending For Request
04/16 Canceled By Cancel Request
04/19 Volser Unexpectedly Readable
04/20 Bad Read Of Volser
04/21 Volsers MisCompare
04/22 Cell Is Full
04/23 Cell Is Empty
04/24 Drive Is Empty
04/25 Drive Is Active
04/26 Drive Is Not Rewound
04/27 Cartridge Is Not Mounted
04/28 Media Miscompare

04/29 Media and Volser Mismatch
04/30 Incompatible Media/Drive

05/xx - LMU Hardware Error Codes

05/01 Rejected; No LSM At Node
05/02 Rejected; Bad LSMid
05/03 Rej.; LSM Not Communicating
05/04 Rejected; Transmission Error
05/05 Rejected; No Acknowledgment
05/06 Rejected; No Operating LAN
05/07 Rejected; Buffer Shortage
05/08 Rejected; Buffer Overflow
05/09 Rejected; No Response To Cmd
05/10 Rejected; LSM Forced Offline
05/11 CAP unlock already active

06/xx - LMU Logical Error Codes

06/01 Unknown Allocation Request
06/02 Bad Qualifier Byte 0
06/03 Bad Qualifier Byte 1
06/04 Bad Qualifier Byte 2
06/05 LSM Online
06/06 Pending Offline Over-Ridden
06/10 Unk Panel Type in LMU Config
06/11 LMU Logical Problem Detected
06/12 Pass-Thru Port Cell Full
06/13 Pass-Thru Port Cell Empty
06/15 Dyn Task Found Full Mailbox
06/16 Allocation Pending Timed Out
06/17 LSM Command Pending Time-Out
06/20 Path logically unavailable

07/xx - LSM Robotics Error Codes

07/01 Arm Malfunction
07/02 Hand Malfunction
07/03 Pass-thru Port Malfunction
07/04 Non-Existent Pass-thru Port
07/05 CAP Malfunction
07/06 No Way To Get There
07/07 Required Element Malfunction
07/08 Robotic Move Failed
07/09 Bad Put
07/10 Bad Get
07/11 Bad Reach Retraction
07/12 Bad Reach Extension
07/13 Pass-thru Port Position Error
07/14 No Hands Operative

07/15 Drive Did not Detect Cart.
 07/16 Move Targeting Failed
 07/17 Reach Is In Unsafe Position
 07/18 Cell Recalibration Failed

08/xx - LSM Hardware Error Codes

08/01 LSM Did not Respond
 08/04 CAP unlock switch overload
 08/05 Unlock Failed
 08/06 Lock Failed
 08/07 Drive Not Communicating
 08/08 Tape Unit Interface Failure
 08/09 Copy Image To Memory Failed

09/xx - LSM Logical Error Codes

09/01 Wrong LSM On Get Response
 09/02 Response Packet Type Not Rec
 09/03 Wrong Task ID On Response
 09/04 Wrong Function ID On Resp.
 09/05 Wrong Cell Address On Resp.
 09/06 LSM Is Offline
 09/07 Bad Cell Location
 09/08 Unknown Ending Status
 09/09 LSM Gave Invalid Response
 09/10 Illogical CAP message
 09/16 Ending Status Ind. Failure
 09/17 Ending Status Indicates Busy
 09/18 Bad Command
 09/19 Bad Params On Command
 09/20 Bad Address Type
 09/21 Bad Panel, Row, Or Column
 09/22 Arm Currently Reserved
 09/23 CAP Currently Reserved
 09/24 Port 1 Currently Reserved
 09/25 Port 2 Currently Reserved
 09/26 Playgrnd Currently Reserved
 09/43 LSM Is Online
 09/44 LSM Is In Maintenance Mode
 09/45 LSM Is Offline
 09/46 LSM Access Door Is Open
 09/47 LSM Is Not Initialized
 09/50 Non-Existent Cell Location
 09/51 Hand Is Full
 09/52 Hand Is Empty
 09/53 Drive Is Full
 09/55 Door Already Unlocked
 09/56 Cannot Unlock In Idle
 09/57 Door Is Open

09/58 Door Already Locked
09/60 Already In Idle Mode
09/61 Already In EJECT Mode
09/62 Already In ENTER Mode
09/63 Cannot EJECT In ENTER Mode
09/64 Cannot ENTER In EJECT Mode
09/60 Door Not Locked For Idle
09/70 Not A Drive Panel
09/71 No Drive Avail. At Address
09/72 Invalid Drive Command Spec.
09/75 Actively Passing Data
09/76 Cannot Rewind
09/77 Cannot Unload
09/78 Drive Cannot Honor Write Protected
09/79 Drive Currently Reserved

10/xx - Drive Error Codes

10/01 Drive Is Not Communicating
10/02 Drive Is Not Operational
10/03 Pending Request For Drive
10/04 Drive Is Allocated
10/05 Drive Has Loaded Cartridge
10/10 Drive Cannot Load Cartridge
10/11 Load/Unload In Progress
10/12 Load Failure on Special Use Cartridge
10/13 Mount Failure Caused by Media Error
10/14 Drive Maintenance Required

Cartridge Status Suffix (for cartridge movement requests):

"CCCCCCCCCCCC LSM LL"

CCCCCCCCCCCC Cartridge Status Descriptor:

Cart Not Mvd	Cartridge Was Never Moved
In Recovery	Cartridge Is Being Recovered
Retd To Src	Cartridge Was Returned To Source
Stuck In Mch	Cartridge Is Stuck In A Mechanism
Unk End Stat	Unknown Cartridge Ending Status
LL	LSMid where cartridge is now

Manual Recovery Suffix (after mechanical failures):

CCC DD/D	Mechanism cartridge is stuck in:
HND D	Robotic Hand (0/1)
PTP DD	Pass-thru Port Panel (01-11)
DRV DD/D	Panel (01-11) & Drive (0/3)

System Action: No further action is taken automatically by the HSC.



Note: Requests ending with 04/01 errors are put in the Temp. Outage Queue and automatically retried when the affected LSM becomes ready again. Requests ending with either 04/11 or 10/03 errors are put on the Waiting Request Queue and retried after 10 seconds. These requests are never reported in SLS0698I and SLS0699I messages unless they eventually end with different errors.

User Response: Depends on the type of error encountered.

If the error indicates that the CAP door is open, insure that the CAP door is closed and latched.

If a parameter error was encountered, modify the appropriate parameter and reissue the request.

If a timing problem was encountered, re-enter the request once the device in question becomes available.

If hardware problem is indicated, retry the failing request. If the problem persists, call StorageTek Hardware Support.

If an HSC or LMU software problem is indicated, retry the failing request. If the problem persists, contact Sun Microsystems Support.

SLS0702I DDname CCCCCCCC failed to open

Explanation: An unsuccessful attempt to open the named file was encountered.

System Action: Validate the data set names of the files being opened.

User Response: Attempt to start the ACS subsystem again. If the error continues, contact your systems programmer for further assistance. If further support is required, contact StorageTek Software Support.

SLS0704E Unable to acquire any ITT blocks; all are owned by host CCCCCCCC

Explanation: A search of the primary control data set revealed that the majority of the ITT blocks are owned by the specified host.

System Action: Attempt to bring up the listed host which will free up ITT blocks.

User Response: Restart the HSC subsystem.

SLS0707I VARINUSE flag off

Explanation: An attempt was made to update a volume record in the ACS control data set, and the in-use flag was not set.

System Action: The attempt is aborted.

User Response: Contact StorageTek Software Support.

SLS0708I VARVOL mismatch

Explanation: An attempt was made to write a volume record, and the volume serial number in the record did not match the volume serial number in the parameter list.

System Action: The attempt is aborted.

User Response: Contact StorageTek Software Support.

SLS0712I DCH invalid

Explanation: An attempt was made to update the control data set when an error was encountered.

System Action: The update attempt is terminated.

User Response: Contact StorageTek Software Support.

SLS0713I VAR area overflow

Explanation: An attempt was made to add a volume to the control data set when an error was encountered.

System Action: The volume add is terminated.

User Response: Contact StorageTek Software Support.

SLS0714I DCHFOLL invalid

Explanation: An attempt was made to locate the next DCH queue entry when an error was encountered.

System Action: The control data set request is aborted.

User Response: Contact StorageTek Software Support.

SLS0715I Database {switch|expand} complete

Explanation: The operation to add, delete, rename, or relocate a CDS copy (switch), or the operation to expand the CDS (expand) has completed. This message is issued when all active hosts in a multi-host environment complete synchronization.

System Action: The CDS switch or expand has completed on all HSC active hosts.

User Response: If the switch is due to an error, correct the error and enter the CDs Enable operator command to restore data sets to the HSC. Also, a switch or expand can occur intentionally by using operator commands.

SLS0717I Database reconfiguration required; expecting *V1.R1.M1.bb* and found *V2.R2.M2.bb*

Explanation: A control data set reconfiguration was required by this release of the software and it was not run.

V1.R1.M1.bb = the version, release and modification level expected by the software
V2.R2.M2.bb = the version, release and modification level found in the control data set

System Action: The subsystem is terminated with a 7004 return code.

User Response: Run the reconfiguration program as required by the current release of the HSC software.

SLS0719I Attach for Insert/Delete User Exit 06 Server failed, RC=XX

Explanation: An attempt was made to attach the Insert/Delete User Exit Server routine (SLSDXIT6). *XX* - is the return code from the ATTACH macro.

System Action: The User Exit 06 code will not be available.

User Response: Determine why the attach failed, and correct the problem. You must recycle the HSC to activate the exit. If you are unable to correct the problem, save all information and contact StorageTek Software Support.

SLS0720I Insert/Delete server routine - *CCC...CCC*

Explanation: The Insert/Delete User Exit 06 server routine (SLSDXIT6) ESTAE was invoked due to an abend. *CCC...CCC* is a 30 byte field that will contain one of the following:

SLSDXIT6 EXIT SERVER ABEND

- an abend has been detected in the SLSDXIT6 Insert/Delete server.

ABEND WITHOUT SDWA

- an abend has been detected in the SLSDXIT6 Insert/Delete User Exit server task and the system did not supply the ESTAE routine with a SDWA.

System Action: User Exit 06 is disabled.

User Response: Save all information and contact StorageTek Software Support.

SLS0721I Insert/Delete User Exit 06 DISABLED, "Invalid Function" Return Code

Explanation: The Insert/Delete User Exit has been disabled because the User Exit 06 code gave a return code indicating an invalid entry type (Function Code) as passed to the User Exit by the HSC exit server task.

System Action: User Exit 06 is disabled.

User Response: Examine the user-written code for User Exit 06 to verify that the return code of hex FF is not the result of a coding error. If it is, correct and dynamically reload User Exit 06. If there is no coding error, save all information and contact StorageTek Software Support.



Note: Dynamic LOad/Reload of User Exit 06 is possible only if the "SLSUEXIT" DD card was included in the HSC JCL deck.

SLS0723I ESTAE creation failed in SLSDXIT6

Explanation: The Insert/Delete user exit server routine (SLSDXIT6) attempted to establish an ESTAE. The ESTAE creation failed. Register 2 at entry to abend contains the ESTAE return code.

System Action: User Exit 06 is disabled.

User Response: Check the return code in register 2 with return codes from the MVS ESTAE macro, and correct any errors. If unable to correct the problem, save all information and contact StorageTek Software Support.

SLS0724I Invalid entry type passed to user exit SLSUX06

Explanation: This is an internal error. The Insert/Delete user exit server routine (SLSDXIT6) passed an invalid function entry type to SLSUX06. Register 2 at entry to abend contains the invalid code.

System Action: User Exit 06 is disabled.

User Response: Save all information, and contact StorageTek Software Support.

SLS0725E Too many errant volumes in ACS AA

Explanation: ACS AA contains too many errant volumes. This number of errant volumes must be reduced before additional volumes can be added.

System Action: The addition to the errant set is not made.

User Response: Vary LSMs OFFline/ONline, or Mount or Eject the errant volumes listed on a volume report so as to invoke errant recovery. If the volumes cannot be located, logically eject them from the library.

SLS0726I Invalid ACSid in DESAD

Explanation: The computation for adding errant records detected that the ACSid being used is invalid.

System Action: The errant set add is aborted.

User Response: Contact StorageTek Software Support.

SLS0730I Permanent error attempting to write database

Explanation: The HSC has encountered a permanent I/O error attempting to write a heartbeat record to the CDS.

System Action: HSC abends.

User Response: Check console logs to determine the cause of the I/O error. If you cannot find and correct the error, contact StorageTek Software Support.

SLS0738D Confirm RECOVER for host CCCCCCCC, reply YES or NO

Explanation: A RECover HOSTid FORCE was requested by the operator.

System Action: This message requests confirmation that a RECover HOSTid is requested.

User Response: Determine if host CCCCCCCC is truly down.

If it is, reply YES to confirm recovery.



Note: RECOVERY OF AN ACTIVE HOST MAY CAUSE CONTROL DATA SET CORRUPTION.

Reply NO to cancel recovery.

You may get the message:

SLS0851I Cross Host Recovery not needed for host CCCCCCCC.

This means there were no resources to be recovered on behalf of the dead host. The proper recovery flags have been set, and the dead host will NOT be permitted to update the control data set until it is recycled.

SLS0745I Duplicate volume *volser* found in database is being deleted

Explanation: The volume record for *Volser volser* was a duplicate created during hash shuffle.

System Action: The duplicate volume record is automatically deleted.

User Response: None.

SLS0746I Stray footprint *volser* found in database is being erased

Explanation: Volume record for Volser *volser* was slated to be moved for hash compression. No duplicate was found.

System Action: The footprint is automatically erased.

User Response: None.

SLS0747I Unexpected empty VAR block

Explanation: A severe logic error has occurred during volume deletion.

System Action: Abend 1096, reason code 747.

User Response: Contact StorageTek Software Support.

SLS0750I SLSWMRT INTERFACE ERROR; PLIST=XXXXXXXX1, RSA=XXXXXXXX2, REASON=XX

Explanation: An interface error has been detected in the subsystem message writer routine. This is an internal error.

XXXXXXXX1 is the address of the parameter list supplied to the message writer routine.

XXXXXXXX2 is the address of the register save area containing the registers at entry to the message writer routine.

XX defines the specific error reason code:

- 01 - Invalid control block acronym
- 02 - Invalid process request type
- 03 - Invalid reply area address
- 04 - Invalid reply ECB address
- 05 - Invalid reply length
- 06 - Unknown message id
- 07 - No MLWTO label text supplied

System Action: The message request is aborted.

User Response: Contact StorageTek Software Support.

SLS0751I SLSWMRT MLWTO ERROR; PLIST=XXXXXXXXX1, RSA=XXXXXXXXX2, R15=XX

Explanation: A non-zero return code has been received from WTO while attempting to output a multi-line request. This is an internal error.

XXXXXXXXX1 is the address of the parameter list supplied to the message writer routine.

XXXXXXXXX2 is the address of the register save area containing the registers at entry to the message writer routine.

XX is the return code from WTO.

System Action: The message request is aborted.

User Response: Contact StorageTek Software Support.

SLS0752I SLSWMRT Unknown message SLSNNNN from module CCCCCCCC

Explanation: A request for message NNNN to be issued was received, but the message did not exist within the message table given to SLSWMRT.

System Action: A dump is taken and processing continues.

User Response: Contact StorageTek Software Support.

SLS0760I {DATABASE|JOURNAL} {READ|WRITE} BDAM parm error; Unit XXXX; Vol
volser; DSname CCCCCCCC; Block DDDDDDDD

Explanation: An I/O error occurred while attempting to READ or WRITE to the indicated control data set or journal. The operation was not completed successfully. Verify that the control data sets are online and accessible.

System Action: Subsystem issues an abend.

User Response: Contact StorageTek Software Support.

SLS0761E {DATABASE|JOURNAL} {READ|WRITE} Permanent error; Unit XXX; Vol
volser; DSname CCCCCCCC; Block DDDDDDDD

Explanation: An I/O error occurred on the indicated control data set or journal file.

System Action: Control data set or journal switch automatically occurs.

User Response: Refer to local disaster recovery procedures.

SLS0762E DATABASE {READ|WRITE|INVALID DATA} error RC= XX

Explanation: An I/O error occurred while attempting to READ or WRITE to one of the control data set files. It is also possible that a successful READ of one of the control data set files occurred, but the data block was determined to be incorrect. RC= is the return code, in hex, from the I/O operation as found in the second byte of the DECB completion code field (DECCC2). The I/O operation was not completed to that file.

System Action: Control data set switch automatically occurs, an SDUMP is produced and the HSC continues operations. This is followed by a separate error message describing the control data set with the error. If the data block is determined to be incorrect, an SDUMP is not taken. SLS0761E is generated and a data base switch is invoked.

User Response: Refer to local disaster recovery procedures for recovery of the bad control data set. Save the SDUMP and contact StorageTek Software Support.

SLS0764I Switching journals; either backup the database or offload the journal(s)

Explanation: The current of the two journals is full, and the other journal is about to become the newly current journal. If journals were disabled, recording is discontinued until BACKup or OFFLoad is run. By doing BACKup or OFFLoad, the journal data set(s) are reset and automatically enabled for transaction recording.

System Action: The journal switch occurs.

User Response: Backup the control data set, or offload the full journal.

SLS0765E Journal DSname CCCCCCCC is DDD% full

Explanation: The currently active journal is DDD% full.

System Action: None.

User Response: The journal file currently in use is becoming full. If the alternate journal is full, backup the control data set or off-load the journals.

SLS0766E Cannot switch journals; both journals have now had I/O errors

Explanation: The current journal had an I/O error, but the system cannot switch journals because the other journal has also had an I/O error.

System Action: Abend 1096, reason code 733.

User Response: Refer to local disaster recovery procedures.

SLS0767E Cannot switch journals; journal DSname CCCCCCCC has not been reset

Explanation: Both journals are full. Journaling cannot continue.

System Action: If JRNDEF FULL=Abend is specified in PARMLIB, the HSC issues abend 1096, reason code 736. If JRNDEF FULL=Continue is specified, journaling is discontinued. The HSC continues to process normally without journals.

User Response: If you receive an abend, run the control data set backups more frequently. If Continue is specified, run a BACKup of all data sets. Journaling continues automatically.

SLS0768E Error follows journal switch

Explanation: Journaling I/O error immediately follows a journal switch.

System Action: Abend 1096, reason code 735.

User Response: Refer to local disaster recovery procedures.

SLS0769I Neither journal has been reset; you must backup the database to reset them

Explanation: At HSC initialization time, the journaling initialization routine determined that both journals are full.

System Action: If FULL=Abend is specified on JRNDEF, HSC terminates. If FULL=Continue is specified on JRNDEF, HSC continues with journaling disabled. For more information, see the JRNDEF section in the *HSC System Programmer's Guide*.

User Response: Run the HSC BACKup utility to reset both journals. Restart the HSC subsystem.

SLS0770I One journal is full; you must backup the database to reset the journals

Explanation: At HSC initialization time, the journaling initialization routine determined that one journal is full.

System Action: HSC initialization continues, using the other journal.

User Response: Run the HSC BACKup utility to reset both journals.

SLS0805I {LET|EET|EOM} Subsystem Exit Not Used; RC=XXXXXXXX

Explanation: During HSC Subsystem Initialization, the Address Space Communications Component (ASCOMM) could not install the subsystem functional routine for the identified SSREQ subsystem exit/broadcast.

LET - Late-End-of-Task, function code 4

EOM - End-of-Memory, function code 8

EET - Early-End-of-Task, function code 50

XXXXXXXX = 12 - number of function code slots for the subsystem was zero, or 8 - all the defined function code slots for the subsystem were used.

System Action: ASCOMM initializes; however, some recovery function, {LET|EET|EOM}, is not available.

User Response: Notify the local System Programming staff. If the problem persists, contact StorageTek Software Support.

SLS0810I XXXXXXXX1 Abend CCCCCCCC, XXXXXXXX2, XXXXXXXX3

Explanation: The Address Space Communications (ASCOMM) Component has detected an abend.

XXXXXXXX1 *abend completion code*
CCCCCCCC *module name*
XXXXXXXX2 *bottom half of PSW at time of error*
XXXXXXXX3 *current TCB at time of error.*

System Action: The ASCOMM request is terminated.

User Response: Refer the problem to StorageTek Software Support. There may also be an SDUMP associated with the abend. If it exists, save a copy of this dump to aid in diagnosing the problem.

SLS0850I Host CCCCCCCC is active

Explanation: Cross host recovery was requested, but the specified host was identified as active.

System Action: Cross host recovery is not performed.

User Response: Physically verify that the host in question is inactive. If and only if this host is inactive, reissue the RECover host command with the FORCE option.



Caution: Use the FORCE operand with great caution. Make sure the specified host is actually inactive before specifying this operand.

Forced recovery of an active host requires that the HSC on that host be recycled. All data base activity is prohibited on the recovered host, which can cause unexpected abends when tape activity occurs or when the HSC is recycled on that host.

SLS0851I Cross host recovery not required for host CCCCCCCC

Explanation: Cross host recovery was requested, but there was no work in progress for the specified host.

System Action: Cross host recovery is not performed.

User Response: None.

SLS0852I Cross host recovery in progress for host CCCCCCCC

Explanation: Cross host recovery is in progress for the specified host.

System Action: Cross host recovery is being performed.

User Response: None.

SLS0853I Cross host recovery complete for host CCCCCCCC

Explanation: Cross host recovery is completed for the specified host.

System Action: Cross host recovery is complete.

User Response: None.

SLS0854D Volume *volser* not found; (logically) Delete or Ignore (D/I)

Explanation: Recovery has determined that the specified volume could not be found in the library. You must decide if the volume is to be logically deleted from the data base.

System Action: Recovery waits until you reply either Delete or Ignore.

User Response: Reply with one of the following:

D This response deletes the volume from the CDS. This may be the best response if you are certain the volume is not in the library.

CAUTION:

If the volume is still in the library, an Audit or manual intervention may be required to locate the missing volume

Other action messages may be issued and require operator responses as a consequence of logically deleting the specified volume.

I This response ignores the request for the volume. This may be the best response if you are uncertain of the location of the volume. This message can reappear if the volume has still not been located. In the meantime, the job waits for the volume to be located and mounted.

SLS0856D No available CAP in ACS AA for LSM LL; Retry or Cancel (R/C)

Explanation: Recovery requires a CAP in order to eject a volume, but there were none that could be selected. The CAPs could be in offline LSMs, have a zero priority, or all be allocated.

System Action: Recovery waits until you reply.

User Response: If a CAP can be made available (DRAIN a CAP, MODIFY a LSM online, or give a CAP a non-zero CAPPref), do so and reply R.

If none can be made available, reply C.

If this occurs during initialization and a CAP cannot be made available, reply C.

When the subsystem completes initialization, make a CAP available and modify the LSM offline and then online.

SLS0857I Invalid reply C

Explanation: A reply to a message was invalid.

System Action: The original message requiring a reply is reissued.

User Response: None.

- SLS0858I** Invalid HOSTid CCCCCCCC
- Explanation:** Cross host recovery was requested for the specified host, but the host is either the same host or not defined to the library software.
- System Action:** Cross host recovery is not performed.
- User Response:** Reissue the command with a correct HOSTid.
- SLS0860D** Non-OCR volume *volser* not found; (logically) Delete or Ignore (D/I)?
- Explanation:** Recovery has determined that the specified non-OCR labeled volume (*volser*) could not be found in the library. You must decide if the volume is to be deleted from the data base.
- System Action:** Recovery waits until you reply.
- User Response:** If the volume should be deleted from the data base, reply D; otherwise, reply I. If recovery is invoked again, the message can reappear if the volume has still not been found.
- SLS0863I** Subtask attach failure; RC=XXXXXXXX; Subsystem not started
- Explanation:** During subsystem initiation, an ATTACH of a task failed with the specified return code.
- System Action:** The subsystem terminates.
- User Response:** Notify the system programmer.
- SLS0864I** Errant recovery of *volser* - Unable to scan {drive XXXX|driveid AA:LL:PP:NN}; it is loaded
- Explanation:** In attempting to locate errant volume *volser*, a drive was found loaded.
- System Action:** Errant recovery of the volume stops.
- User Response:** Unload the drive; then retry errant recovery. To unload a drive in MVS, use the UNLOAD command. To unload a drive in VM, ATTACH the drive to some virtual machine and then DETACH it.

SLS0865I Attached task failure; RC=XXXX

Explanation: During recovery, a task responsible for performing a specific function failed with the specified return code.

System Action: A system dump is taken. Other recovery processing continues.

User Response: Notify the system programmer. Save a copy of the dump to aid in diagnosing the problem.

SLS0866I Host recovery already in progress for HOSTid CCCCCCCC

Explanation: Host recovery was already in progress for the specified host when another RECover host command was issued for that host.

System Action: Processing of the later RECover host command stops.

User Response: None.

SLS0867E Attempting to locate errant volume *volser*

Explanation: The HSC had marked a volume as being errant because it was no longer certain of its location. This is due to many causes. These include modifying the LSM offline, cancelling the HSC, or an error occurring in the LMU or LSM. The HSC is now attempting to locate the volume, and issues this message.

System Action: Processing continues. The message will be DOMed when the location processing is complete.

If the HSC is reasonably sure the volume is not in the ACS, a message will be issued to allow the volume to be deleted from the control data set.



Note: The message will NOT be issued if the HSC is unable to scan locations where the volume might be. For example, if the volume could be in an offline LSM, or on a loaded drive, and the volume could not be located elsewhere, the message will not be issued.

User Response: None.

SLS0868I LMU error XXXXXXXX ACS AA

Explanation: The HSC had an error XXXXXXXX issuing requests to ACS AA

System Action: Processing continues.

User Response: Contact StorageTek Software Support.

SLS0869D Errant recovery of *volser* - {drive XXXX|driveid AA:LL:PP:NN} is loaded; reply Retry, Ignore, or Dismount (R/I/D)

Explanation: :During errant recovery of *volser*, the drive XXXX or driveid AA:LL:PP:NN was found loaded. This implies that the external label could not be read by the robotic vision system.

System Action: Recovery waits for an operator reply.

User Response: If the drive has completed the rewind and unload process, reply R to retry the dismount.

If the volume is known to be on the drive and not allocated to a job on any processor, reply D to force the dismount.

If the drive is in use, reply I to this message, and let the job finish processing the volume on the drive.

If the drive cannot be unloaded due to a malfunction, place the drive offline, contact StorageTek Hardware Support and reply I to this message.

If the volume is not on the drive, reply I.



Note: The I reply will cause the HSC to discontinue the current errant recovery attempt for the volume, leaving it errant. This reply has no lasting effect. This message will be reissued by future errant recovery attempts as long as the drive is loaded and the volume is presumed to be on the drive.

SLS0870I Errant recovery of *volser* - an audit of the locations associated with the volume may be required

Explanation: In attempting to locate errant volume *volser*, a scan of the errant locations could not resolve the location of the volume. Errant recovery found the same OCR readable *volser* at two locations, or both locations had unreadable *volser*s.

System Action: Errant recovery of the volume stops.

User Response: Schedule an audit of the errant locations associated with the volume at a convenient time. The locations can be determined by issuing a Display Volume command.

SLS0871I Errant recovery of *volser* - unable to scan (*D*)

Explanation: In attempting to locate errant volume *volser*, errant recovery was unable to scan a location.

D represents a reason code:

- 7 Drive not communicating. The LMU was unable to communicate with the drive.
- 8 Bad move. The LMU received an error trying to move to a location.

System Action: Errant recovery of the volume stops.

User Response: A Display Volume command shows the volume(s) errant location(s). Contact StorageTek Hardware Support.

SLS0873I Errant recovery of *volser* - Volume at {cell *AA:LL:PP:RR:CC*|drive *XXXX*|driveid *AA:LL:PP:NN*}

Explanation: Errant recovery was able to locate the volume at the specified location.

System Action: If the volume is not in its home location, errant recovery attempts to move it to this location.

User Response: None.

SLS0874A Manually remove cart *XXXXXX* from ACS *AA LSM LL*

Explanation: During HSC startup, cartridge *XXXXXX* was found in ACS *AA LSM LL* in the playground, a robotic hand, or the passthru port. HSC went into recovery mode to try to handle the cartridge. In this case, however, HSC does not have a volume record for this cartridge. HSC will leave the cartridge as found. The cartridge may be manually removed from the LSM, or with HSC 5.0 and later, run the Audit utility with the INTRANS parameter. These cartridges are normally in the playground.

System Action: Processing continues normally. The cartridge is left where it was found.

User Response: Open the LSM and remove the cartridge from the library, or run an Audit utility with the INTRANS parameter. If the cartridge is left in the LSM, this message will be issued at each start up of HSC and each time the HSC Service Level is brought from Base to Full.

- SLS0898I** Recovery of *volser1* - found *volser2* in cell *AA:LL:PP:RR:CC*; new cell assigned for *volser1*
- Explanation:** During recovery *volser2* was found in the home cell of *volser1*.
- System Action:** *Volser1* will be assigned a new home cell.
- User Response:** An audit of the home cell location *AA:LL:PP:RR:CC* may be required to locate *volser2* and insert it into the CDS.
- SLS0899I** Recovery of *volser* - cell *AA:LL:PP:RR:CC* requires auditing
- Explanation:** While attempting to recover the specified volume, an error occurred. The cell the volume was to be moved to was found to be occupied by another cartridge.
- System Action:** Recovery attempts to pick another cell and retries the move.
- User Response:** Audit the cell listed in the message text.
- SLS0901D** Mount of *volser1* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - *volser* readable (*volser2*); Retry, Bypass, Eject, or Ignore (R,B,E,I)
- Explanation:** When going to mount *volser1*, the LMU found a Volser with a different external label *volser2*. The volume was originally marked in the control data set as having no external label.
- System Action:** Mount waits.
- User Response:** If the mount is to be retried, reply R. If the volume is to be marked as bypass label processing and the mount retried, reply B. If the volume is to be ejected, reply E. Volser *volser1* will be deleted from the control data set. Additionally, if *volser2* is not in the control data set, it will be physically ejected.
- If the mount is to be ignored, reply I.
- SLS0902D** Dismount of *volser1* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - *volser* readable (*volser2*); Retry, Bypass, Eject, or Ignore (R,B,E,I)
- Explanation:** When going to dismount *volser1*, the LMU found a Volser with a different external label *volser2*. The volume was originally marked in the control data set as having no external label.
- System Action:** Dismount waits.
- User Response:** If the dismount is to be retried, reply R.
- If the volume is to be marked as bypass label processing and the dismount retried, reply B.
- If the volume is to be ejected, reply E. Volser *volser1* will be deleted from the control data set. Additionally, *volser2* will be physically ejected if it is not in the control data set.
- User Response:** If the dismount is to be ignored, reply I.

SLS0904I Swap of *volser* from {drive XXXX|driveid AA:LL:PP:NN} - Error doing scan

Explanation: In an attempt to swap *volser*, a scan of the drive was required. However, the LMU indicated a move error occurred or it could not communicate with the drive.

System Action: The swap is not executed.

User Response: Enter a DISMount command for drive XXXX|driveid AA:LL:PP:NN (the “from” drive) to retry the dismount portion of the swap. Then enter a Mount command to mount volume *volser* on the “to” drive.

SLS0905D No cartridges to clean {drive XXXX|driveid AA:LL:PP:NN} ACS AA; Reply "I", "T,capid,volser", or "R" (Ignore, Temp Enter or Retry)

Explanation: There were no cleaning cartridges compatible with the drive found in ACS AA.



Note: Different types of transports require different cleaning cartridge media types. For example, longitudinal transports (4480s, 4490s, and 9490s) require standard cleaning cartridges, and RedWood transports require DD3D cleaning cartridges.

System Action: Mount waits for a reply.

User Response: Reply with one of the following:

- | | |
|----------------|--|
| I | Ignore the mount request. Cleaning will no longer be scheduled for this transport. |
| T,capid,volser | Temporarily enter the specified cleaning cartridge from the specified CAP to clean the drive. (Note: The <i>volser</i> of the cleaning cartridge temporarily entered does not have to start with the cleaning prefix.) |
| R | Retry the cleaner lookup (presumably after entering some cleaning cartridges). |



Warning: New cleaning cartridges compatible with the transport must be entered for automated cleaning to proceed. See “Tape Transport Cleaning” in the “Mount/Dismount Functions” section of “Chapter 2 - HSC Functions” of the *HSC System Programmer's Guide*.

- SLS0906E** Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Unable to mount
- Explanation:** The HSC on this host could not mount a volume. Other messages should be issued to indicate the source of the problem.
- System Action:** The mount fails.
- User Response:** Check for error messages on all systems attached to the ACS. Attempt to correct the problem, and reissue the mount request.
- SLS0907I** Mount of *volser1* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Overriding mount *volser2* request
- Explanation:** An attempt was made to mount *volser1*, but there was a mount request queued for volume *volser2*.
- System Action:** The mount of *volser2* is not executed. The mount of *volser1* is executed.
- User Response:** None.
- SLS0908I** Mount of *volser1* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Mount of *volser2* active; attempting suppression
- Explanation:** The mount of *volser1* found a mount request active for *volser2*.
- System Action:** The system attempts to suppress the mount scratch. Regardless of the success of the suppression, the mount of *volser1* is executed.
- User Response:** None.
- SLS0909D** Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - LSM *AA:LL* in manual mode; reply Delete or Ignore (D/I)
- Explanation:** A request was received to dismount a volume in a manual mode LSM.
- System Action:** The dismount waits until you reply D or I, modify the LSM online, or issue a “MNTD Dismount Auto” command.
- User Response:** If the volume is to be manually dismounted, reply D; otherwise, reply I.
- If D, the volume is removed from the control data set. The volume should be removed from the library until an ENter can be performed.
- If I, the volume is not deleted from the control data set.
- If the LSM is modified online, the dismount continues.

SLS0910I - SLS0912I

SLS0910I {Mount|Dismount} of *volser* {on|from} driveid *AA:LL:PP:NN* - Request terminated

Explanation: A request was received to mount or dismount a tape. The request is terminating, and no other message was issued. Check for other outstanding messages or operations that might be holding the volume locked.

System Action: None.

User Response: None.

SLS0911D Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Manual volume at *AA:LL:PP:RR:CC*; reply Delete or Ignore (D/I)

Explanation: A request was made to mount a volume from a manual LSM.

System Action: The mount waits until you reply D or I, or modify the LSM online.

User Response: If the volume is to be manually mounted, remove the volume from location *AA:LL:PP:RR:CC*. When the volume IS IN YOUR HAND, reply D to delete it from the control data set. When dismounted, the volume should be removed from the library until an ENter can be performed.

If the request is to be ignored, reply I.

If the LSM is modified online, the mount proceeds normally.

SLS0912I Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Drive is loaded; mount request is being aborted

Explanation: Mount found a drive that had a volume mounted so it invoked dismount. Dismount found that the drive was loaded, and the volume to be dismounted matched the volume to be mounted.

System Action: The dismount request is cancelled. The mount request will also be aborted.

User Response: If the volume really needs to be dismounted and the drive is not in use, unload the volume from the drive and reissue the mount. To unload a drive in MVS, use the UNLOAD command. To unload a drive in VM, ATTACH the drive to some virtual machine and then DETACH it.

SLS0913I Robotics request active for {drive XXXX|driveid AA:LL:PP:NN} - unable to mount

Explanation: A robotic request was active for the mentioned drive by another system. Two mount requests for the same drive were issued, and the mount from this system found that the request from the other system was being processed first.

System Action: The mount request from this system is cancelled.

User Response: The job requesting the mount may have to be cancelled and resubmitted because the HSC found a mount in process for the same drive by another system. The mount on this system will not be redriven.

SLS0917I Dismount transaction complete

Explanation: A dismount operation, as a result of a dismount message or an HSC DISMount command, is being processed for a volume which has already been put away. HSC determined the volume on the drive is not the volume the dismount request was for. This message is issued as a result of two dismount operations being received for the same drive and same volume.

System Action: HSC issues this message and ignores the dismount request.

User Response: None.

SLS0923I {Drive XXXX|driveid AA:LL:PP:NN} has been cleaned using *volser*

Explanation: The drive was automatically cleaned using the specified *volser*.

System Action: None.

User Response: None.

SLS0925D Eject of *volser* - Volume not in cell AA:LL:PP:RR:CC; Reply (Logically) Delete or Ignore (D,I)

Explanation: An Eject operation found the volume location in the control data set, but the location was empty.

System Action: You are asked to Delete (D) the entry from the control data set, or to Ignore (I) the request.

User Response: A reply of D cleans up the control data set and assumes the volume is not in the library.

A reply of I terminates the operation.

SLS0926I C invalid reply

Explanation: The operator reply does not match the options offered by the WTOR. C is the invalid reply from the operator.

System Action: The WTOR is re-issued to give the operator another chance.

User Response: Reply with a valid option.



Note: C can only be one byte long.

SLS0927A Wrong cartridge entered; expected *volser1* and found *volser2*

Explanation: The operator was requested to enter a specific Volser (*volser1*) in response to a temporary enter. The wrong Volser (*volser2*) was found in the CAP.

System Action: The CAP door is unlocked to allow the operator access.

User Response: Open the CAP door, and remove the incorrect cartridge (*volser2*). Replace it with the correct cartridge (*volser1*), and close the CAP door.

SLS0928A ENTER processing interrupted; empty CAPid *AA:LL:CC*

Explanation: Enter processing has been interrupted. Cartridges have been left in the CAP. CAPid *AA:LL:CC* needs to be emptied.

System Action: The system waits until the operator opens and closes the CAP door at which time the CAP is examined to ensure it is empty. The system may reissue this message if cartridges are left in the CAP. Once the CAP is empty, enter processing continues.

User Response: Open the CAP door, and remove all cartridges.

SLS0929I {Enter|Eject} of *volser* - *CCC...CCC*; run a utility audit against cell *AA:LL:PP:RR:CC*

Explanation: Either an ENter operation found that a cell that was supposed to be empty was not. Or an Eject operation failed and the CAP component was unable to place the volume in errant status. *volser* is the volser of the volume. *CCC...CCC* is a 32-byte description of the error.

System Action: The ENter or Eject operation will terminate.

User Response: Run an audit against the reported cell location to correct the control data set.

- SLS0931I** LSM AA:LL is {NOT READY|OFFLINE PENDING|OFFLINE}
- Explanation:** The specified LSM is OFFLINE, PENDING OFFLINE, or NOT READY.
- System Action:** The request found an LSM that was not online and ready.
- User Response:** Ensure that the specified LSM is online and ready.
-
- SLS0934D** EJECT of *volser*, Drive not rewound; reply Dismount, Retry or Ignore (D,R,I)
- Explanation:** An Eject operation from a drive found that the drive had not been rewound and unloaded.
- System Action:** The system waits for the operator to reply R (Retry), D (Dismount) or I (Ignore).
- User Response:** In MVS, use the MVS Unload command to unload the volume. In VM, ATTACH the drive to some virtual machine and then DETACH it.
- A reply of R retries the eject without the rewind option.
- A reply of D retries the operation with the rewind option.
- A reply of I conditionally makes the volume errant and terminates the operation.
-
- SLS0935D** EJECT of *volser* - *volser* not readable; reply Bypass label checking or Ignore (B,I)
- Explanation:** An Eject operation was requested against a volume, but the operation failed because the cartridge label was not readable.
- System Action:** You are asked to Bypass label checking (B) or Ignore (I) the request.
- User Response:** A reply of B retries the Eject and will bypass label checking.
- A reply of I conditionally makes the volume errant and terminates the operation.
-
- SLS0936D** EJECT of *volser* - SOURCE VOLSER DOES NOT MATCH DB; reply Ejector Ignore (E,I)
- Explanation:** An Eject operation was attempted, and the *volser* found in the location specified by the control data set does not match the requested *volser*.
- System Action:** You are asked to Eject (E) or Ignore (I) the request.
- User Response:** A reply of E retries the Eject with bypass label checking.
- A reply of I unconditionally makes the volume errant and terminates the operation.

SLS0937D - SLS0954D

- SLS0937D** ENTER of *volser* - Source *volser* not readable; reply Bypass label checking or Eject (B,E)
- System Action:** An ENter operation was requested for a volume, but the operation failed because the cartridge label was not readable.
- System Action:** You are asked to Bypass (B) the request, or Eject (E) the volume.
- User Response:** A reply of B retries the ENter with bypass label checking. A reply of E ejects the volume with bypass label processing.
- SLS0938I** Enter failed; requested LSM # is frozen.
- Explanation:** The ENTER command requested a LSM that is frozen.
- System Action:** The ENTER command terminates.
- User Response:** Re-issue the ENTER command using a TLSM that is not frozen. To unfreeze a frozen LSM, use the SLUADMIN SET FREEZE(OFF) utility.
- SLS0953I** Unknown RC *XXXXXXXX* from ASCOMM
- Explanation:** The volume lookup routine made a request of the HSC address space. An unexpected return code was received from the HSC cross memory service (ASCOMM).
- System Action:** The request is aborted.
- User Response:** Notify the system programmer.
- SLS0954D** JES3 C/I waiting for HSC to initialize; start the HSC or reply "GO" to continue
- Explanation:** The HSC address space has not been initialized. JES3 Converter/Interpreter processing is waiting for an operator reply ("GO") or the HSC to initialize before continuing.
- System Action:** The JES3 Converter/Interpreter waits.
- User Response:** If the HSC is required, start the HSC address space. Otherwise, reply "GO". This message causes only one C/I DSP to wait. If no other C/I DSPs are available to convert the HSC JCL, start one by issuing the JES3 command: *F,X,D=CI,MC=(,n) where n is the current value +1.

```

SLS1000I      ACS AA status: CCCCCCCCC1

                Compatibility levels: HSC=DD1, LMU=DD2
                (Partition ID=DDD3)
                (Waiting Queue elements           DDDDDDDDD4)
                (Active Queue elements           DDDDDDDDD5)
                (Temporary Outage Queue elements DDDDDDDDD6)
                Dual LMU CCC2 Configured
                (Master Is C3; Standby Is CCCCC4)
                Station DDDD7 CCCCCCCC5
                Scratch Volumes available       DDDDDDDDD8
                Free Cells available             DDDDDDDDD9

```

Explanation: Issued in response to a Display AcS command. A Partition ID with a value greater than zero signifies a partitioned ACS. Queue counts are only displayed if they are not zero. Master/Standby LMU line is only displayed if Dual LMU is active. One line is displayed for each station defined. If an ACS is either disconnected or unallocated the Free Cell count will be unknown.

Variables:

```

AA           ACSid: "00"-"FF"
CCCCCCCCC1  ACS availability:
    CONNECTED   At least one station is online
    DISCONNECT  No stations currently online
    UNALLOCATED Indicates an ACS place holder
DD1          HSC compatibility levels
             10 means HSC 2.0
             11 means HSC 2.0.1 support for Multi-Media
             12 means HSC 2.1 and greater
             13 means HSC 6.0 and greater
             20 means 6.1 and greater
             21 means 6.1 and greater
DD2          LMU compatibility levels
             05 means LMU 3.2 u-software supporting the enhanced CAP
             06 means LMU 3.8 u-software supporting the 4430 Multi-Media
             10 means LMU 1.0 u-software supporting Wolfcreek
             11 means LMU 1.1 u-software supporting the 93xx Multi-Media
             12 means LMU 1.5+ u-software supporting 9840 and 97xx
             13 means SL8500 Base support
             20 means SL8500 Base and Partitioning Support
             21 means SL8500 and SL3000 Support
DDD3        Partition ID: "000"-"999"
DDDDDDDD4   count of Waiting Request Queue elements
DDDDDDDD5   count of Active Request Queue elements
DDDDDDDD6   count of Temp Outage Queue elements
CCC2        Dual LMU configured: "Is" or "Not"
C3          Master LMU designator: "A" or "B"
CCCCC4      Standby LMU status: "ready" or "not ready"

```

SLS1001I - SLS1002I

If ready, there must be a STANDBY station to enable automatic switchover to occur

DDDD7 Station Device Number.

DDD.DDD.DDD Station IP Address

CCCCCCCC5 Station hostname

CCCCCCCC6 Station Status:

ONLINE	Enabled Path to Master LMU
OFFLINE	Disabled Path to ACS
STANDBY	Enabled Path to Standby LMU
PENDING ONLINE	Path being varied online
PENDING OFFLINE	Path being varied offline
PENDING FORCE	Path being forced offline
NOT READY	Network attached LMU not initialized
NETWORK RECONNECT	Network recovery active
TCP/IP CON ERR	Network recovery failure
UNKNOWN	Station status or Free Cell count

DDDDDDDD8 number of Scratch Volumes available

DDDDDDDD9 number of Free Cells available



Note: The functionality available in the HSC is implied by the lowest number indicated on the compatibility level line.

System Action: System continues processing.

User Response: None.

SLS1001I ENTER not scheduled on CAPid *AA:LL:CC*

Explanation: A SENter command was entered for CAPid *AA:LL:CC*. The ENter was not scheduled. No interruption of the Eject command occurs. Possible reasons for “NOT ACCEPTED” are:

- 1) The CAP is not allocated by this host.
- 2) The CAP is not ejecting.

System Action: None.

User Response: None.

SLS1002I ACS *AA*: Switch already active

Explanation: A SWitch command has already been entered for the named ACS.

AA is the ACSid.

System Action: This SWitch command is terminated, but the previous SWitch command continues processing.

User Response: If a previous SWitch command was entered, no response is necessary; otherwise, report this incident to StorageTek Software Support.

SLS1003I Switch failed, ACSid is required

Explanation: There is more than one ACS in the configuration, so ACSid must be specified.

System Action: SWitch command processing is terminated.

User Response: Re-enter the SWitch command including a specification of the ACSid to be switched.

SLS1004I ACS AA cannot switch; no standby stations

Explanation: Even though the named ACS is a Dual LMU ACS, there are currently no standby stations connecting the HSC to the standby LMU for this ACS.

System Action: SWitch command processing is terminated.

User Response: Vary a station online to the standby LMU, and re-enter the SWitch command.

SLS1005I ACS AA cannot switch; ACS disconnected or not Dual LMU

Explanation: The named ACS is not a Dual LMU ACS or all stations to this ACS are offline, so no station is available to the standby LMU.

System Action: SWitch command processing is terminated.

User Response: None.

SLS1007I ACS AA: Initiating switch via station C...C

Explanation: SWitch command parameters have been validated, and an available standby station has been selected for sending the SWitch command to the standby LMU who notifies the master LMU.

System Action: The selected standby station driver has been notified to initiate the switchover process.

User Response: None.

SLS1010I - SLS1012I

SLS1010I *CCCCCCCC1* value list not allowed with *CCCCCCCC2* value list on *CCCCCCCC3* command

Explanation: A *CCCCCCCC3* command was entered that encountered a *CCCCCCCC1* parameter having a value list (more than one value separated by commas or dashes) and a *CCCCCCCC2* parameter having a value list. However, there can only be one *CCCCCCCC1* value identified on the command if the *CCCCCCCC2* parameter is supplied with a value list.

System Action: The command is rejected.

User Response: Correct the command parameters, and re-enter the command.

SLS1011I The range specified on the *CCCCCCCC1* parameter of the *CCCCCCCC2* command is invalid or not allowed

Explanation: A range of cells was specified on an operator command. The specified range contains more than 100 volumes or a range is not allowed for this parameter.

System Action: None.

User Response: Enter multiple commands specifying ranges of 100 volumes or less, or run the corresponding batch HSC Utility (which has no limit on cell ranges), or remove the invalid range.

SLS1012I The value list specified for the *CCCCCCCC1* parameter of the *CCCCCCCC2* command exceeds the maximum number of list items

Explanation: An attempt was made to enter a command or utility function specifying a value list for the *CCCCCCCC1* parameter of the *CCCCCCCC2* command exceeding the maximum number of list items.

System Action: The requested command or utility terminates.

User Response: Re-enter the command or utility specifying a value list where the number of items is equal to or less than the maximum number listed.

SLS1014I SCRATCH SUBPOOL SUMMARY:
 ACS(AA)
 LSM(LL) SUBPOOL(CCCCCCCCCCCC1) SCRATCH
 COUNT=DDDDDDDD1
 SUBPOOL(CCCCCCCCCCCC2) SCRATCH
 COUNT=DDDDDDDD2
 LSM(LL) SUBPOOL(CCCCCCCCCCCC3) SCRATCH
 COUNT=DDDDDDDD3 SUBPOOL(CCCCCCCCCCCC4) SCRATCH
 COUNT=DDDDDDDD4
 TOTAL SCRATCH=DDDDDDDD

Explanation: The Display SCRatch command successfully completed. The number of scratch volumes available for active subpools is displayed.

System Action: None.

User Response: None.

SLS1015I ACS AA LSM LL:CC...CC1|DD..DD1 invalid for CC...CC2 parameter on CC...CC3 command

Explanation: Invalid data was entered for the specified command.

AA	ACSid (hexadecimal 00-FF)
LL	LSMid (hexadecimal 00-FF)
CC...CC1 DD...DD1	data entered on command in error
CC...CC2	option specified on command in error
CC...CC3	name of command whose syntax rules were violated

System Action: The system takes no further action, except that a default value is used, and the command proceeds when the view time is invalid.

User Response: Re-enter the command with the correct parameters.

SLS1016I - SLS1016I

SLS1016I ACS AA LSM LL: CCCCCCCC1 rejected, CCC...CCC2 CCC...CCC3

Explanation: The specified command was rejected due to the specified condition.

AA	ACSid (hexadecimal 00-FF)
LL	LSMid (hexadecimal 00-FF)
CCCCCCCC1	name of command (Vlew, etc.)
CCC...CCC2	name of object (ACS, ACSid, ADDRESS, CAP column, CAP row, cell column, cell row, COLUMN, Connecting LSM, HOST, HSC, LMU, LSM, LSMid, PANEL, PLAYGRND, PTP column, ROW, XLSM) or LMU request return code (if logic error condition)
CCC...CCC3	condition of object (does not exist, has downlevel micro-software, is disconnected, is invalid, is offline, is shutting down, not found, not specified, parameter specified in error, same as another parameter) OR logic error

System Action: The command is rejected. The system takes no further action.

User Response: The user may re-enter the command when the condition has been alleviated.

SLS1018D	ACS AA LSM LL; holding camera <N> for <time> seconds on <component> <location>
AA	ACSid (hexadecimal 00-FF)
LL	LSMid (hexadecimal 00-FF)
<N>	camera number (decimal 0-1)
<time>	5-120 as entered in the VIEw command or defaulted from the OPTion Viewtime command
<component>	CAPid, CE11, HOSTid & Drive, PLAYgrnd, or PTP as entered on the VIEw command
<location>	address (ROW RR COL CC, PP:RR:CC, XXX, CC, or LL:CC) as specified on the VIEw command

Explanation: The VIEw command successfully completed. The camera is being held in the position requested.

System Action: The camera is held in position for the requested time interval, after which the robot is freed for other work. A record is optionally written to the SMF data set to log this event.

User Response: You should look at the monitor indicated by the ACS, LSM, and camera identifiers, note the status of the element being inspected, and then respond to the outstanding WTOR (any response at all) to free the hand to do other work. If you do not respond to the WTOR, the hand is automatically freed at the expiration of the specified or defaulted time interval.

SLS1021I VOLSER and SUBPOOL are mutually exclusive

Explanation: The SUBpool parameter was specified with a specific volser. The SUBpool parameter may only be specified when SCRTCH is specified.

System Action: The system takes no further action.

User Response: You should re-enter the EJECT command specifying the SUBpool parameter with SCRTCH, or re-enter the command specifying a specific volser only.

SLS1022I VOLSER *volser* remains selected

Explanation: An attempt was made to unselect the above volume after it was entered into the library as scratch. An error occurred while attempting to unselect the volume resulting in the volume being left selected.

System Action: The ENter process terminates.

User Response: You should examine the console log, and determine if other errors have occurred as a result of the ENter process or LMU errors. A Display Volume will indicate the status of the volume. It may be necessary to run the UNSElect utility.

SLS1023I VOLSER *volser* was not made scratch

Explanation: A volume was entered into the library with the SCRatch option; however, a problem was encountered which prevented the volume from being put into the scratch list.

System Action: The ENter process terminates.

User Response: You should examine the console log and determine if other errors have occurred as a result of the ENter process or LMU errors. A Display Volume will indicate the status of the volume. It may be necessary to run the SCRatch update utility to get the volume into the scratch list.

SLS1024I Unable to select VOLSER *volser*

Explanation: An attempt was made to select the above volume after it was entered into the library. An error occurred while attempting to select the volume, resulting in the volume being left unselected.

System Action: The ENter process terminates. The volume is successfully entered into the library but is not considered a scratch volume.

User Response: You should examine the console log and determine if other errors have occurred as a result of the ENter process or LMU errors. A display of the volume will indicate the status of the volume. It may be necessary to run the SCRatch update utility to get the volume into the scratch list.

SLS1026I CCCCCC of EXIT successful

Explanation: CCCCCC is the function. For the Load function, the requested exit was loaded successfully. If the exit is enabled, the new module will be invoked when the exit is invoked. For the Enable function, the most current module for the exit enabled successfully. When the exit is invoked, this module is used. For the Disable function, the most current module for the exit disabled successfully.

System Action: HSC processing continues.

User Response: None.

SLS1027I CCC...CCC1 of EXIT failed, CCC...CCC2

Explanation: CCC...CCC1 is the function requested. For the Load function, the requested exit could not be loaded. For the Enable function, the most current exit could not be enabled. For the Disable function, the most current exit could not be disabled.

CCC...CCC2 is the reason for the error message.

Reason Explanations

- all user exits are inactive--Self Explanatory
- user exit number invalid--Must be UX01-UX99 format
- module not found--Load Module not in Load Library
- load error occurred--HSC internal error, try again
- function is invalid--Not "LOAD", "ENABLE", or "DISABLE"
- exit status invalid--Not "ACTIVE", or "DISABLE"
- lock attempt failed--HSC internal error, try again
- program error occurred--HSC internal error, try again
- exit is not dynamic--Exit may not be reloaded

System Action: HSC processing continues.

User Response: For the load function, verify that the requested module is a member name in the load module library described by the SLSUEXIT DD statement in the HSC startup procedure or within the STEPLIB data set concatenation. For the enable function, verify that a module is successfully loaded and is in a disabled state. For the disable function, verify that a module is successfully loaded and is in an enabled state.

SLS1028I - SLS1028I

SLS1028I User exit status:
EXIT STATUS LOAD-TIMESTAMP MODNAME SEQ # STATUS-CHANGED
ccc1 ccccccc2 ccccccccccccc3 ccccccc4 nnnnn ccccccccccccc5
:
:
:
QUERY of EXIT successful

Explanation: A UEXIT QUERY command was entered. The status of the requested user exit(s) is displayed. One line of information is presented for each exit requested, with the following format:

<i>ccc1</i>	the user exit identifier
<i>cccccc2</i>	represents the user exit status. It is one of: ACTIVE the exit is loaded and active INACTIVE the exit is not loaded DISABLED the exit is loaded, but either was loaded in disabled status, or has been disabled ABENDED the exit is loaded, but was deactivated due to an abend PENDING the exit is loaded, and a UEXIT DISABLE command has been issued. The disable has not completed.
<i>ccccccccccc3</i>	represents the date and time the user exit was loaded. The value is either <i>yyyy-mm-dd hh:mm:ss</i> or NEVER LOADED if the exit is not loaded.
<i>cccccc4</i>	shows the name of the module loaded for this exit, or N/A if the exit is not loaded.
<i>nnnnn</i>	is the number of times this exit has been loaded, or NONE if the exit is not loaded.
<i>ccccccccccc5</i>	represents the date and time the user exit status last changed. The value is either <i>yyyy-mm-dd hh:mm:ss</i> or NEVER CHANGED if the exit is not loaded.

System Action: The user exit status information is displayed.

User Response: None.

SLS1030I HSC service level {BASE|FULL} active

Explanation: The command Display SRVlev successfully completed. The HSC is executing at the indicated service level.

This message appears when the Display SRVlev command for the base or full service level is completed.

System Action: None.

User Response: None.

SLS1031I SUBpool(CCCCCCCCCCCCCC) not found; operator command ended

Explanation: An attempt was made to enter an operator command with the optional parameter SUBpool, but the requested subpool was not known to the HSC.

System Action: The operator command terminates without performing the requested function.

User Response: Validate the SUBpool name, and re-enter the operator command.

SLS1032I No match found for ACSid AA; operator command ended

Explanation: An attempt was made to enter an operator command for a specific ACSid; however, a match for the ACSid was not found.

System Action: The operator command terminates without performing the requested function.

User Response: Re-enter the operator command with the correct ACSid.

SLS1033I No match found for LSMid AA:LL; operator command ended

Explanation: An attempt was made to enter an operator command for a specific LSMid, but the LSMid entered was not found.

System Action: The operator command terminates without performing the requested function.

User Response: Correct the LSMid, and re-enter the operator command.

SLS1034I No subpool data found for SUBpool XXXXXX

Explanation: An attempt was made to enter the Display SCRatch command with optional parameters such as ACSid, LSMid or SUBpool, but no match was found for the specified data. XXXXXX is the SUBpool name.

System Action: No information is displayed.

User Response: Correct the appropriate input parameter, and re-enter the operator command.

SLS1035I CCCCCC of EXIT failed; user exit index is not valid

Explanation: CCCCCC is a function of the UEXIT command. Functions include Load, Enable, Disable or Query. The exit number passed in the UEXIT command was not within the current existing exit numbers.

System Action: The command terminates.

User Response: Provide the correct user exit number.

SLS1036I No scratch volumes exist for subpool CCCCCCCCCCCC in ACS AA

Explanation: The Eject command requested scratch volumes be ejected from a specific subpool; however, no scratch volumes were available for that subpool in the ACS.

System Action: The command terminates.

User Response: Select a different subpool from which to eject scratch volumes, or run the SCRATCH utility to make volumes scratch.

SLS1037I THRESHOLD VALUE SUMMARY:

```
ACS AA Threshold DDDDDD  LSM LL Threshold DDDD
Subpool CCC...CCC  Threshold DDDDDD
Subpool CCC...CCC  Threshold DDDDDD
Subpool CCC...CCC  Threshold DDDDDD
.
.
.
Subpool CCC...CCC  Threshold DDDDDD
```

Explanation: The Warn command successfully completed. The Threshold values represent the values set by the Warn command.

System Action: The system takes no further action, and normal operation continues.

User Response: No further user action is required.

SLS1038I Scratch Subpooling not in effect; Operator command terminated

Explanation: An attempt was made to enter an operator command specifically dealing with scratch subpools; however, scratch subpooling was not in effect.

System Action: The operator command terminates without performing the requested function.

User Response: Enter the command only if scratch subpooling is active.

SLS1039I Invalid Subpool name *XXXXXX* specified in *CCCCCC* - Operator command terminated

Explanation: An operator command *CCCCCC* was issued which specified an invalid subpool name.

System Action: The operator command is terminated without performing the requested function.

User Response: Issue the operator command specifying a valid subpool name.

SLS1040I *CCCCCCCC1 CCCCCCCC2* confirmed

Explanation: This message indicates that *CCCCCCCC1* value is *CCCCCCCC2*.

As an example, the various option setting commands invoked at HSC start-up time can have a HOSTid keyword. If HOSTid is there, it will be confirmed prior to the command executing.

System Action: None.

User Response: None.

SLS1041I A keyword must be provided for the *CCCCCCCC* command

Explanation: Command *CCCCCCCC* was entered without a keyword.

System Action: None.

User Response: Re-enter the command with an appropriate keyword.

SLS1042I - SLS1052I

SLS1042I CCCCCCCC ACS List:

ACSID(s): (AA,AA,AA-AA)

Explanation: This message displays the setting of the CCCCCCCC keyword ACS list where AA is an ACS identifier.

System Action: None.

User Response: None.

SLS1050I CCCCCCCC information is not available; subsystem is not at the proper service level

Explanation: The Display command was not able to obtain the CCCCCCCC information because the subsystem was not at the correct service (functional) level. This message may be displayed before the HSC has fully initialized or when the service level has been changed by the SRVlev command. Display SRVlev can be used to display the current service level of the HSC.

System Action: None.

User Response: Re-enter the Display request when the subsystem is at the proper level.

SLS1051I CCCCCCCC1 command not executed; HSC is at service level CCCC2

Explanation: The Subsystem did not execute the CCCCCCCC1 command because the Subsystem was not at the correct service level as indicated by CCCC2 (BASE or FULL).

System Action: None.

User Response: Re-enter the request when the subsystem is at the proper level.

SLS1052I CCCCCCCC1 command not executed; HSC service level CCCC2 change in progress

Explanation: The Subsystem did not execute the CCCCCCCC1 command because the Subsystem is currently processing a change against CCCC2 (BASE or FULL).

System Action: None.

User Response: Re-enter the request when the subsystem is at the proper level.

SLS1053E CCCCCCCC1 command not executed;VSM not active

Explanation: The Subsystem did not execute the CCCCCCCC1 command because the Virtual Tape Control System (VTCS) support for the Virtual Storage Manager (VSM) is not running on this system.

System Action: None.

User Response: Re-enter the request when VTCS is active.

SLS1071D RELEASE CAP AA:LL:CC requested; reply N to cancel, or Y to continue

Explanation: The RELEase CAP command was entered. Verify that the CAP is not in use by any system before replying Y to this message. To cancel the release of the CAP, reply N.

System Action: If the response is Yes, CAP release processing continues. If the response is No, the CAP is not released.

User Response: Reply with Y or N.

SLS1072I CAP AA:LL:CC released

Explanation: The RELEase CAP command has successfully completed. CAP AA:LL:CC has been released.

System Action: None.

User Response: None.

SLS1074I HSC CCCCCCCCCCCCCC1 options:
CCCCCCCC2 - CCCCCCCC3 (for downlevel SMC)

Explanation: This message displays the setting of all keywords for one of the component related set option commands. If the individual keyword setting is followed by the text “(for downlevel SMC)”, it means that the option is only in effect when servicing requests from a downlevel SMC client.

System Action: None.

User Response: None.

SLS1075D - SLS1152I

SLS1075D Dismount of *volser* from {drive *XXXX*|driveid *AA:LL:PP:NN*} - Error on Tape; Ignore or Eject (I/E)

Explanation: An error (e.g., message IEC512I) caused the dismount of volume *volser*.

System Action: You are asked to Ignore (I) the error on the tape volume or to Eject (E) the tape volume from the library.

User Response: A reply of Ignore causes the volume to be dismounted normally. A reply of Eject causes the volume to be dismounted and ejected from the library. In either case, you should examine the system log for messages (e.g., IEC512I, IEC502E) which describe the tape error and may be important in deciding how to proceed with running the job.

SLS1150I Volume(s) *volser*<-*volser*> not in Library

Explanation: One or more of the volumes requested for a SLUADMIN utility function was not defined in the Library. If a volume range was specified on the utility command and a sequential series of volumes within that range was not found, a single message will be displayed for the series.

System Action: The utility continues processing.

User Response: None.

SLS1151I Scratch subpool definitions not available

Explanation: The HSC was not available for the scratch subpool definitions to be determined, or no subpools were defined.

System Action: The utility continues processing. Scratch subpool totals will not be available.

User Response: None.

SLS1152I NOVOLIST parameter specified; No SUMMARY or VOLDATA present

Explanation: The user specified the NOVOLIST parameter. However, neither SUMMARY nor VOLDATA keywords were present.

System Action: The utility stops processing. A return code 4 is set for the utility.

User Response: None.

SLS1153I *CCCCCCCC1* parameter list not allowed with parameter *CCCCCCCC2* value list, on *CCCCCCCC3* function

Explanation: A *CCCCCCCC3* function was processed that encountered a *CCCCCCCC1* parameter and a *CCCCCCCC2* parameter that had a value list (more than one value separated by commas or dashes). There can only be one *CCCCCCCC1* value identified on the function if the *CCCCCCCC2* parameter is supplied with a value list.

System Action: The utility control statement for the listed function is rejected.

User Response: Correct the parameters on the utility control statement for the function listed, and re-issue the command.

SLS1154I The range specified on the *CCCCCCCC1* parameter of the *CCCCCCCC2* function is invalid or not allowed.

Explanation: A range of cells was specified on a function in a utility command statement. A range is not allowed for this parameter.

System Action: None.

User Response: Remove the invalid range.

SLS1155I *DDDD* volume(s) moved to LSM *AA:LL*

Explanation: *DDDD* number of volumes were moved to LSM *AA:LL* by the MOVE function.

System Action: None.

User Response: None.

SLS1156I *DDDD* volume(s) moved

Explanation: *DDDD* volumes were moved during the MOVE function.

System Action: None.

User Response: None.

SLS1157I *DDDD* volume(s) not moved

Explanation: *DDDD* volumes were not moved during the MOVE function.

System Action: None.

User Response: None.

SLS1158I - SLS1162I

SLS1158I SCRATCH misspelled on ENTER utility control statement

Explanation: A SLUADMIN ENTER utility was attempted; however, the SCRATCH option specified on the ENTER control statement was misspelled.

System Action: The requested utility function terminates.

User Response: Make the necessary control statement correction, and resubmit the utility.

SLS1159I SUBpool (CCCCCCCCCCCC) is invalid - not known to system

Explanation: The EJECT utility requested scratch volumes to be ejected from a specific subpool; however, the subpool is not known to the system.

System Action: The utility terminates.

User Response: Select a different subpool from which to eject scratch volumes.

SLS1160I HSC Address Space Communications is not active

Explanation: The SCREdist (scratch redistribution) utility could not start an ASCOMM task.

System Action: The utility terminates.

User Response: Contact StorageTek Software Support.

SLS1161I Invalid keyword detected on PARM input

Explanation: A SLUADMIN utility job was submitted with a PARM= value that contained an invalid keyword. Valid keywords are:

MIXED, NOHDR, LINECNT=nn and DATE=4YR|2YR

Where nn is a value between 10 and 99. NOHDR and LINECNT are mutually exclusive.

System Action: The utility function is terminated.

User Response: Correct the value in the JCL PARM field and resubmit.

SLS1162I Parm values LINECNT and NOHDR are mutually exclusive

Explanation: A SLUADMIN utility job was submitted with a PARM= value containing both NOHDR and LINECNT. These two parameters are mutually exclusive.

System Action: The utility function is terminated.

User Response: Select either NOHDR or LINECNT for the SLUADMIN job and resubmit.

SLS1163I Invalid LINECNT on PARM input

Explanation: A SLUADMIN utility job was submitted with a PARM= containing an invalid value for LINECNT. The value for LINECNT is a number between 10 and 99.

System Action: The utility function is terminated.

User Response: Correct the value for LINECNT in the JCL PARM and resubmit.

SLS1177I The CDS specified on the CDS keyword is inactive

Explanation: The CDS keyword specified a data set that incurred an error. Refer to other utility messages that should be present.

System Action: The utility terminates.

User Response: If the CDS had an I/O error, run the backup against the other CDS if available. Restore the CDSs as soon as possible.

SLS1178I Volser *volser* CCCCCCCC1 location indicated CAP AA:LL:CC

Explanation: The specified volume was either in transit or errant as denoted by source or destination CCCCCCCC1. The present location is unknown; however, it may be in the CAP designated by AA:LL:CC.

System Action: The utility continues.

User Response: Display the volume. If the volume is currently in its home cell location, no action is necessary. However, if the volume is errant, use the Eject or Mount command to invoke errant recovery. If a RESTore was necessary, errant recovery will occur during HSC initialization.

SLS1179I Volser *volser* CCCCCCCC1 location indicated DRIVE CCCCCCCC2

Explanation: The specified volume *volser* was either in transit or errant as denoted by source or destination CCCCCCCC1. The present location is unknown; however, it may be in the drive designated by CCCCCCCC2.

System Action: The utility continues.

User Response: Display the volume. If the volume is currently in its home cell location, no action is necessary. However, if the volume is errant, use the Eject or Mount command to invoke errant recovery. If a RESTore was necessary, errant recovery will occur during HSC initialization.

SLS1180I - SLS1184I

SLS1180I The block count between the primary and secondary control data sets do not match

Explanation: The BACKup utility data set validation found a mismatch between the number of blocks in the primary and secondary control data set.

System Action: If the CDS parameter indicated secondary, the utility terminates. Otherwise, the utility continues using the primary data set.

User Response: Ensure that the correct data sets are being used. If they are, this error implies that relative location addressing is inconsistent between the two data sets. Analyze the data sets to see if the block count is the same. It may be required to restore the data sets in order to correct this situation. In order to back up the Secondary CDS, if this is the case, specify the Secondary as SLSCNTL and the Primary as SLSCNTL2. This allows a proper reserve to occur on the primary while backing up the secondary.

SLS1181I Open failed for SLSCNTL

Explanation: An attempt to open the specified file was not successful.

System Action: Refer to operating system messages and codes for appropriate action.

User Response: Make the necessary correction, and run the utility again.

SLS1182I Open failed for SLSLIBGN

Explanation: An attempt to open the specified file was not successful.

System Action: Refer to operating system messages and codes for appropriate action.

User Response: Make the necessary correction, and run the utility again.

SLS1183E Wrong format CDS

Explanation: LISTCDS encountered a CDS prior to V1.0.4

System Action: The utility terminates without further action.

User Response: Correct the situation described in the error message, and resubmit the job.

SLS1184I Read error on CDS

Explanation: An attempt to read the file pointed to by the SLSCNTL DD statement has failed.

System Action: The utility terminates.

User Response: Make the necessary correction, and run the utility again.

SLS1185I LSM has no drives or passthru ports

Explanation: The HSC CDS pointed to by SLSCNTL has no indication of drives or a passthru port.

System Action: The utility terminates.

User Response: Verify that the SLSCNTL DD card specifies the correct CDS. If the CDS is correct, contact StorageTek Software Support.

SLS1186I LIBGEN record CCCCCCCCCC

Explanation: A record (CCCCCCCC) is being echoed to the SLSPRINT file from the LIBGEN decompile utility.

System Action: None.

User Response: None.

SLS1187I Possible invalid CDS - (CCC...CCC)
 where (CCC...CCC) is:
 No host count found
 No TCHNIQUE specified
 Unknown panel type
 LSM configuration error

Explanation: SLUDBMAP has found a problem with the HSC CDS pointed to by the SLSCNTL DD statement.

System Action: The utility terminates with a non-zero return code.

User Response: Verify that the SLSCNTL DD card specifies the correct CDS. If the CDS is correct, contact Sun Microsystems Software Support.

SLS1188I Control Data Set updated for volume *volser* with observed cell location *AA:LL:PP:RR:CC*

Explanation: A SLUADMIN AUDIt utility found a volume *volser* in the Cell scan phase in a location that does not agree with the control data set location (different or non-existent) and has updated the control data set with the observed cell location. This message is issued if problem level of detail was requested for the output of the audit (PROBLEM specified).

System Action: Audit processing continues.

User Response: None.

SLS1189I Cartridge in cell *AA:LL:PP:RR:CC* has been ejected to CAP *AA:LL:CC*

Explanation: A SLUADMIN AUDIt utility found a cartridge with a duplicate volume serial or unreadable label in cell *AA:LL:PP:RR:CC* and has ejected the cartridge from the library using CAP *AA:LL:CC*. This message is issued if problem level of detail was requested for the output of the AUDIt (PROBLEM specified).

System Action: Cartridge is physically ejected from the library.

User Response: Remove the cartridge from the CAP. If a previous message was issued that the volume in the the cell has an unreadable label, then, after affixing a readable label, you may wish to re-enter the volume. If a previous message was issued stating that the volume in the cell was a duplicate, you may wish to eject the volume left in the cell and re-enter this one depending on which volume should be in the library.

SLS1190E Maximum *CCCCCC* discrepancy count reached

Explanation: The BACKup analysis routine found that the maximum count of discrepancies was reached for *CCCCCC*. *CCCCCC* can be SCRATCH, SELECT or AUDIT. Limits for each discrepancy type are:

AUDIT = 96,000
SELECT = 10,000
SCRATCH = 10,000

System Action: The utility discontinues discrepancy saving and output for the discrepancy type. All prior discrepancies for this type are still saved and output for RESTore processing.

User Response: If the discrepancy type is AUDIT, a full audit should be run after the RESTore.

If the discrepancy type is SCRATCH, the SCRAtch utility should be run after the RESTore.

If the discrepancy type is SELECT, contact StorageTek Software Support.

SLS1191E (...error text...)

Explanation: LISTCDS encountered a problem. Valid error text messages include:

- Premature end of file
- No DPV record found
- Invalid record in CDS
- OBTAIN failed on CDS
- No VOLSERS in PARM
- No VOLSERS matched CDS
- Invalid count
- SLSCNTL DD not present
- Track calculation error
- Parameter syntax error
- Too many record types in CDS
- Range not allowed
- List max exceeded
- DVAR max of 1000 exceeded

System Action: The utility terminates without further action.

User Response: Correct the situation described in the error message, and resubmit the job. If you get the message “Too many record types in CDS”, it may be an internal error and you should call Sun Microsystems support.

SLS1192I CCCCCCCC1 parameter CCCCCCCC2 invalid

Explanation: A SLUADMIN utility did not recognize a valid keyword CCCCCCCC2 combined with the input parameter CCCCCCCC1.

System Action: The utility terminates processing.

User Response: Supply the proper input keyword and parameter; then submit the SLUADMIN utility job.

SLS1193I Recovery techniques do not match

Explanation: The DPV recover technique flags did not compare between the primary and secondary control data sets.

System Action: The utility continues processing.

User Response: Ensure that the data sets provided are the correct ones. If not, obtain the proper data sets and resubmit the SLUADMIN utility job. If these are the proper data sets, either run the SET utility to re-establish the technique or run a RESTore to resolve the DPV flags.

SLS1194I A CCCC mismatch occurred in block XXXX1 at offset XXXX2

Explanation: A mismatch between the primary and secondary copies of the control data sets was detected. This error message occurs when a bit in either block does not compare. It does not mean that either data set is bad but rather that analysis of the block will be done. CCCC is the block name. XXXX1 is the hexadecimal number of the block that encountered the error. XXXX2 is the hexadecimal offset into the block of the first error.

System Action: The block will be analyzed.

User Response: This information can be used to diagnose a problem with the block indicated.

SLS1197I CCCCCCCC is indicated but the DD statement is not present

Explanation: This is a warning message stating that the recovery technique indicates a secondary or standby data set. However, one of the required DD statements is not present. Valid secondary DD statements are SLSSHDW, SLSCNTL2 and DBASESHD. The valid standby DD statement is SLSSTBY.

System Action: The utility continues.

User Response: Provide the DD statement, if necessary, and resubmit the SLUADMIN backup utility job.

SLS1198I The CCCCCCCC control data set DD statement is invalid or not present

Explanation: The control data set DD statement was not found to be valid. Valid DD statement names are SLSCNTL or DBASEPRM for the primary control data set and SLSSHDW, SLSCNTL2 or DBASESHD for the secondary data set.

System Action: The utility will terminate if this is the primary control data set.

User Response: Provide the DD statement as necessary, and resubmit the SLUADMIN utility job.

SLS1199I The Backup being restored is from DDDDDDDD at HH:MM:SS

Explanation: The RESTore utility found that the backup being restored was taken on DDDDDDDD at HH:MM:SS. The format of DDDDDDDD depends on the DATE=4YR|2YR parameter on the BACKUP utility. For DATE=4YR (default), the date will be in YYYYMMDD format. For DATE=2YR, the date will be in MM/DD/YY format.

System Action: None.

User Response: If this is not the backup desired, obtain the proper backup; and resubmit the SLUADMIN RESTore utility.

SLS1200I Invalid eyecatcher EBCDIC(CCCC) HEX(XXXX) found in CCCCCCCC

Explanation: An invalid block eyecatcher was found. The message gives both the EBCDIC CCCC value and an EBCDIC formatted hex XXXX value so that the actual four byte field may be seen for the CCCCCCCC DD data set.

System Action: The data set found with this condition is placed inactive. If no other control data sets are available, the utility terminates. If this is the BACKup utility and the CDS parm is specified for the data set that went inactive, processing terminates. Otherwise, processing continues on the other control data set if available.

User Response: Ensure that the correct control data set was supplied. Browse the given data set, and find the block in question. If this data set is correct, contact StorageTek Software Support.

SLS1201I SLUDRTL M could not find the VMF control record

Explanation: An attempt by SLUDRTL M to read the TLMS VMF control record was unsuccessful.

System Action: No further processing of the TLMS VMF will be attempted by SLUCONDB.

User Response: Ensure that SLUDRTL M is assembled with the same version of the TLMS source library as is the TLMS VMF. For example, if using a TLMS 5.4 VMF, SLUDRTL M must be assembled with the TLMS 5.4 source library in the SYSLIB concatenation for the assemble step.

SLS1202I Utility incomplete, make corrections and rerun

Explanation: A SLUADMIN utility could not complete due to the errors indicated by other SLSxxxx messages.

System Action: The utility terminates processing.

User Response: Make corrections, and resubmit the SLUADMIN utility job.

SLS1203I Missing or invalid CCCCCCCC DD statement

Explanation: A SLUADMIN utility could not locate the required CCCCCCCC DD statement or the information provided (such as device type or data set) was invalid, or, if running VOLRPT and referencing datasets from HSC, either HSC was not active or was not at the same release level as the VOLRPT.

System Action: The utility terminates processing.

User Response: Supply the proper DD statement, and resubmit the SLUADMIN utility job.

SLS1204I - SLS1208I

SLS1204I I/O error reading the *CCCCCCCC* data set

Explanation: An I/O error occurred while reading to the *CCCCCCCC* DD data set.

System Action: The data set found with this condition is placed inactive. If no other control data sets are available, the utility terminates. If this is the BACKup utility and the CDS parm is specified for the data set that had the error and went inactive, processing terminates. Otherwise, processing continues on the other control data set if available.

User Response: Supply the correct *CCCCCCCC* data set, and resubmit the SLUADMIN utility job.

SLS1205I I/O error writing the *CCCCCCCC* data set

Explanation: An I/O error occurred while writing to the *CCCCCCCC* DD data set.

System Action: The data set found with this condition is placed inactive. If no other control data sets are available, the utility terminates. If this is the BACKup utility and the CDS parm is specified for the data set that had the error and went inactive, processing terminates. Otherwise, processing continues on the other control data set, if available.

User Response: Supply the correct *CCCCCCCC* data set, and resubmit the SLUADMIN utility job.

SLS1207I Not enough space in the *CCCCCCCC* data set

Explanation: A SLUADMIN utility could not continue to process against the *CCCCCCCC* data set because there was not enough space.

System Action: The utility terminates processing.

User Response: Supply the proper amount of space, and resubmit the SLUADMIN utility job.

SLS1208I The *CCCCCCCC1* data set was made inactive; processing will continue on the *CCCCCCCC2* data set

Explanation: The BACKup utility detected that one or the other *CCCCCCCC* DD control data sets went inactive and continued the BACKup on the other data set. Any discrepant data found before the *CCCCCCCC1* data set error is kept. Compares are still performed on *CCCCCCCC2* to obtain cell information and generate DSEL (UNSELECT), DSCR (UNSCRATCH), and DAUD (AUDIT) blocks.

System Action: The utility continues processing on one data set instead of two.

User Response: None.

- SLS1209I** All Control data set copies found inactive; *CCCCCCCC* terminated
- Explanation:** A SLUADMIN utility detected that all control data set copies went inactive. An I/O error or block error occurred.
- System Action:** The utility terminates.
- User Response:** Look for another SLSxxxx message that shows the cause of the error.
- SLS1210I** Processing has started for the *CCCC* block
- Explanation:** The BACKup utility has begun analysis of the *CCCC* block.
- System Action:** Detailed block analysis.
- User Response:** None.
- SLS1211I** Processing complete for the *CCCC* block
- Explanation:** The BACKup utility completed analysis of the *CCCC* block.
- System Action:** None.
- User Response:** None.
- SLS1212I** *CCCCCCCC1* has been verified for the *CCCCCCCC2* utility
- Explanation:** A SLUADMIN utility *CCCCCCCC2* information *CCCCCCCC1* has been verified. An example *CCCCCCCC1* is JCL.
- System Action:** None.
- User Response:** None.
- SLS1213I** Discrepancy blocks have been generated
- Explanation:** At least one Discrepancy block was generated during backup. A Volser or cell location was found to be invalid. A block was placed in the SLSBKUP data set to allow for an action (AUDIT, UNSELECT or UNSCRATCH) upon restore.
- System Action:** A discrepancy block is output to the SLSBKUP data set.
- User Response:** None.

SLS1214I - SLS1218I

SLS1214I No discrepancy blocks were generated

Explanation: No discrepancy blocks were generated during backup. The utility did not find any volser or cell discrepancies.

System Action: None.

User Response: None.

SLS1215I CCCCCCCC1 was successfully copied to CCCCCCCC2

Explanation: The data set specified by the CCCCCCCC1 DD statement was successfully copied to the data set specified by CCCCCCCC2.

System Action: None.

User Response: None.

SLS1216I CCCCCCCC was selected as the control data set to output

Explanation: The data set specified by the CCCCCCCC DD statement was selected to be output to the SLSBKUP data set. This is done by either the BACKup utility keyword CDS(Primary|Secondary) or by the BACKup utility program based on the data set seen to have the most updates.

System Action: None.

User Response: None.

SLS1217I CCCCCCCC data set was not on DASD

Explanation: The data set specified by the CCCCCCCC DD statement was not found to be on a DASD volume.

System Action: The utility terminates.

User Response: Place the CCCCCCCC data set on a DASD volume, and restart the utility.

SLS1218I DHBEFLAGS may not have been reset in a CDS

Explanation: The DHBE host active flags may not have been reset due to a previous error condition.

System Action: Utility terminates.

User Response: Check the report for a prior error and take action based on that message.

- SLS1219I** *CCCCCCCC1* data set was successfully restored from *CCCCCCCC2*
- Explanation:** The data set specified by the *CCCCCCCC1* DD statement was restored from the *CCCCCCCC2* DD data set.
- System Action:** None.
- User Response:** None.
- SLS1220I** The HSC is not at the proper service level
- Explanation:** An attempt was made to run a given utility, but the HSC was not at the correct level to run this utility.
- System Action:** The utility terminates.
- User Response:** Bring the HSC up to the proper service level, and run the utility again.
- SLS1221I** No scratch volumes available for subpool *CCCCCCCCCCCC*
- Explanation:** The EJECT utility requested scratch volumes be ejected from a specific subpool; however, there were no scratch volumes available in the subpool.
- System Action:** The utility terminates.
- User Response:** Select a different subpool from which to eject scratch volumes, or run the SCRATCH utility to make volumes scratch.
- SLS1222I** Parameter *CCC* invalid with HSCLEVEL
- Explanation:** The parameter specified with the HSCLEVEL keyword is invalid.
- System Action:** The command is ignored.
- User Response:** Make sure the named host is down, and rerun the SET utility with a valid HSCLEVEL parameter.
- SLS1223I** HSCLEVEL set to *CCC* for Host *CCCCCCCC*
- Explanation:** The CDS host active and HSC level flags for the named host have been set to indicate that the host is inactive.
- System Action:** None, unless the named host is really active, in which case a running host will turn on its “host active” and HSC level status flags again.
- User Response:** None.

SLS1224I Cells *AA:LL:PP:RR:CC- AA:LL:PP:RR:CC* found empty or invalid

Explanation: The cell or cells in question were found empty or may not be a valid cell to hold a volume. Compare with past audits to check for validity.

System Action: The volume is made errant.

User Response: The mentioned cell should be audited to insure correctness, if necessary.

SLS1227I RESTORE is required before running SET TCHNIQE

Explanation: A SLUADMIN utility (SET TCHNIQE) is attempting to SET the Control DataSet recovery TCHNIQE and has noticed that RESTore was not run. BACKup and RESTore must be run prior to running SET TCHNIQE.

System Action: The utility terminates processing.

User Response: RESTore CDS copies and resubmit the SLUADMIN utility (SET TCHNIQE) job.

SLS1250D ENTER of volume *volser* encountered missing duplicate *volser*;
(Logically) Delete, or Ignore (D,I)?

Explanation: An ENter operation found a duplicate volume in the control data set, but the volume could not be physically located in the library.

System Action: You are asked to Delete (D) the volume entry from the control data set or Ignore (I) the enter request.

User Response: A reply of Delete removes the volume entry from the control data set thus allowing the cartridge to be entered. A reply of Ignore terminates the entry of the new volume.

SLS1251E CAPid *AA:LL:CC (CCCCCCCC1): CCCCCCCC2*

Explanation: The specified requestor (*CCCCCCCC1*) requested that the string *CCCCCCCC2* be displayed when the CAP was opened or unlocked.

System Action: None. The message is unhighlighted when the CAP door is closed.

User Response: None.

SLS1252I EJECT of *volser* - Volume deleted from the CDS

Explanation: An operator replied I to message SLS0925D.

System Action: None.

User Response: None.

SLS1253I CCC...CCC rejected - CCC...CCC is CCC...CCC

Explanation: A CAP operation failed. Possible responses are:

- ENTER|EJECT rejected - ACSid AA is invalid
- ENTER|EJECT rejected - ACSid AA is not connected
- ENTER|EJECT rejected - CAP AA:LL:CC is busy
- ENTER rejected - CAP AA:LL:CC is unavailable
- ENTER|EJECT rejected - LSMid AA:LL is invalid
- ENTER|EJECT rejected - LSMid AA:LL is offline
- ENTER of *volser* rejected - LSMid AA:LL is full
- ENTER of *volser* rejected - Operation is aborted by operator
- EJECT of *volser* rejected - Volume is busy
- EJECT of volume *volser* rejected - CAP AA:LL:CC is not in the same ACS as the volume

System Action: None.

User Response: None.

SLS1254I {ENTER|EJECT} rejected; non-zero return code XXXXXXXX

Explanation: An unexpected return code was returned from CAP processing.

System Action: The request is rejected.

User Response: Contact StorageTek Software Support.

SLS1255I OPTion DUPOFL set to ON, enter of dup *volser* allowed, scan of dup *volser* cell returned LMU RC - XXXX

Explanation: During the ENter of the *volser* it was found to be a duplicate of a *volser* the control data set believes is in the library. There is a hardware issue preventing a physical verification of what is in the cell where the control data set believes the *volser* exists. The LMU RC defines the hardware problem preventing the physical *volser* lookup. See the *HSC Message and Codes Guide*, chapter titled Return Codes for an explanation of the LMU RC.

System Action: The OPTion DUPOFL setting of ON has allowed the duplicate *volser* processing to occur. The duplicate *volser* was logically deleted from the control data set. The *volser* found to be a duplicate during ENter processing is entered into the library.

User Response: None.

SLS1300D - SLS1303I

SLS1300D CAPid AA:LL:CC allocated to AUDIT Utility; KEEP or RELEASE the CAP?
(K or R)

Explanation: A SLUADMIN utility function has a Cartridge Access Port (CAP) allocated which may be released and reallocated to another function requiring the use of a CAP. If the CAP is released, the utility function may at some later time attempt to reallocate the CAP if required.

System Action: The utility waits until either a valid response is provided or for five minutes to pass.

User Response: Respond R if the CAP should be released. Then empty the CAP and close the door. The audit will then resume.

Respond K if the CAP should remain allocated for the duration of the utility.

If no response is provided in the five minute time interval, a default response of K is assumed.

SLS1301I Invalid reply C

Explanation: A reply to a message was invalid.

System Action: The original message requiring a reply is reissued.

User Response: Give a valid reply when the message is reissued.

SLS1302I Unable to allocate CAPid AA:LL:CC, RC=XXXXXXXX

Explanation: A SLUADMIN utility function requiring a Cartridge Access Port (CAP) could not allocate the CAP specified on the utility control statement.

System Action: The utility terminates.

User Response: Determine the reason for the indicated CAP error return code, and resubmit the SLUADMIN utility job.

SLS1303I Unable to allocate CAP in ACSid AA, RC=XXXXXXXX

Explanation: A SLUADMIN utility function requiring a Cartridge Access Port (CAP) could not allocate a CAP in the specified ACS.

System Action: The utility terminates.

User Response: Determine the reason for the indicated CAP error return code, and resubmit the SLUADMIN utility job.

- SLS1304I** No scratch volumes exist for subpool CCCCCCCC in ACS AA
- Explanation:** The EJECT utility requested scratch volumes be ejected from a specific subpool; however, no scratch volumes were available in ACS AA.
- System Action:** The utility terminates.
- User Response:** Select a different subpool from which to eject scratch volumes, or run the SCRATCH utility to make volumes scratch.
- SLS1310I** Invalid LIBONLY specified in PARM parameter of JCL
- Explanation:** A SLUCONDB utility program detected the LIBONLY positional parameter was incorrectly specified in the invoking JCL.
- System Action:** The parameter is indicated in error, and the utility terminates with a return code of 8.
- User Response:** Respecify parameter correctly.
- SLS1311I** Program interface error encountered while processing volume volser;
RC=XXXXXXXX
- Explanation:** A SLUCONDB utility program encountered an error while attempting to place a volume into scratch status via the HSC Program Interface.
- System Action:** The volume and return code are indicated in the message text, and the utility terminates with a return code of 8.
- User Response:** Refer to the *HSC Messages and Codes Manual* to determine the cause of the error, correct the error, and resubmit the job.
- SLS1312I** DDDDDDD volumes successfully scratched
- Explanation:** A SLUCONDB utility program successfully placed the specified number of volumes into scratch status.
- System Action:** None.
- User Response:** None.
- SLS1313I** No valid parameters specified for the CCCCCCCC utility
- Explanation:** The utility depicted by CCCCCCCC requires at least one valid keyword or parameter.
- System Action:** None.
- User Response:** Provide the appropriate keyword, and resubmit the utility.

SLS1314I - SLS1318I

SLS1314I CDS *CCCCCCCCCC* was not provided in the JCL

Explanation: Data set name *CCCCCCCCCC* was found in a CDS but was not provided in the utility JCL.

System Action: Termination occurs for the SET utility.

User Response: Add the appropriate CDS DD statement in the utility JCL.

SLS1315I *DDDDDDDD* was selected as the *CCCCCCCC* control data set

Explanation: The utility function found that data set *DDDDDDDD* was the *CCCCCCCC* CDS according to the DHB block or the JCL.

System Action: The utility continues.

User Response: None.

SLS1316I Standby control data set not used during analysis

Explanation: The utility function found that the standby DD statement was provided during the execution of BACKUP OPT(Analyze).

System Action: The utility discontinues use of the standby data set.

User Response: None.

SLS1317I No DES record found for errant volume *volser*

Explanation: During an AUDIt, a VAR record was found for volume *volser* that showed the volume to be errant. However, no matching DES record was located for the errant volume in the CDS. This message should be accompanied by message SLS0180I in the SLUADMIN AUDIt report.

System Action: The utility terminates without completing the requested function.

User Response: This message indicates a serious logical problem with the CDS, and probably indicates database corruption has occurred. Save all console logs (SYSLOG), and be prepared to provide a backup copy of the CDS as problem documentation. Contact StorageTek Software Support.

SLS1318I Volume *volser* now has a readable label

Explanation: During an AUDIt, a VAR record was found for volume *volser* that showed the volume to have an unreadable external label. However, the actual scan of the volume showed the OCR label was readable and matched the *volser* in the VAR.

System Action: The utility updates the CDS to indicate the volume has a readable external label.

User Response: None.

SLS1320I Unrecoverable mount error on device *DDD* volser *volser* for JOB *NNNNN*

Explanation: HSC detected a volume mount error in response to an IAT5310 message for a mount requested in message IAT5210.

System Action: HSC breaks the mount loop and issues a dismount to the indicated device (*DDD*). The job remains in the MDS VERIFY Q.

User Response: Refer to the IAT5310 message for the cause of the Mount error, and take corrective action.

SLS1321I Invalid parameter found at end of PARM parameter of JCL

Explanation: The SLUCONDB utility program detected additional characters after the end of valid parameters specified in the invoking JCL.

System Action: The utility terminates with a return code of 8.

User Response: Respecify the PARM parameters correctly. Then execute the utility again.

SLS1403I Parmlib control statement value *CCCCCCCC* invalid for
SCRPOOL=*CCCCCCCC*

Explanation: Processing of the SCRPOOL control statement has uncovered the specified error.

'CCCCCCCC' of 'value *CCCCCCCC*' can contain the following text:

<i>RANGE</i>	Indicates a problem with the "RANGE" usage
<i>RANGE=(111111-222222)</i>	Indicates a problem with the "RANGE" list
<i>111111</i>	The 1st value in a given SCRPOOL range list
<i>222222</i>	The 2nd value in a given SCRPOOL range list
<i>NAME</i>	Indicates a problem with the "NAME" usage
<i>LABEL</i>	Indicates a problem with the "LABEL" usage
<i>HOSTID</i>	Indicates a problem with the "HOSTID" usage

SLS1404I - SLS1407I

System Action: The SCRPOOL control statement in error will not be processed, and that subpool definition will not be in the system.

User Response: Make the necessary corrections. Then bring HSC down and back up to activate the changes.

SLS1404I Duplicate definition(s) for SCRPOOL CCCCCCCCCCCCCC ignored

Explanation: HSC detected a SCRPOOL statement for a subpool name that was already defined.

System Action: HSC ignores the duplicate definitions.

User Response: Remove duplicate definitions of subpool CCCCCCCCCCCCCC from the HSC start-up parms.

SLS1405I The scratch threshold task could not be reinstated

Explanation: The scratch threshold task was terminated. HSC could not successfully reinstate the task.

System Action: HSC processing continues.

User Response: Contact StorageTek Software Support.

SLS1406I Label Type CCC is already assigned to SUBPOOL CCCCCCCCCCCCCC

Explanation: HSC initialization found multiple label types being assigned to the same subpool.

System Action: Probable user error. Ensure that only one label type per subpool is being specified when defining subpools to HSC.

User Response: Correct user error in either HSC User Exit 03 or HSC PARMLIB member defining scratch subpools.

SLS1407I User SCRATCH subpool definition from CCCCCCC initiated

Explanation: User SCRATCH subpool definition, using CCCCCCC as the source, has begun.

CCCCCCC = "PARMLIB" - Source for User SCRATCH subpool definition is the "SLSSYSnn" DD card; = "UEXIT03" - Source for User SCRATCH subpool definition is User EXIT 03.

System Action: The user SCRATCH subpools are defined. This message is normally followed by messages SLS1969I and SLS1408I.

User Response: None.

SLS1408I User SCRATCH subpool definition from CCCCCC complete

Explanation: User SCRATCH subpool definition, using CCCCCC as the source, is complete.

CCCCCC = "PARMLIB" - Source for User SCRATCH subpool definition is the "SLSSYS00" DD card; = "UEXIT03" - Source for User SCRATCH subpool definition is User EXIT 03.

System Action: None. This message is normally preceded by messages SLS1407I and SLS1969I.

User Response: None

SLS1409I Subpool XXXXXX has duplicate volser range *volser-volser* - range ignored

Explanation: The definition for subpool XXXXXX has a duplicate volser range.

System Action: The subpool definition continues without the duplicate volser range.

User Response: Ensure that the User Exit 03 or SCRPOOL definition for subpool XXXXXX has no duplicate volser ranges.

SLS1410I VCAM cleaner error detected for LSM AA:LL

Explanation: The record in the HSC Control Data Set (CDS) which tracks cleaner cartridges for LSM AA:LL has an error. The low cartridge serial is greater than the high cartridge serial. The HSC will not use this LSM for cleaner cartridge selection.

System Action: A dump is taken for diagnostic purposes. If cleaning cartridges are available in adjacent LSMs, they may be selected for this cleaning request.

User Response: Ejecting and entering cleaning cartridges in this LSM may correct this error. An HSC RECONFIG will rebuild the cleaning cartridge information.

SLS1411I - SLS1500I

SLS1411I SCRPFDEF cmd(s) disabled by PARMLIB SCRPOOL(s) or USER EXIT03

Explanation:

1. SCRPFDEF command has been disabled during HSC STARTUP by the presence of SCRPOOL command(s) or USER EXIT03 processing as documented in the SYSTEM PROGRAMMER'S GUIDE.
2. The SLS1411I message is issued at the time HSC STARTUP processing disables the SCRPFDEF command.
3. This message is also issued if SCRPFDEF command(s) are requested after the SCRPFDEF command has been disabled.

System Action: SCRPFDEF cmds(s) will be bypassed.

User Response:

1. If the SCRPFDEF commands ARE NEEDED correct the HSC PARMLIB and HSC startup processing as appropriate:
 - Remove the SCRPOOL cmd(s),
 - Remove the USER EXIT03 processing.
2. If the SCRPFDEF commands are NOT NEEDED there is no corrective action needed.

SLS1450I CAP cannot be released. LSM AA:LL is not available

Explanation: A request to release the CAP on LSM AA:LL could not be honored because the HSC could not communicate with the LSM.

System Action: The CAP will not be released by the HSC.

User Response: Examine the console log for other HSC messages which might indicate LMU errors or hardware errors. It is likely that the LSM is in an inactive or not-ready status. Correct any hardware errors which are found before attempting to release the CAP again.

SLS1500I Error copying primary data base to secondary and/or standby data base

Explanation: The secondary and/or standby control data set may be invalid.

System Action: The reconfiguration stops processing.

User Response: The installation may use a utility such as IEBGENER to copy the primary control data set to the secondary and/or standby control data set.

SLS1501I *SYNAD Error Message text*

Explanation: During the copy of the primary control data set to the secondary and/or standby control data set at the end of reconfiguration processing, the SYNAD error routine gained control. The message text is the text provided by SYNAD processing.

System Action: The reconfiguration stops processing.

User Response: After determining the cause of the error, the installation may use a utility such as IEBGENER to copy the primary control data set to the secondary and/or standby control data set.

SLS1502I SMF subparameter CCCCCCCC; subtypes 1-6 being recorded

Explanation: The SUBPARM parameter for this subsystem was NOT SPECIFIED or was INVALID.

System Action: The subsystem defaults to recording subtypes 1-6.

User Response: If the installation wishes to change the subtypes being recorded, a SET SMF or SETSMF command may be entered specifying “SUBPARM(ssnx(SUBTYPE(a,b,c...)))”.

SLS1503E Could not establish ESTAE (rc XX); User exit 7 not invoked

Explanation: Prior to invoking user exit 7, an attempt was made to establish a recovery routine. This failed with return code XX.

System Action: User exit 7 is not invoked. The system continues with initialization or termination.

User Response: Determine why the ESTAE could not be invoked, and correct the problem.

SLS1504I Initialization control statement CCCCCCCC is invalid, default values used

Explanation: The initialization control statement identified by CCCCCCCC is coded with an invalid syntax.

System Action: The HSC subsystem continues to initialize using default values of the parameters for that statement unless the statement is **CDS** or **JOURNAL**. Errors in one of these control statements will cause the HSC subsystem to not initialize.

User Response: Correct the invalid control statement, and restart the HSC subsystem when appropriate.

SLS1505I - SLS1508I

SLS1505I HSC service level {BASE|FULL|JES3} initialization complete

Explanation: The HSC initialization process has completed for the indicated service level.

This message appears when initialization for the base or full service levels or the JES3 subsystem is completed.

System Action: None.

User Response: None.

SLS1506I HSC service level {BASE|FULL|JES3} termination in progress

Explanation: The HSC has begun termination of the indicated service level. This message appears when termination for the base or full service levels or the JES3 subsystem has begun.

System Action: None.

User Response: None.

SLS1507I Command starting at line *NN* has excessive length

Explanation: The HSC was reading commands from the parameter data set when it encountered a command with an excessive length. For operator commands, this limit is 126. For other commands, this limit is 32767.

System Action: Processing continues. The command in error is ignored.

User Response: Ensure the parameter data set has correct syntax.

SLS1508I Unknown command *CCCCCCC* at line *NN*

Explanation: The HSC was reading commands from the parameter data set when it encountered an undefined command.

System Action: Processing continues. The command in error is ignored.

User Response: Ensure the parameter data set has correct syntax.

SLS1509I I/O error *CCCCCCCC*

Explanation: An I/O error occurred. *CCCCCCCC* is a message describing the error. For MVS, this is information from the SYNADAF message buffer. For VM, this includes the jobname, unit address, DD name, a hex dump of the DECB ECB, and the relative block number.

System Action: The remainder of the parameter data set is ignored. Statements successfully read before the error will be processed. The system continues with initialization, if possible. This will not be possible if the CDS or JOURNAL statements were missed.

User Response: Operator commands may be issued for many statements that were missed in the parameter data set. For the CDS or JOURNAL statements, correct the error and restart the HSC.

SLS1510I Comment not terminated near line *NN*

Explanation: While processing the parameter data set, a comment (initiated by a */**) was not terminated by a **/*. This occurred near line *NN*.

System Action: The remainder of the command after */** is ignored. Commands after the one in error will be processed. However, further errors may occur.

User Response: Put a closing comment indicator (**/*) in the parameter data set.

SLS1511I *CCCCCCCCCCCCCCCCCCCC*

Explanation: The HSC is sending the information from the parameter data set to the hardcopy log for documentation purposes.

System Action: Processing continues.

User Response: None.

SLS1512I Error occurred processing *CCC...CCC*

Explanation: An error occurred processing the parameter data set (*CCC...CCC*).

System Action: The remainder of the parameter data set is ignored. Statements successfully read before the error will be processed. The system continues with initialization, if possible. This will not be possible if the CDS or JOURNAL statements were missed.

User Response: Operator commands may be issued for many statements that were missed in the parameter data set. For the CDS or JOURNAL statements, correct the error and restart the HSC.

SLS1513I - SLS1517A

SLS1513I HSC service level {BASE|FULL} termination complete

Explanation: The HSC has terminated the indicated service level. The termination is normal if initiated by operator command. The termination is abnormal if it is initiated by the HSC itself due to a software failure which could not be recovered.

System Action: None.

User Response: None.

SLS1515I MVS 4.1.0 services are not present

Explanation: An attempt was made to initialize the MVS 4.1.0 version of the HSC on an MVS that does not support the necessary services (CVTH4410 is not on).

System Action: The HSC does not initialize.

User Response: Initialize the correct version of the HSC.

SLS1516I HSC Version CCCCCCCC

Explanation: The version of the HSC being initialized is displayed in CCCCCCCC.

System Action: Processing continues.

User Response: None.

SLS1517A The HSC task name does not match a subsystem name or the SSYS keyword was not provided

Explanation: During initialization a subsystem name must match either the startup procedure name or the PARM="SSYS(CCCC)" definition in the startup procedure. CCCC is a one to four character subsystem name.

If the SSYS parameter is specified, the HSC uses the SSYS parameter value to search for a subsystem name that matches the value. If the SSYS parameter is not specified, the HSC uses the startup procedure name (started task name) for the search.

In MVS, the subsystem name is defined in IEFSSNxx. In VM, the startup procedure is the HSC startup SLKJCL file. The LIBSUBSYS parameter value in the system profile (SYSPROF) must match the jobname in the HSC startup SLKJCL file, or the SSYS parameter value must match the LIBSUBSYS parameter value.

System Action: The HSC terminates.

User Response: Supply the correct subsystem name or job name, and restart the HSC.

SLS1518I Pre-initialization complete

Explanation: The HSC startup procedure invoked using the INIT parameter has completed.

System Action: The INIT parameter sets the subsystem up to use the Job Entry Subsystem (JES) services.

User Response: None.

SLS1519I PARMLIB command *CCCCCCCC* at line *NW* is not supported in this environment - ignored

Explanation: The HSC was reading commands from the parameter data set when it encountered a command that is not supported in this environment (MVS or VM).

System Action: Processing continues. The command is ignored.

User Response: None.

SLS1600I Current HSC host-to-host communications parameters summary:

	Hostid	Method	MethLim	VTAMname	LMUpath
[>>]	<i>host1</i>	<i>meth1</i>	<i>methlim1</i>	[<i>name1</i>]	[<i>acsid1</i>]
	<i>host2</i>	<i>meth2</i>	<i>methlim2</i>	[<i>name2</i>]	[<i>acsid2</i>]

	<i>hostn</i>	<i>methn</i>	<i>methlimn</i>	[<i>namen</i>]	[<i>acsidn</i>]

Explanation: A list is displayed of defined HSC HOSTid(s) with corresponding current method and method limit. “>>” is displayed to indicate the parameters are for the executing host. If defined, the VTAMpath name is displayed. If the current method is LMU, the active LMUpath ACSid is displayed.

System Action: None.

User Response: None.

SLS1601I - SLS1603I

SLS1601I Current HSC host-to-host communications parameters detail:

```
[>>]Hostid=hostid1
      Method=meth
      Method limit=methlim
      [VTAMname=name]
      [Active LMU path=acsid]
      [LMU path(s) defined:
        acsid1  acsid2   acsid3   acsid4
        acsid5  acsid6   acsid7   acsid8
        .       .         .         .
        .       .         .         .
        .       .         .         acsidn ]
```

Explanation: The current settings for the defined HSC HOSTid(s) are displayed. “>>” is displayed to indicate the parameters are for the executing host. If defined, the VTAMpath name is displayed. If LMUpath ACSids have been defined and the current method is LMU, the active LMUpath ACSid is displayed. If LMUpath ACSids have been defined, a list is displayed of ACSids in the order to be searched.

System Action: None.

User Response: None.

SLS1602I Method *CCCC* invalid; no *CCCCpath* defined

Explanation: The communications method specified does not have corresponding paths defined.

System Action: The command is rejected.

User Response: Re-enter the command specifying a method having path(s) previously defined or specifying the needed path(s).

SLS1603I Cannot delete all *CCCCpath* definitions while current method is *CCCC*

Explanation: It is invalid to delete all path definitions for the currently active communications method.

System Action: The command is rejected.

User Response: Re-enter the command specifying **inactive** path definitions for the current communications method, or first enter a command specifying a new communications method.

- SLS1604I** Cannot {delete|modify} active *CCCCpath* definition
- Explanation:** It is invalid to delete or modify a path definition which is currently active.
- System Action:** The command is rejected.
- User Response:** Deactivate or change the path or change the communications method. Then re-enter the command.
- SLS1605I** No matching *CCCCpath* definition to delete
- Explanation:** A path definition specified with the DEL parameter is not currently defined.
- System Action:** The command is rejected.
- User Response:** Re-enter the command with the correct path definition(s) desired.
- SLS1606I** Too many *CCCCpath* definitions specified
- Explanation:** The number of path definitions has exceeded the maximum number of definitions allowed.
- System Action:** The command is rejected.
- User Response:** Delete obsolete or unwanted definitions; then re-enter the command with the correct path definition(s) desired.
- SLS1607I** MONITOR STATUS:
- CCCCCCCC1 - CCCCCCCC2*
- Explanation:** This message is issued in response to the Display MONitor command. *CCCCCCCC1* defines the console. *CCCCCCCC2* specifies the type of monitoring in effect.
- System Action:** None.
- User Response:** None.
- SLS1608I** Undefined *CCCCCCCC* specified: *XXXXXXXX*
- Explanation:** A parameter value (*CCCCCCCC*) has not been previously defined. *XXXXXXXX* identifies what was specified.
- System Action:** The command is rejected.
- User Response:** Re-enter the command with the correct parameter.

SLS1609I - SLS1614I

SLS1609I No valid parameters specified for *CCCCCCCC* command

Explanation: An attempt was made to enter the *CCCCCCCC* command, but the command was entered without any valid parameters. Previous messages will describe the errors.

System Action: The command is rejected.

User Response: Re-enter the command with the valid parameters.

SLS1610I Method *CCCC* is higher than limit defined for host *CCCCCCCC*

Explanation: The COMMPATH command specified a communications method that was either higher or lower than the communications method specified by another active host. For example, if host A specified METHOD(CDS) and host B specified METHOD(LMU), then host A would be identified in the message.

System Action: The communication method used between the two hosts will be the highest common level specified between the two hosts. For example, if host A specified METHOD(CDS) and host B specified METHOD(LMU), the two hosts will communicate via the CDS.

User Response: If the communication level is acceptable, do nothing. Otherwise, on the host specified in the message, re-issue the COMMPATH command with the METHOD parameter set to the desired level of communication.

SLS1611I Invalid RETRY function - *CCCCCCCC*

Explanation: An invalid function (*CCCCCCCC*) was specified on the RETry command.

System Action: RETry command processing terminates.

User Response: Refer to the *HSC Operator's Guide*, or issue the HSC Display CMd RETry command to determine the RETry functions that are currently supported.

SLS1613I Data set *CCCCCI* {ENABLED|DISABLED}

Explanation: *CCCCCI* is a data set name. A CD's Enable or Disable command was issued and completed.

System Action: The HSC resumes normal activity.

User Response: None.

SLS1614I Auto Enable {ENABLED|DISABLED}

Explanation: Auto Enable was issued and is either enabled or disabled.

System Action: The HSC resumes normal activity.

User Response: None.

SLS1615I Journal {ABEND|Continue} option enabled

Explanation: The Journal FULL=Abend or Continue command was issued and successfully completed.

System Action: The HSC resumes normal activity.

User Response: None.

SLS1616I Disable request rejected; last active CDS cannot be disabled

Explanation: A disable request was made against the last active CDS.

System Action: The request fails. The system does not allow the action. The HSC must have at least one copy of the CDS active, or it comes down.

User Response: Issue the HSC Display CDS operator command to verify the condition of all copies of the CDS.

SLS1617E Request failed; data set CCCCCC1 not known to this host

Explanation: CCCCCC1 is a data set name. A CDs Disable request was issued and the data set entered was not known to this host.

System Action: The HSC resumes normal activity.

User Response: Only those data sets currently known to the HSC may be disabled. Use the Display CDS command to list the current CDS definitions and then reissue the CDs Disable command.

SLS1619I {ENABLE|DISABLE|EXPAND} request failed

Explanation: An error occurred while processing a CDs Enable, Disable, or EXpand request.

System Action: The HSC resumes normal activity.

User Response: Check other HSC error messages associated with the request.

SLS1620I - SLS1622I

SLS1620I Enable request validation for data set *CCCCC1* failed; *CCCCC2*

Explanation: *CCCCC1* is the data set name. *CCCCC2* will be one of the following:

- Allocation failed
- Deallocation failed
- Data set must be allocated
- Open failed
- Close failed
- Read failed
- Not a valid CDS
- Data set is in error
- Invalid flag

In response to Enable *CCCCC1*, the system attempts to validate the supplied data set name by allocating, opening, reading, and verifying the data set. The system then attempts to close and deallocate the data set. If these tests are successful, the CDS is enabled and/or a switch is performed. Otherwise, this message is issued to indicate what test failed.

System Action: The HSC resumes normal operation.

User Response: Call StorageTek Software Support if the CDS error and its resolution cannot be determined from preceding MVS or HSC console messages.

SLS1621I To enable a new CDS data set, only one CDS copy can be inactive;currently multiple copies inactive

Explanation: An attempt to activate a new CDS data set with a CDs Enable command has failed because more than one copy of the CDS is currently inactive.

System Action: The HSC continues operation with the current CDS definitions.

User Response: Use the Display CDS command to display the current CDS data set definitions. Use the CDs Enable command to activate one of the known CDS copies, then reissue the original CDs Enable command to activate the new CDS data set.

SLS1622I Down-level host *CCC1* found active during attempt to *CCCCCCC2*

Explanation: An attempt to issue a CDs command with an HSC 5.0 feature has detected a down-level HSC system active on host *CCC1*. *CCCCCCC2* is one of the the following HSC 5.0 features:

Enable new CDS data set
Expand CDS

System Action: The HSC continues operation with the current CDS definitions.

User Response: Stop the down-level HSC on host *CCC1* (and any other down-level HSCs on other hosts) and reissue the CDs command.

SLS1623I CDS *CCCC...CCCC* inactive; all CDS copies must be enabled to expand CDS

Explanation: An attempt to expand the CDS with a CDs EXpand command detected that a copy of the CDS, data set *CCCC...CCCC*, was inactive. To expand the CDS, all CDS copies must be active (enabled).

System Action: The HSC continues operation with the current CDS definitions.

User Response: Use the CDs Enable command to make CDS *CCCC...CCCC* active. Then reissue the CDs EXpand command.

SLS1624I Attempt to *CCCCCCCC* failed; could not read DHB

Explanation: An attempt to perform an HSC 5.0 feature with the CDs command has failed while reading the active CDS DHB record. *CCCCCCCC* is one of the the following HSC 5.0 features:

Enable new CDS data set
Expand CDS

System Action: The HSC continues operation with the current CDS definitions.

User Response: Call StorageTek Software Support if the CDS read error and its resolution cannot be determined from previous IBM or HSC console messages.

SLS1625I *CCCC..CCC1* obsolete; use *CCCC..CCC2*

Explanation: The requested function *CCCC..CCC1* is no longer supported. Use the specified alternative *CCCC..CCC2*. Below are a list of requested functions with the specified alternatives:

LOad SLSDDQR Display CDS
LOad SLSLDQR Display Requests
LOad SLSMDQR Display DRives

System Action: None.

User Response: None.

SLS1626I - SLS1626I

SLS1626I *CCCCCCCC* Parms installed from data set *DDDDDDDD*

Explanation:

CCCCCCCC = Type of parameters being installed
(LMUPDEF, MGMTDEF, TREQDEF, SCRDEF,
UNITDEF, VOLDEF, MVCDEF, LKEYDEF)
DDDDDDDD = data set name

In response to a LMUPDEF, MGMTDEF, TREQDEF, UNITDEF, SCRDEF, LKEYDEF, VOLDEF, or MVCDEF command, the HSC has successfully loaded the parameter statements contained in the named data set. The parameters are in use by the HSC as soon as this message is issued.

System Action: The HSC resumes normal operation.

User Response: None.

SLS1627I *CCCCCCCC*Parms not installed, Reason code *XXXX*

Explanation: In response to a LMUPDEF, MGMTDEF, TREQDEF, UNITDEF, VOLDEF, SCRPFDEF, LKEYDEF, or MVCDEF command, the HSC did not successfully load the parameter statements contained in the named data set.

CCCCCCCC = Type of parameters being installed
 (LMUPDEF, MGMTDEF, TREQDEF, SCRPFDEF,
 UNITDEF, VOLDEF, MVCDEF, LKEYDEF)
XXXX = Hexadecimal reason code

The following reason codes and definitions indicate why the parameters were not loaded:

- 0008 - A syntax error occurred on at least one statement
- 0009 - An inconsistency was found between two statements
- 000A - An unsupported parameter was specified on a JES3 system
- 000B - Supplied information is invalid.
- 000C - An I/O error occurred reading the data set
- 0010 - The HSC was not able to allocate the data set
- 0014 - The HSC was not able to open the data set
- 0018 - Sufficient memory was not available to process the data set
- 001C - Excessive number of errors

In each case, this message will be preceded by message SLS1628I or SLS0002I giving details of the error(s) encountered.

System Action: The HSC resumes normal operation.

User Response: Correct the problem with the parameter data set, and retry the command.

SLS1628I - SLS1628I

SLS1628I *CCCCCCCC: Record DDDDDDDD ... EEEE*

Explanation: While processing a LMUPDEF, MGMTDEF, TREQDEF, UNITDEF, VOLDEF, MVCDEF, LKEYDEF, SLSMERGE, OR SCRPDEF command or control statement, the HSC has encountered an error.

CCCCCCCC= Type of command or control statement (LMUPDEF, MGMTDEF, TREQDEF, VOLDEF, UNITDEF, MVCDEF, LKEYDEF, SLSMERGE, SCRPDEF)

DDDDDDDD = Decimal number of the record within the file

EEEE= System-generated number used for identifying the following line of this multiple-line message

The record number identifies the statement in error. A record number of zero (0) indicates a problem with the data set or an error involving more than one record.

This message is a two line message; the second line indicates the nature of the error. Second-line text will be one of the following:

- ACS - unknown ACSid
The ACSid specified with the ACS keyword is unknown to HSC.
- ACSlist - duplicate ACSids
The list of ACSids specified with the ACSlist keyword contains duplicate values.
- ACSlist - maximum number of ACSids exceeded
The number of ACSids specified with the ACSlist keyword exceeds the maximum number allowed.
- ACSlist - unknown ACSid
One or more of the ACSids specified with the ACSlist keyword is unknown to HSC.
- ARCHAge - Must be between 1 and 999 days
The ARCHAge parameter value exceeds these limits.
- ARCHPol - Number of STORclas names exceeds maximum
Depending upon the CDS level for VTCS, the number of storage class names is either limited to 2 or 4.
- ARCHPol - STORclas name is invalid
The storage class name does not start with an alphabetic character.

- *CCCCCC* value out of range; must be *D-DDD*

The value specified for an MVCPOOL parameter was not within the accepted range.

CCCCCC = MVCFREE, MAXMVC, THRESH, or START parameter
D-DDD = acceptable range for parameter value

- Comment unclosed at end of file
- CONSRC - invalid specification

The storage class name does not start with an alphabetic character.

- CONSRC - MIGpol does not specify > 1 STORclas name

The MIGpol parameter is also required and must contain more than two unique names.

- CONSRC - No matching STORclas name on MIGpol parameter

The storage class name specified must match to one of the names upon the MIGpol parameter.

- CONSRC - VSM(ADVMMGMT) FEATures not active
- CONTGT - invalid specification

The storage class name does not start with an alphabetic character.

- CONTGT - VSM(ADVMMGMT) FEATures not active
- DELSCR - invalid specification

The value specified with the DELSCR keyword was not NO or YES.

- Drives specified in list or range are not the same type of device
- DUPlex - invalid specification

The value specified with the DUPlex keyword was not YES or NO.

- Duplicate UNITATTR ADDRESS value encountered
- Error allocating dataset; Code *XXXX-XXXX*

XXXX-XXXX = DYNALLOC error and reason codes

- Error opening dataset; Completion code *XXX-XX*

XXX-XX = OPEN completion code and reason code

- Error near column *NNN:TTTTTTTT*

NNN = column number where error was detected
TTTTTTTT = error text

- Error on *CCCCCCCC* {parameter|list|range}: *TTTTTTTT*

CCCCCCCC= parameter, list, or range that is in error

TTTTTTTT= error text (listed below)

Possible error text (*TTTTTTTT*) for the above two second-line messages includes:

- Cleaning Media invalid as media value
 - Co-requisite parameter missing
 - Invalid length of value
 - Invalid value
 - Mandatory parameter missing
 - Mutually exclusive parameters found
 - Positional error
 - Required value not found
 - Syntax error
 - Unknown keyword
 - Value supplied when none allowed
- File processing terminated due to excessive number of errors
 - FUNCTION - Unrecognized value
 - I/O error reading dataset:*CCCCCCCC*
CCCCCCCC = SYNADAF produced error message
 - IMMEDmig - invalid specification
The value specified with the IMMEDmig keyword was not NO, KEEP, or DELETE.
 - Insufficient memory
 - LKEYINFO: Supplied information is invalid
The information supplied on the LKEYINFO statement is invalid.
 - LMUADDR IP address syntax is invalid; *CCCCCCCC*
An LMUADDR parameter contained only digits and periods but was not a valid IP address format (4 sets of one to three numeric digits separated by periods, with each numeric value less than 256).
 - LMUADDR list contains more than maximum allowed items
A maximum of four (4) hostnames or IP addresses may be specified for a single LMUADDR keyword.
 - LMUPATH duplicate ACS ID found
An ACS ID has been encountered that was specified on a previous LMUPATH statement.

- LMUPATH Invalid ACS ID found

The ACS ID specified has not been defined to HSC.

- LMUPDEF: DOES NOT CONTAIN ANY LMUPATH STATEMENTS

This text will be issued if while reading the LMUPDEF file a LMUPATH statement cannot be found on any line. If a LMUPATH statement is in the file then the previous comment statement should be reviewed. The comment must be within a comment block, which starts with a slash asterisk and ends with a asterisk slash, and columns 73 - 80 are ignored.

- MAXCLEAN incompatible with implied/default MEDIA

The MEDIA keyword was not specified, and the implied or default media type is not STD, DD3D, STK1U, or STK2W (the only media types compatible with MAXclean). Either remove the MAXclean keyword or specify a MEDIA keyword with a compatible media value.

- MAXCLEAN incompatible with MEDIA(XXXXXXXX)

XXXXXXXX is the value specified for the MEDIA keyword. STD, DD3D, STK1U, and STK2W (or one of their synonyms or abbreviations) are the only media values compatible with MAXclean.

- MAXCLEAN valid only for Cleaning Cartridge Volsers (XXXXXX)

XXXXXX represents the format of a Cleaning Cartridge Volser composed of the HSC Cleaner Prefix followed by .xxx.

- MAXCLEAN value not within allowable range

The MAXclean keyword was specified, but the value is not within the allowable range of 1-32767

- MAXVtvsz exceeds that supported by CDS - Defaulted

The value specified in the MAXVtvsz parameter exceeds that which is supported by the level of CDS. The parameter value will default to the highest value supported by the CDS level.

- MAXVtvsz - invalid specification

The value specified with the MAXVtvsz keyword was not 400, 800, 2000 or 4000.

- MEDIA - cleaner cartridge media invalid

Cleaner cartridge media types are invalid on the STORclas statement.

- MEDIA - duplicate types in list

Duplicate media types were found on the STORclas statement.

- MEDIA - too many types in list

The number of media types cannot exceed 20 on the STORclas statement.

- MGMTCLAS is not valid with this FUNCTION
- MIGpol - Number of STORclas names exceeds maximum

Depending upon the CDS level for VTCS, the number of storage class names is either limited to 2 or 4.

- MIGpol - STORclas name is invalid

The storage class name does not start with an alphabetic character.

- MIGpol - VSM(ADVMMGMT) FEATures not active
- MVCPOOL Names ALL and DEFAULTPOOL not allowed
- MVCPOOL values conflict with those on Record *DDDDDDDD*

An MVCPOOL statement has a different MVCFREE, MAXMVC, THRESH, or START value than that on a previous MVCPOOL statement with the same name.

DDDDDDDD = record number of previous MVCPOOL statement

- MVCPOOL/STORCLAS not valid with FUNCTION(SPECIFIC)
- MVCPOOL/STORCLAS/PREVVTTSS not valid with FUNCTION(SCRATCH)
- NAME - invalid specification

The value specified with the NAME keyword exceeds 8 characters or contains invalid characters. The value specified for NAME must begin with A-Z and can contain only A-Z, 0-9, and \$, #, @.

- Parameter unsupported on JES3
- REPlicat - invalid specification

The value specified with the REPlicat keyword was not NO or YES.

- REPlicat(YES) - VSM(ADVMMGMT) FEATures not active
- RESTIME - invalid specification

The RESTIME must have a value between 1 and 9999.

- RESTIME - Mutually exclusive with IMMEDMIG(DELETE)

You cannot specify that a VTV should be retained resident within the VTSS and also migrated and deleted immediately.

- RESTIME - VSM(ADVMMGMT) FEATures not active

- Statement is too long
- STORclas - Migrate option invalid specification

The value specified for the MIGRATE parameter is invalid.

- STORclas - VSM(ADVMMGMT) FEATures not active
- Text indicating that unit, model, media type and rectech are invalid or incompatible
- Unrecognized statement
- Volser specification conflicts with that on Record *DDDDDDDD*

The Volser specification on an MVCPOOL statement overlaps with the Volsers defined on a previous MVCPOOL statement having a different name.

DDDDDDDD = record number of previous MVCPOOL statement

- VTSSSEL - VSM(ADVMMGMT) FEATures not ACTIVE
- VTPPAGE - invalid specification

The value specified with the VTPPage keyword was not STANDARD or LARGE.

- VTPPAGE value not supported by CDS - Ignored

The parameter value of LARGE is not supported by the level of CDS. The request is ignored and the value of STANDARD is assumed.

- VTPPAGE(STANDARD) is invalid with MAXVtvsz > 800 - defaulting to LARGE

The parameter value of STANDARD is not valid with MAXVtvsz > 800. The request is ignored and the value of LARGE is used.

- Wild card(s) not allowed in MVCPOOL

Wild card(s) are not permitted in Volser specifications on an MVCPOOL statement.

See message SLS1973I in the *HSC Messages and Codes Manual* for a description of any text not listed here.

System Action: The HSC continues to process the dataset unless the record number displayed is zero, or unless there have been 50 errors encountered in the file. For those two cases, processing of the dataset is terminated.

User Response: Correct the problem with the parameter dataset and re-issue the command.

SLS1629I - SLS1630I

SLS1629I CCCCCCCC: DDDDDDDD does not contain any stmts to process

Explanation:

CCCCCCCC = Type of parameters being installed
(LMUPDEF, MGMTDEF, TREQDEF, SCRPFDEF,
LKEYDEF, VOLDEF, UNITDEF)

DDDDDDDD = data set name

In response to a LMUPDEF, MGMTDEF, TREQDEF, UNITDEF, SCRPFDEF, LKEYDEF, or VOLDEF command, the HSC has not found any statements of the appropriate type in the named data set. The appropriate statements by command are:

- LMUPDEF - LMUPATH
- MGMTDEF - MGMTCLAS
- TREQDEF - TAPEREQ
- VOLDEF - VOLATTR
- UNITDEF - UNITATTR
- SCRPFDEF - SCRPOOL
- LKEYDEF - LKEYINFO

System Action: The HSC resumes normal operation.

User Response: Correct the problem with the parameter data set, and retry the command.

SLS1630I CCCCCCCC parameters are not loaded

Explanation:

CCCCCCCC = Type of parameters being displayed (LMUPDEF, MGMTDEF, SCRPFDEF, TREQDEF, VOLDEF, UNITDEF, LKEYINFO)

In response to a Display LMUPDEF, Display MGMTDEF, Display SCRPFDEF, Display TREQDEF, Display UNITDEF, Display LKEYDEF, or Display VOLDEF command, the HSC has found that no parameters of that type have been loaded.

System Action: The HSC resumes normal operation.

User Response: None.

SLS1631I CCCCCCCC parameter status:

Explanation:

CCCCCCCC = Type of parameters being displayed
(LMUPDEF, MGMTDEF, TREQDEF, LKEYDEF,
SCRPDEF, VOLDEF, UNITDEF)

In response to a Display MGMTDEF, Display TREQDEF, Display UNITDEF, Display LMUPDEF, Display LKEYDEF, Display SCRPFDEF, or Display VOLDEF command, the HSC displays information about the requested parameters. This message is the first of a three or four line display. The other lines displayed are:

- LOADED FROM DDDDDDDD

Displays the data set (including member name, if appropriate) from which the parameters were loaded.

- TITLE : CCCCCCCC

Displays the title (from an OPTIONS statement) which was in the data set from which the parameters were loaded. If the parameters did not contain a TITLE, this line of the display is omitted.

- LOADED ON YYYY-MM-DD AT HH:MM:SS

Displays the date and time the parameters were loaded by the HSC.

System Action: The HSC resumes normal operation.

User Response: None.

SLS1632I MODIFY command cancelled - a non-610 HOST active.

Explanation: MODIFY CONFIG was entered, but one or more HOST(s) is at a level lower than HSC610.

System Action: None.

User Response: Bring the non-610 HOST down and enter the MODIFY CONFIG command again.

SLS1633I SCRPFDEF parameters not installed from DDDDDDDD

Explanation: In response to a SCRPFDEF command, the HSC has either found no SCRPOOL statements or at least one invalid SCRPOOL statement in the data set named DDDDDDDD.

System Action: The HSC does not replace the previous HSC scratch subpool settings.

User Response: Correct the problem with the parameter data set and retry the command.

SLS1634I - SLS1637I

SLS1634I MODIFY command is cancelled - VTCS DR Test is active.

Explanation: A MODIFY CONFIG command entered with a VTCS DR Test active. The command is not executed.

System Action: None.

User Response: Wait until the VTCS DR Test completes before reentering the command.

SLS1635D To allow RESET to proceed; Reply Y to continue or N to cancel.

Explanation: Before a CONFIG RESET is allowed to continue, the Operator is asked to reply to a message to make sure the command wasn't entered accidentally.

System Action: None.

User Response: Respond Y to allow RESET to continue, otherwise reply N to cancel the RESET option.

SLS1636D To DELETE the ACS; Reply Y to continue or N to cancel.

Explanation: Before an ACS can be deleted the Operator must reply to this message to make sure the command was not entered accidentally.

System Action: None.

User Response: Respond Y to allow DELETE ACS to continue, otherwise reply N to cancel.

SLS1637I Verify the ACS is CCCCCCCC for the CCCCCCCC ACS command.

Explanation: Verify the ACS is active (connected) for the UPDATE command and offline (disconnected) for the DELETE command.

System Action: The F CONFIG UPDATE/DELETE ACSid command is rejected.

User Response: Re-enter the command after the ACS is in the correct state.

SLS1650E ACS AA: Dual LMU {is|is not} configured; Master Is y, Standby is not ready

Explanation: The standby LMU is not ready. This may be a temporary condition due to an operator-induced switchover action.

y will be the master LMU ID "A" or "B", but could be "0" due to an LMU error.

System Action: Processing continues using the master LMU.

User Response: If the standby LMU is not ready due to an operator-initiated switchover action, then no response is necessary.

If the standby LMU is not ready due to an apparent failure, then report this incident to StorageTek Hardware Support.

SLS1651I ACS AA: Dual LMU is configured; Master is y, Standby is ready

Explanation: This message indicates which LMU is the master LMU and the status of the standby LMU. Even though the standby LMU is ready, at least one station must have a STANDBY status for a fully automated switchover to occur.

AA is the ACSid number

y will be the Master LMU ID "A" or "B", but could be "0" due to an LMU error.

System Action: Processing continues with the master LMU.

User Response: None.

SLS1652I ACS AA: Switch aborted, C...C not standby station

Explanation: Station C...C was a standby station when the SWitch command was issued, but it is no longer a standby station. Presumably an automatic switchover has occurred.

System Action: SWitch command processing is terminated.

User Response: If SLS1650E or SLS1651I have been issued, then no response is necessary. If a hardware error is suspected, report this incident to StorageTek Hardware Support.

SLS1653D - SLS1656E

SLS1653D ACS AA: *NN* {CAP|CAPs} active; confirm switch to standby LMU (Y/N)

Explanation: This message indicates the number of CAPs that are active in the ACS and allows the operator to terminate the switchover process.

NN is the number of CAPs active in the ACS.

System Action: The HSC waits for an answer before either proceeding with the switchover (Y) or terminating SWitch command processing (N).

User Response: Make sure all CAP doors are closed securely prior to responding Y to this message, or else reply N to abort the switchover.

SLS1654I ACS AA: Switch terminated due to operator response

Explanation: This message confirms that switch processing was cancelled due to operator response.

System Action: SWitch command processing terminates.

User Response: None.

SLS1655I ACS AA, Station C...C: Switch uncertain, standby LMU *CCCCCC* error

Explanation: The HSC sent the SWitch command to the standby LMU but did not get a validated response due to the error that occurred.

CCCCCC will be one of the following errors:

TIMEOUT, ACK-1, ACK-2, RESPONSE, READ-1, READ-2, NOISE, or EDIT-1

System Action: The switchover may or may not occur.

User Response: Wait 1 minute. If message SLS1650E or SLS1651I is not issued, enter the SWitch command again. Report this error to StorageTek Hardware Support.

SLS1656E ACS AA: Switch initiated, expect notification in 20 seconds

Explanation: The SWitch command has been accepted by the master LMU.

System Action: The master LMU should reIPL, and the standby LMU should take over as the master LMU.

User Response: If SLS1650E or SLS1651I is issued in 20 seconds, no response is necessary. If SLS1650E or SLS1651I is not issued, a problem exists. Try the SWitch command again. If the command fails, the switch may be generated by manually reIPLing the master LMU. Report failures to StorageTek Hardware Support.

SLS1657I ACS AA: Switch rejected, CCC...CCC

Explanation: The standby LMU tried to tell the master LMU to reIPL, but an error caused the communication to be unsuccessful.

CCC...CCC will be one of the following reasons:

- Not “Dual LMU”
- Not standby Station
- LAN link down
- NAK from Master LMU
- SWITCH already active
- Master did not respond
- Unknown error

System Action: SWitch command processing is terminated.

User Response: If SLS1650E or SLS1651I have been issued, no response is necessary. Otherwise, try the SWitch command again, and report the failure to StorageTek Hardware Support. The switch may be generated by manually IPLing the master LMU.

SLS1658E ACS AA: CCCCCC station C...C connected to LMU y as ZZZZZZ

Explanation: Logical inconsistency detected:

CCCCCC	station is either online or standby depending on connecting LMU status
C...C	is the station address.
y	is the LMU ID, “A” or “B”
ZZZZZZ	is the LMU status, master or standby

System Action: HSC attempts to continue.

User Response: Verify that the stations are connected to the correct ACS, then vary the ACS offline and then back online. If problem persists, notify StorageTek Hardware Support.

SLS1659E - SLS1661I

SLS1659E ACS AA: CCCCCC station C...C MMM...MMM

Explanation: Logical inconsistency detected:

CCCCCC station is either online or standby depending on the connecting LMU status C...C is the station address. MMM...MMM will be one of the following:

- not a Dual LMU station
- invalid Dual LMU ident

System Action: HSC attempts to continue.

User Response: Verify that the stations are connected to the correct ACS, then vary the ACS offline and then back online. If problem persists, notify StorageTek Hardware Support.

SLS1660E ACS AA: Master LMU W level XX, Standby LMU Y level ZZ

Explanation: LMU microcode inconsistency detected.

Master and Standby LMUs have different microcode.

W	is the Master LMU ID, "A" or "B"
XX	is the Master LMU compatibility level
Y	is the Standby LMU ID, "A" or "B"
ZZ	is the Standby LMU compatibility level

System Action: HSC will continue.

User Response: Report this to StorageTek Hardware Support. Install the same LMU microcode level in both LMUs of the dual LMU configuration. The HSC can run with different compatibility levels on the two LMUs, but this is not the recommended procedure and should be corrected. Varying all standby LMU stations offline will stop the occasional reporting of this message but will impede automatic switchovers.

SLS1661I ACS AA, Station XXXX: LMU driver has been restarted

Explanation: The LMU driver for ACS AA and station XXXX has been restarted after a previous abend. A prior message, SLS0680I, describes the abend.

System Action: The station driver sends requests to and receives responses from the LMU.

User Response: No immediate action is required, but the previous abend of the LMU driver should be reported to StorageTek Software Support.

SLS1662I LMU driver monitor task has been restarted

Explanation: The LMU driver monitor task is restarting after a previous abend. A prior message, SLS0680I, describes the abend.

System Action: The station driver monitor task resumes responsibility for starting, monitoring, and restarting LMU driver tasks.

User Response: No immediate action is required, but the previous abend of the LMU driver monitor task should be reported to StorageTek Software Support.

SLS1663I ACS AA, Station C...C: Driver has abended

Explanation: The LMU driver for the named ACS and station has abended and has not been restarted. SLS0680I describes the abend.

System Action: The monitor task will restart the LMU driver unless the monitor task has abended, and the operating system does not permit the monitor task to be restarted.

User Response: No immediate action is required, but the previous abend of the LMU driver should be reported to StorageTek Software Support.

SLS1664A ACS AA is disconnected {- unallocated}

Explanation: The HSC has determined that no LMU drivers are currently working for the named ACS. The HSC cannot automate cartridge motion requests with the current configuration. Unallocated indicates this ACS has been deleted via NCO by the operator. NCO ADD ACST is required to put this ACS back ONLINE in a connected state.

System Action: HSC issues this message about once every five minutes and DOMs it after about 30 seconds even if the condition has not been resolved. This is a periodic reminder that an ACS is disconnected.

User Response: If the HSC is required to automate mounts and dismounts to the affected ACS, the operator should do one of the following: (1) Vary a station online, (2) Force a Dual LMU switch to activate a standby station, or (3) Restart the HSC.

SLS1665E - SLS1700I

SLS1665E ACS AA, Station XXXX: Driver CCC...CCC

Explanation: ACS AA, Station XXXX, has experienced one of the following conditions (CCC...CCC):

attach failed

means that three attempts in a row failed to result in the driver task being established.

inoperable, maximum attach attempts failed

means that 33 total attempts to attach this driver have been exhausted.

System Action:

attach failed

The first time this message is issued for a station, SLSLDMON will abend to cause a dump to be taken. Then it will try to attach the driver again until the global attach limit is exhausted. On subsequent issuances of this message for a single station, no additional dumps will be taken.

inoperable, maximum attach attempts failed

SLSLDMON will not try to attach this driver any more. The HSC should be restarted to re-enable this station.

User Response:

attach failed

No immediate action is required, but the previous abend of the LMU driver and the subsequent abend of SLSLDMON should be reported to StorageTek Software Support.

inoperable, maximum attached attempts failed

Report this occurrence to StorageTek Software Support and schedule a restart of the HSC at a convenient point in time.

SLS1700I DHB eyecatcher bad in CCC...CCC

Explanation: A DHB record (block zero of the CDS) was passed for validation but the program could not find the eyecatcher DHB.

System Action: This copy of the CDS will be disabled. If it is the last CDS copy, the HSC terminates processing.

User Response: Check the input CDS(s) to ensure you are running with the correct one(s). Check to see if you are attempting to run the HSC on a non-LIBGENed host. Also, check to see if they have not been corrupted and written over. If you are using the proper CDS copies and they have not been corrupted, contact StorageTek Software Support.

SLS1702I Self correcting out-of-sync CDS block *blk-id*

Explanation: A corrupted CDS block (*blk-id*) has been found when comparing the Primary and Secondary CDS copies.

System Action: The correct copy replaces the incorrect copy.

User Response: None.

SLS1703I *CCC...CCC* is being copied to *CCC...CCC*

Explanation: A CDS data set is being enabled by copying the records from an existing CDS. This could be the result of a CDS Enable command issued on this host, or this host has recognized a new CDS that was enabled by another host. SLS1704I should follow this message when the copy process is finished. SLS0715I should follow when all active hosts in a multi-host environment have completed synchronization.

System Action: The CDS reserve is held at this time and will be released when the copy completes. HSC activity waits until all hosts synchronize to the new CDS configuration.



Note: If after about 20 seconds, all hosts have not complied, the configuration reverts back to what it was before the copy, i.e., an enabled CDS will be disabled, or a disabled CDS may be re-enabled.

User Response: None.

SLS1704I CDS copy complete for *CCC...CCC*

Explanation: Message SLS1703I should precede SLS1704I. A CDS synchronization has occurred for the named CDS and is now complete. The newly enabled CDS data set has had its data refreshed from an active CDS.

System Action: The HSC resumes normal activity using the new CDS allocations.

User Response: None.

SLS1705E All Control Data Set allocations failed, HSC cannot initialize

Explanation: Dynamic allocation for ALL data sets specified in the PARMLIB CDSDEF (or RECDEF if this is Reconfig) entry have failed.

System Action: The HSC cannot initialize without at least one copy of the CDS.

User Response: The error may have been caused by a missing or invalid PARMLIB entry. Check the MVS SYSLOG/SCP CONSLOG to determine the dynamic allocation failure(s) from message SLS1706E, if present. Correct the problem, and re-start the HSC.

SLS1706E Allocation failed for *CCC...CCC* on volume *volser*, reason code *XXXX*, information code *XXXX*

Explanation: Dynamic Allocation failed for the specified data set on the specified volume. If no volume was specified, it will be blank or asterisks.

System Action: If this is during startup, HSC Initialization continues, but the data set is not allocated. If this is from a CDs Enable command, the HSC continues operation with the current CDS definitions.

User Response: The reason and information codes are from SVC99 (Dynamic allocation). One of the most common reason codes is 17xx indicating that the named CDS could not be found. Refer to the IBM SVC99 dynamic allocation documentation for further details and reason code definitions.

If the reason code is not 17xx, the information code may contain a key that provides more specific information about the cause of the error. Use the following keys to determine which parameter is in error:

Key	Field
01	DDname
02	Dsn
04	Status
07	Unconditional Unallocation
10	Volser
15	Unit
55	Return DDname

User Response: Determine the cause of the dynamic allocation failures from the error messages presented. If this is during startup, correct the problem in PARMLIB or JCL and restart the HSC. If this is from a CDs Enable command, correct the specification of the DSN parameter, or for uncataloged data sets specify the NEWVol and possibly the NEWUnit parameters.

SLS1708I CCCCCCCC failed - RC=XXXXXXXX

Explanation: A command to Enable or Disable a copy of the CDS has failed or a module name of a failed program is displayed along with the return codes. Therefore, CCCCCCCC can be either Enable, Disable, or a module name.

System Action: On an Enable/Disable command, the action does not occur. If a module name is displayed, the HSC is failing.

User Response: Determine the cause of the problem from the return codes. Refer to Chapter 4 for return codes listings and descriptions. Correct the problem, and rerun.

SLS1709I Attach failed for CCCCCCCC, RC=XX

Explanation: An unsuccessful attempt was made to attach a database server task.

XX is the return code from the ATTACH macro as documented in the MVS SPL: System Macros

System Action: The I/O routines for the CDS are not available; the HSC cannot initialize.

User Response: Determine why the attach failed, and correct the problem. The HSC must be restarted.

If you are unable to correct the problem, save all information and contact StorageTek Software Support.

SLS1710E Database switch failed

Explanation: During CDS recovery, the enabling of an alternate copy failed. This may be due to a dynamic allocation, open, or copying error.

System Action: If a viable primary copy is available, processing continues.

User Response: Determine the availability of alternate CDS copies, or any reason for an open failure, or an I/O error on the copy. If correctable, issue a CDS Enable command to bring the alternate back online.

SLS1711I Database services unavailable

Explanation: A catastrophic internal failure has occurred, and HSC CDS services cannot continue.

System Action: The HSC terminates.

User Response: Call StorageTek Software and/or Hardware Support. Save dumps to aid in the diagnosis of the problem.

SLS1712I Hostid *CCCCCCCC* not found in *CCC...CCC*

Explanation: The specified host identifier does not match any host identifier found in the copy of the control data set being scanned. Possible user error attempting to run with the wrong copy of the CDS or the CDS has been corrupted and/or destroyed.

System Action: If it is the last CDS copy, the HSC terminates processing.

User Response: Check the input CDS(s) to ensure you are running with the correct one(s). Check to see if you are attempting to run the HSC on a non-LIBGENed host. Also, check to see if they have not been corrupted and written over. If you are using the proper CDS copies and they have not been corrupted, contact StorageTek Software Support.

SLS1713I CDS *CCC...CCC* disabled

Explanation: CDS *CCC...CCC* has been disabled.

System Action: The CDS is unallocated from the HSC.

User Response: Check the system log for additional messages showing the reason the CDS was disabled.

SLS1715I *CCCCCCCC* initializing on: *CCC...CCC1 CCC...CCC2 CCC...CCC3*

Explanation: This host has initialized on listed copies of the CDS. *CCCCCCCC* is the HOSTid. *CCC...CCC1*, *CCC...CCC2* and *CCC...CCC3* depict the CDS data set names. Errors from previous HSC sessions or from other hosts could affect which copies this host initializes at startup. The HSC may not use all data sets as presented in PARMLIB, and they may not be in the same order.

System Action: None.

User Response: None.

SLS1717I Standby CDS *CCC...CCC* disabled due to "DISABLE" parameter in the CDSDEF PARMLIB command

Explanation: The user specified DISABLE on the CDSDEF statement when defining the standby CDS (DSN3) to the system.

System Action: An attempt is made to read that CDS copy to ensure it is a valid CDS; then it is made inactive and de-allocated.

User Response: Should this CDS be needed, the HSC will NOT automatically use it in the case of a CDS switch or disable of either the primary or secondary CDS. You must manually enable it for use with the CDs Enable operator command.

SLS1718I CDS *CCC...CCC* disabled, not in use by other hosts

Explanation: In order to prevent CDS corruption and mismatches, the named CDS copy was disabled because it was not being used by other active hosts.

System Action: The CDS is disabled and unallocated from this HSC.

User Response: If you wish to utilize that CDS copy, use the CDs Enable operator command to bring the copy online.

SLS1719I CDS *CCC...CCC* disabling due to operator command

Explanation: CDS *CCC...CCC* will be unallocated due to an operator CDs Disable command.

System Action: The CDS is disabled and unallocated from this HSC.

User Response: If you wish to utilize that CDS copy, use the CDs Enable operator command to bring the copy online.

SLS1720E Database {switch|expand} not adopted by active host *CCCCCCCC*

Explanation: After a successful CDS switch or expand, another active host failed to recognize the CDS change within a reasonable amount of time.

System Action: The issuing host continues with operations. This host may revert to a more restrictive CDS configuration.

User Response: If the HSC has been terminated precipitously on another host, it may appear active to other hosts. Verify if the other host has terminated. If it has, either recycle it or run SLUADMIN (SET HSCLEVEL) to reset it. If CDS Enable, Disable, or EXpand commands are entered simultaneously on multiple hosts, this message may appear on one or more of those hosts when it should not. If this occurs, use the Display CDS command to verify the CDS configuration. If it is correct, no further action is required. If all hosts are active or if the CDS configuration is incorrect when commands are entered from multiple hosts, there is an internal problem. In MVS, issue the MVS DUMP operator command against that host then recycle it. In VM, issue the CP VMDUMP command on the virtual machine of that host then recycle it. Collect the dump, MVS SYSLOG/SCP CONSLOG, and LOGREC/EREP data for problem determination, and call StorageTek Software Support for assistance.

SLS1721I - SLS1725I

SLS1721I CDS *CCC...CCC* disabled, not in use at prior HSC termination

Explanation: CDS *CCC...CCC* was disabled at initialization because it was not in use when the HSC was last terminated.

System Action: The CDS is disabled and unallocated from this HSC.

User Response: To utilize this CDS copy, enter the CDs Enable command to bring the CDS online.

SLS1722I CDS *CCC...CCC* enabled, in use by other hosts

Explanation: It was determined that CDS *CCC...CCC* was disabled to this host and active to other hosts. This was the result of an operator CDs Enable command issued on another host. The CDS data set has been enabled for use by this host.

System Action: Enabling of the CDS on this host is automatic.

User Response: None

SLS1723I SVARSRV service detects invalid VALUEL *XXXX*

Explanation: While parsing a PARMLIB entry, an internal routine was passed an invalid length.

System Action: The HSC initialization fails.

User Response: Preserve a copy of the MVS SYSLOG/SCP CONSLOG and a copy of the HSC PARMLIB entry. Contact StorageTek Software Support.

SLS1724I *CCCCCCCC1* is invalid on the *CCCCCCCC2* statement

Explanation: While parsing the PARMLIB entry, an invalid command (*CCCCCCCC1*) was found on the specified PARMLIB statement (*CCCCCCCC2*).

System Action: The HSC initialization fails.

User Response: Correct the failing entry for the specified statement, and re-start the HSC.

SLS1725I Command parsed with no keywords

Explanation: While parsing a PARMLIB entry, a command was found that contained no keywords.

System Action: The HSC initialization fails.

User Response: Correct the PARMLIB command entry and re-start the HSC.

SLS1727I Invalid data set type (X) for dynamic allocation

Explanation: While parsing a PARMLIB entry, a command was found that contained no keywords.

System Action: The HSC initialization fails.

User Response: Correct the PARMLIB command entry, and restart the HSC.

SLS1729E The last copy of the CDS is in error; the HSC cannot continue

Explanation: Due to errors, the last remaining copy of the CDS was lost.

System Action: The HSC will not continue to run.

User Response: Look for previous messages which should explain why the CDS was lost. Correct these problems, and re-start the HSC. If you are unable to correct the problems, obtain a current copy of the MVS SYSLOG/SCP CONSLOG and/or the HSC job log. Also, IEBGENER dump a copy of each CDS used by the job, prior to any re-start attempts, to show their current state. Contact StorageTek Software Support.

SLS1730I Invalid return code from SLSDCOPY

Explanation: Internal error. During a switch to the Standby CDS, SLSDCOPY returned an unknown return code.

System Action: The copy operation terminates. The HSC continues to run if there is at least one good copy of the CDS. If not, the HSC terminates.

User Response: Attempt to restart the HSC. If an HSC is still running on another host, the restart should work. If restart does not work, it could be because all copies of the CDS are determined to be invalid. Obtain a current copy of the MVS SYSLOG/SCP CONSLOG and/or the HSC job log and a copy of all CDSs along with any system dumps that have been taken. Contact StorageTek Software Support.

SLS1731I Host-to-Host Communications registration failed, RC=XXXX

Explanation: An attempt to register for host-to-host communications failed. The return code is from the communications component.

System Action: Any communications between this host and any other active host in a multi-host environment will be through the CDS.

User Response: Look up the return code and follow the instructions. If unable to solve the problem, obtain a current copy of the MVS SYSLOG/SCP CONSLOG and/or the HSC job log along with any system dumps that have been taken. Contact StorageTek Software Support.

SLS1733E Hostid required for JRNDEF PARMLIB entry

Explanation: A JRNDEF statement found in PARMLIB did not contain a HOSTID parameter

System Action: Since the system does not know which host owns those journal files and journaling was requested, the system will not come up.

User Response: Add the HOSTID parameter to the JRNDEF statement for the proper host.

SLS1735I No journal files available

Explanation: The HSC lost the last valid journal file for this host.

System Action: If the JRNDEF parameter FULL was set to Abend (the default), the journal task and the HSC will abend. If the JRNDEF parameter FULL was set to Continue, the journal task will quiesce and the HSC will continue without journals.

User Response: At this point, NO journal files are valid for any host. Also, any offloaded journal files will be invalid. You should take an immediate backup of the HSC system. The reason “no files available” should be investigated. If the message is issued because the journal files filled up, the backup will reset them and journaling will continue automatically. If the message is issued because of an I/O error on the file, re-allocate that file and re-cycle the HSC. A backup should be taken as soon as that HSC is available again. If you cannot determine why this happened, notify StorageTek Software Support.

SLS1737E None of the Control Data Set copies is a valid primary CDS; HSC initialization terminated

Explanation: For all of the CDS copies specified by the CDSDEF parameter which it was possible to open and read, the CDS data set information in the DHB was inspected. The best CDS copy was not a primary or secondary CDS when it was last used and it has not been restored since. Thus, it would not be a valid primary CDS. It is impossible to bring up the HSC without serious questions about CDS integrity.

System Action: HSC initialization terminates.

User Response: Review the CDSDEF PARMLIB control statement to determine if incorrect data set names were specified.

If the right data sets were specified, use the HSC BACKup utility to select and backup the most current CDS copy followed by an HSC RESTore to synchronize all CDS copies. When starting the HSC after a BACKup and RESTore, make sure that the order of the CDS copies is correct in the CDSDEF parameter.

SLS1738E The CDS copies appear to belong to separate library environments;
HSC initialization terminated

Explanation: Based on the CDS data set information in the DHB, the data sets specified by the CDSDEF parameter do not seem to belong to a single library environment. Specific reasons for this are:

(1) The CDS copies appear to belong to separate library environments or are the result of multiple HSCs running on separate hosts after a remote link was lost. The procedure for merging the separate control data sets was not followed after the link was restored.

(2) The CDS copy with the highest shadow sequence number is not a valid primary CDS copy. This might be the former standby CDS copy after a reconfig.

It is impossible to bring up the HSC without serious questions about CDS integrity.

System Action: HSC initialization terminates.

User Response: Review the CDSDEF PARMLIB control statement to determine if incorrect data set names were specified.

If CDS copies are split among hosts when a link fails, follow the procedure in the BACKup utility section of the *HSC System Programmer's Guide* after the link is restored.

If the correct data sets were specified, use the HSC BACKup utility to select and backup the most current CDS copy followed by an HSC RESTore to synchronize all CDS copies. When starting the HSC after a BACKup and RESTore, make sure that the order of the CDS copies is correct in the CDSDEF parameter.

SLS1825I Volume *volser* is not in the library

Explanation: The volume was not in the library.

System Action: The function does not process the volume.

User Response: None.

SLS1900I Invalid reply: CCCCCCCC

Explanation: A reply to a WTOR was invalid.

System Action: The HSC reissues the WTOR.

User Response: Respond with a valid reply.

SLS1901I A communications path switched from *CCCC* to *CCCC*; {initiated by|with} *CCCCCCCC*

Explanation: The HSC on this host performed a switch of a communications method. If indicated, the switch was initiated by host *CCCCCCCC*, and this host has responded by performing a switch. Otherwise, a failure occurred on this host, and the other host will be notified to perform a switch. The previous and current methods are displayed.

System Action: If due to an error on this host, a search is performed to find the next lower level method available. If initiated by another host, the new method specified by that host is used.

User Response: If due to an error on this host (or possibly on an initiating host), find and correct the problem which prompted the switch. Then, if desired, return to the previous communications method by using the *COMMPATH* command.

SLS1902D Specified communications method is VTAM and VTAM is not active; reply *RETRY* or *NOVTAM*

Explanation: The communications method is specified as VTAM, but VTAM was not active when HSC tried to open the VTAM ACB.

System Action: The next lower method available is used until VTAM becomes active.

User Response: Reply *RETRY* to cause HSC to try again to open the VTAM ACB. If VTAM is active, a switch to the VTAM method occurs. Reply *NOVTAM* to cause HSC not to wait for VTAM to become active and to continue using the method already selected.

SLS1903I Communications method switch not initiated; host *CCCCCCCC* specified unacceptable *parm: CCCC*

Explanation: The HSC on host *CCCCCCCC* requested a communications method switch, but the *parm CCCC* is unacceptable on this host.

System Action: The request is ignored.

User Response: Since a method switch was requested, you may need to check for error messages on the requesting host and respond accordingly. If the results would have been desired, modify the definitions for this host and the requesting host by using the *COMMPATH* command.

SLS1904E Communications error: *function* XXXXXXXX1 XXXXXXXX2 [XXXXXXX3]

Explanation: The HSC host-to-host communications component encountered a processing error for the specified function. XXXXXXXX1 and XXXXXXXX2 are the primary and secondary error codes, respectively. If present, XXXXXXXX3 is further error information. Possible function values and error codes include:

Possible Function Values	Primary Error Codes (XXXXXXX1)	Secondary Error Codes (XXXXXXX2)	Additional Information (XXXXXXX3)
VTAM ALLOC	1 or 2	3	5
VTAM CLOSE	1	4	N/A
VTAM CNOS	1	3	5
VTAM DEALLOC	1 or 2	3	5
VTAM OPEN	1	4	N/A
VTAM OPRCNT	2	3	5
VTAM PREPRCV	2	3	5
VTAM RCVFMH5	1 or 2	3	5
VTAM RECEIVE	2	3	5
Issue VTAM RECEIVE	1	3	5
VTAM RECEIVE complete	1	3	5
VTAM RECEIVE WHATRCV	1	3	6
VTAM REJECT	1 or 2	3	5
VTAM RESETRCV	2	3	5
VTAM SEND	2	3	5
VTAM SEND FLUSH	1	3	5
VTAM SETLOGON	1	3	N/A



Note: See “value definitions” sections below for definitions of the numbers in this list (1-6) used to represent error codes.

Value definitions for primary and secondary error codes as well as additional error information include:

Primary Error Code (XXXXXXXX1) value definitions:

- 1 Primary return code from R15 (for VTAM requests)
- 2 Recovery action return code from R0 (for VTAM SYNAD and LERAD exits)

Secondary Error Code (XXXXXXXX2) value definitions:

- 3 Two bytes with value from RPLRTNCD field and two bytes with value from RPLFDB2 field in RPL
- 4 Value from ACBERFLG field in ACB

Additional Information (XXXXXXXX3) value definitions:

- 5 Two bytes with value from RPL6RCPR field and two bytes with value from RPL6RCSC field in RPL extension
- 6 Value of WHATRCV mask from RPL6WHAT field in RPL extension

Primary (XXXXXXXX1) and secondary (XXXXXXXX2) error codes as well as additional information (XXXXXXXX3) display when applicable. The codes consist of four bytes displayed as eight characters. For example,

SLS1904E Communications error: VTAM ALLOC 00000000 0000000B 00040000

VTAM code definitions are documented in applicable VTAM manuals.

System Action: Processing attempts to continue. Depending on the severity of the error, execution may be affected later on.

User Response: Determine and correct the problem. If the error caused a communications method switch, determine if you want to return to the higher COMM level (use the COMMPATH command).

SLS1905I Unexpected RC *XXXXXXXX* from *CCCCCCCC*

Explanation: An unexpected return code was returned from a component.

System Action: The system continues operating and bypasses the requested function of the component.

User Response: Contact StorageTek Software Support.

SLS1906I Invalid message data:

CCCCCCCCCC
ZZZZZZZZZZ
NNNNNNNNNN

Explanation: Invalid character(s) were detected in a communications message being sent to another host. *CCCCCCCCCC* is the EBCDIC representation of the message data. *ZZZZZZZZZZ* and *NNNNNNNNNN* are the zones and numerics of the message data.

System Action: The system continues operating and the communications message is ignored.

User Response: Contact StorageTek Software Support.

SLS1907I CDS output message queue count for host *HHHH* is *CCCCCC*

Explanation: There are *CCCCCC* messages on the CDS output message queue for host *HHHH*.

System Action: If the HSC on host *HHHH* is active the messages will eventually be processed. If the HSC on host *HHHH* is inactive then the messages will not be processed and will continue to accumulate.

User Response: If the HSC on host *HHHH* is active and VTCS is installed, Sun recommends that the HSC COMMPATH METHOD parameter be set to either LMU or VTAM. If host *HHHH* is not active then the RECOVER command can be used to delete the queued messages.



Caution:
command.

See the REC

SLS1950I Volume *volser* moved from location *AA:LL:PP:RR:CC* to location *AA:LL:PP:RR:CC*

Explanation: Volume *volser* was moved to location *AA:LL:PP:RR:CC*.

System Action: The volume was moved as requested.

User Response: None.

SLS1951I - SLS1954I

SLS1951I Volume *volser* not in ACS *AA*

Explanation: A volume, *volser*, requested in a command or utility was not found in the CDS if *AA* is blank or in the target ACS if *AA* is displayed.

System Action: The command or utility function is not performed for the volume.

User Response: If *Flsm* and *TLsm* are specified on a MOVE statement, insure they are within the same ACS configuration. Otherwise, a Display Volume may be used to determine if it exists and/or where.

SLS1952I {MOVE} Rejected; Conflicting audit in progress on {ACS|LSM}
{ACSid|LSMId}

Explanation: A command or utility function was attempted against library volumes that were being audited by a SLUADMIN AUDIt utility.

System Action: The requested command or utility terminates.

User Response: Wait until the AUDIt utility job is finished, and re-enter this request.

SLS1953I I/O error processing control database

Explanation: An I/O error on the control data set occurred during processing of a command or utility function.

System Action: The command or utility terminates before completing the requested function.

User Response: Determine the cause of the I/O error. Re-enter the request after the control data set problem is corrected.

SLS1954I {MOVE} rejected; {ACS|LSM} {ACSid|LSMId} is {OFFLINE|INVALID|NOT
CONNECTED}

Explanation: A command was rejected because the specified component of the system required to complete the command was unavailable.

System Action: The command is rejected.

User Response: Verify that the ACS is connected, the LSM is online (available) as indicated in the message, and then re-enter the command. If the ACSid or LSMid is invalid, re-enter the command with the correct ACSid or LSMid. If the problem persists, contact StorageTek Hardware Support.

- SLS1955I** Cell *AA:LL:PP:RR:CC* is not a valid CELLid
- Explanation:** A Cell (*AA:LL:PP:RR:CC*) requested in a command or utility was found to be an invalid location for a storage cell.
- System Action:** The command or utility function is not performed for the cell.
- User Response:** Determine the correct location, and repeat the function.
- SLS1956I** Unable to select volume during *CCCCCC* of volume *volser*
- Explanation:** During processing of the *CCCCCC* command, Volume *volser* was already in use and could not be selected to complete the operation.
- System Action:** The *CCCCCC* command continues with the next volume in the scope of the requested command.
- User Response:** Enter a separate *CCCCCC* command for the volume when it is not in use.
- SLS1957I** MOVE rejected; no target LSMs are connected, online, or valid
- Explanation:** An attempt to move volume(s) to specified LSM(s) was rejected. None of the LSMs were valid, connected, or online to the host where the command was executed.
- System Action:** The operator command terminates.
- User Response:** Connect one or more of the LSMs to this host (see Vary and MODIFY commands), and re-enter the operator command.
- SLS1958I** No free cells found in specified PANEL or LSM(s) to continue the MOVE function
- Explanation:** A MOVE command was issued, but no free cells were found in the specified panel or LSM(s). Reasons for this include:
- Panel or LSM is UNALLOCATED
 - Panel or LSM is full (no empty cells)
- System Action:** The MOVE function terminates due to lack of free cells.
- User Response:** Free up cells in the LSMs where volumes are to be moved by ejecting volumes from the LSM, or re-enter the MOVE command specifying a different panel in the LSM or a different LSM. Lack of free cells when empty cells exist may be caused by Capacity on Demand (COD) and Partitioning. If this is the reason, add more capacity or increase the Partition.

SLS1959I - SLS1961I

SLS1959I Volume in cell location *AA:LL:PP:RR:CC* does not physically match specified Volser *volser*

Explanation: During the process of verifying the volume and its location, the volume was not where the control data set indicated it should have been.

System Action: The volume was not moved during this operation and is made errant.

User Response: An attempt should be made to locate the volume in question. If necessary, perform an audit of the panel where the volume resided.

SLS1960I External label on volume *volser* is unreadable

Explanation: While executing a command, the label on Volume *volser* has become unreadable.

System Action: The volume was not moved during this operation. The control data set is marked to reflect this condition.

User Response: The specified volume should be ejected from the library and its external label examined to determine why the label is not readable. If this condition exists on several volumes, report this condition to StorageTek Hardware Support.

SLS1961I Cell *AA:LL:PP:RR:CC* is empty - found during *CCCCCC*

Explanation: While running the *CCCCCC* command, the cell in question was found to be empty.

System Action: The volume is made errant.

User Response: Perform one of the following actions:

- Audit the referenced cell (*AA:LL:PP:RR:CC*)
- Mount or eject the volume to invoke errant recovery to allow a logical eject to occur

SLS1962I CCCCCC of volser at AA:LL:PP:RR:CC failed; LMU/LSM error (XXXX)

Explanation: Command CCCCCC of volume volser or Cell AA:LL:PP:RR:CC failed. XXXX is an LMU/LSM error. Possible LMU/LSM errors are:

6510 - No pass-thru port for transfer
 6511 - LMU offline
 6512 - Lost communication with LMU
 6514 - LSM hardware error
 6515 - LMU hardware error
 6528 - LMU Server Dead
 6592 - LSM is offline
 65FF - Request purged

System Action: The action in progress will not complete. The cartridge may be made errant depending on the point at which the failure occurred.

User Response: Use the Display Volume command to determine the status and location of the volume. If the volume is made errant, perform one of the following actions:

- Audit the referenced cell (AA:LL:PP:RR:CC)
- Mount or eject the volume to invoke errant recovery to allow a logical eject to occur

SLS1963I Unexpected RC received in module CCCCCCCC1 while processing CCCCCCC2 (XXXXXXXXXX)

Explanation: Module CCCCCCCC1 returned an unexpected return code (XXXXXXXXXX) while attempting to perform the CCCCCCC2 function. The success or failure of the function is unknown.

System Action: The state of action in progress is unknown, and a SNAP dump has been taken.

User Response: Preserve the SNAP dump and contact StorageTek Software Support.

SLS1964I TPANEL specified for MOVE of volser conflicts with source location panel

Explanation: A MOVE command or utility function was attempted specifying the same panel where the source volume resides. A move to the same panel is not allowed.

System Action: The requested command or utility terminates. The move is not performed.

User Response: Re-enter the command or utility specifying a TPanel that is not the source location panel.

SLS1965I - SLS1968E

SLS1965I AT *HH:MM:SS* CCCCCCCC REQUESTED DDDDDDDD volser EEEEEEEE

Explanation: In response to a MONITOR command, this message indicates that the specified job CCCCCCCC has issued a programmatic interface or VM TMI call requesting the specified motion against the specified volser (*volser*).

HH:MM:SS Specifies the time the request was issued. If a single request specified multiple volumes (e.g. Eject), then each message for that request will display the same time.

DDDDDDDD Specifies the type of motion. Valid values are Mount, DISMount, MOVE or Eject.

EEEEEEEE Specifies the location involved. This is either a CAPid (Eject), LSMid (MOVE target), or a drive device number (Mount, DISMount).

System Action: None.

User Response: None.

SLS1966I CCCCCCCC task failed, attempting to restart

Explanation: The task (CCCCCCCC) either failed to initialize, or it completed its processing out of sequence, either normally or via an abend. An attempt will be made to detach and reattach the task in order to restart it.

System Action: HSC processing continues.

User Response: None.

SLS1967I CCCCCCCC task restarted successfully

Explanation: The task that failed earlier was detached and reattached and now has initialized successfully.

System Action: HSC processing continues.

User Response: None.

SLS1968E CCCCCCCC task could not be restarted

Explanation: The attempt to detach and reattach the task did not succeed. The maximum number of reattach attempts for this task was tried, but the task could not be restarted. The HSC should be recycled soon in order to re-establish the functions of this task.

System Action: HSC processing continues.

User Response: You should recycle the HSC in order to recover the functionality of the non-restartable task.

SLS1969I User Exit *CC* module *CCCCCCCC* *RRRRRRRR*

Explanation: The HSC User Exit Service responded with one of the following conditions:

If *RRRRRRRR* = **ABENDED and DISABLED**

User Exit *CC* had an error for module *CCCCCCCC*

If *RRRRRRRR* = **INACTIVE**

User Exit *CC* returned inactive for module *CCCCCCCC*

If *RRRRRRRR* = **NOT DISABLED**

User Exit *CC* was being processed when an abend occurred

System Action: If status displayed is **INACTIVE**, the system no longer executes the User Exit module, as this is the requested action.

If status is **ABENDED and DISABLED**, User Exit had a processing error and is no longer executed.

If status is **NOT DISABLED**, this implies there was an abend while processing this user exit, but it was outside the boundaries of the user exit itself. In this case, the exit is not disabled. The abend should still be investigated.

User Response: If status displayed is **INACTIVE**, no further action is required, as this is the requested action.

If status displayed is **ABENDED and DISABLED** or **NOT DISABLED**, notify the systems programmer immediately of this condition.

SLS1970I OPEN Error on User Exit Module Library: *CCCCCCCC*

Explanation: An error occurred at initialization time when the system attempted to OPEN the User Exit Module Library specified by the *CCCCCCCC* DD JCL card.

System Action: The System attempts to load the default User Exit Modules from JOBLIB/STEPLIB instead of specified User Exit Module Library. Dynamic LOAD/RELOAD of User Exits is --NOT-- possible due to OPEN Error.

User Response: Notify your systems programmer immediately of this condition. Correct the spelling of User Exit Module Library name and/or resolve the reason for OPEN Error.

SLS1971I - SLS1972D

SLS1971I HSC User Exit Service Error: User Exit CC Now INACTIVE

Explanation: An internal maintenance/check program detected a serious data structure error condition in the User Exit Table.

System Action: The System changes the status of problem User Exit to “INACTIVE” and takes steps to correct the data structure error with next dynamic LOAD of User Exit CC.

User Response: Dynamically RELOAD User Exit CC via the UEXIT operator command. If this problem occurs again, notify your systems programmer immediately.

Note: Dynamic LOAD/RELOAD of User Exit Modules is only possible if the “SLSUEXIT” DD procedure statement was included in the HSC JCL.

SLS1972D ATTACH/Initialization of CCCCCCCC is OVERDUE; Retry or Cancel (R,C)

Explanation: The HSC is attempting to ATTACH and Initialize the required module CCCCCCCC, but, it is taking longer than expected. The ATTACH/Initialization process will continue for several minutes, but, could eventually abend the HSC startup process.

System Action: Processing continues, Response is NOT mandatory. The message is issued to give the customer an opportunity to enter the various user response options as described below.

Possible user responses:

- | | |
|------------------|--|
| R | Retry will restart the ATTACH and Initialization timers. |
| C | Cancel will force an HSC abend, take a system DUMP and Cancel the HSC startup process. |
| no action | The HSC will wait for several more minutes for the CCCCCCCC to ATTACH and initialize. If successful the HSC will continue processing. If not successful the HSC startup process will issue an abend and then begin its shutdown logic. |

SLS1973I (...error text...)

Explanation: A specified value is invalid or an incompatibility exists between model, unit, media, and/or recording technique information for a request. Valid error text messages include:

RECTECH is incompatible with UNIT

The value specified for the RECtech parameter is not compatible with the drive specified for the unit.

MODEL is incompatible with UNIT

The value specified for the MODel parameter is not compatible with the drive specified for the unit.

MEDIA is incompatible with UNIT

The value specified for the MEDia parameter is not compatible with the drive specified for the unit.

UNIT is incompatible with both MEDIA and RECTECH

The drive specified for the unit is not compatible with the MEDia or RECtech values.

UNIT is incompatible with both MEDIA and MODEL

The drive specified for the unit is not compatible with the MEDia or MODel values.

MEDIA is incompatible with RECTECH

The value specified for the MEDia parameter is not compatible with the value specified for the RECtech parameter.

MEDIA is incompatible with MODEL

The value specified for the MEDia parameter is not compatible with the value specified for the MODel parameter.

RECTECH is incompatible with both UNIT and MEDIA

The value specified for the RECtech parameter is not compatible with the drive and MEDia parameters.

MODEL is incompatible with both UNIT and MEDIA

The value specified for the MODel parameter is not compatible with the drive and MEDia parameters.

MEDIA is incompatible with both UNIT and RECTECH

The value specified for the MEDia parameter is not compatible with the drive and RECtech parameters.

MEDIA is incompatible with both UNIT and MODEL

The value specified for the MEDia parameter is not compatible with the drive and MODel parameters.

MEDIA, RECTECH and UNIT are all incompatible

The values specified for MEDIA, RECTech and the drive parameters are not compatible with each other.

MEDIA, MODEL and UNIT are all incompatible

The values specified for MEDIA, MODEL and the drive parameters are not compatible with each other.

MEDIA is invalid

The value specified for the MEDIA parameter is unknown or incorrect.

RECTECH is invalid

The value specified for the RECTech parameter is unknown or incorrect.

MODEL is invalid

The value specified for the MODEL parameter is unknown or incorrect.

MEDIA and RECTECH are invalid

The values specified for the MEDIA and RECTech parameters are unknown or incorrect.

MEDIA and MODEL are invalid

The values specified for the MEDIA and MODEL parameters are unknown or incorrect.

UCB/LMU Drive type mismatch; UCB device type assumed

The MVS UCB indicated a device type which is not compatible with the LMU device type. HSC will assume the UCB device type for this operation: 3480 is assumed to be 18TRACK; 3490/3490E are assumed to be 36ATRACK; and 3590 is assumed to be STK1R.

UCB/LMU UNITATTR Drive type mismatch; UCB/LMU type assumed

The UNITATTR for the device does not match what the UCB or LMU indicates. HSC will use the type of device that the UCB/LMU indicates.

System Action: None

User Response: Correct the situation described in the error message and resubmit your job.

SLS2008I

CAP Status:

CAP ID	Size	Partid	Hostid	Priority	Mode	Status
<i>CCCC1</i>	<i>CCCC2</i>	<i>PPP</i>	<i>CCCC3</i>	<i>DD</i>	<i>CCCC4</i>	<i>CCCC5</i> <i>CCCC5</i>

Explanation: The status of one or more CAPs is displayed in response to the Display Cap command. One status line is displayed for each CAP. If there are no CAPs attached to the host, the message “LSM AA:LL|AA:LL:CC has no CAPs available” is displayed instead of the CAP status messages.

<i>CCCC1</i>	CAPid (AA:LL:CC)
<i>CCCC2</i>	CAP size, which is one of the following: 21-CELL: Standard 4410 CAP 20-CELL: WolfCreek CAP 30-CELL: WolfCreek optional CAP 40-CELL: Enhanced CAP PCAP: Priority CAP (Enhanced/Wolfcreek) 14-CELL: 9740 14 cell CAP 10-CELL: 9740 CAP with 10 cell magazine 9740-TYPE: 9740 CAP when HSC does not yet know the number of cells 26-CELL: Streamline 3000 CAP with two 13 cell magazines 39-CELL: StreamLine 8500 CAP with three 13 cell magazines
<i>PPP</i>	PARTid of the partition owning the CAP. This is only displayed if the CAP is active.
<i>CCCC3</i>	HOSTid of the host owning the CAP. This is only displayed if the CAP is active.
<i>DD</i>	CAP priority
<i>CCCC4</i>	CAP Mode, which is one of the following: Entering: CAP is being used to enter tapes. Ejecting: CAP is being used to eject tapes. Draining: CAP is being drained. Cleaning: CAP needs cleaning Idle: CAP is idle. Unknown: Error occurred. Unknown CAP type.

CCCC5 CAP Status, which is one or more of the following:
Manual: CAP is in Manual mode.
Online: CAP is Online
Offline: CAP is Offline.
Active: CAP is performing a task.
Recovery: Error occurred. Recovery needed.
Automatic: CAP is in automatic mode
Unknown: Error occurred. Unknown CAP status.

System Action: HSC processing continues.

User Response: None.

SLS2009I EJECT|ENTER|VIEW rejected; unexpected RC *XXXX* from *FIGMNGR|SLSCGREC*

Explanation: An Eject|ENter|VieW command was rejected because an unexpected return code was encountered from Configuration Management (FIGMNGR) or CAP Services detected an error attempting to locate a CAP record (SLSCGREC).

XXXX the called service return code.

FIGMNGR|SLSCGREC the called service presenting the return code.

System Action: The command is rejected.

User Response: None.

SLS2011I The VIEW command is not supported for this library type

Explanation: An attempt to VIEW a cell in a SL8500 or SL3000 library has failed because this library has no lights or cameras.

System Action: The VIEW command is terminated.

User Response: None.

SLS2012I DRAIN command rejected; CAP *AA:LL:CC* is OFFLINE

Explanation: The specified CAP cannot be drained, as it is not online. Since it is not online, it cannot be doing an enter or an eject and, consequently, should not need to be drained.

AA:LL:CC is the CAPid.

System Action: The DRAin request is rejected.

User Response: Reissue the command with the correct CAPid.

LSM type displayed is as follows:

- 4410 Standard LSM
- 3000 StorageTek Library 3000
- 8500 Streamline
- 9310 PowderHorn
- 9360 WolfCreek
- 9740 TimberWolf

Depending on the format of the Display command, the following information may be included:

- CAP status, which includes CAPid, Size, HOSTid, Priority, Mode and Status. The status of one or more CAPs is displayed in response to the Display Cap command. One status line is displayed for each CAP. If there are no CAPs attached to the host, the message “LSM AA:LL|AA:LL:CC has no CAPS available” is displayed instead of the CAP status messages.

<i>DDDD1</i>	LSM type, which is one of the following: 4410 Standard LSM 3000 StorageTek Library 3000 8500 Streamline 9310 PowderHorn 9360 WolfCreek 9740 TimberWolf
<i>CCCC1</i>	CAPid (AA:LL:CC)
<i>CCCC2</i>	CAP size, which is one of the following: 21-CELL: Standard CAP 20-CELL: WolfCreek CAP 30-CELL: WolfCreek optional CAP 40-CELL: Enhanced CAP PCAP: Priority CAP (Enhanced/WolfCreek) 10-CELL: 9740 CAP with 10 cell magazine 14-CELL: 9740 14 cell CAP 26-CELL: SL3000 with two 13 cell magazines 39-CELL: StreamLine 8500 CAP with three 13 cell magazines 9740-TYPE: 9740 CAP when HSC does not yet know the number of cells
<i>CCCC3</i>	HOSTid of the host owning the CAP. This is only displayed if the CAP is active.
<i>DD2</i>	CAP priority.

CCCC4 CAP Mode, which is one of the following:
 Entering: CAP is being used to enter tapes.
 Ejecting: CAP is being used to eject tapes.
 Draining: CAP is being drained.
 Cleaning: CAP needs cleaning.
 Idle: CAP is idle.
 Unknown: Error occurred. Unknown CAP type.

CCCC5 CAP Status, which is one or more of the following:
 Manual: CAP is in Manual mode.
 Online: CAP is Online.
 Offline: CAP is Offline.
 Active: CAP is performing a task
 Recovery: Error occurred. Recovery needed.
 Automatic: CAP is in automatic mode.
 Unknown: Error occurred. Unknown CAP status.

- Audits in progress, if any
- Number of scratch volumes and free storage cells available in each LSM
- Display each frozen panel, showing the total number of cells (*DDD1*) and number of free cells (*DDD2*) on the panel.

System Action: HSC processing continues.

User Response: None.

SLS2033I {ENTER|EJECT} command rejected; LSMid *AA:LL* does not control a CAP

Explanation: An ENter or Eject command specified an LSMid that does not control a CAP.

System Action: The Eject or ENter command is rejected.

User Response: To view the status of the eligible CAPs, issue the Display Cap command.

Re-issue the command specifying an LSMid that controls an eligible CAP.

SLS2034I MODIFY LSMid AA:LL offline command rejected; CAPid AA:LL:CC reserved to CCCCCCCC

Explanation: An attempt was made to modify the last SL8500 LSM offline that can control the CAP(s) when at least one CAP was still active.

System Action: The MODify lsm OFFline command is rejected.

User Response: Ensure that all the CAPs for the LSM are inactive. Or, vary on another LSM that can control the active CAP. If further CAP processing is impossible due to a hardware error, issue the MODify lsm OFFline command with the FORCE keyword.

SLS2038I DRAIn command rejected; ENter|EJect command not active on CAPid AA:LL:CC.

Explanation: The specified CAP is not currently performing enter or eject processing or an ENter or EJect command is not in progress from the same host from which the DRAIn command is entered.

AA:LL:CC. is the CAPid.

System Action: The DRAIn request is rejected.

User Response: Reissue the command on the host where the ENter|EJect is active.

SLS2039I {ENTER|EJECT} command rejected; no CAPs on {ACS AA|LSMid AA:LL} are eligible for selection

Explanation: An ENter or EJect command did not contain a specific CAPid, and no CAPs are eligible to be selected.

To be eligible for selection, a CAP must have a non-zero CAP preference value, it must be online, it must be idle, and it cannot be in RECOVERY Mode. In addition, for the ENter command, the CAP cannot be in AUTO mode.

System Action: The EJect or ENter command is rejected.

User Response: To view the status of the CAPs, issue the Display Cap command.

If CAP preference values need to be set to non-zero, this is done using the CAPPref command.

If a CAP needs to be brought online, this is done using the MODify command.

If a CAP mode needs to be changed from AUTO to MANual, this is done using the CAPPref command.

If a CAP is in RECOVERY mode then wait until the Recovery process is complete.

Once there are eligible CAPs from which to choose, re-issue the command. Alternatively, the command can be issued with a specific CAPid, so that the selection process is unnecessary.

SLS2043I Scratch warning thresholds have been set to *DDDD* for *ACS acsid/LSM lsmid {SUBPOOL subpool} {MEDIA media RECTECH rectech}*

Explanation: This message indicates that the scratch warning threshold has been adjusted by the Warn command. *DDDD* is the threshold, *acsid* or *lsmid* is the ACS or LSM for which the threshold has been set. *subpool* is the subpool to which the threshold applies. *media* is the media type to which the threshold applies. *rectech* is the recording technique to which the threshold applies.

System Action: None.

User Response: None.

SLS2050I *CCCCCCCC* command not executed; reconfiguration is active

Explanation: The command cannot be executed while reconfiguration is active.

System Action: The command is rejected.

User Response: Re-enter the command when reconfiguration is complete.

SLS2075I Manually mounted volume *volser* from cell location *AA:LL:PP:RR:CC* deleted from the CDS

Explanation: A volume, *volser*, manually mounted in an offline LSM was dismounted manually. The volume is no longer within library control and has been deleted from the Control Data Set (CDS).

System Action: The volume is deleted from the CDS, and processing continues.

User Response: None.

SLS2080I Unable to mark volume *#####* errant - volume is not selected.

Explanation: During a dismount, an attempt was made to mark the specified volume errant. This could not be done as it is not in selected status.

System Action: The volume is not dismounted and is not marked errant.

User Response: Investigate why the volume is not selected and take appropriate action.

SLS2081I Unable to mark volume *#####* errant - VAT not owned by caller.

Explanation: During a dismount, an attempt was made to mark the specified volume errant. This could not be done as the VAT is not owned by the caller.

System Action: The volume is not dismounted and is not marked errant.

User Response: Issue the DISMOUNT from the same system that mounted the cartridge.

SLS2082I - SLS2108D

SLS2082I Unable to mark volume ##### errant - VAR not owned by caller.

Explanation: During a dismount, an attempt was made to mark the specified volume errant. This could not be done as the VAR is not owned by the caller.

System Action: The volume is not dismounted and is not marked errant.

User Response: Issue the DISMOUNT from the same system that mounted the cartridge.

SLS2102D Dismount of *volser* from {drive XXXX|driveid AA:LL:PP:NN} - Volume not in CDS; reply I, A, R or E to Ignore, Add, Retry or Eject

Explanation: An attempt was made to dismount volume *volser* from transport {XXXX|AA:LL:PP:NN}, but the specified volume was not in the control data set.

System Action: The dismount waits for you to reply I; A; R; or E.

User Response: Reply with one of the following:

- Ignore (I)** If the dismount is to be ignored.
- Add (A)** If the volume is to be added to the CDS and the cartridge dismounted to a new home cell.
- Retry (R)** If the control data set lookup is to be retried.
- Eject (E)** If the cartridge is to be ejected.

SLS2108D Mount of *volser* on {drive XXXX|driveid AA:LL:PP:NN} - External media type unreadable; reply Retry/Bypass/Eject/Ignore (R,B,E,I)

Explanation: An attempt was made to mount volume *volser* on transport XXXX|AA:LL:PP:NN, but the external media type was unreadable.

System Action: The mount waits until you reply either Retry, Bypass, Eject, or Ignore.

User Response: Reply with one of the following:

- R** If the mount is to be retried, reply R.
- B** If the mount is to be retried and media type verification bypassed, reply B.
- E** If the volume is to be ejected, reply E. Volume *volser* will be deleted from the control data set.
- I** If the mount is to be ignored, reply I.

SLS2114D Enter of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - *volser* cannot be used; reply E,*volser* to enter cartridge or I to Ignore

Explanation: An attempt was made to ENter volume *volser* to be mounted on drive *XXXX* or driveid *AA:LL:PP:NN*, but the volume is incompatible with the transport, has unreadable media, or is selected to another process.

System Action: The mount waits for you to reply "E,*volser*" or "I".

User Response: Reply with one of the following:

E,*volser* If a different *volser* is to be entered or if the same volume is to be entered after resolving the error condition.

I If the mount is to be ignored.

SLS2119I Allocation record mismatch

Explanation: A DALM block mismatch was detected between the primary and the secondary control data set. This is a warning message that indicates that one or the other control data sets does not contain the correct record allocations.

System Action: None.

User Response: Verify that the control data sets are the proper data sets to backup. If not, obtain the correct set, and resubmit the BACKup utility.

SLS2124I Manual Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Complete

Explanation: In response to an SLS2911D manual mount request or in MVS the detection of mounted volume on the transport, volume *volser* was presumed mounted by the operator on transport *XXXX|AA:LL:PP:NN*.

System Action: Normal processing continues. The volume is retained in the CDS.

User Response: None.

SLS2126D Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - Volume not in library; reply "I", "R", "T", "P", "T,capid" or "P,capid"

Explanation: An attempt was made to mount volume *volser* on specified transport {*XXXX*|*AA:LL:PP:NN*} where *XXXX* = drive and *AA:LL:PP:NN* = DRIVEid, but volume *volser* was not in the library.

System Action: The mount waits until you respond or the volume is entered.

User Response: Reply with one of the following:

I	If the mount is to be ignored.
R	If the mount is to be retried.
T	If the volume required is to be temporarily entered. HSC attempts to allocate a CAP with nonzero CAPpref in the ACS in which the drive is located. HSC does not select a PCAP.
P	If the volume required is to be permanently entered. HSC attempts to allocate a CAP with nonzero CAPpref in the ACS in which the drive is located. HSC does not select a PCAP.
T,capid	If the volume required is to be temporarily entered. HSC attempts to use the CAPid specified.
P,capid	If the volume required is to be permanently entered. HSC attempts to use the CAPid specified.



Notes:

- When you enter "T" or "P" without a CAPid, HSC does not select a PCAP. You must enter "T,capid" or "P,capid" to use a PCAP for entering a cartridge to satisfy the MOUNT.
- If your site does not have a tape management system, be sure to reply to this message (either I; R; T; P; T,capid; or P,capid). Otherwise, the cartridge may be selected and overwritten if a job requests a scratch after entering the volume.

SLS2150I Volume(s) *volser*<-*volser*> not in library

Explanation: One or more of the volumes requested for a SLUADMIN utility function was not defined in the library. If a volume range was specified on the utility command and a sequential series of volumes within that range was not found, a single message will be displayed for the series.

System Action: The utility continues processing.

User Response: None.

SLS2151I "SUMMARY(SUBPOOL)" specified and scratch subpool definitions not available

Explanation: The "SUMMARY(SUBPOOL)" keyword was specified on the VOLRpt utility statement, but no scratch subpool definitions were available either via an SLSSCRPL DD statement or via an accessible SLSUX03 module.

System Action: The utility continues processing. Scratch subpool totals will not be produced.

User Response: None.

SLS2152I *CCCCCCC1* keyword for *CCCCCCC2* not supported in the *CCCCCCC3* environment

Explanation: The *CCCCCCC1* keyword found on the *CCCCCCC2* utility control statement is not supported in the specific *CCCCCCC3* environment.

System Action: A return code of 8 is set and the utility terminates.

User Response: Remove the keyword from the control statement and rerun the utility in the *CCCCCCC3* environment, or run the utility in a compatible environment.

SLS2153I Volume *volser* in cell *AA:LL:PP:RR:CC* has MEDIA-Type mismatch with database

Explanation: A SLUADMIN AUDIt utility function has encountered a library cartridge with the specified volume serial number (*volser*) at the specified location (*AA:LL:PP:RR:CC*) whose MEDIA-type specification in the control data set does not match LMU vision system results.

If the AUDIt is active with APPLY(YES) specified or defaulted on the control statement, the volume's MEDIA-type specification will be altered to match the results from the LMU. If the AUDIt is active with APPLY(NO) specified on the control statement, the HSC issues a warning message, and the control data set is not updated.

System Action: Depending on the APPLY parameter specification, the MEDIA-type specification for the volume may be changed in the control data set.

User Response: None.

SLS2154I - SLS2158I

SLS2154I "SUMMARY" must specify either "TOTAl", "SUBpool", or both

Explanation: The "SUMMary" keyword was indicated for the VOLRpt utility but did not specify a value or specified an invalid value.

System Action: A return code of 8 is set, and the utility terminates.

User Response: Specify either "TOTAl", "SUBpool", or "TOTAl,SUBpool", on the VOLRpt utility, and resubmit the job.

SLS2155I CCCCCCCC1 parameter CCCCCCCC2 already specified

Explanation: The CCCCCCCC1 parameter for the CCCCCCCC2 keyword had been previously specified.

System Action: A return code of 4 is set, and the utility continues.

User Response: None necessary; this message is for warning only.

SLS2156I No more SCRTCH volumes in ACS AA

Explanation: The EJECT utility was run specifying a number of scratch tapes to eject. HSC ejected all available scratch tapes within the ACS (AA) but did not have enough to completely satisfy the request.

System Action: The EJECT utility terminates with a return code of 4.

User Response: Perform another SCRTCH eject against a different ACS.

SLS2157I Unable to obtain storage for volume table

Explanation: There is insufficient storage to obtain a table to store requested volume information. This applies to the VM environment ONLY.

System Action: The VOLRpt utility terminates with a return code of 8.

User Response: Either define a larger virtual machine size (at least four megabytes is recommended), or reduce the amount of data requested.

SLS2158I SLSVA DD missing, data reported may be incorrect

Explanation: The SLSVA DD is needed when the volsers being reported are a mix of media types and recording techniques. When all volsers have the same media and recording technique, this message can be ignored. If mixed media types are involved, then the SLSVA DD should be supplied for the file containing the VOLATTR statements. If the SYSVA dataset was to be determined from HSC, either HSC was inactive or was not at the same release level as the SLUADMIN program running VOLRPT.

System Action: The utility continues processing. Reported data may be incorrect.

User Response: Supply the SLSVA DD for the VOLATTR statements.

SLS2159I *CCCCCC* of volume *volser* - Access denied

Explanation: An attempt to access a volume was denied by user exit 14.

System Action: The utility continues without processing the volume. A return code 4 is set by the *CCCCCC* utility.

User Response: None.

SLS2160I *volser* not ejected, MEDIA MISCOMPARE

Explanation: During eject processing, a volume to be ejected was found to have a miscompare between the media information in the CDS and the media information returned by the LMU. The following messages may also be issued by the HSC at the console: SLS0698I, SLS0699I.

System Action: Eject continues without ejecting the cartridge. Condition code 4 is set.

User Response: The AUDIt utility should be run to correct the media mismatch.

SLS2169I *CCCCCCCC1 (CCCCCCCC2)* must have *CCCCCCCC3*

Explanation: The data set *CCCCCCCC2* defined by the DD statement *CCCCCCCC1* was found not to have the necessary DCB attribute *CCCCCCCC3*.

System Action: A return code of 8 is set, and the utility terminates.

User Response: Ensure that the DD/FILEDEF statement specifies the proper DCB attributes and rerun the utility.

SLS2182I Input CDS from *CCCCCCCC* CDS level *RRRRRRRR* is inconsistent with utility maintenance level

Explanation: The input CDS, which is at release level *RRRRRRRR* cannot be used with the utility maintenance level. *CCCCCCCC* is the data set name.

System Action: The program terminates.

User Response: Resubmit the utility job using a load library for an HSC release level compatible with the current CDS.

SLS2184I Database error: CCCCCCCCCCCC1 on CCCCCCCC2 CDS

Explanation: A database error occurred on the CCCCCCCC2 control data set. The error information is contained in CCCCCCCCCCCC1.

If the error is 70847084 (subfile not found), it may be because one of the parameters in the utility control statement is out of bounds. An example of an out of bounds condition causing this error is if you specified LSM(00:06) for a library that only has one LSM. For any other conditions, there is a possibility of a CDS integrity error on CCCCCCCC2 CDS.

System Action: The utility will go to normal termination with a return code of 8.

User Response: If the problem is an invalid parameter, correct the parameter and rerun the desired utility. If the problem is not an invalid parameter specification, make a copy of the CDS as it currently exists for diagnostic purposes, then restore the respective CDS(s) and rerun the desired utility.

If this error persists, call customer support with the appropriate information.

SLS2189I WARNING: CAP CCCCCC1 unexpectedly released during CCCCCC2 CCCCCC3 processing

Explanation: CAP CCCCCC1 had been released when the CCCCCC3 process of the CCCCCC2 utility expected it to be allocated.

System Action: A return code of 8 is set and the utility either continues or terminates, depending on the process CCCCCC3.

User Response: If possible, the user should rerun the utility ensuring that the CAP which is allocated is NOT released prematurely.

SLS2195I XXXXXXXX command rejected; CAPid AA:LL:CC is in AUTOMATIC mode

Explanation: A utility was run with a specific CAPid. That CAP is currently not available because it is in AUTOMATIC mode.

System Action: None.

User Response: Rerun the utility specifying a different CAP, or take the CAP out of AUTOMATIC mode.

SLS2197I CAPid AA:LL:CC is offline

Explanation: A SLUADMIN utility function required a functional path to a specific CAPid (AA:LL:CC) but found the CAP offline to the host where the utility was executed.

System Action: The utility terminates processing.

User Response: Bring the CAP online to this host (see MODify command), and resubmit the SLUADMIN utility job.

SLS2198I HSC Subsystem maintenance level is not correct for this utility

Explanation: HSC Subsystem maintenance level is not correct for this utility. A SLUADMIN utility function requires that the HSC subsystem and the utility modules are a certain release or PUT level.

System Action: The utility terminates processing.

User Response: Ensure that the HSC and utility load libraries are the same library concatenation. The user should select the libraries associated with the HSC currently running. Resubmit the job once the load library correction has been made.

SLS2200I Warning: Volume *volser* Media-type compare failed between VOLATTR and cartridge label

Explanation: A SLUADMIN utility function has encountered a library cartridge with the specified volume serial number (*volser*). The robotics found the volume label to be of a Media-type that does not match the VOLATTR control statement Media-type specification.

System Action: None. This is a warning/informational message only.

User Response: Check to ensure that the VOLATTR Media-type specification or the volume Media-type label is correct.

SLS2201I (...error text...)

Explanation: A specified value is invalid or an incompatibility exists between model, unit, media, and/or recording technique information for a request. Valid error text messages include:

RECTECH is incompatible with UNIT

The value specified for the RECtech parameter is not compatible with the drive specified for the unit.

MODEL is incompatible with UNIT

The value specified for the MODEL parameter is not compatible with the drive specified for the unit.

MEDIA is incompatible with UNIT

The value specified for the MEDIA parameter is not compatible with the drive specified for the unit.

UNIT is incompatible with both MEDIA and RECTECH

The drive specified for the unit is not compatible with the MEDIA or RECtech values.

UNIT is incompatible with both MEDIA and MODEL

The drive specified for the unit is not compatible with the MEDIA or MODEL values.

MEDIA is incompatible with RECTECH

The value specified for the MEDIA parameter is not compatible with the value specified for the RECtech parameter.

MEDIA is incompatible with MODEL

The value specified for the MEDIA parameter is not compatible with the value specified for the MODEL parameter.

RECTECH is incompatible with both UNIT and MEDIA

The value specified for the RECtech parameter is not compatible with the drive and MEDIA parameters.

MODEL is incompatible with both UNIT and MEDIA

The value specified for the MODEL parameter is not compatible with the drive and MEDIA parameters.

MEDIA is incompatible with both UNIT and RECTECH

The value specified for the MEDIA parameter is not compatible with the drive and RECtech parameters.

MEDIA is incompatible with both UNIT and MODEL

The value specified for the MEDIA parameter is not compatible with the drive and MODEL parameters.

MEDIA, RECTECH and UNIT are all incompatible

The values specified for MEDIA, RECtech and the drive parameters are not compatible with each other.

MEDIA, MODEL and UNIT are all incompatible

The values specified for MEDIA, MODEL and the drive parameters are not compatible with each other.

MEDIA is invalid

The value specified for the MEDIA parameter is unknown or incorrect.

RECTECH is invalid

The value specified for the RECTech parameter is unknown or incorrect.

MODEL is invalid

The value specified for the MODEL parameter is unknown or incorrect.

MEDIA and RECTECH are invalid

The values specified for the MEDIA and RECTech parameters are unknown or incorrect.

MEDIA and MODEL are invalid

The values specified for the MEDIA and MODEL parameters are unknown or incorrect.

UCB/LMU Drive type mismatch; UCB device type assumed

The MVS UCB indicated a device type which is not compatible with the LMU device type. HSC will assume the UCB device type for this operation.

UCB/LMU UNITATTR Drive type mismatch; UCB/LMU type assumed

The UNITATTR for the device does not match what the UCB or LMU indicates. HSC will use the type of device that the UCB/LMU indicates.

System Action: The utility terminates without further action.

User Response: Correct the situation described in the error message, and resubmit your job.

SLS2202I

No scratch volumes (MEDIA/RECTECH); Scratch Redistribution will not run

Explanation: The SLUADMIN utility determined that there are no scratch volumes available within the ACS that match the specified MEDIA and/or RECTech criteria.

System Action: The utility terminates without further action.

User Response: Use the SCRATCH utility to define scratch volumes in the ACS, then resubmit the SLUADMIN utility job.

SLS2203I - SLS2205I

SLS2203I Volume *volser* in cell *AA:LL:PP:RR:CC* has unreadable MEDIA label

Explanation: A SLUADMIN AUDIt utility function has encountered a library cartridge with the specified volume serial number (*volser*) at the specified location (*AA:LL:PP:RR:CC*) that has an unreadable external MEDiA label.

If the audit is active with APPLy(YES) specified or defaulted on the control statement, the volume entry in the control data set is updated to reflect this fact. If the audit is active with APPLy(NO) specified on the control statement, the HSC issues a warning message and the control data set is not updated.

System Action: Depending on the APPLy parameter specification, the volume entry in the control data set will be updated.

User Response: Determine the reason the MEDiA label is unreadable.

SLS2204I Volume *volser* in cell *AA:LL:PP:RR:CC* is not in control database. MEDIA label unreadable

Explanation: A SLUADMIN AUDIt utility function has encountered a library cartridge with the specified volume serial number (*volser*) at the specified location (*AA:LL:PP:RR:CC*) that is not in the control data set. However, the external MEDiA label on the cartridge is unreadable.

If the audit is active with APPLy(YES) specified on the control statement, the cartridge will be ejected. If the audit is active with APPLy(NO) specified on the control statement, the HSC issues a warning message.

System Action: Depending on the APPLy parameter specification, the volume may be ejected from the library.

User Response: Examine cartridge to determine cause of unreadable external MEDiA label.

SLS2205I No more SCRTCH volumes (MEDIA/RECTECH) in ACS AA

Explanation: The SLUADMIN utility determined that there are no scratch volumes available within ACS AA that match the specified MEDiA and/or RECtech criteria.

System Action: The utility terminates without further action.

User Response: If you want this utility to continue, use the SCRAtch utility to define scratch volumes in the ACS with the correct MEDiA and RECtech criteria, and resubmit the SLUADMIN utility job.

SLS2206I Error ejecting Volume *volser* with unreadable MEDIA in cell
AA:LL:PP:RR:CC

Explanation: A SLUADMIN AUDIt utility was unable to eject volume (*volser*) at cell *AA:LL:PP:RR:CC* that is not in the control data set and has an unreadable MEDIA external label. An attempt was made to eject the cartridge, but the AUDIt encountered an LMU error and was unable to eject the cartridge.

System Action: The situation is treated as a condition code 4 error; the AUDIt job continues.

User Response: If an error persists, contact your local StorageTek CSE. The tape may have to be removed by EJECT command.

SLS2207I BALTOl parameter value invalid

Explanation: The BALtol parameter is not within the specified type or range of values.

System Action: The utility terminates without further action.

User Response: Permissible value for the BALtol parameter are 1 through 999 (inclusive). Correct the BALtol parameter value and resubmit the SLUADMIN utility job.

SLS2208E VERIFY parameter invalid

Explanation: The VERIFY parameter was specified with an invalid program.

System Action: The JOB will end with a return code 8.

User Response: Remove the VERIFY parameter or change the program name to TMSTPNIT for CA1 Tape Initialization.

SLS2250I Attempting cleanup of CAP *AA:LL:CC*

Explanation: Cleanup is being attempted for CAPid *AA:LL:CC*.

System Action: The CAP is scanned.

User Response: None.

SLS2251A CAP ejecting; please empty cartridges out of CAP *AA:LL:CC*

Explanation: When attempting to get a CAP for processing, volumes were found in the selected CAP. The volumes must be removed before processing can continue.

System Action: CAP processing waits.

User Response: Open the CAP door, remove the cartridges, and close the CAP door.

SLS2252A - SLS2255I

SLS2252A CAP processing terminating; please empty cartridges out of CAP
AA:LL:CC

Explanation: The library subsystem is attempting to shutdown, but a CAP was in use.

System Action: Termination processing waits.

User Response: Open the CAP door, remove the cartridges, and close the door.

SLS2253I LMU error XXXXXXXX ACS AA

Explanation: The HSC had an error XXXXXXXX issuing requests to ACS AA.

System Action: Processing continues.

User Response: Contact StorageTek Software Support.

SLS2254A Empty CAP AA:LL:CC and close door

Explanation: At the beginning or termination of CAP processing, the CAP was found to contain cartridges, and those cartridges must be removed.

System Action: Processing waits.

User Response: The CAP door must be opened, the cartridges removed, and the CAP door closed.

SLS2255I Module CCCCCCCC ABEND XXXXX, RC=XXXXXXXX; ZZ dump taken

Explanation: A CAP component software failure occurred. CCCCCCCC is the abending module; XXXXX is the System or User abend code; CCCCCCCC is the reason code; and ZZ will be "No" if no dump was taken or spaces if a dump was taken.

System Action: Application error handling routines attempt to resolve the problem.

User Response: Save any dumps taken. Contact StorageTek Software Support.

SLS2256I Automatic CAP Service {Available|Unavailable}

Explanation: An attempt was made to execute a CAP component feature supporting the Automatic CAP service. The Automatic CAP service may be available even though no ACSs are connected. A reply of Unavailable indicates this service is not functioning. Therefore, CAPs in the “automatic” state will not process an automatic ENter.

System Action: HSC continues to function but without the Automatic CAP service.

User Response: If the Automatic CAP service is Available no response is needed.

If the Automatic CAP service is Unavailable you may set the CAP to manual mode and continue. Determine the cause of the problem and correct it, if possible. If accompanied by a dump, save the dump and contact StorageTek Software Support.

To reactivate Automatic CAP services, stop and restart the HSC.

SLS2257I Return code CCCCCC1 from CCCCCC2; unable to make CAP AA:LL:CC
CCCCC3

Explanation: Operation CCCCCC2 failed on CAP AA:LL:CC, and the CAP could not be put into a CCCCCC3 (MANual or AUTO) state. CCCCCC1 is the return code from operation CCCCCC2.

System Action: The specified CAP is not put into the CCCCCC3 state; execution continues.

User Response: Determine the reason for the return code and, if possible, correct and retry the command.

SLS2258I Auto CAP AA:LL:CC in recovery; remove cartridges found in CAP

Explanation: A CAP in automatic mode processing an enter found the CAP in recovery.

System Action: The system continues processing. Cartridges remaining in the first slots of the CAP are processed. Cartridges remaining in the CAP with an empty slot before them are not processed.

User Response: Remove any cartridges found in the CAP before filling the CAP with new cartridges.

SLS2259A CAP AA:LL:CC unlocked; Magazine(s) installed improperly or CAP not closed completely

Explanation: Either there are no magazines in CAP AA:LL:CC, the magazines are installed incorrectly, or the CAP is not closed completely. The CAP must contain at least one magazine, and unless the CAP is a StreamLine 8500 CAP, it must be in the bottom position in the CAP.

System Action: The system waits until the operator has opened and closed the CAP door. Then, the CAP is scanned again to ensure that the magazine(s) have been installed correctly. If the problem has not been corrected, this message is re-issued.

User Response: If the CAP contains no magazines, insert at least one. For the StreamLine 8500 CAP, the magazine can be placed at the top, middle or bottom position. For all other CAPs, insert the magazine(s) starting at the bottom of the CAP; if there is an empty magazine slot below any magazine, move that magazine down to fill the gap. Then close the CAP door completely.



Note: A magazine without the "N" symbol on its top right corner is not recognized by WolfCreek LSMs. If one of these magazines is installed in the bottom position in a WolfCreek CAP, it causes this message to be issued. If one of these magazines is installed in a WolfCreek CAP but not in the bottom position, this message is not issued; however, only magazines beneath that one will be used.

SLS2260I Auto CAP Enter of *volser* failed; {LSM PATH OFFLINE|ACS OFFLINE|CARTRIDGE MADE ERRANT|CAP OFFLINE|CAP ID INVALID}

Explanation: Volume *volser* was not entered because:

- the LSM Path, ACS, LSM, or CAP were offline, or
- the CAPid was invalid or Cartridge Made Errant.

System Action: The system operation continues. Volume *volser* remains in the CAP.

User Response: Make certain that the LSM path, ACS, LSM, and CAP are online; then retry the operation.

SLS2261I Auto CAP Enter - unexpected Return Code XXXXXXXX

Explanation: Auto CAP enter unexpected return code XXXXXXXX was received.

System Action: The auto CAP enter operation is not completed. However, system operation continues.

User Response: Contact StorageTek Software Support.

SLS2262I Return code *CCCCCCC1* from *CCCCCCC2*; CAP *AA:LL:CC* is unlocked

Explanation: The specified operation (*CCCCCCC2*) failed trying to lock CAP *AA:LL:CC*. Return code *CCCCCCC1* was issued.

System Action: The specified CAP is not locked from this host but is still set to manual mode in the CDS; execution continues.

User Response: You may need to open and shut the specified CAP door.

SLS2263I CAP *AA:LL:CC* in {AUTO|MANUAL} mode

Explanation: CAP *AA:LL:CC* is now in the indicated mode (AUTO or MANual). If the indicated mode is AUTO, the CAP is unlocked and available for entering cartridges. If the indicated mode is MANual, you must issue the ENter command to unlock the CAP in order to enter cartridges.

System Action: The CAP is locked if the mode is MANual and unlocked if the mode is AUTO.

User Response: None.

SLS2264E Auto CAP *AA:LL:CC* still active; CAP component termination pending

Explanation: During HSC level 2 termination, Auto CAP *AA:LL:CC* was still in active status.

System Action: HSC level 2 termination waits until Auto CAP *AA:LL:CC* is no longer active.

User Response: Ensure that the CAP door is closed. If the CAP is in recovery respond to any prior messages requesting removal of cartridges from the CAP.

SLS2266E Cartridge *volser* in CAP cell *AA:LL:CC:RR:CC* has an invalid media label and cannot be entered

Explanation: A cartridge (*volser*) has been found in CAP cell *AA:LL:CC:RR:CC* with an unreadable optical media label and cannot be entered.

System Action: Cartridge entry leaves the cartridge in the CAP cell in which it is found and continues with the next cartridge in the CAP.

User Response: Remove the cartridge from the CAP. If the cartridge must be entered, correct the media label.

SLS2267I Eject of *volser* into PCAP - media type changed from *MM1* to *MM2*

Explanation: The initial attempt to eject volume *volser* into a PCAP failed with a media miscompare.

A media miscompare error occurs when the HSC-supplied media type to be verified (*MM1*) did not match the media type read by the vision system (*MM2*). The LMU reports the mismatch to the HSC as a media miscompare error. Media miscompare errors occur only when the HSC requests the LMU to perform media verification.

System Action: The media type for the volume in the Control Data Set (CDS) is changed to the media type read by the vision system. The eject is automatically retried.

This message is issued only when media verification is in effect, and media verification is done when the eject is automatically retried. If a miscompare occurs again the eject will fail and the PCAP will be released.

User Response: If *MM1* and *MM2* are the same, a hardware problem with the LMU or vision system may exist. If the automatically retried eject fails, try to eject the volume into a non-PCAP. If the retried eject is successful, no response is necessary.

SLS2268I CAP reserved to another host group; unable to make CAP *AA:LL:CC* AUTO

Explanation: Another host group, such as ACSLS, has reserved CAP *AA:LL:CC*, and the CAP could not be put into the AUTO state.

System Action: The specified CAP is not put into the AUTO state; execution continues.

User Response: Wait for the other host group to release the CAP; or, use the other host group software or the hardware mechanism to free the CAP.

SLS2275I CAP *AA:LL:CC*: unavailable for *CCCCCCC1 CCCCCC2*

Explanation: CAP *AA:LL:CC*: had been unexpectedly released during a previous process for *CCCCCCC1* and is hence unavailable for the *CCCCCCC2* process. This message may accompany message SLS2189I.

System Action: The indicated phase of the utility is bypassed.

User Response: If possible, the user should rerun the utility ensuring that the CAP which is allocated is NOT released prematurely.

SLS2276I Drive *XXXX* is incompatible with media for volume *volser*

Explanation: The CARTINIT utility attempted to mount volume *volser* on the specified transport *XXXX*, but the tape media and transport are incompatible.

System Action: The system ejects the cartridge and continues with the next one.

User Response: On the SLSTAPE DD statement, specify a transport that matches the media being initialized.

SLS2277I RECONFIG volume copy started using *DDDDDDDD*

Explanation: The *DDDDDDDD* method is being used for the RECONFIGuration volume copy. *DDDDDDDD* may be CDS I/O or Data Space. The data space method offers improved performance.

System Action: The utility continues.

User Response: None.

SLS2278D Creation of the RECONFIG utility Data Space failed - *MMMMMMMM* - *CC*
- *RRRRRRRR*; reply CDS or Terminate (C/T)

Explanation: *MMMMMMMM* is the IBM macro call that failed creating the Reconfiguration utility data space. *CC* is the return code that describes the failure. *RRRRRRRR* is the reason code that describes the failure. Refer to the appropriate IBM documentation for an explanation of the return/reason code.

If the failing macro is DSPSERV with a 08 return code and a reason code of xx0005xx, the size of the data space violates installation criteria (IEFUSI exit). This indicates that the HSC is not running in Protect Key 1-7. Check the MVS Program Properties Table in the SCHEDxx member of SYS1.PARMLIB for proper specification of the Protect Key for HSC.

System Action: The RECONFIGuration utility waits until you reply with either CDS (C) or Terminate (T).

User Response: Reply with one of the following:

- C If the RECONFIGuration utility is to continue using the CDS I/O method for the volume copy step. This will lengthen the run time of the utility.
- T If the RECONFIGuration utility is to terminate.

SLS2279E RECDEF dataset is not a newly recreated CDS

Explanation: The reconfiguration utility found volume records in the RECDEF CDS. The RECDEF CDS must be a newly created CDS.

System Action: The reconfiguration utility terminates with return code of 08.

User Response: Run the SLICREAT utility to create a new CDS.

SLS2314I CAP *AA:LL:CC* released or drained

Explanation: The EJECT utility found that an allocated CAP *AA:LL:CC* was released or drained.

System Action: The utility continues if other CAPs are active.

User Response: None.

SLS2315I - SLS2318I

SLS2315I DDDDDDDD was selected as the CCCCCCCC control data set and was disabled

Explanation: The utility function found that data set DDDDDDDD was the CCCCCCCC CDS according to the DHB block or the JCL and was disabled for the duration of utility processing.

System Action: The utility continues.

User Response: None.

SLS2316I Volume *volser* not ejected; CAP(s) released in ACSid AA

Explanation: The EJECT utility found that all allocated CAPs in ACSid AA were released or drained.

System Action: The utility continues if CAPs in other ACSs are active.

User Response: None.

SLS2317I Unexpected EOF reading journal specified by SLSJRN*dd* DD statement

Explanation: The RESTore utility encountered the end-of-file condition while attempting to read the journal file SLSJRN*dd*. (*dd*=01 - 99.)

System Action: The utility terminates with a U1096-0202 abend.

User Response: Check to see that the specified journal file was properly formatted. If it was not, then use SLICREAT to format the journal file.

If the specified journal file is properly formatted, then contact StorageTek Software Support.

SLS2318I Volume *volser* is a VSM MVC cartridge; cannot be entered into Scratch List

Explanation: A SLUADMIN SCRATCH Update utility attempted to add a specified volume serial number (*volser*) to the library scratch pool, but the *Volser* qualifies as a VSM MVC cartridge and cannot be treated as a scratch volume.

System Action: :The utility continues processing.

User Response: The error does not cancel the SCRATCH Update utility, but you may want to check the specified volume serial number, correct it, and resubmit the SLUADMIN SCRATCH update job.

SLS2319I Volume *volser* already defined in VSM as scratch

Explanation: A SLUADMIN SCRATCH Update utility attempted to add a specified volume serial number (*volser*) to the VSM scratch pool, but the volume was already defined as scratch.

System Action: The utility continues processing.

User Response: The error does not cancel the SCRATCH Update utility, but you may want to check the specified volume serial number, correct it, and resubmit the SLUADMIN scratch update job.

SLS2320I Volume *volser* not defined in VSM as scratch

Explanation: A SLUADMIN SCRATCH Update utility attempted to remove a specified volume serial number (*volser*) the VSM scratch pool, but the volume was not defined as a scratch volume.

System Action: The utility continues functioning.

User Response: This error does not cancel the SCRATCH Update utility, but you may want to check the specified volume serial number and resubmit the SLUADMIN scratch update job.

SLS2321I Volume *volser* successfully added to VSM as scratch

Explanation: A SLUADMIN SCRATCH Update utility has added the specified volume serial number (*volser*) to the VSM scratch pool.

System Action: HSC processing continues.

User Response: None.

SLS2322I Volume *volser* successfully deleted from VSM scratch pool

Explanation: A SLUADMIN SCRATCH Update utility has deleted the specified volume serial number (*volser*) from the VSM scratch pool.

System Action: HSC processing continues.

User Response: None.

SLS2323I Volume *volser* is NOT eligible to be scratched

Explanation: A SLUADMIN SCRATCH Update utility attempted to add a specified volume serial number (*volser*) to the library scratch pool, but the Volser has been set as NOT eligible to be scratched.

The Volser has been placed in the DO NOT SCRATCH condition by one of the following reasons:

- The volser is a VSM Multiple Volume Cartridge (MVC).

System Action: The utility continues processing.

User Response: The error does not cancel the SCRATCH Update utility, but you may want to check the specified volume serial number, correct it, and resubmit the SLUADMIN SCRATCH update job.

SLS2324I Volume *volser* not scratched, DFSMSRMM API Error, *ffffffff*, RC=*xx*, RS=*yy*

Explanation: A SLUADMIN SCRATCH Update utility has attempted to scratch the specified volume serial number (*volser*) but was unable to because DFSMSRmm returned a non zero return code. *ffffffff* is the RMM function that failed. The function will be either LISTVOLUME or CHANGEVOLUME. Reference the DFSMSRMM documentation to find the meaning of the return code *xx* and the reason code *yy*.

System Action: The utility continues functioning.

User Response: This error does not cancel the SCRATCH Update utility. Correct the problem and re-run the SCRATCH Update utility for this volser.

SLS2325I Volume *volser* not scratched because it is not a scratch in the DFSMSRmm database.

Explanation: A SLUADMIN SCRATCH Update utility has attempted to scratch the specified volume serial number (*volser*) but was unable to because the volume was not in scratch status in the DFSMSRmm control dataset.

System Action: The utility continues functioning.

User Response: This error does not cancel the SCRATCH Update utility. When the volume is placed in scratch status in the DFSMSRmm control dataset then re-run the SCRATCH Update utility for this volser.

SLS2401E User SCRATCH subpool definition unsuccessful - ccccccccccccccccccc2

Explanation: User SCRATCH subpool definition is unsuccessful. The reason is given by ccccccccccccccc2, and may be any one of the following:

Bad number of subpools: *n*

The user attempted to define more than the maximum of 255 subpools, or zero subpools. *n* is the number of subpools specified.

Subpool defined out of order: *n*

The user attempted to define subpools out of order. The subpool numbers presented to HSC must be sequential beginning with 1. *n* is the number of the first subpool which is defined out of sequence.

Bad number of subpool entries: 0

The user attempted to define zero subpool ranges.

Bad volsr range: *vvvvv1-vvvvv2*

The user attempted to define a subpool with an invalid VOLSER range. The beginning and ending volsers of the invalid range are shown as *vvvvv1* and *vvvvv2*.

Bad label type: X“*xx*”

The user attempted to define a subpool with an invalid label type. The invalid label type is shown in hexadecimal as *xx*.

Subpools already defined

The user attempted to define subpools a second time. HSC allows subpools to be defined only once during a single execution.

System Action: Subpools are not defined.

User Response: Correct the invalid subpool definition and resubmit the definitions to HSC. This requires stopping and starting HSC unless the definitions are being submitted through the VM Tape Management Interface.

SLS2402E - SLS2405E

SLS2402E Scratch Pool Depletion Warning for ACS AA|LSM AA:LL {Subpool CCCCCC1} {Media CCCCCC2}, DDDDDDDDDD Scratch Volumes remaining

Explanation: The scratch warning threshold/interval has been reached for media type CCCCCC2. The specified ACS (AA) or LSM (AA:LL) has (DDDDDDDDDD) scratch volumes remaining. If the threshold was specified for a subpool, the subpool is also identified by CCCCCC1.

This message is first issued when the scratch pool has reached the initial scratch warning level. The message is repeated whenever the scratch pool is depleted by the scratch interval amount. (See the Warn and OPTion Warnmsg operator commands for more details on scratch thresholds and warning intervals.)

System Action: The ACS or LSM is running low on scratch volumes as specified by the user via the Warn command. When all scratch volumes have been used, the HSC attempts to allocate scratch mount requests to non-library transports.

User Response: Add more scratch cartridges to the ACS or LSM scratch pool for the correct media type (by running the SCRAtch update utility function), or lower the scratch warning threshold.

SLS2405E Configuration manager (FIGMGR) Error: Program - CCCCCC1, Function - CCCCCC2, Level - CCC3, Type - CCCCC4, RC - XXXX

Explanation: The HSC Configuration Manager reported an unexpected error condition.

System Action: The task is abended, and a dump is produced.

User Response: Save the dump. Contact StorageTek Software Support.

SLS2412I Previously unselected volume VVVVVV incurred an error while the record was being CCCCCCCCCCCCCCCCCCCC

Explanation: Volume VVVVVV had the UNSElect utility run against it sometime prior to the CCCCCCCCCCCCCCCCCCCC action.

The process encountering the error had the volume selected when the utility unselected the volume.

The CCCCCCCCCCCCCCCCCCCC action is defined as follows:

Unselected

Made errant

Updated

Inserted as scratch

Deleted

System Action: The action is not completed. There might also be a subsequent U1096 abend with a return code 4004, "volume not selected".

User Response: The U1096 abend return code 4004 is the residual affect of a user action and is not applicable to the present volume circumstance. The conditions of the cartridge need to be determined and corrective action may be necessary. Scan the system logs to find out what the last system action against the volume was prior to this message. Display the volume to determine where HSC believes the cartridge is located. With this information use the VIEw command to check each of the potential cartridge locations. If a VIEw shows it is not in its home cell and a Display Volume shows it is in its home cell but it is unselected, two primary paths of resolution are present.

SLS2450E - SLS2450E

The first is that a View accounted for the physical location of the volume in the library based on system log messages or actions taken. If the volume is on a transport in MVS, you must issue an Unload command for the transport; and if it is online, the Unload command delays unloading the device until it is no longer allocated. If it is not online to any system, issue an HSC DISMount command without the volser. In VM, if the device is ATTACHed to the tape management virtual machine (such as VMTAPE), issue an HSC DISMount without the volser. If the device is not ATTACHed to any virtual machine, you should attempt to ATTACH the device to some virtual machine and then DETACH it which unloads the tape. If the transport is assigned to another system, the ATTACH fails. If the volume is in a CAP, input an HSC ENter command to allocate the CAP and then remove the cartridge. Follow the procedure below to logically remove the volume reference from the control dataset. If the volume is in an inaccessible location due to a hardware failure, (PTP, Transport, CAP, LSM), contact StorageTek Hardware Support.

The second is that the volume was removed from the LSM during CAP processing or manual mode and is external to the library. This can usually be corrected by running an AUDIt against the cell. Another method is to perform an HSC Eject or Mount command against the volume and reply to the subsequent message to eject or delete the "logical" volume reference from the control dataset.

SLS2450E Error reading control database - RC = XXXX

Explanation: A Configuration Control function received an error return code from the Data Base Server and could not proceed.

System Action: The Configuration Control function is aborted. This may cause other top level functions to be aborted as well.

User Response: Check the device containing the control data set. If the device is operational, obtain the most recent backup of the control data set and run a SLUADMIN RESTore utility.

SLS2459I Panel Mismatch - LSM AA:LL

```

                                1111111111
Panel Number 01234567890123456789
LMU Status  CCCCCCCCCCCCCCCCCCCCCC
             XXXXXXXXXXXXXXXXXXXXXX
CDS Status  CCCCCCCCCCCCCCCCCCCCCC
             XXXXXXXXXXXXXXXXXXXXXX

```

Explanation: The Configuration Control verification function detected a mismatch between the panel type definitions in the LMU and those found in the control data set for LSM AA:LL. Each status area contains two lines of characters, where the first line represents the high order of a panel type, and the second line represents the low order. Each high-order “C” and low-order “X” will be replaced by the following characters:

blank	no panel
	<i>High Capacity LSMs (4410, 9310)</i>
00	PowderHorn Window panel
01	cell panel
02	cell (panel 10) adjacent to door
03	door panel
04	passthru right panel (a master PTP panel, unless connected to panel 2 on a WolfCreek)
05	passthru slave panel
06	normal drive panel
07	drive (panel 10) adjacent to door
08	LCU Panel (panel 0)
09	Clipper door panel (panel 11)
10	inside cell (panels 13-18)
11	inside cell (panel 19)
12	inside door (panel 12)
13	wide drive panel (configured for 20 drives)
14	wide drive panel (configured for 20 drives) adjacent to door (panel 10)
	<i>WolfCreek LSMs (9360)</i>
20	panel 0
21	panel 2 with slave passthru
22	panel 0 with master passthru
23	panel 1 without drive
24	panel 1 with drive

25	panel 2
26	panel 2 with master passthru
27	panel 3
28	panel 3 with drives
29	panel 4 with 1 CAP
30	panel 4 with 2 CAPs
31	panel 3 without cells
32	panel 3 with drives without cells
33	panel 3 with viewing window
34	panel 3 with drive hole without drive
35	panel 4 with 1 CAP without cells
36	panel 4 with 2 CAPs without cells
37	panel 4 with CAP without optional cells
	<i>97XX LSMs (9740)</i>
40	9740 panel with no cells (door with a window)
41	9740 panel with 4 columns of cells and no passthru port (panel 0 or door with cells)
45	9740 CAP panel
46	9740 drive panel
47	9740 panel with slave passthru port (panel 0)
48	9740 panel with master passthru port (panel 2)
99	unknown panel type for the LMU

System Action: Configuration Control verification continues in order to report on all mismatches. The HSC remains up, but the station (LMU) stays offline.

User Response: A comparison of the two status areas shows where the differences in LSM panel configurations are. Based on the actual physical configuration, (1) change the LIBGEN parameters to correspond to the LMU configuration and regenerate the control data set with another LIBGEN, (2) have the StorageTek CSE change the LMU configuration to match the LIBGEN parameters, or (3) change the drive panel type with the Set SLIDRIVS utility.

SLS2460I Select override occurred for a *CCCC* record at address *HHHHHHHH*

Explanation: The Configuration Manager timed out waiting for a lock to be released for a *CCCC* record. Since no update occurred, a new request was allowed to access the record at address *HHHHHHHH*.

System Action: Processing continues, some operator intervention may be required.

User Response: Take a dump of the HSC address space and call StorageTek Software Support.

SLS2463I Drive record for drive *AA:LL:PP:NN* not written; key CDS fields have changed

Explanation: The HSC attempted to rewrite a drive record, but either the driveID, unit address, or deleted status was changed by a Set SLIDRIVS command.

System Action: The rewrite of the drive record is bypassed.

User Response: Recycle the host to refresh the HSC drive records.

SLS2501I *CCCCCCCCI* task was found to be active during HSC termination; waiting for completion

Explanation: The HSC found a *CCCCCCCCI* task active during component termination and must complete before termination may continue. Below is a list of *CCCCCCCCI* tasks:

- Automatic CAP
- Station Monitor
- Attach Monitor
- Listener
- Server

System Action: Termination waits until the action completes or a cancel is done.

User Response: When possible, complete the action. For utilities it may be necessary to cancel the job. The jobname may be obtained by issuing a Display Status command. If this is an enter, drain the proper CAP.

SLS2502I HSC Initializing with a cold start because the release levels of the previous and current HSCs are different

Explanation: HSC initialization determined that the HSC subsystem that was previously active was at a different release level than the present HSC. An internal cold start is invoked to ensure that all in-memory data structures, etc. are compatible with this HSC release.

System Action: HSC initialization continues.

User Response: None.

SLS2526I Reconfiguration function did not run successfully -- Component=MMMMMMMM, RC= XXXXXXXX

Explanation: An attempt was made to run the reconfiguration function; however, an error occurred which prevented the reconfiguration function from running successfully. Component is the name of the HSC component that failed. RC is the return code from that operation.

System Action: The reconfiguration function terminates processing.

User Response: Check the return code associated with the named component. If you are unable to ascertain the proper corrective measures, contact StorageTek Software Support.

SLS2528I Reconfiguration function has skipped the copy to the new secondary CDS.

Explanation: The secondary CDS was undefined, so the copy of the new primary to the new secondary was skipped.

System Action: The reconfiguration function continues processing, and a condition code 4 is set.

User Response: The installation may use a utility such as IEBGENER to copy the primary control data set to the secondary and/or standby control data set if they intend to use a shadow copy.

SLS2550I LLLLLLLL keyword value must be enclosed in double parentheses.

Explanation: The value specified for the LLLLLLLL keyword must be enclosed in a set of double parentheses as required.

System Action: The LIBGEN assembly terminates with a condition code of 12.

User Response: Insert parentheses where necessary, keeping sets balanced, and resubmit the LIBGEN assembly.

- SLS2557I** Door type of *dddd* not valid on this lsm type
- Explanation:** An invalid door has been specified on a SLILSM macro. The LSM type defined by the SLILSM macro does not support a *dddd* door.
- System Action:** Processing continues. A return code of 0C is set.
- User Response:** Correct the error, and resubmit the LIBGEN assembly.
- SLS2559I** Passthru parameter *N* of WolfCreek LSM *LLLLLLLLL1* must be "MASTER" for connection to adjacent *MMMM* LSM *LLLLLLLLL2*
- Explanation:** The *Nth* passthru parameter specified for the WolfCreek LSM at label *LLLLLLLLL1* was defined as a "slave" and the adjacent LSM is the standard (4410) or Powderhorn (9310) LSM at label *LLLLLLLLL2*. The WolfCreek LSM must always be the "master" when it is to be connected via PTP to a standard or Powderhorn LSM.
- System Action:** The LIBGEN assembly terminates with a condition code of 12.
- User Response:** Redefine the passthru relationship between the WolfCreek and the standard/Powderhorn LSMs, and resubmit the LIBGEN assembly.
- SLS2580E** Insufficient space was allocated for the control data set; the number of blocks required is *DDDDD*
- Explanation:** During database creation, SLICDATA determined that the space allocated for the CDS data set was insufficient for the LIBGEN definition being used.
- System Action:** SLICREAT terminates.
- User Response:** Reallocate the data set with the appropriate amount of space.
- SLS2581A** No scratch volumes exist for device address *DDDD* recording technique *RRRRRRRR*; enter a scratch volser or I to Ignore
- Explanation:** While executing the SLIEXERS utility, it was determined that no scratch tapes exist that match the recording technique (*RRRRRRRR*) of the device identified (*DDDD*).
- System Action:** SLIEXERS waits for an operator response.
- User Response:** Respond with a six digit volser that can be used as a scratch tape, or respond with I to ignore exercising device *DDDD*.

SLS2582I The HSC is not at FULL service level

Explanation: An attempt was made to run a given utility, but the HSC was not at the correct level.

System Action: The utility terminates.

User Response: Bring the HSC up to the FULL service level, and rerun the utility.

SLS2583I Device address *DDDD* was Ignored|Verified|Not Available

Explanation: Unit *DDDD* was either ignored because no scratch tapes were available, verified by the SLIEXERS utility, or not available to the SLIEXERS utility.

System Action: The utility continues.

User Response: None.

SLS2584I Error locating or attempting to use volser *vvvvvv*; Please enter another volser

Explanation: The SLIEXERS utility was unable to locate the specified volser (*vvvvvv*) in the ACS, or the media type of the volume was not valid for the tape drive.

System Action: Message SLS2581A is displayed.

User Response: Respond as indicated in message SLS2581A.

SLS2585E Module is not APF authorized

Explanation: The SLIEXERS utility must be executed from an APF authorized library.

System Action: The utility stops processing.

User Response: Execute the SLIEXERS utility from an APF authorized library.

SLS2586E HOSTid CCCCCCCC; Device number XXXX is a duplicate

Explanation: A comparison was made between all transports associated with HOSTid (CCCCCCCC). Device number XXXX was found to be duplicated for this host.

System Action: Processing continues.

User Response: Confirm which XXXX device is correct in the LIBGEN and perform one of the following actions:

1. Use LIBGEN and SLICREAT.
 - Change or delete the duplicate device XXXX associated with the incorrect SLIDRIVS macro ADDRESS parameter in the LIBGEN.
 - Assemble the new LIBGEN, and run the SLICREAT utility to recreate the database.
2. Use the Set SLIDRIVS utility to change or delete the duplicate device XXXX within the current database.

SLS2587E Invalid mix of LSM types found in an ACS

Explanation: LSMs that can not be connected via PTP were found in the same ACS.

System Action: Processing continues with RC=58305830

User Response: Rework the LIBGEN to separate the invalid LMS types into separate ACSs. Examples of an invalid LSM mix are:

1. SL3000 libraries must be a single LSM per ACS
2. SL8500 can only be in an ACS with other SL8500's

SLS2610I CCCCCCCC command rejected; unable to activate CAPid AA:LL:CC; CAP {recovery|reserve} unsuccessful

Explanation: An attempt was made to execute an ENter, or Eject command for a specific CAP, but the CAP could not be placed in the requested state.

System Action: The ENter or Eject command is rejected.

User Response: Re-enter the command. If the problem continues and software is suspected, contact the StorageTek Software Support.

SLS2615I - SLS2618I

SLS2615I EJECT subtask failure *XXXX*; EJECT attempting to continue

Explanation: One of the CAP tasks for an Eject command terminated due to an abnormal condition as depicted by return code *XXXX*.

System Action: If other CAPs are still active for this eject then command processing will continue. If the command cannot continue then messages will be issued to display cartridges that were not ejected.

User Response: None.

SLS2616D REPATH requested by EJECT for CAPid *AA:LL:CC*; Reply C to (C)ancel or R to (R)EPATH

Explanation: The CAP task for *AA:LL:CC* ended during an Eject command, and OPTion Repath was set to Reply.

System Action: If other CAPs are still active for this eject, command processing continues. If the command cannot continue, messages will be issued to display cartridges that were not ejected.

User Response: Reply with one of the following:

- C If the Repath is to be cancelled. Messages for cartridges not ejected are issued.
- R If the Repath is to be done. This will transfer cartridges for this CAP to another CAP if one is available. If no other CAP is available, messages for cartridges not ejected are issued.

SLS2617I CAPid *AA:LL:CC* not REPATHed

Explanation: A CAP task ended during an Eject command and Repathing was not done. Repath was either set to No, no CAPs were available for a Repath, or a reply of (C)ancel was given to the Repath option reply message.

System Action: Messages will be issued to display cartridges that were not ejected.

User Response: None.

SLS2618I {ENTER|EJECT} cannot select CAPid *AA:LL:CC*; *CCCCCCCCCCCC*

Explanation: A CAP could not be selected for use by either an ENter or an EJECT command. *CCCCCCCCCCCC* is either the condition of the CAP or an explanation stating that the CAPid has been bypassed.

System Action: If other CAPs are still active for this eject, command processing continues; otherwise, the command ends.

User Response: None.

- SLS2619I** ENTER failed; No free cells in LSM xx:xx
- Explanation:** The ENTER command requested an LSM that did not contain any free cells.
- System Action:** The ENTER command terminates.
- User Response:** Free up cells in the LSM where the volumes are to be entered and re-enter the ENTER command.
- SLS2620I** Unexpected return code XXXXXXXX processing {Volume|CAP} list; EJECT attempting to continue
- Explanation:** During processing of an Eject command an unexpected return code, XXXXXXXX, was detected while processing either a volume or CAP list.
- System Action:** The Eject command will attempt to continue unless no more CAPs are present.
- User Response:** None.
- SLS2621I** EJECT rejected; Number of volumes specified (NNNN), exceeds EJLimit
- Explanation:** The number of cartridges specified exceeds the OPTion EJLimit.
- System Action:** The Eject command terminates.
- User Response:** Reduce the number of cartridges specified or expand the OPTion EJLimit.
- SLS2622I** {CAPPREF} error; {ACS IN PATH OFFLINE| LSM IN PATH OFFLINE|CAP IN PATH OFFLINE|CAP IN PATH INVALID| CARTRIDGE MADE ERRANT}
- Explanation:** An error occurred during execution of the CAPPref command due to one of the following situations:
- ACS IN PATH OFFLINE
 - LSM IN PATH OFFLINE
 - CAP IN PATH OFFLINE
 - CAP IN PATH INVALID
- System Action:** The command is rejected.
- User Response:** Correct the cause of the error and re-issue the CAPPref command.

SLS2623I {CAPPREF} rejected; AUTO CAP services are not available

Explanation: The AUTO CAP service is not available most likely because the CAP specified in the command is a shared resource on a partitioned SL3000 or SL8500 Library or due to a prior abend.

System Action: The command is rejected.

User Response: HSC can continue to run without the AUTO CAP service enabled on the CAP specified.

To restart the AUTO CAP service after an AUTO CAP abend, HSC must be brought down and restarted. If there is a dump from an AUTO CAP abend, save it and contact SUN Microsystems Support.

SLS2624I CAPPREF rejected; preference value not allowed for CAP AA:LL:CC

Explanation: The command attempted to give a CAP preference value to a CAP (AA:LL:CC) that is not eligible to be preferenced (e.g., a PCAP).

System Action: The command is rejected.

User Response: Re-issue the CAPPref command, ensuring that the specified CAP is not a PCAP; or, if the CAPPref command is being issued for a PCAP to change it to AUTO or MANual mode, verify that 0 is specified for the preference value.

SLS2625I CCCCCC1 volser CCCCCC2 CCCCCC3

Explanation:

CCCCCC1	will state either "Cartridge" or "Subpool".
volser	is a cartridge volser, the word "SCRATCH", or a subpool name.
CCCCCC2	is "not EJECTed" when a volser is present and "count depleted" when "SCRATCH" is present.
CCCCCC3	is only displayed when the MEDIA keyword is specified and no scratches exists for it.

System Action: None.

User Response: This message provides an audit trail so you may recapture cartridges for a subsequent Eject by using the JOBLOG or SYSLOG.

SLS2627I {ENTER|DRAIN} command rejected; CAP AA:LL:CC is in AUTO mode

Explanation: The ENter command cannot be issued for a CAP which is in AUTO mode. A DRAin command also is not allowed, unless the AUTO CAP is ejecting.

System Action: The command is rejected.

User Response: AUTO CAPs are unlocked and available for entering except when cartridges are being ejected. Therefore, the ENter command is neither required nor allowed.

An AUTO CAP can be drained only when it is ejecting cartridges. To drain an ejecting CAP, the Eject keyword must follow the CAPid.

Use the CAPPref command to change the CAP mode from AUTO to MANual.

SLS2628E CAP AA:LL:CC task found active for the CCCCCCCC command; awaiting completion of the task

Explanation: CAP AA:LL:CC task for the CCCCCCCC command was found to be active during command termination.

System Action: The command does not complete until the task ends. This message reappears every three minutes until the task ends. This message may be followed by message SLS0031D, asking if you want to DRAIN the tasks or WAIT for them to complete. Once you respond DRAIN, HSC issues additional HSC2628E messages to inform you of tasks in progress every three minutes.

User Response: Take any actions necessary to allow the commands in progress to complete. This may involve opening, emptying, and closing the indicated CAP.

SLS2629I CAPid AA:LL:CC REPATHed

Explanation: One of the CAP tasks for an Eject command ended and Repath was set to ON or Reply and the user responded R to Repath.

System Action: All volumes associated to this CAP have been assigned to a different CAP or CAPs. Processing will continue, however more passthru than normal may occur during this time period.

User Response: None.

SLS2630I CAPPREF command rejected; CAPid AA:LL:CC is already in {AUTO|MANUAL} mode

Explanation: An attempt was made to change a CAP to AUTO or MANual mode when it was already in the requested mode.

System Action: The CAPPref command is rejected.

User Response: None.

SLS2631I {CAPPREF|RELEASE|MODIFY|DRAIN} rejected; *XXX* is not a unique CAPid

Explanation: The command requires a unique CAPid, and *XXX* does not uniquely identify a CAP. If the LSM access door contains the Enhanced CAP feature or the LSM is a WolfCreek, the CAPid must be specified as *AA:LL:CC*. If the LSM access door contains only one CAP, it may be specified as *AA:LL:CC* or just *AA:LL*.

System Action: The command is rejected.

User Response: Reissue the command, ensuring that the CAPid is specified as described above.

SLS2632I CAPPREF for *AA:LL:CC* rejected; cannot specify AUTO/MANUAL when CAP is busy

Explanation: The CAP must be drained on all systems before AUTO or MANual can be specified on the CAPPref command.

System Action: The command is rejected.

User Response: Wait until the CAP is drained on all systems, then re-issue the command. If it is not necessary to specify AUTO or MANual, the command can be re-issued prior to when the CAP is drained.

If the CAP is not active, and the Display Cap command shows that it is idle but scheduled for recovery, then issue the RELease CAP command for that CAP prior to re-issuing the CAPPref command.

SLS2633E UENT Control Block has no paired SRIB Control Block
(*uuuuuuuu;tttttttt;rrrrrrrr*)

Explanation: A UENT (Utility Entry) Control Block was found that did not have a paired SRIB Control Block. The SRIB holds details (e.g. Jobname) of the Utility that was run.

<i>uuuuuuuu</i>	the Address of the UENT Control Block
<i>tttttttt</i>	the UENT Token used to find the paired SRIB Control Block
<i>rrrrrrrr</i>	the Return Code from the SRIB search routine

System Action: The “Display Status” command is terminated.

User Response: At a convenient point, stop and re-start HSC. It may be useful to take a Dump of the Address Space first for later diagnosis.

SLS2636A - SLS2638I

SLS2636A Please enter the *CCCCCCC* command password for
DD

Explanation: User exit 15 has requested password checking for command *CCCCCCC*. The *DD* may state that this request was for a console, a userid, an operator, or the user exit may specify site-specific information.

Explanation: The system waits for a reply. If an incorrect password is entered the command is rejected. Otherwise, processing continues.

User Response: Respond with the correct password. If the password is unknown, contact your security administrator or system programming staff responsible for HSC user exits. Reissue the request after security measures have been corrected.

SLS2637I User Exit SLSUX15 is inoperative; RC= *XX*

Explanation: User exit 15 is inoperative because it returned an invalid return code *XX*.

System Action: Operator commands are not sent to the user exit for processing while the user exit is inoperative.

User Response: Contact the system programming staff responsible for HSC user exits, and have them modify user exit 15 to return a valid return code.

SLS2638I Scratch Summary

LSM *LLL* Subpool *SSSSS* *MMMMM* *RRRRR* *DDDDD*

Explanation: This is the output from the Display SCRatch command. The output produced varies depending on the parameters specified. Summary information may include:

<i>LLL</i>	LSMid
<i>SSSSS</i>	Subpool name
<i>MMMMM</i>	Media Type
<i>RRRRR</i>	Recording Technique for the media
<i>DDDDD</i>	number of scratch tapes

In addition, there may be total lines at the ACS, LSM, and Subpool level, or the text *Nothing to Display* may be shown.

System Action: None.

User Response: None.

SLS2639I {Display THReshld|Display SCRatch|Warn} command failed; Media type CCCCC is used for cleaning cartridges

Explanation: An attempt was made to issue a command for scratch volumes using a media type of CCCCC which can only be used for cleaner cartridges.

System Action: The command is rejected.

User Response: Re-enter the command with a different media type.

SLS2640I Display Status command

Requestor	Action	Element	Volser	Associated
CCCCCCC1	CCCCC2	XXXXX1	volser	CCCCCCCCC3
CAP	queue is	CCCCCCC4		
LMU	queue is	CCCCCCC4		
Utility	queue is	CCCCCCC4		
Mount	queue is	CCCCCCC4		
Total pending mounts:			DDD1	
Total pending dismounts:			DDD1	
Total pending LMU request:			DDD1	
Total utilities active:			DDD1	
Total CAPs active:			DDD1	
End of Status display				

Explanation: This message displays the status of pending requests in the HSC.

CCCCCCC1	the Requestor. This may be from an internal or external source. Internally, Operator is an operator command and Clean depicts an action by the Mount/Dismount process. Externally, system jobnames are used for utilities and normal Mount/Dismounts, or External for a process initiated by a broadcast from another HSC host. Also, PGMI is used for external programmatic interface requests.
CCCCCCC2	the action being performed. Actions include Dismount, Enter, Eject, Modify, Mount, Move, Vary and View.
XXXXXXXX1	the physical element (CAPid, LSMid, ACSid, Station, DRIVEid, or Library).
volser	the volume serial number.

SLS2641I - SLS2643I

CCCCCCC3 the identified ACS object or external host associated with the physical element, *XXXXXXXXI* or action, *CCCCCCC2*.

If any pending requests are found, the current status concerning the processes is given, along with the total pending requests for each.

CCCCCCC4 Process status:
READY|NOT READY|PURGING|RECOVERING

DDDI Total pending requests.

System Action: None.

User Response: None.

SLS2641I {ENTER|EJECT} ended; No CAPs were selected

Explanation: The ENter or Eject command requires that at least one CAP be available for processing.

System Action: The ENter or Eject command processing ends.

User Response: Reissue the command, ensuring that at least one CAPid that is specified is available.

SLS2642I MODIFY command pending; CAPid *AA:LL:CC* reserved to *CCCCCCC*

Explanation: An attempt was made to modify an LSM offline when the LSM still had CAPs active.

System Action: The MODify lsm OFFline command is pended until all CAPs are made inactive.

User Response: Ensure that all the CAPs for the LSM are inactive. If further CAP processing is impossible due to a hardware error, issue the MODify lsm OFFline command with the FORCE keyword.

SLS2643I MODIFY OFFLINE FORCE for LSM *AA:LL* rejected; MODIFY OFFLINE must be tried first

Explanation: An attempt was made to modify an LSM offline with the FORCE option. However, an attempt to modify the LSM offline without the FORCE option was not tried first.

System Action: The MODify lsm OFFline FORCE command is rejected.

User Response: Issue a MODify OFFline command for the LSM first. Do not attempt a MODify lsm OFFline command with the FORCE option until you receive one of the following messages - 1) SLS2644I, which states that the HSC cannot communicate with the LMU, or 2) SLS0017I, which states that the LSM lock is not available. Please note that the MODify lsm OFFline FORCE command will not be rejected if the LSM is already offline.

- SLS2644I** MODIFY command for LSM AA:LL failed; cannot communicate with LMU
- Explanation:** An attempt was made to modify an LSM offline, but the HSC cannot communicate with the LMU.
- System Action:** The MODify lsm OFFline command fails, and the state of the LSM does not change.
- User Response:** If the LSM needs to be placed in manual mode, issue the MODify lsm OFFline command using the FORCE option.
- SLS2645I** Unable to {DRAIN} {CAP} {AA:LL:CC}; {CAP} is in RECOVER processing
- Explanation:** An attempt was made to drain a CAP that is currently in recovery processing. The CAP cannot be drained until the recovery processing is completed.
- System Action:** The DRAin is rejected.
- User Response:** Complete the recovery processing (opening, emptying, and closing the CAP) and then re-issue the DRAin command.
- SLS2646I** Communications lost with LMU station XXXX
- Explanation:** LMU return code from a Vary station command indicates that communication with the LMU station is lost.
- System Action:** The Vary station command fails.
- User Response:** This is probably a hardware error. Contact StorageTek Hardware Support. This message can be normal if the LMU station was varied offline with the FORCE option.
- SLS2647I** {ENTER|EJECT|CAPPREF|RELEASE|MODIFY|DRAIN} command failed; LSM AA:LL is not available
- Explanation:** A CAP related command was executing against LSM AA:LL but it was not online.
- System Action:** The command terminates.
- User Response:** Examine the console log for other HSC messages which might indicate LMU errors or hardware errors. It is likely that the LSM is in an inactive or not-ready status. Correct any hardware errors which are found before attempting to reissue the command.

SLS2648I DFSMS services not available

Explanation: An ALLOC SMSACSR(ON) or SMSMOD(ON) command was issued but DFSMS services are not available or the HSC/DFSMS interface is not activated. This condition can exist if:

- This level of the MVS code does not support DFSMS.
- This level of the HSC code does not support DFSMS.
- The DFSMS address space has not been initialized.
- ALLOC SMSACSR(ON) was not in effect when the ALLOC SMSMOD(ON) was issued.

System Action: One of the following actions may occur:

- If DFSMS services were not available when the ALLOC SMSACSR(ON) was issued, the command terminates.
- If the HSC/DFSMS interface was not enabled when ALLOC SMSMOD(ON) was issued, then SMSMOD(ON) status is saved but does not take effect until ALLOC SMSACSR(ON) is issued.

User Response: Ensure your MVS code and this level of the HSC support DFSMS processing and that the HSC was properly refreshed after introduction of the HSC/DFSMS interface. Ensure the DFSMS subsystem has been activated. Ensure the HSC/DFSMS interface is activated.

SLS2649I Threshold Value Summary:

LSM *LLL* Subpool1 *SSSSS* *MMMMM* *RRRRR* *DDDD1* *DDDD2*

Explanation: This is the output from the Display THReshold command. The output produced varies depending on the parameters specified. Summary information may include:

LLL

LSMid

SSSSS

Subpool name

MMMMM

Media Type

RRRRR

Recording Technique for the media

DDDD1

number of scratch tapes

DDDD2

threshold number of scratch tapes

In addition, there may be total lines at the ACS, LSM, and Subpool level, or the text *Nothing to Display* may be shown.

System Action: None.

User Response: None.

SLS2651I - SLS2654I

SLS2651I ACS AA: Switch aborted, CCC query error for ID *III*, return code *XXXX*

Explanation: A configuration return code *XXXX* other than zero returned for a query of ACS or LSM (*CCC*) records for an id *III*. Below are a list of the possible Configuration return codes:

- 4502 - Invalid Plist
- 4504 - Error reading/writing data base
- 4512 - Subsystem is inactive
- 4522 - ACS identifier is invalid
- 4524 - LSM identifier is invalid
- 453C - Data was invalid
- 453E - Data type not found
- 4556 - Not the FIGMGR move requested
- 4568 - Database release failed
- 456B - No reserve on the CDS
- 456C - No record found
- 456D - Record already selected
- 456E - Insufficient space for output
- 456F - Config manager error

System Action: The SWitch function is aborted.

User Response: Contact StorageTek Software Support.

SLS2654I ACS AA has no requests queued

Explanation: A request was made to display the requests queued to ACSs via the Display Requests command. None were queued to ACS AA.

System Action: Processing continues.

User Response: None.

SLS2656I ACS AA: CCCCCCCC1 CCC CCCCCCCC2 XX1 XX2 XX3

Explanation: A request was made to display the requests queued to ACSs via the Display Requests command. This message describes a single request.

AA is the ACSid.

CCCCCCCC1 is the request type. Requests vary between a change of status, a query of status, and moving from one location to another. The LMU is also used to communicate between hosts for messages that need to be recognized globally. Request types include:

Vary LSM	Mount
Dismount	View
Swap	Move
Reserve CAP	Release CAP
Enter	Eject
Catalog	Read Config.
Read Volser Status	Read LMU Stats
Targeted Msg. Route	Host to Host Brdcst.
Quiesce Host	Read Trans. Carts
Read LSM Status	Read LMU Status
Query Request Status	Cancel
Catalog	Unlock CAP
CAP Status	

CCC is the sequence number of the request.

CCCCCCCC2 describes the status of the request: ACTIVE (sent to the LMU), WAITING (waiting to be sent to the LMU), or TEMP OUT (the request is for a not-ready LSM).

XX1 is the source LSM

XX2 is the destination LSM. This may not be present for all requests.

XX3 is the not ready LSM the request is waiting for. If this is 10, the field has no meaning.

System Action: Processing continues.

User Response: None.

SLS2716I Database Information

Explanation: This message issues a multi-line WTO showing certain database and journal information. An example of the message is shown below.

-SLS2716I Database Information

```

SYSNNNNN = DDD...DDD1
  PRIVOL = volser1 FLAGS(XX) { ACTIVE|INACTIVE|
    HOST-RESERVED|ERROR}
SYSNNNNN = DDD...DDD2
  SECVOL = volser2 FLAGS(XX) { ACTIVE|INACTIVE|
    HOST-RESERVED|ERROR}
SYSNNNNN = DDD...DDD3
  SBYVOL = volser3 FLAGS(XX) { ACTIVE|INACTIVE|
    HOST-RESERVED|ERROR}

JOURNAL1 = DDD...DDD4
JRNVOL = volser4 - CURRENT  NN % FULL
JOURNAL2 = DDD...DDD5
JRNVOL = volser5 -
JOURNAL RECOVERY = (XX) { ABEND|CONTINUE|DISABLED }
  --or--
JOURNALING NOT ACTIVE FOR THIS SUB-SYSTEM

{
RECONFIGURATION IN PROCESS; HOST REFRESH MAP: BBBBBB1 |
A DISASTER/RECOVERY TEST IS ACTIVE |
THIS IS A DISASTER/RECOVERY CDS
}

CDS LEVEL = 0n0n0n    DATE = creation_d
CREATE     = cccid    TIME = creation_t
VSM CDS LEVEL = 1
  --or--
VTCS RECORDS NOT FOUND IN THIS CDS

LAST CDS BACKUP = backup_d backup_t
LAST CDS RESTORE = restore_d restore_t
LAST NCS ON host
  START = ncs_strt_d ncs_strt_t
  END = ncs_end_d ncs_end_t

ENQNAME = qqqqname    - SMFTYPE = DDD
CLEAN PREFIX = cln    - LABTYPE = (XX) {SL|AL|NL|NSL}
RECOVERY = (00) RRRRRRRR - DELETE DISP = (XX) deldisp
THIS HOSTID IS: CCCCCC1 - CDS BLOCK COUNT = nnnnnnn

```

```

HOSTID ---- LEVEL----FLAG---DESCRIPTION
CCCCCCCC2 n.n.n      (XX)  {ACTIVE PRIMARY <SECONDARY
                                     <STANDBY>> |
CCCCCCCC3 -.-.-      (00)  -INACTIVE-}
CCCCCCCC4 5.0.0      (F0)  ACTIVE PRIMARY SECONDARY STANDBY
...
CCCCCCCC5 -.-.-      (00)  -INACTIVE-

```

Database Information End

where:

```

DDD...DDDn (44) data set name
volser      (6) volume serial number
XX          (2) hexadecimal flags
BBBBBBBB1  (16) a bit map when a Reconfiguration process is active corresponding to
              the host list at the end of the display showing if a host needs a
              Configuration Refresh (1) or not (0)
qqqqname   (8) ENQ name used when reserving this database
DDD        (3) SMFTYPE
cln        (3) volser prefix for cleaning cartridges
RRRRRRRR  (8) recovery characteristics {NEITHER|JOURNAL|SECONDARY
                                         BOTH |ALL}
deldisp    (10) delete disposition {SCRATCH|NONSCRATCH|ASCRTCH|VSCRATCH}
CCCCCCCn  (8) host name
nnnnnn    (10) number of 4096-bytes in current CDS
0n0n0n    (8) HSC level in CDS (e.g. 020100)
n.n.n     (5) HSC level (e.g. 2.1.0, 4.1.0, 5.0.0)
creation_d (8) Date CDS created (yyyymmdd)
creation_t (8) Time CDS created (hh:mm:ss)
cccid     (8) Change ID for SLICREAT program
1         (1) VSM CDS Level (A, B, C, D, E or F)
           Or, VTCS not installed or not configured
backup_d  (8) Date of last CDS backup (yyyymmdd)
backup_t  (8) Time of last CDS backup (hh:mm:ss)
restore_d (8) Date when CDS restored (yyyymmdd)
restore_t (8) Time when CDS restored (hh:mm:ss)
ncs_strt_d (8) Date when last configuration change began
           (yyyymmdd)
ncs_strt_t (8) Time when last configuration change began
           (hh:mm:ss)
ncs_end_d (8) Date when last configuration change ended
           (yyyymmdd)
ncs_end_t (8) Time when last configuration change ended
           (hh:mm:ss)

```

System Action: None. This is an informational message only.

User Response: None.

SLS2740I CDS Directory recovery operation successful

Explanation: The database directory was successfully re-built.

System Action: None. This is an informational message only.

User Response: None. This is an informational message only.

SLS2741E Journals specified but not allocated; RC=XXXXXXXX

Explanation: This message is normally produced when Journaling is specified in the LIBGEN but no JRNDEF statement is specified in the startup PARMLIB.

It can also result from allocation errors, in which case earlier console messages explain the error.

System Action: HSC terminates.

User Response: If the error was the result of a missing JRNDEF, add the necessary statement to PARMLIB. If it was the result of an allocation failure, correct the problem causing allocation to fail.

SLS2742E Unexpected return code *NNNN* on *DB access request* in *module*;
resulting action

Explanation: An unexpected return code was received from the database access request specified in the module listed. Database access requests include:

DBOPEN

Open a database thread

DBCLOSE

Close a database thread

DBREAD for subfile subfile-id

Read a database record in the specified subfile

DBWRITE for subfile subfile-id

Write a database record in the specified subfile

DBQSF for subfile subfile-id

Query the attributes of the specified subfile

The resulting action describes how processing continues.

System Action: HSC processing continues, as described in *resulting action*.

User Response: Contact StorageTek Software Support.

SLS2850I Errant recovery of *volser* - Volume may be within LSM AA:LL

Explanation: Errant recovery could not locate an errant volume. Indications for this volume suggest that it may be within an LSM that is not performing automated operations.

System Action: Errant recovery processing continues.

User Response: If the LSM will be returning to an automated condition soon, the user may want to reply "Ignore" to any subsequent user prompts for errant recovery regarding this volume. Once automatic operations are restored and errant recovery is invoked for this LSM, the volume should be recovered or another prompt for this volume will occur. If the LSM will be disabled for a long time, the user may want to check the playground, passthru ports and hands within the LSM in question in order to locate the volume prior to logically ejecting it from the control data set.

SLS2901D Mount of *volser1* on {drive XXXX|driveid AA:LL:PP:NN} - *volser* different (*volser2*); reply Retry, Bypass, Eject, or Ignore (R,B,E,I)

Explanation: An attempt was made to mount volume *volser1* on transport XXXX|AA:LL:PP:NN, but the LMU found a volume with a different external label of *volser2*.

System Action: The mount waits until you reply either Retry, Bypass, Eject, or Ignore.

User Response: Reply with one of the following:

- | | |
|---|---|
| R | If the mount is to be retried, reply R. |
| B | If the mount is to be retried and the volume is to be marked as having an unreadable external label, reply B. |
| E | If the volume is to be ejected, reply E. Volume <i>volser</i> will be deleted from the control data set. |
| I | If the mount is to be ignored, reply I. |

SLS2905D All cleaners {drive XXXX|driveid AA:LL:PP:NN} ACS AA over-use; reply "I"gnore, "T,cap,volser"=Temp enter, "R"etry, "U"se over-limit

Explanation: All cleaning cartridges compatible with the drive in ACS AA are over-use (over-limit or over-limit and spent).

Over-limit cleaning cartridges have a select count greater than MAXclean. Spent cleaning cartridges have exhausted their cleaning material.



Note: Different types of transports require different cleaning cartridge media types.

System Action: Mount waits for a reply. If no response is received within 5 minutes, the default action of "Use an over-limit cleaning cartridge" will be selected.

User Response: Reply with one of the following:

- | | |
|----------------|---|
| I | Ignore the mount request. Cleaning will no longer be scheduled for this transport. |
| T,capid,volser | Temporarily enter the specified cleaning cartridge from the specified CAP to clean the drive. (Note: The volser of the cleaning cartridge temporarily entered does not have to start with the cleaning prefix.) |
| R | Retry the cleaner lookup (presumably after entering some cleaning cartridges). |
| U | Use an over-limit cleaning cartridge. |



Warning: Over-limit cleaning cartridges should be ejected from the ACS and replaced with new cleaning cartridges compatible with the transport. See "Tape Transport Cleaning" in the "Mount/Dismount Functions" section of the *HSC System Programmer's Guide*.

SLS2911D Mount of volser on {drive XXXX|driveid AA:LL:PP:NN} - manual volume at AA:LL:PP:RR:CC; reply Mount or Ignore (M/I)

Explanation: A request was made to mount a volume from a manual LSM.

System Action: The mount waits until you reply M or I, or modify the LSM online.

User Response: If no reply is given and the LSM is modified online, the mount proceeds normally.

If the volume is to be manually mounted, reply M and the message will be DOMed. Remove the cartridge from location AA:LL:PP:RR:CC as displayed on the transport and mount it.

If the request is to be ignored, reply I.

SLS2912I - SLS2916I

SLS2912I Dismount of fixed volume *volser*; volume displaced from manual LSM cell *AA:LL:PP:RR:CC* to cell *AA:LL:PP:RR:CC*

Explanation: A volume *volser* was in a fixed cell because MNTD Float was set to off. Between the time of the mount and the subsequent dismount, the LSM to which the volume is assigned went offline.

System Action: Volume *volser* is retained in an online, automatic LSM.

User Response: None.

SLS2914I Display of drives complete

Explanation: The display of HSC-controlled drives, requested by the Display DRives command, has ended.

System Action: The Display DRives command terminates.

User Response: None.

SLS2915I Nothing to display

Explanation: The display of HSC-controlled drives, requested by the Display DRives command, has ended. No drive activity was found by this function.

System Action: The Display DRives command terminates.

User Response: None.

SLS2916I Drive *XXXX*|Driveid *AA:LL:PP:NN*} < *volser CCCCCCCC* >

Explanation: In response to a Display DRives command, the status of the drive is displayed. The volume *volser* and status (*CCCCCCCC*) is displayed when one of the following status values is true: (Dismount; Mounting; On drive, UNKNOWN).

If MEDia or RECtech parameters are specified, the drives displayed are only those that meet this specification.

System Action: None.

User Response: None.

SLS2918I Found *DDD1* {over-use|over-limit|spent} cleaning cartridges in ACS *AA*; searched *DD2* LSMs for cleaner compatible with {drive *XXXX*|driveid *AA:LL:PP:NN*}

Explanation: HSC found *DDD1* over-use cleaning cartridges in ACS *AA* while searching *DD2* LSMs for a cleaning cartridge compatible with the drive. (Over-limit cleaning cartridges have a select count that is over the applicable MAXclean value. Spent cleaning cartridges have exhausted their cleaning material. Over-use cleaning cartridges are either over-limit or spent.)



Note: (There are at least *DDD1* over-use, over-limit or spent cleaning cartridges compatible with the drive in the *DD2* LSMs searched. However, there may be more over-use cleaning cartridges in the ACS if a compatible cleaning cartridge has been selected to clean the transport.)

System Action: The drive cleaning process continues.

User Response: No immediate action is necessary.



Warning: Over-use cleaning cartridges should be ejected from the ACS and replaced with new cleaning cartridges compatible with the transport(s). See “Tape Transport Cleaning” in the “Mount/Dismount Functions” section of “Chapter 2 - HSC Functions” of the *HSC System Programmers Guide*.

SLS2919D Cleaning cartridge *volser* select count *DDD* is greater than MAXclean; reply "E" to Eject or "K" to Keep cleaner

Explanation: The cleaning cartridge *volser* has select count *DDD* that is greater than the applicable MAXclean value. (See “Automated Tape Transport Cleaning” in the “Mount/Dismount Functions” section of the *HSC System Programmer's Guide*.) This message is issued after the drive has been cleaned, before it is dismounted.

System Action: The dismount of the cleaning cartridge *volser* waits for the reply. If no response is received within 5 minutes, the default action of Keep the over-use-limit cleaning cartridge will be selected.

User Response: Reply with one of the following:

- | | |
|---|---|
| E | Eject the cleaning cartridge from the ACS when the cartridge is dismounted. |
| K | Keep the cleaning cartridge in the ACS when it is dismounted. CAP to satisfy the mount. |



Warning: Over-use-limit cleaning cartridges should be ejected from the ACS and replaced with new cleaning cartridges compatible with the transport.

SLS2920I Cleaning cartridge *volser* has select count *DDD* which is greater than MAXclean; cartridge kept in ACS AA

Explanation: The cleaning cartridge specified has a select count of *DDD*, which is greater than the applicable MAXclean value. This message is issued when the HSC has been directed to keep an over-use-limit cleaning cartridge in the ACS. The message is issued prior to dismounting the cartridge. (See “Automated Tape Transport Cleaning” in the “Mount/Dismount Functions” section of the *HSC System Programmer's Guide* for additional details.)

System Action: HSC continues with the dismount of this cartridge.

User Response: No immediate action is necessary.

Over-use-limit cleaning cartridges should be ejected from the ACS and replaced with new cleaning cartridges compatible with the transport.

SLS2934 (...message text...)

Explanation: Generally, a specified value is invalid or an incompatibility exists between volume, unit, media, and/or recording technique information for a request. The *message text* can be one of the following:

Mount rejected - cleaning cartridge is not a scratch volume

A cleaning cartridge cannot be used to satisfy a scratch mount request

Mount rejected - VOLATTR media type for specified volume is incompatible with unit

The media type of the specified volume, as defined by a VOLATTR statement, is incompatible with the media capabilities of the unit

Mount rejected - VAR media type for specified volume is incompatible with unit

The media type of the specified volume, as defined by a Volume Attribute Record in the CDS, is incompatible with the media capabilities of the unit

System Action: The mount of the specified volume is rejected and the original action message is re-issued to request a new volume.

User Response: Reply to the action message and specify a volume that is compatible with the media capabilities of the unit.

SLS2962I Mount of *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*} - media type changed from *MM1* to *MM2*

Explanation: The initial attempt to mount volume *volser* on transport *XXXX|AA:LL:PP:NN* failed with a media miscompare error.

A media miscompare error occurs when the HSC-supplied media type to be verified (*MM1*) did not match the media type read by the vision system (*MM2*). The LMU reports the mismatch to the HSC as a media miscompare error. Media miscompare errors occur only when the HSC requests the LMU to perform media verification.

System Action: The media type for the volume in the Control Data Set (CDS) is changed to the media type read by the vision system. The mount is retried, but media verification is bypassed.

This message is issued only when media verification is in effect, so it is not issued again for this mount request. Other messages will subsequently indicate if the mount was completed successfully, or encountered additional problems.

User Response: If *MM1* and *MM2* are the same, a hardware problem with the LMU or vision system may exist. Otherwise, no response is necessary.

SLS2964E {Drive *XXXX*|Driveid *AA:LL:PP:NN*} and volume *volser* are incompatible - request rejected {before|after} the mount was attempted

Explanation: An incompatibility was detected between the media and recording technique capabilities of transport {*XXXX|AA:LL:PP:NN*} and volume *volser* before or after the mount was attempted.

System Action: The mount is rejected. The job waits for the volume to be mounted, but this is impossible because the cartridge can never be physically mounted on the allocated device.

User Response: Cancel the job, correct the JCL, definition statements (VOLATTR, UNITATTR, TAPEREQ), and/or SMS routines, and rerun the job.

SLS2972I Volume *volser* not *CCCCCCCC*; No {CAPs|LSMs} were available in ACS *AA*

Explanation: Volume *volser* was either not pathed or not ejected because all CAPs or LSMs were unavailable in ACS *AA*.

System Action: Processing for other volumes continues.

User Response: Supply an online LSM or CAP within the ACS to satisfy the request.

SLS2973I - SLS2979I

SLS2973I Volume *volser* not CCCCCCCC; Volume not in the library.

Explanation: Volume *volser* does not reside within any LSM.

System Action: The volume is not ejected.

User Response: No response.

SLS2974I Audit of LSM *AA:LL* is recommended

Explanation: A MOVE command or utility detected an error either in the source or target location. Additional messages should precede this one to let you know the exact nature of the error.

System Action: The MOVE for that cartridge fails.

User Response: As a result of the error, an audit of the specified LSM is recommended, at least for the location in error, if not a full audit of the LSM.

SLS2976I MOVE incomplete; Volume *volser* stuck in LSM *AA:LL* {HAND *N*|PANEL *NN*
DRIVE *NN*|PTP PANEL *NN*}

Explanation: The MOVE of a volume was incomplete because of a hardware interruption of an LSM. The location of the volume is displayed.

System Action: None.

User Response: If you did not reply Delete to the previous SLS0854D message for this volume, you may use the Eject command to remove it. When you receive the SLS0854D, reply Delete. This will remove the volume from the CDS. Afterwards, manually remove the volume from the specified location and use the ENTER command to insert it into an LSM.

SLS2977I Panel index *DD* is invalid

Explanation: The target panel *DD*, of a MOVE request, is greater than the number of panels available in the LSM.

System Action: The MOVE function terminates processing.

User Response: Specify a Panel index that is within the range of the LSM.

SLS2979I User Exit SLSUX14 is inoperative; RC = *XX*

Explanation: The volume access user exit, SLSUX14, is inoperative because an invalid return code was returned.

System Action: User exit 14 is disabled.

User Response: Correct the user exit so that it returns a valid return code.

SLS2980I Access to volume *volser* denied for *CCCCCCC* processing for
DD

Explanation: User exit 14 returned access denied for volume *volser* during a *CCCCCCC* process. This process may be Mount or Eject. The
DD may state that this request was for a job name, a userid, an operator or the user exit may specify site specific information.

System Action: The Mount or Eject request ends without allowing the function to proceed.

User Response: Make sure the correct user exit is loaded and, if so, contact your security administrator or system programming staff responsible for HSC user exits for assistance. Site-specific information should be detailed by site procedures. Re-issue the request after security measures have been corrected.

SLS2984D *volser* on {drive *XXXX*|driveid *AA:LL:PP:NN*}; shortage *AA*; *MMMMMMMM*;
RRRRRRRR; *SSSSSSSS*; reply I / T,capid,vol / R / M,vol

Explanation: There were no volumes found in ACS *AA* to satisfy a scratch mount for the requested media, recording technique, and/or subpool.

<i>AA</i>	the ACS number
<i>MMMMMMMM</i>	the media type
<i>RRRRRRRR</i>	the recording technique
<i>SSSSSSSS</i>	the subpool name. If the subpool name is "SUBPOOL 0", either scratch subpooling is not in effect, or scratch subpooling is in effect but no subpool was specified for the request.

System Action: The Mount waits for you to reply I; T,capid,vol; R; or M,vol.

User Response: Reply with one of the following:

I (Ignore)

Ignore the Mount request. The HSC leaves the mount pending.

T,capid,vol (Temporarily enter)

Temporary enter (the specified volume) from the specified CAP and SUBpool to satisfy the mount.

R (Retry)

Retry the scratch lookup (after replenishing the subpool scratch list).

M,vol (Mount)

Mount the specified volume to satisfy the request.

SLS4002I CCCCCCCC CAP AA:LL:CC failed. CAP is unallocated.

Explanation: The CCCCCCCC command requested an unallocated CAP.

System Action: The command terminates.

User Response: Determine why the CAP is unallocated. Once the problem is corrected, modify the CAP online and re-enter the failing CCCCCCCC command.

SLS4011I Invalid ID XXXXXX entered for DISPLAY CAP

Explanation: An invalid ID was specified. XXXXXX is the ID entered. The ID must specify a valid ACSid, LSMid, or CAPid.

System Action: None.

User Response: Re-enter the Display Cap command, specifying a valid ID.

SLS4068I Current TRACE LKP Status:

TAPEREQ	{Traced NOT Traced}
UNITATTR	{Traced NOT Traced}
VOLATTR	{Traced NOT Traced}
LMUPATH	{Traced NOT Traced}
MVCPool	{Traced NOT Traced}
MGMTCLAS	{Traced NOT Traced}
STORCLAS	{Traced NOT Traced}
LKEYINFO	{Traced NOT Traced}
LOOKFAIL	{Traced NOT Traced}

Explanation: The TRACE LKP command successfully completed. A list of LOOKUP tables and their tracing status is displayed.

System Action: HSC processing continues.

User Response: None.

SLS4075I Spent cleaning cartridge volser did not clean {drive XXXX|driveid AA:LL:PP:NN}; cartridge {returned to home cell|left mounted|errant}

Explanation: The cleaning cartridge volser did not clean the drive because its cleaning material has been exhausted (spent).

System Action: The LMU returns the spent cleaning cartridge to its source. If it cannot do so, the volume becomes errant. In the event of a mount failure, the cartridge is left mounted and the HSC attempts to eject it.

User Response: Spent cleaning cartridges should be ejected from the ACS and replaced with new cleaning cartridges compatible with the transport(s). See "Tape Transport Cleaning" in the "Mount/Dismount Functions" section of the *HSC System Programmers Guide*.

SLS4076I - SLS4080D

SLS4076I Special use action by cartridge *volser* failed on {drive *XXXX*|driveid *AA:LL:PP:NN*}; cartridge {returned to home cell|left mounted|errant}

Explanation: A special use cartridge has been mounted on the indicated drive, but the requested action failed. Special use cartridges include 9840 microcode update and 9840 dump collection cartridges.

System Action: The LMU returns the special use cartridge to its home cell. If it cannot do so, the volume becomes errant. In the event of a mount failure, the cartridge is left mounted and the HSC attempts to eject it.

User Response: If the cartridge is left mounted, dismount it. Eject the special use cartridge. If it is a 9840 dump collection cartridge, there may be no dumps to collect. If it is a 9840 microcode update cartridge, contact your StorageTek CSE to determine the action required.

SLS4077E Cleaning cartridge *volser* with select count *DDD* is {over-limit|spent}; cartridge ejected from ACS *AA*

Explanation: The cleaning cartridge specified has a select count of *DDD*. The cleaning cartridge is over-limit (its use count is found to be greater than the applicable MAXclean value) or spent (the cleaning material has been exhausted). This message is issued when the HSC has been directed to eject an over-limit or spent cleaning cartridge in the ACS. The message is issued prior to dismounting and ejecting the cartridge.

System Action: The HSC continues with the dismount and ejection of the cartridge.

User Response: Remove the cartridge when the message to empty the CAP is received. See "Tape Transport Cleaning" in the "Mount/Dismount Functions" section of the *HSC System Programmer's Guide*.

SLS4080D Requested {drive *XXXX*|driveid *AA:LL:PP:NN*} reserved by host CCCCCCCC; reply Ignore or Retry (I,R)

Explanation: The HSC attempted to reserve a drive for mount or dismount. Another host has reserved the drive.

System Action: The HSC waits for the host to release the drive or for your response to this message.

User Response: Reply with one of the following:

I (Ignore)

To cancel the mount/dismount request.

R (Retry)

To attempt to reserve the drive.

Use the HSC RECover *host-id* command to recover a host that is no longer active to clear up its drive reserves.

SLS4081E Dismount of cartridge *volser1* from {drive *XXXX*|driveid *AA:LL:PP:NN*}; found *volser2* in home cell *AA:LL:PP:RR:CC*

Explanation: If *volser1* and *volser2* have the same volume serial, a duplicate volume may be present in the library, or two concurrent dismount requests may have been processed by the LMU. If *volser1* and *volser2* have different volume serials, another volume is in the home cell of *volser1*.

System Action: If *volser1* and *volser2* have the same volume serial, a cell scan of the drive is performed to determine whether a duplicate volume is in the ACS. If *volser1* is not equal to *volser2* then a new home cell is acquired for *volser1*.

User Response: An audit of the home cell location *AA:LL:PP:RR:CC* may be required to locate *volser2* and insert it into the CDS.

SLS4082I Dismount of cartridge *volser1* from {drive *XXXX*|driveid *AA:LL:PP:NN*}; expected *volser2*; drive found loaded

Explanation: The HSC attempted to dismount volume *volser1* from a drive but the drive is loaded. The drive status information indicates that *volser2* is mounted on the drive. Either a different physical volume *volser1* is on the drive, or the internal volume serial *volser1* does not match the external volume serial *volser2*.

System Action: The HSC continues processing.

User Response: If the volume on the drive should be dismounted, issue the MVS UNLOAD command and then issue the HSC DISMount command.

SLS4083I Dismount of cartridge *volser1* from {drive *XXXX*|driveid *AA:LL:PP:NN*}; volume location information is incorrect; volume deleted from database

Explanation: The HSC attempted to dismount volume *volser1*. The volume status information indicates the volume is errant, but the HSC failed to locate the volume.

System Action: The HSC deletes the volume from the database.

User Response: If the volume is not found on the drive and is believed to be in the library, run the audit utility.

SLS4084D - SLS4086I

SLS4084D Swap of volume to same {drive XXXX|driveid AA:LL:PP:NN}; reply "S", "C", or "I" to Swap, Clean, or Ignore

Explanation: A swap operation specified the same drive that the volume is mounted on.

System Action: The HSC waits for a response to this message.

User Response: Reply with one of the following:

S (Swap)

To dismount the volume and remount to the same drive.

C (Clean)

To dismount the volume, mount a cleaner cartridge, and remount the volume when the cleaning is complete.

I (Ignore)

To cancel the swap request.

SLS4085I Swap of *volser* on {drive XXXX|driveid AA:LL:PP:NN} - Volume not on drive

Explanation: The HSC attempted to dismount volume *volser* from a drive, but either the drive is empty or a different cartridge is mounted.

System Action: The swap operation fails.

User Response: If the swap operation is required, use HSC commands to perform the swap operation. First, issue the HSC DISMount command to remove the current volume from the drive. Then, issue the HSC Mount command to mount the volume on the new drive.

SLS4086I {Mount|Dismount} of *volser* {on|from} {drive XXXX|driveid AA:LL:PP:NN} sent to HSC

Explanation: This message is returned to SMC when a dismount or non-MVS mount is queued for processing by HSC.

System Action: None. The requested dismount or mount will be processed by HSC. No error messages from the operation are returned to SMC.

User Response: None.

SLS4087I Dismount request for {drive XXXX|driveid AA:LL:PP:NN} - found {drive reserved|drive loaded on scan|drive loaded on dismount}; request terminated

Explanation: The HSC was unable to complete a dismount operation requested from SMC because of the condition indicated in the message.

System Action: The dismount request is terminated. If the next mount for the drive is an MVS mount requested by SMC, the drive will be unloaded or the system will wait until the drive is no longer reserved. If the next mount for the drive is a non-MVS mount (for example, an RTD mount), WTOR messages will be issued to wait or force the drive unload.

User Response: None.

SLS4088I Duplicate volser *volser* in cell AA:LL:PP:RR:CC and on {drive XXXX|driveid AA:LL:PP:NN}; ejecting volume on drive

Explanation: This message is displayed when the same volume serial is found both in the volume's home cell and on the drive during a dismount.

System Action: The volume on the drive will be ejected from the ACS, and the volume serial will be removed from the CDS.

User Response: Audit the cell shown in the message to re-add the volume to the CDS.

SLS4150I Number of drives per panel cannot be changed with FORHOST

Explanation: The number of drives specified on a SET SLIDRIVS utility control statement does not match the current number of drives defined for the panel. This SET SLIDRIVS statement included the FORHOST parameter. Changing the number of drives on a panel for only one host is not supported.

System Action: The control statement is ignored. A return code of 8 is set.

User Response: Correct the number of drives on the SET SLIDRIVS statement to agree with the existing value, or remove the FORHOST parameter from the statement to change the number of drives for all hosts, and resubmit the SLUADMIN utility job.

SLS4151I HSC Parmlib not accessible, data reported may be incorrect

Explanation: The HSC Parmlib is not accessible, and data reported may be incomplete or incorrect. The Parmlib may be identified by the SLSSCRPL DD statement or accessed by the active HSC on this host.

System Action: The utility continues processing. Scratch subpool totals will not be produced and scratch subpool IDs will not be reported for volumes. Because the global maximum cleaning limit cannot be determined, cleaning cartridges over the maximum usage limit are not reported.

User Response: Identify the HSC Parmlib via the SLSSCRPL DD statement or by running the utility on a host with an active HSC that accesses the correct Parmlib.

SLS4152I - SLS4155I

SLS4152I Panel must be empty to use SET SLIDRIVS to change cell geometry

Explanation: The SET SLIDRIVS utility control statement cannot be used to change one type of drive panel to another unless the two panels have the same cell geometry or the panel being changed is empty.

System Action: The utility control statement is ignored. A return code of 8 is set.

User Response: Either (1) resubmit the job, changing the number of drives defined for the panel, or (2) set MNTD Float(OFF) and do not enter volumes into the LSM, then use the MOVE or EJECT command or utility to remove all volumes from the panel and then resubmit the job.

SLS4153I New CDSLVL not allowed

Explanation: The SET CDSLVL can only be used to REGRESS a CDS one level or to CONVERT a CDS one level. For example, a CDS at level 2.0.0 can be converted to 2.1.0, or a CDS at level 2.1.0 can be regressed to 2.0.0.

System Action: The utility control statement is ignored. A return code of 8 is set.

User Response: Determine the current CDS level. If the current level is 2.0.0, the CDS can be converted to 2.1.0. If the current level is 2.1.0, the CDS can only be regressed to 2.0.0. If the CDS is at a level prior to 2.0.0, the utility is not supported.

SLS4154I SET CDSLVL REGRESS is not allowed; host CCCCCCCC marked as active

Explanation: The SET CDSLVL REGRESS utility cannot be executed while the HSC is marked as active on any host.

System Action: The utility control statement is ignored. A return code of 8 is set.

User Response: Stop or recover HSC on all hosts and resubmit the job.

SLS4155I SET CDSLVL CONVERT requires all active hosts to have coexistence PTFs applied

Explanation: The SET CDSLVL CONVERT utility requires that all active hosts must be executing HSC 2.0.1 with the PTF(s) for HSC 2.1 coexistence applied.

System Action: The utility control statement is ignored. A return code of 8 is set.

User Response: Bring all hosts to the required HSC maintenance level and resubmit the job.

SLS4156I SET CDSLVL REGRESS failed; invalid LSM or panel type found in CDS

Explanation: The SET CDSLVL REGRESS utility attempted to regress a CDS to an earlier CDS level. However, an LSM or panel type was defined in the CDS which is not supported at the earlier CDS level.

For example, 9740 LSMs and drive panels configured for 20 drives are not supported at CDS level 2.0.0. Thus a 2.1.0 level CDS which includes 9740 LSMs or 20 drive panels cannot be regressed to CDS level 2.0.0.

System Action: The utility control statement is ignored. A return code of 8 is set.

User Response: All LSMs which are not supported at the earlier CDS level must be removed from the library configuration before the CDS can be regressed to the earlier CDS level. The LIBGEN, SLICREAT, and RECONFIG processes can be used to remove the LSMs from the library configuration. Then the CDS can be regressed to an earlier CDS level.

SLS4157I SET SLIDRIVS requires host CCCCCCCC down or LSM AA:LL offline

Explanation: The SET SLIDRIVS utility requires that all affected hosts be down or the LSM offline to change existing drives or panel type.

System Action: The utility control statement is ignored. A return code of 8 is set.

User Response: Bring down all affected hosts or modify the LSM offline, and resubmit the SET SLIDRIVS utility.

SLS4158I HOST CCCCCCCC LSM(AA:LL) PANEL(PP) drive unit addresses changed:

From: XXXX, XXXX, XXXX, XXXX ...
 XXXX, ...
 To: XXXX, XXXX, XXXX, XXXX ...
 XXXX, ...

Explanation: The SET SLIDRIVS command has changed unit addresses for a host.

System Action: None.

User Response: None.

SLS4159I WARNING: REGRESS with HSC 2.1 created CDS

Explanation: The CDS was created with HSC 2.1 SLICREAT.

System Action: Regress of CDS continues, but the CDS may be incompatible with some utilities and may cause unpredictable results.

User Response: The regressed CDS should be run through RECONFIG. Create new HSC 2.0 CDSs and specify them in the RECONFIG RECDEF PARMLIB statement; specify the regressed CDS in the CDSDEF PARMLIB statement.

SLS4160I - SLS4163I

SLS4160I Errant volume *VVVVVV* possibly located in drive *AA:LL:PP:NN*

Explanation: During SET CDSLVL REGRESS, the utility discovered an errant volume possibly located in the indicated tape drive. The drive is not one of the first four drives on the panel. Once regressed, the CDS can no longer store the driveid for this drive as a possible errant location, and HSC can no longer check this drive during errant volume recovery.

System Action: The utility removes the indicated drive as a possible errant location and continues. On completion, it exits with a return code of 4.

User Response: When the LSM comes online to an active HSC, errant volume recovery is performed automatically. If the volume remains errant after this attempt, manually check the indicated drive for the errant volume. If found, manually remove the volume from the drive and the library. Eject the volume to logically delete it from the CDS, and re-enter it into the library.

SLS4161I Number of drives is invalid

Explanation: The number of drives defined in the panel is not an allowable value or exceeds the maximum allowed for the LSM type.

System Action: A return code of 8 is set and the utility function terminates.

User Response: Correct the error and resubmit the job.

SLS4162I Panel map not found for panel *PP* in LSM *AA:LL* panel type *TT*

Explanation: The panel cell map for the indicated panel type was not found in the panel map table.

System Action: A return code of 8 is set and the utility function terminates.

User Response: Make sure that the utility is executing with the correct version of the HSC software. If the error persists, contact StorageTek Software Support.

SLS4163I Insufficient space for *CCCCCCC* dataset; number of blocks required is *DDDDD*

Explanation: Processing could not continue against the *CCCCCCC* data set because insufficient space was allocated.

System Action: The program terminates.

User Response: Supply the proper amount of space and resubmit the job.

SLS4164E CDS error - missing {ACS|LSM} for {LSM AA:LL|DRIVEID AA:LL:PP:NN|CAP ID AA:LL:CC}

Explanation: A record was found with a key that does not match any existing ACS/LSM.

System Action: The utility terminates with return code 8. If the error is encountered in SLUDBMAP (LIBGEN), then statements are generated for portions of the library that are not in error.

User Response: Report this condition to StorageTek Software Support. It may be necessary to re-create the CDS using the merge or reconfigure utility.

SLS4196I CDS {converted|regressed} from V.R to V.R format

Explanation: The CDS was converted from an earlier format to a later format, or vice versa. The version and release (V.R) are given for both the earlier and later format of the CDS. The SET CDSLVL CONVERT/REGRESS utility is used to convert or regress the CDS. Conversion of the CDS to a later format may be required when migrating to a later HSC release. During a down-level migration to an earlier HSC release, regressing the CDS to an earlier release is optional.

System Action: None.

User Response: After the CDS has been converted, only HSC subsystems compatible with this CDS format can be started.

SLS4203I DDname CCCCCCCC allocated to dataset name DDD...DD

Explanation: The utility has allocated the DD name noted by CCCCCCCC to the data set name of DDD...DD (a string which may be up to 54 characters, including the member name if the data set is a PDS member). The DD name CCCCCCCC may be one of the following: SLSCNTL, SLSSCRPL, or SLSVA.

The allocation may have been due to the JCL supplied to the utility job, or the allocation may have been dynamic, based on the data sets being used by the HSC active on this host system.

System Action: The utility continues.

User Response: This message is only informational. If the utility fails to produce the expected results, the series of SLS4203I messages should be examined to be sure that the intended data sets were actually the ones allocated to the job.

SLS4204E - SLS4207I

SLS4204E {ACS AA|LSM AA:LL} on MERGE control statement not found in {FROM|TO} CDS

Explanation: A MERGE control statement contains an ACS or LSM that does not exist in the specified CDS.

System Action: The utility continues with the validation process. The merge will not occur. A return code of 8 is set.

User Response: Correct the information and resubmit the utility job. If the TO CDS was just created with the SLICREAT utility, ensure that it contains the correct ACS and LSM information.

SLS4205E LSM AA:LL in MERGE TO CDS is not empty

Explanation: The merge utility has detected that the indicated LSM, which is a destination LSM for the merge, contains one or more volumes in the TO CDS.

System Action: The utility continues with the validation process. The merge will not occur. A return code of 8 is set.

User Response: Verify that the LSM is the intended merge destination. If it is, then EJECT or MOVE all volumes before proceeding with the merge.

SLS4206I LSM AA:LL in FROM CDS is not same type as LSM AA:LL in TO CDS

Explanation: The source and destination LSMs in the CDS merge are not the same LSM type.

System Action: The utility continues. The merge is not performed for this LSM.

If the LSM was requested with a specific FLSM/TLISM parameter statement, then the merge will not occur, and a return code of 8 is set.

If the unmatched LSM is within an ALL or FACS/TACS parameter statement, and the VALIDATE option was not specified, then the merge will occur for other LSMs, and a return code of 4 is set.

User Response: If the FLSM/TLISM parameter was specified for the LSM, correct the statement and resubmit the utility. If the LSM is within a specified ACS or is part of an ALL group, verify that the LSM should be bypassed in the merge process.

SLS4207I Panel PP LSM AA:LL in FROM CDS is not same type as LSM AA:LL in TO CDS

Explanation: The panel type for panel PP is not the same in the merge FROM and TO CDSs.

System Action: The utility continues. Volumes on the unmatched panel are not merged. A return code of 4 is set.

User Response: Verify that the panel is specified correctly in the TO CDS.

SLS4208I LSM AA:LL does not exist in TO CDS

Explanation: There is no LSM AA:LL in the MERGE TO CDS. The merge was specified using either the ALL option or the FACS/TACS control statement.

System Action: The utility continues. Volumes from the indicated LSM will not be merged. A return code of 4 is set.

User Response: Verify that the LSM should be bypassed in the merge process.

SLS4209I Duplicate volume *volser* found in FROM CDS; target location is ACS(AA) LSM(LL) PANEL(PP) ROW(RR) COLUMN(CC)

Explanation: During the merge process, a volume (*volser*) in a merged LSM on the FROM CDS already exists in the TO CDS.

System Action: The utility continues. The merge process will not copy the volume information into the destination LSM of the TO CDS. The existing volume in the TO CDS will be unaffected. A return code of 4 is set.

User Response: Verify that the duplicate volume is processed as intended. Following the merge, execute the AUDIt utility function on all target locations that contained duplicate volumes to eject the duplicates from the LSM.

SLS4210I Volume *volser* found errant during Merge; target home location is ACS(AA) LSM(LL) PANEL(PP) ROW(RR) COLUMN(CC)

Explanation: The merge function encountered an errant volume (*volser*) in the FROM CDS whose home location in the TO CDS will be AA:LL:PP:RR:CC.

System Action: The utility continues. If the VALIDate option was not specified, the errant volume was copied to the TO CDS and marked errant. A return code of 4 is set.

User Response: Perform an audit of the specified cell on the TO CDS after the merge to clear errant status.

SLS4211I Volume *volser* found selected during Merge; target home location is ACS(AA) LSM(LL) PANEL(PP) ROW(RR) COLUMN(CC)

Explanation: The merge function encountered a selected volume (*volser*) in the FROM CDS whose home location in the TO CDS will be AA:LL:PP:RR:CC.

System Action: The utility continues. If the VALIDate option was not specified, the selected volume was copied to the TO CDS and marked unselected. A return code of 4 is set.

User Response: Perform an audit of the specified cell on the TO CDS after the merge to verify the location of the volume.

SLS4212E - SLS4213I

SLS4212E FROM CDS name is the same as TO CDS name

Explanation: The FROM CDS has the same data set name as the primary, shadow, or standby version of the TO CDS.

System Action: The CDS Merge process terminates.

User Response: Correct the name of the file specified as the FROM CDS on the SLUADMIN jobstep.

SLS4213I CDS Merge Phase *N* (CCCCCCCC) completed

Explanation: This is a SLUADMIN MERGEcds utility checkpoint message, indicating that phase *N*, function CCCCCCCC, has completed. Phases are:

Phase 1-Initialization

The merge process has successfully reserved the TO CDS and has allocated, initialized, and reserved the FROM CDS.

Phase 2-Validate Parameters

The merge process has validated all LSMs being merged.

Phase 3-Build Dataspace

The merge process has successfully allocated and populated the dataspace with merged CDS information.

Phase 4-Write Dataspace

The merge process has successfully written the merged data to the primary CDS copy. Phase 4 is bypassed when the VALIDate option is specified.

Phase 5-Cleanup

The merge process has successfully copied the primary CDS to the secondary version (if any), and has completed the termination process.

System Action: After completion of Phases 1 through 4, the merge process continues. After completion of Phase 5, the merge process terminates.

User Response: None.

SLS4214E Creation of CDS Merge utility Data Space failed -
 MMMMMMMM-CC-RRRRRRRR

Explanation: *MMMMMMMM* is the IBM macro call that failed while creating the CDS Merge utility data space. *CC* is the return code describing the failure. *RRRRRRRR* is the reason code describing the failure. Refer to the appropriate IBM documentation for an explanation of the return/reason code.

If the failing macro is DSPSERV with a return code of “08” and a reason code of “xx0005xx”, the size of the data space violates installation criteria (IEFUSI exit).

This indicates that the HSC is not running in Protect Key 1-7. Check the MVS Program Properties Table in the SCHEDxx member of SYS1.PARMLIB for proper specification of the Protect Key for HSC.

System Action: The CDS Merge process terminates.

User Response: Determine the cause of the failure, and resubmit the CDS Merge utility request.

SLS4215E No DD statement(s) found for FROM CDS.

Explanation: A MERGEcds command did not include any DD statements for the FROM CDS.

System Action: The CDS Merge process terminates.

User Response: Supply a DD statement for SLSFCNTL, specifying the FROM CDS. If shadow and/or standby copies are available, supply DD statements (SLSFCTL2/SLSFSTBY) for these files as well. The CDS merge utility will determine the current primary CDS and use it as the FROM CDS for the merge.

SLS4216E Missing or invalid SLSMERGE dataset found for MERGEcds

Explanation: Either the SLSMERGE DD statement was missing, or the data set could not be opened, or no parameters were found and the keyword “ALL” was not specified on the MERGEcds statement.

System Action: The CDS Merge process terminates.

User Response: Either specify “ALL” on the MERGEcds statement, or include an SLSMERGE DD statement with one or more parameters in the SLUADMIN job.

SLS4217E - SLS4220I

SLS4217E MERGEcds ALL was specified with a SLSMERGE DD statement

Explanation: The MERGEcds statement specified ALL, but an SLSMERGE DD statement was found in the SLUADMIN job.

System Action: The CDS Merge process terminates.

User Response: Either remove the ALL keyword from the MERGEcds statement, or remove the MERGEDEF DD statement from the SLUADMIN job.

SLS4218I CDS Merge complete on CCCC...CCCC

Explanation: The CDS Merge has successfully updated the CDS with a data set name of CCCC...CCCC.

System Action: The CDS Merge process continues.

User Response: None.

SLS4219E Unable to select a primary CDS for MERGEcds

Explanation: For all the FROM CDS copies specified as input to SLUADMIN, information in the DHB was inspected. The best CDS copy was not a primary or secondary CDS when it was last used, and it has not been restored since; therefore it would not be a valid primary CDS.

System Action: The CDS Merge process terminates.

User Response: Review the SLSFCNTL, SLSFCTL2, and SLSFSTBY data sets that were specified for the SLUADMIN job. If the right data sets were specified, use the HSC BACKUp utility to select and back up the most current CDS copy, followed by an HSC RESTore to synchronize all CDS copies. Then restart the SLUADMIN job.

SLS4220I Cleaner prefix XXX on FROM CDS does not match XXX on TO CDS

Explanation: There is a mismatch in the cleaner prefixes for two CDSs being merged.

System Action: The CDS Merge process continues. If any cleaning cartridges are found in the FROM CDS they will be listed in message SLS4221E.

User Response: If the CDS Merge was run with the VALIDate option, eject all cleaning cartridges from the FROM LSM.

If the CDS Merge was run without the VALIDate option, eject all cleaning cartridges from the TO LSM after the merge completes.

SLS4221E Volume VVVVVV in LSM AA:LL merged as non-cleaner

Explanation: Volume VVVVVV has a prefix matching the cleaner prefix of the FROM CDS but not the TO CDS.

System Action: The CDS Merge process continues. The volume is added to the TO CDS, but it will not be used as a cleaning cartridge.

User Response: If the CDS Merge was run with the VALIDate option, eject the volume from the FROM LSM.

If the CDS Merge was run without the VALIDate option, eject the volume from the TO LSM after the merge completes.

SLS4222E Duplicate {FROM|TO} {ACS AA|LSM AA:LL} found on MERGE control statement

Explanation: A duplicate ACSid or LSMid was specified as the FROM or TO ACS/LSM on a MERGE control statement, or the ACSid of a FROM/TO merge parameter overlaps another FROM/TO LSMid.

System Action: The CDS Merge process terminates.

User Response: Correct the error and resubmit the CDS Merge.

SLS4223E Audit in progress on TO LSM AA:LL

Explanation: There is an audit in progress on LSM AA:LL which is the target of a CDS Merge.

System Action: If the VALIDate option was specified, a return code of "4" is set and the validation process continues; otherwise, the CDS Merge process terminates.

User Response: Resubmit the CDS Merge after the audit completes. If the LSM contains volumes, it cannot be the target of a merge.

SLS4225E Unexpected CDS Merge error - Component=MMMMMMMM, RC=XXXXXXXX

Explanation: While processing a CDS Merge, an unexpected error occurred. MMMMMMMM is the name of the HSC component that failed. XXXXXXXX is the return code from the operation.

System Action: The CDS Merge process terminates.

User Response: Check the return code associated with the named component. If you are unable to resolve the problem, contact StorageTek Software Support.

SLS4226I SLSMERGE input parameter:XXXX...XXXX

Explanation: The indicated parameter statement has been read from the SLSMERGE data set.

System Action: None.

User Response: None.

SLS4227E VAR area overflow during CDS merge

Explanation: There is no space in the TO CDS to add a volume.

System Action: The CDS Merge process terminates.

User Response: Contact StorageTek Software Support.

SLS4230I CCCCCCCC1 CCCCCCCC2 parameter not valid

Explanation: Parameter CCCCCCCC2 of command or control statement CCCCCCCC1 is not valid.

System Action: The utility continues processing. Reports generated may be incorrect. A return code of X'04' is set.

User Response: Correct the command or control statement in error and rerun the utility.

SLS4231I Panel PP on LSM AA:LL CCCCCCCC

Explanation: Confirmation that LSM AA:LL Panel PP has been frozen, unfrozen or is unallocated. An unallocated panel will be bypassed and can not be frozen or unfrozen.

System Action: The SET function is complete.

User Response: None.

SLS4232I Entire LSM AA:LL CCCCCCCC

Explanation: Confirmation that the entire LSM AA:LL has been frozen or unfrozen. If the state is already what was asked for, the message will say that it is already frozen or unfrozen.

System Action: The SET function is complete.

User Response: None.

SLS4233I Unable to Freeze/Unfreeze an Unallocated or non-existent LSM or Panel

Explanation: An attempt was made to freeze or unfreeze an unallocated LSM or a panel that is unallocated in an LSM. Also, you can get this error if you try to Freeze or Unfreeze a non-existent LSM or panel. An unallocated panel will be bypassed and can not be frozen or unfrozen.

System Action: The SET function is complete with RC=8

User Response: None.

SLS4244E Parameter "ALL" specified, but no virtual data was defined in the "TO" CDS. No virtual data copied.

Explanation: The specification of "ALL" was made, but no virtual configuration data was found in the "TO" CDS. No virtual records were copied.

System Action: The utility terminates following phase 2. No data was merged. A return code of 8 is set.

User Response: Run the SWSADMIN CONFIG function to define the virtual information, and resubmit the CDS Merge to copy the virtual information if desired.

SLS4247I CCCCCCCC parameter value invalid; must be 'YES' or 'NO'

Explanation: A SLUADMIN utility function specified a parameter with a value other than YES or NO.

System Action: The utility function terminates.

User Response: Correct the parameter on the utility control statement, and resubmit the SLUADMIN utility job.

SLS4248I Blank ACSDRV esoteric only valid with VSMONLY

Explanation: A blank ACSDRV esoteric was specified for an ACS that is not VSMONLY. The ACS can be set as being VSMONLY via a LIBGEN or a SET ACSDRV VSMONLY(YES).

System Action: The utility function terminates.

User Response: Correct the parameter on the utility control statement, and resubmit the SLUADMIN utility job.

SLS4266A Cartridge *volser* in CAP *AA:LL:CC* has an invalid media label and cannot be entered

Explanation: A cartridge (*volser*) has been found in CAP *AA:LL:CC* with an unreadable media label and cannot be entered.

System Action: Cartridge entry leaves the cartridge in the CAP cell in which it is found and unlocks the CAP so the cartridge can be removed.

User Response: Remove the cartridge from the CAP. If the cartridge must be entered, correct the media label.

SLS4350I CDS Merge terminated prematurely; merge complete on {NO CDS copies|PRIMARY CDS copy|ALL CDS copies}

Explanation: The HSC subsystem merge process was notified of an abnormal termination of the merge utility. The merge has already updated the CDS copies noted.

System Action: The CDS Merge process terminates.

User Response: Check the message to determine the status of the merge, then proceed as follows:

- If no CDS copies were updated, then you can restart the merge at the beginning.
- If only the primary CDS copy was updated, then the secondary copy will be disabled automatically. You can enable the CDS to force synchronization with the primary.
- If all CDS copies were updated, then the merge is complete and no action is necessary.

SLS4351I Inconsistent copy flag found on *DDDDDDDD*

Explanation: The utility function found the inconsistent copy flag turned on in the CDS copy for DDNAME *DDDDDDDD*.

System Action: If a valid CDS copy exists, the utility continues. The data set *DDDDDDDD* is not processed.

User Response: Synchronize the inconsistent copy by doing one of the following:

- Restore all CDS copies from a backup, or
- Enable the inconsistent copy to HSC. This will force synchronization of the inconsistent copy.

SLS4352I 'DIAGSCAN' parameter value invalid; must be 'ONLY' or 'ALSO'

Explanation: A SLUADMIN AUDIt utility specified a DIAGScan parameter with a value other than ONLY or ALSO.

System Action: The AUDit utility terminates.

User Response: Correct the DIAGScan parameter on the utility control statement and resubmit the SLUADMIN utility job.

SLS4353I No diagnostic cells for LSMid *AA:LL*, panel *DD*

Explanation: A SLUADMIN AUDIt utility function was requested to scan diagnostic cells by the inclusion of the DIAGScan parameter. However, there were no diagnostic cells in the specified LSMid (*AA:LL*) and panel (*DD*).

System Action: HSC processing continues.

User Response: None.

SLS4354I Diagnostic cell *AA:LL:PP:RR:CC* is empty

Explanation: A SLUADMIN AUDIt utility function was requested to scan diagnostic cells by the inclusion of the DIAGScan parameter. The diagnostic cell at the specified location (*AA:LL:PP:RR:CC*) was found to be empty.

System Action: HSC processing continues.

User Response: None.

SLS4355I Cartridge in diagnostic cell *AA:LL:PP:RR:CC* has an unreadable external label

Explanation: A SLUADMIN AUDIt utility function was requested to scan diagnostic cells by the inclusion of the DIAGScan parameter. The diagnostic cell at the specified location (*AA:LL:PP:RR:CC*) was found to contain a cartridge with an unreadable external Volser label.

System Action: HSC processing continues.

User Response: The cartridge may have been erroneously placed in the diagnostic cell during a time when the LSM was in manual mode. The user may wish to return the LSM to manual mode, enter the LSM and retrieve the cartridge. If it is a data cartridge, determine its Volser, label the cartridge and re-enter it through a CAP after the LSM has been brought back online.

SLS4356I Volume *volser* is in diagnostic cell *AA:LL:PP:RR:CC*

Explanation: A SLUADMIN AUDIt utility function was requested to scan diagnostic cells by the inclusion of the DIAGScan parameter. The diagnostic cell at the specified location (*AA:LL:PP:RR:CC*) was found to contain a cartridge with the external Volser label *volser*.

System Action: HSC processing continues.

User Response: If the cartridge is not a diagnostic cartridge (usually with an external label in the form "DG nnn", where nnn are decimal digits), then the cartridge may have been erroneously placed in the diagnostic cell during a time when the LSM was in manual mode. The user may wish to return the LSM to manual mode, enter the LSM and retrieve the cartridge and re-enter it through a CAP after the LSM has been brought back online.

SLS4357I Unable to scan diagnostic cells in LSMid *AA:LL* (9740)

Explanation: A SLUADMIN AUDIt utility function was requested to scan diagnostic cells by the inclusion of the DIAGScan parameter. The specified LSM (*AA:LL*) is a 9740 type LSM which currently does not support diagnostic cell scans.

System Action: HSC processing continues.

User Response: None.

SLS4358I No in-transit cartridges in LSMid *AA:LL*

Explanation: A SLUADMIN AUDIt utility function was requested to process in-transit cartridges by the inclusion of the INTRANs parameter, but there were no in-transit cartridges in the specified LSM (*AA:LL*).

System Action: HSC processing continues.

User Response: None.

SLS4359I Unable to select in-transit volume *volser* in LSMid *AA:LL*

Explanation: A SLUADMIN AUDIt utility function was requested to process in-transit cartridges by the inclusion of the INTRANs parameter, but was unable to select the specified library volume (*volser*) in the specified LSM (*AA:LL*).

System Action: HSC processing continues.

User Response: Investigate if the volume is selected and if it is, consider running the SLUADMIN UNSElect utility to free the volume then rerun the SLUADMIN AUDIt utility with the INTRANs parameter.

SLS4360I DDname *CCCCCCCC* allocated to dataset name *DDD...DD*

Explanation: The utility has allocated the DD name noted by *CCCCCCCC* to the data set name of *DDD...DD* (a string which may be up to 54 characters, including the member name if the data set is a PDS member). The DD name *CCCCCCCC* may be one of the following: SLSCNTL, SLSSCRPL, or SLSVA. The allocation may have been due to the JCL supplied to the utility job, or the allocation may have been dynamic, based on the data sets being used by the HSC active on this host system.

System Action: The utility continues.

User Response: This message is informational only. If the utility fails to produce the expected results, the series of SLS4203I messages should be examined to be sure that the intended data sets were actually the ones allocated to the job.

SLS4361I Ejected in-transit volume *volser* from LSMid *AA:LL*

Explanation: A SLUADMIN AUDIt utility function was requested to process in-transit cartridges by the inclusion of the INTRANs parameter. A library volume(*volser*) was found to be in-transit in the specified LSM (*AA:LL*) and was ejected.

System Action: HSC processing continues.

User Response: Consider if the volume should be re-entered into the library. (Note: the operator is informed of the cartridge ejection and is required to empty the CAP either when the CAP is full or the SLUADMIN AUDit utility completes.)

SLS4362I Error ejecting in-transit volume *volser* from LSMid *AA:LL*

Explanation: A SLUADMIN AUDIt utility function was requested to process in-transit cartridges by the inclusion of the INTRANs parameter. A library volume (*volser*) was found to be in-transit in the specified LSM (*AA:LL*) and was attempted to be ejected but the eject failed.

System Action: HSC processing continues.

User Response: Investigate other HSC messages associated with the eject failure. Consider re-running the SLUADMIN AUDit utility with the INTRANs parameter.

SLS4363I Ejected an in-transit cartridge with an unreadable external label from LSMid AA:LL

Explanation: A SLUADMIN AUDIt utility function was requested to process in-transit cartridges by the inclusion of the INTRANs parameter. A cartridge with an unreadable external label was found to be in-transit in the specified LSM (AA:LL) and was ejected.

System Action: HSC processing continues.

User Response: Consider if the volume should be labeled and re-entered into the library. (Note: the operator is informed of the cartridge ejection and is required to empty the CAP either when the CAP is full or the SLUADMIN AUDIt utility completes.)

SLS4364I Error ejecting in-transit cartridge with an unreadable external label from LSMid AA:LL

Explanation: A SLUADMIN AUDIt utility function was requested to process in-transit cartridges by the inclusion of the INTRANs parameter. A cartridge with an unreadable external label was found to be in-transit in the specified LSM (AA:LL) and was attempted to be ejected but the eject failed.

System Action: HSC processing continues.

User Response: Investigate other HSC messages associated with the eject failure. Consider re-running the SLUADMIN AUDIt utility with the INTRANs parameter.

SLS4365I Virtual Volume merge bypassed, VTCS has not been activated.

Explanation: A merge operation has been requested specifying a 'from' CDS that contains VTV and MVC entries. Since VTCS has not been activated on this system, these VTV and MVC entries will not be merged into the 'to' CDS.

System Action: HSC processing continues.

User Response: None.

SLS4370I SLUINCT processing on XXXX {STARTED|ENDED}

Explanation: An SLUINCT operation has been requested and drive XXXX has been requested.

System Action: Utility processing continues.

User Response: None.

SLS4400I HSC dynamic reconfiguration initiated

Explanation: HSC dynamic reconfiguration processing has started.

System Action: Dynamic reconfiguration processing continues.

User Response: None

SLS4401I {Transport|Drive record|LSM/rail} {AA:LL:PP:NN|AA:LL} successfully {added to|removed from|allocated to|unallocated from} current HSC configuration.

Explanation: Dynamic reconfiguration has either added or removed a transport, drive record or LSM. Transport indicates both the HSC configuration drive record and the transport in the library have been processed. Drive record indicates only the HSC configuration was changed (i.e. when SLUADMIN is run to add configuration drive records but the transports are not yet connected). LSM/rail indicates a LSM has been processed based on the SL8500 configuration discovered. Additionally, with SL8500 partitioning support a LSM can be unallocated from or allocated to the current HSC configuration. In this situation the LSM configuration data remains in place but is recognized as either allocated or unallocated. Both are considered part of the running HSC configuration but only an allocated LSM is considered a usable resource of that running HSC.

System Action: HSC continues processing configuration changes until complete.

User Response: None.

SLS4402I CDS {drive|LSM} record {not found|previously removed} for existing {transport|LSM/rail; id={AA:LL:PP:NN|AA:LL}}

Explanation: Dynamic reconfiguration has found a connected tape transport or LSM in the SL8500 library with no corresponding configuration record on the CDS. Either the drive record was removed with SLUADMIN or was never present on the CDS. For LSMs, no corresponding record was established in the LIBGEN using the FUTURLSM parameter.

System Action: The HSC cannot add a transport to the current configuration without a corresponding drive record on the CDS. The same rule applies with LSMs. WTOR SLS4405D is issued to ask the customer to proceed or abort.

User Response: Reply 'N' to the SLS4405D message, add the specific record to the CDS and launch dynamic reconfiguration again. A reply of 'Y' will proceed with reconfiguration however, in this situation, the specific drive or LSM will not be added to the current configuration.

SLS4403I - SLS4405D

SLS4403I CDS {drive|LSM} record found with no matching {transport|LSM/rail}; library location = {AA:LL:PP:NN|AA:LL}

Explanation: Dynamic reconfiguration has found a configuration record on the CDS with no corresponding transport or LSM at the specified location. Either 1) the transport was removed from the library without removing the drive record from the CDS; 2) the drive record has been added to the CDS and the transport has not been added to the library or 3) the LSM/rail is being taken away from the HSC.

System Action: The HSC will issue WTOR SLS4405D in this situation asking the customer to proceed or abort.

User Response: If this mismatch is not expected, reply 'N' to the SLS4405D message, connect the transport to the library, and launch dynamic reconfiguration again. For LSMs, this mismatch is expected as no dynamic CDS updates can be made. A reply of 'Y' will 1) mark the drive record as "unconfigured" whether resulting from the addition of the drive record or removal of the transport or 2) remove the LSM from the HSC configuration.

SLS4404I {Drive {type|unit address|host definition|type and unit address}|{LSM {panel configuration|passthru configuration|panel and passthru configuration} successfully modified for {transport|LSM/rail} {AA:LL:PP:NN|AA:LL} during dynamic reconfig

Explanation: Dynamic reconfiguration has successfully modified 1) the specified drive's type, unit address, or host definition; or 2) the specified LSM's panel and/or passthru configuration.

System Action: The HSC has updated the current configuration accordingly.

User Response: None.

SLS4405D CDS / LMU conflicts exist; allow dynamic reconfig to proceed; Reply 'Y' or 'N'

Explanation: Dynamic reconfiguration has either; 1) found a connected transport with no corresponding drive record; 2) found a configuration drive record on the CDS with no corresponding transport in the library; 3) found an LSM record on the CDS with no corresponding SL8500 LSM; or 4) found an SL8500 LSM/rail with no corresponding LSM record on the CDS. Preceding messages SLS4402I and SLS4403I provide the specific SL8500 elements and locations.

System Action: Dynamic reconfiguration waits to receive a reply to this message. If 60 seconds expires before a reply is received, dynamic reconfiguration is aborted and message SLS4405D is deleted from the console.

User Response: If reply of 'Y' is given, dynamic reconfiguration will process all eligible changes. Any other reply will result in dynamic reconfiguration aborting with reason = operator request.

SLS4406I Dynamic reconfiguration processing did not occur, no changes found or unable to process

Explanation: Dynamic reconfiguration processing determined that no configuration changes in the SL8500 or SL3000 library or in the HSC were made; or that changes were not able to be processed. Possible situations include: 1) new transports found with no corresponding drive records and 'Y' was replied to SLS4405D WTOR; 2) new LSM(s) found with no corresponding LSM records and 'Y' was replied to SLS4405D WTOR; 3) no SL8500 or SL3000 based elements found to process.

System Action: Dynamic reconfiguration processing ends.

User Response: If configuration changes were anticipated ensure all changes are in place, both in the CDS and the library.

SLS4407I HSC dynamic reconfiguration processing has ended.

Explanation: HSC dynamic reconfiguration processing has ended. In some cases hardware reconfiguration may not have taken place; message SLS4505D received a 'N' reply or no configuration changes were detected. To determine any configuration changes that may have occurred look at the reconfiguration messages that precede message SLS4407I. The message range for these messages is SLS4400I through SLS4412I.

System Action: Dynamic reconfiguration processing ends.

User Response: None

SLS4408I {LMU|Database|Configuration} request error during dynamic reconfig;
rc = *nnnn*

Explanation: An LMU, database or configuration request has returned an error condition during dynamic reconfiguration processing. The failing component's return code; *nnnn* is included in the message which can be referenced in the HSC Messages and Codes guide, chapter 4.

System Action: Dynamic reconfiguration processing ends.

User Response: Consult the Messages and Codes guide, determine the exact reason for the error and call STK support.

SLS4409I HSC dynamic reconfiguration has aborted; reason = {operator request|timeout|LMU request error|database request error|config request error|unknown}

Explanation: Dynamic reconfiguration has aborted for one of the following reasons:

- operator request: A reply of N was given to message SLS4405D to abort dynamic reconfiguration.
- timeout: No reply was given to message SLS4405D within the 60 seconds allowed.
- LMU request error: LMU request error(s) prevent the continuation of dynamic reconfiguration, no changes to the existing configuration were made.
- database request error: database error(s) prevent the continuation of dynamic reconfiguration, contact Sun support.
- configuration request error: internal configuration component error(s) prevent the continuation of dynamic reconfiguration, contact Sun support.
- config verification error: internal config verification error(s) prevent the continuation of dynamic reconfiguration, contact Sun support.
- SCR UPDATE utility active: A Scratch Update utility is currently running and prevents the continuation of dynamic configuration, issue the previous Modify CONFIG command again after the utility has completed.
- AUDIT utility active: An AUDIT utility is currently running and prevents the continuation of dynamic configuration, issue the previous Modify CONFIG command again after the utility has completed.
- SCR REDIS utility active: A Scratch Redistribution utility is currently running and prevents the continuation of dynamic configuration, issue the previous Modify CONFIG command again after the utility has completed.
- MOVE utility active: A Move utility is currently running and prevents the continuation of dynamic configuration, issue the previous Modify CONFIG command again after the utility has completed.
- unknown: An unexpected error, such as an abend, has been detected, contact Sun support.

System Action: Dynamic reconfiguration processing ends.

User Response: Contact Sun support.

SLS4410I CDS drive record for library location *AA:LL:PP:NN* marked as unconfigured

Explanation: Dynamic reconfiguration has marked a drive record as unconfigured for one of two reasons; 1) Transports were removed but SLUADMIN has not run to remove the drive records from the CDS or 2) drive records have been added to the CDS using SLUADMIN however the corresponding transports have not been connected to the library.

System Action: The drive records remain in the HSC configuration but are marked as unconfigured and will not reflect valid types or recording techniques. They will display with a status of "unconfg" (unconfigured).

User Response: The drives can remain in the unconfigured state until transports are connected at the corresponding library location id or removed with SLUADMIN if no longer wanted.

SLS4411I Drive record *AA:LL:PP:NN* remains unconfigured, no changes made.

Explanation: Dynamic reconfiguration has determined that a drive remains unconfigured since the last reconfiguration or initialization.

System Action: The drive record is not processed.

User Response: None.

SLS4412I HSC deleted volume *VVVVVV* from CDS for unallocated
[LSMid *AA:LL* | cell *AA:LL:PP:RR:CC*]

Explanation: A volume was found in the CDS still remaining in an LSM that has been unallocated via the partitioning process, or in a cell that has been unallocated via the capacity on demand process.

System Action: The volume is deleted from the CDS.

User Response: The volume will be "owned" by the new host (or host group) to which the unallocated LSM or cell has been assigned. The new host must perform an HSC audit to recover the volume. In the event the volume is mounted on a drive, the new host must issue an HSC DISMOUNT command to recover the volume.

SLS4413I - SLS4415I

SLS4413I HSC failed to delete volume VVVVVV from CDS for unallocated
[LSMid AA:LL | cell AA:LL:PP:RR:CC] RC= RCRRCRC

Explanation: The HSC attempted to delete a volume from the CDS but was unable to do so. The return code identifies the reason for the failure but the most likely reason is that the volume was in use by another process when the attempt to delete the volume was made.

System Action: The volume remains in the CDS and becomes “inaccessible”.

User Response: After the partitioning process or the capacity on demand process has completed the volume will be “owned” by the host to which the unallocated LSM or cell has been assigned. This host must do an HSC audit function to recover the volume. In the event the volume is mounted on a drive, the new host must issue an HSC DISMOUNT command to recover the volume.

SLS4414I Initial configuration for LSM AA:LL, total cells nnnnn, free cells nnnnn

Explanation: Config verification was executed for the first time for LSM AA:LL. Initial values are displayed for the total cells in the LSM and the number of free cells in the LSM.

System Action: Processing continues.

User Response: None.

SLS4415I Configuration change for LSM AA:LL, total cells [unchanged | increased | decreased] by nnnnn, free cells [unchanged | increased | decreased] by nnnnn

Explanation: Config verification found the configuration for LSM AA:LL has changed. The differences in cell counts are displayed for the total cells in the LSM and the number of free cells in the LSM.

System Action: Processing continues.

User Response: None.

SLS4416E Config verification
for LSM AA:LL found something unexpected [for the following
panel(s):
p1[, p2, ...]]

Explanation: During config verification of the specified location(s) (AA:LL, p1, p2, etc.), something unexpected was found, such as, a cartridge in an unexpected location, a cartridge in a cell but no matching volser in the database, etc.

System Action: Processing continues.

User Response: First run the AUDIT utility with APPLY(NO) for the panel locations indicated to discover the problems found. The VOLRPT utility may need to be run to determine certain information for volumes. Part of problem resolution may be running the AUDIT utility with APPLY(YES). After problems are resolved, the SET utility specifying FREEZE OFF may need to be run.

- It is recommended to run AUDIT with APPLY(NO) first in order to discover and resolve problems before any changes are made to the CDS with APPLY(YES).
- During configuration changes, panels are initially set to “frozen” status. When the configuration change is completed, if something unexpected is found, panels will remain in “frozen” status. In this case, when the problems are resolved, the SET utility must be run specifying FREEZE OFF for the locations indicated.

SLS4417E Database I/O error (RC=xxxxxxx) occurred with *rectype* records during config verification

Explanation:

- VAR records: A control data set error occurred while gathering volume information to verify volume and cell location status. Without the volume information, volume locations cannot be verified during the config verification.
- DCX records: A control data set error occurred while updating location index records. The process did not complete.

System Action:

- VAR records: Processing continues.
- DCX records: Config verification terminates.

User Response:

- VAR records: Determine the cause of the control data set error and correct it.
- DCX records: Determine the cause of the control data set error and correct it. Then use the MODIFY CONFIG command to update the configuration.

- SLS4418E** LMURQST error (RC=xxxxxxxx) occurred during config verification; verification cannot continue
- Explanation:** A request to the LMU failed with error code xxxxxxxx during config verification.
- System Action:** Config verification terminates.
- User Response:** Determine the cause of the LMURQST error and correct it. Then use the MODIFY CONFIG command to update the configuration.
- SLS4419I** CAPid AA:LL:CC status changed from (UNALLOCATED|ONLINE|OFFLINE) to (OFFLINE|UNALLOCATED)
- Explanation:** During reconfiguration, the CAP state was changed in the SLC console from an SL8500 or SL3000 library.
- System Action:** HSC configuration accepts the CAP change from the library and is reflected in this message.
- User Response:** None.
- SLS4420E** Invalid cell status *n* for cell location AA:LL:PP:RR:CC
- Explanation:** During processing of config verification the LMU returned an unknown or invalid cell position status for the specified location.
- System Action:** Processing continues.
- User Response:** Determine the cause of the invalid cell position status code.
- SLS4421E** No more invalid cell status messages will be displayed
- Explanation:** Multiple invalid cell status messages have been displayed. This may indicate a problem with the hardware and/or software. In order to avoid flooding the console with messages, additional invalid cell status messages will be suppressed.
- System Action:** :Processing continues.
- User Response:** Determine the cause of the invalid cell position status code(s).

SLS4422E An abend occurred during config verification while *CCC...CCC*

Explanation: Config verification has ended because of an abend. *CCC...CCC* is a description of the active stage of the process at the time of the abend:

- processing configuration records: Configuration records were being queried to determine the configuration previously defined.
- processing volume records: Volume records were being processed to verify locations of volumes in the library.
- obtaining library configuration: The current hardware configuration of each panel in the library was being obtained from the library hardware.
- verifying library configuration: The previously defined configuration was being compared with the current hardware configuration of the library.
- finalizing verification: Config verification was in the final stage and attempting clean up of acquired storage areas, etc.

System Action: Config verification terminates.

User Response: The action(s) to perform are dependent on the active stage of the process at the time of the abend. First determine and correct the cause of the abend. Then perform the action(s) shown below for the specified stage of the process.

- processing configuration records: No configuration updates have been made. After determining and correcting the cause of the abend, use the MODIFY CONFIG command to verify / update the configuration.
- processing volume records: No configuration updates have been made. After determining and correcting the cause of the abend, use the MODIFY CONFIG command to verify / update the configuration.
- obtaining library configuration: No configuration updates have been made. After determining and correcting the cause of the abend, use the MODIFY CONFIG command to verify / update the configuration.
- verifying library configuration: If any differences were found, updates to the configuration records may have occurred. After determining and correcting the cause of the abend, use the MODIFY CONFIG command to complete the verification / update of the configuration.
- finalizing verification: Config verification has completed any configuration updates.No additional action is necessary.

SLS4423E SLS4423E {ACS|ACSTTYPE} {AA|SL8500|SL3000} can not be {deleted|added} on the current configuration

Explanation:

Case: In the case of ACS DELETE, the ACS is UNALLOCATED and can not be deleted because it is not at the end of the ACS string or it was not a SLICREATED FUTRACS.

Case: In the case of ACS ADD, there is no FUTRACS or UNALLOCATED ACS available to be used for this ACSTYPE LSM.

System Action: None, the ACS ADD or DELETE does not occur.

User Response: Display ACS to help determine the reason. Check your CDS configuration via LIBGEN decompile. Reference HSC NCO documentation on ACS ADD/DELETE.

SLS4424E A SLUADMIN <name> utility is active on this host, Dynamic Reconfiguration can not proceed.

Explanation: A SLUADMIN utility function is currently active on this host. This NCO update can not run with utilities active on this host.

System Action: If the HOST is trying to do NCO REFRESH the message will be repeated every 15 seconds until the utility completes then NCO REFRESH will continue processing and should complete normally.

If the HOST initiating the NCO update discovers a utility active it will fail and the NCO update will not be executed.

User Response: Cancel the utility or wait until it completes then reissue the Modify Config or Modify Config Update command if necessary.

SLS4425E LMU panel count for LSM {AA:LL} exceeds maximum panel count allowed in CDS. Reconfiguration cannot proceed

Explanation: During dynamic reconfiguration of an SL8500, the LMU responded with a panel count for the specified LSM that is greater than the maximum panel count in the specified CDS LSM record. If the CREATE field in the DISPLAY CDS is equal to I825061 then the maximum number of panels in the current CDS for an SL8500 is 44 panels per LSM.

System Action: The NCO update is not executed.

User Response: A new CDS will need to be created at a minimum level of I813156. After the new CDS is created a MERGECDS from the I825061 CDS to the I813156 CDS will need to be done. Once the MERGECDS is complete then a MODIFY CONFIG command will initiate dynamic hardware reconfiguration.

- SLS4451I** Drive records are inconsistent with the CDS for LSM AA:LL; ACS disconnected
- Explanation:** An inconsistency was found between drive records in the CDS and the HSC in-memory version, probably due to a SET SLIDRIVS utility.
- System Action:** The affected ACS is disconnected.
- User Response:** Leave the ACS disconnected until the host is recycled.
- SLS4453I** Logically deleted record found on CDS for DRIVEID AA:LL:PP:NN
- Explanation:** A SET SLIDRIVS command caused deletion of the drive record in the CDS.
- System Action:** Either the LSM will remain offline, or the ACS will be disconnected. A subsequent message will indicate which action is taken.
- User Response:** Recycle the host to refresh the HSC in-memory drive records.
- SLS4454I** {Unit address|DRIVEID} does not match CDS for HSC {drive
XXXX|DRIVEID AA:LL:PP:NN}
- Explanation:** A SET SLIDRIVS utility caused a change to the CDS drive record, making it inconsistent with the HSC in-memory copy.
- System Action:** Either the LSM will remain offline, or the ACS will be disconnected. A subsequent message will indicate which action is taken.
- User Response:** Recycle the host to refresh the HSC in-memory copies of drive records.
- SLS4455E** Unexpected FIGMGR return code *NNNN* during Configuration processing
- Explanation:** An unexpected return code was received from a FIGMGR service during configuration processing.
- System Action:** HSC terminates.
- User Response:** Contact StorageTek Software Support.
- SLS4456I** Library configuration changes pending on HHHHHHHH
- Explanation:** Near Continuous Operation (NCO) library configuration changes in progress on host id HHHHHHHH
- System Action:** Configuration change continues.
- User Response:** None

SLS4457E Down level host found active when attempting to change library configuration

Explanation: Near Continuous Operation (NCO) library configuration changes can not be run with a down level host active.

System Action: Configuration change not executed.

User Response: Insure all down level hosts are not active and start NCO configuration again.

SLS4458E Library configuration changes in progress on HHHHHHHH

Explanation: Near Continuous Operation (NCO) library configuration changes are in progress on host HHHHHHHH.

System Action: Configuration change not executed, it is already running. Also some utilities will not run because NCO is in progress.

User Response: Wait on NCO configuration to complete before restarting if needed. In some cases NCO will queue the request and will process the queue when the NCO completes.

It is possible however at vary online time of an SL3000 ACS that NCO update may not be initiated. Indications of NCO initiated on an SL3000 would be cap status for that ACS. If no cap status in the HSC log for a particular SL3000 ACS that was varied online then the following operator command must be issued to update the ACS:

MODIFY CONFIG UPDATE ACS(NN)

This can also apply to a newly added SL8500 varied online during NCO REFRESH.)

In come cases a REFRESHing host may fail or be CANCELED by an operator. If the host (HHHHHHHH) is not responding a RECOVER HOST command (with the FORCE option) may be required. Reference the HSC OPERATOR GUIDE before using the FORCE option.If the RECOVER HOST command is required then a MODIFY CONFIG RESET command may also be required. A DISPLAY CDS command will show the REFRESH bit map of the HOSTs that have yet to complete NCO REFRESH.

SLS4459I Library configuration changes started

Explanation: Near Continuous Operation (NCO) library configuration changes started by this host

System Action: Configuration change continues.

User Response: None

- SLS4460I** Library configuration changes complete on HHHHHHHH
- Explanation:** Near Continuous Operation (NCO) library configuration changes on completed on hostid HHHHHHHH.
- System Action:** Configuration change complete.
- User Response:** None
- SLS4461I** Library configuration changes in progress when HSC went down, configuration restarted
- Explanation:** Near Continuous Operation (NCO) library configuration changes in progress on this host when HSC went down. The configuration is attempting to restart.
- System Action:** Configuration change continues.
- User Response:** None
- SLS4462I** Library configuration refresh started
- Explanation:** Near Continuous Operation (NCO) library configuration changes completed by another host are being synchronized on this host.
- System Action:** Configuration change refresh started.
- User Response:** None
- SLS4463I** Library configuration refresh complete
- Explanation:** Near Continuous Operation (NCO) library configuration changes completed by another host have been synchronized on this host.
- System Action:** Configuration change refresh complete.
- User Response:** None
- SLS4464E** Library configuration XXXXXXXX aborted on HHHHHHHH
- Explanation:** Near Continuous Operation (NCO) library configuration (UPDATE or REFRESH) failed on hostid HHHHHHHH.
- System Action:** Configuration change failed to complete successfully.
- User Response:** See previous message for the reason for the failure. Correct discrepancies and rerun NCO configuration.

- SLS4465I** Library configuration flags Reset complete
- Explanation:** Near Continuous Operation (NCO) library configuration CDS flags have been reset as requested by the Modify Config Reset command.
- System Action:** Configuration change flags are reset in the CDS.
- User Response:** None.
- SLS4466I** Library configuration flags not set, Reset not required
- Explanation:** Near Continuous Operation (NCO) library configuration CDS flags were not set, the reset requested by the Modify Config Reset command was not required. Modify Config Reset command does not attempt to run a reconfig. To run a reconfig issue the Modify Config command.
- System Action:** Modify Config Reset command complete.
- User Response:** None.
- SLS4467E** Down level CDS active, library configuration canceled
- Explanation:** Near Continuous Operation (NCO) library configuration changes can not be run with a down level CDS, a 6.1.0 CDS is required.
- System Action:** Configuration change not executed.
- User Response:** Libgen a 6.1.0 CDS and run the MERGECDS utility to enable NCO.
- SLS4500I** *YYYY-MM-DD, HH:MM:SS* HSC subsystem *SSSS* active on hostid *HHHH*
- Explanation:** The message is issued after HSC is initialized to Base service level and also when a new day has begun at midnight.
- System Action:** None.
- User Response:** None.
- SLS4550E** Number of drive addresses is not consistent with previous SLIDRIVS for this panel
- Explanation:** The number of drive addresses on the SLIDRIVS macro does not match the number of addresses on a previous SLIDRIVS macro for the same panel.
- System Action:** Processing continues. A return code of 08 is set.
- User Response:** Correct the number of addresses on the incorrect SLIDRIVS macro and resubmit the LIBGEN assembly.

- SLS4551I** The LIBSIZE parameter has been discontinued and is ignored; it should be removed
- Explanation:** The LIBSIZE parameter is no longer used.
- System Action:** LIBGEN assembly continues normally and the resultant LIBGEN module is not affected.
- User Response:** Remove the LIBSIZE parameter from the SLILIBRY macro when convenient. It is not necessary to rerun the LIBGEN assembly.
- SLS4552I** The minimum number of 4K blocks required for the CDS is *DDDDD*
- Explanation:** The calculated minimum number of CDS blocks is reported. SLICREAT can be executed with no CDS DD statements specified to only report the minimum CDS size for a LIBGEN configuration.
- System Action:** None.
- User Response:** Use the calculated value to allocate CDS copies prior to initializing them with SLICREAT.
- SLS4553E** Number of drives on drive panel *PP* in LSM *AA:LL* is invalid
- Explanation:** The number of drives defined on the indicated panel exceeds the maximum allowed for that panel type.
- System Action:** Processing continues. A return code of 0C is set.
- User Response:** Correct the error and resubmit the LIBGEN assembly. Allowable maximum numbers of drives (depending on panel type) per LSM are: 4, 10, or 20 drives for 4410 or 9310 LSM; 4 or 10 drives for 9740 LSM; 4 drives for 9360 LSM; 4, 8, 12, or 16 drives for SL8500 LSM.
- SLS4554E** The LIBGEN load module release level is inconsistent with the SLICREAT release level
- Explanation:** SLICREAT has been executed with a LIBGEN load module that was created using LIBGEN macros for an incompatible HSC release.
- System Action:** SLICREAT processing terminates. A return code of 0C is set.
- User Response:** Re-create the LIBGEN load module using a MACLIB for the same HSC release as the SLICREAT software.

SLS4555E Missing DD or invalid file allocation for DDname CCCCCCCC

Explanation: SLICREAT was unable to find or allocate the dataset specified by the CCCCCCCC DD statement.

System Action: If the DD is SLSCNTL, or if you specified PARM='STBYONLY', a return code of 12 is set and SLICREAT processing terminates. A return code of 4 is set in all other cases and processing continues.

User Response: If the DDname is a control dataset (SLSCNTL, SLSCNTL2, or SLSSTBY), check the file allocation to ensure that the dataset does not have multiple extents, has either no blocksize specified or a blocksize of 4096, and that its organization is DA or PS. Correct the file allocation and rerun the SLICREAT program with all the expected DD statements.

Refer to the *HSC Configuration Guide* for more information about creating the control dataset(s).

SLS4556E Unable to create dataset for DDname CCCCCCCC

Explanation: SLICREAT was unable to create the dataset specified by the CCCCCCCC DD statement.

System Action: If the DDname is SLSCNTL, a return code of 12 is set and SLICREAT processing terminates. A return code of 8 is set if journaling was specified in the LIBGEN and no journal files could be created. For STBYONLY processing, SLICREAT terminates with a return code of 12. A return code of 4 is set in all other cases.

User Response: Check for other messages from the job, correct the problem(s) identified, and resubmit the SLICREAT job, or delete and redefine the dataset(s) and then resubmit the SLICREAT job. To format only the journal files, remove all the control dataset DD statements and any journal DD statements you do not wish to reformat, and resubmit the SLICREAT job. Refer to the *HSC Configuration Guide* for more information about creating the control dataset(s).

SLS4557I SLSCNTL DD not found, control dataset(s) not formatted

Explanation: SLICREAT was unable to find an SLSCNTL DD statement.

System Action: SLICREAT will not format any control datasets. The required CDS size is calculated and reported. Processing continues with journal dataset formatting.

For STBYONLY processing, SLICREAT terminates with a return code of 12.

User Response: None.

- SLS4558E** CDS size could not be calculated
- Explanation:** SLICREAT was unable to calculate the required CDS size.
- System Action:** SLICREAT processing ends with a return code of 12.
- User Response:** Check any error messages produced by SLICREAT and correct the indicated problem(s).
- SLS4559I** Additional control dataset successfully created
- Explanation:** SLICREAT successfully satisfied the STBYONLY request and created the additional CDS.
- System Action:** SLICREAT processing ends with a return code of 0.
- User Response:** None.
- SLS4560E** A CCCC LSM may not be connected to a CCCC LSM
- Explanation:** LIBGEN detected two different types of LSMs connected. A 9740 LSM may connect to 9740 LSMs only. A 8500 LSM may connect to 8500 LSMs only.
- System Action:** Processing continues. A return code of 0C is set.
- User Response:** Correct the SLILSM macro in error and resubmit the job.
- SLS4561E** Dataset specified by CCCCCC1 is an existing or CDS dataset; CCCCCC2 dataset not formatted
- Explanation:** SLICREAT identified an existing dataset specified by the CCCCCC1 DD statement. CCCCCC2 refers to the type of dataset being processed, control or journal. For control datasets, SLICREAT will not format over an existing dataset. For journal datasets, SLICREAT will not format over an existing CDS dataset. This message is issued if SLICREAT determines that one of its output files contained records prior to being formatted. For SLSJR nn , the output file was identified as an existing CDS dataset.
- System Action:** If the DD statement is a control dataset, no datasets are formatted and SLICREAT processing terminates. If the DD statement is a journal dataset, the control datasets (if specified) and any valid journal files are formatted. A return code of 12 is set in all cases.
- User Response:** Either assign a different dataset(s) or delete and redefine the specified dataset(s) and reexecute SLICREAT. Refer to Chapter 5, "Initializing the Control Data Sets," in the *HSC Configuration Guide* for more information about creating the control datasets.

SLS4562D DDDDDDDD NNNNNNNN is an existing CDS; reply "YES" if the CDS can be overwritten

Explanation: SLICREAT identified an existing CDS dataset NNNNNNNN specified by the DDDDDDDD DD statement.

This message is issued if SLICREAT determined that one of the output files contained records prior to being formatted. For SLSJRNNn, the output file was identified as an existing CDS dataset.

This message is issued for VM/HSC only.

System Action: SLICREAT waits for an operator response.

User Response: Respond with "YES" if the dataset can be overwritten.

:Any other response will terminate the SLICREAT process. SLS4561E will be issued to the SLICREAT SYS PRINT output messages.

SLS4563E The SMC is required for JES3; Start the SMC and resubmit the utility

Explanation: The SMC is required for SLIVERFY to locate the correct JES3 macro offsets to compare HSC library device addresses with actual system devices.

System Action: SLIVERFY processing terminates. A return code of 08 is set.

User Response: Start the SMC and resubmit the SLIVERFY utility.

SLS4564E Invalid ACS found; Number of SL8500 LSMs must be divisible by four.

Explanation: :An ACS was found that contained SL8500 LSMs. The number of LSMs defined in this ACS was not divisible by four.

System Action: SLICREAT processing terminates.

User Response: Correct the configuration file. Re-execute the LIBGEN and the SLICREAT utility.

SLS4602I Drive records are inconsistent with the CDS for LSM AA:LL; LSM will remain offline

Explanation: During an attempt to vary the LSM online, an inconsistency was found between drive records in the CDS and the HSC in-memory version, probably due to a SET SLIDRIVS utility.

System Action: The LSM remains offline.

User Response: Leave the LSM offline until the host is recycled.

SLS4610I Hardware Exception Status:

Explanation: HSC Hardware Exceptions

This command causes the LMU to be queried for the hardware status of the LMUs, each LSM, each CAP, each Robot Hand, each Pass-Thru Port, and each Station. Errors are reported in the format of

AA:LL:CC error message

where the *AA* is the ACS, the *LL* is the LSM, and the *CC* is the CAP identifier. The following error messages are possible:

- CAP Not Allocated: This means the CAP belongs to another partition.
- CAP Not Installed: This means the CAP is not physically installed.
- CAP Not Operational
- CAP Door is Open
- CAP Door is Unlocked
- CAP is Reserved by Partition *nnn* Host *nn*: Use the Display ACS command to find current partition IDs of ACSes and Display CDS command to show the hosts.
- Pass Thru Port is Inoperative
- Robot Hand is Inoperative
- Robot Hand needs Maintenance
- LSM is Not Ready
- LSM is Offline
- LSM is Offline Pending
- LSM is in Maint Mode
- LSM Door is Open
- CAP status not Available for this LSM
- LMU Compat 10 or less; not all functions supported: The LMU will not be able to respond correctly to some of the status queries until its microcode is updated. This condition will also cause SLS0662I LMU Response Error to be issued just before SLS4610I.
- Station *nn* has Inactive Connection: A hardware connection to the LMU is not usable. This may be normal for your configuration if the connection has never been made and is not necessary. The station number is in hex, so Station 0A is the tenth station, and Station 10 is really the sixteenth.
- Station *nn* Inoperative; Host not responding: The station number is in hex, so Station 0A is the tenth station, and Station 10 is really the sixteenth.

The following messages are summaries:

- No CAP problems were detected
- No Pass Thru Port problems were detected
- No Robot Hand problems were detected
- No LSM problems were detected
- No Station problems were detected

Please note that these results only mean that the LMU did not detect Hardware Errors. Something could be wrong with the software configuration, or that the LMU could not detect.

System Action: HSC processing continues.

User Response: None.

SLS4633I Display Drives Command

DRIVE	LOCATION	VOLSER	STATUS	MODEL	MEDIA
<i>UUUU</i>	<i>LLLLLLLLL</i>	<i>volser</i>	<i>SSSSSSSS</i>	<i>0000</i>	<i>MM...MM</i>

Explanation: This message is received in response to a Display DRives command with the DETail option. The display is status and related information for the drives defined by the LIBGEN esoterics. Display information includes:

UUUU

The drive ID. A four-character driveid (unit address).

LLLLLLLLLL

The drive location, *AA:LL:PP:NN*, or NONLIB (non-library).

volser

The volume serial number or “??” if HSC cannot determine the volser.

SSSSSSSS

The drive status. Drive statuses include:

- On drive
- Dismount
- Mounting
- Not rdy
- Offline
- Online
- (blank)

0000

The drive model.

MMMMMMMMMMMMMMMM

The media type supported by this drive, as specified or defaulted by the UNITATTR statement. In the absence of a UNITATTR, the supported media is determined by

the LMU and/or the UCB device type. It does not reflect the media type of a cartridge mounted on the drive.



Note: A blank media type will be displayed when the media type for a drive cannot be determined.

System Action: None.

User Response: None.

SLS4634I Journal command is invalid when Journaling Technique is not enabled

Explanation: The Journal command was entered but the CDS Journaling Technique is not enabled.

System Action: The command is not executed.

User Response: None.

SLS4640I ALLOC *pppppppp* is no longer supported. Use SMC commands.

Explanation: The ALLOC parameter *pppppppp* is no longer supported by HSC. The function has been moved to the SMC product. Use the SMC command to control this function.

System Action: The command continues to process parameters. The unsupported ALLOC parameters are ignored.

User Response: Use the SMC commands to control processing.

SLS4641I {ALLOC|MNTD} *pppppppp* is supported only for downlevel SMC compatibility

Explanation: The specified ALLOC or MNTD parameter *pppppppp* is effective in HSC only in support of downlevel SMC clients. If a current level SMC system is interfacing with this HSC then use the corresponding SMC ALLOCDEF or MOUNTDEF command to control this option.

System Action: The command continues to process parameters. The specified ALLOC or MNTD parameters are updated for downlevel SMC systems but will not be reflected in processing for current level SMC systems.

User Response: Use the corresponding SMC ALLOCDEF and MOUNTDEF commands to specify options to control processing on current SMC systems.

SLS4642I TREQDEF is supported only for downlevel SMC compatibility

Explanation: The TREQDEF command to load TAPEREQ definitions is effective in HSC only in support of downlevel SMC clients. If a current level SMC system is interfacing with this HSC then use the corresponding SMC TREQDEF command to load these definitions.

System Action: The command continues to process. The TAPEREQ definitions are loaded in the HSC but will be used only for downlevel SMC system requests.

User Response: Use the corresponding SMC TREQDEF command to load the TAPEREQ definitions in the SMC system.

SLS4643I {CAPPREF} rejected; AUTO CAP services are not supported on a
PARTITIONED ACS

Explanation: The AUTO CAP feature is not supported on a partitioned ACS. CAPs cannot be put into AUTO mode on this ACS.

System Action: The command is rejected.

User Response: HSC can continue to run without the AUTO CAP feature on this ACS. In order to use the AUTO CAP feature on this ACS, the ACS must not be partitioned.

SLS4650E This HSC release does not support Host/LMU Interface compatibility
level *NN* at LMU station *XXXX*

Explanation: This HSC release does not support Host/LMU Interface compatibility level *NN* returned from LMU station *XXXX*.

System Action: The LMU is not varied online.

User Response: Report this to StorageTek Hardware Support. Install an LMU microcode level on the LMU that is compatible with this HSC release.

SLS4682D ORH: EXTEND OR ABORT? ACS *AA*, SEQNO *BBCCC*, *CCC1*, *CCC2*, *volser*

Explanation: The HSC is asking the system operator what to do with a request whose response wait time interval has expired. Message SLS0681I was previously issued for this request.

<i>AA</i>	ACSid
<i>BB</i>	HOSTid
<i>CCC</i>	the request sequence number (missing if not on the Active Request Queue)
<i>CCC1</i>	the queue the request is waiting on: ACT stands for the Active Request Queue WTG stands for the Waiting Request Queue TMP stands for the Temp Outage Queue
<i>CCC2</i>	the type of request: DMT Dismount MNT Mount MOV Move SWP Swap
<i>volser</i>	is the volume serial number of the cartridge.

System Action: Task waits for operator to enter a reply.

User Response: Answer can be one or more letters of one of the following words:

EXTEND	HSC will extend the response wait time interval another increment to let the LMU finish working on this request. EXTEND is the recommended reply when SLS4682D is first issued for a given LMU request. (Each LMU request is identified by the unique SEQNO.) EXTEND is the recommended response if a dual-LMU switch has just occurred.
ABORT	HSC will free the selected volume so that the operator can enter manual override commands to move the cartridge. ABORT will purge the request from the HSC internal queues. Replying ABORT will probably mean that manual intervention will be necessary. Replying ABORT will also produce an SVCDUMP. A reply of ABORT is recommended if the LMU has reinitialized or if the request has been extended previously.

- SLS4736E** Incompatible HSC found active on HOST *HHHHHHHH*
- Explanation:** During initialization, HSC discovered an incompatible HSC level running on the indicated host. The most probable cause is running a previous release without coexistence PTFs applied.
- System Action:** HSC terminates.
- User Response:** Terminate the HSC on the indicated host and reinitialize it with a compatible level of HSC.
- SLS4737E** CDS directory recovery operation failed
- Explanation:** An attempt was made to rebuild the database directory, but an error was encountered that made it impossible to continue.
- System Action:** HSC or utility terminates after taking an SVC dump.
- User Response:** Restore the CDS from backups. Save the dump and contact StorageTek Software Support.
- SLS4738I** CDS *CCCC...CCCC* disabled; inconsistent copy flag found on
- Explanation:** During initialization or database reserve a CDS copy was found to be inconsistent as a result of a partially completed CDS Merge, copy, or other process.
- System Action:** The inconsistent copy is disabled.
- User Response:** Enable this CDS to force synchronization with a valid copy.

SLS4739E Cannot enable new CDS *CCCC...CCCC1*; *CCCCCCCC2*

Explanation: An attempt to activate a new CDS data set, *CCCC...CCCC1*, with a CDs Enable command has failed because the data set is either unknown or unsuitable for use as a CDS copy. *CCCCCCCC2* is one of the the following reasons:

- Invalid BLKSIZE (the BLKSIZE must be 4096)
- Invalid DSORG (the DSORG must be PS)
- More than one extent
- Invalid UCB type (the data set must reside on a DASD)
- Could not obtain VTOC info

System Action: The HSC continues operation with the current CDS definitions.

User Response: If attempting to activate a renamed existing CDS copy, make sure that the data set was properly renamed and that the DS*n* parameter was correctly specified on the CDs Enable command. If attempting to relocate a new CDS copy and the reason was “Could not obtain VTOC info”, then it is likely that the DS*n*, NEW*Loc*, NEW*Vol*, and/or NEW*Unit* parameters were either missing or incorrectly specified. For all other reasons, if the DS*n* parameter specified the correct data set, then the data set is unsuitable for use as a CDS; reallocate a new CDS data set with the proper attributes and reissue the CDs Enable command.

SLS4740E New CDS *CCCC...CCCC* is of insufficient size; capacity is *DDD1* blocks, required capacity is *DDD2* blocks

Explanation: An attempt to activate a new CDS data set, *CCCC...CCCC*, with a CDs Enable command has failed because the data set is not big enough. It can contain only *DDD1* 4096-byte blocks but the current CDS requires at least *DDD2* blocks.

System Action: The HSC continues operation with the current CDS definitions.

User Response: Reallocate a larger new CDS data set and reissue the CDs Enable command.

SLS4741E BSAM Open failed for new CDS *CCCC...CCCC*

Explanation: An attempt to activate a new CDS data set, *CCCC...CCCC*, with a CDs Enable command has failed during its initialization process. A BSAM Open operation failed.

System Action: The HSC continues operation with the current CDS definitions.

User Response: Look for other error messages from BSAM that might help isolate the error. If the error cannot be resolved, contact StorageTek Software Support.

SLS4742E BSAM Write failed for new CDS *CCCC...CCCC*, block *DDDD*

Explanation: An attempt to activate a new CDS data set, *CCCC...CCCC*, with a CDS Enable command has failed during its initialization process. A BSAM Write operation failed writing block number *DDDD*.

System Action: The HSC continues operation with the current CDS definitions.

User Response: Look for other error messages from BSAM that might help isolate the error. If it is a permanent I/O error, delete and reallocate a new CDS data set and reissue the CDS Enable command. If the error cannot be resolved, contact StorageTek Software Support.

SLS4743I CDS EXpand failed, block count not greater than current size.

Explanation: An attempt was made to expand active CDS, but HSC has determined there is no change in the current size of the CDS.

System Action: CDS EXpand fails.

User Response: Allocate new CDSs of a larger block size. CDS Enable the newly sized CDSs before issuing the CDS EXpand command.

SLS4744E Expand of the Secondary CDS has failed.

Explanation: CDS EXpand has detected an error while reading the Primary CDS and expanding the Secondary CDS.

System Action: CDS Expand command terminates.

User Response: Investigate HSC Job Log and System logs for Database I/O errors and any related HSC messages. Correct the errors indicated. Restore all CDS files from backup copies and reenter CDS EXpand command.

SLS4745E Expand of Primary CDS has failed.

Explanation: CDS EXpand has detected an error while expanding the Primary CDS.

System Action: CDS Expand command terminates.

User Response: Investigate HSC Job Log and System logs for Data base I/O errors and any related HSC messaes. Correct the errors indicated. Restore all CDS files from backup copies and reenter CDS EXpand command.

SLS4746E Copies to Primary/Standby CDS have failed.

Explanation: Secondary CDS copy to either Primary/Standby CDS encountered an error. Status of Primary/Standby CDS is unpredictable.

System Action: CDS Expand command terminates.

User Response: Investigate HSC Job Log and System logs for Data base I/O errors and any related HSC messages. Correct the errors indicated. Restore all CDS files from backup copies and reenter CDS EXpand command.

SLS4747E CDS DALM updates encountered an error.

Explanation: DALM record updates to either Primary or Secondary CDS encountered an error. DALM record status is unpredictable.

System Action: CDS Expand command terminates.

User Response: Investigate HSC Job Log and System logs for Data base I/O errors and any related HSC messages. Correct the errors indicated. Restore all CDS files from backup copies and reenter CDS EXpand command.

SLS4748I CDS EXpand has completed successfully.

Explanation: All CDSs now reflect the new database size.

System Action: HSC CDSs return to normal work activities.

User Response: Update HSC startup parms with new CDS names, if appropriate.

SLS4749I CDS EXpand has completed unsuccessfully.

Explanation: An error has occurred during the CDS EXpand process.

System Action: HSC issued an EXpand related messages prior to this message.

User Response: Investigate HSC Job Log and System Log for I/O errors and any related HSC messages. Correct the errors indicated. Restore all CDSs from backup copies and reenter CDS EXpand command.

SLS4750I Expanded CDS recognized and adopted

Explanation: It was determined that the CDS has been expanded. This was the result of an operator CD's EXpand command issued on another host. The expanded size of the CDS is adopted on this host.

System Action: The HSC continues operation.

User Response: None.

SLS4800I {License key | Emergency key | Trial period} expires in *nn* days:
Product=*product-id*

Explanation: The license key, emergency key or trial period for the product will expire in the number of days indicated. For license key processing, this message is issued during product initialization and at midnight beginning 60 days from the license expiration date. For emergency keys, this message is issued during product initialization and at midnight beginning 7 days from the emergency key expiration date. For trial period processing, this message is issued during initialization and at midnight during the entire 75 day trial period.

System Action: The product or feature continues to operate.

User Response: Customers should acquire a permanent license key from StorageTek for this product. Operation of the product beyond the expiration date may violate your license agreement. Either discontinue use of the product on or before the expiration date or obtain a new license key from StorageTek.

SLS4801I {License Key | Emergency Key | Trial period} has expired:
Product=*product-id*

Explanation: During license key, emergency key or trial period validation (performed during product initialization and at midnight), the identified key was found to be expired or 75 days has passed since the the product initialized on a trial period.

System Action: Permanent license keys - The product will continue to operate and, additionally, product start-up will not be prevented. However, continued operation of the product may violate your license agreement.

Emergency keys and trial periods - The product will terminate and subsequent product start-up will be prevented.

User Response: Discontinue use of the product until a new license key is obtained from StorageTek.

SLS4802E Product *product-id* is not licensed at this site

Explanation: A valid license key was found, however the particular product for the customer site was found not to be licensed.

System Action: The product will not continue to operate and product start-up will be prevented.

User Response: Contact StorageTek to obtain a new license key that enables all registered products at your site.

SLS4803E License Key validation error: Product=*product-id*

Explanation: An error occurred while attempting to validate the license key for a product. The license key information is either missing, incorrect, or outdated. Missing license key information will be indicated by message SLS4802E.

System Action: If this condition is detected during product initialization, execution of the product is terminated. If detected at midnight, processing continues.

User Response: Check the information contained in the LKEYINFO statement for the product. All information must exactly match that provided to Sun Microsystems SMD when the license key was obtained. Correct any errors.

If the information appears to be correct, contact Sun Microsystems Software Support.

SLS4804I License Key does not allow use of feature:
Product=*product-id* Feature=*feature-id*.
Feature disabled.

Explanation: An attempt was made to enable a feature that is not authorized by the product license key. The feature is identified by *feature-id*.

System Action: Processing continues with the feature disabled.

User Response: Either remove the feature specification from your HSC or LibraryStation initialization parameters or obtain a license key from StorageTek that authorizes its use.

SLS4805I vvvvvvvv keyType valid for product *pppppppp*

Explanation: The LKEYDEF command was entered. For each product that the key authorizes, message SLS4805I is issued. The vvvvvvvv is the PROD value in the LKEYINFO statement. The *pppppppp* will be the product name that the key authorizes. The keyType will be one of the following:

License Key
Trial Period
Emergency Key

System Action: None.

User Response: None.

SLS4960I Move "To" panel is frozen

Explanation: A MOVE command or utility function was attempted specifying a move to a frozen panel.

System Action: The requested command or utility terminates. The move is not performed.

User Response: Re-enter the command or utility specifying a TPanel that is not frozen. If the panel should not be frozen, use the SET FREEZE(OFF) utility to unfreeze it.

SLS4970I SEN QUEUE DISPLAY STATUS

CURRENT REQUESTORS 99999999

REQNAME RRRRRRRR LNRNAME LLLLLLLL TOKEN TTTTTTTT

FLAGS FFFFFFFF

EVENT EEEEEEEE

Explanation: This is the output from the Display SEN Queue command. The output produced varies depending on the parameters specified. If no parameters are specified all entries in the SEN QUEUE are displayed. If REQname is specified then only Requestors matching REQname will be displayed. If LNRname is specified REQname must be specified. If LNRname is specified then only Requestors and Listeners matching REQname and LNRname will be displayed.

99999999 Number of Requestors on the SEN QUEUE

RRRRRRRR Requestor name

LLLLLLLL Listener name

TTTTTTTT Hex display of the Requestor Token

FFFFFFF Description of the processing flags for the SEN QUEUE
ENTRY

EEEEEEE Description of the Event to be Listened for

System Action: None.

User Response: None.

- SLS4971I** Significant Event Notification facility not active
- Explanation:** An attempt was made to display SEN Queue entries. However, Significant Event Notification facility is not active.
- System Action:** The DISPLAY SEN command is rejected.
- User Response:** Make certain you are running the correct version of HSC. If you are certain you are running the correct version contact StorageTek HSC support.
- SLS4972I** SEN QUEUE IS EMPTY
- Explanation:** An attempt was made to display SEN Queue entries. However, the SEN QUEUE contained no entries.
- System Action:** Processing continues.
- User Response:** Make certain you have run the task to add entries to the SEN QUEUE. If the task has run correctly contact StorageTek HSC support.
- SLS4973I** REQNAME *nnnnnnnn* NOT FOUND
- Explanation:** An attempt was made to display a specific Requestor on the SEN QUEUE. However, the specified Requestor was not found.
- System Action:** Processing continues.
- User Response:** Make certain you have spelled the Requestor name correctly.
- SLS4974I** LNRNAME *nnnnnnnn* NOT FOUND
- Explanation:** An attempt was made to display a specific Listener on the SEN QUEUE. However, the specified Listener was not found.
- System Action:** Processing continues.
- User Response:** Make certain you have spelled the Listener name correctly.
- SLS5673I** HSC VCI Client Controller started
- Explanation:** The HSC VTCS Communication Interface Client Controller has started. The HSC is ready to issue requests to the VSM system.
- System Action:** HSC processing continues.
- User Response:** None.

- SLS5683I** Client Receive task attach failed
- Explanation:** The Client Receive task failed to attach.
- System Action:** HSC processing continues.
- User Response:** Determine the cause of the attach failure. Previous messages will identify the cause of the failure.
- SLS6001I** Vary online request cancelled by subsequent vary offline for ACS AA
- Explanation:** While executing a request to vary a station or ACS online, the ACS was varied offline by another request.
- System Action:** The vary online request is not executed.
- User Response:** If the ACS or station is to be varied online, reissue the request.
- SLS6002I** No stations defined for ACS AA
- Explanation:** A vary online request was issued for ACS AA, but no stations were found for this ACS.
- System Action:** None. The ACS remains disconnected.
- User Response:** Execute SET SLISTATN to define stations for the ACS. Then reissue the Vary ACS command.
- SLS6003I** Vary station not allowed for network attached ACS AA
- Explanation:** Network connections were defined for ACS AA via an LMUPATH parameter; therefore; the vary station command is not applicable.
- System Action:** :The command is not processed.
- User Response:** HSC automatically retries the network TCP/IP socket communication to the LMU for 30 minutes. Verify TCP/IP and LMUs are operational.
- SLS6004I** ACS AA forced offline due to configuration mismatch for station C...C
- Explanation:** In attempting to establish an LMU connection via station C...C, a mismatch was detected between the CDS and the LMU configuration definition. A previously issued message explains where the mismatch occurred.
- System Action:** All stations for this ACS are forced offline.
- User Response:** Check for previous messages and determine why the configuration does not match. If the problem persists, contact StorageTek Software Support.

- SLS6005I** Network attach function *CCCCCCCC* failed for station *C...C* with
errno *NNNN*
- Explanation:** The network attach function *CCCCCCCC* failed.
- System Action:** The HSC begins network recovery for this station.
- User Response:** Refer to IBM TCP/IP for MVS Application Programming Interface Guide to determine the cause of the failure and take the appropriate action to correct the error. Once corrected, the next iteration for network connectivity to this station will reestablish communication to the LMU.
- SLS6006I** Network attachment failed for station *C...C* because function
CCCCCCCC could not be loaded.
- Explanation:** TCP/IP API load module cannot be loaded.
- System Action:** The station is varied offline.
- User Response:** Ensure TCP/IP is installed, configured and running properly on this host. When the problem is corrected recycle the HSC started task.
- SLS6007I** TCP/IP failure for station *C...C* detected
- Explanation:** Asynchronous select function failure.
- System Action:** The HSC begins network recovery for this station.
- User Response:** Ensure TCP/IP is installed, configured and running properly for this host. Verify the LMUs are operational. Once network problem is resolved, the next iteration for network connectivity to this station will reestablish communication to the LMU.
- SLS6008I** Network attach function *CCCCCCCC* failed because station *C...C* is no
longer connected
- Explanation:** The socket connection to the LMU has been lost.
- System Action:** The HSC begins network recovery for this station.
- User Response:** Ensure TCP/IP is installed, configured and running properly on this host. Verify the LMUs are operational. Once network problem is resolved, the next iteration for network connectivity to this station will reestablish communication to the LMU.
- SLS6009I** No stations were found offline for ACS *AA*
- Explanation:** A Vary ACS ONline was issued for ACS *AA*, but there were no stations marked as offline.
- System Action:** None.
- User Response:** None.

- SLS6010I** ACS, STation, or station addresses required for Vary command
- Explanation:** An attempt was made to enter a Vary request, but neither the ACS or STation keyword or a list of device numbers was specified.
- System Action:** The command is rejected.
- User Response:** Re-enter the command specifying either ACS, or STation, or list of device numbers.
- SLS6011I** VARY {ACS AA|STation C...C} OFFline not allowed; CAP is reserved to this host
- Explanation:** An attempt was made to Vary the ACS OFFline, either by specifying the ACSid or the device address of the last STation. The system has detected that a CAP within the ACS is reserved to this host.
- System Action:** The command is rejected.
- User Response:** Issue the command Display CAP AA to display the status of all CAPs in the ACS. Terminate the CAP activity for the active CAP and reissue the command.
- SLS6012E** ACS nn: Recovery of network connection to station C...C is now active
- Explanation:** The HSC TCP/IP interface has detected an error or timeout condition with station C...C. Network recovery begins.
- System Action:** The HSC will continue trying to reestablish the connection between its socket and the remote station socket every 10 seconds for a total of 30 minutes.
- User Response:** In a dual LMU environment, a switch to the standby station can be done if other host processing is not greatly impacted. Otherwise, diagnose and correct the network problem with the LMU or host. Once corrected, the next iteration for network connectivity will reestablish communication to the LMU.
- SLS6013I** ACS nn: Recovery of network connection to station C...C successful
- Explanation:** The HSC has successfully recovered network connectivity to station C...C.
- System Action:** The HSC will redrive LMU requests that have accumulated during recovery.
- User Response:** None.

SLS6014E ACS nn: Unable to reestablish network connection to station C...C

Explanation: The recovery process to reestablish network connectivity to station C...C has timed out.

System Action: HSC discontinues further connection attempts to the station. The station is considered in error. In a single LMU environment, the ACS is marked offline. In a dual LMU environment, the ACS is marked offline when network recovery has timed out on both stations.

User Response: In a single LMU environment, the ACS can be varied online after the network problem is corrected. In a dual LMU environment, the ACS can be varied online after recovery attempts for both stations have timed out. Note, in both instances all outstanding LMU requests are purged.

SLS6015I ACS AA failed to come ONLINE because it is unallocated

Explanation: The HSC has determined that this ACS is UNALLOCATED. The HSC cannot automate cartridge motion requests with the current configuration so the ACS stays OFFLINE.

System Action: None, the ACS stays OFFLINE.

User Response: To enable this ACS run NCO ADD ACS otherwise no other action is required and the ACS remains OFFLINE.

SLS6024I {AUDIT|CAPPREF AUTO|ENTER|EJECT|MOVE|SCREDIST|VARY ONLINE}
rejected for {CAP XX:XX:XX|ACS XX|STATION XXXX}, DR test active

Explanation: A CAPPREF, ENTER, EJECT, MOVE or VARY command, or an AUDIT, EJECT, MOVE, or SCREDIST utility function was requested but could not be performed because it conflicts with an active DR test. The CAP, ACS, or STATION where the function was not permitted is identified.

System Action: The HSC continues processing. The requested function cannot be performed until the DR test is terminated.

User Response: Wait until the DR test is terminated before attempting to perform the requested function on a production site HSC. The requested function can never be performed from a DR test site HSC.

SLS6027I ENTER rejected; TLSM ACS AA does not equal CAP ACS AA

Explanation: An attempt to process an ENter command was rejected because the LSMid specified by the TLSM parameter resides in a different ACS than the CAP.

System Action: The command is rejected.

User Response: Re-enter the command specifying a CAPid and a TLSM LSMid in the same ACS.

- SLS6028I** No scratch volumes meet eject criteria in ACS AA
- Explanation:** An Eject command was issued specifying the SCRTCH parameter. A CAP was requested from ACS AA or no CAP identifier was specified and the command defaulted to ACS 00. ACS AA did not contain any scratch volumes as requested by the parameters of the Eject command.
- System Action:** The Eject command continues.
- User Response:** Re-enter the Eject command specifying scratch volume criteria for scratch volumes contained in ACS AA.
- SLS6050I** *MMMMMMMM* macro failure RC=XXXX, reason code=XXXXXXXX
- Explanation:** The SLUCONDB utility program received an error invoking system macro (*MMMMMMMM*). The return code (XXXX) is the contents of R15. The reason code (XXXXXXXX) is the contents of R0.
- System Action:** The utility terminates with a return code of 8.
- User Response:** Determine and correct the problem. (Refer to the appropriate manual for the specified macro.) Then execute the utility again.
- SLS6051I** Insufficient work area length for CCC entries;increase value in program for max entries
- Explanation:** The data space work area created by the SLUCONDB utility program is not large enough to accommodate the number of CDS or TMC (CCC) records extracted. The data space size must be increased, which is the value in the field DATSPASZ.
- System Action:** The utility terminates with a return code of 8.
- User Response:** Increase the data space size value in the field DATSPASZ, then assemble and link the SLUCONDB program, and execute the utility again.
- SLS6052I** No CCC records found to extract
- Explanation:** The SLUCONDB utility program attempted to extract CDS or TMC (CCC) records, but no records were extracted.
- System Action:** The utility terminates with a return code of 4.
- User Response:** Determine if the results are correct, or determine the problem and execute the utility again.

SLS6053I QCDS error (RC=DDDD) for function CCCCCCCCC

Explanation: The SLUCONDB utility program received an error (DDDD) invoking the SLSUREQ QCDS function (CCCCCCCC).

System Action: The utility terminates with a return code of 8.

User Response: Determine and correct the problem. (Refer to the HSC System Programmer's Guide for the explanation of the return code for the specified function.) Then execute the utility again.

SLS6054E VTCS CCCCCC CDS level is incompatible with utility maintenance level.

Explanation: CCCCCC CDS was found to be of a type that is not supported by the current Merge utility. VTCS related Merge, supports extended mode formats for the 'to' and 'from' CDS.

System Action: Merge will not populate the 'to' CDS with VTCS related resources.

User Response: None.

SLS6055I Merge unlinking VTV VVVVVV from MVC MMMMMM Maximum supported copies reached.

Explanation: Merge processing is unlinking a copy of VTV VVVVVV from MVC MMMMMM during the process of merging the 'to' and 'from' CDS's. Merge has detected that the 'to' CDS does not support the same number of migrated copies of the VTV as the 'from' CDS. Extra copies will be unlinked from their respective MVC's.

System Action: Processing continues with populating the 'to' CDS.

User Response: None.

SLS6086I Hostid CCCCCCCC already defined in the CDS

Explanation: The Newhost hostid CCCCCCCC is a duplicate of an existing hostid in the database.

System Action: The utility terminates processing.

User Response: Select a new hostid and resubmit the utility.

Hint: SLS7000E

subsystem name is blank

Explanation: An error has occurred during validation of the JCL-supplied PARM= information.

System Action: Processing ends with RC=8.

User Response: Specify a non-blank subsystem name and rerun the PIT copy.

SLS7001E parm too short

Explanation: An error has occurred during validation of the JCL-supplied PARM= information.

System Action: Processing ends with RC=8.

User Response: Specify the missing PARM information and rerun the PIT copy.

SLS7002E parm too long

Explanation: An error has occurred during validation of the JCL-supplied PARM= information.

System Action: Processing ends with RC=8.

User Response: Remove the excess PARM information and rerun the PIT copy.

- SLS7003E** invalid option
- Explanation:** An error has occurred during validation of the JCL-supplied PARM= information.
- System Action:** Processing ends with RC=8.
- User Response:** Specify an option of AB, PC, and/or RR and rerun the PIT copy.
-
- SLS7004E** invalid function
- Explanation:** An error has occurred during validation of the JCL-supplied PARM= information.
- System Action:** Processing ends with RC=8.
- User Response:** Specify a function value of COPY or TEST and rerun the PIT copy.
-
- SLS7005E** logic error - invalid function
- Explanation:** An illogical condition or unexpected data value occurred during processing.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.
-
- SLS7006E** CVTJESCT address is zero
- Explanation:** An illogical condition or unexpected data value occurred during processing.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.
-
- SLS7007E** JESSCT address is zero
- Explanation:** An illogical condition or unexpected data value occurred during processing.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

- SLS7008E** subsystem ssss not active
- Explanation:** An error has occurred during validation of the JCL-supplied information.
- System Action:** Processing ends with RC=12.
- User Response:** The wrong subsystem name was specified in the PARM statement. Correct the name and rerun the PIT copy.
- SLS7009E** ASCB not found
- Explanation:** An illogical condition or unexpected data value occurred during processing.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.
- SLS7010I** SSCVT located for subsystem ssss
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.
- SLS7011I** ASCB for HSC job name *jjjjjjjj* has asid *aaaa*
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.
- SLS7012E** DCV address is zero
- Explanation:** An illogical condition or unexpected data value occurred during processing.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

- SLS7013E** DCV primary info address is zero
- Explanation:** An illogical condition or unexpected data value occurred during processing.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.
- SLS7014E** JCL CDS name does not match primary CDS name
- Explanation:** An error has occurred during validation of the JCL-supplied information.
- System Action:** Processing ends with RC=12.
- User Response:** The CDS name specified on the SLSCNTL DD is not the Primary CDS being used by the subsystem. Specify the data set name listed in the accompanying SLS7025I message on the SLSCNTL DD and rerun the PIT copy.
- SLS7015I** JCL CDS name matches primary CDS name
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.
- SLS7016E** qname is blank or binary zeros
- Explanation:** An illogical condition or unexpected data value occurred during processing.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.
- SLS7017E** {ADRDSU level unknown | ADRDSU level unsupported}
- Explanation:** An unknown or unsupported level of DFSMSdss was encountered. DFSMSdss must be at DFSMS 1.3 or later.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy using a supported level of DFSMSdss, or use SIBBATCH or FDRSNAP instead

- SLS7018E** LVT address is zero
- Explanation:** An illogical condition or unexpected data value occurred during processing.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.
- SLS7019E** invalid PIT copy method
- Explanation:** An error has occurred during validation of the JCL-supplied PARM= information.
- System Action:** Processing ends with RC=8.
- User Response:** Specify a PIT copy method of DSS, FDR, or SNP and rerun the PIT copy.
- SLS7020E** JCL CDS name does not match DHB CDS name
- Explanation:** An error has occurred during validation of the JCL-supplied information.
- System Action:** Processing ends with RC=12.
- User Response:** The CDS name specified on the SLSCNTL DD is not the Primary CDS being used by the subsystem. Specify the data set name listed in the accompanying SLS7025I message on the SLSCNTL DD and rerun the PIT copy.
- SLS7021I** JCL CDS name matches DHB CDS name
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.
- SLS7022E** DEB address is zero
- Explanation:** An illogical condition or unexpected data value occurred during processing.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

- SLS7023E** UCB address is zero
- Explanation:** An illogical condition or unexpected data value occurred during processing.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.
- SLS7024E** SLSCNTL DD dummied
- Explanation:** An error has occurred during validation of the JCL-supplied information.
- System Action:** Processing ends with RC=12.
- User Response:** Undummy the DD statement, specify the correct Primary CDS data set name on the SLSCNTL DD statement, and rerun the PIT copy.
- SLS7025I** primary CDS NAME = *primarycdsdatasetname*
- Explanation:** Information only. The data set name of the primary CDS for the specified subsystem is identified by this message. Specify this data set name on the SLSCNTL DD if a SLS7014E or SLS7020E message is issued.
- System Action:** Processing continues.
- User Response:** None.
- SLS7026E** invalid option value
- Explanation:** An error has occurred during validation of the JCL-supplied PARM= information.
- System Action:** Processing ends with RC=8.
- User Response:** Specify an option of AB, PC, and/or RR and rerun the PIT copy.
- SLS7027E** duplicate option value
- Explanation:** An error has occurred during validation of the JCL-supplied PARM= information.
- System Action:** Processing ends with RC=8.
- User Response:** Remove the duplicated option value and rerun the PIT copy.

SLS7028I *mmmmmmmm*

Explanation: Information only. The message text (*mmmmmmmm*) consists of one of the following:

- HSC subsystem name = *ssss*
- COPY function is in effect
- TEST function is in effect
- FDRSNAP method is in effect
- DFSMSDSS method is in effect
- SNAPSHOT method is in effect
- reserve retry WTOR option is enabled
- PIT copy WTOR option is enabled
- ABEND option is enabled
- no options specified

System Action: Processing continues.

User Response: None. More than one message SLS7028I is issued for a single invocation of SLUPCOPY.

SLS7029E subsystem asid is zero

Explanation: An illogical condition or unexpected data value occurred during processing.

System Action: Processing ends with RC=12.

User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7031I point-in-time copy successful

Explanation: Information only.

System Action: Processing ends normally with RC=0.

User Response: None. The actual PIT copy is successful.

SLS7032I point-in-time copy aborted

Explanation: Information only.

System Action: Processing ends with RC=20.

User Response: None. The actual PIT copy is aborted.

SLS7033I simulated point-in-time copy aborted

Explanation: Information only.

System Action: Processing ends with RC=20.

User Response: None. The simulated PIT copy is aborted.

SLS7034I simulated point-in-time copy complete

Explanation: Information only.

System Action: Processing ends normally with RC=0.

User Response: None. The simulated PIT copy is successful.

SLS7035E point-in-time copy invalid

Explanation: A non-zero completion code was returned from the PIT copy. The PIT copy is invalid.

System Action: Processing ends with RC=12.

User Response: Delete the invalid PIT copy data set, determine the cause of the problem from the SIBBATCH, DFSMSdss, or FDRSNAP messages, fix the problem, and rerun the PIT copy. If the problem persists, retain the invalid PIT copy data set and contact Sun StorageTek Software Support for SIBBATCH or SLUPCOPY problems, IBM for DFSMSdss problems, or Innovation Data Processing for FDRSNAP problems.

SLS7040I JCL CDS name = *jclcdsdatasetname*

Explanation: Information only. The data set name specified on the SLSCNTL DD statement should appear in the message text and may be useful in resolving problems related to messages SLS7014E and SLS7020E.

System Action: Processing continues.

User Response: None.

SLS7041I SSCVT ssss has an active LVT

Explanation: Information only.

System Action: Processing continues.

User Response: None.

- SLS7042I** ASCBJBNI = *jobname*
Explanation: Information only.
System Action: Processing continues.
User Response: None.
- SLS7043I** ASCBJBNS = *taskname*
Explanation: Information only.
System Action: Processing continues.
User Response: None.
- SLS7044I** ADRDSSU LEVEL = *ppvrrmm*
Explanation: Information only. *pp* is the product number, *vv* is the version number, *rr* is the release number, and *mm* is the modification level of DFSMSdss.
System Action: Processing continues.
User Response: None.
- SLS7050E** ESTAE failed. R15=XXXXXXXX
Explanation: An error has occurred attempting to use an IBM service.
System Action: Processing ends with RC=16.
User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.
- SLS7051E** RDJFCB failed. R15=XXXXXXXX
Explanation: An error has occurred attempting to use an IBM service.
System Action: Processing ends with RC=16.
User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7052E LOCASCB failed. R15=XXXXXXXX

Explanation: An error has occurred attempting to use an IBM service.

System Action: Processing ends with RC=16.

User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7053E ATTACH failed. R15=XXXXXXXX

Explanation: An error has occurred attempting to use an IBM service.

System Action: Processing ends with RC=16.

User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7054E OPEN failed. R15=XXXXXXXX

Explanation: An error has occurred attempting to use an IBM service.

System Action: Processing ends with RC=16.

User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7055E RESERVE failed. R1=XXXXXXXX R15=XXXXXXXX

Explanation: An error has occurred attempting to use an IBM service.

System Action: Processing ends with RC=16.

User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7056E CDS DHB READ failed. R15=XXXXXXXX

Explanation: An error has occurred attempting to use an IBM service.

System Action: Processing ends with RC=16.

User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7057E {MAINLINE | ERROR MSG} DEQ failed. R1=XXXXXXXX R15=XXXXXXXX

Explanation: An error has occurred attempting to use an IBM service.

System Action: Processing ends with RC=16.

User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7058E DETACH failed. R15=XXXXXXXX

Explanation: An error has occurred attempting to use an IBM service.

System Action: Processing ends with RC=16.

User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7059E {MAINLINE | ERROR MSG} CLOSE failed. R15=XXXXXXXX

Explanation: An error has occurred attempting to use an IBM service.

System Action: Processing ends with RC=16.

User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7060E ADRDSSU LOAD failed. R1=XXXXXXXX R15=XXXXXXXX

Explanation: An error has occurred attempting to use an IBM service.

System Action: Processing ends with RC=16.

User Response: Make sure that the respective software product is actually installed on the system used for the PIT copy, then make sure that the necessary program libraries are in the system linklist.

SLS7061E FDRSNAP LOAD failed. R1=XXXXXXXX R15=XXXXXXXX

Explanation: An error has occurred attempting to use an IBM service.

System Action: Processing ends with RC=16.

User Response: Make sure that the respective software product is actually installed on the system used for the PIT copy, then make sure that the necessary program libraries are in the system linklist.

- SLS7062E** SIBBATCH LOAD failed. R1=XXXXXXXX R15=XXXXXXXX
- Explanation:** An error has occurred attempting to use an IBM service.
- System Action:** Processing ends with RC=16.
- User Response:** Make sure that the respective software product is actually installed on the system used for the PIT copy, then make sure that the necessary program libraries are in the system linklist.
- SLS7063E** unable to acquire reserve
- Explanation:** An error has occurred attempting to use an IBM service.
- System Action:** Processing ends with RC=16.
- User Response:** Rerun the PIT copy with the RR option, or wait until there is less RESERVE activity to the HSC Primary CDS.
- SLS7070I** read jfcb successful for SLSCNTL DD
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.
- SLS7071I** open successful for SLSCNTL DD
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.
- SLS7072I** reserve successful for SLSCNTL DD
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.
- SLS7073I** CDS DHB read successful
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.

- SLS7074I** attach successful
Explanation: Information only.
System Action: Processing continues.
User Response: None.
- SLS7075I** TCB user CC=uuuu, system CC=yyyy
Explanation: Information only.
System Action: Processing continues.
User Response: None.
- SLS7076I** detach successful
Explanation: Information only.
System Action: Processing continues.
User Response: None.
- SLS7077I** {MAINLINE | ERROR MSG} DEQ successful for SLSCNTL DD
Explanation: Information only.
System Action: Processing continues.
User Response: None.
- SLS7078I** {MAINLINE | ERROR MSG} CLOSE successful for SLSCNTL DD
Explanation: Information only.
System Action: Processing continues.
User Response: None.

SLS7080I ESTAE routine: no SDWA

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. A System Diagnostic Work Area (SDWA) is not present.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7081I ESTAE routine: SDWA present

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. A System Diagnostic Work Area (SDWA) is present.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7082I ESTAE routine: DEQ successful

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The Primary CDS was successfully DEQueued.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7083I ESTAE routine: CLOSE successful

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The Primary CDS was successfully CLOSEd.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7084E ESTAE routine: DEQ failed. R1=XXXXXXXX R15=XXXXXXXX

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The DEQ of the Primary CDS failed, however the operating system should DEQ the Primary CDS when the SLUPCOPY task ends.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7085E ESTAE routine: CLOSE failed. R15=XXXXXXXX

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The CLOSE of the Primary CDS failed, however the operating system should CLOSE the Primary CDS when the SLUPCOPY task ends.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7090A reply Y to initiate point-in-time copy

Explanation: An operator response is required.

System Action: Processing waits until a response is received.

User Response: Reply to the message with "Y" to perform the actual PIT copy, or reply to the message with any other character to abort the PIT copy.

SLS7091A reply Y to simulate point-in-time copy

Explanation: An operator response is required.

System Action: Processing waits until a response is received.

User Response: Reply to the message with "Y" to simulate the PIT copy, or reply to the message with any other character to abort the simulated PIT copy.

SLS7092A reply Y to retry HSC primary CDS reserve

Explanation: An operator response is required.

System Action: Processing waits until a response is received.

User Response: Reply to the message with "Y" to retry the RESERVE, or reply to the message with any other character to abort the retry and end processing without performing an actual or simulated PIT copy.

SLS7100I SLUPCOPY version *v.rr* processing begins

Explanation: Information only. *v* is the version number and *rr* is the release number of SLUPCOPY.

System Action: Processing continues.

User Response: None.

SLS7101E lvt address does not point to an lvt

Explanation: An illogical condition or unexpected data value occurred during processing.

System Action: Processing ends with RC=12.

User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7102I HSC qname = *qqqqqqqq*

Explanation: Information only.

System Action: Processing continues.

User Response: None.

SLS7103E ascb address from HSC lvt is zero

Explanation: An illogical condition or unexpected data value occurred during processing.

System Action: Processing ends with RC=12.

User Response: Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

- SLS7104I** UCB located successfully
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.
-
- SLS7105E** DPV eyecatcher does not match
- Explanation:** An illogical condition or unexpected data value occurred during processing.
- System Action:** Processing ends with RC=12.
- User Response:** Rerun the PIT copy with the AB option specified (if it was not already specified), then send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.
-
- SLS7106I** original last backup date and time = *yyyymmddhh:mm:ss*
- Explanation:** Information only. The date and time of the last successful backup before this PIT copy is displayed.
- System Action:** Processing continues.
- User Response:** None.
-
- SLS7107I** updated last backup date and time = *yyyymmddhh:mm:ss*
- Explanation:** Information only. The last backup date and time in the Primary CDS is updated to the date and time of this PIT copy.
- System Action:** Processing continues.
- User Response:** None.
-
- SLS7108I** DPV restore required
- Explanation:** Information only. The last backup date and time in the Primary CDS needs to be restored to the original value as previously displayed by message SLS7106I; message SLS7172I will subsequently confirm that the restore was successful.
- System Action:** Processing continues.
- User Response:** None.

- SLS7109I** detach bypassed
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.
- SLS7110E** missing DD: *ddddddd*
- Explanation:** An error has occurred during validation of the JCL-supplied information.
- System Action:** Processing ends with RC=12.
- User Response:** Supply a SYSPRINT DD statement for DFSMSdss or FDRSNAP, supply a SYSPRINT or SYSTEM DD for SIBBATCH, and for all PIT copy methods, supply both SLSCNTL and SLSVDI DD statements, then rerun the PIT copy.
- SLS7111I** SLUPCOPY version *v.rr* processing ends
- Explanation:** Information only. *v* is the version number and *rr* is the release number of SLUPCOPY.
- System Action:** Processing ends.
- User Response:** None.
- SLS7112I** SLUPCOPY version *v.rr* abended by request
- Explanation:** Information only. *v* is the version number and *rr* is the release number of SLUPCOPY. This message is issued when the AB option is enabled and one of the eligible error conditions occurs.
- System Action:** Processing ends.
- User Response:** None.
- SLS7150E** CDS DPV READ failed. R15=XXXXXXXX
- Explanation:** An error has occurred attempting to use an IBM service.
- System Action:** Processing ends with RC=16.
- User Response:** None. The last backup date and time does not need to be restored since it was never updated in the Primary CDS.

- SLS7151E** CDS DPV WRITE failed. R15=XXXXXXXX
- Explanation:** An error has occurred attempting to use an IBM service.
- System Action:** Processing ends with RC=16.
- User Response:** None. The last backup date and time does not need to be restored since it was never updated in the Primary CDS.
- SLS7152E** CDS DPV RESTORE failed. R15=XXXXXXXX
- Explanation:** An error has occurred attempting to use an IBM service.
- System Action:** Processing ends with RC=16.
- User Response:** The last backup date and time in the Primary CDS is wrong and reflects the date and time of the invalid PIT copy. If necessary, run a SLUADMIN BACKUP of the CDS to correct the last backup date and time value.
- SLS7153E** SYNAD MSG BUFF = *mmm...mmm*
- Explanation:** An error has occurred attempting to use an IBM service.
- System Action:** Processing ends with RC=16.
- User Response:** Bytes 84-127 of the SYNAD message buffer are displayed. See the description of the SYNADAF macro in z/OS DFSMS Macro Instructions for Data Sets for a more detailed explanation of the contents of this area.
- SLS7170I** CDS DPV read successful
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.
- SLS7171I** CDS DPV write successful
- Explanation:** Information only.
- System Action:** Processing continues.
- User Response:** None.

SLS7172I CDS DPV restore successful

Explanation: Information only.

System Action: Processing continues.

User Response: None. The last backup date and time in the Primary CDS is successfully restored to its original value (as previously displayed by message SLS7106I) because the PIT copy is invalid.

SLS7180I ESTAE routine: DPV restore not required - DPV never updated

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The last backup date and time in the Primary CDS did not need to be restored to its original value (as previously displayed by message SLS7106I) because the CDS was never updated.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7181I ESTAE routine: DPV restore not required - PIT copy successful

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The last backup date and time in the Primary CDS did not need to be restored to its original value (as previously displayed by message SLS7106I) because the CDS was updated but the error occurred after the PIT copy was successful.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7182I ESTAE routine: DPV restore required

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The last backup date and time in the Primary CDS needs to be restored to its original value (as previously displayed by message SLS7106I). Unless message 7186 is issued, run a SLUADMIN BACKUP of the CDS to correct the last backup date and time value if necessary.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7183E ESTAE routine: DPV restore not attempted - logic error

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The ESTAE recovery routine did not attempt to restore the last backup date and time in the Primary CDS because a logic error was detected.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7184E ESTAE routine: DPV restore not attempted - not reserved

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The ESTAE recovery routine did not attempt to restore the last backup date and time in the Primary CDS because the CDS is no longer reserved.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

SLS7185E ESTAE routine: DPV restore not attempted - DCB not open

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The ESTAE recovery routine did not attempt to restore the last backup date and time in the Primary CDS because the CDS DCB is no longer open.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSDUMP data set to Sun StorageTek Software Support.

SLS7186I ESTAE routine: DPV restore successful

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The last backup date and time in the Primary CDS is successfully restored to its original value (as previously displayed by message SLS7106I).

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSDUMP data set to Sun StorageTek Software Support.

SLS7187E ESTAE routine: DPV restore failed. R15=XXXXXXXX

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend. The ESTAE recovery routine attempt to restore the last backup date and time in the Primary CDS failed. If necessary, run a SLUADMIN BACKUP of the CDS to correct the last backup date and time value.

System Action: Processing ends (indicated by message SLS7188I) and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSDUMP data set to Sun StorageTek Software Support.

SLS7188I ESTAE routine: processing ends

Explanation: The ESTAE recovery routine in SLUPCOPY has been invoked for an abend other than the User 555 abend.

System Action: Processing ends and a dump is created for the failing condition (regardless of the AB option) if the JCL did not dummy the SYSMDUMP DD and if the the abnormal disposition of the dump data set was not DELETE.

User Response: Send all required SLUPCOPY output and the SYSMDUMP data set to Sun StorageTek Software Support.

Chapter 3. Abend Reason Code Listings and Descriptions

Introduction

This chapter contains a listing of Abend reason codes and associated descriptions. The reason codes are grouped into separate sections according to issuing modules, components or utilities:

- Operator Command
- Mount/Dismount
- Utilities
- CAP Common
- Subsystem Allocation Modules
- Volume/Cell
- Configuration Control
- Initialization/Termination
- Installation Component
- TMS/User Interface
- LMU Driver
- Subsystem Data base Modules
- WTO Server
- ASCOMM
- Subsystem Services Modules
- Recovery Component
- Host Communications

Note: ABEND reason codes are four byte fields (2 characters per byte). The left-most two bytes contain one of the following:

- an associated message number
- a return code
- other additional information

The right-most two bytes are the ABEND code (leading zeros are truncated). For example, the ABEND code, 1729070d, can be interpreted as follows:

1729	message number associated with abend code 070d
070d	the abend code

Reason Codes Issued by Operator Command

- 0001** A Data base Volume Read request was issued in response to an operator DISPLAY VOLUME command. An invalid return code was received from DVLRD.
R2 = DVLRD return code
- 0002** A syntax error was detected by the SLSSPARS routine. However, SLSOCLEX was unable to determine the point at which the syntax error occurred.
R9 = ORQX
R8 = SLSYKEYH
- 0003** An HSC operator command routine was unable to establish an ESTAE environment. Command processing could not continue without the ESTAE.
R2 = return code from the ESTAE macro
- 0004** A parameter ID was returned by the SLSPARSE routine. However, SLSOCLEX was unable to match the parameter ID with a parameter entry on the parse table provided.
R8 = SLSYKEYH
- 0005** Non-zero return code from SRMM.
- 0006** A nonzero return code was received from SLSONTAB.
R2 = SLSONTAB return code
- 0008** A nonzero return code was received from SLSONTAB.
R2 = SLSONTAB return code
- 000A** A nonzero return code was received from VSSTA.
R2 = VSSTA return code
- 000C** A nonzero return code was received from VCSTA.
R2 = VCSTA return code
- 000E** Reached the end of the LCB queue before finding a matching ACS id.
- 0010** Nonzero return code from SLSONTAB.
R2 = SLSONTAB return code
- 0012** Nonzero return code from SLSONTAB. R2 = SLSONTAB return code
- 0014** Nonzero return code from SLSFCONF FUNC=STATNID.
R2 = SLSFCONF return code
- 0015** A Configuration Control request was issued to convert a device address to a drive ID. Invalid return code from SLSFCONF FUNC=DRIVEID.
R2 = SLSFCONF return code

- 0016** Nonzero return code from SLSFCONF FUNC=ATHSMODE.
R2 = SLSFCONF return code
- 0017** An LMU Server request was issued to write a Host to Host broadcast message.
An invalid return code was received from LMURQST BCSTWRT.
R2 = LMURQST return code
- 0018** A Configuration Control request was issued to flag a drive for cleaning. Invalid
return code from FFLGDRIV.
R2 = FFLGDRIV return code
- 0019** Invalid function for CAP request.
- 0020** Illogical LMU error return code.
- 0021** PATHing error - Corrupted SPPLEDEF SPPLEID field.

Reason Codes Issued by Mount/Dismount

- 0075** An ASCOMM request was received by SLSMAIM. However, it contained an invalid DRIVEid. This is a program logic error.
- 0076** An ASCOMM request was received by SLSMAIM. However, it indicated an invalid function. This is a program logic error.
- 0077** An LMU Server function was requested. However, it returned an invalid return code. This is a program logic error.
- 0078** Mount/Dismount requested a mount function. Upon return, there was an invalid return code. This is a program logic error.
- R14 = addr of instruction detecting the invalid return code
- 0079** A MAIL was received. However, neither mount, dismount, nor swap was set. This is a program logic error.
- 0080** When a mount/dismount ITT routine was called, the routine specified in the ITT was incorrect. This is a program logic error.
- R3 = the address of the ITT
- 0081** Mount/dismount requested a vol/cell function. Upon return, there was an invalid return code. This is a program logic error.
- R14 = addr of instruction detecting the invalid return code
- 0082** Mount/dismount requested a cell scan. The LCCE provided was invalid. This is a program logic error.
- R4 = pointer to the LCCE
- 0083** Mount/dismount requested a recovery function. Upon return, there was an invalid return code. This is a program logic error.
- R14 = addr of instruction detecting the invalid return code
- 0084** Mount/dismount requested a RECVOL function. Upon return, the location returned was invalid. This is a program logic error.
- R2 = addr of the RITT
- 0085** Mount/dismount requested a CAP common function. Upon return, there was an invalid return code. This is a program logic error.
- R14 = addr of instruction detecting the invalid return code
- 0086** Mount/dismount requested a parse function. Upon return, there was an invalid return code. This is a program logic error.
- 0087** Mount/dismount requested a config function. Upon return, there was an invalid return code. This is a program logic error.
- R14 = addr of instruction detecting the invalid return code
- 0088** Mount/dismount wanted to issue a message telling what offline LSM the volume was in. However, the MFCR did not point to a VAT. This is a program logic error.

- 0089** Mount/dismount attempted to establish or delete an ESTAE. However, the ESTAE macro returned a nonzero return code. The upper 2 bytes of the reason code contains the ESTAE return code. This is a program logic error.
- R14 = the addr of the instruction detecting the invalid return code
- 009E** The module was trying to generate the high LSMid for an ACS. It generated more than ICOINLSM LSMids. This is a program logic error.
- R4 = the LSM address for the LSM
- 009F** Mount/dismount requested a db server function. Upon return, there was an invalid return code. This is a program logic error.
- R14 = addr of instruction detecting the invalid return code
- 0100** Mount/dismount requested an STIMERM function. Upon return, there was a nonzero return code. The upper two bytes of the reason code contain the STIMERM return code. This is a program logic error.
- 0101** Mount/dismount had a logic error. Somehow, it is executing without one of the ECBs in an ECB list getting POSTed. This is a program logic error.
- 0102** Mount/dismount had a logic error. It wanted to do an end CAP without setting a flag indicating that the CAP was open. This is a program logic error.
- 0103** Mount/dismount had a logic error. It wanted to issue a message. However, an invalid requestor requested the message. This is a program logic error.
- 0104** Mount/dismount had a logic error. It wanted to issue an LMU error message. However, an invalid requestor requested the message. This is a program logic error.
- 0105** Mount/dismount had a logic error. The swap request did not contain a valid device number. This is a program logic error.
- 0106** Mount/dismount had a logic error. The linkage assist routine was called for a non-supported function.
- 0107** Mount/dismount received too many abends in the SLSMHTH task. This is a program logic error.
- 0108** Mount/dismount received a nonzero return code from SVCUPDT of SVC91.
- 0109** Mount/dismount received an invalid return code from SVOLACC.
- 010A** A request for a virtual mount was received but the text did not contain an address for SLSTMAIN.
- 0110** Invalid parm list for SLSMDRVR.
- 0111** Attempted to add invalid volser to the CDS.

Reason Codes Issued by Utilities

- 0150** Unrecognized function code passed to SLUIO.
- 0151** Could not start ASCOMM Task for Utility Server.
- 0152** Unrecognized response in ASCOMM Response Area (UADRA) from Phase 2 Server - SLSUAUDT2.
- 0153** Unrecognized response in ASCOMM Response Area (UADRA) from Phase 3 Server - SLSUAUDT3.
- 0154** Unrecognized response in ASCOMM Response Area (UADRA) from Phase 4 Server - SLSUAUDT4.
- 0155** Unrecognized function code in ASCOMM Data Area (UADDA or USUDA) from Utility Program.
- 0156** Unrecognized volume characteristics in subroutine SLSUAAVL.
- 0157** Attach SLSUALSM failure.
- 0158** Unrecognized response code from SLSUALSM task.
- 0159** No registered LSM entry address for this LSM.
- 0160** Unrecognized return code from subroutine SLSUAPAV.
- 0161** Undocumented return from LSM scan in Cell Catalog (LCCD).
- 0162** Unrecognized function code in ASCOMM Data Area (UICDA).
- 0163** Did not get returned values descriptor block from keyword table as expected.
- 0164** Unrecognized response in ASCOMM Response Area (UICRA) from Init Carts Server - SLSUINCT.
- 0165** Did not get ACS/LSM table entry as expected.
- 0166** Nonzero return code from SLUBKP10.
- 0167** Error return from SLSJINTA (Initialization Active).
- 0168** Invalid CAPid passed from SLUEJCT to SLSUEJCT.
- 0169** Unexpected return code from SLSUSCRD utility server.
- 0170** Unexpected return code from SLSUSCUP utility server.
- 0171** Invalid ASCOMM token. Token field was probably overlaid.
- 0172** Unexpected return code from Volume/Cell.
- 0174** Utility Parse Error Reporter called with no parse error flagged in Parse Table.
- 0176** No CAP found for the ACS in which the specified volume resides.
- 0177** Invalid function code passed from SLUEJCT to SLSUEJCT in field UECDFUNC to UECDA. Should be 'reserve CAP', 'eject', or 'release CAP'; no others.
- 0178** Invalid ACS id from UCTA.

- 0179** Logic error. End of file.
- 0180** Invalid response received.
- 0181** Set utility read a block whose eyecatcher did not match expected eyecatcher.
R2 = Block
R3 = Eyecatcher
R14 = Address doing read
- 0182** Unable to locate required keyword.
R2 = Keyword
R8 = SLSYKEYH (parse table)
- 0183** Logic error when searching for matching host-id in data base block.
R14 = address where the problem was detected
- 0184** SLUIO was requested to generate a message that was too big.
- 0185** UENTCFGA chain is missing the correct FLSM record for the LSM being audited.
R8+70x = FACS chain
R9+Cx = LSM id
R5 = UCTL
R8 = UENT
- 0186** Table lookup failure - device type table vs. UCBTYPE
R2= UCB
- 0187** Number of LSM records for ACS does not match the number of LSMs in this ACS (ACSCTLISM).
- 0188** Unexpected return code from FIGMGR.
- 0190** Unexpected return code from PGMI QDSN request.
- 0191** Unexpected return code from ASCOMM, either normal return code when end-of-task expected or unexpected end-of-task.
- 0192** Invalid parameter type received from ASCOMM SLUMERGE.
- 0200** SLSCNTL DD entry found in TIOT, but UCB address field contains binary zeros.
- 0201** Logical routine OPEN found no output record passed on the first invocation of the E35 user exit by DFSORT.
- 0202** Logical routine READ hit end of file. Code 0202 indicates a corrupted data set. Make a copy of the data set for problem determination, and restore or recreate it.
- 0203** Logical routine DELTABLK. A delta record, thought to be sorted, was found out of sequence.
- 0204** Logical routine DELTABLK. The 'after' image text within the current delta record is longer than the space in the control data base block to receive the 'after' image.

- 0205** Logical routine APPLY. Sorted delta data set with DDname SLSDELTA is empty.
- 0206** Invalid UEVT chain. The UEVT chain has been corrupted (i.e., the chain header is zero or one of the UEVT entries does not contain 'UEVT' as an eyecatcher).
- 0207** Invalid UEST chain. The UEST chain has been corrupted (i.e., the chain header is zero or one of the UEST entries does not contain 'UEST' as an eyecatcher).
- 0208** ESTAE routing was not successfully established. Return code from issuing ESTAE macro was not zero.
- 0209** Logic error when searching for free cells and adjusting allocation map.
- 0210** Read/Write return code is not zero or end-of-file.

Reason Codes Issued By CAP Common

- 0252** LMU took longer than 10 minutes to post the MOVE request completion ECB.
- 0253** Error attempting to start the enter process with the LMU Server. Info code contains the return code from the LMU Server.
- 0256** Unexpected return code from the VOL/CELL volume insert, volume update, or cell get functions.
- 0257** Unexpected return code from SLSCNCAP when entering a cartridge.
- 0258** Unexpected return code from SLSCGVOL when obtaining VOLSER from operator.
- 0259** Unexpected return code from SLSCCVOL when inserting volume record.
- 025A** After obtaining VOLSER from operator, invalid cell entry left in CAP catalog.
- 025B** Error attempting to delete VAR thru VOL/CELL after a move error which did not result in an errant cartridge.
- 025C** An attempt to create a volume record returned a return code other than no space or duplicate cartridge. Info code contains the bad return code.
- 025D** When attempting to use the LMU Server interface routine, SLSCNCAP, an unexpected return code was received. Info code contains the bad return code.
- 025E** A CAP END was requested, however, one or more of the CAP CONTROL BLOCK status fields was incorrectly set.
- 0260** Initialization found an ACS without a corresponding LSM.
- 0261** An attempt was made to unselect a volume after an error occurred in SLSCMCAP. The Info Code is the VVUNS RC.
R2 = SLSCMCAP return code
- 0262** An invalid PARMLIST was passed to SLSCASET.
- 0263** Unexpected return code during abort of current CAP operation while HSC was in termination.
- 0266** Attempt to add/update volume with an unreadable media type (?). Entry of unreadable media should have been prevented earlier.

Reason Codes Issued by Subsystem Allocation Modules

- 0352** Volume Lookup received error condition from data base VOL Read function.
- 0353** Volume Lookup received error condition from VOL/CELL Scratch Prefer.
- 0367** Volume Lookup received an unexpected return code from SLSTGVSP.

Reason Codes Issued by Volume/Cell

- 0400** Unrecognized panel type in Cell Allocation Map (VCAM).
- 0404** Unable to establish ESTAE.
- 0405** Unable to obtain clock value.
- 0406** Unrecognized function code in SLSVCSCN parameter area gened by VCSCN macro.
- 0408** Cell Scan workarea (VCSCNIWK) not in proper format (header ID field not correct).
- 0410** Unable to unselect selected volume at HSC Termination.
- 0412** SLSVQCHK routine returned an unexpected return code.
- 0414** A volume serial number was encountered on the VAT Queue but does not exist in the data base.
- 0415** A vol cell function returned an invalid vol/cell return code.

R2 = the return code
- 0416** Encountered a negative or zero cleaner select count when unselecting a cleaning cartridge.
- 0418** Called SLSVINSP with an illegal function code.
- 0420** Attempt to store out of the bounds of a structure.
- 0422** Invalid VCPANLST (volume/cell panel list for inclusion/exclusion) from a MOVE routine.
- 0424** Invalid return code from FIGMGR when reading an FDRIVE record for the drive type.

Reason Codes Issued by Configuration Control

0450	Invalid ACS index.
0451	Invalid LSMid (in LRQST).
0452	Unsuccessful Cell Pool GET.
0453	Invalid CAPid (in LRQST).
0454	CAP reserved to another host.
0455	Invalid LSMid returned from SLSCAPA.
0456	Able to Vary Station offline in LMU but not in HST.
0457	No matching HOST id in Drive Table (FDRVVT).
0458	Invalid LSM id (in HST).
0459	LMU register for broadcast failed.
0460	Listener subtask received control, but neither Terminate nor LMU broadcast ECB POSTed.
0461	LMSid invalid (in LST).
0462	HOSTid mismatch with LSM Lock Word.
0463	TCB address mismatch with LSM Lock Word.
0464	Unexpected return code from LMU Driver.
0465	Unsuccessful unselect of LSM (but not I/O error).
0466	Unable to delete ITT record.
0467	Control data base release (DRLSE macro) failed.
0468	Control data base I/O error.
0469	LMURQST broadcast read request failed.
0470	Invalid drive ID.
0471	Invalid data was detected in the FIGMGR Plist.
0472	FIGMGR UPDATE failed.
0473	Unexpected FIGMGR return code during Configuration processing.

Reason Codes Issued by Initialization/Termination

- 0501** An HSC Initialization/Termination routine was unable to establish an ESTAE environment. Processing could not continue without the ESTAE.
- R2 = return code from the ESTAE macro
- 0502** Primary JES name not found in SSCVT chain.
- 0504** Init/Term flags in the SSCVT were altered by some other process during bring-up.
- 0506** Init/Term flags in the SSCVT were altered by some other process during shutdown.
- 0508** Init/Term flags in the SSCVT were altered by some other process during shutdown.
- 0510** Initialization/Termination service routines did not load during subsystem initialization.

Reason Codes Issued by Installation Component

- 0550** Invalid number of parameters. The specified module was called with a parameter list that did not have the high order bit of the last parameter address set. This is a program logic error.
- 0551** Invalid LIBGEN – Pass-Thru Port. The LIBGEN being processed was invalid. The neighbor specified for a Pass-Thru Port was not in the LIBGEN. This is a program logic error.
- 0552** A OBTAIN was issued to read a DSCB. A non-zero return code was returned. This is a disaster level error.
- R11 = the return code
- 0553** Invalid return code. An installation function was called. An invalid return code was received. This is a program logic error.
- R10 = the return code
R14 = address after call to function
- 0554** Invalid IEFEB4UV return code. IEFEB4UV was called to look up a unit name. A return code other than zero or four was returned. This is a disaster level error.
- R11 = the return code
- 0555** Invalid device type (VM only). SLICDATA was performing a table lookup to obtain device characteristics but could not find the device containing the CDS. This is a program logic error.
- 0556** SLICDATA was attempting to find a panel map for a panel type and it could not find one.
- 0557** SLICDATA received a failure from dimension services for a library element not found.
- 0558** SLICDATA encountered an unexpected error when building drive records.

Reason Codes Issued by TMS/User Interface

- 0600** ESTAE macro failed located.
- 0601** OPEN failed for the SLSTLMS file.
- 0602** An unrecoverable IUCV error occurred.
- 0603** ALLOC failed for SLSTLMS file.
- 0605** The user interface made a data base server function. Upon return, there was an invalid return code. This is a program logic error.
- R14 = addr of instruction detecting the invalid return code
- 0606** The user interface made a volume/cell function. Upon return, there was an invalid return code. This is a program logic error.
- R14 = addr of instruction detecting the invalid return code
- 0607** The user attempted to invoke the “call until EOF” form of the PGMI interface, but terminated before the PGMI request was complete.

Reason Codes Issued by LMU Driver

- 0650** A configuration control request was made. However, the return code was invalid. The upper two bytes of the reason code contain the upper two bytes of the config return code.
- 0651** SLSLQ detected that the caller had not properly serialized the requested SLSLQ operation. Detection VIA CS logic.
- 0652** A check was made to see if requests are present on the Waiting Request Queue. The test was positive. However, the LQUEUE POP execution failed.
- 0653** A check was made to see if the caller of SLSLATOQ was holding the LCBLOCK. It was not.
- 0654** ESTAE environment had been previously established, but attempt to cancel the ESTAE environment failed. Driver was attempting to terminate.
- 0655** An error code was returned from SVC 99 while trying to deallocate a station which should have been allocated.
- 0656** Tried 3 times to establish ESTAE recovery routine; never got Return Code = 00 from ESTAE service.
- 0657** The LRT entry corresponding to the entry point called does not contain a source type descriptor bit.
- 0661** An LRQ was supposed to be completed but it was on an active, waiting, or outage queue; or the LCB lock was not held.
- 0663** Unable to establish ESTAE.
- 0664** ESTAE cancel failed. After establishing Recovery routine at startup, received failure trying to cancel ESTAE routine.
- 0665** LMU response error. A response was received which contains a sequence number that does not exist in the LMU Server's active request queue.
- 0666** ESTAE start failed. Did not receive R/C = 00 from ESTAE service after trying three (3) times to establish ESTAE recovery routine.
- 0667** Driver attach failed. Tried three (3) times to attach SLSLDRV. Either the attach failed or SLSLDRV failed to initialize correctly.
- 0668** Cross Memory POST error. An error was experienced when the LMU Driver's simulate write routine attempted to issue a Cross Memory POST.
- 0669** Cross Memory POST error. An error was experienced when the LMU Driver's simulate read routine attempted to issue a Cross Memory POST.
- 0670** An error was experienced when the LMU Driver's queue search attempted to scan more elements than were queued. The queue has been corrupted.
- 0671** An error was experienced when the LMU Driver attempted to add an element to the queue. It already was on the queue or the queue header was corrupt.
- 0672** An error was experienced when the LMU Driver attempted to remove an element from the queue. It was not on the queue.
- 0673** An error was experienced when the LMU Driver attempted to remove an element from the queue. The number on the queue is larger than the maximum.

- 0674** STIMERM failed. An error was experienced when the LMU Driver attempted to remove an element from the queue. The number on the queue is larger than the maximum.
- 0675** An invalid return code was given by SLSFLSMM.
R14 = the return code
- 0676** User abend generated. A nonzero value was placed in WABNDMSG in the local work area triggering a user abend.
- 0677** User abend generated. A nonzero value was placed in WABNDMSG in the local work area triggering a user abend.
- 0678** User abend generated. UCB was not re-initialized upon restarting SLSLDRV after an earlier abend or premature term.
- 0679** LMU Request or Request Modifier entry not found.
- 067A** Simulation requested, but unable to load simulator LINK modules.

Reason Codes Issued by Subsystem Data Base Modules

0700	Internal error. An attempt was made to reserve the CDS when no DPV was available.
0701	Uncorrectable CDS corruption. Database modules detected CDS corruption. SLSDRDIR was unable to correct the error. This reason code can occur during SLICREAT if the CDS space allocation is insufficient.
0702	Uncorrectable CDS corruption. Database modules detected CDS corruption. SLSDRDIR was able to rebuild the CDS, but the corruption remained.
0704	Internal error. Non-Owner attempted to release the data base reserve.
0705	Unable to locate a FREE database block when extending a subfile. User must allocate a larger CDS.
0707	The VARINUSE flag for a volume is not ON during the re-write process.
0708	The replacement VAR given contains a different volume serial number.
070A	BDAM or I/O error attempting to synchronize blocks.
070B	BDAM or I/O error attempting to scan VAR area.
070C	Internal error. No buffers past in DEEREPL.
070D	The last CDS copy is in error. System must come down.
070E	An I/O error occurred attempting to re-write the DHB.
070F	Hostid does not match any in the passed DHB record.
0710	No ITT blocks were available for allocation. This is a program logic error.
0711	Internal error. Block number not within bounds of Index.
0712	Internal Error. Caller has specified an incorrect token (does not match memory address of ITT).
0713	Internal Error. Length of Offset specified exceeds allowed.
0714	Internal Error. DCH eyeball invalid.
0715	Internal error. DCH is not cached.
0716	Internal error. VAR area overflowed.
0717	Internal error. Caller specified either an active or a nonexistent Host.
0718	.Internal error. No ITT extents could be acquired for the specified host (a). No ITT extents for the current host (b).
071A	Internal error. A CDS record's eyecatcher does not match the four (4) character subfile id defined for it.
071B	Internal Error. Invalid OPTION field specified for the SCAN.
071C	Internal error. Internal subroutine NEXTRITT returned other than OK or EOF.
071D	Internal error. One of the LSMs specified by the caller at SCAN init is not valid.

- 071E** Unexpected error attempting to read CDS.
- 0720** Attempt to attach heartbeat failed. R2 = ATTACH return code
- 0723** Internal error. Unable to establish ESTAE. Accompanies message 723E.
- 0724** Internal error. The program passed an invalid entry type to the user exit - SLSUX06. Accompanies message 724E.
- 0725** An attempt to locate an Errant Record for the specified ACS has failed. The ACS is given in message 725I.
- 0726** Internal error. The caller has specified an invalid ACS. Accompanies message 726I.
- 072A** Non-zero return code received from FIGMGR call.
- 072B** No matching panel type found in FLSM record for relative panel.
- 0731** Internal error. A caller of DRPHY has provided invalid parm data to the Data base read routine SLSDRDSR.
- 0732** Internal error. Invalid BDAM parm.
- 0733** Unable to switch Journals because other Journal has had a previous I/O error.
- 0735** Both Journals have had an I/O error.
- 0736** Following Journal switch, the newly current Journal indicates that it has not been reset.
- 0748** Caller passed a VAR whose ILLTERNT field is not within DES area. Message 748I issued.
- 0749** Caller attempts to write an ITT record with a recovery routine value of X'00'.
- 074A** SLSDIOM terminated with active CDS requests.
- 074B** An attempt to reserve CDS when no primary is active.
- 074C** An attempt to reserve CDS failed during error analysis.
- 074D** Internal error. CDS-level HCSRQST error.
- 074E** Internal error. Invalid DCVINFO specified.

Reason Codes Issued by WTO Server

0750 An interface error has been detected by the subsystem message writer routine. This is an internal error.

R2 = a more specific error reason code

0751 A nonzero return code has been received from WTO while attempting to output a multi-line request. This is an internal error.

R14 = the return code

Reason Codes Issued by ASCOMM

- 0802** ASCOMM Termination already proceeding. SLSQDRV ESTAE routine will produce a dump and retry. This abend will not cause the ASCOMM driver task to terminate.
- 0803** ATTACH of SLSQWRK Failed. SLSQDRV ESTAE routine will produce a dump, free the QMTB, and retry. This abend will not cause the ASCOMM driver task to terminate.
- R14 = address of infraction
- 0804** Unable to establish ESTAE. ASCOMM attempt to establish or delete an ESTAE resulted in a nonzero return code. The upper 2 bytes of the reason code contains the ESTAE return code. This is a program logic error.
- R14 = instruction address
- 0805** The QXTRACT service was called by a task not attached by Ascomm. This is a disaster level error.
- 080C** Invalid Option found in QMTB. SLSQDRV ESTAE routine will produce a dump, free the QMTB, and retry. This abend will not cause the ASCOMM driver task to terminate.
- 080E** Invalid element on QMTB queue. The routine's ESTAE includes the invalid storage address in the system dump.
- 0810** Response Token specified by caller could not be located in ASCOMM internal tables. The task issuing the Respond will be terminated.
- 0811** Response length was bigger than the size specified in the original request. The task issuing the Respond will be terminated.
- 0815** Task Token specified by caller was zero. The task issuing the Respond will be terminated.
- 0820** Response Token specified by caller was a zero. The task issuing the Respond will be terminated.
- 0827** Unable to allocate Linkage Index. Initialization for ASCOMM is terminated. This prevents the entire subsystem from initializing.
- 0829** Attach of ASCOMM Driver failed. Initialization for ASCOMM is terminated. This prevents the entire subsystem from initializing.
- 0830** ASCOMM Driver Initialization Failed. Initialization for ASCOMM is terminated. This prevents the entire subsystem from initializing.
- 0833** Unconditional SETLOCK Failure.
- 0834** Unable to locate LVT. SRB is terminated.

Reason Codes Issued by Subsystem Services Modules

- 0900** An attempt to allocate more than the maximum permissible save/work areas has been detected by SLSCALL. This is a program logic error.
- R9 = module being called
R12 = module doing calling
R14 = return address
- 0901** An attempt to allocate less than 72 bytes for a save/work area has been detected by SLSCALL. This is a program logic error.
- R9 = module being called
R12 = module doing calling
R14 = return address
- 0902** An attempt to free a partial save area stack has been detected by SLSBSADB. This is a program logic error.
- 0903** An attempt to free a partial save area stack has been detected by SLSBSADS. This is a program logic error.
- 0904** An attempt to allocate an initial save area stack larger than the maximum has been detected by SLSMAINP. This is a program logic error.
- 0905** A call was made to the lock/unlock service specifying invalid parameters. Either R1 was nonzero or R0 was zero. This is a program logic error.
- 0906** A call was made to the lock/unlock service and no DPV was available. This is a program logic error.
- 0907** A call was made to the lock/unlock service. An ENQ or DEQ was issued returning an invalid return code. This is a program logic error.
- 0908** A call was made to the SSAT service. However, an invalid entry was specified. This is a program logic error.
- R2 = invalid entry
- 0909** A call was made to the SSAT SET service. However, an active ENQ indicates the requestor was already processing a SET. This is a program logic error.
- 0910** Return code from internal subroutine PARSK000 was larger than could be handled by the jump table.
- R2 = the return code
- 0911** SLSSSATS either attempted to create or delete an ESTAE. ESTAE returned a nonzero return code. This is a program logic error.
- R2 = the return code
- 0912** Return code from internal subroutine PARSV000 was larger than could be handled by the jump table.
- R2 = the return code
- 0913** A call to the volume/cell routine returned an invalid return code.
- R14 = area calling the volume/cell routine

- 0914** A call to the SLSSHSRQ routine requested an invalid function.
- 0915** A call to the SLSSHSRQ routine specified an invalid request or response.
- 0916** A task was attached to handle a request from another host. The ATTACH returned a nonzero return code.
- R14 = the return code
- 0917** A SRIBRQ macro was issued with an invalid function code.
- R10 = addr of the SRIBPL
- 0918** An error occurred during an attempt to establish an ESTAE for this module.
- R15 = the return code
- 0919** An error occurred during an attempt to establish an ESTAE for this module.
- R15 = the return code
- 0920** An error occurred during STIMERM simulation. ERRET was not specified on the STIMERM macro.
- R15 = the return code
- 0921** An error occurred in the STIMERM CPOOL FREE routine. The cell could not be freed.
- R15 = the return code
- 0922** An error occurred during SLSSACCM processing.
- R8 = SRCSECTB table
R7 = SRCSECEL element
R2 = the return code
R15 = the return code
- 0923** An error occurred during SLSSUXQP processing.
- R5 = user exit entry code
R8 = token for SACCUM
- 0924** An error occurred during SLSSUXCP processing.
R7 = user exit entry BUXCHB
- R8 = address for BUXCHT
- 0925** The entry point address passed to SLSCALL was zero.
- R9 = module being called will contain zeros
R12 = module doing calling
R14 = return address
- 0926** LSMid invalid.
- 0927** The module ATTACH request timed out.
- R4 = module ATTACH request preceded by SLS1972D message

- 0928** An unknown return code was received by a subroutine. The return code is placed in the SCALBDR field of the SCALLV parameter list.
- 0929** Requestor specified an invalid location for the destination or target of a motion.
- 0930** Unexpected return code from SRMM RESOLVE for a unit address.
- 0931** An error was detected in the UENT (Utility entry) Control Block chain.
- 0942** SSI request failure when retrieving HSC's subsystem index value using the Verify Subsystem SSREQ.

Reason Codes Issued by Recovery Component

- 8502** A host recovery RRPL was passed to SLSRMQUE, however, it contained an invalid HOST id. For same host recovery, the HOST id <> LVTHID. This is a disaster level error.
- R9 = RRPL
- 8506** A recover RRPL was passed, however, it contained an invalid ACHS id. This is a disaster level error.
- R9 = RRPL
- 850A** A recover LSM RRPL was passed to SLSRMQUE, however, it contained an invalid LSM id. This is a disaster level error.
- R9 = RRPL
- 850E** A clean CAP RRPL was passed to SLSRMQUE, however, it contained an invalid CAP id. This is a disaster level error.
- R9 = RRPL
- 8516** A VOL/CELL function was requested. However, it returned an invalid return code. The high order two bytes of the reason code contain the high order two bytes of the return code. This is a program logic error.
- 851A** A config function was requested. However, it returned an invalid return code. The high order two bytes of the reason code contain the high order two bytes of the return code. This is a program logic error.
- 851E** A CAP common function was requested. However, it returned an invalid return code. The high order two bytes of the reason code contain the high order two bytes of the return code. This is a program logic error.
- 8522** A clean volume RRPL was passed to SLSRMQUE. However, the VOLSER was invalid. This is a program logic error.
- R9 = RRPL
- 8526** An invalid RRPL was supplied. This is a program logic error.
- R9 = RRPL
- 852A** An LMU Server function was requested. However, it returned an invalid return code. The high order two bytes of the reason code contain the high order two bytes of the return code.
- 852E** The number of errors allowed by RCVTERRA has been exceeded.
- 8532** The recovery ITT Recovery routine was called but was passed an ITT that specified a different ITT Recovery routine. This is a program logic error.
- R9 = RITT
R10 = RITP

- 8536** A task responsible for performing host recovery abended. This is a program logic error.
- R9 = RRPL
- 853A** A clean volume RRPL was passed to SLSRMQUE. However, the caller had the LSM locked. This is a program logic error.
- R9 = RRPL
- 853E** A database server function was requested. However, it returned an invalid return code. The high order two bytes of the reason code contain the high order two bytes of the return code. This is a program logic error.
- 8542** An invalid parameter list was passed to a recovery function. This is a program logic error.
- 8546** A recovery function was requested. However, it returned an invalid return code. The high order two bytes of the reason code contain the high order two bytes of the return code. This is a program logic error.
- 854A** Recovery detected a DES with an invalid source or destination record. This is a program logic error.
- R3 = location being checked
R9 = DES
- 854E** Recovery was unable to attach a task. This is a program logic error.
- R14 = Attach return code
- 8552** Recovery received an invalid LTCE. This is a program logic error.
- R2 = LTCE
R3 = LTCE
- 8556** Recovery of a CAP or LSM was requested, however, the LSM could not be found in the LSMid table.
- R2 = LSMid
R6 = LSMid table
- 855A** Recovery of a CAP or LSM was requested. However, the ITT specified had a routine type of zero.
- R9 = RRPL

Reason Codes Issued by Host Communications

- 9200** An ESTAE error occurred.
R2 = ESTAE error return code
- 9201** An ATTACH error occurred. The ESTAE routine produces a dump and retries. SLSHINIT gives error return code to initialization.
R2 = ATTACH error return code
- 9202** Unknown ECB posted. Dispatched task could not determine the POSTed ECB. The ESTAE routine produces a dump and retries.
- 9203** Unknown return code. SLSHWRT returns error return code to caller. ESTAE routine produces a dump and retries.
- 9204** Downward switch from CDS method attempted. SLSHSWT returns error return code to caller. ESTAE routine produces a dump and retries.
- 9205** Unknown current method. SLSHSWT gives error return code to caller. ESTAE routine produces a dump and retries.
- 9206** Unable to add entry to exit work queue. ESTAE routine produces a dump and retries.
- 9207** Unable to remove VTAM exit work queue. ESTAE routine produces a dump and retries.
- 9208** Unknown VTAM exit work queue entry type. ESTAE routine produces a dump and retries.

Chapter 4. HSC Return Codes

Introduction

This chapter contains the summary of the HSC return codes. These are organized by category and are in tabular form. Categories described are:

- operator command return codes
- initialization/termination return codes
- mount/dismount return codes
- mount/dismount trace identification numbers
- utility return codes
- audit utility return codes
- utility response codes
- utility condition codes
- CAP processing return codes
- volume/cell return codes - no parameter list
- volume/cell return codes - with parameter list
- volume/cell return codes - GTRACE Ids
- configuration return codes
- LMU server return codes
- data base server return codes
- address space communications return codes
- address space communications function codes
- recovery return codes
- host communications services return codes.

Return Code Listings and Descriptions

Table 2. Return Codes for Operator Commands

Equate Value	Name	Description
X '0000'	ORCOK	OK return code
X '000A'	ORCNOSSI	No SMF SSI module loaded
X '0004'	ORCMORE	More processing required
X '000B'	ORCNOSLT	No slot in the SSVT
X '000C'	ORCNOCMD	No command SSI module loaded
X '000D'	ORCABEND	Operator command routine abended: SDUMP taken
X '000E'	ORCFORCE	The operator command component was forced down with a reply "TERM" to WMSG 031D.
X '000F'	ORCXCLSV	Mutually exclusive parms specified

Table 3. Return Codes for Initialization/Termination

Equate Value	Name	Description
X'0000'	BRCOK	Operation occurred without an error
X'0004'	BRC4	return code 4 (non-fatal error)
X'0008'	BRC8	Operation occurred with error
X'0012'	BRC12	SLSBCITP initialize module failure
X'0016'	BRC16	Init/Term module did not load
X'0508'	BRCFLOAD	Load error on any initialization module
X'0509'	BRCFMODL	Called module returned a bad return code

Table 4. Return Codes for Mount/Dismount

Equate Value	Name	Description
X'0000'	MRCOK	Good return
X'0704'	MRCSTOP	Stop processing
X'0708'	MRCNOACS	No local HCT was found (SLSMINIT)
X'070C'	MRCNOHCT	NO ACS entries found (SLSMINIT)
X'0710'	MRCVNF	Volume not found
X'0714'	MRCRETRY	Retry

Table 4. Return Codes for Mount/Dismount (Continued)

Equate Value	Name	Description
X'0718'	MRCRVFWC	Recover Volume Wrong Cell
X'071C'	MRCRVFCC	Recover Volume CAP Cell
X'0720'	MRCVAS	Volume already selected
X'0724'	MRCVNE	Volume not errant
X'0728'	MRCERSEL	Volume errant and selected
X'072C'	MRCRTRYI	Incompatible scratch mount retry
X'0730'	MRCUSE	Use an over-limit cleaner
X'0734'	MRCEJECT	Eject response
X'0738'	MRCKEEP	Keep response
X'073C'	MRCFSPNT	Drive load fail spent clean cart
X'0740'	MRCRTNVL	LMU volser unmatched on dismount
X'0744'	MRCLSMOF	LSM was offline
X'0748'	MRCACSOFF	ACS was disconnected
X'074C'	MRCVNOD	Volume to dismount not on drive
X'0750'	MRCDRVLD	Drive cell scan shows loaded
X'0754'	MRCLMUER	LMU error returned on cell scan
X'0758'	MRCVERNT	Volume is errant
X'075C'	MRCVTCSN	Virtual mount; VTCS not active

Table 5. Return Codes for Utilities

Equate Value	Name	Description
X'0000'	URCOK	Good return
X'1501'	URCUACT	Utility functions active at ALS term
X'1502'	URCSCU	Scratch update in process
X'1503'	URCSRDR	Scratch redistribution in process
X'1504'	URCAUD	Audit utility in process
X'1505'	URCTRM	Utility termination in progress
X'1506'	URCSUB	Subsystem is not active
X'1507'	URCDSFAL	RECONFIG data space failed
X'1508'	URCDSTRM	RECONFIG data space terminate

Table 5. Return Codes for Utilities

Equate Value	Name	Description
X'1509'	URCDVARF	RECONFIG data space DVARs full
X'150A'	URCDSFMM	RECONFIG data space subfile record number mismatch CDSDEF and RECDEF
X'150B'	URCDSNNW	RECONFIG data space RECDEF not

Table 6. Audit Utility Return Codes

Equate Value	Name	Description
X'0000'	URCAOK	Good return
X'2001'	URCADUP	Duplicate found
X'2002'	URCAADD	Volume added
X'2003'	URCACHG	Volume updated
X'2004'	URCASEL	Volume was selected (unavailable)
X'2005'	URCAEJE	Cartridge eject failed
X'2006'	URCABGNC	Unable to acquire CAP
X'2007'	URCAMED	Volume/MEDIA mismatch
X'2008'	URCAUMED	MEDIA unreadable – existing tape
X'2009'	URCAMEDE	MEDIA unreadable – new tape
X'2010'	URCAMEJE	Cartridge eject failed – MEDIA
X'2011'	URCAVOLR	Volume became unreadable
X'2050'	URCETRM	Early stop signalled by ASCOMM
X'2098'	URCALER	LMU/LSM error occurred
X'2099'	URCAIOE	I/O error detected

Table 7. Return Codes for CAP Processing

Equate Value	Name	Description
X'0000'	CRCOK	CAP finished request without error
X'2504'	CRCLSM	Invalid LSMid
X'2508'	CRCLSMOF	LSM is manual mode (offline)
X'250C'	CRCATHS	Invalid IATHSid
X'2510'	CRCATHOF	ACS is disconnected (offline)
X'2514'	CRCBSYCP	Specified CAP is busy
X'2518'	CRCBADCP	CAP ACS <> Vol/cell/drive ACS
X'251C'	CRCRLSCP	CAP is released
X'2520'	CRCIDLCP	CAP not in use
X'2524'	CRCNOCAP	No (>0 priority) CAPs available
X'2528'	CRCLMUER	LMU request failure
X'252C'	CRCVBSY	VOLSER is already selected

Table 7. Return Codes for CAP Processing (Continued)

Equate Value	Name	Description
X'2530'	CRCVDUP	Requested volser is a duplicate
X'2534'	CRCERRNT	Cartridge is errant
X'2538'	CRCOPRAB	Operator aborted process
X'253C'	CRCVRCER	Volume/cell control error
X'2540'	CRCNOSPC	No cells available in ACS
X'2544'	CRCDR CER	Data base server error
X'2548'	CRCFCRER	Configuration control error
X'254A'	CRCRECER	Recover errant volume error
X'2550'	CRCINVFN	Invalid CAP function requested
X'2554'	CRCMTCAP	Ask operator to empty CAP
X'254C'	CRCLNOCP	LSM does not control a CAP
X'2558'	CRCVOL	Invalid volser
X'2560'	CRCNOVOL	CAP door closed with no vols
X'2564'	CRCCAPOF	CAP LSM is offline
X'2566'	CRCCOFFP	CAP pending offline
X'256C'	CRCOPRRT	Operator retry request
X'2570'	CRCNCNCL	Can not cancel request
X'2574'	CRCTFULL	Target is full
X'2578'	CRCABEND	CAP ABEND - Software Failure
X'257C'	CRCOPRDE	Operator deleted volume
X'2584'	CRCLSMPO	LSM in path offline
X'2588'	CRCAUTER	AUTO specified on nonspecific request
X'258C'	CRCCAPER	Nonzero CAP specified for 4410
X'2590'	CRCCAUTO	CAP is in AUTO mode
X'2594'	CRCSTTER	Status error between CCAPDS and CDS
X'2598'	CRCINVID	Invalid CAPid
X'25A0'	CRCNAUTO	CAP AUTO services unavailable
X'25A4'	CRCPRFNA	CAPPref invalid for this CAP
X'25A8'	CRCANCEL	Cancel Command Received (x22)
X'25AC'	CRCNOACT	Unable to activate a spec. CAP

Table 7. Return Codes for CAP Processing (Continued)

Equate Value	Name	Description
X'25B0'	CRCSTAT	MODIFY CAP to state it's already in (F CAP ON when CAP already ON)
X'25B4'	CRCAMBIG	ACS+LSM does not discretely identify a CAP
X'25B8'	CRCRECVR	CAP is in RECOVER processing
X'25BC'	CRCNOTAC	Media incompatible with drive
X'25C0'	CRCVREAD	Invalid volser during LS enter
X'25C4'	CRCACDNY	Access Denied by user exit 14
X'25C8'	CRCURMED	Unreadable media (? from LMU)
X'25CE'	CRCCAPNO	CAP not operational

Table 8. Volume/Cell Return Codes -- No Parameter List

Equate Value	Name	Description
X'0000'	VR15GOOD	register 15 shows good return
X'40F1'	VR15BAD	register 15 shows error return
X'40F2'	VR15ACTV	register 15 shows active VATs at termination
X'40F3'	VR15NOTF	register 15 shows VAT not on VAT queue
X'40F4'	VR15NOTO	register 15 shows VAT not owned
X'40F5'	VR15SPE1	register 15 shows bad number of subpool entries
X'40F6'	VR15SPE2	register 15 show bad number/order of subpools
X'40F7'	VR15SPE3	register 15 shows bad subpool entry range
X'40F8'	VR15SPE4	register 15 shows bad label type
X'40F9'	VR15SPE5	register 15 shows subpools already defined
X'40FA'	VR15SPE6	register 15 subpools out of order
X'4100'	VR15ATFL	ATTACH SLSVSK failed
X'4104'	VR15DOWL	VCAMs down level
X'4108'	VR15IOER	I/O error processing VCAM

Table 9. Volume/Cell Return Codes -- With Parameter List

Equate Value	Name	Description
VR15GOOD	VRCOK	function successful
X'4001'	VRCVNF	volume not found
X'4002'	VRCVAS	volume already selected
X'4003'	VRCVER	volume errant
X'4004'	VRCVNS	volume not selected
X'4005'	VRCVNO	VAT not owned by caller
X'4006'	VRCRNO	VAR not owned by system
X'4007'	VRCIVC	illegal VAR change
X'4008'	VRCVSC	volume already scratch
X'4009'	VRCLNC	location not cell
X'4010'	VRCVDP	volume is duplicate
X'4011'	VRCNSC	no scratch volumes
X'4012'	VRCAIP	audit is in process
X'4013'	VRCNCA	no cells available
X'4014'	VRCCIN	cell id not allocatable
X'4015'	VRCCAF	cell already free
X'4016'	VRCILI	invalid LSM id
X'4017'	VRCICI	invalid cell id
X'4018'	VRCVNE	volume not errant
X'4019'	VRCIPI	invalid panel index
X'401A'	VRCBAL	Out-of-balance free cell count
X'4020'	VRCCVL	cell has volume
X'4021'	VRCCNV	cell has no volume
X'4022'	VRCTRM	cell scan terminated
X'4023'	VRCIET	invalid errant record
X'4024'	VRCISP	invalid scratch subpool index
X'4025'	VRCILB	invalid label type
X'4026'	VRCLWS	label without subpool qualifier
X'4027'	VRCNCL	no cleaning cartridges
X'4028'	VRCSCL	illegal attempt to scratch cleaner

Table 9. Volume/Cell Return Codes -- With Parameter List (Continued)

Equate Value	Name	Description
X'4029'	VRCNCM	unable to communicate
X'4030'	VRCNSV	Not scratch volume
X'4031'	VRCSAE	Volume selected by errant recovery
X'4032'	VRCNAP	Not approved for scratch selection
X'4033'	VRCABT	Abort scratch selection
X'4034'	VRCMVC	Illegal to scratch VSM MVC
X'4037'	VRCDRTST	DR test prevents scratch request
X'4098'	VRCIOS	data base I/O error, (vol selected)
X'4099'	VRCIOE	data base I/O error

Table 10. Configuration Return Codes

Equate Value	Name	Description
X'0000'	FRCOKAY	function completed normally
X'0004'	FRCMORE	More data present (FIGMGR LOOP=Y)
X'4502'	FRCIPLST	invalid Plist
X'4504'	FRCDDBIO	error reading/writing data base
X'4508'	FRCNHOST	no matching host id found in HCT
X'450C'	FRCILTIV	ILLT invalid or not supported
X'4510'	FRCCPOOL	no available storage in cell pool
X'0000'	FRCSACT	subsystem is active
X'4512'	FRCSIAT	subsystem is inactive
X'0000'	FRCAACT	ACS is connected
X'4514'	FRCAIAT	ACS is disconnected
X'0000'	FRCLACT	LSM is in automatic state
X'4516'	FRCLIAT	LSM is in manual state
X'4518'	FRCCIAT	CAP is not active
X'451A'	FRCCMANL	CAP is in manual mode
X'451C'	FRCCACT	CAP is not idle
X'451D'	FRCCOFF	CAP is offline
X'451E'	FRCCLEAN	drive needs cleaning

Table 10. Configuration Return Codes (Continued)

Equate Value	Name	Description
X'4520'	FRCALFLG	drive already flagged
X'4522'	FRCAINV	ACS identifier invalid
X'4524'	FRCLINV	LSM identifier invalid
X'4526'	FRCCINV	CAP identifier invalid
X'4528'	FRCUINV	unit address invalid
X'452C'	FRCDINV	drive identifier invalid
X'452E'	FRCMINV	LSM mode invalid
X'452F'	FRCMAIV	ACS mode invalid
X'4530'	FRCLKIV	lock token mode invalid
X'4532'	FRCALOK	LSM lock is not available
X'4534'	FRCNLOK	LSM was not previously locked
X'4536'	FRCRECFD	queue record found
X'453A'	FRCITOKN	token was incorrect
X'453C'	FRCIDATA	data was invalid
X'453E'	FRCTNFND	DATA type not found
X'4542'	FRCRCAP	CAP could not be released
X'4544'	FRCNCAP	no CAP available
X'4545'	FRCNCPAC	no CAP accessible in specified LSM
X'4546'	FRCHCAP	CAP not owned by this host
X'4548'	FRCACAP	CAP could not be activated
X'4550'	FRCABNR	CAP activated, but needs recovery
X'4552'	FRCNUCB	no UCB generated on this host
X'4554'	FRCNATT	SLSFLSMC could not be attached
X'4556'	FRCNMODE	not the FIGMGR mode requested
X'455A'	FRCPANIV	panel invalid
X'455C'	FRCROWIV	row invalid
X'455E'	FRCCOLIV	column invalid
X'4560'	FRCLMUC	LMU configuration read error
X'4562'	FRCNFER	configuration match error
X'4564'	FRCNBRD	host-to-host broadcast error

Table 10. Configuration Return Codes (Continued)

Equate Value	Name	Description
X'4566'	FRCLMUL	LMU error varying LSM status
X'4568'	FRCNRLS	data base release failed
X'456A'	FRCVRYFL	LMURQST vary station failure
X'456B'	FRCNRSRV	no reserve on the CDS
X'456C'	FRCNRECF	no record found
X'456D'	FRCSELECT	record already selected
X'456E'	FRCNAREA	insufficient space for output after configuration change
X'456F'	FRCLOGIC	config manager error
X'4570'	FRCNFTW	ACS contains 9740 LSMs
X'4571'	FRCNF20	LSM has 20 drive panels
X'4572'	FRCDRVNM	CDS/in memory drive discrepancy
X'4573'	FRCDRVTY	Drive type has been changed

Table 11. LMU Server Return Codes

Equate Value	Name	Description
X'0000'	LMUOKAY	function successfully completed
X'6500'	LMUESINV	source is invalid
X'6501'	LMUESEMP	source is empty
X'6502'	LMUESVNM	source volser does not match
X'6503'	LMUESVNR	source volser not readable
X'6504'	LMUESUVL	unexpected volser on source
X'6505'	LMUETINV	target is invalid
X'6506'	LMUETFUL	target is full
X'6507'	LMUESTNA	source/target not in same ATHS
X'6508'	LMUESTNL	source/target not in same LSM
X'6509'	LMUESTNS	source/target not the same type
X'6510'	LMUENPTP	no passthru port available for xfer
X'6511'	LMUENLMU	LMU not online
X'6512'	LMUELLMU	lost communication with LMU
X'6513'	LMUEMIHX	cancelled by missing interrupt handler

Table 11. LMU Server Return Codes (Continued)

Equate Value	Name	Description
X'6514'	LMUELSME	LSM hardware error
X'6515'	LMUELMUE	LMU hardware error
X'6516'	LMUECMNT	CAP in maintenance mode
X'6517'	LMUECDOP	CAP door is open
X'6518'	LMUEENTP	enter request pending
X'6519'	LMUEEJTP	eject request pending
X'6520'	LMUECCTP	CAP catalog pending
X'6521'	LMUEDLDE	drive load error
X'6522'	LMUEDULE	drive unload error
X'6523'	LMUEDALC	drive allocated error
X'6524'	LMUECRST	CAP already reserved to this host
X'6525'	LMUECRSO	CAP reserved to a host
X'6526'	LMUECNRT	CAP not reserved to this host
X'6527'	LMUEMPND	move is pending to/from CAP
X'6528'	LMUEDEAD	LMU is dead
X'6529'	LMUEIOPT	invalid option flag specified
X'652A'	LMUECRHG	CAP reserved to other host group
X'6530'	LMUEIOPC	option code is invalid
X'6531'	LMUESTBY	station is on standby
X'6532'	LMUEVUXR	volser unexpectedly readable
X'6533'	LMUEECBI	ECB Parm is invalid
X'6534'	LMUEEC2I	ECB2 Parm is invalid
X'6535'	LMUEVTMI	VIEW time is invalid
X'6536'	LMUEBVOB	bad VIEW object
X'6537'	LMUEDDSV	device doesn't support VIEW
X'6538'	LMUECMPT	compat level feature mismatch
X'6540'	LMUESTNF	Stations not found for initialization
X'6541'	LMUELAF	LMU listener attach failed
X'6542'	LMUETAF	LMU timer attach failed
X'6543'	LMUEDAF	LMU driver attach failed

Table 11. LMU Server Return Codes (Continued)

Equate Value	Name	Description
X'6544'	LMUESAF	LMU station simulator attach failed
X'6545'	LMUELSAF	LMU simulator attach failed
X'6546'	LMUEWAF	LMU worker attach failed
X'6547'	LMUEMNS	LMU level unsupported for HSC
X'6548'	LMUENHCT	no HCT address was found in LVT
X'6549'	LMUEORIP	offline request already in progress
X'6550'	LMUENOFF	station is not offline
X'6551'	LMUENONL	station is not online
X'6552'	LMUELDNE	LMU does not exist
X'6553'	LMUENSTA	station does not exist
X'6554'	LMUENSPN	source and target not in same panel
X'6555'	LMUESOFF	station is offline
X'6558'	LMUEINVF	invalid function
X'6568'	LMUENMSG	no broadcast message present
X'6574'	LMUEICIV	invalid character in volser
X'6575'	LMUEICIM	invalid character in message
X'6578'	LMUENSEQ	no seq number on vary station on
X'6579'	LMUEVSTO	timeout on vary station online
X'657B'	LMUEVACC	request cancelled by force offline
X'657C'	LMUENVST	no stations varied online by request
X'657D'	LMUEBCON	TCP/IP connection failure
X'6582'	LMUEMFAC	motion found against cartridge
X'6584'	LMUEIBID	invalid broadcast id
X'6586'	LMUEDNRW	drive is not rewind
X'6590'	LMUEUAST	unable to allocate station
X'6591'	LMUEOFST	open failed for station
X'6592'	LMUELSMO	LSM is offline
X'6593'	LMUESHPF	set host path group failed
X'6595'	LMUEEOTR	enter operations terminated
X'6596'	LMUERDNW	release did not work

Table 11. LMU Server Return Codes (Continued)

Equate Value	Name	Description
X'6598'	LMUEINVR	invalid response received from LMU
X'65A0'	LMUELON	LSM is online
X'65A1'	LMUELPON	LSM is pending online
X'65A2'	LMUELPOF	LSM is pending offline
X'65A3'	LMUELNON	LSM is not ready
X'65A4'	LMUELNOF	LSM is not offline
X'65A5'	LMUELMM	LSM is in maintenance mode
X'65A6'	LMUEIOE	LSM I/O error
X'65A7'	LMUECINV	invalid cancel request
X'65A8'	LMUEKILD	request was cancelled
X'65A9'	LMUECRNA	request to be cancelled not active
X'65AA'	LMUECLAT	too late to cancel specified request
X'65AB'	LMUEFOFF	LSM forced offline
X'65AC'	LMUESMMC	media miscompare
X'65AD'	LMUESMVM	media and volser miscompare
X'65AE'	LMUESIMD	incompatible media/drive
X'65AF'	LMUEMMAG	missing CAP magazine
X'65B0'	LMUERQBE	buffer not large enough to fit all request queue entries
X'65B1'	LMUERQBR	buffer required for request qcount, rqueues
X'65B2'	LMUEMNTO	maintenance door open
X'65E0'	LMUEAUTO	Auto operation completed
X'65F1'	LMUETERM	server in termination
X'65FF'	LMUEPRGD	request purged

Table 12. Data Base Server Return Codes

Equate Value	Name	Description
X'0000'	DRCOK	operation occurred without error
X'7004'	DRCPRMER	permanent I/O error on DB
X'7008'	DRCNODDN	no DDNAME statement for file

Table 12. Data Base Server Return Codes (Continued)

Equate Value	Name	Description
X'700C'	DRCRNF	record not found
X'7010'	DRCLOGIC	logic error, bad parameters
X'7014'	DRCNTRSV	data base not reserved by this task or any parent of this task
X'7024'	DRCHACT	host active
X'7028'	DRCHQIS	host inactive
X'702C'	DRCHNON	host non-extant
X'7030'	DRCINOB	no ITT blocks
X'7034'	DRCSHIO	uncorrectable I/O error on CDS
X'7038'	DRCRETIO	I/O path aborted
X'703C'	DRCENBAD	bad ENABLE from DEERE
X'7040'	DRCBDEYE	bad eyecatcher in record
X'7044'	DRCHRCVH	this host has been recovered
X'704C'	DRCABEND	user exit abend
X'7050'	DRCALLOC	dynamic allocation failed
X'7054'	DRCOPNER	open error
X'7058'	DRCATTCH	DIOM attach failed
X'705C'	DRCPARME	error found in PARMLIB entry
X'7060'	DRCNVS	named variable service error
X'7064'	DRCUNALO	database is unallocated
X'7068'	DRCERROR	database is in error status
X'7078'	DRCLNMM	length mismatch
X'707C'	DRCFMMM	Reserved
X'7080'	DRCEOSF	end of Subfile
X'7084'	DRCSFNF	subfile not found
X'7088'	DRCINVLN	RECLN < 1 or > 4000
X'708C'	DRCDSUTR	all CDS copies are untrustworthy
X'7090'	DRCDSMLT	CDS copies not from a single CDS
X'7094'	DRCNRDIR	SLSDRDIR unable to rebuild dir
X'7098'	DRCFCORR	Corruption found. Retry read.
X'709C'	DRCFHSQ	shadow sequence out-of-sync

Table 12. Data Base Server Return Codes (Continued)

Equate Value	Name	Description
X'70A0'	DRCHSTIC	Incompatible host found at startup
X'70A4'	DRCRDEOF	Block read is not in the CDS
X'70A8'	DRCNCBAD	New CDS is an unusable dataset
X'70AC'	DRCNCSIZ	New CDS insufficient size
X'70B0'	DRCNCIOE	I/O error initializing new CDS
X'70B4'	DRCDEXSI	CDS current size unchanged
X'7400'	DRCDUPL	duplicate record found on add
C'E'	DRCENA	an enable switch has come in
C'D'	DRCDISA	a disable switch has come in

Table 13. Address Space Communications Return Codes

Equate Value	Name	Description
X'0000'	ORCOK	function complete
X'8004'	QRCNOALS	ALS is not active
X'800C'	QRCINVFC	invalid function code
X'8010'	QRCNOLVT	PC routine could not find LVT
X'8014'	QRCQNOA	ASCOMM is not active
X'8018'	QRCINVOP	invalid QUAB option
X'801C'	QRCINVTK	invalid token
X'8020'	QRCEDTIS	end dedicated task issued
X'8024'	QRCTABND	ASCOMM server task abended
X'8028'	QRCXDPER	XDPLST offset in DATA or RSP bad
X'8078'	QRCGMFAL	GETMAIN request for CSA failed

Table 14. Address Space Communication Function Codes

Equate Value	Name	Description
1	QFCXUSER	HSC user interface request
2	QFCUNSEL	unselect
3	QFCSVARS	named variable service
4	QFCSVXIQ	VOL/CELL query subpool service

Table 14. Address Space Communication Function Codes (Continued)

Equate Value	Name	Description
5	QFCSVXST	VOL/CELL set scratch threshold
9	QFCSLCD	Load/Call/Delete service
12	QFCUINCT	initialize cartridges
21	QFCUCFGR	MVS/CSC Configuration verify
24	QFCUEJCT	eject cartridges
35	QFCUAUDT	audit
36	QFCUSCUP	scratch update
48	QFCXTLMS	VM tape management interface
49	QFCUENTR	enter utility server
64	QFCUMERG	CDS Merge
68	QFCUVOLR	volume report
70	QFCUSCRD	scratch redistribution
80	QFCUMOVE	move cartridge
124	QFCTOAMD	operator command
127	QFCAVLKP	allocation volume lookup
130	QFCJVLKP	job processing volume lookup
131	QFCJTLKP	Job Processing tapereq lookup
132	QFCJDLKP	Job Processing drive lookup
134	QFCMRQST	mount/dismount request
135	QFCMEJW	mount/dismount eject waiter
140	QFCEVLKP	JES3 volume lookup
150	QFCFMGR	config management
151	QFCMVPST	mount search and post
152	QFCSTRAC	cross memory SLSTRACE
160	QFCSTSR	VTCS QUIM Server Request Handler

Table 15. Recovery Return Codes

Equate Value	Name	Description
X'0000'	RRCOK	good return
X'8504'	RRCCINIT	cease initialization

Table 15. Recovery Return Codes (Continued)

Equate Value	Name	Description
X'8508'	RRCVOLER	volume is errant
X'850C'	RRCHOACT	host is active
X'8510'	RRCNOITT	no ITT records for host recovery
X'8514'	RRCACHDI	ACS is disconnected
X'8518'	RRCLSMOF	LSM is offline
X'851C'	RRCVOLDE	volume does not exist
X'8520'	RRCDBERR	data base error
X'8524'	RRCNOCAP	no CAP available
X'8528'	RRCSTDO	subsystem is terminating
X'852C'	RRCABEND	received SLS ABEND; high order two bytes contain the low order two bytes of R15 at abend time (reason code)
X'8530'	RRCBHOST	invalid host id
X'8534'	RRCVOLNE	volume is not errant
X'8538'	RRCVOLUN	volume should be unselected
X'8540'	RRCHRCAC	host recovery already in progress
X'8544'	RRCLMUER	LMU error
X'8548'	RRSELERR	selected by errant volume recovery
X'854C'	RRCVOLME	Volume mount errant on drive
X'85FC'	RRCMVSAB	received an MVS ABEND; high order two bytes contain the abend flag bits and system completion code
X'8550'	RRCDRVLD	drive loaded, no message requested
X'8554'	RRCVLMSM	wrong volume after forced rewind

Table 16. Service Component Return Codes

Equate Value	Name	Description
X'0000'	SRCOK	service successfully completed
X'0004'	SRCMORE	More processing required
X'9000'	SEIDPGMI	PGMI/TMI move type request
X'9001'	SRCVRNF	volume not found in CDS
X'9002'	SRCRNF	cell not a storage cell

Table 16. Service Component Return Codes (Continued)

Equate Value	Name	Description
X'9003'	SRCSEERR	FROM volume could not be selected
X'9004'	SRCACSI	ACS ID is invalid
X'9005'	SRCACSD	ACS ID is disconnected
X'9006'	SRCINVL	invalid LSM ID
X'9007'	SRCLMOF	LSM ID is offline
X'9008'	SRCLMUE	LMU error
X'9009'	SRCNCEL	no cells available for service
X'9010'	SRCNLSM	no LSMs available for service
X'9011'	SRCAUDA	conflicting Audit Utility active
X'9012'	SRCAREC	audit of LSM x is recommended
X'9013'	SRCNMAT	volume does not match location
X'9014'	SRCEXUR	external label is unreadable
X'9015'	SRCCEMY	cell is empty
X'9016'	SRCTPCF	"TO" panel conflicts with Source Panel
X'9017'	SRCTLOF	"TO" LSM offline
X'9018'	SRCSTUC	cartridge is stuck
X'9019'	SRCLOFF	LMURQST LSM offline indicator VAR
X'901A'	SRCVRAC	Volume not found in specific ACS
X'901B'	SRCNSUBS	HSC subsystem not active
X'901C'	SRCESNES	ESTAE not established
X'901D'	SRC SABND	Service abended
X'9020'	SRCBDVL	length specified for VALUEL was too small to contain value
X'9021'	SRCNOMA	no match found for specified NAME
X'9030'	SRC SACIL	length specified for INLEN was invalid
X'9031'	SRC SACOL	length specified for OUTLEN was invalid
X'9032'	SRC SACTB	no match found for specified Accumulation table
X'9033'	SRC SACEL	invalid element was found
X'9034'	SRC SACPL	invalid parameter list found
X'9035'	SRC SACDT	invalid data type found

Table 16. Service Component Return Codes (Continued)

Equate Value	Name	Description
X'9036'	SRCSACER	SLSSACCM logic error
X'9040'	SRCMINL	length not adequate for minimums
X'9041'	SRCINVC	command is not valid
X'9050'	SVXINEND	end of list
X'9051'	SVXIVFUN	invalid SVXINQ function code
X'9052'	SVXINOMT	no match found for subpool name
X'9053'	SVXINOAC	no match found for ACS
X'9054'	SVXINOLM	no match found for LSM
X'9055'	SVXINSBF	no subpool data found
X'9056'	SVXINOSP	No space in buffer provided
X'9057'	SVXINCAL	Invalid SVXINQ request
X'9058'	SVXINMSC	No MSC found
X'9060'	SRCINVMN	invalid monitor string
X'9070'	SRCNOMON	monitor service not available
X'9071'	SRCNOSTR	no storage available
X'9080'	SRCSVINV	console ID is invalid
X'9090'	SRCUXBUX	BUXCHT missing all inactive
X'9091'	SCRUXNUM	bad user exit number
X'9092'	SRCUXMOD	module not found
X'9093'	SRCUXERR	load error on module
X'9094'	SRCUXPLT	bad function or plist
X'9095'	SRCUXSTA	status invalid for request
X'9096'	SRCUXLOK	a lock attempt failed
X'9097'	SRCUXLGC	a logic error occurred
X'9098'	SRCUXDDN	SLSUEXIT DD missing
X'9099'	SRCUXNOD	no dynamic load allowed
X'909A'	SRCABEND	Software failure
X'90A0'	SRCSNPTH	SPATH no CAPs available for pathing
X'90B0'	SRCNSAV	Service not available
X'90B9'	SRC90B9	Abend occurred - ESTAE invoked

Table 16. Service Component Return Codes (Continued)

Equate Value	Name	Description
X'90FF'	SRCUNKN	unknown error from SLSSMOVE
X'9101'	SRCSABAN	scratch-request not tried; service not up
X'9102'	SRCSABRL	scratch-request not OK; in retry and Q-lckd.
X'9103'	SRCSABLK	scratch-request not processed; Q-locked
X'9104'	SRCSABAO	subtask Attach-time ran out
X'9105'	SRCSABDN	detach-request not tried; service not up
X'9106'	SRCSABDO	subtask Detatch-time ran out
X'9107'	SRCSABTS	subtasks still around at termin.
X'9108'	SRCSABSN	duplict/same-name subtask; no attach
X'9109'	SRCSABAT	bad MVS attach macro return code
X'9110'	SRCSABIM	can't initialize & attached. max times
X'9120'	SRCCVFNS	FLSM record not supplied
X'9121'	SRCCVIFR	Invalid FLSM record supplied
X'9122'	SRCCVILN	Location/FLSM LSM numbers are different
X'9123'	SRCCVIPT	Invalid panel type
X'9124'	SRCCVCNA	Cell not allocatable
X'9130'	SRCACDNY	Access denied
X'9131'	SRCWRTPR	Write protect

Table 17. Host Communications Services Return Codes

Equate Value	Name	Description
X'0000'	HCSOK	function successfully completed
X'9201'	HCSENINT	service not initialized
X'9202'	HCSETRMP	termination already in progress
X'9203'	HCSEINVF	invalid function requested
X'9204'	HCSEINVL	invalid message data length specified
X'9205'	HCSENTRG	not previously registered
X'9206'	HCSENOMS	no message available
X'9207'	HCSWWD	method switch needed

Table 17. Host Communications Services Return Codes (Continued)

Equate Value	Name	Description
X'9208'	HCSEINVT	invalid message type
X'9209'	HCSEINVH	invalid host specification type
X'920A'	HCSENHST	no matching host found
X'920B'	HCSENCMS	no CDS message for host
X'920C'	HCSEINVM	invalid method (no path defined)
X'920D'	HCSEUNKM	unknown method specified
X'920E'	HCSEHMLM	host's method limit exceeded
X'920F'	HCSEACTV	action attempted for active VTAMPATH
X'9210'	HCSEACTL	action attempted for active LMUPATH
X'9211'	HCSEDALL	DEL ALL specified for current method
X'9212'	HCSEMXP	maximum LMUPATH definitions exceeded
X'9213'	HCSEINVA	invalid ACSid (method not LMU)
X'9214'	HCSEUNDA	undefined ACSid (LMUPATH)
X'9215'	HCSENMVP	no matching VTAMPATH to delete
X'9216'	HCSENMPL	no matching LMUPATH to delete
X'9217'	HCSESWTE	switch routine returned error
X'9218'	HCSEINVP	invalid message priority specified
X'9219'	HCSEINVB	invalid control block passed
X'921A'	HCSEIMLM	invalid method limit
X'921B'	HCSEEMLM	host entry method limit exceeded
X'921C'	HCSEHNVL	host not available via LMU
X'921D'	HCSENSCA	no send conversation active
X'921E'	HCSEISWF	invalid "switch from" parameters
X'921F'	HCSEABND	abend occurred

Appendix A. Message Route Codes and Descriptor Codes

This appendix provides a cross-reference list of message numbers to route codes and descriptor codes.

If a message does not have an associated route code listed in the following table, the message is a response to a command. In this case, the message is routed only to the console where the command was issued.

Table 18. Message Route Codes & Descriptor Codes

Message-ID	Route Code(s)	Descriptor Code
SLS0001I		5
SLS0002I		5
SLS0003I		5
SLS0004I		5
SLS0005I		5
SLS0006I		5
SLS0007I	11	5
SLS0010I		5
SLS0011I		5
SLS0013I		5
SLS0015I	2,11	5
SLS0016I	2,11	5
SLS0017I	2,11	5
SLS0018I		5
SLS0019I	2,11	5
SLS0020I		5
SLS0021I		5
SLS0022I		5

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS0023I		5
SLS0024I	11	5
SLS0028I	11	5
SLS0029I	11	5
SLS0030I		2
SLS0031D	2,3,5,11	2
SLS0032I	2,11	4
SLS0033A	9	2
SLS0034I	9,11	5
SLS0035A	3,5,11	2
SLS0036I	3,5,11	4
SLS0037I	3,5,11	4
SLS0040I		5
SLS0041I		5
SLS0042I	3,11	4
SLS0045I		5
SLS0046I		5
SLS0047I		5
SLS0048I	11	5
SLS0049I	11	5
SLS0050I		5
SLS0053I		5
SLS0054I	3,11	5
SLS0055I		5
SLS0056I		5
SLS0057I	2,11	4
SLS0059I	3,11	5
SLS0060I		5
SLS0061I		5
SLS0062I		5

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS0063I		5
SLS0068I		5
SLS0069I	2,11	5
SLS0070I	3,11	5
SLS0071I	2,11	5
SLS0072I	5,11	5
SLS0075D	3,5,11	2
SLS0076I	2,11	4
SLS0077I	3,5,11	4
SLS0078I	3,5,11	4
SLS0079I	3,5,11	4
SLS0080I	3,5,11	4
SLS0081I	3,5,11	4
SLS0082I	3,5,11	4
SLS0083I	3,5,11	4
SLS0085I	3,5,11	4
SLS0086I	3,5,11	4
SLS0087I	3,5,11	4
SLS0088D	3,5,11	2
SLS0089E	3,5,11	3
SLS0090I	3,5,11	4
SLS0091I	3,5,11	4
SLS0092I	3,5,11	4
SLS0093I	3,5,11	4
SLS0094E	3,5,11	11
SLS0096I	3,5,11	4
SLS0098A	3,5,11	2
SLS0099I	3,5,11	4
SLS0100D	3,5,11	2
SLS0101I		5

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS0103E	3,11	11
SLS0104D	3,5,11	2
SLS0105A	3,5,11	2
SLS0107D	3,5,11	2
SLS0108D	3,5,11	2
SLS0109D	3,5,11	2
SLS0110I	3,5,11	4
SLS0111I	3,5,11	4
SLS0112E	3,11	11
SLS0113D	3,5,11	2
SLS0114D	3,5,11	2
SLS0115I	3,5,11	4
SLS0116I	3,5,11	4
SLS0117E	3,11	11
SLS0118D	3,5,11	2
SLS0119D	3,5,11	2
SLS0120E	3,11	11
SLS0121I	3,11	4
SLS0122D	3,5,11	2
SLS0123I	3,11	4
SLS0124I	3,5,11	4
SLS0125D	3,5,11	2
SLS0127I	3,11	4
SLS0128A	3,5,11	2
SLS0129I	2,11	4
SLS0130I	3,5,11	4
SLS0131I	3,11	4
SLS0132I	3,5,11	4
SLS0133I	3,5,11	4
SLS0134D	3,5,11	2

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS0135I	3,5,11	4
SLS0136D	3,5,11	2
SLS0137E	3,11	11
SLS0138D	3,5,11	2
SLS0139I	3,5,11	4
SLS0140I	3,5,11	4
SLS0141I	3,5,114	4
SLS0142I	3,5,11	4
SLS0143I	3,5,11	4
SLS0144I	3,5,11	4
SLS0145I	3,5,11	4
SLS0146I	3,5,11	4
SLS0147I	3,5,11	4
SLS0148I	3,11	4
SLS0149I	3,11	4
SLS0154A	2,11	2
SLS0250D	3,5,11	2
SLS0251E	3,5,11	3
SLS0252I	3,5,11	4
SLS0254I	3,5,11	4
SLS0255E	3,5,11	3
SLS0256I	3,5,11	4
SLS0257I	3,5,11	4
SLS0258I	3,5,11	4
SLS0259A	3,5,11	2
SLS0261A	3,5,11	2
SLS0262A	3,5,11	4
SLS0263D	3,5,11	2
SLS0265A	3,5,11	2
SLS0266I	3,5,11	4

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS0267A	3,5,11	2
SLS0268I	3,5,11	4
SLS0269I	3,5,11	4
SLS0301I	11	4
SLS0303I	3,11	4
SLS0306I	3,11	4
SLS0308I	3,11	4
SLS0310I	3,11	4
SLS0313E	2,11	11
SLS0315I	2,5	4
SLS0316I	2,5	4
SLS0317I	3,5,11	4
SLS0318I	2,5	4
SLS0319I	2,5	4
SLS0320I	2,11	4
SLS0360E	2,3,11	11
SLS0381A	2,3,11	11
SLS0404I	5,11	4
SLS0410I	3,5,11	4
SLS0411I	3,5,11	4
SLS0451I	2,11	4
SLS0452I	2,11	4
SLS0453I	3,11	4
SLS0454I	2,11	4
SLS0455I	2,11	4
SLS0456I	3,11	4
SLS0457I	3,11	4
SLS0458I	3,11	4
SLS0460I	2	4
SLS0500I	2	4

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS0501I	2,11	4
SLS0503I	2,11	4
SLS0504I	2,11	4
SLS0505I	2,11	4
SLS0506I	2,3,5	4
SLS0507I	2,11	4
SLS0508I	2,11	4
SLS0509I	2,11	4
SLS0510I	2,11	4
SLS0511I	2,11	4
SLS0512E	2,11	3
SLS0518D	2,11	2
SLS0519I	2,11	4
SLS0520I	2,11	4
SLS0521I	2,11	4
SLS0522I	2,11	4
SLS0523I	5,11	4
SLS0524I	5,11	4
SLS0525I	2,11	4
SLS0527I	2,3,5	4
SLS0529I	5,11	4
SLS0530I	2,11	4
SLS0531E	2,5,11	3
SLS0545I	2,3,5,11	4
SLS0548I	3,11	4
SLS0600I		5
SLS0601I		5
SLS0602I		5
SLS0603I		5
SLS0604I		5

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS0605I		5
SLS0606I		5
SLS0607I		5
SLS0608I		5
SLS0609I		5
SLS0610I	11	5
SLS0611I		5
SLS0612I	11	5
SLS0613I		5
SLS0651I	3,11	4
SLS0652I	3,11	4
SLS0653I	3,11	4
SLS0655I	3,11	4
SLS0660I	3,11	4
SLS0661E	3,11	11
SLS0662I	3,11	4
SLS0663I	3,11	4
SLS0664I	3,11	4
SLS0665E	3,11	11
SLS0666A	3,11	2
SLS0667I	3,11	4
SLS0668I	3,11	4
SLS0669A	3,11	2
SLS0670I	3,11	4
SLS0671I	3,11	4
SLS0672E	3,11	11
SLS0673I	3,11	4
SLS0674I	2,11	4
SLS0675E	3,11	3
SLS0676I	2,11	4

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS0677I	3,11	4
SLS0678I	3,11	4
SLS0679E	2,11	11
SLS0680I	2,11	4
SLS0681I	3,11	4
SLS0682D	3,11	2
SLS0683I	3,11	4
SLS0684I	3,11	4
SLS0685I	3,11	4
SLS0686I	3,11	4
SLS0687I	11	4
SLS0688I	3,11	4
SLS0689I	3,11	4
SLS0690E	3,11	3
SLS0691I	2,3,5,11	
SLS0696A	3,11	4
SLS0697I	3,11	4
SLS0698I	3,11	4
SLS0699I	3,11	4
SLS0702I	2,11	4
SLS0704E	2,11	3
SLS0707I	11	4
SLS0708I	11	4
SLS0712I	11	4
SLS0713I	11	4
SLS0714I	11	4
SLS0715I	2,11	4
SLS0717I	2,11	4
SLS0719I	2,11	4
SLS0720I	2,11	4

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS0721I	11	4
SLS0723I	2,11	4
SLS0724I	2,11	4
SLS0725E	2,5,11	3
SLS0726I	2,11	4
SLS0730I	2,3,5,11	4
SLS0745I	5,11	4
SLS0746I	5,11	4
SLS0747I	2,5,11	4
SLS0750I	2,11	4
SLS0751I	2,11	4
SLS0752I	2,11	4
SLS0760I	2,11	4
SLS0761E	2,11	3
SLS0762E	2,11	3
SLS0764I	2,5,11	4
SLS0765E	2,5,11	11
SLS0766E	2,5,11	3
SLS0767E	2,5,11	3
SLS0768E	2,5,11	3
SLS0769I	2,5,11	4
SLS0770I	2,5,11	4
SLS0805I	2,11	4
SLS0810I	2,11	4
SLS0850I	2,11	4
SLS0851I	2,11	4
SLS0852I	2,11	4
SLS0853I	2,11	4
SLS0854D	3,5,11	2
SLS0856D	3,5,11	2

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS0857I	11	4
SLS0858I	11	4
SLS0860D	3,5,11	2
SLS0863I	2,11	4
SLS0864I	3,5,11	4
SLS0865I	2,11	4
SLS0866I	2,11	4
SLS0867E	3,5,11	11
SLS0868I	3,11	4
SLS0869D	3,5,11	2
SLS0870I	3,5,11	4
SLS0871I	3,5,11	4
SLS0873I	3,5,11	4
SLS0900I	3,11	4
SLS0901D	3,5,11	2
SLS0902D	3,5,11	2
SLS0903D	3,5,11	2
SLS0904I	3,11	4
SLS0905D	3,5,11	2
SLS0906E	3,5,11	11
SLS0907I	3,5,11	4
SLS0908I	3,5,11	4
SLS0909D	3,5,11	2
SLS0910I	3,5,11	7
SLS0911D	3,5,11	2
SLS0912I	3,5,11	4
SLS0913I	3,5,11	4
SLS0917I	11	4
SLS0923I	3,11	4
SLS0925D	3,5,11	2

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS0926I	3,5,11	4
SLS0927A	3,5,11	2
SLS0928A	3,5,11	2
SLS0929I	3,5,11	4
SLS0931I	3,5,11	4
SLS0934D	3,5,11	2
SLS0935D	3,5,11	2
SLS0936D	3,5,11	2
SLS0937D	3,5,11	4
SLS0950I	2,11	7
SLS0951I	2,11	7
SLS0952I	2,11	7
SLS0953I	2,11	4
SLS0954D	2,11	2
SLS0955E	2,11	11
SLS0973I	5,11	7
SLS0974A	5,11	7,11
SLS1000I	11	5
SLS1001I	11	5
SLS1002I	11	5
SLS1003I	11	5
SLS1004I	11	5
SLS1005I	11	5
SLS1007I	2,3,11	5
SLS1010I		5
SLS1011I		5
SLS1012I		5
SLS1014I	11	5
SLS1015I		5
SLS1016I		5

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS1018I		5
SLS1026I		5
SLS1027I		5
SLS1028I		5
SLS1030I		5
SLS1031I	11	5
SLS1032I	11	5
SLS1033I	11	5
SLS1034I	11	5
SLS1035I		5
SLS1037I	11	5
SLS1038I	11	5
SLS1039I	11	5
SLS1040I	11	5
SLS1041I	11	5
SLS1042I	11	5
SLS1050I	11	5
SLS1051I	11	5
SLS1052I	11	5
SLS1071D	2,3,11	2
SLS1072I	11	4
SLS1074I	11	5
SLS1075D	3,5,11	2
SLS1250D	3,5,11	2
SLS1300D	2,3,11	2
SLS1301I	2,3	4
SLS1317I	2,11	4
SLS1320I	1,3,5,11	2,7
SLS1403I	5,11	11
SLS1406I	5,11	11

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS1407I	3,5,11	4
SLS1408I	3,5,11	4
SLS1409I	5,11	11
SLS1450I	11	4
SLS1500I	2,11	4
SLS1501I	2,11	4
SLS1502I	11	4
SLS1505I	2,3,5,11	4
SLS1506I	2,3,5,11	4
SLS1507I	2,11	5
SLS1508I	2,11	5
SLS1509I	2,11	5
SLS1510I	2,11	5
SLS1512I	2,11	5
SLS1513I	2,3,5,11	4
SLS1515I	2,11	4
SLS1519I	2,11	5
SLS1600I	11	5
SLS1601I	11	5
SLS1602I		5
SLS1603I		5
SLS1604I		5
SLS1605I		5
SLS1606I		5
SLS1607I		5
SLS1608I		5
SLS1610I		5
SLS1611I		5
SLS1612I		5
SLS1613I		5

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS1614I		5
SLS1615I		5
SLS1616I		5
SLS1617E		5
SLS1618I		5
SLS1619I		5
SLS1620I		5
SLS1625I		5
SLS1626I		5
SLS1627I		5
SLS1628I		5
SLS1629I		5
SLS1630I		5
SLS1631I		5
SLS1616I		5
SLS1650E	2,3,11	11
SLS1651I	2,3,11	4
SLS1652I	2,3,11	4
SLS1653D	2,3,11	2
SLS1654I	2,3,11	4
SLS1655I	2,3,11	4
SLS1656E	2,3,11	11
SLS1657I	2,3,11	4
SLS1658E	2,3,11	11
SLS1659E	2,3,11	11
SLS1660E	2,3,11	3
SLS1661I	2,11	4
SLS1662I	2,11	4
SLS1663I	2,3,11	11
SLS1664A	2,3,11	11

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS1665E	2,11	4
SLS1700I	2,11	4
SLS1702I	2,11	4
SLS1703I	2,11	11
SLS1704I	2,11	4
SLS1705E	2,11	11
SLS1706E	2,11	11
SLS1708I	2,11	5
SLS1709I	2,11	11
SLS1710E	2,11	11
SLS1711I	2,11	11
SLS1712I	2,11	4
SLS1713I	2,11	5
SLS1714I	2,11	5
SLS1715I	11	4
SLS1717I	2,11	4
SLS1718I	2,11	4
SLS1719I	2,11	4
SLS1720E	2,11	5
SLS1721I	2,11	4
SLS1722I	2,11	4
SLS1723I	2,11	4
SLS1724I	2,11	4
SLS1725I	2,11	5
SLS1727I	2,11	11
SLS1729I	2,11	11
SLS1730I	2,11	4
SLS1731I	2,11	11
SLS1733I	2,11	11
SLS1735I	2,11	4

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS1737E	2,11	3
SLS1738E	2,11	3
SLS1900I	2,11	5
SLS1901I	2,11	4
SLS1902D	2,11	4
SLS1903I	2,11	4
SLS1904E	2,11	3
SLS1905I	2,11	4
SLS1906I	2	4
SLS1950I		5
SLS1951I		5
SLS1952I		5
SLS1953I	2,11	5
SLS1954I		5
SLS1955I		5
SLS1956I		5
SLS1957I		5
SLS1958I		5
SLS1959I	5	5
SLS1960I	5	5
SLS1961I	5	5
SLS1962I	2,11	4
SLS1963I	2,11	4
SLS1964I		5
SLS1965I		4
SLS1966I	2,11	4
SLS1969I	2,11	4
SLS1970I	11	4
SLS1971I	2,11	4
SLS1972D	2,11	4

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS2008I	11	5
SLS2009I	11	5
SLS2011I		5
SLS2012I		5
SLS2013I		5
SLS2014I	11	5
SLS2033I		5
SLS2034I		5
SLS2038I		5
SLS2039I		5
SLS2075I	11	2
SLS2080I	3,5,11	4
SLS2081I	3,5,11	4
SLS2082I	3,5,11	4
SLS2102D	3,5,11	2
SLS2108D	3,5,11	2
SLS2114D	3,5,11	2
SLS2124I	3,5,11	4
SLS2126I	3,5,11	2
SLS2154I	11	5
SLS2155I	11	5
SLS2169I	11	5
SLS2250I	3,11	4
SLS2251A	3,5,11	2
SLS2252A	3,5,11	2
SLS2253I	3,11	4
SLS2254A	3,5,11	2
SLS2255I	3,5,11	2
SLS2256I	3,5,11	2
SLS2257I	3,5,11	4

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS2258I	3,5,11	4
SLS2259A	3,5,11	2
SLS2260I	3,5,11	2
SLS2261I	3,5,11	2
SLS2262I	3,5,11	4
SLS2263I	3,5,11	4
SLS2264E	3,11	11
SLS2267I	3,5,11	4
SLS2276I	3,5,11	4
SLS2303I	3,11	4
SLS2305I	3,11	4
SLS2375I	20	10
SLS2412I	3,5,11	4
SLS2450E	2,11	3
SLS2459I	2,11	4
SLS2460I	2,11	4
SLS2463I	2,3,11	4
SLS2501I	2,11	4
SLS2502I	2,11	4
SLS2526I	2,11	4
SLS2528I	2,11	4
SLS2550I	3,5,11	2
SLS2559I	3,5,11	2
SLS2580E	3,5,11	2
SLS2581A	3,5,11	2
SLS2610I		5
SLS2615I		5
SLS2616D		5
SLS2617I		5
SLS2618I		5

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS2620I		5
SLS2621I		5
SLS2622I		5
SLS2623I		5
SLS2624I		5
SLS2625I	11	5
SLS2627I		5
SLS2628I		5
SLS2629I	11	5
SLS2630I		5
SLS2631I		5
SLS2632I		5
SLS2633E		4
SLS2635I		5
SLS2636A	9	2
SLS2637I		4
SLS2639I	5	4
SLS2640I		5
SLS2641I		5
SLS2642I		5
SLS2643I		5
SLS2644I		5
SLS2645I		5
SLS2646I		5
SLS2647I	2,11	4
SLS2648I	2,11	4
SLS2651I	2,3,11	4
SLS2654I		5
SLS2656I		5
SLS2701E	2,11	11

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS2702E	2,11	11
SLS2716I		4,8,9
SLS2740I	5	11
SLS2741E	2,11	11
SLS2850I	3,5,11	4
SLS2901D	3,5,11	2
SLS2911D	3,5,11	2
SLS2912I		5
SLS2914I	11	5
SLS2915I	11	5
SLS2916I	11	4
SLS2934I	3,5,11	4
SLS2962I	3,5,11	4
SLS2964E	3,5,11	11
SLS2972I	11	5
SLS2973I	11	5
SLS2974I	2,11	4
SLS2976I	2,11	4
SLS2977I	2,11	4
SLS2978A	9	2
SLS2979I		4
SLS2980I		5
SLS2984D	3,5,11	2
SLS2985I		5
SLS2986I		5
SLS4266A	3,5,11	2
SLS4306I	1,3,11	2,7
SLS4308I	1,3,11	2,7
SLS4310D	1,3,11	2
SLS4451I	2,3,11	4

Table 18. Message Route Codes & Descriptor Codes (Continued)

Message-ID	Route Code(s)	Descriptor Code
SLS4453I	2,3,11	4
SLS4454I	2,3,11	4
SLS4455E	2,3,11	4
SLS4650E	2,3,11	3
SLS4736E	2,11	11
SLS4737E	2,11	11
SLS4738I	2,11	11
SLS6001I	3,11	4
SLS6002I	3,11	4
SLS6004I	3,11	4
SLS6009I	11	5
SLS6010I	11	5
SLS6011I	11	5

Appendix B. Message Change Summary - HSC 6.1

This appendix presents a summary of messages added, deleted, changed, and replaced for HSC 6.1.

Message Modifications

Messages Added

Message No.	Message No.	Message No.	Message No.
SLS0008I	SLS0009I	SLS0012I	SLS0073I
SLS0695I	SLS1183E	SLS1191E	SLS1255I
SLS1633I	SLS1636D	SLS1637I	SLS1907I
SLS2050I	SLS2587E	SLS4001I	SLS4002I
SLS4232I	SLS4233I	SLS4252I	SLS4412I
SLS4413I	SLS4414I	SLS4415I	SLS4416E
SLS4417E	SLS4418E	SLS4419I	SLS4420E
SLS4421E	SLS4422E	SLS4423E	SLS4424E
SLS4425E	SLS4467E	SLS4805I	SLS6015I
SLS6029I	SLS6040I	SLS6045I	SLS7000E
SLS7001E	SLS7002E	SLS7003E	SLS7004E
SLS7005E	SLS7006E	SLS7007E	SLS7008E
SLS7009E	SLS7010I	SLS7011I	SLS7012E
SLS7013E	SLS7014E	SLS7015I	SLS7016E
SLS7017E	SLS7018E	SLS7019E	SLS7020E
SLS7021I	SLS7022E	SLS7023E	SLS7024E
SLS7025E	SLS7026E	SLS7027E	SLS7028I
SLS7029E	SLS7031I	SLS7032I	SLS7033I
SLS7034I	SLS7035E	SLS7040I	SLS7041I
SLS7042I	SLS7043I	SLS7044I	SLS7050E
SLS7051E	SLS7052E	SLS7053E	SLS7054E
SLS7055E	SLS7056E	SLS7057E	SLS7058E
SLS7059E	SLS7060E	SLS7061E	SLS7062E
SLS7063E	SLS7070I	SLS7071I	SLS7072I
SLS7073I	SLS7074I	SLS7075I	SLS7076I
SLS7077I	SLS7078I	SLS7080I	SLS7081I
SLS7082I	SLS7083I	SLS7084E	SLS7085E
SLS7090A	SLS7091A	SLS7092A	SLS7100I

Message No.	Message No.	Message No.	Message No.
SLS7101E	SLS7102I	SLS7103E	SLS7104I
SLS7105E	SLS7106I	SLS7107I	SLS7108I
SLS7109I	SLS7110E	SLS7111I	SLS7112I
SLS7150E	SLS7151E	SLS7152E	SLS7153E
SLS7170I	SLS7171I	SLS7172I	SLS7180I
SLS7181I	SLS7182I	SLS7183E	SLS7184E
SLS7185E	SLS7186I	SLS7187E	SLS7188I

Messages Deleted

Message No.	Message No.	Message No.	Message No.
SLS4510A	SLS4514E		

Messages Changed

Message No.	Message No.	Message No.	Message No.
SLS0040I	SLS0054I	SLS0056I	SLS0073I
SLS0157I	SLS0197I	SLS0275I	SLS0388I
SLS0460I	SLS0512E	SLS0553I	SLS0557I
SLS0653I	SLS0663I	SLS0695I	SLS0699I
SLS0869D	SLS0929I	SLS0938I	SLS1000I
SLS1074I	SLS1187I	SLS1610I	SLS1627I
SLS1628I	SLS1632I	SLS1634I	SLS1635D
SLS1664A	SLS1958I	SLS2008I	SLS2011I
SLS2014I	SLS2184I	SLS2619I	SLS2623I
SLS2640I	SLS2716I	SLS2916I	SLS4000I
SLS4087I	SLS4231I	SLS4233I	SLS4244E
SLS4251D	SLS4400I	SLS4401I	SLS4406I
SLS4407I	SLS4409I	SLS4419I	SLS4424E
SLS4456I	SLS4457E	SLS4458E	SLS4459I
SLS4460I	SLS4461I	SLS4462I	SLS4463I
SLS4464E	SLS4465I	SLS4466I	SLS4610I
SLS4633I	SLS4641I	SLS4642I	SLS4643I
SLS4682D	SLS4803I	SLS4805I	SLS4970I
SLS4971I	SLS4972I	SLS4973I	SLS4974I

Messages Replaced

None.

Glossary

Terms are defined as they are used in the text. If you cannot find a term here, check the index.

A

AC— Alternating current.

access method— A technique for moving data between processor storage and I/O devices.

ACS— *See* Automated Cartridge System.

ACSid— An ACSid (*acs-id*) is a hexadecimal value from 00 through FF that identifies the LMU. An ACSid is the result of defining the SLIALIST macro during the library generation (LIBGEN) process. The first ACS listed in this macro acquires a hexadecimal identifier of 00, the second acquires a hexadecimal identifier of 01, and so forth, until all ACSs are identified.

allocation— The selection of a cartridge drive, either inside the library or outside (by the SMC software for SMC allocation, or MVS for MVS allocation without the HSC).

APF— Authorized Program Facility.

APPL— VTAM APPLID definition for the HSC.

archiving— The storage of backup files and associated journals, usually for a given period of time.

Automated Cartridge System (ACS)— The library subsystem consisting of one or two LMUs, and from 1 to 16 attached LSMs.

automated library— *See* library.

automatic mode— A relationship between an LSM and all attached hosts. LSMs operating in automatic mode handle cartridges without operator

intervention. This is the normal operating mode of an LSM that has been modified online.

B

basic direct access method (BDAM)— An access method used to directly retrieve or update particular blocks of a data set on a direct access device.

basic sequential access method (BSAM)— An access method for storing and retrieving data blocks in a continuous sequence, using either a sequential access or direct access device.

BDAM— *See* Basic direct access method.

beginning-of-tape (BOT)— The location on a tape where written data begins.

block— A collection of contiguous records recorded as a unit. Blocks are separated by interblock gaps, and each block may contain one or more records.

BOT— *See* beginning-of-tape.

BSAM— *See* Basic Sequential Access Method.

buffer— A routine or storage used to compensate for a difference in rate of data flow, or time of occurrence of events, when transferring data from one device to another.

C

CA-1 (TMS)— Computer Associates Tape Management

System— Third-party software by Computer Associates International, Inc.

CAP— *See* Cartridge Access Port.

capacity— *See* media capacity.

CAPid— A CAPid uniquely defines the location of a CAP by the LSM on which it resides. A CAPid is of the form *AAL:CC* where *AA* is the ACSid, *L* is the LSM number, and *CC* is the CAP number. Some commands and utilities permit an abbreviated CAPid format of *AAL*.

cartridge— The plastic housing around the tape. It is approximately 4 inches (100 mm) by 5 inches (125 mm) by 1 inch (25 mm). The tape is threaded automatically when loaded in a transport. A plastic leader block is attached to the tape for automatic threading. The spine of the cartridge contains a Tri-Optic label listing the VOLSER.

Cartridge Access Port (CAP)— An assembly which allows an operator to enter and eject cartridges during automated operations. The CAP is located on the access door of an LSM.

See also standard CAP, enhanced CAP, priority CAP, WolfCreek CAP, WolfCreek optional CAP, or TimberWolf CAP.

Cartridge Drive (CD)— A device containing two or four cartridge transports with associated power and pneumatic supplies.

Cartridge Scratch Loader— An optional feature for the Cartridge Drive. It allows the automatic loading of premounted tape cartridges or the manual loading of single tape cartridges.

cartridge system tape— Also known as a Standard tape. The basic tape cartridge media that can be used with 4480, 4490, or 9490 Cartridge Subsystems. They are visually identified by a one-color cartridge case.

CAW— *See* Channel Address Word.

CD— *See* Cartridge Drive.

CDRM— Cross Domain Resource Manager definition (if not using existing CDRMs).

CDRSC— Cross Domain Resource definition.

CDS— *See* control data set.

CE— Channel End.

CEL— Customer Emulation Lab. cell. A storage slot in the LSM that is used to store a tape cartridge.

Central Support Remote Center (CSRC)— *See* Remote Diagnostics Center.

CFT— Customer Field Test.

channel— A device that connects the host and main storage with the input and output control units.

Channel Address Word (CAW)— An area in storage that specifies the location in main storage where a channel program begins.

channel command— A command received by a CU from a channel.

Channel Status Word (CSW)— An area in storage that provides information about the termination of I/O operations.

check— Detection of an error condition.

CI— Converter/Interpreter (JES3).

connected mode— A relationship between a host and an ACS. In this mode, the host and an ACS are capable of communicating (at least one station to this ACS is online).

control data set (CDS)— The data set containing all configuration and volume information used by the host software to control the functions of the automated library. Also known as a library control data set.

See also Primary CDS, Secondary CDS, and Standby CDS.

control data set allocation map— A CDS subfile that marks individual blocks as used or free.

control data set data blocks— CDS blocks that contain information about the library and its configuration or environment.

control data set directory— A part of the CDS that maps its subdivision into subfiles.

control data set free blocks— CDS blocks available for future subfile expansion.

control data set pointer blocks— CDS blocks that contain pointers to map data blocks belonging to a subfile.

control data set recovery area— A portion of the CDS reserved for maintaining integrity for updates that affect multiple CDS blocks.

control data set subfile— A portion of the CDS consisting of Data Blocks and Pointer Blocks containing related information.

Control Unit (CU)— (1) A microprocessor-based unit situated logically between a host channel (or channels) and from two to sixteen transports. It functions to translate channel commands into transport commands, send transport status to the channel(s), and pass data between the channel(s) and transport(s). (2) A device that controls I/O operations for one or more devices. cross-host recovery. The ability for one host to perform recovery for another host that has failed.

CSE— Customer Service Engineer.

CSI— Consolidated System Inventory.

CSL— *See* Cartridge Scratch Loader.

CSRC— Central Support Remote Center (*See* Remote Diagnostics Center)

CST— (1) A value that can be specified on the MEDia parameter and that includes only standard capacity cartridge tapes. (2) An alias of Standard. (3) *See* Cartridge System Tape.

CSW— *See* Channel Status Word.

CU— *See* Control Unit.

D

DAE— Dump Analysis Elimination.

DASD— Direct access storage device.

data— Any representations such as characters or analog quantities to which meaning is, or might be, assigned.

Database Heartbeat record (DHB)— The record that contains the names of the control data sets recorded by the HSC and identifies the correct primary, secondary, and standby CDS.

data class— A collection of allocation and space attributes, defined by the storage administrator, that are used to create a data set.

data compaction— An algorithmic data-reduction technique that encodes data from the host and stores it in less space than unencoded data. The original data is recovered by an inverse process called decompression.

data-compaction ratio— The number of host data bytes mathematically divided by the number of encoded bytes. It is variable depending on the characteristics of the data being processed. The more random the data stream, the lower the opportunity to achieve compaction.

Data Control Block (DCB)— A control block used by access routines in storing and retrieving data.

data set— The major unit of data storage and retrieval, consisting of a collection of data in one of several prescribed arrangements and described by control information to which the system has access.

data streaming— A continuous stream of data being transmitted in character or binary-digit form, using a specified format.

DC— Direct current.

DCB— *See* Data Control Block.

DD3— A generic value that can be specified on the MEDia and RECtech parameters and includes all types of helical cartridges and recording techniques.

DD3A, DD3B, DD3C, DD3D— Values that can be specified on the MEDia parameter and include only the specified type of helical cartridge. Aliases are A, B, C, and D, respectively.

DDR— *See* Dynamic Device Reconfiguration.

default value— A value assumed when no value has been specified.

demand allocation— An MVS term meaning that a user has requested a specific unit.

device allocation— The HSC function of *influencing* the MVS device selection process to choose either a manual transport or a transport in a particular ACS, based on the location of the volume (specific requests) or the subpool rules in effect (scratch requests).

device group— A subset of the eligible devices. Device groups are defined by esoteric unit names but also may be created implicitly if common devices exist in different device groups.

device number— A four-digit hexadecimal number that uniquely identifies a device attached to a processor.

device separation— *See* drive exclusion.

DFP— Data Facility Product. A program that isolates applications from storage devices, storage management, and storage device hierarchy management.

DFSMS— Refers to an environment running MVS/ESA SP and DFSMS/MVS, DFSORT, and RACF. This environment helps automate and centralize the management of storage through a combination of hardware, software, and policies.

DFSMS ACS routine— A sequence of instructions for having the system assign data class, storage class, management class, and storage group for a data set.

DHB— *See* Database Heartbeat record.

directed allocation— *See* drive prioritization.

disconnected mode— A relationship between a host and an ACS. In this mode, the host and an ACS are not capable of communicating (there are no online stations to this ACS).

DOMed— Pertaining to a console message that was previously highlighted during execution, but is now at normal intensity.

drive exclusion— (previously referred to as *device separation*) refers to the Storage Management Component (SMC) function of excluding drives for an allocation request based on SMC exclusion criteria. *See* the *SMC Configuration and Administration Guide* for more information.

drive loaded— A condition of a transport in which a tape cartridge has been inserted in the transport, and the tape has been threaded to the beginning-of-tape position.

drive panel— A wall of an LSM that contains tape transports. Drive panels for T9840A transports have either 10 or 20 transports per panel; drive panels for

all other transports contain up to four transports per panel.

drive prioritization— (previously referred to as *directed allocation*) refers to the Storage Management Component (SMC) function of influencing selection of a particular drive based on allocation criteria, including volume location. *See* the *SMC Configuration and Administration Guide* for more information.

DRIVEid— A DRIVEid uniquely defines the location of a tape transport by its location within an LSM. A DRIVEid is of the form *AAL:PP:NN* where *AA* is the ACSid, *L* is the LSM number, *PP* is the panel where the drive is located, and *NN* is the drive number within the panel.

DSI— Dynamic System Interchange (JES3).

dual LMU— A hardware/ μ -software feature that provides a redundant LMU capability.

dual LMU HSC— HSC release 1.1.0 or later that automates a switch-over to the standby LMU in a dual LMU configuration.

dump— To write the contents of storage, or of a part of storage, usually from an internal storage to an external medium, for a specific purpose such as to allow other use of storage, as a safeguard against faults or errors, or in connection with debugging.

Dynamic Device Reconfiguration (DDR)— An MVS facility that allows a dismountable volume to be moved and repositioned if necessary, without abnormally terminating the job or repeating the initial program load procedure.

E

ECAP— *See* enhanced CAP.

ECART— (1) Cartridge system tape with a length of 1100 feet that can be used with 4490 and 9490 Cartridge Drives. These tapes are visually identified by a two-tone (black and tan) colored case. (2) A value that can be specified on the MEDIA parameter and that includes only 36-track enhanced capacity cartridge system tapes. (3) *See* Enhanced Capacity Cartridge System Tape.

ECCST— (1) A value that can be specified on the MEDiA parameter and that includes only enhanced capacity cartridge system tapes. (2) An alias of ECART. (3) *See* Enhanced Capacity Cartridge System Tape.

EDL— *See* eligible device list.

EDTGEN— Eligible Device Table Generation. A process used to replace an installation-defined and named representation of the devices that are eligible for allocation.

EETape— *See* Extended Enhanced Tape.

Effective Recording Density— The number of user bytes per unit of length of the recording medium.

eject— The process where the LSM robot places a cartridge in a Cartridge Access Port (CAP) so the operator can remove it from the LSM.

eligible device list— (1) A group of transports that are available to satisfy an allocation request. (2) For JES2 and JES3, a list of devices representing the UNIT parameter specified by way of invoking JCL. The EDL can contain both library and nonlibrary transports depending on the I/O GEN.

enable— The modification of system, control unit, or device action through the change of a software module or a hardware switch (circuit jumper) position.

enhanced CAP (ECAP)— An enhanced CAP contains two forty-cell magazine-style CAPs and a one-cell priority CAP (PCAP). Each forty-cell CAP holds four removable magazines of ten cells each. An LSM access door with an enhanced CAP contains no cell locations for storing cartridges.

See also Cartridge Access Port, standard CAP, priority CAP, WolfCreek CAP, WolfCreek optional CAP, or TimberWolf CAP.

Enhanced Capacity Cartridge System Tape— Cartridge system tape with increased capacity that can be used with 4490 and 9490 Cartridge Drives. These tapes are visually identified by a two-tone (black and tan) housing.

EOF— End-of-File.

EOT— End-of-Tape marker.

EPO— Emergency Power Off.

EREP— Environmental Recording, Editing, Printing.

ERP— *See* error recovery procedures.

error recovery procedures (ERP)— Procedures designed to help isolate and, where possible, to recover from errors in equipment.

esoteric— A user-defined name that groups devices into classes.

ETAPE— (1) A value that can be specified on the MEDiA parameter and that includes only enhanced capacity cartridge system tapes. (2) An alias of ECART. (3) *See* Enhanced Capacity Cartridge System Tape.

Extended Capacity Tape— *See* Enhanced Capacity Cartridge System Tape.

Extended Enhanced Tape (EETape)— A synonym for a ZCART, which is a cartridge that can only be used with a 9490EE drive. An EETape (ZCART) provides greater storage capacity than an ECART.

ExtendedStore Library— One or more LSMs with no Cartridge Drives (CDs) that are attached by pass-thru ports to other LSMs (with CDs) in an ACS. These LSMs provide archive storage for cartridges containing less active data sets. Cartridges can be entered and ejected directly into and out of this LSM though either a standard CAP or an enhanced CAP.

F

FDRPAS™— A product from Innovation Data Processing, Inc. that allows two disk devices to be non-disruptively swapped with each other.

FIFO— First in, first out.

file protected— Pertaining to a tape volume from which data can be read only. Data cannot be written on or erased from the tape.

format— The arrangement or layout of data on a data medium.

frozen panel— A panel to which cartridges cannot be moved. This restriction includes allocating new cartridge locations on a panel as a result of:

- a MOVE command, utility, or PGMI request
- cartridge entry into the ACS
- float, scratch dismount, or scratch redistribution processing.

G

GB— Gigabyte, billion (10^9) bytes.

GDG— Generation Data Group. An MVS data set naming convention. Sequence numbers are appended to the basic data set name to track the generations created for that data set.

GDG Separation— Occurs when a Generation Data Group gets separated because the volumes of different generations reside in different locations. Usually, all generations of a GDG are mounted on a single drive to reduce the number of drives needed for a job.

GTF— Generalized Trace Facility. An MVS facility used to trace software functions and events.

H

HDA— Head/disk assembly.

Helical— A generic value that can be specified on the RECTECH parameter and includes all helical transports.

HOSTid— A HOSTid is the host identifier specified in the HOSTID parameter of the SLILIBRY LIBGEN macro. The HOSTid is the SMF system identifier for both JES2 and JES3.

High Watermark Setup (HWS)— In JES3, a setting specified on the HWSNAME initialization statement that reduces the number of devices reserved for a job. JES3 accomplishes this task by assessing each jobstep to determine the maximum number of devices needed for each device type and reserving those devices.

Host Software Component (HSC)— That portion of the Automated Cartridge System which executes on host systems attached to an automated library. This component acts as the interface between the

operating system and the rest of the automated library.

host system— A data processing system that is used to prepare programs and the operating environments for use on another computer or controller.

HSC— *See* Host Software Component.

HWS— *See* High Watermark Setup.

I

ICRC— *See* Improved Cartridge Recording Capability.

ID— Identifier or identification.

IDAX— Interpreter Dynamic Allocation Exit. This is a subfunction of the DFSMS/MVS subsystem request (SSREQ 55) that the MVS JCL Interpreter and dynamic allocation functions issue for calling DFSMS ACS routines for management of the data set requested.

IDRC— Improved Data Recording Capability.

IML— *See* Initial Microprogram Load.

Improved Cartridge Recording Capability (ICRC)— An improved data recording mode that, when enabled, can increase the effective cartridge data capacity and the effective data rate when invoked.

index— A function performed by the cartridge scratch loader that moves cartridges down the input or output stack one cartridge position. A scratch loader can perform multiple consecutive indexes.

INISH deck— A set of JES3 initialization statements.

Initial Microprogram Load (IML)— A process that activates a machine reset and loads system programs to prepare a computer system for operation. Processors having diagnostic programs activate these programs at IML execution. Devices running μ -software reload the functional μ -software usually from a floppy diskette at IML execution.

Initial Program Load (IPL)— A process that activates a machine reset and loads system programs to prepare a computer system for operation. Processors having diagnostic programs activate these

programs at IPL execution. Devices running μ -software reload the functional μ -software usually from a floppy diskette at IPL execution.

initial value— A value assumed until explicitly changed. It must then be explicitly specified in another command to restore the initial value. An initial value for the HSC is the value in effect when the product is installed.

inline diagnostics— Diagnostic routines that test subsystem components while operating on a time-sharing basis with the functional μ -software in the subsystem component.

input stack— The part of the cartridge loader where cartridges are premounted.

intervention required— Manual action is needed.

IPL— *See* Initial Program Load.

ips— Inches per second.

IVP— Installation Verification Programs. A package of programs that is run by a user after the library is installed in order to verify that the library is functioning properly.

J

JCL— *See* Job Control Language.

Job Control Language— Problem-oriented language designed to express statements in a job that are used to identify the job or describe its requirements to an operating system.

journal— The log associated with journaling. The log (stored in a data set) contains a record of completed work and changes to the control data set since the last backup was created.

journaling— A technique for recovery that involves creating a backup control data set and maintaining a log of all changes (transactions) to that data set.

JST— Job Summary Table (JES3).

K

KB— Kilobyte, thousand (10^3) bytes.

keyword parameter— In command and utility syntax, operands that include keywords and their related values (*See* positional parameter).

Values are concatenated to the keyword either by an equal sign, “KEYWORD=value,” or by parentheses, “KEYWORD(value).” Keyword parameters can be specified in any order. The HSC accepts (tolerates) multiple occurrences of a keyword. The value assigned to a keyword reflects the last occurrence of a keyword within a command.

L

LAN— *See* Local Area Network.

LCU— *See* Library Control Unit.

LED— *See* Light Emitting Diode.

LIBGEN— The process of defining the configuration of the automated library to the host software.

library— An installation of one or more ACSs, attached cartridge drives, volumes placed into the ACSs, host software that controls and manages the ACSs and associated volumes, and the library control data set that describes the state of the ACSs.

library control data set— *See* control data set.

Library Control Unit (LCU)— The portion of the LSM that controls the picking, mounting, dismounting, and replacing of cartridges.

Library Management Unit (LMU)— The portion of the ACS that manages from one to sixteen LSMs and communicates with the host CPU.

Library Storage Module (LSM)— The storage area for cartridges plus the robot necessary to move the cartridges. The term LSM often means the LCU and LSM combined.

Light Emitting Diode (LED)— An electronic device used mainly as an indicator on status panels to show equipment on/off conditions.

Linear Tape Open (LTO)— A technology developed jointly by HP, IBM, and Seagate for new tape storage options. LTO technology is an open format, which means that users have multiple sources of products and media.

LMU— *See* Library Management Unit.

LMUPATH— An HSC control statement contained in the definition data set specified by the LMUPDEF command. An LMUPATH statement allows users to define network LMU attachments.

LMUPDEF— An HSC command used to load the definition data set that contains LMUPATH control statements.

load point— The beginning of the recording area on magnetic tape.

loader— *See* Cartridge Scratch Loader.

Local Area Network (LAN)— A computer network in which devices within the network can access each other for data transmission purposes. The LMU and attached LCUs are connected with a local area network.

logical ejection— The process of removing a volume from the control data set without physically ejecting it from its LSM location.

Logical End Of Tape— A point on the tape where written data normally ends.

LONG— (1) A value that can be specified on the MEDia parameter and that includes only enhanced capacity cartridge system tapes (not to be confused with LONGitud). (2) An alias of ECART. (3) *See* Enhanced Capacity Cartridge System Tape.

LONGitud— (1) A generic value that can be specified on the RECtech parameter and includes all 18-track and 36-track devices. (2) A generic value that can be specified on the MEDia parameter and includes all standard and enhanced capacity cartridge system tapes.

LSM— *See* Library Storage Module.

LSMId— An LSMId (*lsm-id*) is a hexadecimal value that consists of the ACSid and LSM number separated by a colon (i.e., AA:LL, where AA is the ACSid and LL is the LSMId). The LSMId differentiates an LSM from every other LSM in a library.

LSM number— A method used to identify an LSM. An LSM number is the result of defining the SLIACS macro LSM parameter during a LIBGEN.

The first LSM listed in this parameter acquires the LSM number of 00 (hexadecimal), the second LSM listed acquires a hexadecimal number of 01, and so forth, until all LSMs are identified (maximum of 24 or hexadecimal 17).

LTO— *See* Linear Tape Open.

LTOx— A media type designating either an LTO data cartridge with a capacity between 10GB and 400GB or an LTO cleaning cartridge.

M

machine initiated maintenance— *See* ServiceTek.

magnetic recording— A technique of storing data by selectively magnetizing portions of a magnetizable material.

magnetic tape— A tape with a magnetizable surface layer on which data can be stored by magnetic recording.

magnetic tape drive— A mechanism for moving magnetic tape and controlling its movement.

maintenance facility— Hardware contained in the CU and LMU that allows a CSE and the RDC to run diagnostics, retrieve status, and communicate with respective units through their control panels.

management class— A collection of management attributes, assigned by the storage administrator, that are used to control the allocation and use of space by a data set.

manual mode— A relationship between an LSM and all attached hosts. LSMs operating in manual mode have been modified offline and require human assistance to perform cartridge operations.

master LMU— The LMU currently controlling the functional work of the ACS in a dual LMU configuration.

MB— Megabyte, million (10^6) bytes.

MDS— Main Device Scheduler (JES3).

MEDia— The parameter used to specify media type.

This is not to be confused with MEDIA1 or MEDIA2, which are values that can be specified on the MEDia parameter.

MEDIA1— (1) A value that can be specified on the MEDIA parameter and that includes only standard capacity cartridge tapes. (2) An alias of Standard.

MEDIA2— (1) A value that can be specified on the MEDIA parameter and that includes only enhanced capacity cartridge system tapes. (2) An alias of ECART. (3) *See* Enhanced Capacity Cartridge System Tape.

media capacity— The amount of data that can be contained on storage media and expressed in bytes of data.

media mismatch— A condition that occurs when the media value defined in a VOLATTR control statement does not match the media value recorded in the CDS VAR record.

micro-software— *See* μ -software under Symbols.

MIM— Multi-Image Manager. Third-party software by Computer Associates International, Inc.

mixed configurations— Installations containing cartridge drives under ACS control and cartridge drives outside of library control. These configurations cause the Host Software Component to alter allocation to one or the other.

MODEL— The parameter used to specify model number.

modem— Modulator/demodulator. An electronic device that converts computer digital data to analog data for transmission over a telecommunications line (telephone line). At the receiving end, the modem performs the inverse function.

monitor— A device that observes, records, and verifies selected system activities to determine significant departure from expected operation.

MSM— Multiple Sessions Management. Third-party software by Computer Associates International, Inc.

N

Near Continuous Operation (NCO) — Facilities and techniques that allow customers to make dynamic changes to the library that do not disrupt the library hardware and environment. In most cases,

users can perform these procedures without requiring the HSC to be terminated and restarted.

O

OCR— Optical Character Recognition.

operating system (OS)— Software that controls the execution of programs that facilitate overall system operation.

output stack— The part of the cartridge loader that receives and holds processed cartridges.

over-limit cleaning cartridge— A cleaning cartridge that has been used more than the value (limit) specified by either the MNTD MAXclean or VOLATTR MAXclean settings. This kind of cartridge may not be able to adequately clean a tape transport, however, it can be mounted and will attempt to execute the cleaning process. *See also* spent cleaning cartridge.

over-use cleaning cartridge— A cartridge that has a usage (select) count over the MAXclean value (*see* over-limit cleaning cartridge) or that has used up its cleaning surface (*see* spent cleaning cartridge).

P

paired-CAP mode— The two forty-cell CAPs in an enhanced CAP function in paired-CAP mode as a single eighty-cell CAP.

PARMLIB control statements— Parameter library (PARMLIB) control statements allow you to statically specify various operation parameters which take effect at HSC initialization. Identifying your system requirements and then specifying the appropriate control statements permits you to customize the HSC to your data center.

pass-thru port (PTP)— A mechanism that allows a cartridge to be passed from one LSM to another in a multiple LSM ACS.

PCAP— *See* priority CAP.

P/DAS— Peer-to-Peer Remote Copy Dynamic Address Switching. An IBM capability to non-disruptively swap PPRC volumes.

Peer-to-Peer Remote Copy (PPRC)— An IBM capability to mirror disk volumes from one storage subsystem to another.

physical end of tape— A point on the tape beyond which the tape is not permitted to move.

playground— The playground is a reserved area of cells where the robot deposits cartridges that it finds in its hands during LSM initialization. Normal LSM initialization recovery processing moves cartridges from the playground cells to either their home cells or their intended destinations, but under abnormal circumstances cartridges may be left in playground cells.

positional parameter— In command and utility syntax, operands that are identified by their position in the command string rather than by keywords (*See* keyword parameter).

Positional parameters must be entered in the order shown in the syntax diagram.

PowderHorn (9310) LSM— A high-performance LSM featuring a high-speed robot. The PowderHorn has a capacity of up to approximately 6000 cartridges.

PPRC— *See* Peer-to-Peer Remote Copy.

primary CDS— The active control data set. It contains the inventory of all cartridges in the library, the library configuration, information about library hardware and resource ownership across multiple processors, and serves as a vehicle of communication between HSCs running on multiple processors.

priority CAP (PCAP)— A one-cell CAP that is part of an enhanced CAP. A PCAP allows a user to enter or eject a single cartridge that requires immediate action.

See also Cartridge Access Port, standard CAP, enhanced CAP, WolfCreek CAP, WolfCreek optional CAP, or TimberWolf CAP.

Program Temporary Fix (PTF)— A unit of corrective maintenance delivered to a customer to repair a defect in a product, or a means of packaging a Small Programming Enhancement (SPE).

Program Update Tape (PUT)— A tape containing a collection of PTFs. PUTs are shipped to customers

on a regular basis under the conditions of the customer's maintenance license.

PTF— *See* Program Temporary Fix.

PTP— *See* pass-thru port.

PUT— *See* Program Update Tape.

Q

QSAM— *See* Queued Sequential Access Method.

Queued Sequential Access Method (QSAM)— An extended version of the basic sequential access method (BSAM). When this method is used, a queue is formed of input data blocks that are awaiting processing or output data blocks that have been processed and are awaiting transfer to auxiliary storage or to an output device.

R

RACF— *See* Resource Access Control Facility.

RDC— *See* Remote Diagnostics Center.

Recording Density— The number of bits in a single linear track measured per unit of length of the recording medium.

RECtech— The parameter used to specify recording technique.

RedWood— (1) The program name of the Sun StorageTek transport that supports a helical recording technique. (2) *See* SD-3.

Remote Diagnostics Center (RDC)— The Remote Diagnostics Center at Sun StorageTek. RDC operators can access and test Sun StorageTek systems and software, through telecommunications lines, from remote customer installations. Also referred to as the Central Support Remote Center (CSRC).

Resource Access Control Facility (RACF)— Security software controlling access to data sets.

S

SCP— *See* System Control Program.

scratch tape subpool— A defined subset of all scratch tapes. Subpools are composed of one or more

ranges of VOLSERS with similar physical characteristics (type of volume {reel or cartridge}, reel size, length, physical location, etc.). Some installations may also subdivide their scratch pools by other characteristics, such as label type (AL, SL, NSL, NL).

The purpose of subpooling is to make sure that certain data sets are built only within particular ranges of volumes (for whatever reason the user desires). If a volume which does not belong to the required subpool is mounted for a particular data set, it is dismounted and the mount reissued.

SD-3— The model number of the Sun StorageTek transport that supports a helical recording technique.

SDLT— *See* SuperDLT.

SDLTx— A media type designating an SDLT data cartridge with a capacity of either 125GB or 160GB.

secondary CDS— The optional duplicate copy of the primary CDS.

secondary recording— A technique for recovery involving maintaining both a control data set and a copy (secondary) of the control data set.

SEN — *See* Significant Event Notification.

SER— Software Enhancement Request.

ServiceTek (machine initiated maintenance)— A unique feature of the ACS in which an expert system monitors conditions and performance of subsystems and requests operator attention before a potential problem impacts operations. Customers can set maintenance threshold levels.

servo— A device that uses feedback from a sensing element to control mechanical motion.

Shared Tape Allocation Manager (STAM)— Third-party software by Computer Associates International, Inc.

Significant Event Notification (SEN) — An HSC facility that allows an application to request notification of specific HSC and VTCS events.

Silverton— *See* 4490 Cartridge Subsystem.

SL3000 library— *See* StreamLine (SL3000) library.

SL8500 library— *See* Streamline (SL8500) library.

Small Programming Enhancement (SPE)— A supplement to a released program that can affect several products or components.

SMC— Storage Management Component.

SMF— System Management Facility. An MVS facility used to record system actions which affect system functionality.

SMP— System Modification Program.

SMP/E— *See* System Modification Program Extended.

SMS— Storage Management Subsystem.

SPE— *See* Small Programming Enhancement.

special use cartridge— A generic description for a type of cartridge used on T9840A drives. These include:

- T9840A cleaning cartridge
- T9840A microcode load cartridge
- T9840A dump collection cartridge.

When an attempt is made to mount a special use cartridge, LMU error response code 1012 is generated.

The error code is defined as “load failure for special use cartridge.”

If the error code is received for a special use cleaning cartridge, it is either ejected or marked as unusable, and it is retained in the ACS (depending on the MNTD EJctauto setting). The HSC does not mount unusable cartridges.

spent cleaning cartridge— A cleaning cartridge that has exhausted its cleaning material and can no longer be used to clean tape transports. *See also* over-limit cleaning cartridge.

SSD— Solid state disk.

STAM— *See* Shared Tape Allocation Manager.

Standard— (1) A value that can be specified on the MEDia parameter and that includes only standard capacity cartridge tapes. (2) *See* Cartridge System Tape.

standard CAP— A standard CAP has a capacity of twenty-one cartridges (three rows of seven cells each). An LSM access door with a standard CAP contains cell locations for storing cartridges.

See also Cartridge Access Port, enhanced CAP, priority CAP, WolfCreek CAP, WolfCreek optional CAP, or TimberWolf CAP.

standard (4410) LSM— An LSM which provides a storage capacity of up to approximately 6000 cartridges.

standby— The status of a station that has been varied online but is connected to the standby LMU of a dual LMU ACS.

standby CDS— The optional data set that contains only one valid record, the Database Heartbeat (DHB). The DHB contains the names of the control data sets recorded by the HSC and is used to identify the correct primary, secondary, and standby CDS.

standby LMU— The redundant LMU in a dual LMU configuration that is ready to take over in case of a master LMU failure or when the operator issues the SWitch command.

station— A hardware path between the host computer and an LMU over which the HSC and LMU send control information.

STD— (1) A value that can be specified on the MEDia parameter and that includes only standard capacity cartridge tapes. (2) An alias of Standard.

STK1— A generic value that can be specified on the MEDia and RECtech parameters and includes all types of T9840A cartridges and recording techniques.

STK1R— Value that can be specified on the MEDia and RECtech parameters and includes only the specified type of T9840A cartridge or recording technique. STK1R can be abbreviated as R.

STK1U— Value that can be specified on the MEDia parameter and includes the specified types of T9840A, T9840B, and T9840C cleaning cartridges. STK1U can be abbreviated as U.

STK1Y— Value that can be specified on the MEDia parameter and includes only the specified type of

T9840D cleaning cartridge. STK1Y can be abbreviated as Y.

STK2— A generic value that can be specified on the MEDia parameter and includes all types of 9940 cartridges and recording techniques.

STK2P— Value that can be specified on the MEDia and RECtech parameters and includes only the specified type of 9940 cartridge or recording technique. STK2P can be abbreviated as P.

STK2W— Value that can be specified on the MEDia parameter and includes only the specified type of 9940 cleaning cartridge. STK2W can be abbreviated as W.

storage class— A named list of storage attributes that identify performance goals and availability requirements for a data set.

storage group— A collection of storage volumes and attributes defined by the storage administrator.

Storage Management Component (SMC)— Required NCS software component that performs the allocation function for NCS, replacing the functions previously performed by HSC and MVS/CSC. The SMC resides on the MVS host with HSC and/or MVS/CSC, and communicates with these products to determine policies, volume locations, and drive ownership.

StreamLine (SL3000) library— A modular library that can scale from 200 to 4500 cartridges in mainframe, Windows, UNIX, and supercomputer environments. The SL3000 utilizes hot swap components and multiple robots.

StreamLine (SL8500) library— A modular library that can scale from 1,500 to over 200,000 cartridges in mainframe, Windows, UNIX, and supercomputer environments. The SL8500 utilizes hot swap components and multiple robots.

StreamLine CAP— The StreamLine CAP contains 3, 13-cell removable magazines. You can also add an optional CAP that has the same configuration.

SuperDLT— The next generation of DLT (Digital Linear Tape) products, which remains a standard for mid-range operating systems.

switchover— The assumption of master LMU functionality by the standby LMU.

SYNCSORT— Third-party software by Syncsort, Inc.; a sort, merge, copy utility program.

System Control Program— The general term to describe a program which controls access to system resources, and allocates those resources among executing tasks.

system-managed storage— Storage that is managed by the Storage Management Subsystem, which attempts to deliver required services for availability, performance, space, and security applications.

System Modification Program Extended— An IBM-licensed program used to install software and software maintenance.

T

T10000 Tape Drive— A cartridge tape drive that features a 500GB (T10000A) or 1TB (T10000B) cartridge capacity and data transfer rates up to 120MB/sec. In addition, the T10000 offers media reusability for at least two generations and device-based encryption.

tape cartridge— A container holding magnetic tape that can be processed without separating it from the container.

tape drive— A device that is used for moving magnetic tape and includes the mechanisms for writing and reading data to and from the tape.

tape unit— A device that contains tape drives and their associated power supplies and electronics.

TAPEREQ— An SMC control statement that is contained in the definition data set specified by the TREQDEF command. A TAPEREQ statement defines a specific tape request. It is divided into two parts, the input: job name, step name, program name, data set name, expiration date or retention period, and an indication for specific requests or nonspecific (scratch) requests; and the output: media type and recording technique capabilities.

TDMF™— Transparent Data Migration Facility. A product from Softek Storage Solutions Corp. that

allows two disk devices to be non-disruptively swapped with each other.

Timberline— *See* 9490 Cartridge Subsystem.

Timberline EE— *See* 9490EE Cartridge Subsystem.

TimberWolf (9740) LSM— A high performance LSM that provides a storage capacity of up to 494 cartridges. Up to 10 drives (STD, 4490, 9490, 9490EE, T9840A, and SD-3) can be configured. TimberWolf LSMs can only attach to other TimberWolfs.

TimberWolf CAP— The TimberWolf CAP contains either a 10-cell removable magazine or a 14-cell permanent rack. It is not necessary to define a configuration; the HSC receives CAP information directly from the LMU.

See also Cartridge Access Port, standard CAP, enhanced CAP, priority CAP, WolfCreek CAP, or WolfCreek optional CAP.

TP— Tape-to-Print.

transaction— A short series of actions with the control data set. These actions are usually related to a specific function (e.g., Mount, ENter).

transport— An electromechanical device capable of threading tape from a cartridge, moving the tape across a read/write head, and writing data onto or reading data from the tape.

TREQDEF— An SMC command that is used to load the definition data set that contains TAPEREQ control statements.

Tri-Optic label— An external label attached to the spine of a cartridge that is both human and machine readable.

TT— Tape-to-Tape.

U

unit affinity— A request that all cartridges be mounted on a single drive (either for read or write purposes), usually to reduce the number of drives needed for a job.

unit parameter value— A JCL term meaning the value of a JCL UNIT parameter. The value can be a

single address of a drive, an esoteric list, or a generic list.

UNITATTR— An SMC control statement that defines the transport's media type and recording technique capabilities.

utilities— Utility programs. The programs that allow an operator to manage the resources of the library and to monitor overall library performance.

V

VAR— *See* Volume Attribute Record.

VAT— *See* Volume Attribute Table Entry.

Virtual Storage Manager (VSM)— A storage solution that virtualizes volumes and transports in a VTSS buffer in order to improve media and transport use.

Virtual Tape Control System (VTCS)— The primary host code for the Virtual Storage Manager (VSM) solution. This code operates in a separate address space, but communicates closely with HSC.

Virtual Tape Storage Subsystem (VTSS)— The DASD buffer containing virtual volumes (VTVs) and virtual drives (VTDs). The VTSS is a Sun StorageTek RAID 6 hardware device with microcode that enables transport emulation. The RAID device can read and write "tape" data from/to disk, and can read and write the data from/to a real tape drive (RTD).

virtual thumbwheel— An HSC feature that allows read-only access to a volume that is not physically write-protected.

VOLATTR— An HSC control statement that is contained in the definition data set specified by the VOLDEF command. A VOLATTR statement defines to the HSC the media type and recording technique of the specified volumes.

VOLDEF— An HSC command that is used to load the definition data set that contains VOLATTR control statements.

VOLSER— A six-character alphanumeric label used to identify a tape volume.

volume— A data carrier that is mounted or dismounted as a unit. (*See* cartridge).

Volume Attribute Record (VAR)— An HSC internal record that contains the data base-resident information of a cartridge entered into the library.

Volume Attribute Table Entry (VAT)— An HSC internal table that contains entries to the intransit record token and the Volume Attribute Record (VAR). The VAT is used as the communications area for internal service calls.

W

WolfCreek (9360) LSM— A smaller capacity high-performance LSM. WolfCreek LSMs are available in 500, 750, and 1000 cartridge capacities (model numbers 9360-050, 9360-075, and 9360-100, respectively). WolfCreek LSMs can be connected by pass-thru ports to 4410, 9310, or other WolfCreek LSMs.

WolfCreek CAP— The standard WolfCreek CAP contains a 20-cell magazine-style CAP and a priority CAP (PCAP).

See also Cartridge Access Port, standard CAP, enhanced CAP, priority CAP, WolfCreek optional CAP, or TimberWolf CAP.

WolfCreek optional CAP— The WolfCreek optional CAP contains a 30-cell magazine-style CAP which is added to the standard WolfCreek CAP.

See also Cartridge Access Port, standard CAP, enhanced CAP, priority CAP, WolfCreek CAP, or TimberWolf CAP.

Write Tape Mark (WTM)— The operation performed to record a special magnetic mark on tape. The mark identifies a specific location on the tape.

WTM— *See* Write Tape Mark.

WTO— Write-to-Operator.

WTOR— Write-to-Operator with reply.

Z

ZCART— (1) Cartridge system tape with a length of 2200 feet that can be used only with 9490EE Cartridge Drives. (2) A value that can be specified on

the MEDia parameter and that includes only 36-track 9490EE cartridge system tapes. (3) *See also* Extended Enhanced Tape.

Symbols

μ-software— Microprogram. A sequence of microinstructions used to perform preplanned functions and implement machine instructions.

Numerics

18-track— A recording technique that uses 18 tracks on the tape. The tape is written in only the forward motion.

18track— A generic value that can be specified on the RECtech parameter and includes all 18-track transports.

3480— (1) A value that can be specified on the MEDia parameter and that includes only standard capacity cartridge tapes. (2) An alias of Standard.

3480X— The 3480 upgrade that supports ICRC.

3490— The IBM cartridge drive that replaced the 3480X and supports ICRC but not 36-track or long tape. It is equivalent to the IBM 3480X.

3490E— (1) The IBM cartridge drive that replaced the 3490 and supports ICRC, 36-track, and long tape. It reads 18-track but does not write 18-track. (2) A value that can be specified on the MEDia parameter and that includes only enhanced capacity cartridge system tapes. (3) An alias of ECART.

3590— The IBM cartridge drive that supports 128-track recording and holds 10GB of uncompressed data. It has the same form factor as a 3490E.

36-track— A recording technique that uses 36 tracks on the tape. 18 tracks of data are written in the forward motion and then an additional 18 tracks in the backward motion for a total of 36.

36track— A generic value that can be specified on the RECtech parameter and includes all 36-track transports.

36Atrack— A value that can be specified on the RECtech parameter and includes only 4490 (Silverton) 36-track transports.

36Btrack— A value that can be specified on the RECtech parameter and includes only 9490 (Timberline) 36-track transports.

36Ctrack— A value that can be specified on the RECtech parameter and includes only 9490EE (Timberline EE) transports.

4410 LSM— *See* standard LSM.

4480 Cartridge Subsystem— Cartridge tape transports that provide read/write capability for 18-track recording format. The Sun StorageTek 4480 Cartridge Subsystem is equivalent to a 3480 device.

4490 Cartridge Subsystem— Cartridge tape transports that provide read/write capability for 36-track recording format and extended capacity tape. 4490 transports can also read data recorded in 18-track format. The Sun StorageTek 4490 Cartridge Subsystem is equivalent to a 3490E device.

3000 library— *See* StorageTek Library (SL3000).

8500 library— *See* StreamLine (SL8500) library.

9310 LSM— *See* PowderHorn LSM.

9360 LSM— *See* WolfCreek LSM.

9490 Cartridge Subsystem— Cartridge tape transports that provide read/write capability for 36-track recording format and extended capacity tape and provide improved performance over the 4490 Cartridge Subsystem. 9490 transports can also read data recorded in 18-track format. The Sun StorageTek 9490 Cartridge Subsystem offers better performance (faster data transfer rate, faster load/unload) than a 3490E device.

9490EE Cartridge Subsystem— A high-performance tape transport that provides read/write capability for Extended Enhanced tape (EETape) cartridges. It is functionally equivalent to the IBM 3490E device.

9740 LSM— *See* TimberWolf LSM.

T9840A Cartridge Subsystem— A high performance tape transport for enterprise and open systems environments that reads and writes T9840A cartridges. T9840As can be defined in 10-drive and 20-drive panel configurations. The T9840A can perform as a standalone subsystem with a cartridge

scratch loader attached, or it can be attached to a Sun StorageTek ACS.

T9840B—The Sun StorageTek cartridge transport that reads and writes T9840B cartridges.

T9840C— The Sun StorageTek cartridge transport that reads and writes T9840C cartridges.

T9840D— The Sun StorageTek cartridge transport that reads and writes T9840D cartridges

T9940A— The Sun StorageTek capacity-centric cartridge transport capable of reading and writing 60GB T9940A cartridges.

T9940B— The Sun StorageTek capacity-centric cartridge transport capable of reading and writing 200GB T9940B cartridges.

Index

Numerics

- 4480 Cartridge Subsystem, defined 491
- 4490 Cartridge Subsystem, defined 491
- 9490 Cartridge Subsystem, defined 491
- 9490EE Cartridge Subsystem, defined 491
- 9840 Cartridge Subsystem, defined 491

A

- Abend reason codes
 - issued by ASCOMM 421
 - issued by CAP common 409
 - issued by configuration control 412
 - issued by host communications 427
 - issued by initialization/termination 413
 - issued by installation component 414
 - issued by LMU driver 416
 - issued by mount/dismount commands 404
 - issued by operator command 402
 - issued by subsystem allocation modules 410
 - issued by subsystem data base modules 418
 - issued by subsystem services modules 422
 - issued by TMS/User Interface 415
 - issued by utilities 406
 - issued by volume/cell 411
 - issued by WTO server 420
- access method, defined 477
- ACS *See* Automated Cartridge System
- ACSid, defined 477
- allocation, defined 477
- audience for this guide ix
- Automated Cartridge System (ACS), defined 477

B

- BDAM, defined 477
- BSAM, defined 477

C

- CAP Common Messages (0250-0274) 63
- CAPid, defined 478
- cartridge
 - defined 478
 - ECART, defined 480
 - over-limit cleaning cartridge, defined 485
 - over-use cleaning cartridge, defined 485
 - special use cartridge, defined 487
 - spent cleaning cartridge, defined 487
 - ZCART, defined 490
- Cartridge Access Port (CAP)
 - defined 478
 - standard, defined 488
 - TimberWolf, defined 489
 - WolfCreek optional, defined 490
 - WolfCreek, defined 490
- Cartridge Drive (CD), defined 478
- Cartridge Scratch Loader (CSL), defined 478
- CD *See* Cartridge Drive
- CDS *See* control data set
- Configuration Control Messages (0450-0499) 93
- connected mode, defined 478
- contacting Sun Microsystems StorageTek Support xiii
- control data set (CDS)
 - allocation map, defined 478
 - data blocks, defined 478
 - defined 478
 - directory, defined 478
 - pointer blocks, defined 478
 - recovery area, defined 479
 - subfile, defined 479
- Control Unit (CU), defined 479
- CST, defined 479
- CU *See* Control Unit
- Customer Resource Center (CRC) xii
- customer support xiii
- customer-initiated maintenance (CIM) xiii

D

Database Heartbeat (DHB) record, defined 479
descriptor codes, message 451
device group, defined 480
device number, defined 480
DFP (Data Facility Product), defined 480
DFSMS
 ACS routine, defined 480
 defined 480
directed allocation, defined 480
disconnected mode, defined 480
DOMed, defined 480
drive exclusion, defined 480
drive loaded, defined 480
drive panel, defined 480
drive prioritization, defined 480
DRIVEid, defined 480
dual LMU, defined 480
dump, defined 480
Dynamic Device Reconfiguration (DDR), defined 480

E

ECART
 defined 480
ECCST, defined 481
eject, defined 481
eligible device list, defined 481
Enhanced CAP (ECAP), defined 481
Enhanced Capacity Cartridge System Tape (ECCST), defined 481
esoteric, defined 481
ETAPE, defined 481
Extended Enhanced Tape (EETape), defined 481
ExtendedStore, Library, defined 481

F

FDRPAS, defined 481

G

Generation Data Groups (GDG) separation, defined 482
guide
 audience definition ix
 organization x

H

Helical, defined 482
help, technical support xii
Host Software Component (HSC)
 defined 482
host system, defined 482
HOSTid, defined 482

I

Improved Cartridge Recording Capability (ICRC), defined 482
Index, defined 482
INISH deck, defined 482
Initial Microprogram Load (IML), defined 482
Initial Program Load (IPL), defined 482
initial value, defined 483
input stack, defined 483
Installation Messages
 0550-0599 102
Installation Verification Programs (IVP), defined 483

J

Job Control Language (JCL)
 defined 483
Journaling Messages
 0760-0799 147
journaling, defined 483

K

keyword parameter, defined 483

L

LAN, defined 483
LCU *See* Library Control Unit
LIBGEN
 defined 483
library
 defined 483
Library Control Unit (LCU), defined 483
Library Management Unit (LMU)
 defined 483
 standby, defined 488
Library Storage Module (LSM)
 defined 483
 number, defined 484
 standard (4410), defined 488

TimberWolf (9740), defined 489
WolfCreek (9360), defined 490
LMU *See* Library Management Unit
LMU Driver Messages
0650-0699 116
LMUPATH control statement
defined 484
LMUPDEF command and control statement
defined 484
logical ejection, defined 484
LONGItud, defined 484
LSM *See* Library Storage Module
LSMid, defined 484

M

manual mode
defined 484
master LMU
defined 484
media capacity, defined 485
media mismatch, defined 485
MEDia, defined 484
Messages
changes in HSC 4.0 473
description 2
descriptions 5
descriptor codes 451
formatting 1
listings 5
route codes 451
syntax 1
variable definitions 3
MODEl, defined 485

N

Near Continuous Operation (NCO)
defined 485

O

organization of this guide x
output stack, defined 485
over-limit cleaning cartridge
defined 485
over-use cleaning cartridge
defined 485

P

P/DAS, defined 485
Paired-CAP mode, defined 485
partners web site, SUN xii
pass-thru port (PTP), defined 485
Peer-to-Peer Remote Copy (PPRC), defined 486
playground, defined 486
positional parameter, defined 486
PowderHorn (9310) LSM, defined 486
primary CDS
defined 486
priority CAP (PCAP), defined 486

Q

Queued Sequential Access Method (QSAM), defined 486

R

Recovery Messages
0850-0899 151
RECtech, defined 486
Remote Diagnostics Center (RDC), defined 486
return codes, HSC
address space communication 444
address space communications 444
audit utility 433
CAP processing 433
configuration 437
data base server 442
host communications services 449
initialization/termination 430
LMU server 439
mount/dismount 430
operator commands 430
recovery 445
service component 446
utilities 431
volume/cell (no parameter list) 435
volume/cell (with parameter list) 436
route codes, message 451

S

secondary CDS
defined 487
ServiceTek, defined 487
Significant Event Notification (SEN)
defined 487
special use cartridge, defined 487

spent cleaning cartridge
 defined 487
standard (4410) LSM, defined 488
standard CAP, defined 488
standby CDS
 defined 488
standby LMU
 defined 488
standby, defined 488
station, defined 488
storage
 class, defined 488
 group, defined 488
support, technical xii
symbols, μ -software, defined 491

T

T10000 tape drive, defined 489
T9840B Cartridge Subsystem, defined 492
T9840C Cartridge Subsystem, defined 492
T9940A Cartridge Subsystem, defined 492
T9940B Cartridge Subsystem, defined 492
technical support xii
TimberWolf (9740) LSM, defined 489
TimberWolf CAP, defined 489
transport, defined 489
Tri-Optic label, defined 489
troubleshooting xii

U

unit affinity, defined 489

V

Virtual Thumbwheel, defined 490
VOLSER
 defined 490
volume, defined 490
volume/cell control messages (0400-0449) 92

W

web site, SUN xii
WolfCreek (9360) LSM, defined 490
WolfCreek CAP, defined 490
WolfCreek optional CAP, defined 490

worldwide offices, SUN xiv

Z

ZCART, defined 490



Sun Microsystems, Inc. 4150 Network Circle, Santa Clara, CA 95054 USA Phone 1-650-960-1300 or 1-800-555-9SUN Web sun.com



ARGENTINA: 5411-4317-5636 • AUSTRALIA: 1-800-550-786 • AUSTRIA: 43-1-601-26-0 • BALKANS: 301-6188-111 • BELGIUM: 32-2-704 89 83 • BRAZIL: 55-11-51872100 • BRUNEI: 65-216-8333 • CANADA: 1-800-422-8020 (GENERAL); 416-964-2001 (LEARNING MANAGEMENT SYSTEM SALES, TORONTO) • CHILE: 562-372-4500 • COLOMBIA: 571-629-2323
CZECH REPUBLIC: 420-2-33009311 • DENMARK: 45-4556-5040 • EGYPT: 00-202-570-9442 • FINLAND: 358-9-525-551 • FRANCE: 33-1-41-33-17-17 • GERMANY: 49-89-460-08-2788 • GREECE: 30-01-6188101 • HONG KONG: 852-2877-7077 • HUNGARY: 361-202-4415 • INDIA: 91-80-229-8989 • INDONESIA: 65-216-8333 • IRELAND: 353-1-668-4377
ISRAEL: 972-9-9710500 • ITALY: 39-02-9259511 • JAPAN: 81-3-5779-1820 • KOREA: 82-2-3453-6602 • MALAYSIA: 603-2116-1887 • MIDDLE EAST: 00-9714-3366333 • MEXICO: 525-261-0344 • NETHERLANDS: 31-33-4515200 • NEW ZEALAND: 0800-786-338 • NORTH WEST AFRICA: 00-9714-3366333 • NORWAY: FROM NORWAY: 47-22023950, TO NORWAY: 47-23369650 • PAKISTAN: 00-9714-3366333 • PEOPLE'S REPUBLIC OF CHINA: 8610-6803-5588 • PHILIPPINES: 632-885-7867 • POLAND: 48-22-8747848 • PORTUGAL: 351-21-413-4000 • RUSSIA: 7-095-935-8411 • SAUDI ARABIA: 00-9714-3366333 • SINGAPORE: 65-216-8300 • SOUTH AFRICA: 27-11-256-6300 • SPAIN: 34-902-210-412 • SRI LANKA: 65-2168333 • SWEDEN: 46-8-631-22-00 • SWITZERLAND: 41-1-908-90-50 (GERMAN) 41-22-999-0444 (FRENCH) • TAIWAN: 886-2-25185735 • THAILAND: 662-344-6855 • TURKEY: 90-212-335-22-00 • UNITED KINGDOM: 44-1276-416-520 • UNITED STATES: 1-800-422-8020 • VENEZUELA: 582-905-3800 • VIETNAM: 65-216-8333 • WORLDWIDE HEADQUARTERS: 1-650-960-1300

SUN™ THE NETWORK IS THE COMPUTER ©2006 Sun Microsystems, Inc. All rights reserved. Sun, Sun Microsystems, and the Sun logo are trademarks or registered trademarks of Sun Microsystems, Inc. in the United States and other countries.