

Sun Flash Accelerator F40 PCIe Card Product Notes

ORACLE®

Part No: E29742-12
March 2017

Part No: E29742-12

Copyright © 2012, 2017, Oracle and/or its affiliates. All rights reserved.

This software and related documentation are provided under a license agreement containing restrictions on use and disclosure and are protected by intellectual property laws. Except as expressly permitted in your license agreement or allowed by law, you may not use, copy, reproduce, translate, broadcast, modify, license, transmit, distribute, exhibit, perform, publish, or display any part, in any form, or by any means. Reverse engineering, disassembly, or decompilation of this software, unless required by law for interoperability, is prohibited.

The information contained herein is subject to change without notice and is not warranted to be error-free. If you find any errors, please report them to us in writing.

If this is software or related documentation that is delivered to the U.S. Government or anyone licensing it on behalf of the U.S. Government, then the following notice is applicable:

U.S. GOVERNMENT END USERS. Oracle programs, including any operating system, integrated software, any programs installed on the hardware, and/or documentation, delivered to U.S. Government end users are "commercial computer software" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, use, duplication, disclosure, modification, and adaptation of the programs, including any operating system, integrated software, any programs installed on the hardware, and/or documentation, shall be subject to license terms and license restrictions applicable to the programs. No other rights are granted to the U.S. Government.

This software or hardware is developed for general use in a variety of information management applications. It is not developed or intended for use in any inherently dangerous applications, including applications that may create a risk of personal injury. If you use this software or hardware in dangerous applications, then you shall be responsible to take all appropriate fail-safe, backup, redundancy, and other measures to ensure its safe use. Oracle Corporation and its affiliates disclaim any liability for any damages caused by use of this software or hardware in dangerous applications.

Oracle and Java are registered trademarks of Oracle and/or its affiliates. Other names may be trademarks of their respective owners.

Intel and Intel Xeon are trademarks or registered trademarks of Intel Corporation. All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. AMD, Opteron, the AMD logo, and the AMD Opteron logo are trademarks or registered trademarks of Advanced Micro Devices. UNIX is a registered trademark of The Open Group.

This software or hardware and documentation may provide access to or information about content, products, and services from third parties. Oracle Corporation and its affiliates are not responsible for and expressly disclaim all warranties of any kind with respect to third-party content, products, and services unless otherwise set forth in an applicable agreement between you and Oracle. Oracle Corporation and its affiliates will not be responsible for any loss, costs, or damages incurred due to your access to or use of third-party content, products, or services, except as set forth in an applicable agreement between you and Oracle.

Documentation Accessibility

For information about Oracle's commitment to accessibility, visit the Oracle Accessibility Program website at <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=docacc>.

Access to Oracle Support

Oracle customers that have purchased support have access to electronic support through My Oracle Support. For information, visit <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=info> or visit <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=trs> if you are hearing impaired.

Référence: E29742-12

Copyright © 2012, 2017, Oracle et/ou ses affiliés. Tous droits réservés.

Ce logiciel et la documentation qui l'accompagne sont protégés par les lois sur la propriété intellectuelle. Ils sont concédés sous licence et soumis à des restrictions d'utilisation et de divulgation. Sauf stipulation expresse de votre contrat de licence ou de la loi, vous ne pouvez pas copier, reproduire, traduire, diffuser, modifier, accorder de licence, transmettre, distribuer, exposer, exécuter, publier ou afficher le logiciel, même partiellement, sous quelque forme et par quelque procédé que ce soit. Par ailleurs, il est interdit de procéder à toute ingénierie inverse du logiciel, de le désassembler ou de le décompiler, excepté à des fins d'interopérabilité avec des logiciels tiers ou tel que prescrit par la loi.

Les informations fournies dans ce document sont susceptibles de modification sans préavis. Par ailleurs, Oracle Corporation ne garantit pas qu'elles soient exemptes d'erreurs et vous invite, le cas échéant, à lui en faire part par écrit.

Si ce logiciel, ou la documentation qui l'accompagne, est livré sous licence au Gouvernement des Etats-Unis, ou à quiconque qui aurait souscrit la licence de ce logiciel pour le compte du Gouvernement des Etats-Unis, la notice suivante s'applique:

U.S. GOVERNMENT END USERS. Oracle programs, including any operating system, integrated software, any programs installed on the hardware, and/or documentation, delivered to U.S. Government end users are "commercial computer software" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, use, duplication, disclosure, modification, and adaptation of the programs, including any operating system, integrated software, any programs installed on the hardware, and/or documentation, shall be subject to license terms and license restrictions applicable to the programs. No other rights are granted to the U.S. Government.

Ce logiciel ou matériel a été développé pour un usage général dans le cadre d'applications de gestion des informations. Ce logiciel ou matériel n'est pas conçu ni n'est destiné à être utilisé dans des applications à risque, notamment dans des applications pouvant causer des dommages corporels. Si vous utilisez ce logiciel ou matériel dans le cadre d'applications dangereuses, il est de votre responsabilité de prendre toutes les mesures de secours, de sauvegarde, de redondance et autres mesures nécessaires à son utilisation dans des conditions optimales de sécurité. Oracle Corporation et ses affiliés déclinent toute responsabilité quant aux dommages causés par l'utilisation de ce logiciel ou matériel pour ce type d'applications.

Oracle et Java sont des marques déposées d'Oracle Corporation et/ou de ses affiliés. Tout autre nom mentionné peut correspondre à des marques appartenant à d'autres propriétaires qu'Oracle.

Intel et Intel Xeon sont des marques ou des marques déposées d'Intel Corporation. Toutes les marques SPARC sont utilisées sous licence et sont des marques ou des marques déposées de SPARC International, Inc. AMD, Opteron, le logo AMD et le logo AMD Opteron sont des marques ou des marques déposées d'Advanced Micro Devices. UNIX est une marque déposée d'The Open Group.

Ce logiciel ou matériel et la documentation qui l'accompagne peuvent fournir des informations ou des liens donnant accès à des contenus, des produits et des services émanant de tiers. Oracle Corporation et ses affiliés déclinent toute responsabilité ou garantie expresse quant aux contenus, produits ou services émanant de tiers, sauf mention contraire stipulée dans un contrat entre vous et Oracle. En aucun cas, Oracle Corporation et ses affiliés ne sauraient être tenus pour responsables des pertes subies, des coûts occasionnés ou des dommages causés par l'accès à des contenus, produits ou services tiers, ou à leur utilisation, sauf mention contraire stipulée dans un contrat entre vous et Oracle.

Accessibilité de la documentation

Pour plus d'informations sur l'engagement d'Oracle pour l'accessibilité à la documentation, visitez le site Web Oracle Accessibility Program, à l'adresse <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=docacc>.

Accès aux services de support Oracle

Les clients Oracle qui ont souscrit un contrat de support ont accès au support électronique via My Oracle Support. Pour plus d'informations, visitez le site <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=info> ou le site <http://www.oracle.com/pls/topic/lookup?ctx=acc&id=trs> si vous êtes malentendant.

Contents

Using This Documentation	7
Sun Flash Accelerator F40 PCIe Card Product Notes	9
Supported Hardware and Software	9
Supported Servers and Operating Systems	9
Minimum Supported Card Firmware Version	11
Required Host Software	13
Keeping Drivers and Firmware Up To Date	13
Card Implementation Considerations	14
Configuring Sun Flash Accelerator F40 PCIe Card For Optimum Performance	14
Sun Server X3-2L Configuration	15
SPARC Server T5-4 and T5-8 Configuration	15
SPARC M5-32 Server Configuration	16
Card Volume Management	16
Accessing DDCLI Software Updates and Firmware Downloads	17
Known Issues	18
▼ FATAL resetting due to F80 and F40 <code>fault_state(0x0d04)</code> (22727539)	18
▼ Cards failed with "poor performance" at the same time, due to background recycler (22843161 and 22848220)	19
▼ Card may fail at initial power on after no power on for long period (19140306)	19
▼ Card may not show up on power cycle (18160181)	19
▼ Card may not initialize at power cycle (17773639)	19
▼ SUNBT7181173 variable (up to 25% IOPS) reads throughput (11%) performance (15801572)	20
▼ SUNBT7185967 DFF is reported missing during power cycle (15805379)	20

- ▼ SUNBT7178453 Panic Logs found on Sun Flash Accelerator F40 PCIe Card (15799303) 20
- ▼ Sun Flash Accelerator F40 PCIe Card DDCLI reports overall health as GOOD even if SSD temperature is over 74C (15780582) 21

Using This Documentation

- **Overview** – These product notes include information about supported software and firmware, and important operating guidelines for Sun Flash Accelerator F40 PCIe Cards.
- **Audience** – Technicians, system administrators, authorized service providers, and users.
- **Required knowledge** – Experience with servers and advanced understanding of server storage systems.

Product Documentation Library

Documentation and resources for this product and related products are available at <http://www.oracle.com/pls/topic/lookup?ctx=sunflashf40>.

Feedback

Provide feedback about this documentation at <http://www.oracle.com/goto/docfeedback>.

Sun Flash Accelerator F40 PCIe Card Product Notes

This document contains late-breaking information about the Sun Flash Accelerator F40 PCIe Card from Oracle. Read this document before reading other Sun Flash Accelerator F40 PCIe Card documentation.

For specific installation instructions, see your system installation guide. For late-breaking information about the installation and use of the Sun Flash Accelerator F40 PCIe Card on your server, see the most recent version of the server product notes.

The following sections are included in this document:

- Supported Hardware and Software
- Card Implementation Considerations
- Known Issues

Supported Hardware and Software

The following sections describe the servers, operating systems, software and firmware supported for the Sun Flash Accelerator F40 PCIe Card.

- Supported Servers and Operating Systems
- Minimum Supported Card Firmware Version
- Required Host Software
- Keeping Drivers and Firmware Up To Date

Supported Servers and Operating Systems

This section describes servers that support the Sun Flash Accelerator F40 PCIe Card. For detailed information about using this card with your server, see the product notes for your server, available at:

<https://docs.oracle.com>

The following servers are supported for the Sun Flash Accelerator F40 PCIe Card:

SPARC Servers	Number of Cards	Slots Supported and Preferred Order for Installing F40 Card	Supported Operating Systems
SPARC T4-1	1 to 2	5, 3	<ul style="list-style-type: none"> ■ Oracle Solaris 11.1 ■ Oracle Solaris 10 8/11 OS with required patchsets ■ Oracle Solaris 10 9/10 OS with the Solaris 10 8/11 SPARC Bundle and required patchsets
SPARC T4-2	1 to 4	9, 8, 7, 0 (Slot 6 if Slot 0 is unavailable)	<ul style="list-style-type: none"> ■ Oracle Solaris 11.1 ■ Oracle Solaris 10 8/11 OS with required patchsets ■ Oracle Solaris 10 9/10 OS with the Solaris 10 8/11 SPARC Bundle and required patchsets
SPARC T5-2	1 to 4	1, 8, 2, 7, 3, 6, 4, 5	<ul style="list-style-type: none"> ■ Oracle Solaris 11.1 SRU 4 ■ Oracle Solaris 10 1/13 OS with required patchsets
SPARC T5-4	1 to 8	1, 3, 5, 7, 9, 11, 13, 15	<ul style="list-style-type: none"> ■ Oracle Solaris 11.1 ■ Oracle Solaris 10 1/13 OS with required patchsets
See “ SPARC Server T5-4 and T5-8 Configuration ” on page 15			
SPARC T5-8	1 to 8	1, 3, 5, 7, 9, 11, 13, 15	<ul style="list-style-type: none"> ■ Oracle Solaris 11.1 ■ Oracle Solaris 10 1/13 OS with required patchsets
See “ SPARC Server T5-4 and T5-8 Configuration ” on page 15			
SPARC M5-32	1 to 60	Slot 8 in each I/O unit (IOU) is not supported.	<ul style="list-style-type: none"> ■ Oracle Solaris 11.1 SRU 4 ■ Oracle Solaris 10 1/13 OS with required patchsets
See “ SPARC M5-32 Server Configuration ” on page 16			
Fujitsu M10-1	1 to 3	2, 0, 1	<ul style="list-style-type: none"> ■ Oracle Solaris 11.1 SRU 1.4 ■ Oracle Solaris 10 1/13 OS with required patchsets
Fujitsu M10-4	1 to 11	10, 6, 2, 8, 4, 9, 5, 1, 7, 3, 0	<ul style="list-style-type: none"> ■ Oracle Solaris 11.1 SRU 1.4 ■ Oracle Solaris 10 1/13 OS with required patchsets
Fujitsu M10-4S	1 to 8	6, 2, 4, 5, 1, 7, 3, 0	<ul style="list-style-type: none"> ■ Oracle Solaris 11.1 SRU 1.4 ■ Oracle Solaris 10 1/13 OS with required patchsets

Note - Direct I/O support (DIO) is available for SPARC T4-1 and T4-2 servers.

x86 Servers	Number of Cards	Slots Supported for Installing F40 Card	Supported Operating Systems
Sun Server X3-2L See “ Sun Server X3-2L Configuration ” on page 15.	1 to 4	1, 2, 4, 5	<ul style="list-style-type: none"> ■ Oracle Solaris 11.1 ■ Oracle Solaris 10 8/11 ■ Oracle Linux 5.8, based on UEK2 (Unbreakable Linux Kernel Release 2) ■ Oracle Linux 6.2, 6.3, based on UEK2 (Unbreakable Linux Kernel Release 2)

Other servers and processors may be added to this list in the future, if they qualify. Check your server product notes for confirmation that your server has subsequently been qualified.



Caution - Any unsupported configuration causes the host to power off as soon as it is powered on. A fault is generated on the service processor when an unsupported configuration is detected. The fault clears after the unsupported configuration is fixed and the host is powered on.

Note - For up-to-date information on supported servers, operating systems and required patchsets, refer to the product notes for the servers.

Minimum Supported Card Firmware Version

Use the DDCLI utility to check and update firmware.

Firmware	Version	Patch
F40 Firmware Package (recommended)	13.05.10.01	SW2.0 25292105
F40 Firmware Package	09.05.40.00	SW1.2 19933424
F40 Firmware Package	08.05.01.01	SW1.1 16005846
F40 Firmware Package (minimum)	08.05.01.00	SW1.0 14383129

Summary of Changes in Firmware 13.05.10.01 Release

The following improvements and changes are included in SW2.0 Phase 13.05.10.01 release of the Sun Flash Accelerator F40 PCIe Card:

- Permanently disabled SMART caching, removed the checksum error reported by smartctl.

- DDCLI updated to 112.05.25.00 for F40 Management Command line utility (OS specific) for management and monitoring of the F40 PCIe card. Utility update for both Linux and Solaris (compatible with F80)
- Bug 22727539 - FATAL resetting due to F80 and F40 fault_state(0x0d04)
- Bugs 22843161 and 22848220 - Cards failed with "poor performance" at the same time, due to background recycler.

If you install the Sun Flash Accelerator F40 PCIe Card as an x-option on a server, you must update the firmware from 08.05.01.01 to 13.05.10.01, or a subsequent release if available.

Summary of Changes in Firmware 09.05.40.00 Release

The following improvements and changes are included in firmware Phase 09.05.40.00 release SW1.2 (Released November 2014) of the Sun Flash Accelerator F40 PCIe Card:

- Bug 19140306 – F40 card may fail at initial power on after no power on for long period.
- Bug 18160181 – F40 card may not show up on powercycle.
- Bug 17773639 - Sun Flash Accelerator F40 flash module may not initialize at powercycle.
- DDCLI updated to 11.00.12.00, Utility update for both Linux and Solaris (compatible with F80)

If you install the Sun Flash Accelerator F40 PCIe Card as an x-option on a server, you must update the firmware from 09.05.40.00 to 13.05.10.01, or a subsequent release if available.

Summary of Changes in Firmware 08.05.01.01 Release

The following improvements and changes are included in firmware Phase 08.05.01.01 release SW1.1 (Released December 2012) of the Sun Flash Accelerator F40 PCIe Card:

- Bug 15801572 - SUNBT7181173 variable (up to 25% IOPS) read throughput (11%) performance.
- Bug 15805379 - SUNBT7185967 DFF is reported missing during power cycle.
- Bug 15799303 - SUNBT7178453 Panic Logs found on Sun Flash Accelerator F40 PCIe Card.
- DDCLI updated to 107.00.00.05 Utility for both Linux and Solaris-SPARC provided.
- Bug 15780582 - DDCLI reports overall health as GOOD even if SSD temperature is over 74C.

If you install the Sun Flash Accelerator F40 PCIe Card as an x-option on a server, you must update the firmware from 08.05.01.00 to 13.05.10.01, or a subsequent release if available.

Required Host Software

The Sun Flash Accelerator F40 PCIe Card runs with the minimum required host software listed below:

SPARC Driver	Minimum Required Host Firmware Version With Patches	Recommended System Software Version (Patch No.)
SPARC T4-1	8.2.1.b	148822-03
SPARC T4-2	8.2.1.b	148823-03
SPARC T5-2	9.0.0.h	16588974
SPARC T5-4	9.0.2.g	17019069
SPARC T5-8	9.0.2.g	17019069
SPARC M5-32	9.0.1.b	1540816.1
Fujitsu M10-1	XCP version 2041	Patch 16687261: FUJITSU M10-1 XCP2041 FIRMWARE
Fujitsu M10-4	XCP version 2041	Patch 16687263: FUJITSU M10-4 XCP2041 FIRMWARE
Fujitsu M10-4S	XCP version 2041	Patch 16687267: FUJITSU M10-4S XCP2041 FIRMWARE

x86 Driver	Minimum Required Host Firmware Version With Patches	Recommended System Software Version (Patch No.)
Sun Server X3-2L	Software 1.2.0	<ul style="list-style-type: none"> ■ X3-2L SW 1.2.0 Firmware Pack - Patch number 16039828 ■ X3-2L SW 1.2.0 OSA Updater - Patch number 16039823

Note - For up-to date information on supported servers, drivers, host software, firmware and required patchsets, refer to the product notes for the servers.

Keeping Drivers and Firmware Up To Date

Use the DDCLI utility to check and update card firmware. For information on updating drivers and firmware for Sun Flash Accelerator F40 PCIe Card, refer to the *Sun Flash Accelerator F40 PCIe Card User's Guide* and [“Accessing DDCLI Software Updates and Firmware Downloads” on page 17](#).

Card Implementation Considerations

The following sections contain important information for configuring Sun Flash Accelerator F40 PCIe Card.

- “Configuring Sun Flash Accelerator F40 PCIe Card For Optimum Performance” on page 14
- “Sun Server X3-2L Configuration” on page 15
- “SPARC Server T5-4 and T5-8 Configuration” on page 15
- “SPARC M5-32 Server Configuration” on page 16
- “Card Volume Management” on page 16
- “Accessing DDCLI Software Updates and Firmware Downloads” on page 17

Configuring Sun Flash Accelerator F40 PCIe Card For Optimum Performance

Sun Flash Accelerator F40 PCIe Cards must be configured for optimum flash card performance. You should take the following into account when configuring your server system for installed Sun Flash Accelerator F40 PCIe Cards:

- Follow performance guidelines for implementing Sun Flash Accelerator F40 PCIe Card 8k block tuning. The Sun Flash Accelerator F40 PCIe Card is designed to provide best performance for data transfers that are multiples of 8k size, and using addresses that are 8k aligned. Partitions should be aligned to start on 8k boundaries.

Oracle Solaris OS automatically ensures 8k alignment when the default SMI label type is selected. If a label of type EFI is desired, care must be taken to specify and ensure 8k alignment: the default start sector of 34 for EFI labels is not an 8k aligned value. Use the partition subcommand of the Solaris format command to change the start sector to 48, or any other 8k aligned value. Note that there are 512B per sector. The ZFS file system automatically aligns partitions to start on 8k boundaries when a full disk is allocated to ZFS (recommended). If you allocate individual EFI partitions to a ZFS pool, ensure the partition is 8k-aligned as discussed above. Refer to:

- ZFS Tuning Guide: http://docs.oracle.com/cd/E26502_01/html/E29022/chapterzfs-flash.html
- *Card Optimization Guidelines* in *Sun Flash Accelerator F40 PCIe Card Users Guide*
- Follow cache flush recommendations for servers with ZFS and installed Sun Flash Accelerator F40 PCIe Cards. Refer to the ZFS Tuning Guide for cache flush recommendations. See http://docs.oracle.com/cd/E26502_01/html/E29022/chapterzfs-flash.html.

- Do not disable power management in BIOS menus, to avoid a reduction in card performance if the server is reset.
- When configuring Power Safe mode, CPU deep cstates should be disabled in/etc/system files.
- Install the latest software and firmware for servers with installed Sun Flash Accelerator F40 PCIe Cards. See [“Keeping Drivers and Firmware Up To Date” on page 13](#).

Sun Server X3-2L Configuration

Sun Flash Accelerator F40 PCIe Card support ing Sun Server X3-2L is restricted to the following Intel Xeon processors:

- 7100604 - Intel® Xeon® E5-2609 4-core 2.4 GHz processor (for factory installation)
- 7100602 - Intel® Xeon® E5-2640 6-core 2.5 GHz processor (for factory installation)
- 7100601 - Intel® Xeon® E5-2660 8-core 2.2 GHz processor (for factory installation)

Refer to the Sun Server X3-2L documentation for more information on card installation at: <http://www.oracle.com/pls/topic/lookup?ctx=SunServerX3-2L>.

SPARC Server T5-4 and T5-8 Configuration

SPARC Server T5-4 and SPARC Server T5-8 require a doublewide PCIe hot plug carrier extension for each installed Sun Flash Accelerator F40 PCIe Card to facilitate air flow. Doublewide carriers do not allow the use of one adjacent PCIe slot. PCIe hot plug carrier extensions (Mkt PN 710710) are installed in odd numbered PCIe slots. The Sun Flash Accelerator F40 PCIe Card cannot be installed in slot 16.

- Refer to the SPARC Server T5-4 documentation for more information on card installation at: <http://www.oracle.com/goto/T5-4/docs>.
- Refer to the SPARC Server T5-8 documentation for more information on card installation at: <http://www.oracle.com/goto/T5-8/docs>.

The following figure shows an example of doublewide PCIe hot plug carrier extensions that populate two PCIe slots for each Sun Flash Accelerator F40 PCIe Card.



SPARC M5-32 Server Configuration

Fifteen Sun Flash Accelerator F40 PCIe Cards are supported per SPARC M5-32 server physical domain. A SPARC M5-32 server can include one to four physical domains. For example, a server with two physical domains supports 30 Sun Flash Accelerator F40 PCIe cards, fifteen in each physical domain. A server with four physical domains supports 60 cards.

The Sun Flash Accelerator F40 PCIe card requires increased cooling to remove the heat generated by the card. By the internal design of the I/O Unit (IOU), PCIe slot 8 receives less airflow than the other slots. Do not install a Sun Flash Accelerator F40 PCIe card into PCIe slot 8. Hot-plug installation of the Sun Flash Accelerator F40 PCIe card is not supported. For IOU slot priority, additional configuration options, and PCIe card installation instructions, refer to the *SPARC M5-32 Server Service Manual* at <http://www.oracle.com/goto/M5-32/docs>.

Card Volume Management

Use the Automatic Storage Management (ASM) volume manager or other volume manager to concatenate multiple flash memory module domains. For example, a volume manager can be used to concatenate four 200 GB domains into a single 800 GB volume. A volume manager can also present multiple SSD cards as one larger volume.

Refer to the documentation for more information at: http://docs.oracle.com/cd/B28359_01/server.111/b31107/asmcon.htm#OSTMG036

Accessing DDCLI Software Updates and Firmware Downloads

Sun product patches, updates and firmware are available on My Oracle Support at <https://support.oracle.com>. from the Patches and Updates tab. Information on accessing and using My Oracle Support can be found at the *My Oracle Support Welcome Center for Oracle Sun Customers and Partners*.

▼ Downloading the Card Software Package

To find the card software package that includes the DDCLI utility, access My Oracle Support and download the latest software package for the Sun Flash Accelerator F40 PCIe Card.

1. **Sign in to MyOracle Support at <https://support.oracle.com>.**
2. **Click the "Patches & Updates" tab.**
3. **In the "Patch Search" box on the right side, select "Product or Family (Advanced Search)"**
4. **Enter a partial product name for "Product is".**
A list of matches displays.
5. **Select the product of interest.**
Select one or more "releases" in the "Release is" drop down list.
Close the pop-up window.
6. **Click Search.**
A list of product downloads (listed as patches) displays.
7. **Select the download of interest.**
The Download Information Page displays.

If, on the Download Information Page, you get the message "You do not have permissions to download this Patch...", see *How Patches and Updates Entitlement Works* at <https://support.oracle.com> to help you determine the reason.

Known Issues

The following sections describe known issues for the Sun Flash Accelerator F40 PCIe Card:

SW 2.0:

- Permanently disabled SMART caching, removed the checksum error reported by smartctl.
- Bug 22727539 - FATAL resetting due to F80 and F40 fault_state(0x0d04)
- Bugs 22843161 and 22848220 - Cards failed with "poor performance" at the same time, due to background recycler.

SW 1.2:

- Bug 19140306 – F40 card may fail at initial power on after no power on for long period.
- Bug 18160181 – F40 card may not show up on powercycle.
- Bug 17773639 - Sun Flash Accelerator F40 flash module may not initialize at powercycle.

SW 1.1:

- Bug 15801572 - SUNBT7181173 variable (up to 25% IOPS) read throughput (11%) performance.
- Bug 15805379 - SUNBT7185967 DFF is reported missing during power cycle.
- Bug 15799303 - SUNBT7178453 Panic Logs found on Sun Flash Accelerator F40 PCIe Card.
- Bug 15780582 - DDCLI reports overall health as GOOD even if SSD temperature is over 74C.

▼ **FATAL resetting due to F80 and F40 fault_state (0x0d04) (22727539)**

The Sun Flash Accelerator F40 PCIe Card may fail with FATAL resetting due to critical error fault_state(0x0d04).

Workaround

- **Update the firmware to SW 2.0 or later.**

▼ Cards failed with "poor performance" at the same time, due to background recycler (22843161 and 22848220)

Multiple Sun Flash Accelerator F40 PCIe Cards may fail with "poor performance" at the same time. Fix for reset due to `fault_state (0x0d04)`, and performance improvement due to background recycler.

Workaround

- Update the firmware to SW 2.0 or later.

▼ Card may fail at initial power on after no power on for long period (19140306)

The Sun Flash Accelerator F40 PCIe Card may fail at initial power on after no power on for long period.

Workaround

- Update the firmware to SW 2.0 or later.

▼ Card may not show up on power cycle (18160181)

The Sun Flash Accelerator F40 PCIe Card may not appear to be present after a power cycle.

Workaround

- Update the firmware to SW 2.0 or later.

▼ Card may not initialize at power cycle (17773639)

The Sun Flash Accelerator F40 PCIe Card may not initialize at power cycle.

Workaround

- **Update the firmware to SW 2.0 or later.**

▼ **SUNBT7181173 variable (up to 25% IOPS) reads throughput (11%) performance (15801572)**

The Sun Flash Accelerator F40 PCIe Card SUNBT7181173 variable (up to 25% IOPS) reads throughput (11%) performance.

Workaround

- **Update the firmware to SW 2.0 or later.**

▼ **SUNBT7185967 DFF is reported missing during power cycle (15805379)**

The Sun Flash Accelerator F40 PCIe Card SUNBT7185967 DFF is reported missing during power cycle.

Workaround

- **Update the firmware to SW 2.0 or later.**

▼ **SUNBT7178453 Panic Logs found on Sun Flash Accelerator F40 PCIe Card (15799303)**

Sun Flash Accelerator F40 PCIe Card Panic Logs are generated.

Workaround

- **Update the firmware to SW 2.0 or later.**

▼ **Sun Flash Accelerator F40 PCIe Card DDCLI reports overall health as GOOD even if SSD temperature is over 74C (15780582)**

The Sun Flash Accelerator F40 PCIe Card DDCLI utility reports overall health as GOOD even if the SSD temperature exceeds 74 degrees C.

Workaround

- **Update the firmware to SW 2.0 or later.**

