Oracle® Communications IP Service Activator

Release Notes

Release 7.2

E35658-01

October 2013



Oracle Communications IP Service Activator Release Notes, Release 7.2

E35658-01

Copyright © 2011, 2013, Oracle and/or its affiliates. All rights reserved.

This software and related documentation are provided under a license agreement containing restrictions on use and disclosure and are protected by intellectual property laws. Except as expressly permitted in your license agreement or allowed by law, you may not use, copy, reproduce, translate, broadcast, modify, license, transmit, distribute, exhibit, perform, publish, or display any part, in any form, or by any means. Reverse engineering, disassembly, or decompilation of this software, unless required by law for interoperability, is prohibited.

The information contained herein is subject to change without notice and is not warranted to be error-free. If you find any errors, please report them to us in writing.

If this is software or related documentation that is delivered to the U.S. Government or anyone licensing it on behalf of the U.S. Government, the following notice is applicable:

U.S. GOVERNMENT END USERS: Oracle programs, including any operating system, integrated software, any programs installed on the hardware, and/or documentation, delivered to U.S. Government end users are "commercial computer software" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, use, duplication, disclosure, modification, and adaptation of the programs, including any operating system, integrated software, any programs installed on the hardware, and/or documentation, shall be subject to license terms and license restrictions applicable to the programs. No other rights are granted to the U.S. Government.

This software or hardware is developed for general use in a variety of information management applications. It is not developed or intended for use in any inherently dangerous applications, including applications that may create a risk of personal injury. If you use this software or hardware in dangerous applications, then you shall be responsible to take all appropriate fail-safe, backup, redundancy, and other measures to ensure its safe use. Oracle Corporation and its affiliates disclaim any liability for any damages caused by use of this software or hardware in dangerous applications.

Oracle and Java are registered trademarks of Oracle and/or its affiliates. Other names may be trademarks of their respective owners.

Intel and Intel Xeon are trademarks or registered trademarks of Intel Corporation. All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. AMD, Opteron, the AMD logo, and the AMD Opteron logo are trademarks or registered trademarks of Advanced Micro Devices. UNIX is a registered trademark of The Open Group.

This software or hardware and documentation may provide access to or information on content, products, and services from third parties. Oracle Corporation and its affiliates are not responsible for and expressly disclaim all warranties of any kind with respect to third-party content, products, and services. Oracle Corporation and its affiliates will not be responsible for any loss, costs, or damages incurred due to your access to or use of third-party content, products, or services.

Contents

| Pr | eface | v |
|----|--|------------|
| | Audience | . V |
| | Related Documents | |
| | Documentation Accessibility | . v |
| 1 | IP Service Activator New Features | |
| | What's New in IP Service Activator | 1-1 |
| | OSM to IP Service Activator Design Studio Project | 1-1 |
| | Design Studio Enhancements for IP Service Activator | 1-2 |
| | OSM to IP Service Activator Integration Reference Implementation | 1-2 |
| | OSM to IP Service Activator Best Practices Documentation | |
| | IP Service Activator Web Services Interface | 1-3 |
| | Cisco IOS XR Cartridge: MPLS L3 VPN for IPv6 | 1-3 |
| | Cisco IOS XR Cartridge: LSP for IPv6 | |
| | Cisco IOS XR Cartridge: QoS for IPv6 | 1-4 |
| | Cisco IOS XR Cartridge: Interface Configuration Management | 1-4 |
| | Juniper JUNOS Cartridge: Interface Configuration Management | 1-4 |
| | Support for Multilink Frame Relay Interfaces | |
| | Configuration Template Module Enhancements | |
| | Enhancements | 1-5 |
| | Deprecated Features | 1-6 |
| 2 | Issues | |
| | Fixes in This Release | 2-1 |
| | Known Problems | 2-6 |

Preface

This document lists new features, product enhancements, and deprecated features in Oracle Communications IP Service Activator 7.2. It also includes a list of customer issues fixed in this release and current known issues.

For third-party copyright information and trademark acknowledgements, see the product documentation for this release. For product licensing information, see the Product License document for this release.

Audience

This document is intended for network administrators, network configuration engineers, network managers, and other individuals who need to maintain and work with IP Service Activator.

Related Documents

For more information, see the following documents in the Oracle Communications IP Service Activator documentation set:

- See *IP Service Activator Installation Guide* for system requirements and information on installing, upgrading and uninstalling *IP Service Activator*.
- See *IP Service Activator Administrator's Guide* for information and procedures related to the duties a system administrator performs in monitoring and managing *IP Service Activator*.

Documentation Accessibility

For information about Oracle's commitment to accessibility, visit the Oracle Accessibility Program website at

http://www.oracle.com/pls/topic/lookup?ctx=acc&id=docacc.

Access to Oracle Support

Oracle customers have access to electronic support through My Oracle Support. For information, visit

http://www.oracle.com/pls/topic/lookup?ctx=acc&id=info or visit http://www.oracle.com/pls/topic/lookup?ctx=acc&id=trs if you are hearing impaired.

IP Service Activator New Features

This chapter lists new features, product enhancements, and deprecated features in Oracle Communications IP Service Activator. It also includes deployment and installation considerations for IP Service Activator and related software.

This chapter consists of the following sections:

- What's New in IP Service Activator
- Deprecated Features

What's New in IP Service Activator

This section contains the new features and product enhancements in IP Service Activator release 7.2.

The new features in this release of IP Service Activator are:

- OSM to IP Service Activator Design Studio Project
- Design Studio Enhancements for IP Service Activator
- OSM to IP Service Activator Integration Reference Implementation
- OSM to IP Service Activator Best Practices Documentation
- IP Service Activator Web Services Interface
- Cisco IOS XR Cartridge: MPLS L3 VPN for IPv6
- Cisco IOS XR Cartridge: LSP for IPv6
- Cisco IOS XR Cartridge: QoS for IPv6
- Cisco IOS XR Cartridge: Interface Configuration Management
- Juniper JUNOS Cartridge: Interface Configuration Management
- Support for Multilink Frame Relay Interfaces
- Configuration Template Module Enhancements

OSM to IP Service Activator Design Studio Project

The OSM to IP Service Activator Design Studio project enables you to use Oracle Communications Design Studio to develop Oracle Communications Order and Service Management (OSM) to IP Service Activator automated tasks, which are used as part of IP service provisioning workflows. The OSM to IP Service Activator Design Studio project has two parts:

- **IP Service Activator Service Action Definitions**: exposes IP Service Activator functionality as a set of service actions that you can use in the activation task to construct automated tasks for OSM.
- IP Service Activator Data Dictionary: provides predefined data definitions from the IP Service Activator objects and parameters available within core service modules and configuration policies.

Design Studio support for IP Service Activator reduces integration complexity compared to manual integration approaches. Design Studio, along with the OSM to IP Service Activator Design Studio project, aligns IP Service Activator with Oracle Communications OSS integration tools and best practices. You can create workflows that integrate IP Service Activator data and activation actions with other tools and systems.

Note: To use this release of IP Service Activator with Design Studio, you require Design Studio 7.2.1 or later.

Design Studio Enhancements for IP Service Activator

Design Studio is enhanced to provide support for IP Service Activator. These enhancements are:

- Configuration Template Module (CTM) import: You can now import CTM templates into Design Studio.
- **Activation Task support for IP Service Activator:** As part of the OSM to IP Service Activator integration, the Design Studio Activation task is enhanced to provide support for IP Service Activator.

Note: For more information about Design Studio enhancements for IP Service Activator, see *Design Studio Release Notes*.

OSM to IP Service Activator Integration Reference Implementation

The OSM to IP Service Activator integration reference implementation provides an integrated L3 Multiprotocol Label Switching (MPLS) VPN service solution sample, including configuration of Ethernet-based access for sites. L3 MPLS VPN is a widely deployed business service with a high degree of provisioning order complexity, as well as network configuration complexity.

The solution is packaged as a Design Studio project, which implements OSM workflows that consume structured provisioning orders and drive activation operations to devices in the network using IP Service Activator.

This tested and documented solution uses best practices for OSM to IP Service Activator integration. The solution includes workflows that allow you to create, modify, and delete services, as well as configure activation tasks.

You can adapt this implementation to suit specific needs, use it as a pattern for new workflows, or reference it as a set of worked examples that illustrate specific capabilities for OSM to IP Service Activator integration. This limits the risks when developing the overall solution and provides concrete examples of how an integrated system works, allowing you to more accurately assess the effort required to develop a specific solution.

For more information about IP Service Activator reference implementation, see OSS Integrated Service Provisioning Reference Implementation for Layer 3 MPLS VPN

Service with Metro Ethernet Access (Doc ID 1479821.1) knowledge article on Oracle Support:

https://support.oracle.com

OSM to IP Service Activator Best Practices Documentation

OSM to IP Service Activator integration best practices documentation describes the recommended approach for implementing a workflow-driven activation system using OSM and IP Service Activator. This document presents the cumulative knowledge Oracle experts have gained from their experience in developing OSM workflows.

Using this documentation allows you to more rapidly develop workflows, and ensures that these workflows are easier for you to maintain and enhance in the future.

If you want to obtain IP Service Activator best practices documentation, see OSS Integrated Service Provisioning Reference Implementation for Layer 3 MPLS VPN Service with Metro Ethernet Access (Doc ID 1479821.1) knowledge article on Oracle Support:

https://support.oracle.com

IP Service Activator Web Services Interface

A comprehensive Web services-based interface for IP Service Activator provides a robust, scalable transport mechanism. Through Web services, you can use all core service modules and all configuration policies supported by IP Service Activator, allowing you to control activation operations from upstream systems. In addition, the Web services interface allows you to manage the service activator transaction cycle, lessening the complexity of upstream logic.

IP Service Activator aligns with industry standards and, using existing Oracle technology, you can integrate IP Service Activator with a range of industry and Oracle products that support Web services.

Note: To use Web services with the OSM to IP Service Activator integration, OSM release 7.2.0 patch 1, or later is required.

Cisco IOS XR Cartridge: MPLS L3 VPN for IPv6

The MPLS L3 VPN cartridge for IP Service Activator for Cisco devices running IOS XR is enhanced to include support for IPv6 traffic. This cartridge extends and expands on the existing IP Service Activator multi-vendor support. Service providers can now manage their MPLS networks, consisting of devices from multiple vendors, using one model within IP Service Activator. This allows you to rapidly create, modify, and delete MPLS L3 VPNs and their parts across the network.

This functionality includes support for:

- IPv6 addressing in the VPN
- IPv6 static routing

Cisco IOS XR Cartridge: LSP for IPv6

IP Service Activator is enhanced with the introduction of IPv6 support for MPLS Traffic Engineering Label Switched Path (TE LSP) on Cisco IOS XR devices.

It includes IPv6 support for:

- Activation of MPLS-TE LSP paths
- Path protection (primary and secondary)
- Automating mirror LSP paths
- Link/Node protection and configuring fast re-route

Cisco IOS XR Cartridge: QoS for IPv6

IP Service Activator is enhanced with the introduction of IPv6 support for Quality of Service (QoS) using Modular QoS CLI (MQC) per hop behavior (PHB) on Cisco IOS XR devices.

It includes IPv6 support for the key QoS mechanisms:

- Classification
- Marking
- Policing
- Shaping

Cisco IOS XR Cartridge: Interface Configuration Management

An Interface Configuration Management cartridge is introduced for IP Service Activator for Cisco devices running IOS XR.

This cartridge enables you to:

- Create, modify and delete logical interfaces
- Modify configuration on physical interfaces

Juniper JUNOS Cartridge: Interface Configuration Management

An Interface Configuration Management cartridge is introduced for IP Service Activator for Juniper devices running JUNOS.

This cartridge enables you to:

- Create, modify and delete logical interfaces
- Modify configuration on physical interfaces

Support for Multilink Frame Relay Interfaces

IP Service Activator is enhanced with support for Multilink Frame Relay interfaces on Cisco devices running IOS. New interface configuration policies have been introduced to allow you to create, modify and delete Multilink Frame Relay interfaces, including the ability to specify whether existing interfaces are part of a Multilink Frame Relay interface.

Configuration Template Module Enhancements

IP Service Activator is enhanced with new functionality for the Configuration Template Module (CTM).

New features include:

- New CTM field types
- Improved support for wildcards in the depends statement

The ability to nest templates

See the CTM online Help modules for more information.

Enhancements

Table 1–1 list the enhancements that are included in this release of IP Service Activator.

Table 1–1 IP Service Activator Enhancements

| BugDB Number | Description |
|--------------|--|
| 13887017 | IPV6 CHANGES FOR CISCO IOS XR LSP CARTRIDGE AND LSP MODULE |
| 13887011 | IPV6 SUPPORT FOR CISCO IOS XR QOS CARTRIDGE |
| 13887026 | IPV6 SUPPORT FOR CISCO IOS XR L3 VPN CARTRIDGE |
| 13636111 | SUPPORT THE NO IP PIM AUTORP STATEMENT FOR MULTICAST FEATURE |
| 10217119 | CONFIGURE CISCO MARTINI XCONNECT ON VLAN MAIN INTERFACES |
| 9556354 | UPGRADE TO SUPPORT MULTICAST WITH VRF-LITE CONFIGURATION |
| 13527085 | DEVICE DESCRIPTION FIELD LIMITED TO 128 CHARACTERS |
| 12985989 | IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING FROM 0 TO 4294967295 |
| 12567327 | SUPPORT FOR IPV6 IN JUNIPER DEVICE DRIVER |
| 12372878 | ALLOW MQCPHB TO USE NESTING WITH MARK ONLY SELECTED |
| 12591514 | IP SERVICE ACTIVATOR MAXIMUM-PREFIX COMMAND |
| 10100930 | SUPPORT FOR CONFIGURABLE TAG COMMAND IN IPSA SAA |
| 10323740 | IMPROVED ORGANIZATION OF COS MECHANISMS IN PHB AND MQCPHB OBJECTS |
| 12340142 | LSP SUPPORT FOR AUTOROUTE ANNOUNCE |
| 12340200 | LSP XR IOS NOT SENDING LDP COMMAND WHEN SELECTED |
| 12351604 | HUAWEI LSP ENHANCEMENTS. |
| 12377665 | INPUT INTERFACE TRAFFIC TYPE DOES NOT SUPPORT HYPHEN |
| 12613342 | ISR G2 & ASR ROUTERS SHOULD SUPPORT "NO IP PIM DM-FALLBACK" COMMAND |
| 9338421 | SUPPORT FOR "MATCH COS <n>" AND "MATCH COS INNER <n>"</n></n> |
| 12779414 | EXTRA OPTIONS FOR BGP NEIGHBOR LOCAL-AS COMMAND ON CISCO IOS CARTRIDGE |
| 12928024 | IP SERVICE ACTIVATOR THROWS EXCEPTION WHILE REMOVING HOLD-QUEUE COMMAND FROM INTERFACE |
| 12774990 | ABILITY TO SPECIFY THE OSPF PROCESS ID IN CISCO IOS CARTRIDGE |

Table 1–1 (Cont.) IP Service Activator Enhancements

| BugDB Number | Description |
|--------------|--|
| 12779613 | EXTRA COMMAND IN ROUTE POLICY FOR THE CISCO IOS CARTRIDGE. |
| 12852561 | CISCO PROPRIETARY MIB TO BE USED FOR IPV6 DATA |
| 12552096 | CANNOT USE WILDCARD IN AUTODISCOVERY.CFG RENAME COMMAND |
| 12940624 | FEATURE FOR ALCATEL DISCOVERY MODULE TO INCLUDE CARD NAME IN INTERFACE PROPERTIES |
| 12940687 | ALCATEL DISCOVERY MODULE WILL NOT REDISCOVER DEVICE IF IT IS IN A NOT FOUND STAT |
| | JUNIPER CARTRIDGE REPLACEMENT FOR JUNIPER DEVICE DRIVER |
| 14126939 | HUAWEI CARTRIDGE APPENDING AUTOGENERATED NUMBER TO QOS OBJECTS |
| 14232221 | SUPPORT FOR EXTRA COMMANDS IN VIRTUAL TEMPLATE CONFIGURATION POLICY |
| 14604666 | DUPLEX/SPEED SETTING ON CISCO UNIVERSAL CONFIG POLICY |
| 13952990 | ADDITIONAL SUPPORT FOR MULTICAST VPN FOR CISCO |
| 13780160 | ENHANCEMENT TO SUPPORT BFD SUPPORT FOR BGP FOR L3 VPN |
| 13452054 | ENHANCEMENT TO CISCO BGP AND VRF ROUTE POLICIES TO SUPPORT SET AS PATH-PREPEND AND SET ORIGIN COMMANDS |
| 14102924 | SUPPORT OF IP PIM DR-PRIORITY 10 |
| 16385851 | SUPPORT CORE INTERFACE CREATION POLICIES FOR JUNOS CARTRIDGE |
| | SOLARIS 11 SUPPORT |
| 10169508 | MLFR INTERFACES SUPPORTED IN IP SERVICE ACTIVATOR |
| 16658331 | CTM ENHANCEMENTS |
| 13774183 | SUPPORT FOR CONFIGURATION POLICIES FOR CISCO IOS XR |
| 14181099 | THE ABILITY TO LINK A CONFIG POLICY TO A DEVICE WITHOUT THE USE OF AN INTERFACE |
| 16210996 | THE SAME MULTIPATH FUNCTIONALITY FOR JUNIPER AS FOR CISCO IOS XR |
| 16990518 | UPVERSION JRE TO 1.7.0 U IN IP SERVICE ACTIVATOR / CM |
| 9963766 | SUPPORT FOR 4-BYTE ASN NUMBERS IN JUNIPER DEVICE DRIVER |

Deprecated Features

The following features have been removed from the feature set in this IP Service Activator release:

- Juniper E-series Device Support
- LSP Module

- Oracle Solaris 32-bit
- ASAP-IP Service Activator Process Integration Pack
- Transaction Export Utility
- Dual Dispatch

Issues

This chapter provides two tables: a list of all fixed issues and current known problems in this release of Oracle Communications IP Service Activator.

Fixes in This Release

This section lists all the fixed issues in this release of IP Service Activator.

Table 2–1 provides the service request number, the bug number and a brief description of the issue.

Table 2-1 Customer Issues Fixed in IP Service Activator

| Service Request (SR) Number | BugDB Number | Description |
|-----------------------------------|-----------------|---|
| 3-6090680241 | 6383340 | WHEN A NETWORK HAS MANY DOWN DEVICES, THE JUNIPER DEVICE DRIVER WILL CONSTANTLY CHECK DEVICE STATUS AND CAUSE A FREEZE |
| 2-5849378 | 9068784 | DATASCRIPT AND CONFIGLET CLEANUP FAILS TO CLEAN UP CONFIGLETS |
| 3-1229453731 | 9262489 | NP FAILS TO STARTUP IF PROCESSES ON NAMING SERVICE MACHINE NOT FULLY STARTED |
| 3-1889804711 | 9881193 | IP SERVICE ACTIVATOR IS NOT DELETING THE LAST DEVICE MODEL IN THE DATABASE WHE N USERS DELETE DEVICES FROM IP SERVICE ACTIVATOR |
| 3-1911600931 | 9892859 | THE OIM COMMAND GETID IS SLOWER WITH PROXY THAN THE GETID COMMAND WITHOUT PROXY |
| 3-2051612981 | 10100930 | CANNOT CONFIGURE TAG COMMAND IN IP SERVICE ACTIVATOR SAA |
| 3-2474565621 | 10367395 | DURING RIP IPV4 ADDRESS FAMILY REMOVAL, NP ISSUES "NO VERSION 2" COMMAND |
| 3-2768268931 | 11682346 | LINKING TWO MARTINI ENDPOINTS IN DIFFERENT TRANSACTIONS CAUSES TIMEOUT |
| 7643437.992 | 11883783 | IP SERVICE ACTIVATOR ASSIGNED DUPLICATE RD AUTOMATICALLY WHEN MANUAL RD VALUE SAME AS GENERATED RD VALUE |
| 3-3182517271 | 12313193 | INCORRECT BANDWIDTH VALUE ON INTERFACES |
| 3-3349331431 | 12339743 | LSP CONFIGURATION POLICY DOES NOT ALLOW 0 FOR BANDWIDTH RANGE |
| 3-3349331431 | 12340142 | LSP SUPPORT FOR AUTOROUTE ANNOUNCE |

Table 2–1 (Cont.) Customer Issues Fixed in IP Service Activator

| Service Request (SR) Number | BugDB Number | Description |
|-----------------------------------|-----------------|--|
| 3-3349331431 | 12340200 | SUPPORT FOR DYNAMIC LABEL SWITCHING OF LSP TRAFFIC |
| 3-3353814521 | 12340403 | ERROR IN IP SERVICE ACTIVATOR WHILE APPLYING THE IP MTU VALUE GREATER THAN INTERFACE MTU |
| 3-3359093721 | 12351604 | HUAWEI LSP ENHANCEMENTS |
| 3-3332514011 | 12363434 | DELETING FAULT IN IP SERVICE ACTIVATOR TAKES OVER 1 HR TO REPUSH CONFIG |
| 3-3357137741 | 12372878 | ALLOW MQCPHB TO USE NESTING WITH MARK ONLY SELECTED |
| 3-3357137741 | 12377665 | INPUT INTERFACE TRAFFIC TYPE DOES NOT SUPPORT HYPHEN, CANNOT ENTER INTERFACE RANGE |
| 3-3571544121 | 12539067 | A SMALL SAA PROBE CHANGE ON ONE DEVICE CAUSES MASSIVE NUMBER OF COMMITS |
| 3-3591356521 | 12552400 | ALCATEL DISCOVERY MODULE DOES NOT FIND ALL INTERFACES, CANNOT CHANGE DISCOVERY QUERY FILTERS |
| 3-3569487011 | 12557474 | CISCO 15.1-M. IOS NO LONGER ACCEPTS AROUND CLASSMAP AND POLICY |
| 3-3603593111 | 12557683 | INTERFACE DECORATION ROLLBACK CAN REMOVE INTERFACE IP ADDRESS |
| | 12558573 | IOSXR: IP SERVICE ACTIVATOR DOES NOT CONFIGURE EXCLUSIVE MODE |
| 3-2546876611 | 12591514 | IP SERVICE ACTIVATOR MAXIMUM-PREFIX COMMAND IS NOT SUPPORTED |
| 3-3569061521 | 12607579 | POLICY SERVER RESTARTED DURING A PROXY PUSH |
| 3-3732817831 | 12613342 | IP SERVICE ACTIVATOR DOES NOT SUPPORT "NO IP PIM DM-FALLBACK" COMMAND |
| | 12626942 | JUNOS BASE CARTRIDGE 'CONFIGURE PRIVATE' AND 'CONFIGURE EXCLUSIVE' SUPPORT IS REQUIRED |
| 3-3733180941 | 12627026 | UPGRADE TO 7.0 NPSNAPSHOT.SH DOES NOT RUN, JAVA EXCEPTION OCCURS |
| 3-3753249831 | 12627694 | LOOPBACK ADDRESS CHANGES UPON DISCOVERY |
| | 12631270 | IPV4 AND IPV6 ADDRESSES ARE REMOVED WHEN CHANGING INTERFACE TAGGING, ENCAPSULATION TYPE |
| 3-3733180941 | 12632652 | UPGRADE TO 7.0 - NPUPGRADE FAILS TO COMPLETE |
| 3-3357664678 | 12642739 | IOSXR: DELETION OF FAULT AFTER ROLLBACK ON REMOVAL DOES NOT INITIATE RE-PUSH |
| 3-3746233581 | 12652845 | CARTRIDGE ALWAYS REDUCES SPOKE SITES INTO ONE VRF |
| | 12661071 | NETWORK PROCESSOR/CISCO CARTRIDGE THROWS NULLPOINTEREXCEPTION WHILE DOING VRF REDUCTIONS |
| 3-1330352221 | 12661773 | NETWORK PROCESSOR: IOS CARTRIDGE RIP DEFAULT ROUTE SUPPORT |

Table 2–1 (Cont.) Customer Issues Fixed in IP Service Activator

| Description Description Description | | | |
|---|--------------|----------|--|
| DUE TO RUNNING DISCOVERY SIMULTANEOUSLY WITH USER TRANSACTIONS | | | Description |
| THEIR VPN WITH AN IPV6 ADDRESS | 3-3871400701 | 12686925 | DUE TO RUNNING DISCOVERY SIMULTANEOUSLY WITH |
| UPON COMMAND RE-ISSUE | 3-6514003681 | 12712070 | |
| 24082370365 12779414 EXTRA OTPIONS REQUIRED FOR BGP NEIGHBOR LOCAL-AS COMMAND ON CISCO IOS CARTRIDGE 3-4082789871 12779613 EXTRA COMMAND IN ROUTE POLICY IS REQUIRED FOR THE CISCO IOS CARTRIDGE 3-4107175171 12808285 JUNIPER BASE CARTRIDGE PROMPT MATCH DOES NOT HANDLE MX DEVICE PROMPT - 12901214 CANNOT DISCOVER IPV6 INTERFACES FROM DEVICES RUNNING CISCO PROPRIETARY MIB 3-3124242631 12903647 SUPPORT FOR IPV6 IN JUNIPER DEVICE DRIVER 12928024 IP SERVICE ACTIVATOR THROWS EXCEPTION WHILE REMOVING HOLD-QUEUE COMMAND FROM INTERFACE 3-4416544531 12940624 ALCATEL DISCOVERY MODULE DOES NOT INCLUDE CARD NAME IN INTERFACE PROPERTIES 3-3338581371 12940687 ALCATEL DISCOVERY MODULE DOES NOT REDISCOVER DEVICE IF IT IS IN A NOT FOUND STATE 3-3338581371 12976514 JUNIPER DEVICE DRIVER LOGS A COMMIT ERROR EVEN IF THE COMMIT IS SUCCESSFUL - 12977771 INLINE AUDIT FAILS WHEN ONLY ONE VLAN ID IS IN THE COMMAND 3-4510448161 12985989 IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING BEYOND 4GBPS 3-4636146171 13045036 NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES - 13054425 IP SERVICE ACTIVATOR GUI RESPONSE TO OPENING PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4871320691 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL | 3-3949058321 | 12760830 | |
| LOCAL-AS COMMAND ON CISCO IOS CARTRIDGE 3-4082789871 12779613 EXTRA COMMAND IN ROUTE POLICY IS REQUIRED FOR THE CISCO IOS CARTRIDGE 3-4107175171 12808285 JUNIPER BASE CARTRIDGE PROMPT MATCH DOES NOT HANDLE MX DEVICE PROMPT - 12901214 CANNOT DISCOVER IPV6 INTERFACES FROM DEVICES RUNNING CISCO PROPRIETARY MIB 3-3124242631 12903647 SUPPORT FOR IPV6 IN JUNIPER DEVICE DRIVER 3-4366122921 12928024 IP SERVICE ACTIVATOR THROWS EXCEPTION WHILE REMOVING HOLD-QUEUE COMMAND FROM INTERFACE 3-4416544531 12940624 ALCATEL DISCOVERY MODULE DOES NOT INCLUDE CARD NAME IN INTERFACE PROPERTIES 3-4419218621 12940687 ALCATEL DISCOVERY MODULE DOES NOT REDISCOVER DEVICE IF IT IS IN A NOT FOUND STATE 3-3338581371 12976514 JUNIPER DEVICE DRIVER LOGS A COMMIT ERROR EVEN IF THE COMMIT IS SUCCESSFUL - 12977771 INLINE AUDIT FAILS WHEN ONLY ONE VLAN ID IS IN THE COMMAND 3-4510448161 12985989 IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING BEYOND 4GBPS 3-4636146171 13045036 NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES - 13054425 IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING BEYOND 4GBPS 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4871320691 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | 3-4082370351 | 12774990 | |
| 3-4107175171 12808285 JUNIPER BASE CARTRIDGE PROMPT MATCH DOES NOT HANDLE MX DEVICE PROMPT - 12901214 CANNOT DISCOVER IPV6 INTERFACES FROM DEVICES RUNNING CISCO PROPRIETARY MIB 3-3124242631 12903647 SUPPORT FOR IPV6 IN JUNIPER DEVICE DRIVER 3-4366122921 12928024 IP SERVICE ACTIVATOR THROWS EXCEPTION WHILE REMOVING HOLD-QUEUE COMMAND FROM INTERFACE 3-4416544531 12940624 ALCATEL DISCOVERY MODULE DOES NOT INCLUDE CARD NAME IN INTERFACE PROPERTIES 3-4419218621 12940687 ALCATEL DISCOVERY MODULE DOES NOT REDISCOVER DEVICE IF IT IS IN A NOT FOUND STATE 3-3338581371 12976514 JUNIPER DEVICE DRIVER LOGS A COMMIT ERROR EVEN IF THE COMMIT IS SUCCESSFUL - 12977771 INLINE AUDIT FAILS WHEN ONLY ONE VLAN ID IS IN THE COMMAND 3-4510448161 12985989 IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING BEYOND 4GBPS 3-4636146171 13045036 NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES - 13054425 IP SERVICE ACTIVATOR GUI RESPONSE TO OPENING PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4871320691 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL | 3-4082370365 | 12779414 | |
| HANDLE MX DEVICE PROMPT - 12901214 CANNOT DISCOVER IPV6 INTERFACES FROM DEVICES RUNNING CISCO PROPRIETARY MIB 3-3124242631 12903647 SUPPORT FOR IPV6 IN JUNIPER DEVICE DRIVER 3-4366122921 12928024 IP SERVICE ACTIVATOR THROWS EXCEPTION WHILE REMOVING HOLD-QUEUE COMMAND FROM INTERFACE 3-4416544531 12940624 ALCATEL DISCOVERY MODULE DOES NOT INCLUDE CARD NAME IN INTERFACE PROPERTIES 3-4419218621 12940687 ALCATEL DISCOVERY MODULE DOES NOT REDISCOVER DEVICE IF IT IS IN A NOT FOUND STATE 3-33338581371 12976514 JUNIPER DEVICE DRIVER LOGS A COMMIT ERROR EVEN IF THE COMMIT IS SUCCESSFUL - 12977771 INLINE AUDIT FAILS WHEN ONLY ONE VLAN ID IS IN THE COMMAND 3-4510448161 12985989 IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING BEYOND 4GBPS 3-4636146171 13045036 NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES - 13054425 IP SERVICE ACTIVATOR GUI RESPONSE TO OPENING PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | 3-4082789871 | 12779613 | |
| RUNNING CISCO PROPRIETARY MIB 3-3124242631 12903647 SUPPORT FOR IPV6 IN JUNIPER DEVICE DRIVER 3-4366122921 12928024 IP SERVICE ACTIVATOR THROWS EXCEPTION WHILE REMOVING HOLD-QUEUE COMMAND FROM INTERFACE 3-4416544531 12940624 ALCATEL DISCOVERY MODULE DOES NOT INCLUDE CARD NAME IN INTERFACE PROPERTIES 3-4419218621 12940687 ALCATEL DISCOVERY MODULE DOES NOT REDISCOVER DEVICE IF IT IS IN A NOT FOUND STATE 3-3338581371 12976514 JUNIPER DEVICE DRIVER LOGS A COMMIT ERROR EVEN IF THE COMMIT IS SUCCESSFUL | 3-4107175171 | 12808285 | |
| 3-4366122921 12928024 IP SERVICE ACTIVATOR THROWS EXCEPTION WHILE REMOVING HOLD-QUEUE COMMAND FROM INTERFACE 3-4416544531 12940624 ALCATEL DISCOVERY MODULE DOES NOT INCLUDE CARD NAME IN INTERFACE PROPERTIES 3-4419218621 12940687 ALCATEL DISCOVERY MODULE DOES NOT REDISCOVER DEVICE IF IT IS IN A NOT FOUND STATE 3-3338581371 12976514 JUNIPER DEVICE DRIVER LOGS A COMMIT ERROR EVEN IF THE COMMIT IS SUCCESSFUL 12977771 INLINE AUDIT FAILS WHEN ONLY ONE VLAN ID IS IN THE COMMAND 3-4510448161 12985989 IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING BEYOND 4GBPS 3-4636146171 13045036 NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES 13054425 IP SERVICE ACTIVATOR GUI RESPONSE TO OPENING PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | | 12901214 | |
| REMOVING HOLD-QUEUE COMMAND FROM INTERFACE 3-4416544531 12940624 ALCATEL DISCOVERY MODULE DOES NOT INCLUDE CARD NAME IN INTERFACE PROPERTIES 3-4419218621 12940687 ALCATEL DISCOVERY MODULE DOES NOT REDISCOVER DEVICE IF IT IS IN A NOT FOUND STATE 3-3338581371 12976514 JUNIPER DEVICE DRIVER LOGS A COMMIT ERROR EVEN IF THE COMMIT IS SUCCESSFUL 12977771 INLINE AUDIT FAILS WHEN ONLY ONE VLAN ID IS IN THE COMMAND 3-4510448161 12985989 IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING BEYOND 4GBPS 3-4636146171 13045036 NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES 13054425 IP SERVICE ACTIVATOR GUI RESPONSE TO OPENING PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | 3-3124242631 | 12903647 | SUPPORT FOR IPV6 IN JUNIPER DEVICE DRIVER |
| 3-4419218621 12940687 ALCATEL DISCOVERY MODULE DOES NOT REDISCOVER DEVICE IF IT IS IN A NOT FOUND STATE 3-3338581371 12976514 JUNIPER DEVICE DRIVER LOGS A COMMIT ERROR EVEN IF THE COMMIT IS SUCCESSFUL - 12977771 INLINE AUDIT FAILS WHEN ONLY ONE VLAN ID IS IN THE COMMAND 3-4510448161 12985989 IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING BEYOND 4GBPS 3-4636146171 13045036 NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES - 13054425 IP SERVICE ACTIVATOR GUI RESPONSE TO OPENING PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | 3-4366122921 | 12928024 | REMOVING HOLD-QUEUE COMMAND FROM |
| 3-3338581371 12976514 JUNIPER DEVICE DRIVER LOGS A COMMIT ERROR EVEN IF THE COMMIT IS SUCCESSFUL - 12977771 INLINE AUDIT FAILS WHEN ONLY ONE VLAN ID IS IN THE COMMAND 3-4510448161 12985989 IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING BEYOND 4GBPS 3-4636146171 13045036 NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES - 13054425 IP SERVICE ACTIVATOR GUI RESPONSE TO OPENING PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | 3-4416544531 | 12940624 | |
| IF THE COMMIT IS SUCCESSFUL INLINE AUDIT FAILS WHEN ONLY ONE VLAN ID IS IN THE COMMAND 3-4510448161 12985989 IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING BEYOND 4GBPS 3-4636146171 13045036 NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES - 13054425 IP SERVICE ACTIVATOR GUI RESPONSE TO OPENING PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | 3-4419218621 | 12940687 | |
| 3-4510448161 12985989 IP SERVICE ACTIVATOR GUI RESTRICTS ETHERNET PORT SHAPING BEYOND 4GBPS 3-4636146171 13045036 NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES - 13054425 IP SERVICE ACTIVATOR GUI RESPONSE TO OPENING PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | 3-3338581371 | 12976514 | |
| 3-4636146171 13045036 NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES 13054425 IP SERVICE ACTIVATOR GUI RESPONSE TO OPENING PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | | 12977771 | |
| 13054425 IP SERVICE ACTIVATOR GUI RESPONSE TO OPENING PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | 3-4510448161 | 12985989 | |
| PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 INSTALLATION 3-4732604681 13114928 THE AUTOMATIC DISCOVERY STATUS SHOWS A LARGE NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | 3-4636146171 | 13045036 | NPADMIN NOT DISPLAYING FULL IPV6 ADDRESSES |
| NUMBER OF OBJECTS AND THE TIME HAS HAS CHANGED 3-4820134941 13253038 AUDIT FAILS DURING NETWORK PROCESSOR UPGRADE BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | | 13054425 | PHB OBJECT PROPERTIES IS SLOW AFTER THE PATCH 14 |
| BECAUSE OF REORDERING OF CLASSMAPS AND ACLS 3-4863694921 13344440 INCORRECT DOCUMENTATION IN OPTION EDITOR TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | 3-4732604681 | 13114928 | NUMBER OF OBJECTS AND THE TIME HAS HAS |
| TOOL 3-4871320691 13344817 ALCATEL CARTRIDGE DOES NOT DETECT FAILOVER HAS OCCURED | 3-4820134941 | 13253038 | |
| HAS OCCURED | 3-4863694921 | 13344440 | |
| 13345287 NPUPGRADE DEVICE OPTION FAILING TO RUN | 3-4871320691 | 13344817 | |
| | | 13345287 | NPUPGRADE DEVICE OPTION FAILING TO RUN |

Table 2–1 (Cont.) Customer Issues Fixed in IP Service Activator

| Service Request (SR) | BugDB | |
|-------------------------|----------|--|
| Number | Number | Description |
| 3-4866353641 | 13397028 | INTEGRITY CHECKER ONLY FINDS FIRST CHILD UNDER PARENT OBJECT, CHILDREN IDS WRONGLY ACCUMULATED |
| 3-4999551997 | 13454837 | UPGRADE RUN ERROR DUE TO MISSING CLASSIFICATION IN CLASSIFICATION RULE |
| 3-4994460431 | 13481586 | MULTIPLE NPUPGRADES RUNNING ON DIFFERENT SERVERS, DEVICE UPGRADE ERROR |
| 3-5058527301 | 13502438 | UPGRADE RUN FAILURE DUE TO MULTIPLE NPUPGRADES ON DIFFERENT SERVERS |
| 3-5092918381 | 13528774 | IP SERVICE ACTIVATOR SENDS ALL ROUTE TARGET COMMANDS IN VRF CONTEXT REGARDLESS OF THE ADDRESS FAMILY SELECTED |
| 3-5085084621 | 13559898 | OIM CLI IS MISSING FROM WINDOWS 64BIT DISTRIBUTION |
| 3-5095254081 | 13567111 | CARTRIDGECONFIGURATIONTOOL.SH DOES NOT WORK IN LINUX |
| 3-5206762751 | 13623194 | IP SERVICE ACTIVATOR DOES NOT HONOUR "CLIPORT" |
| 3-5206282581 | 13628093 | NP AUDIT USES MANAGEMENT IP ADDRESS FROM CACHE/LDM INSTEAD OF REAL ADDRESS |
| 3-5244267781 | 13767151 | THE CTM MODULE DOES NOT SUPPORT ALL THE CHARACTER SETS AVAILABLE WITH ORACLE DATABASE 11G2 |
| 3-5198240401 | 13799843 | THE POLICY SERVER CAN SOMETIMES GENERATE A CORE ON SHUTDOWN |
| 3-5363685891 | 13824733 | ON CISCO IOS XR, THE SERVER POLICY IS NOT BEING APPLIED TO FRAME-RELAY DLCI INTERFACES |
| 3-5440547331 | 13840876 | IP SERVICE ACTIVATOR REMOVED ACCESS-LISTS OFF ROUTER USING A DEVICE DRIVER |
| 3-5484539951 | 13921128 | WHEN A MASTER VPN SITE IS MOVED TO ANOTHER VPN ON CISCO IOS- XR, IP SERVICE ACTIVATOR AUTOMATICALLY CHANGES VRFS |
| 3-5576576241 | 13955118 | NETWORK PROCESSOR REPORTS A PROBLEM FOR ROUTERS WITH 2 ATM POLICIES |
| 3-2474565621 | 13960648 | THE REMOVAL OF RIP CONFIGURATION RESULTS IN RIP V2 CONFIGURATION BEING REMOVED |
| 3-5600784301 | 13981368 | CRITICAL ERROR RAISED DURING DEVICE MANAGEMENT PROCESS OF A CISCO 4924 |
| 3-5484539951 | 14008774 | RENAMING A SITE WITHIN A VPN CAN CAUSE UNWANTED VRF NAMING FOR OTHER SITES |
| 3-5731881591 | 14103423 | IP SERVICE ACTIVATOR REMOVED VRFS FROM AN IOS-XR DEVICE |
| 3-5718982591 | 14113299 | THE JUNIPER DRIVER CANNOT SEND COMMANDS FOR IPV6 MULTIPATH COMMANDS |
| | 14127887 | THE VRFREBUILDWAITTIME IS IN SECONDS NOT MILLISECONDS |

Table 2–1 (Cont.) Customer Issues Fixed in IP Service Activator

| Service Request (SR) Number | BugDB Number | Description |
|-----------------------------------|-----------------|---|
| 3-5782693271 | 14163620 | LINKAGE ERRORS ON SYSTEM STARTUP AFTER PATCH UPGRADE |
| 3-5782693271 | 14163620 | AFTER A PATCH UPGRADE, THERE ARE LINKAGE ERRORS ON THE SYSTEM |
| 3-5916292691 | 14285143 | IN CISCO IOS RELEASES 15.0, 12.0, AND LATER, THE IMPORT KEYWORD WAS REPLACED |
| 3-5952630401 | 14331331 | CTM USES OBJECT NAMES WHICH CAUSES PROBLEMS WHEN TWO TARGETS HAVE THE SAME NAME |
| 3-5855169911 | 14359916 | IP SERVICE ACTIVATOR COMMIT TIMES ARE GETTING LONGER |
| 3-6026372671 | 14405581 | WHEN THE DEVICE DESCRIPTION CONTAINS TWO QUOTATION MARKS, THE IOS VERSION PRECHECK FAILS |
| 3-6023925861 | 14470759 | THERE ARE DELAYS IN A NETWORK PROCESSOR PUSH ON THE SECOND PUSH IN A PRODUCTION SYSTEM |
| 3-6172276241 | 14652918 | WHEN A DEVICE IOS VERSION ENDS WITH A SPACE, THE CARTRIDGE CONFIGURATION TOOL CANNOT RECOGNIZE THE IOS VERSION |
| 3-6257108261 | 14697603 | WHEN ONLY THE INTERFACE COMMAND IS SELECTED FOR RE-ISSUE, IP SERVICE ACTIVATOR SENDS ALL THE DEVICE COMMANDS |
| 3-6301017331 | 14752629 | IN HUAWEI OS, AN AUDIT PROBLEM CAN OCCUR WHEN THERE IS ONLY ONE QOS TRAFFIC CLASSIFIER |
| 3-6348399961 | 14792031 | CERTAIN VPN CONFIGURATIONS CAN CAUSE A NETWORK PROCESSOR UPGRADE ERROR |
| 3-6360037831 | 14807316 | CISCO IOS 15X DEVICES DO NOT SUPPORT THE MAX-RESERVED-BANDWIDTH PARAMETER |
| 3-6405184061 | 15831823 | APPLYING MORE THEN ONE HSRP SERVICE POLICY TO A SINGLE INTERFACE CAUSES AN ERROR |
| 3-6430966961 | 15866893 | POLICY SERVER CAN CRASH WHEN A DISCOVERY IS RUN TO A NON-EXISTANT IP ADDRESS AND A TRANSACTION COMMIT IS ASLO CCURUING |
| 3-6503838191 | 15922512 | THE JUNOS DEVICE DRIVER CANNOT GENERATE IPV4 SUPER ADDRESS STATIC ROUTE 0.0.0.0/0 ANYMORE |
| 3-6414441301 | 15923539 | THE MAXIMUM ROUTE DISCREPANCY IS NOT SHOWING UP IN THE NETWORK PROCESSOR AUDIT REPORT |
| 3-6503838207 | 15934919 | THE JUNOS DEVICE DRIVER REDISTRIBUTION CONTAINS EXTRA STATIC WHEN ONE VPN SITE HAS STATIC ROUTE AND REDISTRIBUTION AND THE OTHER DOES NOT |
| 3-6574537591 | 16035763 | JUNIPER DEVICE DRIVER TAKES LONGER TO SEND CONFIGURATIONS WHEN USING FTP MODE |
| 3-6527410701 | 16068241 | SOLARIS 64BIT INTEGRITY CHECKER TRUNCATES REPORT SIZES TO 4K |
| 3-6635084001 | 16079094 | POLICY SERVER IS LOGGING ASSERTION ERRORS AND THEN SHUTTING DOWN AND LEAVING A CORE FILE |

Table 2–1 (Cont.) Customer Issues Fixed in IP Service Activator

| | 1 | |
|-----------------------------------|-----------------|--|
| Service Request (SR) Number | BugDB Number | Description |
| 3-6657709541 | 16191460 | INCORRECT TEXT IS DISPLAYED IN THE VRF REDUCTION MULTIPATH ERROR MESSAGE |
| 3-6696922701 | 16237175 | THE IOS XR CARTRIDGE DOE S NOT ALLOW RIP CONFIGURATION WITH AN IPV4+6 ROUTE |
| 3-6725605891 | 16387874 | IN CISCO IOS XR, CAPS ARE NOT FETCHED FOR A NEW FRAME-RELAY SUBINTERFACE |
| 3-6828460841 | 16409288 | IP SERVICE ACTIVATOR REPORTS THAT ATM HOLDQ DEPTH IS NOT SUPPORTED |
| 3-6883640511 | 16431700 | DATABASE UPGRADE FROM 5.2.4 FAILS |
| 3-6894070041 | 16453816 | IP SERVICE ACTIVATOR TRANSACTION STATUS MONITOR REPORTS FALSE NEGATIVES IN CASES INVOLVING VIRUTAL DEVICES |
| 3-6894602541 | 16457025 | IPV6 IP ADDRESS ON AN INTERFACE WILL NOT SHOW IN THE IP SERVICE ACTIVATOR UI IN DEVICE PANEL |
| 3-6939690271 | 16503075 | THE JUNIPER CATRIDGE IS OVERWRITING THE SYSTEM GROUP INTERFACE AND REMOVING MANUAL CONFIGURATION |
| 3-6957953311 | 16545867 | IP SERVICE ACTIVATOR GUI CRASHES ON WINDOWS 2008 R2 WHILE CLOSING |
| 3-7084309844 | 16727946 | THE JUNIPER DEVICE DRIVER FTP SESSION TIMES OUT AFTER 15 MINUTES DURING JUNIPER CONFIGURATION |
| 3-7352971284 | 16932843 | OFFLINE AUDITS ARE SHOWING ALL COMMANDS MISSING EVEN THOUGH THEY ARE IN THE CONFIGURATION FILE |

Known Problems

This section lists known problems found during testing of this release of IP Service Activator that remain unresolved at the release date.

Table 2–2 provides the service request number, the bug number and a brief description of the problem.

Table 2–2 Known Problems in IP Service Activator

| Service Request (SR) Number | Bugbane Number | Description |
|-----------------------------------|-------------------|--|
| 3-2854771401 | 11705527 | IP SERVICE ACTIVATOR PATCH UI INSTALLER CAUSES ABNORMAL TERMINATION |
| | | Problem |
| | | When installing an IP Service Activator patch, the size of the file path causes the following error message to appear: |
| | | Abnormal program termination. An internal error has occurred. |
| | | Workaround |
| | | Copy the installer zip file to a new folder with a shorter name, for example: |
| | | C:\IPSA\ |
| | | Extract the installer zip file to the new location and run the installer. |
| | 14181889 | IP SERVICE ACTIVATOR UI FREEZES AFTER RESTART OF THE PS AND OTHER NP AND PROCESSES |
| | | Problem |
| | | When using the IP Service Activator user interface (UI) with Windows 7, the UI sometimes does not reconnect to the server after the server is restarted. |
| | | Workaround |
| | | Close and reopen the UI. |
| | 14251008 | IP SERVICE ACTIVATOR TRANSACTION SUCCEEDED WHEN VPN CONCRETE IN CONFLICT |
| | | Problem |
| | | If a transaction generates a concrete in the conflict state, the transaction monitor reports the transactions as succeeded. |
| | | Workaround |
| | | None. |
| | 14292525 | CONFIG GUI DOES NOT UPDATE PATHS WHEN INSTALLING IP SERVICE ACTIVATOR TO A NEW LOCATION |
| | | Problem |
| | | If you are upgrading into a new directory, such as from 5.2.4 Solaris 32-bit to 7.2.0 Solaris 64-bit, the procedure is to copy the cman.cgf file to the new directory. The Configuration GUI does not update the paths in the cman.cfg file to the new path. |
| | | Workaround |
| | | Edit the cman.cfg file and change the directory paths to the new directory paths before running the confgGui tool. |
| _ | 14298841 | IP SERVICE ACTIVATOR PS TM LOGS THE SAME MESSAGE TWICE |
| | | Problem |
| | | Transaction-related logs may appear twice in the policy_server logs when a transaction fails. |
| | | Workaround |
| | | Ignore the additional log. |