


Pillar Axiom® 300, 500, and 600



Customer Release Notes

For Release 4.1



Pillar Axiom 300 Pillar Axiom 500 Pillar Axiom 600	Document Number: 4420-00026-3000
	Document Title: Customer Release Notes

Revision History

Rev Description	Rev Date	Effective Date
Release 4.1	2010-03-30	2010-04-27
Release 4.0	2009-11-20	2009-12-21
Release 3.4 GA	2009-07-22	2009-08-28 [Pillar Axiom 600 only]
Release 3.3 GA	2009-03-20	2009-05-01
Release 3.2 GA	2008-10-20	2008-10-27
Release 3.2 Beta	2008-10-10	2008-10-20
Release 03.01.00	2008-06-06	2008-06-18
Release 03.00.00	2008-03-12	2008-03-14
Release 02.08.00	2008-01-10	2008-01-14

1 Purpose

This document describes new features, capacities, configuration requirements, operating constraints, known issues and their workarounds, and other items for release 4.1 of the Pillar Axiom 300, 500, and 600 storage systems. The document covers hardware, firmware, software, cabling, and documentation. The information provided is accurate at the time of printing. Newer information may be available from your Pillar Data Systems authorized representative.

2 Product Release Information^a

Release 4.1 is a maintenance and feature enhancement release of the unified NAS/SAN Pillar Axiom 300, 500, and 600 storage systems.

^a Throughout this document, all references to release 2.x apply to the Pillar Axiom 500 system. The corresponding release number for Pillar Axiom 300 systems is 1.x. In other words, the software for those two release numbering schemes is equivalent.

2.1 System Enhancements

This update provides substantial quality improvements to all NAS and SAN Pillar Axiom models along with several feature and performance enhancements.

This release provides improved system efficiency and robustness, as well as including a rollup of all defects fixed in customer patches up to and including release 4.1.

For the list of defects that this release resolves, see Table 9 beginning on page 32.

2.1.1 Hardware Enhancements

- Fibre Channel Bricks and solid state drive (SSD) Bricks can now be intermixed in the same Pillar Axiom system.
- A new Pilot control unit (CU) is now available for Axiom systems running release 4.1 software and will begin shipping in the near future. After upgrading an older system to release 4.1, this new Pilot CU can be used to replace an older Pilot CU.

2.1.2 Software Enhancements

- Brick storage is now internally managed by means of a new mechanism that groups Brick types into what are called *Storage Classes*. Each Storage Class has distinct characteristics with regard to performance characteristics of data access. This feature allows an administrator to explicitly manage volume placement within the overall system storage pool, first by Storage Class and then by any of the relative priorities within that Storage Class. Supported Storage Classes in this release are:

- 7.2 K RPM, serial ATA (SATA)
- 15 K RPM, Fibre Channel
- Single-level cell, solid state drive (SLC SSD)

All Storage Classes now support all Quality of Service Priority settings, from archive to premium.

- Native remote asynchronous replication is now available as a licensed feature for Axiom 500 and Axiom 600 SAN systems. Replication configuration and control is provided through scripting on the following hosts:
 - Linux (Enterprise versions 4 and 5)
 - Windows (Vista, XP, Windows Server 2003, and Windows Server 2008)
- Native remote asynchronous replication is now available as a licensed feature for all Axiom NAS systems. Replication configuration and control is provided through scripting on the following hosts:
 - Linux (Enterprise versions 4 and 5)
 - Windows (Windows 7, XP, Windows Server 2003, and Windows Server 2008)
 - Solaris 10
- NAS filesystems now support the use of default quotas for users and groups, allowing administrators to easily set the same quota (in terms of hard and soft limits) for many users and many groups, new and old. (Specific quotas that already exist are maintained.)

- Background copy and data migration priority settings are now selectable. Administrators can now choose the optimum setting on a volume-by-volume basis to balance the impact on overall system performance with the speed of the copy or data migration operation.
- This release allows the operating modes of the Pilot management interface to be configured through the GUI. Auto-negotiation and the speed of the management interface are now directly configurable.
- Pillar Axiom systems now support all Storage Management Initiative Specification (SMI-S) version 1.3 profiles. This release of SMI support conforms to the SNIA CTP test for version 1.3.
- Axiom system software has been enhanced to accommodate upcoming hardware changes.

Tip: For optimal performance with the 4.1 release of the Pillar Axiom software, we recommend that APM clients use round-robin access from the host. Doing so ensures that all ports and Pillar Axiom CPUs are fully utilized.

2.2 Changes to How the Axiom System Operates in This Release

2.2.1 Capacity Utilization Across Brick Types (Storage Classes)

In software releases prior to release 4.1, on an Axiom system containing a mix of SATA and Fibre Channel (FC) Bricks, it was possible for individual logical volumes to utilize space from both the SATA and FC storage pools. Beginning with release 4.1, administrators can no longer *create* volumes that span Storage Classes. Legacy volumes created prior to release 4.1 that span Storage Classes, however, can continue to exist in the system after updating to release 4.1.

Important! Beginning with release 4.1, administrators cannot grow these legacy volumes (or in-fill a thinly-provisioned volume) that spans multiple Storage Classes unless available capacity exists for doing so in the Storage Class on which the volume was originally created.

Also, beginning with release 4.1, if legacy volumes that span the SATA and FC Storage Classes exist, the available capacity shown in the management interfaces (the GUI and the CLI) will be reported differently. These interfaces now report the capacity that is available by Storage Class, which is more accurate.

The system-wide available capacity, however, continues to be reported in the same manner as it was reported in earlier releases.

2.2.2 Get Storage Configuration CLI Command

Starting with release 4.1, the CLI uses a new command `GetStorageConfig` rather than `GetStorageConfigDetails` (which is no longer supported) to query for the system capacities. For `GetStorageConfig`, the total system capacity is reported just as before. However, instead of reporting capacity on the basis of performance bands, the system now reports capacity on the basis of Storage Classes.

2.2.3 SecureWORMfs Daily Scan

In software releases prior to release 3.3.26, the Daily Protection Scan feature scanned all protected files on the WORM filesystem on a daily basis. Starting with release 3.3.33, however, the Daily Protection Scan feature has been removed. The following mechanisms take the place of the Daily Protection Scan feature:

- For CIFS connections, the system automatically protects files in this way:
 - Files under 10 MB in size are protected immediately, in-line.
 - Files 10 MB in size or larger are protected near in-line, but without holding up the client.
- For NFS connections, you can edit the Immutable field in the appropriate XML file in the `.attributes` directory that is located within the WORM filesystem.

2.2.4 Triple Redundancy

Beginning with release 3.0, the Pillar Axiom system dropped the Triple Redundancy Quality of Service (QoS) option for *new* volumes (see also Section 0). Using double redundancy in a Pooled RAID 10 array, however, effectively provides quadruple redundancy, if that is desired.

Important! Systems having existing triple redundancy logical volumes cannot be upgraded to release 4.1. Please contact the Pillar World Wide Customer Support Center for assistance in migration.

2.2.5 Back-Up-to-Disk Feature

Full-block backups (Volume Backup) of logical volumes (filesystems and LUNs) are no longer supported in the AxiomONE Storage Services Manager (GUI) or in the Command Line Interface (CLI). As such, administrators need to be aware of the following when updating a pre-3.0 Axiom system to release 4.1:

- Existing volume backups will automatically activate and become full-fledged LUNs and filesystems. If a volume already exists with the same name, the name of the activated backup will contain a numeric suffix to uniquely identify it. LUN backups that are activated will be mapped but not to any specific hosts.
- To create volume backups, use the new backup-to-disk feature: Clone FS and Clone LUN, both of which allow for the creation of inactive clones.

In release 4.1, the functional equivalent of volume backups is inactive Clone FSs and inactive Clone LUNs (formerly referred to as *Snap LUNs*). These inactive objects have the same structure and behavior as their active clone counterparts, the difference being that inactive clones cannot be made accessible for I/O, while active clones are accessible for I/O.

The main purpose of an inactive clone, like that of its predecessor the volume backup, is archival. In the GUI, an administrator can create clones of either an active or inactive type. The CLI requests for clones (these requests for LUNs still use the term *snap* instead of *clone*) generally can be used to create or manipulate either active or inactive clones.

In release 4.1, as a result of Volume Backup and Copy no longer being supported, the associated Command Line Interface (CLI) requests have been removed from the CLI. (Refer to the current CLI documentation to determine which requests are supported in this release.)

See Section 9.20 for a complete list of the commands that have been removed.

2.3 Available Licenses

Table 1 Feature licenses

Feature	Comments	Pillar Axiom model		
		300	500	600
1 MB Stripe	Automatically included.	•	•	•
Automatic Storage Management (Oracle) performance profile	Automatically included.	•	•	•
AxiomONE Replication	Optional. <ul style="list-style-type: none"> – NAS Slammers require the AxiomONE Replication for NAS license. ^b – SAN Slammers require the AxiomONE Replication for SAN license. ^c (Not available on Axiom 300 systems.) 	•	•	•
AxiomONE Path Manager	SAN Slammer: Automatically included.	•	•	•
CIFS and NFS Protocols	NAS Slammer: One protocol included at no cost.	•	NA	NA
	NAS Slammer: At least one protocol license should be ordered.	NA	•	•
Clone FS	Optional. For Pillar Axiom 300, see “Copy Services bundle” below.	NA	•	•
Clone LUN	Optional. For Pillar Axiom 300, see “Copy Services bundle” below.	NA	•	•
Copy Services bundle	Optional: <ul style="list-style-type: none"> – NAS: Clone FS + Volume Copy / Backup – SAN: Clone LUN + Volume Copy / Backup 	•	NA	•
Fibre Channel Protocol and iSCSI Protocol	SAN Slammer: One protocol included at no cost.	•	•	•

^b AxiomONE Replication for NAS licenses need to be installed on at least one of the Axiom servers hosting a replication pair.

^c AxiomONE Replication for SAN licenses need to be installed on the Primary Axiom server hosting the source volume.

Feature	Comments	Pillar Axiom model		
		300	500	600
NDMP	NAS Slammer: <ul style="list-style-type: none"> – Automatically included for Axiom 500 and Axiom 600 systems. – Must be purchased for Axiom 300 systems. 	•	•	•
Pooled RAID 10	Automatically included.	•	•	•
SecureWORMfs	Optional.	•	•	•
Snap FS	NAS Slammer: Automatically included.	•	•	•
SNMP	Automatically included.	•	•	•
Support Tool	Automatically included.	•	•	•
Thin Provisioning: FS	Optional.	•	•	•
Thin Provisioning: LUN	Optional.	•	•	•
Volume Copy / Backup	Optional.	NA	•	•

The features that you have licensed each have a unique feature key. These feature keys are listed in a separate document^d and are associated with your Pillar Axiom storage system. These keys allow access to the features that you have licensed. Please keep the license key document in a secure place for future reference. For additional information, please contact Pillar Data Systems at 1-877-4PILLAR or go to www.pillardata.com.

2.4 Pillar Axiom Software Update

The 4.1 release may be installed through the GUI Software Update process.

Note: If your Pillar Axiom 500 system contains Fibre Channel Bricks and is running software below release 2.4.2, contact the Pillar World Wide Customer Support Center to update the system.

Tip: If you have existing NAS systems running software earlier than release 3.0, contact your Account Representative to obtain a Thin Provisioning: FS license. Without this license, existing filesystems will continue to be accessible after the software update, and growth will continue to take place, *but newly created* filesystems will not be allowed to grow.

^d Feature keys are listed on the packing slip associated with your product shipment. You can also obtain the keys on the Support portal.

When updating a Pillar Axiom system from release 4.0 to release 4.1, *the data path is not disrupted*.

Important! Updating a Pillar Axiom system to release 4.1 from a release earlier than release 4.0 is disruptive to the data path. Be sure to thoroughly read this entire section before beginning the update process to release 4.1.

If you prefer, you can have Pillar Professional Services update your system software. For more information, refer to Table 4 Contact information.

2.4.1 Prerequisites to Updating Pillar Axiom Software

Because triple-redundancy support is no longer included in release 4.1, all systems running software earlier than 3.3.25 *must first be updated to release 3.3.25 (or a higher 3.3.x version)* and then disruptively updated to release 4.1. This staged update ensures that a triply-redundant logical volume has been automatically migrated to double redundancy and the existence of any user-created triply-redundant volumes will be flagged by means of a Call Home event.

Important! If your system is running software release 4.0.0 or 4.0.1 software, you must first update your system to release 4.0.2, which is non-disruptive to the data path. If your system is running software *earlier* than release 4.0, you must perform the following actions:

1. Update your Axiom system to release 3.3.25 (or higher). When you are ready to update your system to release 3.3.25, be sure to consult Section 2.4 (in particular Section 2.4.2.2) in the Release 3.3 Customer Release Notes (part number 4420-00026-2700).
2. After upgrading your system to release 3.3.25 (or higher), your system must be audited. Please contact the Pillar World Wide Customer Support Center for details.

Important! Beginning with release 4.0, the maximum export path size is changed to 1023 UTF-8 bytes and the maximum host name in the export access list to 255 UTF-8 bytes. All exports or hosts with names that exceed these limits will become inaccessible after the update. We strongly recommend that, before you upgrade your system to release 4.1 from release 3.3.25 (or higher 3.3.x version), you ensure that all export and host names do not exceed these limits.

Tip: For *single-Slammer* Pillar Axiom 600 systems, we highly recommend that you provide additional intra-control unit (CU) cabling that takes full advantage of the Opteron CPU in both Slammer controllers. Contact Pillar Worldwide Customer Support Center for assistance in cross cabling the two CUs. If you don't provide this extra cabling, after upgrading to release 4.1, you will receive an Administrator Action reminding you to provide that cabling.

2.4.2 The Release 4.1 Update Process

To update your Pillar Axiom system to release 4.1, you must first perform several additional preliminary steps. When those steps are complete, you can begin the update process.

2.4.2.1 Before Starting the Update

Before you start the non-disruptive software update process to release 4.1, ensure no background processes are running. You can check for running background processes from the system GUI by pressing **Display All Background Processes Running** in the lower right corner of each GUI screen.

It is not necessary to disconnect channel attachments from the Pillar Axiom system.

2.4.2.2 Starting the Update

When you start the update process from release 3.3.25 to release 4.1, the Axiom automatically selects all the check boxes^e, including the Restart System option.

CAUTION! Do not change the automatically selected check-boxes when you begin the update process to release 4.1; otherwise, a potential for data loss exists.

Note: The Restart System check box is unavailable when you are performing a non-disruptive update from release 4.0.2 to 4.1.

Important! Do not initiate any system or storage actions until the update process completes.

2.4.2.3 After the Update

After a successful update, all system components will report Normal in the GUI and user data will be available.

Important! After updating the system software to release 4.1, you cannot reverse the update and downgrade to an earlier release level without explicit action by the Pillar World Wide Customer Support Center.

2.4.3 Using the AxiomONE Replication Feature

If you have purchased licensing for AxiomONE Replication for NAS or SAN, or both, you must use Professional Services to establish a new installation (or migrate from an existing replication solution).

2.4.4 Software Versions for This Release

Software for this release includes the versions listed in the following table. After updating your system, check your software versions in the GUI by going to **Support > Software Modules**.

Table 2 Pillar Axiom Software versions

Software module		Pillar Axiom model	Software version
Pilot OS		All	04.01.00
Pilot Software		All	04.01.00
Slammer PROM		300 and 500 600	03.00.00 04.00.00
Slammer Software		All	04.01.00
Brick Firmware	Version 1 SATA RAID controller	All	07.08.04
Brick SATA2 Firmware	Version 2 SATA RAID controller, including SSD	All	00.08.04
Fibre Channel Brick Firmware		All	00.68.04
Brick Disk Drive Firmware		<i>Version depends on the drive capacity and whether it is the spare or array drive.</i>	

^e When starting the update, Pillar Axiom 300 systems indicate the equivalent Pillar Axiom 500 release on the GUI Software Modules page. Simply click OK and perform the software update. However, if you are not certain, contact the Pillar World Wide Customer Support Center for confirmation.

Note: If your Pillar Axiom system does not have Fibre Channel, SATA, or SSD Bricks installed, the GUI will not display the firmware entry for those Bricks.

Important! Starting with the 2.x releases, the WWN was changed to use a common base World Wide Node Name. When updating a Pillar Axiom system from 1.7.x to 4.1, be prepared for a change in how WWNs are managed. For more information, see Section 9.19 on page 57.

2.5 AxiomONE Path Manager Software

The AxiomONE Path Manager (APM) software provides for the following:

- Automatic data path failover
- Automatic recognition of SAN hosts in the AxiomONE Storage Services Manager.
- Management of the APM driver from within the AxiomONE Storage Services Manager.

The current release of APM for SAN hosts varies by platform, as shown in Table 3.

Table 3 APM support

Operating system	OS release	APM release	Platforms
AIX	5.2	2.1	All platforms
	5.3 6.1	3.0	All platforms
Community Enterprise Operating System (CentOS)	4.5 and 4.6	3.0	32-bit x86, 64-bit x86, Itanium
	4.7	3.1	32-bit x86, 64-bit x86
	4.8	3.2	32-bit x86, 64-bit x86
	5.2	3.0	32-bit x86, 64-bit x86
	5.3	3.1	32-bit x86, 64-bit x86
	5.4	3.2	32-bit x86, 64-bit x86
HP-UX	11i v1 11i v2	2.0	All 64-bit platforms
	11i v3	2.0	All 64-bit platforms
Novell SUSE Linux Enterprise Server (SLES)	9 SP2 and SP3	2.2	32-bit x86, 64-bit x86, Itanium
	10 SP2	3.0	32-bit x86, 64-bit x86
Oracle VM Server for x86	2.2	3.1	All platforms

Oracle Enterprise Linux (OEL)	4 u4	2.2	32-bit x86, 64-bit x86
	4 u5 and u6	3.0	32-bit x86, 64-bit x86
	4.7	3.1	32-bit x86, 64-bit x86
	4.8	3.2	32-bit x86, 64-bit x86
	5.2	3.0	32-bit x86, 64-bit x86
	5.3	3.1	32-bit x86, 64-bit x86
	5.4	3.2	32-bit x86, 64-bit x86
Red Hat Enterprise Linux (RHEL)	3 u7 and u8	2.2	32-bit x86, 64-bit x86, Itanium
	4 u3 and u4	2.2	32-bit x86, 64-bit x86, Itanium
	4 u5 and u6	2.3	POWER
	4 u5 and u6	3.0	32-bit x86, 64-bit x86, Itanium
	4.7	3.1	32-bit x86, 64-bit x86, POWER
	4.8	3.2	32-bit x86, 64-bit x86
	5.0	2.0	32-bit x86, 64-bit x86, Itanium
	5.2	3.0	32-bit x86, 64-bit x86
	5.3	3.1	32-bit x86, 64-bit x86
	5.4	3.2	32-bit x86, 64-bit x86
Solaris	8	01.04.05	SPARC with non-Sun HBAs
	9	01.04.05	SPARC with non-Sun HBAs
	9	2.0	SPARC with Sun HBAs
	10	2.0	SPARC, 64-bit x86
Windows	2000 Server	2.3	All platforms
	Server 2003	3.2	All platforms
	Server 2003 R2		
	Server 2008		
Server 2008 R2			

Tip: For optimal performance with the 4.1 release of the Pillar Axiom software, we recommend that APM clients use round-robin access from the host. Doing so ensures that all ports and Pillar Axiom CPUs are fully utilized.

Note: Unless otherwise explicitly stated in your APM Release Notes, there are no co-requisite relationships between the AxiomONE Path Manager and Pillar Axiom software versions.

For release information, refer to the *AxiomONE Path Manager Installation Guide and Release Notes* for your platform. For the latest information on supported platforms and hardware, see the *Pillar Axiom Support and Interoperability Guide* or ask your Pillar Data Systems representative.

3 Terms and Conditions of Use

All systems are subject to the terms and conditions of the software licensing agreements and relevant copyright, patent, and trademark laws. Refer to those documents for more information.

4 Support

Pillar Data Systems provides various levels of customer service on a contract basis. If you have purchased a service contract from Pillar Data Systems, authorized Pillar Data Systems personnel will perform support and repair according to the terms and conditions of that agreement.

Table 4 Contact information

For help with...	Contact...
Technical Support	U.S. and Canada: 877-4PILLAR (877-474-5527) Europe: +800 PILLAR FS (+800 74 55 27 37) Asia Pacific: +1-408-518-4515 South Africa: +0 800 980 400 Have your system serial number ready. Email: support@pillardata.com Web: support.pillardata.com
<ul style="list-style-type: none"> Implementation assistance System information Enhancement requests 	sales@pillardata.com . USA: 1-877-4PILLAR (1-877-474-5527)—request Sales at the prompt. International: +1 408 503 4200
Documentation improvements and resources	docs@pillardata.com . www.pillardata.com/techdocs —log in with your username and password.

4.1 Supported Hardware Components in a Pillar Axiom System

Pillar Data Systems supports only Pillar-supplied parts for Pillar Axiom storage systems. Hardware that does not conform to Pillar specifications or is not a Pillar-supplied part voids the warranty and may compromise data integrity.

4.2 Access to Pillar Axiom Systems

You manage a Pillar Axiom system by means of the standard user interfaces:

- The AxiomONE Storage Services Manager (GUI)
- The AxiomONE Command Line Interface (CLI)

Remote access by any other means (ssh, telnet, ftp, and others) is not supported and voids the warranty for your Pillar Axiom system. Furthermore, remote access may also compromise integrity of data that is stored on the system.

4.3 Download Software or Firmware Updates

To download software or firmware updates:

1. Point your browser to support.pillardata.com.
2. Enter your username and password.
3. Click **Log In**.
4. In the left navigation pane, click **Software Downloads**.
5. Click the platform or software category in which you are interested.
6. Navigate to and click on the software package you want.
Download details for that software appears in the bottom of the display.
7. Click the green arrow icon or the **Click here to download SW** link.

Note: To obtain a license to enable a feature that is in addition to those that you initially purchased, contact a Pillar sales representative. (See Table 4 Contact information.)

4.4 Configuration Documentation

For information on the connectivity and interoperability of Pillar Axiom systems with various third-party software and hardware, see your Pillar Account Representative.

For detailed configuration guidelines in a CIFS environment, see the *Pillar Axiom Windows Integration Guide for NAS Systems*.

For detailed configuration guidelines in an iSCSI environment, see the *Pillar Axiom iSCSI Integration Guide for SAN Systems*.

For information regarding the primary features of a Pillar Axiom storage system and how to configure them:

- Navigate through the AxiomONE Storage Services Manager GUI.
- Read the *Administrator's Guide* PDF.
- Read the online help in the AxiomONE Storage Services Manager GUI.

The above documents are available on the **Support > Documents** page in the GUI and on the Pillar Data Systems Web portal at www.pillardata.com/techdocs/.

5 Pillar Axiom System Limits

This version of the Pillar Axiom storage system operates within the supported limits listed below.

Important! Use care when operating a system that has been configured to run at or near the system operating limits. The system may exhibit anomalies when all limits are exercised concurrently. Also, the time to start Pillar Axiom systems from a powered-off or shutdown state and the responsiveness of the GUI are extended under the following conditions:

- You configure a system near one or more of its limits.
- You increase the number of customer-defined system objects—File Servers, filesystems, LUNs, shares, exports, snapshots, and so on.

Consult with Pillar Professional Services to plan your Pillar Axiom system configuration prior to actual installation and configuration.

5.1 Pillar Axiom System Operating Limits

For detailed information on system limits, refer to the online help or to the *Administrator's Guide* PDF file (search for *Ranges for Field Definitions*).

Table 5 Operating limits for Pillar Axiom NAS systems

Item	Description and range
File Servers ^{f, g}	Maximum = <ul style="list-style-type: none"> • 4 for each Pillar Axiom 300 Slammer • 8 for each Pillar Axiom 500 or 600 Slammer
VIFs for each File Server	Minimum = 1 Maximum = 16
VIFs for each Slammer port	Maximum = 16 (any of which may belong to any File Server)
VLANs for each File Server	Minimum = 0 Maximum = 32
Static and default network routes for each File Server	Minimum = 0 Maximum = 8 default, 16 static
Static and default network routes for each File Server	Minimum = 0 Maximum = 8 default, 16 static
NIS alternative file size	Up to 50 MB

^f The virtual interfaces (VIFs) of a File Server can be configured on multiple Slammer control units (CUs). The presence of VIFs is what counts against the above limit. Such a File Server is considered to be present on each Slammer on which it has VIFs. Pillar recommends, however, that multiple File Servers be defined across a collection of Slammer CUs rather than spreading a single File Server across those CUs.

^g VLAN tagging does not need to be enabled for more than one File Server. Also, as of release 3.0, File Servers no longer require a unique VLAN tag.

Item	Description and range
Volume groups	From 1 to 5000, out to four levels
Filesystems	Minimum = 1 Maximum ^h = 1024
Filesystem size	Minimum: 1 to 2 GB. The exact value depends on these factors <ul style="list-style-type: none"> • Brick type (Fibre Channel or SATA) • RAID geometry (RAID 5 or Pooled RAID 10) • Strip size (1 MB or normal) Maximum ⁱ = system capacity
Directory quotas	Unlimited
Snap FSs	Maximum = <ul style="list-style-type: none"> • 250 for each filesystem • 16,000 for each Pillar Axiom system
Clone FSs (partial block snapshots)	Maximum ^j = 4095 for each Pillar Axiom system
Replication targets	Maximum = 5 for each replicated filesystem
Concurrent NDMP sessions	Maximum = 10 for a given system
NFS exports	Maximum = 1000 for each File Server
NFS host entries	Maximum = 4000 for each File Server
CIFS shares	Maximum = 128 for each File Server
User security groups	Maximum = 1024 for each CIFS user
CIFS connections ^k	Maximum for each Slammer (combined memory for both control units): <ul style="list-style-type: none"> • 400 for 6 GB combined memory (Pillar Axiom 300 systems only) • 1200 for 12 GB combined memory (Pillar Axiom 500/600 systems only) • 6000 for 24 GB combined memory (Pillar Axiom 500/600 systems only) • 12000 for 48 GB combined memory (Pillar Axiom 600 systems only)

^h Filesystem maximum limit applies to both the system and to a NAS Slammer.

ⁱ Maximum capacity is *unlimited* for a logical volume if the Thin Provisioning license is installed.

^j The 4095 maximum is the maximum number of VLUNs supported in a Pillar Axiom system. VLUN structures underlie all filesystems, LUNs, Clone FSs, and Clone LUNs. This 4095 maximum covers all four volume types, in total.

^k The maximum number of CIFS connections supported in failover mode is the same as the number supported on a single CU, which is ½ of the maximum for the entire Slammer. However, for 24 GB and 48 GB Slammers, Pillar highly recommends a maximum of 2400 CIFS connections (1200 for each CU).

Table 6 Operating limits for Pillar Axiom SAN systems

Item	Description and range
SAN LUNs	Maximum ^l = <ul style="list-style-type: none"> • 4095 visible for each system • 256 visible for each host • 4095 visible for each SAN Slammer
SAN LUN size	Minimum: 1 to 2 GB. The exact value depends on these factors <ul style="list-style-type: none"> • Brick type (Fibre Channel or SATA) • RAID geometry (RAID 5 or Pooled RAID 10) • Strip size (1 MB or normal) Maximum ^m = system capacity
Volume Copies (full block snapshots)	Maximum = <ul style="list-style-type: none"> • 1024 for each Pillar Axiom system • 12 active for each LUN
Replication pairs	Maximum ⁿ = 16 for each Pillar Axiom system
Clone LUNs (partial block snapshots)	Maximum ^o = number of unallocated SAN LUNs, up to 4095
iSCSI	Maximum = <ul style="list-style-type: none"> • 256 TCP connections for each iSCSI port • 256 iSCSI Initiators for each iSCSI port • 32 persistent reservation registration keys for each LUN • 512 simultaneous commands for each iSCSI port

^l See footnote *j* on the previous page for more information regarding this maximum.

^m See footnote *i* on the previous page for more information regarding this capacity maximum.

ⁿ Pillar highly recommends for release 4.1 that no more than 8 replication pairs be created on each Axiom system.

^o See footnote *j* on the previous page for more information regarding this maximum.

5.2 Slammer and Brick Configuration Limits

The minimum and maximum configurations for Pillar Axiom 500 and 600 systems are summarized in the following table:^P

Table 7 Brick configuration limits

Number of Slammers	Minimum number of Bricks		Maximum number of strings	Maximum number of Bricks
	Supported	Recommended		
1 ^q	2	3	4	32
2	4	All NAS or all SAN Slammers = 5 NAS / SAN combo Slammers = 6	8	64
3	6	8	8	64
4	8	8	16	64

Note: The maximum number of Brick storage enclosures in any string is 8.

The first two Bricks in all Pillar Axiom 500 and 600 configurations must be of the same type and capacity.

For Fibre Channel (FC) Bricks:

- FC Bricks normally come in pairs of one FC RAID Brick plus one FC Expansion Brick of the same capacity. FC RAID Bricks however can be installed without an Expansion Brick.
- Single-Slammer Pillar Axiom 500 and 600 systems have a limit of 16 FC Bricks. Multi-Slammer systems can have up to 32 FC Bricks.
- SATA hard disk drives (HDDs), solid-state drives (SSDs), and FC Bricks may co-exist in the same Brick string subject to current configuration recommendations.
- A given Brick string can contain up to four FC Bricks (RAID or Expansion). Maximum number of FC Expansion Bricks in any string, however, is two.

For a complete list of the rules for configuring FC, SATA, and SSD Bricks, see the appropriate *SSF Cabling Reference* for your Pillar Axiom system.

^P The minimum configuration for Pillar Axiom 300 systems is one Slammer and one Brick (SATA or FC). The maximum number of Bricks in Axiom 300 systems is four.

^q For single-Slammer Axiom 500 and 600 configurations, the minimum number of Bricks is two of the same type. However, for mixed configurations, the minimum number of Bricks is three, as outlined below:

- For a mix of FC and SATA (or SSD) Bricks: 2 SATA (or SSD) + 1 FC or 2 FC + 1 SATA (or SSD).
- For a mix of SSD and SATA Bricks: 2 SATA + 1 SSD or 2 SSD + 1 SATA.

6 System Requirements

6.1 Using Browsers on Windows XP Operating Systems

When using Microsoft Windows XP, set the Windows Desktop appearance to something other than the default XP theme to ensure that lines and boxes are displayed correctly.

Important! If you use the default theme, some controls (such as radio buttons) will appear as though they were not there.

Configure the browser:

- Set security to medium-low (or lower) to enable the security certificate.
- Enable image support (if not enabled).
- Enable JavaScript.
- For Microsoft Internet Explorer, disable the Script Debugger.
- Set the displayed text size to the smallest comfortable viewing size.

When logging into the AxiomONE Storage Services Manager using Secure HTTP, you may see warnings that the server certificate is not issued by a trusted authority. The server certificate is installed and signed by Pillar Data Systems during the manufacturing process.

6.2 Network Requirements

6.2.1 Pilot Network Requirements

The Pilot management controller requires:

- Two 100 BaseT ports for the public connection to the management network. For added redundancy, the two connections should be to separate switches. The Pillar Axiom system provides a standard Cat 5 RJ-45 jack on each Pilot control unit (CU) for this connection.
- Three IP addresses on the same subnet: one IP for each physical interface and one shared IP.

Note: VLAN tagging is not supported on the management interfaces.

The AxiomONE Path Manager communicates with the Pilot over secure, encrypted XML. If the Path Manager is installed on a SAN host, that host will require an Ethernet interface for communication with the AxiomONE Storage Services Manager. The network configuration must allow the SAN host to reach the Pilot management IP Ethernet interfaces.

6.2.2 Slammer Network Requirements

NAS data paths require gigabit Ethernet connections. Both fiber and copper are supported.

SAN data paths require 1 Gb/s, 2 Gb/s, or 4 Gb/s Fibre Channel (optical) connections, which can be single or multi-mode.

The type of connection should be specified when ordering your Pillar Axiom system. Contact your Account Representative if you need to change the type of physical connection for either Gigabit or Fibre Channel.

6.3 NDMP Requirements

For a list of data management applications (DMAs) that Pillar Axiom systems support, see the latest *Pillar Axiom Support and Interoperability Guide*.

6.3.1 File Server

The NDMP subsystem uses the networking configuration from a single File Server, which can be selected by means of the AxiomONE Storage Services Manager (GUI). Currently, a File Server must be set in the NDMP configuration portion of the GUI.

6.3.2 NDMP Command Interface

The NDMP command and response interface on a Pillar Axiom system is the Pilot management interface. Data movement is performed over the data path interfaces on the Slammer storage controllers. Be sure that any external NDMP backup servers are able to reach the Pilot management IP addresses.

6.3.3 Virtual Interface (VIF)

Only one VIF is required. For local backups, the networking configuration must be on the Slammer control unit (CU) to which the tapes are attached. The tape menu in the GUI lists the CU as a control unit number.

There are two ways to ensure there is networking on the CU with tapes:

- The first method is to create the File Server on the CU with tapes (or alternatively move it once it has been created).
- The second method is to create a second VIF on the CU to which the tapes are attached.

Note: The File Server used must be the File Server listed in the NDMP configuration.

6.3.4 Fibre Channel (FC) Tape Library LUNs

Even though the AxiomONE Storage Services Manager (GUI) allows you to configure tape library LUNs from 0 to 255, the FC tape driver only supports eight (0-7). To avoid difficulties, don't define library LUNs above number 7.

6.4 Power-Off Requirements

If you need to turn off the system, use the Shutdown capability in the GUI. Because of the redundant architecture, you may not turn off the system by switching off components (including the power distribution units).

Note: If you will be powering down the system for more than a day, remove the Slammer batteries so they do not discharge.

6.5 Power Cycling

Contact the Pillar World Wide Customer Support Center before power cycling a Pillar Axiom system except in the event of an emergency, in which case, drop all power and then contact the Support Center. Contact the Support Center before touching any power cables or switches. There are some situations where *not* power cycling the entire system is the correct action.

For *failure* testing, do not power cycle individual components without first contacting the Pillar World Wide Customer Support Center.

7 Known Issues

The Pillar Axiom server issues listed in Table 8 are known at the time of this release. They are planned for resolution in upcoming releases. When available, Pillar Data Systems will provide updated software or hardware.

For additional information or help on any of the issues below, please contact your Pillar Data Systems authorized representative (see Table 4 Contact information).

Table 8 Known Pillar Axiom server issues

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
All	In rare cases, the core dump may be unavailable after the Slammer warmstarts.	This issue will be fixed in a future release.
	When deleting an extremely large LUN or filesystem, the Brick takes a large amount of time to complete the transition of the related storage from allocated to unallocated. During this time, the Brick is temporarily inaccessible until the operation completes.	Contact the Pillar World Wide Customer Support Center for assistance. This issue will be fixed in a future release.
	When a Brick experiences a read error on two drives in the same stripe or a read error during a RAID array rebuild, the data for the associated stripe is lost and a Bad Block Log entry is created to track the bad stripe. If any reads are sent to this stripe, they are rejected with an error. If the stripe is written, the Bad Block Log entry will be cleared.	Contact the Pillar World Wide Customer Support Center for assistance. This issue will be fixed in a future release.
	PIM replacement, which includes powering off and powering on of the parent Slammer control unit (CU), may cause NonOptimizedAccess events for APM.	This issue will be fixed in a future release.
	Relevant Brick logs might not be automatically collected for Call Home when a fault event for a RAID controller occurs.	This issue will be fixed in a future release.
	Following an upgrade from release 3.1 to 3.3, a filesystem that was offline (due to a defect in geomap startup) failed to come online following the upgrade that was intended to correct the original offline failure.	A warm start of the Slammer control unit or a restart of the Pillar Axiom system will clear the condition. This issue will be fixed in a future release.

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
	<p>The system may mis-detect tape devices after a warmstart or restart. If the tape device returns an error, the Pillar Axiom tape driver may not retry the error correctly.</p>	<p>Rescan for the tape devices using the CLI or the GUI.</p> <p>This issue will be fixed in a future release.</p>
	<p>The Pilot uses a version of OpenSSH (OpenBSD Secure Shell) that has several known vulnerabilities.</p>	<p>Although there is no workaround, Pillar Axiom systems have numerous security features that make it unlikely anyone could break in. <i>(See Section 9.91 for more information.)</i></p> <p>An upgrade to the latest release of OpenSSH will be available in a future release.</p>
	<p>If a system software update is initiated while Pilot tasks are in progress (such as a SecureWORMfs scan, automatic Call Home, and log collection), the update will not begin and no information is provided that the update is waiting for the tasks to complete.</p>	<ul style="list-style-type: none"> • Schedule updates when it is known that long-running tasks will not be running. • Before starting a software update, be sure all tasks are complete (or, if desired, cancel them). <p>This issue will be fixed in a future release.</p>
	<p>When a Brick RAID controller is removed during Guided Maintenance, the remaining controller may send a “RAID Controller Fault” event to the host in addition to the “RAID Controller Removed” event.</p>	<p>This issue will be fixed in a future release.</p>
	<p>On rare occasions when upgrading system software, the firmware upgrade in a Brick RAID controller can fail to complete, which causes the system upgrade to fail.</p>	<p>Replace the RAID controller that has failed the firmware upgrade. Then restart the system software upgrade.</p> <p>This issue will be fixed in a future release.</p>
	<p>In rare situations, when a SATA RAID controller is failing and a drive in the same Brick is taking a very long time to execute commands, a RAID controller reset may take the whole Brick offline.</p>	<p>Address the RAID controller failure and the drive issue separately.</p> <p>This issue will be fixed in a future release.</p>

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
	Call Home transfers by means of an HTTPS proxy server may be reported as successful on the Pillar Axiom system when in fact the Call Home log bundle has not been received by Pillar.	Verify whether the system serial number of the Axiom system is properly registered with the Pillar Call Home server so the proxy server can login and send Call Home log bundles. This issue will be fixed in a future release.
	When an untagged Slammer port is connected to a CISCO switch that is configured to accept tagged packets, the switch drops all received packets. However, the Slammer does not report the connection problem. The Slammer simply reports that the port is Normal. Also, the port does not fail over.	Change the configuration of the CISCO switch to accept untagged packets. This issue will be fixed in a future release.
	In rare cases, the system status (exhibited for example on the Health page or in Administrator Actions) may not be entirely accurate.	Depends on the component. Contact the Pillar World Wide Customer Support Center. This issue will be fixed in a future release.
	SNMP clients receive events from the Pillar Axiom system using the specific IP address assigned to each individual active Pilot rather than the public IP address associated with the system.	The SNMP client should accept events coming from the static IP address of the active Pilot. This issue will be fixed in a future release.
	Pillar Axiom systems do not support the use of Windows 2003 SP1 or higher as the NTP server for the system.	For an explanation of how to provide a stable NTP for both Windows and Unix environments, refer to Microsoft TechNet article " Appendix H: Configuring Time Services for a Heterogeneous UNIX and Windows Environment " (http://technet.microsoft.com/en-us/library/bb463171.aspx). The Meinberg NTP server is a software product that can be installed on a Windows platform to provide NTP services for a Pillar Axiom system. This issue will be fixed in a future release.
	Trying to modify any characteristic of a scheduled software update can lead to the system error: Cannot add fully qualified name (FQN) to table because the name already exists Enter a different FQN.	Delete the scheduled update you wish to change and create a new one with the desired characteristics. This issue will be fixed in a future release.

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
	<p>If a drive is performing marginally, the system does not notify the storage administrator until the error-rate becomes high enough that the drive is taken offline. At that point, the spare drive is used automatically.</p>	<p>This issue will be fixed in a future release.</p>
	<p>The <code>GetStorageConfigDetails</code> PDSCLI command returns raw capacities based on a RAID 5 geometry. This does not account for capacity requirements when using Pooled RAID 10.</p>	<p>Note: In release 4.1, this command has been replaced by <code>GetStorageConfig</code>.</p> <p>When using the PDSCLI command <code>GetStorageConfigDetails</code> on a Pooled RAID 10 system, divide the listed capacities by 2 to get the actual capacity.</p> <p>In release 4.1, reported capacities are raw. For RAID 5 (SATA or SSD) volumes, use a factor of 5/6. For RAID 5 (FC) volumes, use a factor of 10/11.</p> <p>This issue will be fixed in a future release.</p>
	<p>When changing the Pilot management IP from static to DHCP in the GUI, the change does not get committed.</p>	<p>Run the CLI command <code>ModifyManagementConfig</code> with <code>DHCPEnabled</code> set to true and the <code>pilot1</code> and <code>pilot2 IPAddress</code> fields set with proper static values.</p> <p>This issue will be fixed in a future release.</p>
<p>NAS</p>	<p>On rare occasions, a NAS replication target filesystem can become corrupted when running multiple replications on the same replication pair at the same time.</p>	<p>Issue a <code>set_live</code> command on the target filesystem. When that command successfully completes, re-establish the replication pair to allow further incremental synchronization operations.</p> <p>To avoid this issue, avoid scheduling replications in short intervals so the previous replication can complete before the next scheduled replication begins.</p> <p>This issue will be fixed in a future release.</p>
	<p>The user filename parameters of the <code>axiomcli</code> or <code>pdscli</code> requests for uploading NIS files can only be filenames. If they are pathnames to the files, the requests will fail.</p>	<p>Place the files in the same directory where the upload script is located. Then, use only the file names to identify the files to be uploaded.</p> <p>This issue will be fixed in a future release.</p>

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
	When you move a subdirectory to a different parent directory and then delete the former parent, if you then create a new file (fileX) somewhere and create a hard link (hdlinkK) to that file from the above subdirectory, attempting to move another file into that subdirectory results in an error.	Remove fileX and then remove hdlinkK. Then move the file into the subdirectory. This issue will be fixed in a future release.
	When the I/O from the backend is slow, some filesystems can run out of journal space in the battery-backed memory, causing these filesystems to switch to a disk-based journal. However, when the issue is resolved, the filesystem fails to switch back to the normal mode of using the memory-based journal.	When you observe that the filesystem is in conservative mode, contact the Pillar World Wide Customer Support Center for assistance. This issue will be fixed in a future release.
	Issuing a <code>discover</code> command on a NAS replication pair may cause a currently running synchronization operation to fail.	Avoid running the <code>discover</code> command on a replication pair in this situation. Instead, monitor the output from the <code>sync</code> command. Resubmit the <code>sync</code> command, which will cause synchronization to restart from the point of failure. This issue will be fixed in a future release.
	When more than 1023 customer filesystems are created, the Slammer is not able to successfully handle failover, which results in both control units being disabled.	To recover from this condition, re-enable both Slammer control units and restart the system. After the system restarts, delete one of the filesystems. This issue will be fixed in a future release.
	Under certain conditions, when the amount of resources required to maintain a large number of open files (e.g., 1200 files) or a number of files that have path names of 100 or more characters, plus the resources for the other activity on the connection cause an internal threshold to be exceeded, Kerberos authentication requests or file open requests may be denied. In some case, the Slammer control unit may warmstart.	In these scenarios, each user should use a separate connection by running one user or application per Windows client (or per virtual client with a different IP address). Contact Pillar World Wide Customer Support Center if you need additional help. This issue will be fixed in a future release.
	Cannot delete a directory quota on a non-empty directory while the filesystem is online.	To delete a directory quota on a non-empty directory, first take the filesystem offline. This issue will be fixed in a future release.

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
	If a filesystem is renamed while it is offline because of corruption, sometimes the system might erroneously put the filesystem online. In this case, the filesystem will go offline again when the system detects the corruption.	Avoid renaming a corrupted filesystem. This issue will be fixed in a future release.
	Sometimes the event for "Quota hard limit" may not be generated. Though the event is not generated, the hard limit is honored.	This issue will be fixed in a future release.
	When CREATOR_OWNER role is expanded, the newly created ACL entry (ACE) does not appear as inherited.	This issue will be fixed in a future release.
	When a filesystem is corrupt, an attempt to create clone space for this filesystem will fail, generating a Failed ModifyFileSystemTask Administrator Action.	Contact the Pillar World Wide Customer Support Center for help in cloning the filesystem. This issue will be fixed in a future release.
	If there are many disabled server entries listed in the DNS, the Pillar Axiom system may fail to join the domain due to no response from them and a time out (250 seconds).	Remove the disabled Domain Controllers from the domain. This issue will be fixed in a future release.
	When a Pillar Axiom system undergoes warmstart recovery or upgrade, the underlying I/O subsystem may become congested. If the congestion lasts more than five minutes, the filesystem may go offline and have to be manually brought online.	Contact the Pillar World Wide Customer Support Center. This issue will be fixed in a future release.
	When doing directory listings using OpenDir API, the directory entries may not always fit into the system memory because of its size. In the case where the memory size did not fit with the directory listing, the operation may fail.	This issue will be fixed in a future release.
	The filesystem statistic <code>ReadMBPerSecond</code> is always 0 in the output of the <code>GetFileSystemDetails</code> CLI command. The "Current MB per second" filesystem statistic in the following GUI page is also affected: Health > Performance > Filesystem > (specific filesystem statistics).	This issue will be fixed in a future release.

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
	When using InMage for replication with a Pillar Axiom system as the target, the file attributes have the HIDDEN attributes set.	Use the option in InMage that makes explicit "Copy the contents of the source directory into the target directory". This issue will be fixed in a future release.
	A filesystem that cannot flush its journal to disk generates a pinned data condition. When a filesystem that is being deleted has a pinned data condition, the system automatically discards the pinned data. This results in a BBM (battery-backed memory) lost event.	This event is harmless. Because the filesystem is being deleted, there is no <i>unintended</i> data loss. This issue will be fixed in a future release.
	When the DNS server is slow and multiple local Domain Controllers are down, the Pillar Axiom system may not be able to join the domain using a remote Domain Controller if the time remaining allowed to join the domain expires.	Ensure the DNS server points to functional and working local Domain Controllers. This issue will be fixed in a future release.
	Sometimes, when a system is under heavy I/O loads, the system may slow and Slammers may begin to warmstart because of I/O timeouts. Also, under these conditions, a filesystem may show a Conservative status.	This condition is usually transient. The system should automatically resume to a normal performance mode when the I/O congestion clears up. If, after five minutes, the condition does not clear, warmstart the control unit that owns the filesystem. This issue will be fixed in a future release.
	While a SecureWORMfs scan is in progress, operations on that WORM filesystem (such as cloning) that require the filesystem to be quiesced may cancel the scan.	Wait for the scan to complete before performing those operations, or restart the scan. This issue will be fixed in a future release.
	Events are logged when a <i>user-initiated</i> daily protection scan of a SecureWORMfs filesystem completes but not when a <i>scheduled</i> daily protection scan completes.	This issue will be fixed in a future release
	A Pillar Axiom system may have trouble joining a CIFS domain when one or more of the CIFS domain controllers are offline.	Join the domain when all of the domain controllers are available. This issue will be fixed in a future release.

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
	<p>When using Computer Management or Microsoft Management Console to change the owner of a share, if the user selects the option to "Replace owner on subcontainers and objects", the request fails.</p>	<p>Change the ownership in this way:</p> <ol style="list-style-type: none"> i. Change the owner of the share, without the "Replace owner on subcontainers and objects" option. ii. Repeat the step to change the owner of the share (to the same owner) but this time, do select the "Replace owner on subcontainers and objects" option. <p>This issue will be fixed in a future release.</p>
	<p>The TCP/IP statistics GUI page under Health > Performance > NAS Protocols always shows link aggregation (LA) status as disabled, even when LA is properly configured.</p>	<p>Use the System > Networking page to verify LA status.</p> <p>This issue will be fixed in a future release.</p>
	<p>If both control units (CUs) in a NAS Slammer are failed over and the system is already running with another NAS Slammer, you cannot fail back the CUs in the failed over NAS Slammer.</p>	<p>Place the system in shutdown mode and restart the system.</p> <p>This issue will be fixed in a future release.</p>
	<p>A filesystem may switch from battery-backed journaling mode to conservative mode if it runs out of battery-backed memory (BBM) journals. This may happen when existing in-use journals cannot be flushed out in time, which can be indicative of a heavy load, a sluggish backend, or a code defect that causes a journal leak. Once the filesystem has switched to conservative mode, it stays in that mode until the Slammer control unit warmstarts.</p>	<p>This issue will be fixed in a future release.</p>
	<p>If memory consumption approaches the limit (around 400 KB) on a particular CIFS connection, individual CIFS requests on that connection will fail. In rare conditions, the Slammer control unit may drop a CIFS connection and possibly warmstart.</p>	<p>This issue will be fixed in a future release.</p>
	<p>Joining a domain may not succeed if TCP traffic to port 464 is blocked. Port 464 is used by the KPASSWD protocol to set the domain account password for a domain client. The KPASSWD protocol supports both UDP and TCP. However, a Pillar Axiom system fails the operation if the TCP port is blocked.</p>	<p>Unblock port 464 for TCP network traffic. Ensure that the domain controller and all routers in the path have port 464 unblocked for TCP traffic.</p> <p>This issue will be fixed in a future release.</p>

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
	If a Slammer warmstarts after a request to create a Snap FS has been issued, in very rare circumstances the request may fail.	Reissue the Snap FS request. This issue will be fixed in a future release.
	Under some circumstances, an opportunistic lock (OpLock) is not released on a file. This causes a software fault when another lock request is made.	This issue will be fixed in a future release.
	Under certain conditions, the Pillar Axiom system will fail to recognize user credentials, such as when a client requests to map a drive. Such requests will be rejected.	Contact the Pillar World Wide Customer Support Center for assistance. This issue will be fixed in a future release.
	Under certain conditions, when a CIFS client writes data to the Pillar Axiom system, the write might fail, the CIFS connection is terminated, and the log contains this record: Got EBADF error, terminating CIFS connection	Contact the Pillar World Wide Customer Support Center for assistance. This issue will be fixed in a future release.
	If the TCP ports for LDAP services on a Domain Controller are blocked, a request by a File Server to join the domain will fail.	Port blocking and failover from TCP to UDP when TCP is blocked applies to Kerberos and kpasswd but not to LDAP. The domain controller should not block any port for LDAP services. This issue will be fixed in a future release.
	Mounting a filesystem on a secondary virtual interface (VIF) will fail if the connection uses UDP through a firewall.	Use TCP. If UDP must be used, limit the VIFs for the File Server to one. This issue will be fixed in a future release.
	Un-checking the "Require Authentication" option on the File Server CIFS tab in the GUI does not allow a client with an anonymous connection to the File Server to obtain a list of shares with either "net view" or "net use".	Leave the "Require Authentication" option checked. This issue will be fixed in a future release.
	Because of a network issue, the request from the Pillar Axiom system to the Windows Domain Controller, DNS server, or WINS generated no response, eventually causing the system to fail a health check after the health check timed out.	Check the network and Domain Controller if this happens repeatedly. This issue will be fixed in a future release.

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
	<p>When using a device with less than 1 Gbps link speed to connect to a NAS Slammer, the I/O Port Details screen will indicate 0 Gbps for the Negotiated Link Speed.</p>	<p>Use the Filesystems or TCP/IP statistics pages to view the actual speed in Mbps. This issue will be fixed in a future release.</p>
	<p>When there is high volume CIFS traffic and multiple accesses to the same file with opportunistic lock (OpLock) enabled, the OpLock will not be released in a timely manner leading to a health check timeout.</p>	<p>This issue will be fixed in a future release.</p>
	<p>When both a directory and one of its subdirectories are being shared, restrictive permissions on the top directory may prevent some users from mapping the subdirectory. In particular, if the top directory has permissions that prevent some users from traversing this directory, these users will be unable to use either share.</p>	<p>Allow everyone the right to traverse all directories leading up to any directory that is being shared. Being able to traverse a directory does not imply that these users will be able read or modify the contents of that directory. This issue will be fixed in a future release.</p>
SAN	<p>When the primary and secondary Axiom systems hosting a replication pair are started at the same time, sometimes one or both systems may not complete the restart, which can result in Pilot failover and a significant delay in getting both systems operational.</p>	<p>Start up one Axiom system and then run the <code>start_session</code> command against that system. When that command completes successfully, repeat those two actions for all remaining Axiom systems participating in SAN replication. After all systems have successfully started, run the following command for all replication pairs: <code>start_replication_pair</code> This issue will be fixed in a future release.</p>
	<p>The task to remove a Brick may fail if a system has LUNs that participate in replication pairs, even though all of the volumes that claim to be using that Brick have been deleted.</p>	<p>Stop all replication and delete the replication pairs. Attempt to remove the Brick again. This issue will be fixed in a future release</p>
	<p>On the Identity tab in the GUI, when activating an inactive Clone LUN that was created by SAN Replication, if any other tab is visited before un-checking the Inactive checkbox, the protocol choices for LUN Access are cleared of previous values. Also, an error occurs and the user needs to return to the Identity tab and specify the desired protocols.</p>	<p>Un-check the Inactive checkbox before leaving the Identity tab. This issue will be fixed in a future release.</p>

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
	A defective Fibre Channel network interface module (NIM) may result in a kernel panic and a warmstart of the Slammer control unit.	Replace the defective NIM. This issue will be fixed in a future release.
	For a given host system, only one axmrepsan session can be active for a given unique userid. Attempts to run more than one axmrepsan session for a given userid will fail with unpredictable results.	Have a unique userid for each axmrepsan session. This issue will be fixed in a future release.
	Continual SNMP querying of "cSANHostConfig" causes a slow but steady consumption of Pilot CPU and memory resources, causing degradation in Pilot performance and ultimately Pilot failover.	Avoid SNMP queries for this item, or do so as infrequently as possible. This issue will be fixed in a future release.
	Due to an initial failure, where the maximum number of LUNs were allocated, a secondary warmstart occurred.	This issue will be fixed in a future release.
	On a Linux host, paths may not be restored to an online status after a warmstart or path failure.	Run the Qlogic or Emulex Rescan utility. This issue will be fixed in a future release.
	When using the Capacity Planner to create a very large quantity of LUNs, it fails and the GUI shows an error dialog with no text, just an OK button.	Try creating 20 LUNs at a time. If you want to create more than 20 LUNs, try using a CLI script. This issue will be resolved in a future release.
	Using a software iSCSI initiator when an issue in an ESX server configuration (misconfigured LUN) exists can cause performance issues.	Be sure the ESX server is correctly configured or switch to a hardware iSCSI initiator. This issue will be resolved in a future release.
	Sometimes when mapping a LUN, the mapping fails with error 11202 but, internally, the system makes it appear to the host that the mapping succeeded. The host will see a LUN as that LUN number mapped to it, even though the mapping is not really mapped to the host. Also, the invalid LUN mapping shows on the GUI pages that display mappings.	Restart the system to clear the out-of-sync mapping in the SAN and to re-synchronize the Pillar Axiom system and the SAN. This issue will be resolved in a future release.

Slammer type	Pillar Axiom server issue or impact	Workaround or planned fix
iSCSI	In rare circumstances, iSCSI systems under heavy load or with high numbers of network errors may warmstart.	<p>Try to rebalance the load.</p> <p>If you're getting a large number of network errors, replace the iSCSI network interface module in the Slammer.</p> <p>This issue will be resolved in a future release.</p>
	Modification of iSCSI port settings using the <code>ModifyiSCSIPortDetails</code> CLI request fails if attempted within two minutes of a system restart.	<p>Wait at least 2 minutes after a system restart completes before executing a <code>ModifyiSCSIPortDetails</code> request.</p> <p>This issue will be resolved in a future release.</p>
	On rare occasions, the iSCSI network interface card can hang, which causes the system to warm start.	<p>Replace the iSCSI card, or contact Pillar World Wide Customer Support for assistance.</p> <p>This issue will be fixed in a future release.</p>
	During Windows startup, the iSCSI Software Initiator may attempt to register with the Microsoft iSNS Server v3.0 if it has been configured to do so. If the iSNS Server is installed on the same host and has not started yet, the iSCSI Initiator may fail to register with the server.	<p>Edit the Windows registry to add a dependency that causes the iSCSI Initiator to wait for the iSNS Server to start.</p> <p>This issue will be fixed in a future release.</p>

8 Resolved Issues

A number of issues, some previously undocumented, have been resolved in this release. Items that were documented as known issues in the previous release and are resolved with this release are described below. These items are no longer product issues.

Table 9 Resolved Pillar Axiom server issues

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
4.1	All	<p>During the startup of a Brick enclosure, sometimes an internal fault occurs that causes both RAID controllers to restart.</p>
		<p>On a very heavily loaded system, a potential exists for the mishandling of I/O requests, which results in a Slammer warmstart.</p>
		<p>When any of the following is true, the owning Slammer control unit can sometimes become Disabled:</p> <ul style="list-style-type: none"> • A collection of thinly provisioned volumes exists for which the total capacity actually in-filled approaches 40 TB. • More than 20,000 growth operations have taken place across all volumes in the system. • Any combination of the above (where one volume growth equates to 2 GB of in-fill) exists. <p>The fix increases greatly the number of extents that can be tracked. However, Pillar still highly recommends that Thin Provisioning only be used when only a fraction of a volume will actually need to be accessed over time.</p>
		<p>If a Brick has a drive that goes into copyback mode, available capacity on that Brick may become unavailable temporarily as the system prepares the reconfigured Brick for use. In such a case, one may unexpectedly find that there is inadequate capacity in the system for creating new volumes or doing other operations that require additional capacity.</p>
		<p>In some cases, deleting a clone out of order (relative to when it was created) causes an alert to be sent and the owning Slammer to warmstart.</p> <p>The fix allows any clone to be deleted in any order (though it is faster to delete them in creation order).</p>
		<p>Even though the capacity reported by the user interface appears to indicate that sufficient capacity exists to in-fill a thinly provisioned volume, an attempt to in-fill that volume can result in pinned data, especially in a mixed SATA and FC system.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		<p>The management software requires that version 2 Slammers exist before inquiring about SFP information from version 2 SATA Bricks. When version 1 Slammers exist, the status inquiry reports that the SATA V2 Bricks have invalid SFP states.</p>
		<p>Exhausting the system storage capacity by doing thin-provisioned volume infilling may cause the system to crash.</p>
		<p>In release 4.0, on rare occasions, a timing window can cause a failure in updating the metadata for a system VLUN, which results in the LUN or filesystem failing to come online.</p>
		<p>When an attempt is made to increase the current and maximum capacities of a volume at the same time, and there isn't enough free capacity to honor the request, the maximum capacity is increased but the current capacity is silently left unchanged. This means that a volume which was not sparse, with current = maximum, could become sparse, with current < maximum.</p> <p>The fix only allows both changes to be made, or neither.</p>
		<p>If the firmware on a new Brick being added to a running Axiom system needs to be updated to match the version on the system, the Brick addition could lead to a temporary loss of access to customer data.</p>
		<p>Growing the capacity (usually automatically) of a logical volume thousands of times can cause the system to exceed several internal limits and then to experience multiple panics.</p>
		<p>When a Brick is added to an Axiom system and is then powered up, in rare circumstances the private interconnect (PI) may be disrupted long enough, while the Brick firmware is being updated, to cause a loss of access to both RAID controllers of that Brick.</p>
		<p>When a new Slammer is added to an Axiom system without first shutting down the system and then restarting it after the Slammer is added, the system will panic and the Slammer will failover.</p>
		<p>When continuous power-cycle tests are performed on a Slammer, sometimes a PersistenceFailure Administrator Action is generated and the system restarts.</p>
		<p>When a logical volume is being created or modified, if the background process hangs and then the system is restarted, sometimes the processes are still hanging and the volume may become stuck in the "Configuring" state indefinitely. The volume may not be usable in this case, and it is not possible to modify or delete it.</p>
		<p>When the total of the maximum capacities of all LUNs and filesystems on a Pillar Axiom system exceeds 950 TB, the system will fail.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
	NAS	<p>Sometimes, a condition can arise in which the Pillar Axiom system cannot allocate sufficient memory to complete an I/O operation, causing the Slammer to warmstart. On rare occasions, the warmstart cannot complete, which in turn causes the system to power on with data recovery (PODR).</p> <p>In all releases subsequent to the introduction of FC bricks, topology validation does not correctly identify the Brick at the top of a string that contains Fibre Channel or version 2 SATA Bricks. As a result, the Administrator Action sometimes flags the incorrect Brick or even the incorrect type of violation.</p> <p>The used and total capacity of a volume group were not given correctly in the Call Home session header file, particularly if the volume group contained LUNs (as opposed to filesystems).</p> <p>When creating a logical volume, an attempt to modify the volume before it is fully created might fail with the following error message: Cannot look up globally unique ID (GUID) from fully qualified name (FQN). FQN not in table. Reenter GUID.</p> <p>For Windows 7, the default LAN manager authentication level defaults to NTLM version 2, which is not supported by Pillar Axiom systems. As a result, Windows clients that default to NLTM v2 are not able to authenticate.</p> <p>When creating a share that has the same name as another share on the File Server, the generated error message is unclear. The fix displays an error message that more clearly states that share names must be unique within a File Server</p> <p>When an NFS client attempts to delete a file that the CIFS server has marked as "Delete on Close", NFS does not handle the error gracefully, causing the Slammer to warmstart.</p> <p>The system might respond poorly to Windows clients when wild card searches are performed on very large directories. The fix requires that the Server Comment field in the CIFS server definition contain the following string at the start of the comment: <i>PDS_DIR_TIMEOUT=5</i>. For this fix to take effect, force the Slammer to warmstart.</p> <p>When using the GUI to simultaneously rename a filesystem and to add a share or export, the filesystem gets stuck indefinitely in the Configuring state.</p> <p>When a Slammer control unit (CU) warmstarts while its buddy CU has file locks, the buddy CU sometimes panics and warmstarts.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		<p>Even though every filesystem has its own nsswitch.conf, there is only one table maintained in memory. When there is a change to the nsswitch.conf, the single in-memory table is updated, which allows for conflicts with locks when reads or writes occur at the same time.</p> <p>The fix provides for each server its own nsswitch.conf information in memory.</p>
		<p>For release 4.0, in a lossy or heavy traffic network environment, sometimes network driver buffers are not released in time by the NFS stack resulting in the Slammer warmstarting.</p>
		<p>Health check failures due to delayed or no response from the Kerberos Key Distribution Center (KDC) during authentication can occur as a result of an error while setting up connections between the Axiom system and the domain controllers.</p>
		<p>ildcard search could return wrong results when the number of matching files is relatively small compared with the directory size.</p>
		<p>When the filesystem detects a corrupted block, it may choose to quarantine those blocks to minimize the damage.</p> <p>Pillar recommends not updating to software release 3.3.26. Update to 3.3.33 instead.</p>
		<p>NTLM authentication fails when Windows 2008 R2 domain controllers are used.</p>
		<p>An Axiom system limits the total size of all logs in a Slammer control unit by deleting old logs when the maximum size is exceeded. The large FSCK logs exceeded the maximum size, which caused the Axiom system to delete older Slammer debug logs.</p> <p>The fix reduces unnecessary logging by FSCK.</p>
		<p>When the Pillar Axiom system is under an extreme NFS load, the system may become unresponsive for 10 minutes, leading to control unit warmstarts.</p>
		<p>For Windows 2008, Windows Vista, and Windows 7, the default LAN manager authentication level defaults to NTLM version 2, which is not supported by Pillar Axiom systems. As a result, Windows clients that default to NLTM v2 are not able to map shares, and their account password can be disabled.</p>
		<p>When a large number of filesystems are being accessed under a heavy workload, sometimes the Slammer may warmstart.</p>
		<p>When a CIFS client sets the read-only bit for a file or a directory, an NFS client may still see the file or directory as writable.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		SNMP queries for the value of <code>pFileServerStatisticsCIFSServerMetricsFilesOpen.1</code> is always zero.
		Under a very heavy workload and high number of concurrent CIFS connections, Slammer control units (CUs) may warmstart. This condition is due to the internal system resources being consumed by the high load.
		When running a heavy workload, an internal service used within the Pillar Axiom system sometimes malfunctions resulting in a Slammer warmstart.
		For NFS clients, when the <code>setuid</code> and <code>setgid</code> bits are set on a file, that file executes in a special way. When the owner or group changes, the <code>setuid</code> and <code>setgid</code> bits are not cleared, opening a potential security hole.
		When operating normally, the Pillar Axiom CIFS server contacts various external servers to perform authentication or query operations. Occasionally, an external server may not respond immediately. The CIFS server retries the operation or, if the operation would not complete in a timely manner, fails the operation. Sometimes, the request hangs, resulting in the Slammer warmstarting.
		When copying a filesystem on a single-Slammer system, system performance may decrease.
	SAN	During heavy loads over a non-optimized access path, a system deadlock may occur (because of mutex lock contention) resulting in a system restart.
		When an attempt to increase the capacity of a LUN is made while also attempting to change its Quality of Service (QoS), the change in QoS occurs but not the increase in capacity. The fix increases the capacity of the LUN before changing its QoS.
		When a continuous series of LUN numbers (which includes the maximum of 254) are assigned, the AxiomONE CLI <code>hostmap</code> command erroneously reports that those numbers are available for use.
		Given a SAN Slammer that supports both FC and iSCSI protocols, a change in the protocol for a mapped LUN from one protocol to the other will appear to succeed (from the perspective of the GUI), but the changes are not reflected in the SAN or the client.
		In certain situations, the Pillar Axiom Storage Service Manager (GUI) may not reflect the proper LUN state. Specifically the Normal state of a LUN may be reported as Conservative when it is in fact Normal.
		Certain memory issues in the SAN network interface module (NIM) can interfere with heartbeats between the two Slammer control units (CUs), causing CU failover.

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
4.0	iSCSI	<p>If an APM host uses iSCSI to connect to an Axiom system, and the host uses an iSCSI Initiator Name that is the same as its hostname, the entry for that host in the AxiomONE Storage Services Manager is continually deleted and recreated, disappearing and reappearing intermittently in the GUI.</p> <p>A Pilot restart may result if the CHAP Secret iSCSI password is only entered once in the GUI or pdscli request instead of twice as specified.</p> <p>On 4.0 systems, if a DHCP server is not made available shortly after a system restart, sometimes the iSCSI interface to an Axiom system becomes unresponsive, E.g., no IO is processed and the interface does not respond to ping requests.</p> <p>If an APM host uses iSCSI to connect to a Pillar Axiom system, and it uses an iSCSI Initiator Name which is the same as its host name, then the entry for that host in the AxiomONE Storage Services Manager will be continually deleted and recreated. The host entry will disappear and reappear intermittently in the GUI.</p>
	All	<p>When a Fibre Channel drive becomes unresponsive to I/O, sometimes logical volumes mapped to that drive will go Offline.</p>
	<p>Pillar Axiom system time can become out of sync with Network Time Protocol (NTP) servers, particularly after a Pilot failover.</p>	
	<p>When upgrading SSD drive firmware, the firmware update may fail the first time.</p>	
	<p>When a component takes too much time flushing data from cache, this occasionally prevents the system from shutting down successfully.</p>	
	<p>Under certain conditions, a PIM component can log out a Fibre Channel port without notifying the driver code, resulting in the Slammer control unit warmstarting. (This issue was fixed also in R3.3.20 and R3.4.1.)</p>	
	<p>In rare circumstances, if multiple read requests for the same RAID stripe with varying logical block address offsets arrive in a burst, the RAID controller may fault, resulting in a failover to the partner controller. (This issue was fixed also in R3.3.20.)</p>	
	<p>Sometimes, when growing a thinly-provisioned volume, an internal inconsistency can cause the system to hang.</p>	
	<p>In rare cases where a drive read error is encountered and the first level error recovery does not succeed, it is possible for the read command to get "stuck" in the firmware whereby a status is never returned. This would result in the Brick becoming unresponsive. (This issue was fixed in R3.3.10.)</p>	
	<p>Snapshot schedules are not visible when an NFS license is not installed.</p>	

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		Cannot download a system log from the Pillar Axiom system when the log file is greater than 2 GB in size.
		After Slammer battery replacement, if a slightly discharged battery is inserted, the battery will charge and eventually show a Normal status but the logical volumes owned by the Slammer will continue to show a Conservative status.
		In rare circumstances, a Slammer control unit can warmstart due to internal resource contention.
		Performance can degrade following a Slammer control unit failover and failback because the system has switched to conservative mode. The fix provides a message in the GUI to inform you that the system is operating in conservative mode.
		Repeatedly selecting the <i>Check for Tape Devices</i> item in the Actions dropdown list in the GUI can cause a software deadlock resulting in a healthcheck timeout.
		After a power failure, data that is not properly flushed from the Slammer cache can cause the control unit to fail and result in a failure to restart.
		Upgrades from R2.x may fail with a "Cold Start failed in configuration step 28 (CM)" error if one of the copy-on-disk (COD) instances is discovered to be inconsistent during the conversion performed for this upgrade.
		When a Slammer control unit fails excessively, causing a <i>SlammerControlUnitDisabled Administrator Action</i> to be generated, the notice is not removed by the <i>CLI ReenableAllSlammers</i> request.
		If a problem occurs when updating the RAID controller firmware, the controller is excluded from the system and a misleading <i>Offline/Missing</i> status displays. The fix changes the status to <i>Excluded</i> .
		During Guided Maintenance, the system may not function properly if sufficient time isn't allowed between multiple FRU replacements. The fix provides a better message in the Guided Maintenance help pages.
		In extremely rare situations when restarting a Pillar Axiom system, errant configuration information may prevent the system from restarting.
		Occasionally, an internal inconsistency can arise regarding the Brick configuration, resulting in the Brick faulting and the system being unable to start.
		On rare occasions, an attempt to grow a logical volume (LUN or filesystem) can fail, resulting in multiple Slammer panics.

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		An internal data structure to map IDs appears to have been corrupted for unknown reasons and returned invalid data. That caused an abort when the data was de-referenced, but since the structure was in volatile memory, it was rebuilt on the restart, and the system returned to normal function.
		Currently the system does not explicitly alert an administrator to the possible presence of loopback connectors installed on the system Fibre Channel (FC) ports.
		An intermittent firmware problem with the 4 Gb Fibre Channel (FC) interface could cause the FC interface to hang and disrupt I/O.
		In rare cases when an FC drive goes offline, it is possible that only the data LUN will be rebuilt to the spare. This implies the COD LUN will not be rebuilt to the spare.
		In rare cases where the Brick is heavily loaded, the firmware can run out of a critical internal resource.
		On a heavily loaded Pillar Axiom 300 system (with, for example, more than 1000 connections), a software deadlock may occur, causing the Slammer to warmstart.
		Occasionally, updating RAID controller firmware can fail because of the length of time to perform the update.
		Additional backend FC loop recovery code meant to detect and resolve loop issues was introduced in the upgraded code. Unfortunately, manufacturing test loopback plugs were accidentally left in the ports, and these have the same loop issue signature the new recovery code looks for, and will trigger the recovery action. The problem is that the recovery code does not give up as long as the "issue" remains.
		A faulty Enclosure Services module in a Fibre Channel Expansion Brick can prevent the Expansion Brick and its RAID partner from coming on line.
		If a logical volume is being restored from a backup, attempts to modify the attributes of the volume (such as the Slammer control unit assigned to the volume) will fail.
		Very large system information or Call-Home files cannot be downloaded to a client system using the web download function. You get an error popup: <div style="margin-left: 40px;"> <p>A system error has occurred:</p> <p>Cannot download file. Try again or contact the Pillar World Wide Customer Support Center.</p> </div>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
	NAS	<p>If there are many Kerberos entries in a DNS controller that are unresponsive, the Pillar Axiom system may fail upon a health check, which causes the Slammer to warmstart.</p> <p>Under a race condition, a CIFS process can use a TCP socket that has been freed, causing a Slammer control unit to warmstart.</p> <p>When a user attempts to modify an ACL (Access Control List) using the Microsoft Management Console (MMC) in Windows, if the user isn't using a CIFS administrator account, the changes are not implemented and no message is returned stating that the change attempt failed. The fix causes MMC to withhold the mechanism that allows an ordinary user to modify an ACL.</p> <p>When directories contain too many entries (for example, thousands of files), a wildcard search such as "dir a*" may not return the complete list.</p> <p>If a CIFS client attempts Kerberos authentication and the request fails due to an invalid ticket, the Pillar Axiom system will retry to decrypt the ticket, but leak an internal resource on each retry attempt. If the client retries many times (perhaps more than 1000 times), all system resources become depleted and the node warmstarts.</p> <p>When a CIFS share has an Access Control List (ACL) that restricts access to a limited set of users, the Pillar Axiom system rejects attempts by all CIFS clients to map the share.</p> <p>When multiple, large SecureWORMfs filesystems are homed on the same Slammer control unit and validation scans are running on those filesystems at the same time, scan progress can be slow. Furthermore, when an administrator attempts to cancel one of these scans, the cancel request sometimes can fail.</p> <p>When an NFS client submits a <code>mkdir</code>, <code>mknod</code>, or <code>create</code> request without specifying the permissions mode, the resulting mode is unpredictable. The fix causes the permissions mode to default to 000.</p> <p>A NAS Slammer control unit may warmstart if <code>lock/unlock</code> or <code>mount/unmount</code> commands are sent in rapid succession.</p> <p>If a snapshot creation occurs while reading the <code>.snapshot</code> folder, the process doing the directory listing of the <code>.snapshot</code> folder may encounter a self-deadlock. In this situation, the newly created snapshot is delayed until the Slammer control unit warmstarts.</p> <p>The CIFS server incorrectly returns a 32-bit (instead of a 64-bit) timestamp when responding to the <code>FileNetworkOpenInformation</code> function.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		<p>Deleting or moving a filesystem may leave unnecessary lock records of the moved or deleted filesystem in the warmstart memory. This situation can lead to a warmstart of the Slammer control unit when the system detects the spurious lock records.</p>
		<p>After a share is disabled using the GUI, a new CIFS connection can be established to this share after the Pillar Axiom system is restarted, even though the share had been disabled earlier (A "disable share" checkbox was ignored by the restart configuration routine).</p>
		<p>If a single file has more than 250 locks and the control unit (CU) warmstarts during an un-lock or cancel lock operation, the CU might warmstart repeatedly. The original warmstart must be within a small time period within the unlock operation or the cancel lock operation for this to happen.</p>
		<p>When an ACL is changed, the "change" time is not updated to the current time. One consequence of not updating the change time is that an NFS client can still believe that it can safely use its cache.</p> <p>For example, run "ls" on a directory that is accessible to everyone. Now change the ACL of the directory to have more restrictive permissions. When the "ls" command is repeated, the NFS client gets the attributes of the directory and checks to see if the change time has been updated. If it hasn't, then the NFS client concludes that the directory hasn't changed and it can rely on its cached data.</p> <p>So, the repeated "ls" also works when it should be failing.</p>
		<p>When a file or directory is created by a CIFS client and then accessed by a NFS client, subsequent NFS operations do not update the access control list (ACL) or the mode correctly: NFS permissions appear to be more restricted than intended.</p>
		<p>A Slammer control unit warmstart can occur when an NFS client terminates a connection while having a lot of requests being processed by the Pillar Axiom system.</p>
		<p>A mixture of CIFS and NFS operations can result in the creation of an incorrect ACL. For example, sometimes a new directory can result in an incorrect mode of 0000.</p>
		<p>Under certain conditions, when the amount of resources required to maintain a large number of open files (e.g., 1200 files) or to maintain a number of files that have path names of 100 or more characters, plus the resources for the other activity on the connection cause an internal threshold to be exceeded, Kerberos authentication requests or file open requests may be denied. In some case, the Slammer control unit may warmstart.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		When a single CIFS connection is shared by multiple users and the network connection information for an OpLock is modified, the CIFS server may cause the NAS Slammer control unit to warmstart after successfully processing an OpLock Break.
		If a filesystem is offline, filesystem snapshot schedules cannot be deleted. A "Delete filesystem snapshot task failed" Administrator Action will be generated.
		Occasionally, an attempt by a client to delete a file results in I/O errors because of a corrupt quota tree index.
		Under rare conditions, the internal accounting of the OpLock ownership can be out of sync between CIFS protocol and the filesystem. When this occurs, the system will be stuck waiting for a long time, resulting in a warmstart.
		Under certain conditions, a Slammer warmstarts when a request to break an OpLock fails.
		For a Slammer that has 12 GB memory for each control unit, when the number of CIFS connections reaches approximately 1300, new connections are rejected until some existing connections are closed.
		When a CIFS server has joined a domain in ADS mode and a user successfully authenticates using ADS and connects to that server, if the administrator then assigns CIFS local group and the user subsequently tries to make use of the privileges as part of CIFS local group assignment, such as trying to access a folder for which he or she did not previously have permissions, the attempt will fail.
	SAN	When a LUN creation task fails due to a lack of space in the system, internal records that reference the LUN number are left behind, causing the LUN number to be unavailable for use and the defunct internal records undeletable.
		Sometimes a request to create or delete a Clone LUN can cause a Slammer control unit to warmstart repeatedly.
		Creating and deleting a large number of Clone LUNs can cause a Slammer control unit to warmstart repeatedly.
		When using iSCSI under very heavy loads, a queue full condition might be encountered when a false PCI bus fault error is generated.
		On an iSCSI SAN system, a problem in the heartbeat code that monitors for the proper function of the iSCSI interface chip can cause the Slammer control unit to warmstart.

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
3.4	ALL	<p>The Pillar Axiom iSNS client may cause the Slammer control unit to warmstart under the following conditions:</p> <ul style="list-style-type: none"> • The iSNS client is running while the iSNS server is not accessible. • The iSNS client is subsequently shut down. • The final attempt of the iSNS client to establish iSNS server access is close enough in time to the iSNS client shutdown.
		<p>Deleting LUN mappings with the AxiomONE CLI can take much longer than expected.</p>
		<p>Using either of the CLI products to delete a large number of host mappings can take a long time to delete the mappings.</p> <p>The fix enhances the command syntax to allow efficient batch deletions.</p>
		<p>When upgrading a Pillar Axiom system from release 2.x to release 3.0 and then further upgrading to release 3.3, it is possible that invalid metadata might be present in the storage array, causing LUNs to come up with an incorrect Offline status.</p>
		<p>Creating a Clone LUN when the underlying storage is not properly initialized can cause the system to repeatedly check the storage status, resulting in a hang condition.</p>
		<p>Due to a very small timing window in buffer handling when a Slammer warmstart occurs, additional warmstarts may occur.</p>
		<p>An internal component may hang during LUN duplication when there are numerous bad blocks in the Brick array.</p>
		<p>Due to a change in the way that mutli-control unit processing of logical volumes was implemented in 3.3, the possibility exists that on a non-disruptive upgrade from 3.2 to 3.3.4 or earlier may result in logical volumes coming up in the offline state.</p>
		<p>When one control unit (CU) fails over and is followed by a CU warmstart, the warmstart may timeout and fail due to an internal processing deadlock.</p>
		<p>If an administrator enters 0 for both soft and hard quota limits in the GUI, they will get an error message indicating that both fields cannot be zero.</p>
<p>A race condition exists in the 64-bit timer handling routine of the Pillar Axiom software that under very rare circumstances can cause a control unit to warmstart.</p> <p>The clock_handler() ISR is being preempted by other interrupts in the system.</p>		

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		<p>In 3.x software prior to release 3.3.5, if a Slammer control unit (CU) fails over and the surviving CU warmstarts immediately (before the failover completes), write operations may occur in write-through mode only, resulting in poor write performance.</p>
		<p>If RAID controller 1 in an FC Brick has previously had a warmstart due to an error, it is possible that a rebuild that is initiated by the Pilot will get stuck.</p>
		<p>A bug exists in the Axiom software related to handling a temperature related automatic shutdown. In this case, a bad fan FRU caused a Slammer control unit (CU) to detect the over-heating and to fail over to it buddy CU. The surviving CU flush out orphaned I/O destined for the failed CU. This bug causes the clearing of the orphaned I/O to be slow. The system interpreted the slowness as a hang and warm started the surviving CU to recover the perceived hang.</p>
		<p>The Lost Data flag could not be cleared for a non-standard logical volume, such as a clone of a filesystem or LUN.</p>
		<p>In software versions prior to 3.2, if a large number of write I/O transactions were in process when a control unit (CU) failover occurs, a warmstart may result due to an excessive delay in timing out mirrored writes to the failed CU.</p>
		<p>After a drive failure, it is possible for the firmware to encounter an exception as the rebuild to the spare is started. If this should occur, the rebuild to the spare will not complete and the system will be unable to perform a copyback operation.</p>
		<p>When a Brick becomes inaccessible, warmstarts may result due to the inability of the system software to access critical operating metadata.</p>
		<p>It is possible for a failing Fibre Channel drive to get into a state where it drops off and comes back on the backend loop repeatedly. This behavior causes a disturbance in the backend loop, which can greatly hinder the performance of the Brick.</p>
		<p>This problem was due to a defect in the code for managing data migrations. When adjusting internal data structures to reflect the migration, the code made a reference to memory that had already been reclaimed. Often this happens soon enough after de-allocation that there is no problem. In this case, the memory reference caused an infinite recursion stack overflow, causing a Slammer control unit to warmstart. That warm start actually fixed the problem, because the memory contents were then regenerated correctly.</p>
		<p>A slow memory leak was detected that could cause a warmstart of a Slammer control unit after one year of uptime.</p>
		<p>Following the update of the system software to R3.3, a pointer was not properly initialized resulting in an improper memory access.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		<p>A component responsible for re-configuration during Slammer control unit (CU) failback after a failure sets a "failback in progress" state that it expects to clear when failback configuration is done, and it can shift back to normal operation.</p> <p>That state was not saved over a warmstart. So, in this case, when another CU happened to warm start during the failback, the state was lost, and the system behaved as if it were restored to normal state prematurely.</p> <p>A component responsible for re-configuration during Slammer control unit failback after a failure sets a "failback in progress" state that it expects to clear when failback configuration is done, and it can shift back to normal operation.</p> <p>In addition to the state, it also sets a watchdog timer with a limit (30 minutes) for the time in that state. It assumed that if it exceeded 30 minutes, it was probably a bug in clearing the state. In this defect, however, re-configuration had to do large amounts of disk I/O, and it legitimately took longer than the watchdog allowed, causing the component to abort configuration.</p> <p>A defect was detected in the low level kernel routines of the Pillar Axiom system software that can lead to a failover of a control unit. This is a very rare occurrence that has to do with a segmentation fault while the kernel is in the middle of sending a pulse to a kernel process.</p> <p>Under very rare circumstances, an error may be encountered during system shutdown. The GUI reports the status of the system shutdown operation as "Shutdown Failed".</p> <p>If you change the name of a LUN or filesystem to a name that already exists, the system may erroneously allow the change, which may prevent the administrator from making subsequent modifications to that LUN or filesystem.</p> <p>A system warmstart may result when fewer than half of the configured Bricks are online, which can cause a Slammer control unit to become disabled.</p> <p>When a number of Bricks have gone offline, the system may warm start.</p> <p>When viewing the simulation results in the Capacity Planner in the GUI, the summary values for Used system capacity, Total system capacity, and Remaining system capacity are inaccurate and should be ignored.</p>
	NAS	<p>In very rare conditions, the pathnames or file name may contain illegal characters. In those cases, the Pillar Axiom system returns an illegal sequence error causing the CIFS server to warm start.</p> <p>When a Snap FS is accessed during failback, a small window can occur when the snapshot is mounted for access but the active filesystem ownership has not been reestablished. This situation causes the NAS control unit (CU) to warmstart repeatedly leading to the CU being disabled.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		Under a race condition, a CIFS process can use a TCP socket that has been freed causing a NAS Slammer control unit to warmstart.
		When a file is being deleted and another file with CIFS reservation is closed at the same time, the machine may sometimes warm start.
		In very rare conditions, the path names or file name may contain illegal characters. In those cases, the Pillar Axiom system should have returned an error code indicating this is an invalid pathname. Instead, it returned illegal sequence error causing the CIFS server to warm start.
		The filesystem was not handling a case where the linked list was empty. As a result, while de-referencing an empty linked list, a segmentation fault was encountered.
		In a rare condition, the filesystem database tracking user opportunistic locks (OpLocks) can get out of sync. In those cases, a stale lock record could cause the NAS control unit to time out on a health check due to the wait time of breaking OpLock that would exceed the desirable time.
		In rare cases, the OpLock (opportunistic lock) records in the database are not cleaned up properly causing OpLock related issues.
		A NULL quota tree was getting associated because of a variable not being set, this NULL quota tree was causing the segmentation fault. The code has been rectified to handle the NULL quota tree condition.
		Validation scans on SecureWORMfs filesystems can slow system performance significantly.
		A SecureWORMfs audit directory (<code>/.audit</code>) and its logs are not readable and cannot be made readable in Windows.
		If more than one host entry exists for a given NFS export, the order of processing the entries could be different from the one shown in the GUI display (usually after inserting host entries in the middle of the list).
		When a CIFS client has been given an opportunistic lock (OpLock) that allows writes to be delayed and the connection between the client and the CIFS server is experiencing network difficulties, the client can experience delayed-write errors.
		For an extremely large configuration having more than 1000 filesystems, a Slammer warmstart sometimes causes control unit failover.

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		<p>Both file deletion and truncation to a smaller size are asynchronous operations. Multiple file deletions and truncations can be batched and processed in the background. When a batch includes large files, the delete or truncate will take too many CPU cycles and lead to system warm start. This is especially true if all files to be deleted or truncated are in the same directory.</p>
		<p>While using the supporttool wbinfo to enumerate local groups, the Pillar Axiom system might warmstart under certain circumstances.</p>
	SAN	<p>When host systems that are attached to the Pillar Axiom server drive I/O at a higher rate than the server can support, the server returns BUSY. The fix now returns TASK_SET_FULL instead of BUSY.</p> <p>On systems running VMware ESX the host system may not properly select preferred IO paths resulting in non-optimized accesses. This issue is resolved in Pillar Axiom release 3.3.8 and above.</p> <p>When an administrator changes the selection of a host in the mapping tab during a LUN create or modify request in the GUI, the administrator can create a map based on the available numbers before the list of available numbers is updated, resulting in a number that is not available.</p> <p>Some operating systems may respond better to a TASK_SET_FULL I/O return as opposed to a BUSY return in situations where the Pillar Axiom system is being overdriven by I/O.</p> <p>In rare situations the Slammer may warmstart in situations where I/O is overdriven to the Slammer.</p> <p>Following the update of the system software to release 3.3, a pointer was not properly initialized resulting in an improper memory access.</p> <p>In situations where a mis-configured system results in a large number of non-optimized access I/Os, the potential exists for a system warmstart.</p> <p>If, in the process of configuring SAN Host mappings for LUNs during failback of a Slammer control unit, MCC encounters a missing SAN Host software record, no mappings for any LUNs beyond that point will be configured.</p> <p>If a warmstart occurs following deletion of Clone LUNs, the data structures for these Clone LUNs are not properly reclaimed, which may result in running out of available Clone LUNs and then another system warmstart.</p> <p>Due to a problem handling quorum disk handling clustering failover may not successfully occur.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		<p>If two or more APM hosts connect to a Pillar Axiom management interface using the same source IP address (as seen by the Pilot), then the Pilot will repeatedly run out of resources. This causes the Pilot to dump core and restart, briefly interrupting any management connections. The APM hosts will appear to continuously connect and disconnect from the Pilot.</p> <p>Configurations of this sort can be created by using Network Address Translators (NATs) between the hosts and the Pilot; although the hosts themselves may be configured with unique IP addresses, the connections at the Pilot may all appear to come from the IP address used by the NAT.</p> <p>In the unlikely situation where clustered hosts are being used without benefit of APM and non-optimized paths result, if a RESERVE command is sent from the host to the Pillar Axiom system and the non-optimized accesses result in a delayed execution whereby the host aborts the RESERVE command at the same time the Pillar Axiom system has processed the RESERVE command, a warmstart may occur.</p>
	iSCSI	<p>In iSCSI environments with noisy power, high temperatures, or very heavy I/O loads, a system warmstart may result.</p>
		<p>Downgrade of iSCSI Initiator from <code>Initiator-2.08-build3825-x64fre.exe</code> to <code>Initiator-2.06-build3497-x64chk.exe</code> may cause a problem with iSCSI session login handling.</p>
		<p>In rare situations the iSCSI chip used in the Axiom may hang in certain network error conditions resulting in an Axiom warmstart and an access outage of up to 5 minutes.</p>
		<p>It is not possible to create multiple iSCSI sessions to Pillar Axiom systems through a QLogic 4052C iSCSI HBA when using the latest QLogic 4052C HBA software and the latest Microsoft iSCSI Initiator software.</p>
3.3	ALL	<p>After upgrading a multi-Slammer system to release 3.2, when a write operation to a double redundant logical volume fails or a similar issue occurs that causes the mirrors to lose synchronization, the system may panic and warm start repeatedly.</p> <p>In release 3.x, live Brick logs cannot be collected as part of doing a manual system log collection.</p> <p>On rare occasions, after a Slammer control unit (CU) fails over, the fail back may complete incorrectly, leaving the CU in a Normal state but with the IP address of one of the virtual interfaces being inactive.</p> <p>Under extremely rare circumstances, a Slammer control unit (CU) will experience multiple, consecutive software failures due to incorrect internal (non-data path) memory handling during normal operation. This will usually lead to the CU being disabled for excessive errors.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		<p>When upgrading a Pillar Axiom system from 2.x to a 3.x release earlier than 3.2.7, the internal growth increment that is selected for a large LUN or filesystem may be too great, which results in the volume using system capacity inefficiently (by wasting space) or not being able to grow at all (by exceeding available system space).</p> <p>An NDMP backup operation sometimes can hang because of an internal snapshot issue. When this occurs, NDMP will cause the Slammer to warm start but the backup operation will continue to hang.</p> <p>After upgrading from release 2.x to release 3.2, attempts to modify the system Global Settings might fail.</p> <p>Under some conditions, if a Slammer Fibre Channel cross connection fails, the system fails to generate an Administrator Action that identifies the missing connection.</p> <p>If a system is in a Startup Failed state, attempting to shut down or restart the system from the GUI or CLI may result in filesystem corruption.</p> <p>The Doho (Qatar) and Riyadh (Saudi Arabia) time zone setting sets the time to GMT-3 instead of GMT+3.</p> <p>During Guided Maintenance, if a Slammer battery replacement fails diagnostics, the battery will not be charged, eventually causing the Slammer control unit to go into Conservative mode.</p> <p>If the passive Pilot control unit (CU) is turned off or fails during a software update process, that Pilot CU may not have the target versions of the Pilot OS and Pilot Software installed in the update. Also, the system may not indicate that a failure has occurred.</p>
	NAS	<p>Creating and deleting a large number of Snap FSs over a lengthy period of time without an intervening restart or warmstart can cause an out-of-memory event and a subsequent warmstart.</p> <p>When a filesystem is homed on (assigned to) one Slammer control unit (CU) and the user accesses the filesystem through the buddy CU, sometimes that access can cause the Slammer to warm start.</p> <p>Reclaiming the space formerly allocated to large files and reporting the reclaimed space as free can take a long time.</p> <p>When an administrator attempts to have a Pillar Axiom system join a Window 2008 domain, the request will fail because Windows 2008 DC is not supported.</p> <p>When several Snap FSs are created on the same filesystem and the mounting of the first snapshot fails, the mounting of the second snapshot may also fail.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		<p>When the user accesses a Snap FS while the source filesystem is in journal recovery mode, the Slammer can repeatedly warm start, even after the filesystem has recovered and is in a Normal state.</p> <p>Reassigning a filesystem to a different owning Slammer control unit, particularly while I/O is in progress to that filesystem, can cause system crashes and possible data loss or corruption.</p> <p>NLM locking operations can sometimes hang, which after a few minutes causes the system to warm start. Typically, the NFS client automatically retries the lock operation.</p> <p>In rare circumstances, disk usage reports might show less free space than anticipated after big files or a large number of files are deleted or truncated.</p> <p>In release 3.2, deleting large files or a large number of files can take longer to reclaim data blocks than in earlier releases. When queried (for example, with <code>df -k</code>), the amount of free space does not immediately appear.</p> <p>If Clone FSs are actively used for I/O during a failover-failback event, the clone may go offline for a few seconds before coming back online.</p> <p>If a user enters a default route for a File Server that already exists in the system, the system responds with an error code that is not handled by the GUI properly, which results in an Error tab with no dialog showing what caused the error.</p> <p>The CIFS server scans trusted domains every five minutes. If one of the servers within the trusted domain list fails while the scan process is running or when a Slammer control unit (CU) is attempting to connect to that server, the CU could warmstart.</p> <p>If a snapshot is restored after the filesystem FSCK is performed, there is a chance the snapshot can still have the same corruption.</p>
	SAN	<p>When the VTL license is not installed, creating a single SAN LUN with the Capacity Planner will fail. When "Finish" is selected, the Capacity Planner returns a blank Information pop-up with just an OK in it.</p> <p>When using an SNMP client to get specific LUN details (such as statistics), the Pilot management software increases the Pilot workload significantly, which can cause a Pilot failover if the system contains 50 LUNs or more.</p> <p>Unable to activate Clone LUN without a Volume Copy license.</p> <p>Performance degradation of non-optimized path accesses causes extent lock thrashing, resulting in a PANIC and a system warmstart.</p>

Fixed in Release	Slammer type	Pillar Axiom server issue or impact
		<p>When a Clone LUN other than the oldest for a snapshot tree is deleted, the snapshot repository space that was allocated to the clone is reassigned to the next older clone. While this reassignment occurs, all older clones and the next newer clone (or the source if the newest clone is being deleted) are not accessible. This can take a long time when much data exists that has to be reassigned and may cause problems for applications and command timeouts within the system.</p>
	iSCSI	<p>The VMware iSCSI Hardware Initiator fails during virtual machine (VM) creation if a 2-MB, 4-MB, or 8-MB block size is used to create the VM filesystem on a Pillar Axiom LUN.</p>
		<p>On occasion, an iSCSI client using a QLogic HBA may see the Pillar Axiom system warmstart, which causes a short interruption in I/O.</p>

9 Additional Notes

For items in this section that refer to inserting and/or removing field replaceable units (FRUs), please refer to the *Pillar Axiom Service Guide* for more information.

For items in this section that refer to provisioning and/or configuring a Pillar Axiom storage system, please refer to the *Pillar Axiom Administrator's Guide* for more information.

9.1 Host Queue Depth on SAN Hosts

The recommended maximum queue depth for all SAN hosts attached to a Pillar Axiom storage system is 64. This value is the maximum number of outstanding I/O requests to the Pillar Axiom system. Exceeding this value may cause I/O errors if the input/output queue of the Pillar Axiom system is exceeded.

This value is typically set in the BIOS or similar firmware configuration of the HBA on the SAN Host. Consult your HBA documentation for the setting that controls the maximum I/O queue depth for your HBA and for configuring this setting.

9.2 Limitation of the Linux `sginfo` Utility

The `sginfo -l` utility (part of the Linux `sg3_utils` package) has a limitation by which it can only display up to 31 LUNs. To display the actual number of devices recognized by a host, use the `fdisk -l` utility instead.

9.3 LUN Ranges in Windows

Windows 2000 and 2003 will not configure LUN 255. If you configure a LUN in the Slammer at address 255, Windows will not see the LUN.

9.4 Issues with LUN Capacity Calculations on Solaris

The Solaris operating system calculates the size of a LUN using disk geometry information from Mode Sense queries rather than the more common and accurate practice of using the response to a Read Capacity Query. For Pillar Axiom LUNs larger than approximately 400 Gigabytes, this calculation can result in a reported capacity that is different from the Pillar Axiom configured value.

The Solaris `format` utility may return an error stating that it is adjusting the number of sectors on the Pillar Axiom LUN or may indicate that the number of heads is something other than 64 or that the number of sectors is something other than 128 when Solaris adjusts the number of cylinders to be 65,533 during the size calculation. If `format` returns an error, it is typically:

Mode sense page(3) reports nsect value as 128, adjusting it to 127

Disk geometry information does not apply to SAN LUN arrays on Pillar Axiom systems. This information is returned, however, in Mode Sense with the number of heads and sectors being 64 and 128 and with the number of cylinders varying for those operating systems (such as Solaris) that calculate LUN size rather than using the actual Capacity.

If the difference between the information calculated by Solaris and the actual LUN size is an issue for your applications, create and use a unique disk label or `/etc/format.dat` entries for the Pillar Axiom LUNs.

9.5 VMware ESX Server 3.0.1 Connections to Pillar Axiom iSCSI Systems

When booting from SAN, only one path to the Pillar Axiom system should be configured in the iSCSI HBA BIOS. The boot LUN is assigned a LUN ID of 0 (zero) to which the iSCSI adapter ports must be mapped.

9.6 Avoid Adding iSCSI HBAs While Heavy I/O is Occurring

During the addition of iSCSI HBAs to the Pillar Axiom system, the system attempts to flush all pending I/O writes to storage so that the system can go into write-through mode. Going into write-through mode ensures that no data is in cache should a catastrophic error occur. If there is heavy write activity during this time, an Administrator Action may be generated in the GUI warning the administrator that the system cannot properly prepare for the upgrade.

In this case, retry the operation or quiesce the hosts that are writing data to the Pillar Axiom system.

9.7 MS iSNS Server Could Add or Remove Discovery Domain Members Quietly

Under certain circumstances, the Microsoft iSNS Server v3.0 may add or remove members of the Pillar Axiom's discovery domain without notifying the Pillar Axiom system. If iSNS access control is enabled, the missing notifications can cause the Pillar Axiom iSCSI target to accept or reject iSCSI initiator logins when it should not.

To prevent this problem from occurring, follow these guidelines:

- When creating a new discovery domain, add the Pillar Axiom to the discovery domain before adding any iSCSI initiators.
- Disable a discovery domain set before deleting it.
- Ensure that an iSCSI initiator is registered with the iSNS server before adding it to an existing discovery domain.

If a problem already exists, any of the following actions will cause the Pillar Axiom system to query the iSNS server for the latest discovery domain information:

1. Disable and re-enable iSNS server registration in the Pillar Axiom system.
2. Disable and re-enable the discovery domain set(s) in the iSNS Server GUI.

9.8 HP-UX HBA Connections to Pillar Axiom Systems

The AxiomONE user interfaces show that host Fibre Channel (FC) HBA ports are either Connected or Not Connected to the Slammer ports. The meaning of Connected is that the HBA port on the SAN host has logged in to the port on the Slammer using the FC protocol.

In most operating systems, host ports log in to the Slammer ports immediately after the two are physically connected and enabled and remain logged in until the physical connection is broken. Therefore, Connected in the UI effectively means that there is an enabled physical connection between the ports.

Some HBA device drivers on HP-UX, however, use a different approach—they log out from the connection when there is no traffic to send. An HP-UX HBA port often shows as Not Connected even though there is an enabled physical connection between the ports.

9.9 LUN Assignment and Accessibility

If you use Pillar Axiom LUN masking or switch zoning and do not use LUN assignment, you may create a situation in which a LUN is not exposed on the ports on which you want to access it. To avoid this situation, it is recommended that you assign the LUN to the Slammer control unit (CU) on which you have the mapping set.

9.10 LUNs Created Through Capacity Planner Accessible by All Hosts

When you create a LUN using the Capacity Planning Manager, the LUN is created without port mapping or masking information. To configure port mapping or masking for a LUN that was created through the Capacity Planner:

1. In the Storage>LUN section of the GUI, click the link for the LUN you want to configure.
2. In the LUN Access section, select the “Only selected hosts” option.
3. Click the Mapping tab.
4. Configure the LUN for mapping and port masking as needed.

9.11 System May Rebalance LUNs Without Prompting the Administrator

If you auto-assign LUNs to a Slammer CU, the system may move those LUNs to another CU when the system starts up (or restarts). The system may take this action to rebalance the system load by QoS bands. This strategy works well if AxiomONE Path Manager is installed on all client hosts that use the auto-assigned LUNs.

If, however, the client host does not have APM installed, this strategy may cause Non-Optimized Access events. In this case, Pillar recommends that you explicitly assign all LUNs for non-APM clients to a specific Slammer CU.

9.12 Blacklisting Local Drives on RHEL4 Platforms

Device Mapper on RHEL4 U4 platforms may display local SCSI SAS or SATA drives along with the FC drives as multipathed. Including local drives can be avoided by blacklisting the devices in the `/etc/multipath.conf` file:

```
devnode_blacklist {
    wwid 26353900f02796769
    devnode "^(ram|raw|loop|fd|md|dm-|sr|scd|st|sda) [0-9] *"
    devnode "^hd[a-z] [0-9] *"
    devnode "^cciss!c[0-9]d[0-9]* [p[0-9]*] "
```

The above work-around is suggested by Redhat in their knowledgebase at http://kbase.redhat.com/faq/FAQ_85_7319.shtm.

After running the following commands, the local disks should no longer be listed in the new multipath maps:

```
multipath -F
multipath -v2
```

9.13 Supported Versions of IBM AIX Operating Systems

The AIX versions of the `pdsccli` and `axiomcli` products distributed with the following Pillar Axiom software releases are supported only on AIX 5.3 TL5 and later versions of AIX:

Pillar Axiom 300	Pillar Axiom 500	Pillar Axiom 600
3.1 and later	3.1 and later	3.1 and later
2.0.3 and later 2.0.x	3.0.3 and later 3.0.x	-
1.8 and later 1.x	2.10 and later 2.x	-
1.7.3 and later 1.7.x	2.9.3 and later 2.9.x	-
1.6.10 and later 1.6.x	2.8.10 and later 2.8.x	-

9.14 iSCSI Software Initiator May Have Two Names Associated With It

The Microsoft iSCSI Software Initiator may sometimes use an iSCSI Initiator Name other than the one set in its configuration. For example, if the configured Initiator Name ends with the Fully Qualified Domain Name of the host, when making iSCSI connections, the Software Initiator may use a Name ending with only the node name of the host. In this case, the Pillar AxiomONE Storage Services Manager GUI and CLI will report that the host is using two iSCSI Initiator Names, both the configured name and the name it is actually using.

9.15 Resetting the Primary System Administrator Password

If you forget the Primary System Administrator password, you can reset it in these ways:

- Use a Type 1 Administrator account, if one exists, to reset the password. A Support Administrator cannot reset the Primary Administrator password.
- Contact the Pillar World Wide Customer Support Center for the encrypted file (for resetting the password), which may be placed in a USB key. Use the USB key as instructed.

It is strongly recommended that you set up an additional Type 1 Administrator account when you install the system. A Type 1 Administrator can modify account passwords without knowing the previous password for any accounts.

9.16 Uploading Software Update Packages over Slow Connections

It is not recommended that you upload a software update to your Pillar Axiom system over a slow connection (such as a WAN connection). Use an internal network connection (10 Mbit/sec or greater) only.

9.17 When Updating the Software

Whenever you update Pillar Axiom software, ensure that all non-Pillar Data Systems components are working correctly with all redundant paths enabled and no maintenance being performed on any other component in the network.

9.18 Non-Disruptive Software Updates

The Pillar Axiom system implements non-disruptive software updates by warmstarting the Slammer control units (CUs) and restarting the Pilot CUs to bring up the new software. As each Slammer CU warmstarts, there is a temporary protocol service disruption of a few seconds on each CU. This disruption is typically non-disruptive to most applications and protocols.

For NAS Slammers, the brief protocol disruption is such that most client applications either time out and recover or see a fast reboot of the Pillar Axiom server.

For SAN Slammers, if the HBA timeouts and retries are set correctly, this brief protocol disruption should be handled gracefully by most operating systems and applications.

However, any application or operating system that bypasses the Fibre Channel protocol stack and issues SCSI commands with short timeouts may not be capable of handling the brief interruption of a non-disruptive software update. For example, the Microsoft Cluster Service will initiate retries in 3 sec and, at 7 sec, will begin reconfiguration and recovery that will probably disrupt any applications using the Cluster Service. Microsoft, however, is promising to fix this issue in the upcoming release of the Windows “Longhorn” server (successor to Windows Server 2003).

9.19 WWN Designation Changed in Release 2.0

Starting with the 2.0 release of Pillar Axiom 500 systems, the WWN was changed to use a common base World Wide Node Name (WWNN):

- In release 1.x, each Slammer was assigned a unique WWNN with the Slammer Fibre Channel ports being assigned World Wide Port Names based on the WWNN of the Slammer. For each Slammer, CU0 would have World Wide Port Names using 1 and 3 and Slammer CU1 would have World Wide Port Names using 2 and 4 to indicate the port, based off the Slammer WWNN.
- Starting with release 2.0, the entire Pillar Axiom system has a single base WWNN based on the MAC address of Slammer CU0. The World Wide Port Names are derived by a fixed formula from this single base WWNN using the Slammer, Slammer CU, Slammer Port Number, and Port Type.

9.20 Some CLI Requests Have Been Removed

As of release 4.0, the following requests have been removed from the Command Line Interface (CLI):

- CreateLUNCopy
- ModifyLUNCopy
- DeleteLUNCopy
- GetAllLUNCopies
- GetLUNCopyDetails

- CreateVolumeBackup
- ModifyVolumeBackup
- DeleteVolumeBackup
- GetAllVolumeBackups
- GetVolumeBackupDetails

- CreateFileSystemCopy
- ModifyFileSystemCopy
- DeleteFileSystemCopy
- GetAllFileSystemCopies
- GetFileSystemCopyDetails
- PerformFileSystemCopyActivation
- PerformLUNCopyActivation

- PerformFileSystemBackupActivation
- PerformLUNBackupActivation
- RestoreFromVolumeBackup

- PerformBackgroundLUNCopy
- PerformBackgroundFileSystemCopy

- PerformTidyMediaPlacement
- SetValidate

As of release 4.1, the following request has been removed from the Command Line Interface (CLI):

- GetStorageConfigDetails (replaced by GetStorageConfig)

The above requests may appear to be supported in the `pdscli` or `supporttool` executable, but when these requests are invoked, the result will be the following:

Error (4028):

The requested feature is no longer supported by the product.

9.21 Possible Errors When Running Unsupported Linux Variants

When attempting to run the Command Line Interface (CLI) application on unsupported Linux variants (such as Fedora Core 3 and Core 4 versions of Linux), you may see the following message:

```
pdscli-Linux: error while loading shared libraries:  
libstdc++.so.5: cannot open shared object file: No such file or  
directory.
```

These and certain other variants of Linux do not include the necessary libraries in their standard installation. Although these are unsupported Linux variants, you may be able to use these versions of Linux by installing the appropriate version of the `compat-libstdc++` rpm package.

Note: If you need support for another operating system, contact your Pillar Account Representative.

9.22 Linux 2.6 Marks Filesystems Read-Only When Access to Boot LUN Is Lost

Linux 2.6 is sensitive to losing all paths to a boot LUN. When a SAN host loses access to all paths to a boot LUN, to prevent data corruption, the Linux system marks the file system on the client as read-only. This behavior is as designed and would occur regardless whether the AxiomONE Path Manager is installed on the SAN host. To improve the path recovery time, Pillar recommends that you:

- Modify the `/etc/multipath.conf` file and set “failback immediate”.
- Configure the host to minimize the chances of all paths being lost at the same time.

9.23 Dynamic LUN Expansion Not Well Supported on Linux

In general, device-mapper does not support dynamic LUN expansion. Specifically, the latest QLogic rescan utility on a Linux host does not gracefully handle LUN expansion on a Pillar Axiom storage system.

If you expand a LUN on the Pillar Axiom system, you need to reboot the Linux host to make the LUN expansion visible.

9.24 Status of Filesystems and LUNs

System Health screens in the GUI display the status of hardware and firmware components of the Pillar Axiom system. The overall system status icon on the bottom of the screen is a summary of the hardware status and does not reflect the status of LUNs or filesystems.

A hardware problem typically causes filesystems and LUNs to go offline or to a degraded state. Because this is not always the case, you should check the state of the filesystems and LUNs or any associated Administrator Actions that may be listed.

9.25 Change in Default Failback Configuration of NAS Slammers

Automatic failback of NAS Slammers is the default configuration beginning with release 2.0 of Pillar Axiom 500 systems (release 1.0 of Pillar Axiom 300 systems). If this is not desired, automatic failback of NAS Slammer CUs can be disabled in the GUI Global Network settings menu (System>Global Settings>Network).

Automatic failback of SAN Slammer CUs is always enabled.

9.26 Changing the Time on a Pillar Axiom System

A Network Time Protocol (NTP) server is required for some environments, such as those using CIFS, SecureWORMfs, and some NFS environments. Even though your environment may not require an NTP server, Pillar recommends that you use an NTP server.

Note: If an NTP server is controlling the time on a Pillar Axiom system, you should change the date and time *only* on that time server.

If you are not using an NTP server, we recommend not changing the date once the initial installation is complete and the system is operational. If you change the date on a Pilot or Slammer by more than 15 minutes, the NTP daemon will mistrust the request and exit. Changing the date may result in reporting of events and alerts with bad dates. Should you do this or see date stamps on events or alerts that are obviously invalid, contact Pillar the Pillar World Wide Customer Support Center for recovery assistance.

Tip: If you are about to switch to using an NTP server, be sure the current time on the Pillar Axiom system is within 15 minutes of that on the time server; otherwise, a Pilot failover may result.

9.27 Automatic Snapshots

When you create a filesystem, the default action is to also create a snapshot schedule that will create filesystem snapshots every four hours. If this schedule is not appropriate for your data, perform one of these actions:

- On the Create Filesystem menu, clear the Create Automatic Snap FS Schedule (every 4 hours) checkbox.
- Modify the automatically created snapshot schedule to satisfy your requirements.

To avoid SAN filesystem inconsistencies, AxiomONE Storage Services Manager does not provide for creation of schedules for Clone LUNs (formerly called Snap LUNs). Before creating a Clone LUN for a LUN, be sure that the SAN host has placed the filesystems on that LUN in a state where they will be consistent. If desired, you can use the CLI with a scripting language to create Clone LUNs periodically.

9.28 Keeping Clone LUNs From Being Deleted

When the repository for Clone LUNs (formerly called Snap LUNs) consumes more than 90% of its allocated capacity, the system is likely to begin automatic deletion of Clone LUNs. When repository usage crosses this 90% threshold, the system creates an Administrative Action SnapLUNStorageFillingButCannotGrow (“Extra space for Clone LUNs has reached maximum and is nearly full”) to warn of this possibility. If you see this Administrative Action, you should manually delete some of the Clone LUNs.

If you want to use lots of I/O on a Clone LUN, to keep the Clone LUN from being deleted, you should allocate a size of 120% of the source LUN. For multiple Clone LUN descendants of a source LUN, each one requires more space, so you should allocate an additional 50% for each Clone LUN that you intend to have in existence at a given time. Actual storage space used for the repository is only grown to the amount of space being used.

Clone LUNs are not intended for heavy I/O, they are intended to be temporary—anywhere from minutes to several weeks in existence. As long as they are deleted the space will be recycled. All repository space is recycled when the last Clone LUN is deleted.

9.29 Deleting Clones From the Youngest to the Oldest

When several clones are deleted at the same time using the GUI, the process can take about seven minutes for each clone. The length of time it takes to delete a clone is related to the time it was created and how it relates to the clone storage space being used. The best approach to deleting clones would be to choose the youngest clone first and work your way back to deleting the oldest.

9.30 Small Maximum Clone LUN Space

When creating a LUN, you can specify Max space for Clone LUNs that is as little as 50% of the LUN capacity, or lower (minimum 1 GB). Choosing a small number is only appropriate for LUNs that have the following characteristics:

- It has only a few Clone LUNs at any given time.
- Its Clone LUNs will have short lifetimes (for example, they will be deleted after making a backup).
- It will get minimal write activity while there are Clone LUNs.

Specifying a larger Max space for Clone LUNs (for example, up to 300% of the LUN capacity) is safe and reasonable. The system will allocate a small fraction of the specified Max and will increase the space automatically as warranted by Clone LUN activity up to that Max.

It is good practice to delete Clone LUNs when you are done with them. Old Clone LUNs run the risk of running out of space and losing synchronization with their source LUN. If that occurs, their data will be corrupt, and they will be automatically deleted. If you need a long-term copy of an active LUN, consider using the Backup to Disk option instead.

9.31 Reassigning a Logical Volume to another Slammer or Control Unit

If you reconfigure the Slammer or the Slammer control unit (CU) to which a logical volume (filesystem or LUN) is assigned, the Pillar Axiom system recreates the volume at the new location. Attempting to use a logical volume while it is being moved can result in lost data.

Important! Pillar recommends that all NAS clients unmount the filesystem (and SAN clients unmount the LUN) that is to be reassigned before reassigning the logical volume.

Important! If the LUN is a member of a SAN replication pair, you should isolate the pair before re-homing the LUN to a different Slammer.

9.32 SAN Replication Pair Isolation and Active Communication Channels

When isolating SAN replication pairs, the primary (source) and secondary (destination) Axiom systems must have an active communication channel between them. If the communication channel is lost between the primary and secondary systems, the replication pair will not be properly isolated at the secondary side.

In this situation should occur, restore the communications channel between the Axiom systems and re-issue the command to isolate the replication pair from the primary system.

9.33 Isolate SAN Replication Pairs Before Shutting Down

Pillar recommends that SAN replication pairs should be isolated before powering down an Axiom system. Doing so will reduce the communication between Axiom systems hosting the replication pairs during startup.

If SAN replication pairs are not isolated before a shutdown or a power loss does not allow time to isolate the pairs, the following procedure should be followed to shorten the time to start up the Axiom systems that have configured replication pairs:

1. Start up one Axiom system and then run the `start_session` command against that system.
2. When that command completes successfully, repeat Step 1 for all remaining Axiom systems participating in SAN replication.
3. After all systems have successfully started, run the `start_replication_pair` command for all replication pairs.

9.34 System Scaling

You may increase storage capacity on a system by adding components and increasing assigned capacities. You may not decrease storage capacity of a system without the help of a Pillar Data Systems authorized representative.

9.35 Running Slammer Diagnostic Tests from the GUI

When you run diagnostics on a Slammer through the GUI, read the instructions and warnings concerning the removal of external cables.

Note: Slammers always run diagnostics when powered on or restarted. Hence, you should not need to run diagnostics unless instructed to do so by a Support Engineer.

As the diagnostic executes, resources on the Slammer control unit (CU) will fail over to the other CU. The CU being tested will go offline, which generates an Administrator Action indicating that the CU has failed. The system status will show Critical.

If the diagnostic passes:

- The Slammer CU is placed online, the Administrator Actions are automatically deleted, and the system Status shows Normal.
- For SAN Slammer CUs, all resources will automatically fail back.
- For NAS Slammer CUs, if automatic failback has not been enabled, you need only execute the Administrator Action associated with the failed over CU to fail back the resources to the CU that has successfully completed diagnostics.

Important! Do not attempt to run Diagnostics on more than one Slammer CU at a time or when the system is busy. Doing so may cause additional resources to go offline.

9.36 Information Screens for Slammer Power Supplies

In the System Health screens for the Slammer Components, the information fields for Slammer power supplies are intentionally blank.

9.37 GUI Accurately Displays the Status of Components

In earlier releases, during system or core restart, all components would show a status of "Booting". The GUI now more accurately displays the status of the components as they are discovered and initialized by the management software.

- During a Pilot restart:
 - The typical initial display shows the active Pilot CU as Booting. The standby Pilot CU may show Warning, Offline, or Booting, then transition to Online when start-up finishes.
 - Slammers initially show as Unknown as the Pilot software checks their functional status, then show Normal if the Slammers are still running.
 - Bricks show as Offline or Unknown and then transition to their true status as soon as the Slammer check completes.
- During a system restart:
 - The initial Slammer state shows as Unknown and then proceeds to Boot State Ready, Booting, Booting 0xnnn, and then Online as the Slammers are discovered and initialized.
 - The initial Brick state shows as Offline and then Booting as the storage enclosures are discovered and initialized.

9.38 Cause of Degraded Status for a Volume Has Changed

Beginning with release 4.0, a failed, missing, or pulled drive will not by itself cause a logical volume to become degraded. Only an inability to write to the mirror in a doubly redundant volume will result in a degraded status.

The inability to write to the mirror can occur because a Brick that underlies that mirror is not available or is not communicating, or a RAID LUN has faulted.

9.39 A Drive May Display Blank Data in the GUI or Create an Administrator Action

Drives are validated by the Pillar Axiom system. In some cases, the following may occur:

- The GUI may report a blank part number or serial number for a drive and, occasionally, a "Cannot read" status for that drive. However, the system will perform normally.
- The system generates an Incompatible Hardware Administrator Action. In this case, contact the Pillar World Wide Customer Support Center for assistance in replacing the drive or resolving the Administrator Action.

9.40 Changing Components

Use Guided Maintenance in the GUI when changing hardware components. Guided Maintenance provides instructions for you and performs tasks to get the system ready for the component replacement. Make sure to follow the instructions provided.

Notes:

- Adding memory to existing Slammer CUs in the field is not supported in this release. Contact your Account Representative for assistance.
- Replacing Brick and Slammer chassis are not supported in this release. If you have attempted to replace a Brick chassis, contact the Pillar World Wide Customer Support Center for assistance in recovering.

9.41 Alternative to Guided Maintenance Identify Step for Pilots

Do not rely solely on the Pilot Identify process during Guided Maintenance. That process uses the hard drive LED as the method to identify the selected pilot and, depending on the activity on the Pilot control unit (CU), it may not be possible to identify clearly which CU is being beaconsed.

The best method to identify a Pilot CU is to match the serial numbers reported in the GUI with the labels on the Pilot CUs.

9.42 Pilot CUs Must Not Be Powered On Independent of Replacement Procedures

After receiving a replacement 1U Pilot control unit (CU), do not power it on outside of the Pilot replacement procedure documented in the *Pillar Axiom Service Guide*. If a Pilot CU is powered on prematurely, you must contact the Pillar World Wide Customer Support Center. Also, when you need to replace a Pilot CU, contact the Support Center for assistance.

9.43 Differentiate Between FC RAID Bricks and FC Expansion Bricks.

The system must be able to tell one Fibre Channel (FC) Brick from another. The thumbwheel in the ES component at the back of a FC Brick enables you to make this distinction. As such, you must set the FC RAID Brick thumbwheel to 0 and the FC Expansion Brick thumbwheel to 1.

9.44 Replacing a Drive

When replacing a drive, always use a new one from Pillar Data Systems.

- Do not reseal a drive unless instructed to do so by the Pillar World Wide Customer Support Center.
- Do not attempt to replace a failed drive with one from another Brick or from another Pillar Axiom system.
- If testing Drive Pull, wait a few seconds after removing the drive before reinserting it. Be sure to check for Administrator Actions to accept the drive.

Important! You should contact the Pillar World Wide Customer Support Center before pulling a drive for test purposes.

- If a drive fails to be accepted into a Brick and the drive is set to Rejected status, do not attempt to use that drive. Contact Pillar Data Systems for another drive and for assistance.
- If an Administrator Action asking you to accept the drive is generated, be sure to select the Accept Drive option, which will initiate a copyback operation.

Important! If an Administrator Action to Accept a Drive is ever answered negatively, do not attempt to use that drive again. Contact Pillar Data Systems for another drive.

Contact the Pillar World Wide Customer Support Center for a new replacement drive.

9.45 Moving Drives

Do not move drives from their original positions. If you move a drive, all data on that drive will be lost. If multiple drives are moved, you will lose data.

If a drive is defective, use Guided Maintenance in the AxiomONE Storage Services Manager GUI to replace the drive.

9.46 Reseat Drives before Powering On New or Replacement Bricks

The drive latch may appear to be fully latched, but sometimes the drive is not making good contact with the Brick chassis midplane. With poor contact, the drive will fault, and the GUI will typically display a state of Unknown for that drive:

```
Drive 06 05_Fault 00_Unknown
```

To prevent loose drives and as a precaution, before powering on a new or a replacement Brick, visually inspect each drive to verify that they are fully seated.

If a drive is not fully seated, either or both of the following will be true:

- The metal portion of the carrier will be visible.
- The front of the drive carrier will not be flush with the other carriers.

To seat an improperly seated drive, perform the following steps:

1. Press on the drive to latch them.
2. Press the drive carrier firmly until it snaps into place.
3. Snap shut the latch to lock the carrier in place.

Important! Do not unlatch and re-latch a drive carrier unnecessarily. Doing so can lead to potential troubles in the future.

9.47 Testing Multiple Drive Failures

Important! Do not test multiple drive failure scenarios in the same Brick storage enclosure without contacting the Pillar World Wide Customer Support Center for guidance.

9.48 ACT LEDs on Drives Can Blink When Inactive

When there is no I/O activity on a Brick storage enclosure, the RAID firmware runs a background operation that scans all drives for media errors and, if media errors are found, performs repair operations. This background activity causes the ACT LEDs to blink green on the idle system or Brick. Such activity can take several hours to complete. When host I/O resumes, this background operation stops; it resumes only when there are no further I/Os from a host.

9.49 Replacement of Brick Storage Enclosures

To avoid data loss, contact the Pillar World Wide Customer Support Center before you attempt to replace an entire Brick storage enclosure or Slammer storage controller. The Support Center can help you determine whether a particular filesystem or LUN is physically on the Brick.

9.50 Adding a Brick Generates Error and Warning Messages

When you add a Brick storage enclosure to an existing Pillar Axiom system, the system begins the process to bring the Brick online. While the system is bringing the Brick online, you will see the message: Topology Discovery Task.

Also, you may see a series of error and warning messages similar to these:

- Fibre Channel RAID Array Inaccessible
- Fibre Channel Path to Brick Failed
- Software Update Succeeded

These messages are normal and to be expected. During the bring-up process, the status of the Brick will go from red to yellow to green. After the system completes the process, the Brick will show a Normal status and will remove all Administrator Actions related to adding the Brick. If any Administrator Actions remain, contact the Pillar World Wide Customer Support Center.

9.51 Priority QoS Bands and Fibre Channel Bricks

As of release 3.1, Fibre Channel (FC) Bricks support the bleed up of lower-performance bands from SATA to FC storage in a mixed SATA/FC system. Furthermore, you can create one logical volume having a non-Premium QoS that occupies all SATA and all FC Bricks. Logical volumes having a Premium QoS setting, however, are constrained to FC Bricks.

As of release 4.1, such bleed up is no longer supported. Release 4.1 introduces the Storage Class feature, which only allows legacy volumes to grow or in-fill using the Brick type on which the volume was originally created. This feature does not automatically move legacy volumes to return them to their original Storage Class. If the Axiom system has a volume that has bled upwards, if you want to resolve it, contact the Pillar World Wide Customer Support Center.

CAUTION! After updating to release 4.1, a legacy thinly provisioned volume that has bled upward will not grow. This situation may cause data loss or pinned data if not resolved. This condition can be determined with a pre-upgrade audit and the Customer Support Center can offer assistance with resolving this type of issue.

All *new* volumes created in release 4.1 consume capacity only from within the Storage Class (Brick type) in which it was created.

9.52 Testing RAID Rebuild and Simulated Drive Fault

You can use Guided Maintenance to identify a Brick and to show the location of an individual drive for testing drive pulls. But the “Prepare System” and “Replace Hardware” functions should not be used when testing or demonstrating RAID rebuild and drive replacement where the existing drive is to be removed and then re-installed.

The Guided Maintenance process is intended for use only when a drive, or other FRU, has encountered a fault and is to be replaced with a new drive or other FRU. If Guided Maintenance “Prepare System” and “Replace Hardware” is used to replace a drive, you will be instructed to remove and replace the drive. The Pillar Axiom system may defer any further actions on the Brick until this is done, which may result in the Brick Redundancy repair actions not being initiated properly.

To test Drive Fault, simply pull the drive. Wait a few seconds until drive activity is observed on either the top or bottom drive LEDs on all other members of that RAID array, then carefully reinsert the drive and make sure it is fully seated and latched in place. The background tasks to rebuild the array and then copyback the array data to the re-inserted drive should start automatically and be displayed within a few minutes, depending on overall system activity. If an Administrator Action to accept the drive is displayed, be sure to select “yes” to accept the drive.

If a drive is genuinely faulted, use the Guided Maintenance menus to Identify the Brick, note the position of the drive in the Brick, Prepare the System for replacement, and then “Replace Hardware” to remove the old drive and replace it from spares as instructed.

9.53 Brick Issues Can Cause a Slammer to Warmstart

The Array Manager software component in Pillar Axiom Slammers requires a quorum of successful I/O for its metadata processing. Sometimes a quorum cannot be met because some Bricks return a Busy state due to underlying issues on the Bricks. After a number of unsuccessful retries, the Array Manager can fail a health check and cause the Slammer to warmstart.

In these cases, when you resolve the underlying Brick issues, the array manager will be able to successfully access metadata. To help avoid Slammer warmstarts, ensure that all drives are functioning and Bricks remain operational.

9.54 Testing Brick Power Loss

Pillar Professional Services can assist in testing power loss to Brick storage enclosures.

Use the GUI Guided Maintenance screens for testing any power cycle of a solid-state drive (SSD) Brick.

CAUTION! Testing the power cycling of Brick001 or Brick002 can cause the Axiom system to shut down.

9.55 Use Care When Recovering a Faulted Data LUN in a Brick

In any given Brick storage enclosure, if there are enough drive failures that cause a data LUN on that storage enclosure to fault, care should be used in recovery.

When the drives are replaced, as soon as enough drives become available to allow the Pillar Axiom system to perform a `RecreateRAIDArray` task, the system generates an Administrator Action.

CAUTION! Do not accept this Administrator Action on Brick001 or Brick002, because the acceptance may render the Axiom system inoperable, and cause it to shut down. As a safety measure, contact the Pillar World Wide Customer Support Center before accepting the Administrator Action.

If you do not accept the Administrator Action, in most instances the Support Center may be able to recover any data that may have been lost. To do this, all internal fabric connections to the Brick must be disconnected during the recovery; otherwise, the system will detect the recovered drives and proceed with the creation of a new blank LUN.

If the data on the Brick is non-essential, accept the Administrator Action, in which case all data on that Brick LUN will be permanently lost. You can then replace the data or delete the affected volumes.

9.56 Creating Logical Volumes Immediately After Replacing a Failed Drive

When a failed drive in a Brick storage enclosure is replaced, the system copies the data temporarily stored on the spare drive to the drive replacement. This write operation is called *copyback*. When the copyback operation starts, the unused storage on the affected Brick temporarily becomes unavailable for new allocation. This condition is necessary to guarantee that the unused space is correctly reconditioned.

Approximately once a minute, the Slammer updates the active Pilot control unit with allocation information. If a request for a new allocation happens to arrive during the same minute the copyback operation started, a discrepancy can exist between the allocation information on the Pilot and that on the Slammer. If the discrepancy is large enough to make the difference between success and failure of the allocation, the Pilot can believe the allocation request will succeed, even though the Slammer will fail the request. If this situation occurs, the allocation request appears to fail for no reason because it seems enough free space exists.

If the same request is re-submitted a minute later, after the Pilot has received the next update from the Slammer, the request will correctly fail because the Pilot now has the information that the free space produced by the copyback operation is not available. After the copyback operation has made enough progress in reconditioning enough free space, that same allocation request will succeed, as it would have if there had been no copyback operation.

9.57 Persistence Vulnerability in Single-SATA Brick Systems

When a factory-fresh, single-SATA Brick system is first powered up, Persistence (which is the Axiom data store containing many system settings) will be configured on that Brick. Persistence will be doubly-redundant with both instances residing on the same Brick (on two data LUNs). If additional Bricks are added later, Persistence will not be migrated to locate the different copies on separate Bricks for higher protection against single-Brick failure.

Important! The Persistence store will still be vulnerable to that original, single SATA brick going offline, as will user data.

9.58 Replacing a Slammer Motherboard Can Cause Several Status Changes

When replacing a Slammer motherboard tray, while the new tray is inserted and powered on, the GUI may initially show the new motherboard status as green (Normal), indicating that the motherboard is functionally OK.

While the Pillar Axiom system attempts to place the new motherboard in service, it will check the Slammer PROM version to see if it matches the installed software version. If necessary, the system updates the PROM to match the current software package version. If the update occurs, the GUI may change the status of the new motherboard to red, because the FRU is offline during the PROM upgrade process, which takes a few minutes. If the upgrade completes successfully, the GUI shows the status of the new motherboard as green and restores it to service if configured to do so.

As the new motherboard is brought online, the Axiom system attempts to perform a failback operation on that motherboard. The system checks the PROM version during the failback sequence and, if necessary, updates the PROM. When PROM update completes, the system resets the Slammer CU, which causes the CU to go offline and then go through the failover-failback sequence again. This double failover-failback sequence is normal for Slammer motherboard replacements, if the revision currently installed on the Axiom system is higher than that on the replacement motherboard.

If the preceding operation succeeds, the Slammer CU status becomes Normal and is brought online automatically for SAN Slammers. NAS Slammer CUs are brought online automatically only when the global setting for failback of NAS resources is configured (see Enable Automatic Failback of NAS Control Units in the GUI).

Important! Do not attempt the Verify function during Guided Maintenance of a Slammer motherboard. The verification will fail.

Important! Do not run Slammer diagnostics without explicit instructions and assistance from the Pillar World Wide Customer Support Center.

9.59 Testing Failure Recovery from Loss of Slammer Power

Testing failure recovery by removing all power from a Slammer in a dual-Slammer system may result in the remaining Slammer going offline or the system restarting.

The power inputs, power supplies, management paths, and control units in the Slammer are redundant, making this failure injection a multiple failure. Perform this type of multiple fault injection only when it is acceptable to lose the services of the remaining Slammer. Consider contacting Pillar Professional Services who can assist in testing Slammer failover through the use of a support-level CLI command.

9.60 Reverse Name Lookups for NFS Exports

NFS mount authentication time has been improved by adding reverse name lookups for NFS exports defined by hostnames. For this to be effective, you should configure external naming servers with the reverse records.

- DNS servers should be configured with PTR records for all client hostnames.
- NIS servers should be configured with host.byaddr records for all client hostnames.

Important: On the File Server Services tab, you should specify the appropriate order for “Host Name Resolution Search Order”. Name resolution policies must be applied consistently. Configure the reverse and the forward name lookup systems to provide matching names (both must return fully qualified names, such as “myhost.mycompany.com”, or both must return unqualified names, such as “myhost”). NFS mount requests may be rejected when a DNS server returns a fully qualified name and an NIS server returns an unqualified name.

For example, if the DNS server returns the host name as “myhost.mycompany.com”, the customer’s netgroup must have a membership list that includes the fully qualified name “myhost.mycompany.com”. Similar restrictions apply to name resolution by means of local files.

9.61 Mapping UIDs and GIDs to Those of the NFS "anonymous" User

To map all UIDs and GIDs to the anonymous user, create the following special export under any filesystem on the desired File Server: `/PleaseEnableAllSquashFeature` (this special path does not have to exist).

Then, set the Anonymous User ID to the desired value.

The userID and GroupID for all users, including root, on any host defined with this export will be treated as though they were the configured anonymous user ID.

Normal user and root semantics and permissions will apply to any host that is not included in this export.

All exports listed after the `/PleaseEnableAllSquashFeature` export will map incoming UIDs and GIDs to the one specified under the UID field for the special export.

Setting the "Root Access" for a host will disable all mapping for that host, even though the special export exists.

9.62 Deleting Files from a Full Filesystem with Snapshots

If a filesystem containing snapshots is allowed to completely consume the allocated space, it may become impossible to delete files from that filesystem to recover space.

Snapshots consume space from the original filesystem allocation in order to preserve QoS. If a file is deleted, the data from that file would need to be placed in the appropriate snapshot copies to preserve the integrity of existing filesystem snapshots. If there is no space left, the file deletion will be failed in order to preserve these views.

To delete files from such a filesystem, delete one or more snapshots to recover filesystem space, or allocate more space if there is storage available in the current or higher QoS pool.

9.63 Uploading Empty Files Not Allowed

You cannot upload empty files (zero bytes) to a Pillar Axiom system. This restriction applies to all system interfaces where a file upload is allowed.

9.64 Filesystem Checking (FSCK) and Consistency

In this release, FSCK is fully functional in repairing filesystems.

As an additional data protection measure, when a filesystem is created, the default behavior is to create a four-hour snapshot schedule for the filesystem. These snapshots are recommended, because in rare circumstances, the FSCK may fail to repair the filesystem and will provide an Administrator Action choice to revert the filesystem to a snapshot or to delete the filesystem. In addition, Pillar recommends that you create daily, weekly, and monthly snapshots.

If the repair is unsuccessful and there are no available snapshots, you may still place the filesystem online for recovery of the data. Exporting such a filesystem read-only for this recovery is recommended. Contact the Pillar World Wide Customer Support Center if this occurs or before deleting a filesystem due to a failure of the filesystem check.

You have the option to place the filesystem online to revert to a known good snapshot to avoid a lengthy FSCK. Contact the Pillar World Wide Customer Support Center for assistance in determining candidates for good snapshots before reverting in this manner.

If the filesystem becomes inconsistent and a Snap FS exists, FSCK can revert the filesystem back to when the snapshot was created. Any data saved, stored, or modified on the filesystem after the snapshot was created will be lost.

The snapshot frequency defined by a Snap FS schedule is also important. The time lapse between when a Snap FS was created and the discovery of filesystem inconsistency determines how much data will be recovered should the filesystem need to be reverted.

If filesystem inconsistency is detected, the system performs the following:

1. Takes the filesystem offline so that no further changes can be made to the data.
2. Generates an Administrator Action that provides multiple options to the administrator:
 - Perform a filesystem consistency check.
 - Delete the filesystem.
 - Revert to a previous snapshot.
If you choose this option, all changes to the filesystem between the time of that snapshot and the time the filesystem issue was detected is lost.

3. Checks the filesystem for consistency.
 - If the filesystem is consistent, the check is complete and FSCK automatically puts the filesystem online.
 - If the filesystem is inconsistent, FSCK takes one of these courses of action:
 - If the filesystem is fixable, FSCK fixes it and puts the filesystem online.
 - If the filesystem is unfixable, FSCK performs the following actions:
 - Reverts the filesystem to an earlier snapshot.
In this case, FSCK reports “FSCK Complete” along with the snapshot ID.

Note: Any data saved, stored, or modified between when the snapshot was taken and when the filesystem issue occurred will be lost.
 - Verifies the consistency of that snapshot.
If it is fixable, FSCK fixes it and puts the filesystem online; otherwise, FSCK repeats the above steps.

Note: If no good Snap FSs exist and the initial FSCK fails to recover the filesystem, it is recommended that you *not* delete the filesystem but instead contact the Pillar World Wide Customer Support Center. The Support Center may be able to help you recover the filesystem.

Once the consistency check is complete and the filesystem is online, end-users may need to remount the filesystem so they can reconnect.

Important! If you perform a filesystem check on a filesystem, please contact the Pillar World Wide Customer Support Center to clear your logs once the situation has been resolved. Failure to clear logs may result in the Axiom system not being able to collect Slammer logs for future issues.

We strongly recommend that you run only one FSCK process at a time. Even though multiple FSCK processes will queue, the best practice is to check a single filesystem and wait until that check completes before starting a subsequent FSCK process.

9.65 Increasing Redundancy Requires More Space Than Requested

When increasing the Redundancy QoS parameter of a filesystem, the actual amount of additional space the system allocates for the increased redundancy is typically greater than what is requested. For example, you should expect that, when increasing the redundancy of a filesystem to Double, the system could allocate an additional 2 GB.

9.66 Creating Quotas on Non-Empty Directories

When creating a quota on a non-empty directory, you have a choice of allowing the filesystem to go offline temporarily or failing the quota request.

- *Allow the filesystem to go offline.* The system takes the filesystem offline temporarily to calculate quota usage of the directory. The system traverses the entire directory and counts the number of blocks consumed by the directory. The duration of the offline state of the filesystem depends on the number of objects contained in that directory.
- *On empty directories only.* The system tells you about any non-empty directories and fails the quota request in those cases. These quotas can be implemented when taking the filesystem offline is acceptable or by creating a new directory and quota and moving the data to the new directory.

9.67 CIFS Support

A File Server can act as a native member server to an Active Directory environment or emulate a Windows NT member file server.

In the Active Directory environment, Kerberos authentication is supported. A DNS server is required for name resolution, and a Domain Controller is required to provide Active Directory support and to act as the Kerberos Key Distribution Center (KDC). Customers that have implemented higher security policies should be aware that LDAP signing is not supported (the Pillar Axiom CIFS server cannot join the domain when "LDAP server signing requirements = Require signing" is specified on the Domain Controller).

As a Windows NT member file server, NTLM authentication is supported. It uses NetBIOS naming services and requires a Domain Controller and WINS server with static IP addresses and legal NetBIOS names.

A File Server may be used in Windows 2000 or Windows 2003 domains with some special configuration requirements. These requirements are discussed in the *Windows Integration Guide for NAS Systems*.

A File Server may also be used in Windows 2000, Windows 2003, Windows 2008, and Windows 2008 R2 domains.

Furthermore, File Servers also support Windows 7 and Vista clients.

Additional CIFS features will be supported in future releases.

9.68 Domain Local Groups Cannot Be Used in Mixed-Mode Domains

In Windows configurations that are using mixed-mode domains, if Access Control Lists (ACLs) of the domain local group are applied to share objects, access to the objects on the share can fail. This limitation is correct domain client behavior, as defined by Microsoft. See <http://support.microsoft.com/kb/296369>.

Here are some possible alternatives:

- Use domain global group ACLs instead of domain local ACLs on share objects.
- Refrain from applying domain local ACLs on share objects.
- Upgrade the domain from mixed mode to native mode.

9.69 Create CIFS Share

This release implements the `\\<fileserver-name>\IPC$` administrative share, which allows CIFS clients to browse the filesystems that are shared by a File Server. Pillar Axiom systems do not automatically create the `C$`, `D$`, and `<share-name>$` style hidden administrative shares. If these shares are desired, share the filesystem as `C$`, `D$`, and `<share-name>$`. For example, to create a hidden administrative share for a filesystem named `foo`, create a share named `foo$`.

9.70 Sort Order on Pillar Axiom Systems Differs from Native Windows

When using `dir` to list directory contents, specify the requested sort order by means of the command parameters. For example, to order by name, use:

```
dir /on
```

Some CIFS clients, such as Windows Explorer, sort lists of files and directories in a specific order. Other applications, like the `dir` command, default to return the list in the internal order maintained within the File System.

The Windows NTFS File System appears to maintain files sorted alphabetically. The Windows FAT File System does not. The Pillar Axiom File System also does not maintain a default alphabetical sort sequence.

As a result, the Pillar Axiom sort order may differ from native Windows when viewed through some applications. A list of files produced with the default options of the `dir` command do not return a list sorted alphabetically.

9.71 DHCP Behavior on the Pilot

In the current release, the DHCP feature has the following behavior characteristics:

- Dynamically assigns only the public IP address of the Pilot.
- Locks the two private IP addresses.
- Retains DHCP settings during a Pilot failover.
- If the IP address is updated through `pdscli`, the updated address and the status of the DHCP setting are not reflected in the GUI until the Pilot restarts or fails over.
- Updates the values correctly without a need to restart when you change back to static addresses.

Note: You should configure the two private IP addresses to be on the same network as the dynamically assigned public IP address; otherwise, the private interfaces may not work.

If DHCP is enabled on the Pilot and DNS lookup is available on the management console, you can log in to the Pillar Axiom system using the system name rather than its IP address.

9.72 Changing Slammer Port IP Addresses from Static to Dynamic

When changing the IP address from static to DHCP, the change is not instantaneous. The static IP address is retained until a lease is obtained and the system refreshes the status. In other words, the GUI will experience a delay in reporting the newly acquired DHCP address when you change a port from static IP to DHCP.

9.73 VSS Provider Event Numbers Incorrectly Mapped to Descriptions

For VSS Provider events sent to the Windows event log, the VSS Provider plug-in doesn't correctly set the mapping of event number to event description. However, when you click on the event to see its properties, the event text is viewable.

9.74 Disabled/Excluded Slammer States

Repeated failure of a Slammer control unit (CU) can result in that CU becoming non-operational. If the repeated failures occur during normal operation of the Pillar Axiom system, the system marks the CU as Disabled; if the failures occur during startup, the system marks the CU as Excluded. This behavior may be triggered by repeatedly testing power failure simulation for Slammers.

If the system completes startup successfully, it will attempt to remove each Excluded Slammer control unit (CU):

- After startup completes, the CU should transition to Failed Over.
- If the CU is part of a SAN Slammer, the system should then attempt to transition the CU to Failback as long as the buddy CU on that same Slammer is online. If the Failback succeeds, the system puts the CU Online. If the Failback fails, the system repeats the failover-failback sequence until the Slammer CU failure threshold (*see Section 9.75 below*) is reached. If that threshold is reached, the CU will be Disabled.
- If the CU is part of a NAS Slammer and automatic failback is *not* enabled, the system attempts to transition the CU to Failed Over and leave it there for recovery.
- If automatic failback of NAS Slammer resources *is* enabled, the system attempts to transition the CU from Excluded to Failed Over to Failback and, if that succeeds, the system puts the CU online.
- If the CU is not detected, but the other CU is active, a missing CU may show a status of Failed Over when it is really Offline, as in powered down or not connected to the private management network.

Note: Contact the Pillar World Wide Customer Support Center for assistance in recovery of Slammer CUs that have been marked Disabled.

9.75 Hardware Lockout Due To Repeated Power Cycling

IMPORTANT! Do not repeatedly power cycle a Pillar Axiom system or any of its hardware components. Doing so may automatically trigger the hardware-fault lockout mechanism. The current thresholds for repeated power cycles are:

- Two power cycles in a 1-hr period
- Three power cycles in a 24-hr period

If either of these thresholds is exceeded, the affected hardware component may be locked out (Disabled).

Note: The above thresholds and Disabled status apply to repeated failover-failback sequences as well.

Contact the Pillar World Wide Customer Support Center for assistance in recovering and restoring the components to service.

9.76 Powering Off a Pillar Axiom System

If you expect to shut down the system for longer than 12 hours, you should remove the batteries from the Slammer after you power off the system. Reinstall the batteries before restarting the system.

CAUTION! Make sure the system has been placed in Shutdown status before powering it down or removing the batteries; otherwise data loss may result.

9.77 Battery Removal

When removing a Slammer battery, be sure to use Guided Maintenance. After you click the Prepare System button in the GUI, Guided Maintenance prepares the system for replacement of the battery:

- Flushes cached data to the Bricks.
- Places the target CU in conservative mode.
- Powers down the battery charger.

After the system is prepared, Guided Maintenance displays a completion message and enables the Next button. At that point, you can safely remove the battery.

9.78 Battery Insertion

After the insertion of a battery into a Slammer control unit, the battery will show a Warning status in the GUI for a period of time. How long the Warning status remains depends on the charge level of the battery. The time can be up to 18 hrs for a severely discharged battery. If the battery takes longer than 18 hrs to reach a full charge, you should replace the battery. Contact the Pillar World Wide Customer Support Center for assistance in checking the state of the batteries or for a replacement.

9.79 Slammer Warmstart and Startup Failure Handling

Slammer CUs have independently maintained fault thresholds. If any of these are exceeded, the system will disable the Slammer CU to allow the rest of the system to continue operation:

- If a Slammer CU warmstarts four times in one hour, it will fail over. If there is a successful failback, the warmstart history count will be cleared.
- If a Slammer CU fails three times in one hour or four times in one week, it will be disabled.
- If a Slammer CU fails during the startup process, it will be Excluded from the startup. If the system startup succeeds, the system will attempt to recover the CU with the failover/failback process. If that fails, the CU will be disabled.

Contact the Pillar World Wide Customer Support Center for recovery assistance for any Slammer CU that is Excluded or Disabled.

9.80 Preventing Filesystem Corruption Due To Multiple Component Failures

In the unlikely event that more than one drive has failed, filesystem corruption may occur. To avoid this possibility, take advantage of the redundancy and availability options available when creating filesystems.

9.81 When Pinned Data Is Not Written to Stable Storage

Pinned data is the data stored in Slammer cache in the event of the failure of both control units or one of the arrays; this data cannot be written to stable storage. If the conditions are resolved but the pinned data is not written to stable storage, contact the Pillar World Wide Customer Support Center.

9.82 Feature License Reconfiguration

When you change the feature license configuration on a Pillar Axiom system, the AxiomONE Storage Services Manager (GUI) will restart and you will need to log back in. Wait for several minutes before logging in to give the system time to reconfigure; otherwise, you may receive a Page Not Found error.

9.83 Hardware Component States

The state of Slammers, Bricks, and the Pillar Axiom system may not update correctly if the Pilot receives hardware events in rapid succession. To view these hardware states, wait 15 sec. If the AxiomONE Storage Services Manager does not show updated states correctly, refresh your browser display.

9.84 NDMP Backup Operations on Full Filesystems

As an NDMP backup operation begins, the system takes an immediate snapshot of the filesystem. This snapshot is the NDMP data source for the backup. At the end of the backup operation, this snapshot is deleted. Working from this snapshot allows clients to use the filesystem during the NDMP backup operation.

If the filesystem is full, the backup operation may fail or it may be impossible to delete files from the original filesystem during the backup operation, because the data from those files would need to be stored in the backup image snapshot.

The space allocated to the filesystem should be increased to allow any data that is modified or deleted during backup operations to be safely stored in the snapshot created for the backup. If it becomes necessary to recover space, delete any unnecessary snapshots and wait for the space to become available. If there are no snapshots, delete at least 16 KB of data prior to running the backup.

9.85 NDMP DMAs May Disable Tape Storage Devices During a Software Update

Updating system software may cause tape drives or libraries attached to a Pillar Axiom system to go offline. For example, VERITAS has designed their products to take the tape storage devices down the first time a problem appears. In this case, use the administrative tools provided by your NDMP-based data management application (DMA) to bring the tape storage devices back online. If you need assistance, contact the Pillar World Wide Customer Support Center.

9.86 NetBackup 6.5 Can Fail When Running on 64-bit Windows Servers

Some NetBackup 6.5 installations on 64-bit Windows Servers may experience failures during NDMP backup operations. The failures will typically occur at the very end of the backup job. To avoid these failures, upgrade to NetBackup release 6.5.4.

9.87 Point-in-Time Volume Copy Space Allocation

The system can use point-in-time Volume Copies to support NDMP backup requests against non-WORM filesystems. When using an NDMP Volume Copy, there is an additional space limitation above the amount required for file-based NDMP backups. The Volume Copy implementation requires an additional amount of storage equal to the maximum size of the filesystem being backed up.

9.88 Jumbo Frames

To implement jumbo frames, be sure that all Ethernet NICs in all systems, Ethernet switches, local router interfaces, and all other network devices on the same local networks as the Pillar Axiom system are capable of supporting jumbo frames and are configured for the same effective MTU.

Refer to your switch documentation for information on prerequisite software and firmware and for instructions on configuring the switch for jumbo frames. Refer to the documentation for the NIC interface in all client systems and other network devices for information and restrictions on configuring jumbo frames.

The performance boost with jumbo frames will be most noticeable for client systems with slower processors or interrupt handlers that may benefit from the lower interrupt rate offered by jumbo frames. The increase in performance will be most noticeable for single-client stream data transfers.

9.89 Link Aggregation over Fast and Gigabit Ethernet Switches

Link aggregation groups several network links into a single logical link. Link aggregation provides load balancing and fault tolerance for multiple Ethernet links. Using extensions of Ethernet auto-negotiation, the link partners exchange MAC control frames to provide for load balancing and link fault detection.

To make use of link aggregation on a Pillar Axiom system, be sure that:

- All ports that will be used for a given logical aggregated link are on the same Slammer control unit (CU). Ports from multiple Slammers or Slammer CUs must not be configured into the same aggregation group.
- Many Ethernet switches require that all links in an aggregated link be on the same blade or Ethernet controller chip. Consult the switch vendor's documentation for restrictions.
- The Slammer connects to a 100/1000 BaseT switch that has Auto-speed enabled.
- The Ethernet switch must conform to the IEEE 803.2ad link aggregation standard and use link aggregation control protocol (LACP) for managing the links.
- The Ethernet switch should be configured to actively advertise link aggregation capability. The Slammer ports will respond to but not advertise link aggregation.

Note: To provide for continued operation in the event of a Slammer CU failover, if link aggregation is enabled on one Slammer CU, it should also be configured on the partner Slammer CU.

9.90 Vulnerability Scanners May Report False Positives

The Pilot management controller is protected by means of a firewall to help prevent unauthorized access. Some vulnerability scanners may report a false positive by claiming a large quantity of UDP ports are open when in fact they are not.

9.91 OpenSSH Has Some Vulnerabilities

The Pilot uses a version of OpenSSH (OpenBSD Secure Shell) that has several known vulnerabilities. However, for someone to gain access to a Pilot, they would need to successfully perform the following actions:

1. Gain access to the data center network.
2. Install an Encrypted License from Pillar Data Systems using the Primary or an Administrator 1 account.
3. Enable SSH access for the Support account using the Primary or an Administrator 1 account.
4. Use the Support Administrator login credentials to gain access to the Pilot. The Support Administrator must issue a command to enable SSH.

It is unlikely that anyone would be successful in performing those four actions. Furthermore, Pillar addresses security vulnerability in these ways:

- Pillar Axiom systems disable Secure Shell (SSH) access by default.
- Pillar Axiom systems recognize only certain listening addresses for the ports.
- Pillar Axiom systems use shell programs that exist in the cgi-bin directory associated with the web server only to bring up the main GUI login page and to identify whether the login is secure.
- Pillar Axiom systems do not install the source.asp file available for Apache web servers.
- Pillar Axiom systems do not use the Active Server Pages (ASP) feature that runs under mod_perl for Apache servers.
- The Apache modules that Pillar Axiom systems do support are as follows:
 - alias_module
 - auth_basic_module
 - authn_default_module
 - authn_file_module
 - authz_default_module
 - authz_groupfile_module
 - authz_host_module
 - authz_user_module
 - cgid_module
 - core_module
 - dir_module
 - env_module
 - filter_module
 - http_module
 - mime_module
 - mpm_worker_module
 - rewrite_module
 - setenvif_module
 - so_module
 - ssl_module
- Pillar Axiom systems will support the latest version of OpenSSH and SSL in an upcoming release.

9.92 Shutting Down a Pillar Axiom System

In some cases, when you attempt to shut down the system, the system may not shut down but instead return an error message. Before attempting a shutdown or restart, ensure that no background tasks are running. If you are unable to cancel a task, contact the Pillar World Wide Customer Support Center.

9.93 Login to Oracle EM Plugin Fails

The login to the Oracle EM plugin may fail even though you enter the correct username and password. This is fixed in Oracle EM release 10.2.0.3. When using earlier releases, place a blank character at the end of the password field, which will enable the login to work correctly.

9.94 Changes to Host Associations and LUN Mappings

Release 02.07.00 introduces many changes to host associations and LUN mappings for the AssociateInitiatorsToHost feature and to APM.

The GUI page for PerformAssociateInitiatorsToHost enforces many of the changes. For example, Modify can no longer be used to change the name of an Associated host. It also prevents the user from associating an already associated Initiator/port without first removing its association.

9.94.1 Definitions

Initiator. Equivalent to a port (WWN) when using FC or IQN when using iSCSI.

Wrapper host. A host with a single Initiator and has the same name as the Initiator. It is created internally by the Pillar Axiom system when an Initiator is discovered.

Associated host. A host that the user has created with the PerformAssociateInitiatorsToHost request (one or more Initiators). This request is referred to as *PAITH*.

APM host. A host created from a PerformConfigureSANHost request from APM (one or more Initiators). This request is referred to as *PCSH*.

The Pillar Axiom system always creates a Wrapper host for all discovered Initiators and moves each according to Associations and/or APM relevance. A user can map to all of these hosts.

9.94.2 Behavior

9.94.2.1 Moving an Initiator from a Wrapper Host

When an Initiator belonging to a Wrapper host is moved into another host by either a PAITH or PCSH request, the LUN mappings of the Wrapper host are moved to the new host and removed from the Wrapper host. The Wrapper host is deleted. The original mappings belonging to the new host are unaffected. Mappings from the Wrapper host that conflict in LUID or Number with mappings in the new host are deleted and a LUNMappingDeleted event is generated.

9.94.2.2 Moving an Initiator from an Associated Host

When an Initiator is moved from an Associated host by a PAITH request, the mappings of the previous owner Associated host are removed from the Initiator, and the Initiator is mapped with the mappings of the new owner Associated host. The old owner Associated host (even if it has no Initiators left) is left with its LUN mappings in place. No mappings associated with any old owner Associated host are moved to the new Associated host.

The old host must be manually deleted if it's no longer needed.

9.94.2.3 Using PCSH to Move an Initiator to an APM Host

An Initiator can be moved to an APM host from an Associated host or from another APM host by a PCSH(V2) request. For the previous Associated host, its mappings are moved to the new APM host. For the previous APM host, its mappings are not moved to the new APM host.

Important! When moving an initiator to an APM host, APM on the new host (and on the previous owning APM host, if applicable) must be able to log in to the Pillar Axiom system and achieve a "Communicating" status in the AxiomONE Storage Services Manager (see Storage > Hosts display screen). In this way, APM can exchange the necessary information with the Pillar Axiom system:

- The new APM host can report the initiator to the system (but not get the LUNs unless they too have been moved).
- If applicable, the previous owning APM host can remove the initiator(s) when it logs in to the system.

9.94.2.3.1 Moving an Initiator from an Associated Host to an APM Host

Mappings from the Associated host that conflict in LUID or Number with mappings in the new APM host are deleted and a LUNMappingDeleted event is generated. A LUNMappingCreated event is generated for each mapping successfully moved. All of the LUN mappings of the previous owning Associated host stay in place for that host, even if no Initiators are associated with the host.

The old Associated host stays in place until the user deletes it.

9.94.2.3.2 Moving an Initiator from an APM Host to another APM Host

The old mappings to the Initiator are removed and the Initiator is mapped to the configuration of the new owning APM host.

9.94.2.4 Combinations

For combinations, the processing goes from Wrapper host to Associated host to APM host with no order within the different types.

Example:

If an APM claims ownership of Initiators from a Wrapper, Associated, and APM host at the same time, mappings are moved from all Wrapper hosts to the APM host first, followed by moving mappings from the Associate hosts. Then the APM Initiator is moved and remapped.

9.94.2.5 Notes

9.94.2.5.1 Deleting a Host

When deleting a Wrapper, Associated, or APM host, all Initiators that are connected are wrapped with a Wrapper host and all of the LUN mappings belonging to the host are preserved with the new Wrapper host. No Wrapper host is created for a disconnected Initiator.

9.94.2.5.2 Renaming an Associated Host

To rename an Associated host while preserving the mappings, the Associated host must be deleted and then the Initiators can be associated with the new named host.

9.94.2.5.3 Renaming an APM Host

To rename an APM host while preserving the mappings, the APM driver must be stopped, the host deleted, and then the APM driver started with the new name.

9.95 Overloaded Systems Can Result in Multiple System Warmstarts

The Pillar Axiom Pilot software is multi-threaded, and the number of threads available for handling system events and user-requested operations is limited. When a large amount of system activity requires Pilot intervention, this maximum number of threads can become fully utilized, leaving no threads available for user-requested operations. An excessive number of requests for action can result in a multiple failed tasks and multiple warmstarts. Should this situation arise, wait until the number of system events requiring Pilot action is reduced, freeing up the Pilot for user-requested operations.

9.96 IPStor Fails To Recognize LUNs After a Full System Upgrade

IPStor systems do not recognize Pillar Axiom LUNs after a system upgrade from a Pillar Axiom 500 to a Pillar Axiom 600. IPStor systems recognize only the Pillar Axiom 500 as a valid target. To resolve this situation, request from your IPStor vendor the code update necessary for compatibility with the full Pillar Axiom product line.

Pillar Axiom 300 and Pillar Axiom 500 systems can be upgraded to the Pillar Axiom 600 platform. However, as you do so, Bytes 16-31 of the Inquiry Data response (the "ASCII Product Identification" field) for each LUN will change from "Axiom 300" or "Axiom 500" to "Axiom 600". This change may cause some SAN appliances, such as IPStor, and possibly some hosts to not recognize the LUNs unless the appliance or host is reconfigured.

10 Technical Documentation Errata

The following sections describe topics in the technical documentation that were not able to be corrected in time for the current release of the Pillar Axiom 300, 500, and 600 system software.

10.1 AxiomONE Replication User's Guide and Reference for NAS

On page 14, replace the second and third paragraphs with the following:

The AxiomONE Replication for NAS utility requires that the NAS Asynchronous Remote Replication license has been installed on at least one of the Axiom servers hosting a replication pair for replication to function. In addition to the actual NAS replication license, the replication utility depends on the following licensed features as well:

On page 67, in the DESCRIPTION section of the `establish` command, replace the second paragraph (which starts with "The `establish` command...") with the following text:

The `establish` command first initializes the history and then establishes the relationship. However, when the next synchronization request is a full synchronization (typically this is the initial `establish` request), the `establish` command first performs a license check before any other action. When the command completes, the output indicates that the license check passed, failed, or was skipped.

Note: The `establish` command skips the license check during the following operations:

- The direction of the relationship is being reversed.
- The relationship is being re-established

On page 81, in the SYNTAX section of the `sync` command, add the following option after the `retry_interval` option:

```
[allow_compliance_overwrite=overwriteOK]
```

On page 83, add the following text after the `retry_interval` option:

```
allow_compliance_overwrite
```

Specifies that the data contained in the target filesystem may be overwritten if it is a compliance SecureWORMfs instance. This option is only required on the first full synchronization of the target filesystem when it is a compliance SecureWORMfs instance.

Valid values for `overwriteOK` are:

yes

Allows the command to overwrite the target compliance SecureWORMfs instance.

no

*Does not allow the command to overwrite the target compliance SecureWORMfs instance. The default value is **no**.*

10.2 AxiomONE Replication User's Guide and Reference for SAN

On page 14, replace the first two paragraphs and the first bullet with the following:

The AxiomONE Replication for SAN utility requires various licenses to be installed on the Pillar Axiom storage systems that participate in replication operations. In particular, this utility requires that the SAN Asynchronous Remote Replication license is installed on all Pillar Axiom systems designated as the primary Axiom system for a replication pair.

In addition, the AxiomONE Replication for SAN utility depends on several other features that have been licensed and installed on all Axiom systems participating in replication operations:

On page 73, make the following changes:

First sentence: *"AxiomONE Replication for SAN provides replication capabilities for up to 8 pairs...."*

First bullet: *"A maximum of 8 replication pairs...."*

10.3 Pillar Axiom 600 Service Guide

On page 269, add the following notice:

"When you intend to use non-Pillar PDUs, check first with your Pillar Account Representative to ensure you do not jeopardize your system warranty by installing the non-Pillar PDUs."

10.4 Pillar Axiom 600 Advanced Hardware Installation Guide

- In Chapter 2 on page 22, expand the **Important!** notice by integrating the following information:

"We recommend that Pillar racks be used to install Pillar Axiom hardware components. When using non-Pillar racks, do not use Telco two-post racks. Instead, use a four-post rack that can support the weight load of a Pillar Axiom system. Additionally, be sure the non-Pillar rack has square mounting holes in the vertical channels. Round mounting holes are not acceptable."

- In Table 50 on page 175, modify the row for "Vertical Channels" as follows:

In the "Pillar rack" column, change the first bullet to "Square hole unthreaded".

In the "Non-Pillar rack" column, change the last bullet to "Square EIA-standard mounting holes required".

We recommend that Pillar racks be used to install Pillar Axiom hardware components.

10.5 APM 3.0 Installation Guide and Release Notes for RHEL4

- At the top of page 13, the following sentence does *not* apply to APM 3.0 for RHEL4:

You will need to rename “blacklist” to “devnode_blacklist” in the multipath.conf file if you want to blacklist internal SCSI devices.

The above sentence applies only to the APM 3.0 for CentOS4 and OEL4 platforms. APM 3.0 for RHEL4 users should ignore this instruction.

- On page 17, the Operating Limits tables is missing the following entry:

Connect to LUNs Maximum = 256 visible from each Pillar Axiom system

- On page 24, the QLogic HBA driver version number 8.01.04 that is listed in the path is incorrect. The correct driver version number is 8.02.14.01. The correct path should be `cd qla2xxx-8.02.14.01`.

10.6 APM 3.0 Documentation for RHEL5.2, OEL5.2, and CentOS 5.2

The iSCSI Initiator configuration instructions that appear in the following AxiomONE Path Manager books are incorrect:

- *AxiomONE Path Manager 3.0 Installation Guide and Release Notes for RHEL 5.2*
- *AxiomONE Path Manager 3.0 Installation Guide and Release Notes for OEL 5.2*
- *AxiomONE Path Manager 3.0 Installation Guide and Release Notes for CentOS 5.2*

In particular, the incorrect instructions appear in the following two sections of those books:

- “Configure the iSCSI Software Initiator”
- “Start the iSCSI Software Initiator Service”

If you are configuring the iSCSI Initiator for the RHEL5.2, OEL5.2, or CentOS5.2 version of APM 3.0, follow the instructions in the README file for the iSCSI Initiator that comes with your Linux distribution and ignore the iSCSI Initiator configuration instructions in the APM documentation.

If you have questions or require detailed iSCSI Initiator configuration instructions for your installation, please contact the Pillar World Wide Customer Support Center.