

Tekelec EAGLE[®] 5

Release 42.0

Release Notice

910-6025-001 Rev G

September 2011



Tekelec

Legal Information

Copyright, Notice, Trademarks, and Patents

© 2011 Tekelec

All Rights Reserved

Printed in U.S.A.

Notice

Information in this documentation is subject to change without notice. Unauthorized use, copying, or translation of this documentation can result in civil or criminal penalties.

Any export of Tekelec products is subject to the export controls of the United States and the other countries where Tekelec has operations.

No part of this documentation may be reproduced, translated, or transmitted in any form or by any means, electronic or mechanical, including photocopying or recording, for any purpose without the express written permission of an authorized representative of Tekelec.

Other product names used herein are for identification purposes only, and may be trademarks of their respective companies.

RoHS 5/6 - As of July 1, 2006, all products that comprise new installations shipped to European Union member countries will comply with the EU Directive 2002/95/EC "RoHS" (Restriction of Hazardous Substances). The exemption for lead-based solder described in the Annex will be exercised. RoHS 5/6 compliant components will have unique part numbers as reflected in the associated hardware and installation manuals.

WEEE - All products shipped to European Union member countries comply with the EU Directive 2002/96/EC, Waste Electronic and Electrical Equipment. All components that are WEEE compliant will be appropriately marked. For more information regarding Tekelec's WEEE program, contact your sales representative.

Trademarks

TEKELEC, EAGLE, G-Flex, G-Port, and IP7 Secure Gateway are registered trademarks of Tekelec. The Tekelec logo, A-Port, EAGLE 5 ISS, IP7, and V-Flex are trademarks of Tekelec. All other trademarks are the property of their respective owners.

Patents

This product is covered by one or more of the following U.S. and foreign patents:

U.S. Patent Numbers:

5,008,929; 5,953,404; 6,167,129; 6,324,183; 6,327,350; 6,606,379; 6,639,981; 6,647,113; 6,662,017; 6,735,441; 6,745,041; 6,765,990; 6,795,546; 6,819,932; 6,836,477; 6,839,423; 6,885,872; 6,901,262; 6,914,973; 6,940,866; 6,944,184; 6,954,526; 6,954,794; 6,959,076; 6,965,592; 6,967,956; 6,970,542; 6,987,781; 6,987,849; 6,990,089;

Legal Information

6,990,347; 6,993,038; 7,002,988; 7,031,340; 7,035,239; 7,043,000; 7,043,001; 7,043,002; 7,046,667; 7,050,456; 7,050,562; 7,054,422; 7,068,773; 7,072,678; 7,075,331; 7,079,524; 7,088,728; 7,092,505; 7,108,468; 7,110,780; 7,113,581; 7,113,781; 7,117,411; 7,123,710; 7,127,057; 7,133,420; 7,136,477; 7,139,388; 7,145,875; 7,146,181; 7,155,206; 7,155,243; 7,155,505; 7,155,512; 7,181,194; 7,190,702; 7,190,772; 7,190,959; 7,197,036; 7,219,264; 7,222,192; 7,242,695; 7,254,391; 7,260,086; 7,286,516; 7,286,839; 7,295,579; 7,304,957; 7,318,091; 7,319,857; 7,327,670; 7,366,530; 7,372,953; 7,383,298; 7,401,360; 7,403,523; 7,403,537; 7,406,159; 7,439,854; 7,466,807; 7,466,815; 7,468,988; 7,502,611; 7,522,580; 7,525,997; 7,532,647; 7,554,974; 7,564,870; 7,573,905; 7,580,517; 7,606,202; 7,616,659; 7,630,211; 7,631,093; 7,633,872; 7,633,969; 7,644,215; 7,650,367; 7,675,905; 7,680,928; 7,693,066; 7,693,068; 7,701,925; 7,702,963; 7,706,343; 7,716,175; 7,720,463; 7,738,488; 7,738,489; 7,738,648; 7,742,421; 7,743,131; 7,751,836; 7,760,706; 7,760,708;

Foreign Patent Numbers:

CA2033880; CA2292962; CA2351375; CA2352246; EP1062792; EP1135905; EP1161819; EP1169829; EP1173969; EP1177660; EP1192758; EP1240772; EP1247378; EP1252788; EP1266528; EP1269764; EP1285545; EP1290854; EP1303994; EP1308054; EP1314324; EP1356686; EP1364520; EP1371246; EP1377909; EP1425932; EP1556778; EP1679848; EP1715658; EP1755295;

Table of Contents

| | |
|---|-------|
| Introduction..... | RN-2 |
| PR Severity Definitions | RN-2 |
| How to Locate Documentation on the Customer Support Site..... | RN-3 |
| Generic Program Loads | RN-4 |
| Resolved PRs | RN-7 |
| EAGLE 5 42.0.5 Resolved PRs for Build 42.0.5-63.38.37 (09/02/11)..... | RN-8 |
| EAGLE 5 42.0.4 Resolved PRs for Build 42.0.4-63.38.36 (06/24/11)..... | RN-9 |
| EAGLE 5 42.0.3 Resolved PRs for Build 42.0.3-63.38.35 (06/07/11)..... | RN-10 |
| EAGLE 5 42.0.2 Resolved PRs for Build 42.0.2-63.38.33 (04/26/11)..... | RN-11 |
| EAGLE 5 42.0.1 Resolved PRs for Build 42.0.1-63.38.31 (02/04/11)..... | RN-13 |
| EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10)..... | RN-14 |
| EAGLE EMS 42.0 Resolved PRs for Build 42.0.0-140.19.0 (01/28/11) | RN-28 |
| ELAP 9.0.1 Resolved PRs for Build 9.0.1-90.24.0 (08/05/11)..... | RN-30 |
| ELAP 9.0 Resolved PRs for Build 9.0.0-90.22.0 (11/05/10)..... | RN-31 |
| FTRA 4.3.0 Resolved PRs for Build 4.3.0-40.19.0 (11/05/10) | RN-33 |
| Known PRs | RN-34 |
| EAGLE 5 42.0 Known PRs (09/02/11)..... | RN-34 |
| EAGLE EMS 42.0 Known PRs (01/28/11)..... | RN-71 |
| ELAP 9.0 Known PRs (08/05/11)..... | RN-77 |

Introduction

This *EAGLE 5 42.0 Release Notice* is updated to include GPLs and Resolved PRs for EAGLE 5 Release 42.0.5, Build 42.0.5-63.38.37. This Release Notice includes EAGLE 5 Release 42.0.4, Build 42.0.4-63.38.36, EAGLE 5 Release 42.0.3, Build 42.0.3-62.38.35; EAGLE 5 Release 42.0.2, Build 42.0.1-63.38.33; EAGLE 5 Release 42.0.1, Build 42.0.1-63.38.31; EAGLE EMS Release 42.0, Build 42.0.0-140.19.0; EAGLE 5 Release 42.0.0, Build 42.0.0-63.38.17; ELAP 9.0.1, Build 9.0.1-90.24.0; ELAP Release 9.0, Build 9.0.0-90.22.0; and FTRA Release 4.3, Build 4.3.0-40.19.0.

The *EAGLE 5 42.0 Release Notice* includes:

- Generic Program Loads for EAGLE 5 42.0.5, 42.0.4, 42.0.3, 42.0.2, 42.0.1, and 42.0
- Resolved PRs for EAGLE 5 42.0.5, 42.0.4, 42.0.3, 42.0.2, 42.0.1, and 42.0
- Resolved PRs for EAGLE EMS 42.0
- Resolved PRs for ELAP 9.0.1
- Resolved PRs for ELAP 9.0
- Resolved PRs for FTRA 4.3
- Known PRs for EAGLE 5 42.0.0
- Known PRs for EAGLE EMS 42.0
- Known PRs for ELAP 9.0

NOTE: There are no Known PRs for FTRA 4.3.

Release Notices are distributed to customers with a new software release at the time of General Availability (GA) or Limited Availability (LA). EAGLE 5 Release 42.0.5 is a GA Release. EAGLE 5 Release 42.0.4, EAGLE 5 Release 42.0.3, EAGLE 5 Release 42.0.2, EAGLE 5 Release 42.0.1, EAGLE 5 Release 42.0, EAGLE EMS Release 42.0, ELAP Release 9.1, ELAP Release 9.0, and FTRA Release 4.3 are GA releases.

The Release Notice is available only on the Customer Support site. For each new publication to the web, the revision level of the part number is incremented. The Release Notice can be located under the Recent Release Notices tab by its title or part number; or by its product and release; see also *How to Locate Documentation on the Customer Support Site*.

PR Severity Definitions

The PR sections in this document refer to PR severity levels. Definitions of these levels can be found in the following publication:

GR-929-CORE, *Reliability and Quality Measurements for Telecommunications Systems (RQMS)*, Telcordia, December 1998.

How to Locate Documentation on the Customer Support Site

Access to Tekelec's Customer Support area is restricted to current Tekelec customers. This section describes how to log into the Tekelec Customer Support site and how to locate customer documentation. Viewing these files requires Adobe Acrobat Reader.

- 1** Go to the [Tekelec Customer Support site](#).
- 2** Enter your assigned username and chosen password, then click **Login**.
Or, if you do not have access to the Customer Support site, click **Need an Account?**
Follow the instructions on the screen.
NOTE: After 20 minutes of inactivity, you will be logged off, and you must repeat this step to regain access.
- 3** After successful login, select a product from the Product Support drop-down menu (for example, EAGLE 5 shows all EAGLE products after release 34.0).
- 4** Select a release number from the Product Support Release drop-down menu.
- 5** Locate the appropriate documentation section (i.e., a Feature or Release Notice would be under **Notices**, and user documentation would be under **Manuals**).
- 6** To open the documentation in the same window, double-click the document name. To open the documentation in a new window, right-click the document name and select **Open in New Window**.
- 7** To download the document, right-click the document name and select **Save Target As**.

Generic Program Loads

Table RN-1 on page RN-4 lists the latest Generic Program Loads (GPLs). When multiple builds are listed, GPL versions that changed from the previous build are highlighted.

Table RN-1. GPLs - 42.0.5-63.38.37, 42.0.4-63.38.36, 42.0.3-63.38.35, 42.0.2-63.38.33, 42.0.1-63.38.31, 42.0.0-63.38.17

| GPL SYSTEM NAME | Version Build 42.0.5-63.38.37 | Version Build 42.0.4-63.38.36 | VERSION Build 42.0.3-63.38.35 | VERSION Build 42.0.2-63.38.33 | VERSION Build 42.0.1-63.38.31. | VERSION Build 42.0.0-63.38.17 |
|-----------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|-----------------------------------|----------------------------------|
| Date Available | 09/02/11 | 06/24/11 | 06/07/11 | 04/26/11 | 02/04/11 | 11/05/10 |
| ATMANSI | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| ATMHC | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.15 | 133.38.15 |
| ATMITU | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| BLBEPM | 128.21.0 | 128.21.0 | 128.21.0 | 128.21.0 | 128.21.0 | 128.21.0 |
| BLBIOS | 128.21.0 | 128.21.0 | 128.21.0 | 128.21.0 | 128.21.0 | 128.21.0 |
| BLBSMG | 132.48.0 | 132.48.0 | 132.48.0 | 132.48.0 | 132.48.0 | 132.48.0 |
| BLCPLD | 133.18.0 | 133.18.0 | 133.18.0 | 133.18.0 | 133.18.0 | 133.18.0 |
| BLDIAG | 131.2.0 | 131.2.0 | 131.2.0 | 131.2.0 | 131.2.0 | 131.2.0 |
| BLDIAG6 | 133.32.0 | 133.32.0 | 133.32.0 | 133.32.0 | 133.32.0 | 133.32.0 |
| BLMCAP | 133.38.17 | 133.38.17 | 133.38.17 | 133.38.17 | 133.38.17 | 133.38.17 |
| BLROM1 | 132.1.0 | 132.1.0 | 132.1.0 | 132.1.0 | 132.1.0 | 132.1.0 |
| BLVXW | 131.6.0 | 131.6.0 | 131.6.0 | 131.6.0 | 131.6.0 | 131.6.0 |
| BLVXW6 | 133.38.33 | 133.38.33 | 133.38.33 | 133.38.33 | 133.38.17 | 133.38.17 |
| BPDCM | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 |
| BPDCM2 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 |
| BPHCAP | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 |
| BPHCAPT | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 |
| BPHMUX | 133.33.0 | 133.33.0 | 133.33.0 | 133.33.0 | 133.33.0 | 133.33.0 |

Table RN-1. GPLs - 42.0.5-63.38.37, 42.0.4-63.38.36, 42.0.3-63.38.35, 42.0.2-63.38.33, 42.0.1-63.38.31, 42.0.0-63.38.17 (Continued)

| GPL SYSTEM NAME | Version Build 42.0.5-63.38.37 | Version Build 42.0.4-63.38.36 | VERSION Build 42.0.3-63.38.35 | VERSION Build 42.0.2-63.38.33 | VERSION Build 42.0.1-63.38.31. | VERSION Build 42.0.0-63.38.17 |
|-----------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|-----------------------------------|----------------------------------|
| Date Available | 09/02/11 | 06/24/11 | 06/07/11 | 04/26/11 | 02/04/11 | 11/05/10 |
| BPMPL | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 |
| BPMPLT | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 |
| CDU | 163.38.36 | 163.38.36 | 163.38.32 | 163.38.32 | 163.38.14 | 163.38.14 |
| EOAM | 133.38.37 | 133.38.36 | 133.38.34 | 133.38.32 | 133.38.17 | 133.38.17 |
| EROUTE | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| ERTHC | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| GLS | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.31 | 133.38.14 |
| GLSHC | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.31 | 133.38.14 |
| HIPR | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 |
| HIPR2 | 133.33.0 | 133.33.0 | 133.33.0 | 133.33.0 | 133.33.0 | 133.33.0 |
| IMT | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| IMTPCI | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 | 133.34.0 |
| IPGHC | 133.38.37 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| IPGWI | 133.38.37 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| IPLHC | 133.38.37 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| IPLIM | 133.38.37 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| IPLIMI | 133.38.37 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| IPS | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| IPSG | 133.38.37 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| IPSHC | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| MCP | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| MPLG | 163.38.36 | 163.38.36 | 163.38.32 | 163.38.32 | 163.38.14 | 163.38.14 |

Table RN-1. GPLs - 42.0.5-63.38.37, 42.0.4-63.38.36, 42.0.3-63.38.35, 42.0.2-63.38.33, 42.0.1-63.38.31, 42.0.0-63.38.17 (Continued)

| GPL SYSTEM NAME | Version Build 42.0.5-63.38.37 | Version Build 42.0.4-63.38.36 | VERSION Build 42.0.3-63.38.35 | VERSION Build 42.0.2-63.38.33 | VERSION Build 42.0.1-63.38.31. | VERSION Build 42.0.0-63.38.17 |
|------------------------|--|--|--|--|---|--|
| Date Available | 09/02/11 | 06/24/11 | 06/07/11 | 04/26/11 | 02/04/11 | 11/05/10 |
| OAMHC | 133.38.37 | 133.38.36 | 133.38.34 | 133.38.32 | 133.38.17 | 133.38.17 |
| PKTGEN | 163.38.36 | 163.38.36 | 163.38.32 | 163.38.32 | 163.38.14 | 163.38.14 |
| PKTGHC | 163.38.36 | 163.38.36 | 163.38.32 | 163.38.32 | 163.38.14 | 163.38.14 |
| PLDPMC1 | 132.19.0 | 132.19.0 | 132.19.0 | 132.19.0 | 132.19.0 | 132.19.0 |
| SCCPHC | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.31 | 133.38.14 |
| SLANHC | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| SS7EPM | 130.29.0 | 130.29.0 | 130.29.0 | 130.29.0 | 130.29.0 | 130.29.0 |
| SS7HC | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| SS7IPGW | 133.38.37 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| SS7ML | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |
| VCDU | 163.38.36 | 133.38.36 | 163.38.32 | 163.38.32 | 163.38.14 | 163.38.14 |
| VSCCP | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.31 | 133.38.14 |
| VXWLAN | 133.38.36 | 133.38.36 | 133.38.32 | 133.38.32 | 133.38.14 | 133.38.14 |

Resolved PRs

The Resolved PR tables show an impact statement for Severity 1 and 2 PRs as well as for Severity 3 PRs that are associated with a CSR.

Table RN-2 on page RN-8 lists resolved PRs for EAGLE 5 42.0.5.

Table RN-3 on page RN-9 lists resolved PRs for EAGLE 5 42.0.4.

Table RN-4 on page RN-10 lists resolved PRs for EAGLE 5 42.0.3.

Table RN-5 on page RN-11 lists resolved PRs for EAGLE 5 42.0.2.

Table RN-6 on page RN-13 lists resolved PRs for EAGLE 5 42.0.1.

Table RN-7 on page RN-14 lists resolved PRs for EAGLE 5 42.0.0.

Table RN-8 on page RN-28 lists resolved PRs for EAGLE EMS 42.0.

Table RN-9 on page RN-30 lists resolved PRs for ELAP 9.0.1.

Table RN-10 on page RN-31 lists resolved PRs for ELAP 9.0.

Table RN-11 on page RN-33 lists resolved PRs for FTRA 4.3.

NOTE: Resolved PRs are sorted in ascending order by Severity (Sev.), and then by PR number.

Table RN-2. EAGLE 5 42.0.5 Resolved PRs for Build 42.0.5-63.38.37 (09/02/11)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|---|---|
| 203408 | Y | 2 | IPSG obit with Module ath_vxw_mgr. Line 1711 Class 01c3 randomly | This can cause links on the card, that are already in service, to go down. |
| 204917 | Y | 2 | Chg-GTT/GTA does not increment the MRNSET count | The active EOAM's card database is marked inconsistent. The command causing this is aborted and no update occurs. Also the remaining GTT entries pointing to the MRNSET cannot be removed. Please see TN003384. |
| 204423 | Y | 3 | Deleting a linkset (dlt-ls) removes the first tmap entry from the TTMAP table | Since Dlt-ls command incorrectly removes the first TTMAP table entry from OAM, in order to avoid possible traffic impact, customer needs to verify the TTMAP table immediately after every successful dlt-ls command and enter back the missing entry. Please see TN003382. |

Table RN-3. EAGLE 5 42.0.4 Resolved PRs for Build 42.0.4-63.38.36 (06/24/11)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|---|---|
| 202872 | Y | 3 | Command unhb-alm not working | Not possible to un-inhibit any alarm previously inhibited |
| 203053 | | 3 | ent/dlt-rmt-appl commands updated wrong data record | |

Table RN-4. EAGLE 5 42.0.3 Resolved PRs for Build 42.0.3-63.38.35 (06/07/11)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|---|---|
| 199762 | Y | 3 | Standby E5 OAM (E5 MASP) not properly setting up secondary HS clock | When an E5 MASP was removed from a duplex system and then reinserted, the secondary HS clock would remain FAULT. This is an intermittent fault when clock is set to T1framed shorthaul. Entering the clk-opts will correct. |
| 202113 | Y | 3 | ALW-SLK and unhb-slk do not work | Customer can not unihhibit link via normal operation. They would either need to boot the card, deactivate all other links so that the link inhibited is the only link left accessing a point code, or contact TAC. |

Table RN-5. EAGLE 5 42.0.2 Resolved PRs for Build 42.0.2-63.38.33 (04/26/11)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|--|
| 196556 | | 2 | HCMIM will not properly load Vx works after being Init Flashed with 62.50.0 or later releases. | HCMIM cards may not work with new flash image. |
| 196971 | | 2 | R43_LNPMR_GTT: Database corrupted and Sev 1 observed when deleting gttset entry. | OAM database goes inconsistent. |
| 198696 | | 2 | ath_vxw.c Line 2715 Class 0001 Obit on E5-ATM cards when SCCP cards were loading from EPAP | When there is GTT traffic but no SCCP cards, the E5-ATM cards may boot instead of discarding the GTT traffic. This would potentially cause loss of all traffic that the E5-ATM cards are processing. |
| 198700 | Y | 2 | SIGTRAN interface does not always adjust MTU when ICMP is received | SIGTRAN IP networks with MTU less than 1500 may experience faults due to large MTU size packets. |
| 141089 | Y | 3 | UAMs for E5-MDAL "MDAL not responding" being generated | Occasional momentary MDAL Not Responding alarms will appear and then immediately clear themselves when this situation occurs. |
| 165109 | Y | 3 | CSV output has ATM port hardcoded to A | The customer will have to use regular EAGLE terminal command rtrv-slk to see the correct port for ATM cards using the B port. |
| 165932 | Y | 3 | IPSG: Changing MAXSLKTPS to a lower value causes invalid assoc flow control value. | The MAXSLKTPS can be changed with the CHG-LS command - EX: chg-ls:Lsn=ls1305a:maxslktps=3000. When the problem occurs the LS reports the maxslktps value ok, but the association flow control (this is under the cover and users don't see this) value still stays at previous value. This will result in the link supporting the wrong amount of traffic. The work around is to close and open the associations after which the associations will use the new rate. |
| 166111 | Y | 3 | Unable to provision gateway link set via SOIP | Unable to add, verify, change, or delete a gateway linkset via SOIP commands. However, this can be provisioned via the maintenance terminal or flow-through. |
| 166471 | Y | 3 | RSRTDEV=ON does not prevent card from showing isolated after MASP switch over | Customer will have to manually disable devices that were previously disabled but the system has now attempted to initialize. Alarms will be present in the system until those devices are manually inhibited again. |
| 195302 | Y | 3 | A failed terminal can revert back to OOS-MT-DISABLED upon OAM SWACT with rstrdev=on | Customer may need to reinitialize previously allowed (which are in failed status) terminals after an OAM SWACT. |
| 196477 | Y | 3 | rtrv-appl-rtkey only shows lower 16 bits of rcontext | Customer will not see the correct value for the route key for values over 16 bits. The correct value is used by the protocol. |

Table RN-5. EAGLE 5 42.0.2 Resolved PRs for Build 42.0.2-63.38.33 (04/26/11) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|--|
| 196858 | Y | 3 | overlapped selector search in case of Cg selectors with GTI=4 does not work. | Overlapped selector search is not performed in the case of CGPA selectors with GTI=4. If the selectors in the first domain are not found, then the next domains are not searched. For example, if the MSUs' incoming OPC is ITUN, then the GTIN selector table is searched to see if there is a match. If there is not a match, the other domain's (ITUN24, ITUI, ITUNS, ITUIS) GTT selector table should be searched for overlapped selector. With this PR, the latter search is not performed (only the ITUN GTT selector table search would be performed in the example above). |
| 197383 | Y | 3 | Command class changes when upgrading to 42.0 | User-configured command class in pre-42.0 releases may be lost or get the command class altered after the system is upgraded to release 42.0 or higher. |
| 197832 | | 3 | Module uias_msg.c line 2186 - after RTRV-GTWYLS command | |
| 198246 | Y | 3 | Unexpected Hex chain displayed between each UAM when TRM type is MGMT | Customer using third party OSS system expects a clear display of UAMs sent by the Eagle through TRM configured with TYPE =MGMT. This issue prevents a clean collection and interpretation of UAM events by the external OSS system. |
| 199439 | | 3 | SEAS rtrv-gtwy-acthresh does not return correct data | |
| 199849 | Y | 3 | Upgrade failure due to CGPA Conversion set in 41.x | The upgrade will fail in some cases because of invalid entires related to the CGPA GTA. |

Table RN-6. EAGLE 5 42.0.1 Resolved PRs for Build 42.0.1-63.38.31 (02/04/11)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|---|---|
| 195571 | Y | 2 | SCCP cards are experiencing UAM 537- Ethernet error threshold exceeded alarm with recommended configuration | Customer may get false alarm when using the standard half-duplex ethernet configuration on SCCP cards with hub configuration. |
| 195672 | Y | 2 | GLS cards boot due to binder error | The GLS card may continue to boot, keeping screening from downloading. |
| 195046 | Y | 3 | IDPR - DSM4G card reboots if Conditioned Digits length is greater than 21 and service actions is 'ccncchk' | <p>Reboot occurs only when EAGLE receives an IDPR message and Number obtained after number conditioning on CDPN is more than 21 digits in length and service action provisioned is ccncchk. If conditioned number has less than 21 digits then IDPR successfully processes the message.</p> <p>This impacts the processing of IDPR traffic with CDPN such that conditioned digits >21.</p> <p>This issue exists on DSM card only. E5-SM4G does not reboot.</p> |
| 196100 | Y | 3 | Severity 1 Module bndr_utl.c Line 1983 Class 01c3 after GLS card reboot | Screening may not download correctly. |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|---|
| 129837 | | 2 | Btree does not rebalance properly | Both chg and dlt commands for global title entries can cause the Btree to become unbalanced. If this gets futher than 80 deep this can cause cards (OAM and SCCP) to boot. |
| 159348 | | 2 | Module md_hipr2.c Line 367 - Obits on realignment | HIPR2 may take a little longer to load when it is inserted in the system. |
| 159668 | | 2 | pmtc_mgr.c line 696 Severity 1 on 62.58.0 | Should DDB updates be in transit when an IMT virtual circuit drops, DDB will go inconsistent. This would lead UAM 911 to be displayed to report dynamic database inconsistencies. The occurrence is rare, but possible. It appears to impact legacy ATMs more than any other card type. |
| 159741 | | 2 | Upgrade does not complete in maintenance window for large station | Larger system with more than 10 differenet application GPLs will probablaly take longer than the normal 6 hour maintenance window to upgrade. |
| 159787 | | 2 | Upgrade fails to flash cards, reporting INVALID CARD TYPE per imtc_mgr.c Line 47XX troubles | This will cause the upgrade to take longer than expected. |
| 160363 | | 2 | MCP Cards took too long to load during upgrade | Can extend the upgrade time if this problem is hit. |
| 161329 | | 2 | Eagle fails to convert network indicator for MTP routed SCCP DT1 msgs with MTP msg for SCCP apps feature on resulting in sil | With MTP Routed SCCP feature, DT1 or other non UDT(S)/XUDT(S) messges crossing network boundaries will not be converted even though alias exists for the DPC. |
| 163435 | | 2 | IMT with HIPR2 and HIPR &/or HMUX cards will not always align | When HIPR and HIPR2 cards are mixed in a bus, HIPR2 cards may fail to align and the bus remains OOS. This requires a physical removal and re-insertion of a HIPR/HIPR2 card to recover the bus. |
| 163526 | | 2 | E5 Eagle Cards Can't Get on IMT Bus in a -02 Extension Shelf with HIPR2 | When HIPR and HIPR2 cards are mixed in a bus, HIPR2 cards may fail to align and the bus remains OOS. This requires a physical removal and re-insertion of a HIPR/HIPR2 card to recover the bus. |
| 163631 | | 2 | HIPR2: IMT detects BERT errors and won't align at high rate if traffic running | Due to false error detection, the IMT may not align at the correct rate. |
| 163715 | | 2 | HIPR2 gets "locked up" and does not boot | The HIPR2 card could lock in a down state and require a physical reset to recover. |
| 163726 | | 2 | IMT bus B goes down during traffic run with monitoring and STC subsystem in abnormal state | The IMT bus can fail and require physical reset of cards to recover. Also some HIPR2 cards will not work in slot 1110. |
| 164229 | | 2 | B bus was stuck in a down state due to a hipr 2 card not able to boot after an init-mux:bus=b command | This problem causes HIPR2 to lock up. This means the IMT Bus will be down until someone manually re-seats the HIPR2 that locked up. |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|---|
| 164507 | | 2 | HIPR2: Needs a HW watchdog timer. | Currently no hardware watchdog is running for HIPR2 cards that are in a hung state. In order for the card to exit from this state a hardware watchdog is needed to reboot the HIPR2 card in case of any bugs that put the processor of the card in a hung state. |
| 165111 | | 2 | RTRV-OBIT some times only reports (>>>> Log queue is full <<<<) | rtrv-obit command without NUM parameters specified sometimes reports (>>>> Log queue is full <<<<). If this happens then the user must use the command RTRV-OBIT:LOC=<1113 1115>:NUM=xx (where xx = 1 - 149). This workaround will display the requested information except for the last obit of 150. |
| 165277 | | 2 | HIPR2 didn't receive card address via TDM UART | Since the HIPR2 card did align on the IMT bus and there were no cards in the Extension shelf, the system impact would be minimal. Since the HIPR2 shelf LED was blinking amber/off, indicating that the card was waiting for his shelf address, no maintenance blocks to the OAM would occur, therefore the card would look as though it was not inserted. If a LIM card was inserted into the shelf, the TSU capture algorithm would allow the HIPR2 to receive its shelf ID and everything would start working as normal. |
| 165971 | | 2 | CSVGENX hangs on Solaris machine | The FTRA application may hang on a Solaris machine. |
| 166505 | | 2 | HIPR2 is receiving its own packets even when the FC bus is not viable. | Can cause attempt to run at high speed to fail even though the IMT would support it. |
| 166631 | | 2 | IPSG Obit for DAUD with Invalid length Module t4b_bm.c Line 434 Class 01c4 | If a DAUD with an invalid message length comes in, the IP card will boot. |
| 166669 | | 2 | HIPR2 FPGA Buffer Problem | When this buffer problem occurs, the HIPR2 may reboot and cause the IMT bus to go down. The bus will come back up and working once the HIPR2 reboots. |
| 168575 | Y | 2 | Dlt-rte may boot running SS7ANSI, SS&ML and ATMANSI | Deleting a cluster in ANSI can boot all the link interface cards. The work around is to change the ELIA before deleting the cluster entry. |
| 170172 | Y | 2 | TFC handling on M3UA combined with GWS redirect to SCCP can lock PC in congestion. | This could cause a point code to be stuck in congestion until that point code is prohibited and allowed. |
| 192756 | Y | 2 | E5-ATM has shorter LCD period than legacy ATM card. | Links may fail alignment or go down quicker on E5-card when they would work fine on Legacy ATM card. |
| 193132 | Y | 2 | E5 MASP locks up when using rept-stat-iptps | This could cause the E5-OAM cards to lock up and require manual reseal to recover. |
| 109898 | | 3 | SCTP Init Issues22-Telcordia-13) SUT sent incorrect INIT in response to an ERROR chunk with a stale cookie error | |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|---|---|
| 109912 | | 3 | SCTP Init Issues36-Telcordia-8) SUT sent ABORT with wrong error cause in response to a DATA chunk without the User Data param | |
| 123369 | | 3 | Service Selectors process MSUs even though SCCP Service is offline/disabled | |
| 127520 | Y | 3 | UAM 0040 GPL SYSTEM SCCP GPL is Corrupted Displayed - Procedure from Maint Manual Did Not Clear UAM | The Eagle is misreporting thus the customer can not tell if they have a real issue or not. Once the GPL has been swapped out as recommended by the maintenance manual, the customer will have to wait for the next audit cycle to complete (approximately 1.5 - 2 hrs) before the corruption alarm is lowered. This is currently also the time it would take to detect such a corruption. |
| 128587 | | 3 | Telcordia, Sigtran, seas, DURLKOTG register was not correct for IPSG M3UA links | |
| 128590 | | 3 | Telcordia, Sigtran, seas P_RBASE LINK congestion registers were not correct for HSL links | |
| 128592 | | 3 | Telcordia, Sigtran, Seas, SURCVERR did not include messages with an invalid SCTP checksum | |
| 129089 | | 3 | Meas data store clearing enhancement | |
| 129914 | | 3 | SEAS RBASE IP links NRPRSTRS counting not-applicable registers, '*' | |
| 129934 | | 3 | IPSG:inh-alm:dur=timed prompted scm_utl0.c severity 1 ATH | |
| 130405 | | 3 | Unable to generate Circular Routing UIM for M3UA or SUA | |
| 131848 | | 3 | Obit - pvrdbmsg.c - resync timeout after init-card:data=persist | |
| 131862 | | 3 | Potential for NULL_PTR deference in dbcdtInt_display_ipterm_entry_grp5 and trie_search_next functions | |
| 132343 | | 3 | SM4G cards do not error correctly when ULOG level rolls over on ELAP | |
| 132682 | | 3 | TRP on Eagle sends message with 0.0.0.0 vip/subnet on SM4G | |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|---|-----------------|
| 133564 | | 3 | LNP Meas Collection at 2400 incomplete if MCP boots | |
| 134572 | | 3 | IMT LVL1 Stats | |
| 135771 | | 3 | On EAGLE release 40.0.0-61.43.0 , rept-stat-sys command output is not properly formatted. | |
| 135895 | | 3 | Seas measurements caused smea_rep.c severity 1 to be generated. | |
| 136029 | | 3 | drms.c and egle_utl.c Severity 1 ATHs during full upgrade from 39.2.0-61.36.0 to 40.0.0-61.46.0 | |
| 138281 | | 3 | E5-MASP BIOS can't find Flash to boot-up | |
| 138414 | | 3 | rtrv commands should behave in the same manner when printing 0 entries | |
| 139329 | | 3 | mcc.queue Sev 1 trouble on E5OAM while executing a flash-card on the oamhc | |
| 139364 | | 3 | E5SM4G Card obit TCP_MGR.C line 709 | |
| 139522 | | 3 | R41:MEAS: Sev1 meau_oam.c and meau.c are observed with MCP configured | |
| 140178 | | 3 | Terminals do not behave as expected when 'arrow' keys are pressed | |
| 140903 | | 3 | FTR4.2:PC based ATH SEV-1 "\sw_eagle\gpls\common\hex_utl.c line_num" is getting observed on FTRA for "rtrv-gta" command. | |
| 141073 | | 3 | During Upgrade Phase 3 - two different DSMs are marked as Primary causing bouncing primary DSMs | |
| 152378 | | 3 | Link congestion causes Dynamic database Audit Failures with Major alm output. | |
| 153299 | | 3 | dbg-ddb displays only the first mismatch entry info between 2 cards even if it finds more than one mismatch table entry | |
| 154268 | | 3 | Incorrect range for command parameter. | |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|--|
| 154478 | Y | 3 | RTT can exceed RMAX when assocrtt reports a max RTT value lower than max RTO and no retransmissions are logged | This is not traffic affecting. The command output is used as a debug aid in troubleshooting IP network issues or determining the health of the IP connection. Thus, there is no system impact. |
| 154781 | | 3 | Command rept-stat-card:mode=full doesn't complete for HC-MIM card | |
| 155099 | | 3 | DAUD msg sent to SCOPY does not match original UA primitive received | |
| 155310 | | 3 | EGMS: Measurement Platform should not be required to enable GSM MAP Screening | |
| 155931 | | 3 | HIPR2: Command tst-imt needs parameter ACTION=START/STOP | |
| 156163 | | 3 | HIPR2: Advanced Stats not shown | |
| 156245 | | 3 | eagle usb enhancements to improve part number to software mapping | |
| 156480 | | 3 | IDPR: If NAI is unknown and OFNAI is set to incoming, then outgoing NAI is 2 | |
| 156654 | | 3 | REPT-STAT-SCCP does not show processing time or num of messages for MTP routed msgs serviced by SCCPHC/VSCCP cards | |
| 156879 | | 3 | R41.1:ENT-GTTSET command output displays GTTSET table status two times. | |
| 156945 | | 3 | SP_TIF : REPT-STAT-SCCP command shows MNP counter SUCC peg for UIM-1426 (GRN missing) when SPORT is ON | |
| 156946 | | 3 | IPSG cards are booting with OBIT t4b_bm.c Line 396 Class 0001 | |
| 157164 | | 3 | Incorrect SOIP outputs observed for huge SOIP responses. | |
| 157460 | | 3 | EAGLE docs chg-as | |
| 157863 | | 3 | Cards booting with Module ath_vxw.c Line 30XX after INIT-CARD:APPL=<>. | |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|---|---|
| 158019 | | 3 | oamhc gets blocked on chg-db:src=usb:action=restore | |
| 158128 | | 3 | HIPR2: clr-imt-stats:all=yes doesn't clear the Per Minute statistics from HIPR2ERR report | |
| 158191 | Y | 3 | The UASSNMRX measurements register is not being pegged properly. | Customer is unable to determine what UASSNMTX measurement registers are counting. |
| 158405 | | 3 | E5-ATM does not properly report NE LOOPBACK | |
| 158424 | | 3 | IAR SERVICE counts should be displayed in rept-stat-sccp when only IAR BASE feature is enabled and ON. | |
| 158425 | | 3 | NO IAR related measurements should be pegged with IAR Base feature is enabled and off. | |
| 158469 | | 3 | Active Legacy OAM boots continuously when its database is incoherent | |
| 158760 | | 3 | Legacy OAM login problem | |
| 159068 | | 3 | HIPR2: Normal BERT test fails to turn off the BERT receiver if lost sync count threshold aborts the BERT. | |
| 159069 | | 3 | HIPR2: HIPR2 FPGA needs to count lost sync instances | |
| 159116 | | 3 | IMT RX MSU filtering (IMTV1) | |
| 159249 | | 3 | Module restart.c Line 1034 Class 0001 | |
| 159282 | | 3 | Telcordia - Incorrect PROSTAT Value in D_MTCS Report When SIPOs Received | |
| 159461 | | 3 | ssh-keyscan not functional | |
| 159476 | | 3 | IPSGs OBIT with Module ath_vxw_mgr. Line 1770 Class 01c3 | |
| 159733 | | 3 | HIPR2: IMT rate increase on, rept-stat-mux shows cards running high and low on same IMT | |
| 159790 | | 3 | Multiple flash download may fail on account of one slow card | |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|---|--|
| 159906 | | 3 | E5-OAM TDM Frozen. Card 1115 Module tpim_io.c Line 367 Class 01c3 | |
| 159987 | | 3 | HIPR2: IMT Rate change abort procedure needed | |
| 160002 | | 3 | ATM cards Obit - Module itx_rtx.c Line 2038 | |
| 160140 | | 3 | MTP Routed SCCP APPS feature enabling dependencies is incomplete. | |
| 160477 | | 3 | HIPR2: fpb_mgr.c Severity-1 Line 755 observed when Active OAM is booted while one IMT Bus is inhibited | |
| 160478 | | 3 | HIPR2 High Rate mode feature getting activated even if there is any IS-ANR HMUX/HIPR card(s) present in the system | |
| 160517 | | 3 | HIPR2: Extended BERT results invalid when the test terminates prematurely within 1 second of test run due to excess error | |
| 160617 | | 3 | HIPR2: chg-ctrl-feat command for "HIPR2 High Rate mode" feature should be rejected when Extended BERT in progress | |
| 160808 | | 3 | after MASP activity switch, printer terminal is generating output similar to vt320 mode | |
| 160842 | | 3 | HIPR2: PMTC Disconnect Trigger Should Cause the Extended BERT Test to be Terminated (Telcordia-FT) | |
| 161092 | | 3 | HIPR2: Expected card count of zero not reflected following aborted copy-ext-stats command execution. (Telcordia-FT) | |
| 161171 | | 3 | HIPR2: Should not block "init-sys" command when bus rate change or Extended BERT is in progress | |
| 161194 | Y | 3 | rtrv-ctrl-feat command Displays Incorrect Feature Names | Some features show up with erroneous names via rtrv-ctrl-feat. The FAK part numbers are correct. |
| 161246 | | 3 | HIPR2: Extended BERT results not valid for Eagle with shelves 1100, 1200, 2100 and 2200 | |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|---|
| 161439 | | 3 | Display of U17-U32 on E5-MASP does not work for rtrv-secu-user | |
| 161597 | Y | 3 | Doc 910-5792-001 REV B does not contain description of some MOSMS counters MOSMSSEGER and MOSMSSEGOK | Customers will not find all counters related to MOSMS feature in the Feature Description doc. They will have to look in the Measurements Manual until fixed. |
| 161616 | Y | 3 | INPQ service selector fails when provision for secondary point code. | NPREQ traffic routed on load-sharing basis of the secondary point code fails with invalid msg type. |
| 161676 | | 3 | HIPR2: tosil_md.c Line 1104 Class 6003 Severity 1 during IMT alignment | |
| 161716 | | 3 | HIPR2 locks-up when the board is in an eagle shelf and the reset button is pressed | |
| 161742 | Y | 3 | UAM 0084 - IP Connection Unavailable in Maintenance Manual 910-5670-001 needs to be updated | Customer may not be able to troubleshoot UAM 0084 without contacting TAC for support. |
| 161743 | Y | 3 | 0086 - IP Connection Congested, Customer Docs need to be updated. | Customer is unable to fully understand the UAM and why it occurs. Need to have Documentation enhanced to provide the Customer a better understanding of the alarm, when and why it's triggered and suggestions for troubleshooting. |
| 161744 | Y | 3 | UAM 0277 - AS Unavailable and UAM 0279 - AS Restricted needs to be updated. | With current documentation Customer may not be able to fully understand the UAM. We need to update the steps as well as possibly provide additional information to show the Eagle is just reporting an action taken by the far end. |
| 161745 | Y | 3 | UAM 0535 - IP Connection Restricted needs to be updated | Customer may not be able to troubleshoot UAM 535. |
| 161746 | Y | 3 | UAM 0536 - IP Connection Excess Retransmits needs to be updated in Customer Docs | Customer may not understand how to troubleshoot issue. |
| 161768 | Y | 3 | :SLSRSB= restriction needs to be added to Customer Documentation. | Customer will not route traffic according to their understanding of the feature as they do not have information that mismatched SLSRB on combined linkset is not supported. |
| 161774 | Y | 3 | Supported MO Cartridge size needs to be updated in Hardware - Signaling Products manual. | Customer will have to call TAC when mismatched HW isn't accepted. |
| 161781 | Y | 3 | DDB Phase 1/2 debug information to be added in the customer documentation | Customer needs additional information regarding DDB management evolution in order to properly troubleshoot DDB issues. |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|---|
| 161844 | | 3 | HIPR2: utilize the new FPGA lost sync count registers | |
| 161993 | | 3 | HIPR2: chg-ctrl-feat is accepted while HIPR2 flash is in progress | |
| 162095 | Y | 3 | send-msg:ds=1:oa=h'98:da=h'5d:f=hâ™61:loc=XXX X requires ALL=YES to be set on issuing terminal | Command output now correctly comes out when debug is set for terminal. |
| 162373 | | 3 | HIPR2 Ext Bert: IMT Rate change command completes but rate change never occurs during incremental upgrade | |
| 162487 | Y | 3 | EIR Function not working for a CheckIMEI that is duplicated by MAP Screening | EIR Function not working for a CheckIMEI that is duplicated by MAP Screening. |
| 162494 | | 3 | HIPR2: BERT Errors that are injected after the BERT is sync'd do not cause the Ext BERT test to "fail" _. | |
| 162770 | | 3 | IAR: S-Port Missing GRN UIM does not contain necessary data | When S-Port entires are missing GRN the UIM does not give enough information to make it easy to identify. |
| 162864 | Y | 3 | Incorrect handling of SAPC in an M2PA linkset | Eagle is discarding MSUs with cause "Invalid SIO (UIM 1018) when the SAPC does not match the linkset point code for the IP SG M2PA linkset. |
| 162944 | Y | 3 | In upgrade procedure 909-1570-001 REV D Table 6/section 3.2 shows target software download as Non-intrusive, which is wrong. | Customer may think a format disk is not an intrusive action. |
| 163115 | | 3 | HIPR2: rept-imt-lvl1 does not report TAXI bus utilization | |
| 163116 | | 3 | HIPR2: rept-imt-lvl1:hs=yes report is sometimes missing data for cards or shelves | |
| 163117 | | 3 | HIPR2: rept-imt-lvl1 with s and e parameters shows no slots | |
| 163134 | | 3 | Secondary HSCLKSRC Value in CLKOPTS Table Does Not Get Set to Same Value In Primary After Upgrade | |
| 163186 | | 3 | EGLE OPTS DRMS conversion function incorrect for upgrades from 37.5 and 38.0 | |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|---|--|
| 163239 | | 3 | HIPR2: No 100 MS Peak Packets for Signal Units in Advanced Level 1 Stats | |
| 163255 | | 3 | tst-imt:type=extbert action=stop does not halt extended BERT test | |
| 163337 | | 3 | HIPR2: MPKT counter peak value not reported with rept-imt-lvl1 | |
| 163388 | Y | 3 | E2155 uses APPL instead of GPL | The customer may not know that they should use gpl when reading the error recovery. However the requirement is in the Commands Manual. |
| 163762 | Y | 3 | RTRV-GTT for a range of numbers shows GTT entries not in the requested range. | Customer may get data from entires not in range that was requested. The extra data is in the database; however, based on the filtering the customer requested, the extra data should not be displayed. |
| 163955 | Y | 3 | OAM and other cards unable to get on back on IMT following a tst-imt command | If test-IMT is run multiple times to ensure the state of the IMT, the HIPR card in the control shelf for that IMT may become unresponsive. |
| 164022 | | 3 | Module dmshc_oam.c Line 0652 DMS Error when doing a format-disk command for upgrade | |
| 164145 | Y | 3 | Non readable output from rtrv-gttset | User is not able to see readable output if used on non-80 column terminal. |
| 164210 | | 3 | display issue from rept-stat-alm for inhibited alarms | |
| 164228 | | 3 | SUBDFRN mismatch between chg-sccpopts and rtrv-sccpopts commands | |
| 164257 | | 3 | Hardware baseline incorrectly states E5-OAM required for HIPR2. | |
| 164318 | | 3 | Misspellings of HIPR2 in rept-imt-lvl1 stats | |
| 164349 | | 3 | pmtc_oam.c Line: 1252 obit on E5-OAM with HIPR2s in the shelf | |
| 164374 | | 3 | HIPR2 can have multiple masters | |
| 164445 | | 3 | HIPR2: hipr2op_rx_m Line 279 Class 01b9 Severity 1 | |
| 164866 | Y | 3 | UAM balancing matrix not clear for SLKs | Customer documentation may look unclear to the customer. |
| 165072 | | 3 | HIPR2 reports obit Module hipr2op_star Line 553 Class 0075 after init-flash | |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|--|
| 165161 | Y | 3 | Wildcards are not working in rtrv-dstn | Rtrv-dstn using wild cards will not show cluster or network routes. If the specific network or cluster route is entered, the rtrv-dstn will display it. |
| 165176 | | 3 | HIPR2 boot code does not use the correct map bit in the exb_config_0 register. | |
| 165194 | Y | 3 | with GTT LS ARI feature activated it is sometimes not possible to delete some MRNSET entries referenced in MAP table | With GTT LS ARI feature activated it is sometimes not possible to delete some MRNSET entries referenced in MAP table. |
| 165406 | Y | 3 | UAM/UIMs customer documentation indicates that an MSU is dicarded by the Eagle when UIM 1023 is output | Customer is confused by the meaning of UIM 1023. The generation of this UIM does not necessarily means that an MSU has been discarded. It may indicate that some features did not handle an MSU due to its package type. Instead the MSU can be handled by GTT and be processed. |
| 165453 | | 3 | IMT Lvl1 stats do not retrieve the data from a HIPR2 card if there is a shelf missing. | |
| 165829 | | 3 | Invalid HIPR2 interrupt | |
| 165833 | Y | 3 | In service states shown incorrcely in DB Admin manual for E5 class cards | User may be confused why documentation and Eagle output do not match for temperature issues. |
| 165975 | Y | 3 | UAM 33 should be raised after a corrupted disk is repaired | Following the repair, UAMs are cleared on the Eagle but no UAM event is reported for this. The main impact is that these alarms are not cleared on EMS systems since no UAM 33 is triggered after the alarm is cleared. |
| 166183 | | 3 | imt_dispatch Line 339 severity 1 ATH when changing high rate mode for HIPR2 | |
| 166469 | Y | 3 | E5-OAM rejects ent-gta when using uppercase "DFLT" for MRNSET | The commands work correctly if "dflt" is all lower case. Customer with E5-OAMs may be confused as the upper case "DFLT" is rejected when it should not be. |
| 166479 | | 3 | HIPR2: FC Util Statistic reports over 100% | |
| 166519 | | 3 | MAPSET entry reference count not getting incremented/decremented | |
| 166575 | | 3 | Unable to read any thumb drive in removable and usb slots of an E5-OAM | |
| 166859 | | 3 | HIPR2 Memory Single Bit Errors (SBE) | |
| 167083 | Y | 3 | Incorrect information in EIR feature description in customer doc 910-5788-001 Revision B | Wrong EIR response in the documentation may cause the customer to be confused when it is compared to the response from the EIR feature. |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|--|
| 167116 | | 3 | HIPR2: rept-imt-info reports counts for unequipped card slots | |
| 167310 | Y | 3 | UAM 560 deleted from customer maintenance documentation | UAM 560 is missing in the customer documentation. Customer needs this UAM to be documented for troubleshooting perspectives. |
| 167399 | Y | 3 | E5-MDAL is missing power and physical characteristics chart. | Customer will not know power consumption for planning purposes. |
| 167634 | | 3 | HIPR2: Lost Multicast Pkt count not cleared in rept-imt-lvl1 reports | |
| 168859 | | 3 | During upgrade (41.0.2 to 42.0) MCP reported multiple Severity 1: ftp_app.c and mprm_sl.cpp | |
| 169043 | | 3 | Continuous E5-OAM obit during healthcheck 2 | |
| 48657 | | 5 | Upgrade only converts 1 EROUTE card at a time | |
| 55813 | | 5 | Need to display new IMTPCI/HC Blade IMT Stats | |
| 107718 | | 5 | Eagle OA&M Password Security Enhancements | |
| 107719 | | 5 | Eagle OA&M Password Limitation Enhancement | |
| 110048 | | 5 | rept-stat-lvl1 needs a new param. to allow only cards with errors to report | |
| 110049 | | 5 | rept-stat-lvl1 - need to update with new and additional error counts | |
| 111435 | | 5 | E5-OAM Integrated Measurements | |
| 116456 | | 5 | Support of 750K Sigtran system TPS | |
| 118106 | | 5 | 64 PC support in M3UA DAUD message | |
| 130831 | | 5 | Link should not be allowed for deletion when lsrestrict is ON and number of links falls below tfatcabmlq | |
| 134573 | | 5 | New IMT LVL1 stat (add count for times a card gets off a bus) | |
| 134574 | | 5 | New imt lvl1 stat (add a count to reflect the number of times a VC is dropped) | |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|-----------------|
| 137049 | | 5 | Need unique selectors for ITU-I, ITU-N and ITU-N24 GTT selectors | |
| 137259 | | 5 | GTT Actions | |
| 137290 | | 5 | FLOBR Enhancements | |
| 137607 | | 5 | Support >9 SM4G cards with LNP 384 million | |
| 138054 | | 5 | Support >25 SCCP cards with EPAP T1200 application server | |
| 140230 | | 5 | Ability to choose whether last digit 0 should be considered as filler or a valid digit for GTI 2 to GTI 4 case | |
| 140595 | Y | 5 | Large MSU support for IP Signaling | |
| 140909 | | 5 | HIPR2: Add Extended BERT parameter to TST-IMT command | |
| 140913 | | 5 | HIPR2: HIPR2 rate change optimization | |
| 153102 | | 5 | HIPR2 - retrieval of extended statistics | |
| 156488 | | 5 | EIR support for h'80 IMSI tag in Check_IMEI | |
| 157009 | | 5 | G-Flex MAP Layer Routing support for ATI using MSISDN | |
| 157186 | | 5 | ON/OFF Options - add list mnemonic list of options to reduce command parameters | |
| 157316 | | 5 | Removing maximum parameter limit from the UI command messages | |
| 157324 | | 5 | DRMS/DMS Mirroring | |
| 157618 | | 5 | Support IPSPG Link Capacity Sharing | |
| 157622 | | 5 | Extending IPSPG Ethernet alarms to all Eagle applications that run on cards support Ethernet interface | |
| 157754 | | 5 | Increase CSL GT List for IDPR and IAR | |
| 158511 | | 5 | EOAP Hardware Maintenance Phase | |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|-----------------|
| 158676 | | 5 | HIPR-2 Blocks All Ports When One Port Is Full | |
| 158679 | | 5 | Reference Count for GTTSETS | |
| 159291 | | 5 | AMGTT Data needs to be maintained under new command set | |
| 159299 | | 5 | Eagle Command Set Automation (ECSA) | |
| 160039 | | 5 | E5-OAM IP/Ethernet Support | |
| 160420 | | 5 | SCTP Payload Protocol Identifier needs to handle Big Endian or Little Endian byte order | |
| 161125 | | 5 | Increase ATM links per node. Remove ATM card/link level software limits | |
| 161141 | | 5 | HIPR2: report BERT results on a per card basis | |
| 161235 | | 5 | Support FastCopy on IPGW | |
| 161245 | | 5 | Command to perform migration of IPLIM to IPSP | |
| 161314 | | 5 | S-Port Subscriber Differentiation | |
| 161338 | | 5 | sysstat command needs to output OAM DB memory info for both SCCPHC and VSCCP | |
| 161361 | | 5 | Flexible GTT load sharing after MNP RTDB look up | |
| 161877 | | 5 | Change RTRV-MEASOPTS output to be FAK independent | |
| 162897 | | 5 | Upgrade needs to stop after a card set finishes upgrading during which a card was removed from the set | |
| 162941 | | 5 | Support of MAPSET and MRNSET needs to be added in GTA with XLAT=NONE | |
| 163566 | | 5 | rept-imt-lvl1 inconsistent for MUX cards that don't report Advanced Stats | |
| 164369 | | 5 | HIPR2_fpga_stats.c line 4885 sev 1 | |
| 166860 | | 5 | NPS Flag in case of PT=None for own subscribers using MO_SMS_FRAUD_CHECK Feature | |

Table RN-7. EAGLE 5 42.0 Resolved PRs for Build 42.0.0-63.38.17 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|-----------------|
| 167579 | | 5 | Add retransmitted MSU counts to the IMT Level 2 stats | |
| 167954 | | 5 | Route ReportSMDeliveryStatus for non-local or ported out subscribers using GTT | |

Table RN-8. EAGLE EMS 42.0 Resolved PRs for Build 42.0.0-140.19.0 (01/28/11)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|-----------------|
| 136175 | | 3 | EMS: 'Logged-in EAGLE(s)' list not updated on stopping COMMAND port | |
| 136170 | | 5 | EAGLE EMS - Command Class Selection should be mandatory for some CMI Functions | |
| 136912 | | 5 | View Script Page should list the CMI command script name | |
| 137797 | | 5 | EAGLE EMS: SNMP Support of Tekelec MIB | |
| 139410 | | 5 | EMS : CMI upgrade removes the cron entries. | |
| 152535 | | 5 | EAGLE EMS CMI: Portable Character Set | |
| 152567 | | 5 | EMS - Error message when no Eagles are assigned to User | |
| 158788 | | 5 | EAGLE EMS: GA enhancements for Link Utilization Interface feature | |
| 158789 | | 5 | Eagle EMS R42.0 must support upgrade from Eagle EMS R40.0 thru R41.1 | |
| 158790 | | 5 | Eagle EMS R42.0 must support alarms from Eagle R42.0 | |
| 158791 | | 5 | Eagle EMS R42.0 must support Measurement data from Eagle R42.0 | |
| 158792 | | 5 | Eagle EMS R42.0 schema loader must support command set from Eagle R42.0 | |

Table RN-8. EAGLE EMS 42.0 Resolved PRs for Build 42.0.0-140.19.0 (01/28/11) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|-----------------|
| 161432 | | 5 | Unable to modify 'NMS Label' if only the case (lower/upper) of an existing NMS Label is changed. | |
| 162795 | | 5 | EMS - NMS label should start with an alphabetic character | |
| 162979 | | 5 | Starting/Stopping NBI through probuilder | |
| 163440 | Y | 5 | Insecure Web Interface (PHP) | |
| 163441 | | 5 | HTTP Server Security | |
| 163475 | | 5 | Missing Solaris patches on NetBoss Core | |
| 163520 | | 5 | Remove report templates from packages for MeasOAM, MeasPlat, and Inventory | |
| 164152 | | 5 | EMS - Modify the Error message to include number of digits supported | |
| 165484 | | 5 | Inventory behavior does not match marketed functionality | |
| 165579 | | 5 | EMS - Enhance handling of LUI logs and slkdatafiles | |
| 166435 | | 5 | Update LUI Crystal Reports calculation formulae | |
| 167012 | | 5 | EMS - LUI must support new IPTPS command output | |
| 169928 | | 5 | EMS: Include RTRV-RTE command in inventory | |
| 192963 | | 5 | Support for upgrade of MeasOAM and MeasPlat modules to Release 42.0 | |

Table RN-9. ELAP 9.0.1 Resolved PRs for Build 9.0.1-90.24.0 (08/05/11)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|--|
| 194453 | Y | 3 | Syscheck execution from the ELAP GUI reports errors in the class system check | Incorrect information is reported when syscheck is run from the ELAP GUI, while the command line execution of syscheck works properly. |
| 203452 | | 3 | The alarm "Platform Health Check Failure" is reported by syscheck but is not shown on the ELAP 9.0 GUI | |

Table RN-10. ELAP 9.0 Resolved PRs for Build 9.0.0-90.22.0 (11/05/10)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|--|
| 106771 | | 3 | ELAP uiEdit causes different results when using uppercase or lowercase | |
| 130827 | | 3 | Uploading data using batch mode gave server error | |
| 130991 | | 3 | Missing error text when enter updates to the full table from LPU | |
| 131589 | | 3 | Prevent multiple instances of snapmon | |
| 131848 | | 3 | Obit - pvrdbmsg.c - resync timeout after init-card:data=persist | |
| 132337 | | 3 | Status window for eagle cards did not pop up when minimized | |
| 132343 | | 3 | SM4G cards do not error correctly when ULOG level rolls over on ELAP | |
| 132570 | | 3 | In Prov: Senddbinfmtmsg failure ignored | |
| 132572 | | 3 | TRPD errors | |
| 132617 | | 3 | dbaudit give the wrong duplicate record reference count | |
| 132732 | | 3 | ELAP software is not restarted after "Configure DSM Network" | |
| 133240 | | 3 | Prov does not detect failure of networks correctly | |
| 134756 | | 3 | The IPSEC racoon process on a post STANDBY ELAP)after failover) needs a signal 1 (HUP) for IPSEC IKE. | |
| 161741 | Y | 3 | Prov process crashes producing core(s) | Prov process will core. Process will restart by exinit, but syscheck will result in alarms. Service will get hampered until prov process is restarted. |
| 105250 | | 5 | Passwords for Elap users are in DES not MD5 | |
| 122479 | | 5 | ELAP: Ability to Change system required user passwords | |
| 123939 | | 5 | SECURITY: Filter Out ICMP Timestamp Requests / Outgoing Timestamp Replies | |

Table RN-10. ELAP 9.0 Resolved PRs for Build 9.0.0-90.22.0 (11/05/10) (Continued)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|---|-----------------|
| 130300 | | 5 | SECURITY: Disable TFTP Service for ELAP | |
| 130302 | | 5 | SECURITY: Filter Incoming UDP Packets to SNMP Port | |
| 132502 | Y | 5 | RTDB 80% full alarm is not variable on the ELAP while it is on the Eagle. | |
| 136621 | | 5 | ELAP Naming capability | |
| 137607 | | 5 | Support >9 SM4G cards with LNP 384 million | |
| 155708 | | 5 | Remove extraneous graphics from ELAP 8.0 Admin Manual | |
| 161720 | | 5 | Java 1.6 Support Compatability with ELAP | |
| 166907 | | 5 | ELAP9.0_SYSTEM_TEST: Error Numbers and Texts that don't exist in ELAP need to be removed from Admin Manual. | |

Table RN-11. FTRA 4.3.0 Resolved PRs for Build 4.3.0-40.19.0 (11/05/10)

| PR # | CSR? | Sev | Title | Customer Impact |
|--------|------|-----|--|--|
| 162112 | | 2 | FTRA installation instructions not clear in 909-0643-001 | Customer may have to call for help when installing FTRA. |
| 163353 | | 2 | FTRA's SSH connection on Unix fails | With JRE versions 1.5 and 1.6, UNIX-based FTRA is not able to connect using SSH. |
| 114149 | | 5 | FTRA support for GTT Actions | |
| 160656 | | 5 | FTRA 4.3 Enhancements | |
| 161720 | Y | 5 | Java 1.6 Support Compatability with FTRA | |

Known PRs

Table RN-12 on page RN-34 lists known PRs for EAGLE 5 42.0.

Table RN-13 on page RN-71 lists known PRs for EAGLE EMS 42.0.

Table RN-14 on page RN-77 lists known PRs for ELAP 9.0.

NOTE: There are no known PRs for FTRA 4.3.

NOTE: Known PRs are sorted in ascending order by Severity (Sev), and then by PR number.

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11)

| PR # | CSR? | Sev | Status | Dispo- sition | Title | Customer Impact |
|--------|------|-----|----------|------------------|--|---|
| 127232 | | 2 | Resolved | Defer | BPHCAP can only support 4500 Multicast's per second | If DDB updates are over 4500 per second for BP cards, then IMT could be over loaded and messages could be lost, causing DDB corruption should an IMT bus fail. BPHCAP can only support 4500 Multicasts per second. |
| 139147 | | 2 | Resolved | Defer | INM/SNM throttling (TVG rates) | This would take massive network issues to occur at customer site. DDB audit would alarm and catch this issue. |
| 165922 | | 2 | Resolved | Defer | Eagle applications modifying TCAP data need to update SCCP CdPa/CgPa parameter pointers | If the CDPA, CGPA and TCAP are receive in different order than shown in the specification for UDT messages and If the TCAP is modified by and application on EAGLE the pointer for CDPA and CGPA will not b e modified. This will cause those messages to fail. |
| 168734 | | 2 | Resolved | Defer | hw_imtpci_in Line 1554 Class 01bd Severity 1-- HC-MIM went isolated & couldn't recover | The particluar card would have to be reseated. To date have only seen one specific card. |
| 205740 | | 2 | Resolved | Defer | Eagle is not modifying the length of CDPA for DUP/FWD msg when AMGTT is provisioned in the GTA entry with GTT ACTION | The SCCP message (having CgPA PC present) processed AMGTT but not modified by GTT actions the CDPA length is not recalculated. This could cause decode errors in the next node that processes SCCP message. Workaround: Add CDGTMODID or CGGTMODID to the GTT Action configuration. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|---|
| 107960 | | 3 | Resolved | Defer | TELCORDIA-MOBR- Both TCRs concerning SPC (a nested cluster) and TFRs concerning SPC1 (FPC member in the nested cluster) | Duplicate network management information. All information is correct, just extra messages to be processed. |
| 108297 | | 3 | Resolved | Defer | Telcordia - 34.0 audit - NCR: Missing TFR broadcast for FPC Member When Moving from Prohibited to Restricted Status | IMPACT: This will unnecessarily delay the restoration of traffic to the affected node, until the adjacent node sends a route-set-test (RST) message. |
| 108550 | | 3 | Resolved | Defer | Telcordia - 34.0 audit -Unexpected TFAs sent to adjacent STP1 and STP2 when TFPs concerning | IMPACT: Since the TFP broadcast immediately followed the incorrect TFA messages, the impact is minimal and results in inefficient use of network resources. |
| 109130 | | 3 | Resolved | Defer | MTP3Issue16-FMR- Telcordia - FMR: TRAs are prematurely sent on the IPVHSLs during T24. | IPLIM may terminate full restart before completing broadcast, so adjacent nodes may begin to send traffic before all preventive messages are sent. |
| 109884 | | 3 | Resolved | Defer | MTP3Issue02-Telcordia- Improper incrementing of FSN during SIOS transmission | None. During changeover, the LSSU FSN was 1 greater than expected. The LFSN in the COA would simply request the missing MSU, so no traffic loss should occur. |
| 109891 | | 3 | Resolved | No-Fix | SCTP Init Issues15-Telcordia- 6) ABORT was not sent for an INIT with an invalid IPV4 address parameter | When an INIT contains an invalid IPV4 address parameter, the Eagle will not send an ABORT, and continue with association establishment. |
| 109896 | | 3 | Resolved | Defer | SCTP Init Issues20-Telcordia-11) SUT sent malformed ABORT for an INIT ACK containing host name address parameter | When an SCTP INIT ACK containing a host name address parameter is received by the Eagle, it correctly responds with an ABORT, but the ABORT is malformed – it does not contain padding bytes and the unresolvable address contains extra bytes before the address value. This is a minor non-compliance to RFC2960. |
| 109916 | | 3 | Resolved | Defer | SCTP Init Issues39-Telcordia- 11) ABORT is not sent in response to a DATA or SACK chunk when no association existed | When the SUT received a DATA or SACK chunk from an endpoint for which no association existed, it did not send an ABORT. No impact when interfacing with a correct implementation. |
| 109918 | | 3 | Resolved | Defer | SCTP Init Issues46-Telcordia-18) SUT did not retransmit an unacknowledged DATA chunk Association.Max.Retrans times | When the Eagle did not receive a SACK, it did not retransmit the DATA chunk Association.Max.Retrans times. We retransmit 1 too few times. In practice this is not an issue, since we retransmit enough times to guarantee we can meet our performance requirements. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|---|
| 110004 | | 3 | Resolved | Defer | SEAS- Telcordia- Item 12 - P_SYSTOT - originated MSU count and octet counts should be the total from all links | SYS_TOT originated MSU count and octet counts should be the totaled from all links but instead reported ORIGMSUS and ORMSUOCT. This is limited to IPGW cards only. |
| 110190 | | 3 | Resolved | Defer | Traffic rerouting (HMRT) blocks Medium Priority Task for > 500 ms | Customers may see a TVG_HMUX.C or TVG_HIPR.C trouble when this occurs. This will not cause any issues for normal processing. |
| 110352 | | 3 | Resolved | Defer | LNP measurements for SSP is not reported until the second hourly period after 15 minute measurments is turned | One or more measurement report transfers to the FTP server may be delayed until the next reporting cycle. There are no known deficiencies in the report once it has been transferred. Note that any report can be generated manually via the rept-ftp-meas command within the retention period for the desired report. |
| 110895 | | 3 | Resolved | Defer | Backspace/Corrections invalid when selecting an IP terminal for use with an Eagle | The customer is unable to enter backspace character when prompted for terminal number within a Telnet connection. |
| 114678 | | 3 | Resolved | Defer | routing of a SAFETY packet with a CRC error | The likelihood of this PR occurring is extremely rare. Should it occur, most likely no one would realize that it even occurred. It would have to occur many times (5 or more?) before it would have an effect on the Eagle system. Even then it would only affect the IMT bus that had the problem. |
| 115541 | | 3 | Resolved | Defer | ARICENT PV_APCR: PC not marked CRD-Prohibited for CLUSTER PC entry. | A cluster point code (example 3-3-*) has been configured on a Linkset with an adjacent full PC(3-3-1). If a another full PC in the cluster (3-3-2) is marked as CRD-Prohibited that PC is not shown as an X-LIST entry. Insted 3-3-0 is shown as X-LIST entry. |
| 118011 | | 3 | Resolved | Defer | Code loading multiple card types of the same loading priority when one card type has problems can block cards from loading | Update: This problem occured in the field when the upgrade terminated during the flash images were downloading on HCBlade cards. The upgrade attempt to return those cards to IS-NR. The cards kept booting because the upgrade terminated before completing the downloading of the target-release flash images. So the cards were attempting to load the target-release application GPLs while still running on the source-release flash GPLs. The work around was to complete the flashing of these cards. This should not happen in the field, the E5 cards didn't load due because the cards did not have the correct flash gpls. If the cards are properly loaded with the latest flash gpls the problem did not occur. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|--|
| 120269 | | 3 | Resolved | Defer | ARPV: trp_tbl.c severity on rebooting STC cards and DHCP time expiry | The impact is a severity 1 ATH on rebooting STC cards. There is no issue in adding or deleting routes via TRP/DHCP. |
| 120310 | | 3 | Resolved | Defer | E5STC: "help" command generated Severity TMUXLIB2.C Line 729 | The overall help command appears to be too long and produces these troubles towards the end of the output. Individual help on a command by command basis works fine. |
| 120871 | Y | 3 | Resolved | Defer | CDPA Screening Table Capacity Reported Incorrectly | Customer may over provision CDPA rules when relying on the percentage full information. The over provisioning can cause incomplete screening rules download to network card. |
| 120934 | | 3 | Resolved | No-Fix | rept-imt-info:report=util provides incorrect / misleading data | Install HIPR2 cards in at least one shelf in the system. |
| 124268 | | 3 | Resolved | Defer | MLS - DPC of SCCP management messages is not verified before they are processed | If a Eagle receives a message with DPC=MLS SPC and OPC= non adjacent point code then Eagle process that message instead of discarding it. |
| 124357 | | 3 | Resolved | Defer | Module scm_bkgd.c Line 2944 trouble seen after executing INIT-SYS:DATA=PERSIST | The errors are due to tvlg capacity issues on the card. The tvlg information will be updated as soon as the correct information is received by OAM. There is no impact to the system. |
| 124950 | | 3 | Resolved | Defer | Module lb_mgr.c troubles seen during overnight traffic run | During the DSM Boot script (where the SCCP Subsystem is constantly reset) the load balance manager is unable to complete load balance within the engineered limits and produces this trouble. This isn't a concern to date because the SCCP cards do not use LB anymore. |
| 125107 | | 3 | Resolved | Defer | MLS - One-time response method TFRs/TCRs not sent when secondary routes being used have secondary point codes | Eagle may not generate a one time response TFR/TCR message for a destination that is restricted when the secondary routes being used have secondary point codes. |
| 125431 | | 3 | Resolved | Defer | Telcordia - M2PA audit - E5-ENET sent LSOS 3.7753 seconds (instead of ABORT) after not receiving SACKs for ACKs at SCTP | There should be no impact since the link was removed from service and either end may initiate re-establishment of the association. The E5-ENET card started realignment procedures following transmission of LSOS. |
| 125818 | | 3 | Resolved | Defer | scheduled OAM systot reports to the UI showing incorrect time | UI reports when extracted from Measurements Platform after 15-minute collection has been turn on then off again will show incorrect report time. FTP'd measurements reports are correct |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|--|
| 125928 | | 3 | Resolved | Defer | Telcordia - 37.5 audit - SEAS-chg-gtwy-ls with null values overwrites previous supplier specific values | On the SEAS- chg-gtwy-ls command a null value for supplier specific parameter field overwrites existing values with default values. |
| 125990 | | 3 | Resolved | Defer | Module meas_dth.c Line 510 Class 0001 Severity 1 | Some data for the STP-DTH & associate daily measurements would be lost, either 15 minute or 30-minutes depending upon whether 15-minute collection is on or not. Given this occurred during init-sys which would have caused many cards to reset, the relative loss of data associated with this error is small. |
| 126963 | | 3 | Resolved | No-Fix | SCCP messages are not handled correctly during link congestion | SCCP messages may continue to try to route even though the link is in congestion. This behaviour is transient however and fixing it involves a significant amount of effort with relatively little advantage and unpredictable impact. |
| 127773 | | 3 | Resolved | Defer | Telcordia - 37.5 audit - SEAS Register MSUDISC2 in P_COMP Reports Too Few Messages | Minimal system impact. Register count (MSUDISC2) was off by 2 during a 30-minute interval in which link congestion occurred. |
| 127777 | | 3 | Resolved | Defer | Telcordia - 37.5 audit - SEAS - Register MSUDISC3 Present in P_MTCD | Extra register in SEAS MTCD-LINK reports. |
| 128909 | | 3 | Resolved | Defer | AR_DEV_39.0: SID entries on the network cards are not updated on ent-sid completion without system initialization. | For newly defined true point codes the user needs to init-sys to get the cards updated. |
| 129523 | | 3 | Resolved | Defer | On E5-ENET card with a single link EMP connection congestion/discards occurs on at high traffic rates | None - the traffic rate required to cause this issue is well beyond the engineered traffic rates supported for IMF on E5-ENET. EMP socket congestion is expected in this case, |
| 129531 | | 3 | Resolved | Defer | rtrv-ctrl-feat causes multiple sev 1 troubles MTOS_MSB.C Line 362 | The troubles are sent when multiple SCCP cards are downloading from the MPS. The troubles are caused by the active MASP sending too many progress status messages over to the standby. There is no impact on the system as the SCCP cards continue to load and the command output is received. |
| 129958 | | 3 | Resolved | Defer | Copy De-Activate on SSED CM IPGW under network impairment test | If running at card capacity, only IMF copies are being lost due to IMF being disabled - original routed traffic is not lost. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|--|
| 130052 | | 3 | Resolved | No-Fix | ATINPQ: MSU matches ATINP srsvsel, but fails for an unexpected reason | Need better UIM since the failure is due to provisioning done by Customer within the EAGLE. Without this the customer may not realize they have a provisioning error. |
| 130052 | | 3 | Resolved | No-Fix | ATINPQ: MSU matches ATINP srsvsel, but fails for an unexpected reason | Need better UIM since the failure is due to provisioning done by Customer within the EAGLE. Without this the customer may not realize they have a provisioning error. |
| 130175 | | 3 | Resolved | Defer | Remove alarm inhibit support for TPS device | The customer has the ability to inhibit an alarm that will never occur. No operational impact. |
| 130225 | | 3 | Resolved | Defer | Module scm_utl0.c Line 6591 reported during full upgrade from 37.0 to 38.0 | The only known impact was the generation of the ATH. Apparently this did not cause the upgrade to fail, nor did the ATH keep repeating, as there was already code that would only allow this ATH to occur once per card. Also, it is worth noting there were other cards of this type in the system that did not exhibit the same behavior as this card. |
| 130466 | | 3 | Resolved | Defer | IPSG: "E4255 - Total system TPS limit exceeded" not produced when 500,000 limit exceeded. | Customer can provision more than allowed capacity. This could possibly have negative affect of overloading the IMT if all capacity is really used |
| 130622 | | 3 | Resolved | Defer | issue with dlt-card when unresolved symbols auto inhibit exists | If the card is fully deleted from the DB but allowed to be regenerated in the status system (rept-stat-card), then that slot cannot be reprovisioned. A workaround for this issue would be to remove the blade from the slot and init the active OAM. |
| 130656 | | 3 | Resolved | Defer | IPSG: During M2PA CB testing - NtMgmt UIM's displayed as coming from HIPR's | The UIM's card location will be incorrect (appear to originate from a MUX card). This is the mux on the shelf the traffic is coming from. |
| 130776 | | 3 | Resolved | Defer | Daily UA entities STATUS is "I" when the UA has been active all day | Incorrect data status (I=Incomplete) makes report look like it's missing data when it is not. |
| 130835 | | 3 | Resolved | Defer | IPSG: Copy De-Activate on M2PA (1 slk) during IMT inh-alm w/ impairment | Traffic may not be monitored under heavy load and inhibiting and allowing the IMT. |
| 131607 | | 3 | Resolved | Defer | Incorrect LNP TFP description in Feature Guide | Customer may think the EAGLE does not follow protocol for TFPs. |
| 132406 | | 3 | Resolved | Defer | INH/INIT commands reset the card but the network cards dont update there card lists | Very small chance of loosing update due to init or inh of card. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Dispo- sition | Title | Customer Impact |
|--------|------|-----|----------|------------------|---|--|
| 132657 | | 3 | Resolved | Defer | IPSG-M2PA links do not align within MTP Restart window (after init-sys) | The IPSG will not participate in MTP restart after power restart of the system. |
| 132659 | | 3 | Resolved | No-Fix | Module tprc_adj.c Line 4576 Class 01c3 Severity 1 occurs during ITU MTP Restart on IPSG | For IPSG, Sev 1 ATH is generated, instead of silently ignore ITU timer expiry. |
| 132855 | | 3 | Resolved | Defer | Change error code for MTT 4067 to list rcontext | The customer might get confused as to why their default application routekey command is being rejected. |
| 133171 | | 3 | Resolved | Defer | MOBR: Need to investigate removal of Cluster Route Support | If there are provisioned RTX cluster routes before the upgrade. They will become partly dormant for routing & could actually affect routing decisions. Work around - limitation-> check if there are any rtx provisioned for cluster before upgrade. If so, remove them before starting with upgrade. |
| 133177 | | 3 | Resolved | Defer | FTP error 55 (no buffer space available) when attempting a remote restore from FTP server | Error number 55 is seldom observed when FTP is done using E5 IPSM card. It has been observed that FTP is successfully after one or two iteration. |
| 133353 | | 3 | Resolved | Defer | TIF: No Measurement reports for TIF SNS or TIF FWDSCS | Customer will not see any measurement pegs when only using TIFSNS and/or TIFFWDCS service actions. This will not be a common case. Most customers will also be using TIFNP, which allows the generation and reporting of pegs. |
| 133406 | | 3 | Resolved | Defer | 120M_EPAP:Severity 1 "Module gtt_oai.c" is displayed at vsccp cards when we give command dlt-sccp-serv:serv=gflex:pci1=1-7-2. | Will see ath when there is no issue. |
| 133450 | | 3 | Resolved | Defer | The parameter "RI" is ent-gsmmap-scrn is not present in the documentation | None the ri can not be used. |
| 133798 | | 3 | Resolved | Defer | Filename displayed incorrectly in meas error output | If there is a failure the File name will have extra charaters an the end of the name. |
| 134167 | | 3 | Resolved | Defer | RTRV-DATA-RTDB not denied when no ELAP or EPAP dependent feature is enabled or turned on | The customer will see a sev 2 ATH. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|---|
| 134265 | | 3 | Resolved | Defer | IPSM card Severity 1 troubles and COPY-TBL command abort failure | FTP transfer may get aborted in between in rare cases. User will not be able to run act-ftp-trns or other commands for some time. This can be rectified by restarting the IPS card. |
| 134880 | | 3 | Resolved | Defer | EAGLE 40.0_E5TSM:"INIT-CARD" command is getting accepted by both appl and location. | This has no Customer impact as the same has been deferred to subsequent release. |
| 134933 | | 3 | Resolved | Defer | dms_utl.c Severity 1 error during upgrade to R40.0.0-61.38.1 | As long as the upgrade is followed as directed there is no impact on the system. |
| 135736 | | 3 | Resolved | Defer | rept-stat-gpl:gpl=eoam does not show "approved" build version status during remote upgrade | The rtrv-gpl command will provide the desired information. |
| 136099 | | 3 | Resolved | Defer | Measurements timeout issue during upgrade | Measurements may not complete during an upgrade. |
| 136107 | | 3 | Resolved | Defer | uias_msg.c severity 1 ATH received during incremental upgrade to 61.47.0 build | Trouble is put out with no known system impact. |
| 136449 | | 3 | Resolved | Defer | No way to stop monitoring an association definitively (FC heart beat always sent) | Customer will end up with an false alarm for a link they they stopped monitoring. |
| 137649 | | 3 | Resolved | Defer | Card 1113 Module uplo_mgr.c Line 1124 Class 01b6 Severity 1 | The system attempts to generate SEAS output on startup of the standby even though SEAS is not configured on the system. It puts out a trouble and does not persist beyond initial startup of the standby. |
| 138339 | | 3 | Resolved | Defer | pollmv.c severity 1 seen during overnight load/stress/volume test on eagle 1190601 | User could lose measurement data for the incomplete interval after card boot. |
| 138348 | | 3 | Resolved | Defer | SCCP CNV: Sev 1 sih_utl.c is observed on EOAM for MTP routed message with CGPA GTI as 1 from ANSI to ITUI network | UIM propagation into SEAS may have incorrect cdpa digits. Unexpected ATH to user. |
| 138607 | | 3 | Resolved | Defer | Module uplu_aft.c is observed in Upg Phase 2 when FLASH Memory is Activate on Standby GPSM-II. | An erroneous SEV 1 trouble will be generated during upgrade, which has no impact on the upgrade procedure itself. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|--|
| 139382 | | 3 | Resolved | Defer | Resource contention issue on E5IPSM card during remote backup | There is minimal system impact. The second command did not actually run (as indicated by the failure). This command actually should have been rejected as not runnable due to the first command in progress. The command can be run once the first command completes. |
| 139459 | | 3 | Resolved | No-Fix | output for IPSPG 'card' not aligned in rept-stat-sys | This PR was corrected when PR 135771 under BCR 30393 was corrected. |
| 139541 | | 3 | Resolved | Defer | Telcordia-FT - Incorrect Text in MTT When Attempting to Provision ATM Links in ITU-N24 Network | misleading MTT error if customer tries to provision a ATM link into a linkset with an 24-bit apc/sapc. |
| 139723 | | 3 | Resolved | Defer | Both MCP cards status becomes Primary. | When both MCP cards are primary, measurements are collected by both MCPs. Issues arise when each MCP attempts to transfer the collected peg counts to the other MCP. This operation will fail will numerous Sev 1s. Other than the mass of output, the collection works and each MCP has updated values. Boot one or both MCP to recover |
| 140120 | | 3 | Resolved | Defer | FC App de-activated on IPSPG with 272 B MSUs at 5000 TUC | Fast copy monitoring is lost when traffic nears 100% of rated IPSPG card capacity when in extreme configuration. |
| 140222 | | 3 | Resolved | Defer | R41_TOBR:Incorrect error code if only OBSR is ON and cdgtasn is specified with eaglegen in ent-gttset command. | Customer will have to use manual to understand incorrect paramater combination. |
| 140374 | | 3 | Resolved | Defer | R41_TOBR:Incorrect error text is displayed when invalid value is specified in TCAPACN parameter in CHG-SCCP-MSG command. | Customer will need to chaeck commands in commands manual to undestand valid values for the TCAPACN parameter. |
| 140667 | | 3 | Resolved | Defer | Card 1217 Module mc_mgr.c Line 1610 Class 01d0 Severity 1 | The secondary MCP card received a message that was out of phase with the card state. The anomaly was recorded via ATH and no other action was taken. The primary and secondary MCPs resume normal operations. |
| 140795 | | 3 | Resolved | Defer | E5MASP :SEV-1 "dbcd_dcm.c" is getting observed on E5MASP cards. | Tekelec has only observed this internally on one occasion. Deleting and re-entering association cleared the problem. |
| 141039 | | 3 | Resolved | Defer | links status is shown as OOS-MT by rept-stat-card command even when links are up on card | The problem was seen after continuous bouncing of large number of links for few hours. Initializing the affected card will correct the "IS-NR" link status that is shown. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Dispo- sition | Title | Customer Impact |
|--------|------|-----|----------|------------------|--|--|
| 141233 | | 3 | Resolved | Defer | IDPR: CalledPartyBCDNumber Digit Conversion | The conversion that is currently applied digits of the CalledPartyBCDNumber parameter by IDPR is currently limited to the RN and SP. This was the original feature intent. Now additional source for digits are possible so they may not convert properly. |
| 152325 | | 3 | Resolved | Defer | E5OAM cards fail to boot from inactive partition. | If the customer issues the alw-card:loc=<stdby>:code=inactiveprtn before the card has come back up, then the card will not get the notification that it is to boot from the inactive partition and will revert to the active partition. The procedure steps involved with the use of this command should include a verification that the card is up and ready to receive the notification. |
| 152540 | | 3 | Resolved | Defer | Large Eagle with 2800 links takes more than 5 minutes to bring all links in service. | 2800 link systems take longer than the expected 5 mins to come up after system initialization. Testing showed this could be as long as 17 minutes. |
| 152541 | | 3 | Resolved | Defer | First link reload time is more than 1 minute on a low speed link LIM cards | First link reload time is more than 1 minute on a low speed link LIM cards after card boots. It was found that 1st link on E5E1 card took 117 seconds and on HC-MIM card took 81 seconds. |
| 152542 | | 3 | Resolved | Defer | First association reload time is more than 4 minutes on IPGW cards. | First association reload time is more than 4 minutes on IPGW cards. It was found that 1st association on E5ENET card running IPGHC gpl took 6 mins 10 seconds to reload. |
| 152577 | | 3 | Resolved | Defer | INPQ/AINPQ:CC digits used in RTDB lookup not being used in outgoing DRA | In INPQ and AINPQ features, currently DEFCC is always used as CC in outgoing DRA digits, if outgoing DT format specifies CC. This could be wrong if the CC in conditioned CdPN doesn't match DEFCC. |
| 152625 | | 3 | Resolved | Defer | MCP Card Outputs Trouble | The problem causes the 200,000th LRN DTH entry (the last possible entry) not to be processed. This means that the last LRN in the daily LRN report will not be accurate. Since the daily report is an aggregation of the hourly reports, the missing peg counts can be retrieved from the hourly reports and added to the daily totals. The hours in question would be the hour prior to the occurrence of the mdth ATH. |
| 152631 | | 3 | Resolved | Defer | RTDB Database Alarms Are Not Generated For SCCP Cards That Are Booted | The EAGLE will not be notified that a booted service module card has reloaded its RTDB and is now processing RTDB-based traffic. There is no impacts on traffic processing. These alarms are informational only and do not indicate that action is required on the part of the customer. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|--|
| 152649 | | 3 | Resolved | Defer | rept-stat-mon does not show Cards denied eroute service | Rept-stat-mon is slow to display eroute cards denied service when the system goes into overload. The report does correctly display the data 10 mins later. |
| 152947 | | 3 | Resolved | Defer | Remove Special Characters from output of commands | None. The use of tab characters in output does not guarantee proper alignment between rows of a report and may introduce anomalies with automated testing. |
| 153340 | | 3 | Resolved | Defer | IDPR: Mutually Exclusive ANSIGFLEX Yes | A customer could turn on ansigflex with IDPR on. These features are supposed to be exclusive of each other so the cusotmer should not get the FAKs to do this. |
| 155053 | | 3 | Resolved | Defer | Rel41.1_IGM: "chg-sccp-serv" command is supporting "SERV=GPORT" when only IGM feature is enabled and turned ON. | Although the GPORT service state can be changed to online the this does not affect service since you cannot assign PCs/RCS, etc. |
| 155393 | | 3 | Resolved | Defer | Module ftp_mgr.c Line 2050 was seen while performing a remote restore | If the OAM times out, due to the FTP transfer taking too long due to switches not being set to full-duplex the IPS card will need to be booted before another FTP transfer can be completed. |
| 155461 | | 3 | Resolved | Defer | Telcordia - 40.1 Audit - SCOns Sent in Response to DAUDs May Not Contain Updated Congestion Levels | The endpoint would get an incorrect congestion response, then continue to poll (issue a DAUD) until the congestion status was updated. |
| 156077 | | 3 | Resolved | Defer | mtos_msb.c Line 417 trouble during upgrade from 62.38.0 to 62.41.0 | This does not always happen. When is does it has no affect on the system. The messages being posted to the active MASP is informational only. |
| 156269 | | 3 | Resolved | Defer | Telcordia - 40.1 Audit - SACK Chunk Sent Before DATA Chunk Was Received | None as the SACK will be discarded. No traffic has been exchanged yet, so traffic will not be affected. |
| 156595 | | 3 | Resolved | Defer | Telcordia - 40.1 Audit - Incorrect Response to ABORT and SHUTDOWN COMPLETE with Incorrect T Bit Value | An association could abnormally terminated due to the T bit setting, but in normal operation this would not be seen, and thus no impact. |
| 156596 | | 3 | Resolved | Defer | Telcordia - 40.1 Audit - Incorrect Response to SHUTDOWN with Unacknowledged DATA | If, when the far end issues a shutdown to terminate the association, data is unacknowledged at the Eagle, the far end may receive duplicate packets during the association shutdown process. This is a minor non-compliance for the Eagle. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------------|-------------|--|---|
| 156597 | | 3 | Resolved | Defer | Telcordia - 40.1 Audit - Incorrect Response to SACK Indicating Packet Loss | The Eagle will transmit up to cwnd new data in slow start mode even though a SACK has not been received for the retransmitted data, thus putting more data in flight than permitted (1 packet) by the RFC. |
| 156655 | | 3 | Resolved | Defer | SCRC proc time and msgs_num functionality is not consistent | The proc time reporting is not consistent. Different features are interpreting it in different ways. This has no other effect on the system. |
| 156768 | | 3 | Resolved | Defer | SP_INP_AINP: Incomplete error code displayed when RNAIV and DRANAIV are specified out of range. | The reject message gets truncated. The reject reason is output. |
| 156819 | | 3 | Resolved | Defer | R_41.1: Incorrect Display in RTRV-DATA-RTDB command for Digit actions DELCC and DELCCPrefix. | RTRV-DATA-RTDB displays slightly misleading data. The correct data can be gotten by retrieving the DN from the EPAP GUI. |
| 156930 | | 3 | Resolved | Defer | SP_IDPR: REP-STAT-SCCP command shows TTR counter SUCC peg for UIM- 1426 (GRN Missing) when SPORT ON | If IDPR Service portability (S-Port) is to be applied on an IDP message for an own-network subscriber AND GRN is not provisioned in EPAP DB for the DN, Eagle will count this message as Success against TTR service for rept-stat-sccp statistics. Expectation is to report this as Warning. Also, IDPRMSSUCC measurement register is incremented for such scenarios. |
| 157119 | Y | 3 | Pending_Review | Monitor | rept-stat-iptps reporting value 0 for an IPSP link processing traffic | Customer unable to get IP TPS for some links processing traffic. Loss of traffic could occur if the link is deactivated/re-activated. The workaround consists of rebooting the card. |
| 157155 | | 3 | Resolved | Defer | SP_IDPR: Measurement Counter IDPRMSUCC is getting pegged for RTDB lookup fail scenario (No Match CdPN for CDPNNP SA) | In the no-match-with-rtdb-entry-present case, the IDPRMSSUCC measurement will be pegged, instead of the IDPRMSFAIL measurement. This is inconsistent with the customer doc and FD. The customer will see fewer IDPRMSFAIL counts than indicated in the customer doc. The content of outgoing MSUs is not impacted. |
| 157463 | | 3 | Resolved | Defer | 2800_Links:mprml_sl.cpp Line 3636 Class 01c1 Severity 1 | This is very unlikely to happen at a customer site. If it does there would still have to be a switch of MCP activity to lose measurements data stored on the EAGLE. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|---|
| 157714 | | 3 | Resolved | Defer | Stuck Alarm: 0013 Card is isolated from the system | An alarm that should have been cleared is maintained on the MCP card even though it the card is in service. This is a left over alarm from the faulty MCP card that was previously in that slot. An activity switch will clear the alarm. |
| 158049 | | 3 | Resolved | Defer | rept-stat-mps doesn't allow OOS-MT Isolated ELAPs to go Standby/Active if alarms are present | No system impact. Works as designed. If an alarm is present on the MPS, then the PST/SST will show the proper state. An enhancement would allow the AST to show the Active/Standby status of the MPS. |
| 158137 | | 3 | Resolved | Defer | Cannot provision MGTT data in GTA entry for SCCP Conversion - it demands AMGTT! | Customer can not change the GTI unless AMGTT is on. |
| 158246 | | 3 | Resolved | Defer | Telcordia - 40.1 Audit - Verify-PE only shows single port for LIMATM card. | SEAS cannot query the status of port B on link cards. |
| 158250 | | 3 | Resolved | Defer | Telcordia - 40.1 Audit - REPT-SCRREJ contains erroneous data for link-set name parameter. | REPT-SCRREJ output contains bogus link set id in SEAS. |
| 158328 | | 3 | Resolved | Defer | Rel-41.1: "rept-stat-mps" command shows GSM state as Active when G-port feature is enabled and OFF. | The rept-stat-mps:GSM status is slightly misleading when an MPS dependent feature is enabled but not turned on. Use rtrv-sccp-serv to discern the true GPORT status. |
| 158419 | | 3 | Resolved | Defer | Eagle R41.1: unavailable IP connections on SCCPHC card after set-time command | When using set-time IP connections w/EPAP may be lost for 10 seconds. |
| 158675 | | 3 | Resolved | Defer | nppe_apply_1 Severity 1 when Conditioned Number is an Empty Digit String | A Sev 1 is shown but there is no affect on the processing of the message. |
| 158784 | | 3 | Resolved | Defer | A GTTSET can be deleted even if it is referred in gtt selector table | Customer has to verify that GTTSET they are deleting is not refernced buy a GTT selector |
| 158818 | | 3 | Resolved | Defer | M2PA link goes OOS during ARHost failover test | Customer should use RTIMES values greater than 3 to avoid message loss in failover situation. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|---|
| 158995 | | 3 | Resolved | Defer | Eagle R41.1: | <p>When this problem occurs, one or more entities will report "Could not read measurements" instead of reporting the data for scheduled measurements.</p> <p>However, this problem is unlikely to be seen in the field due to the larger system size which alters the timing of the request.</p> <p>The customer can still get the data by manually pulling the data.</p> |
| 159003 | | 3 | Resolved | Defer | tvgr_mgr.c (NO.TVG.RSP.FROM.HW) Sev 1 found during overnight run | No service impact seen as the system self recovers. |
| 159004 | | 3 | Resolved | No-Fix | GWS command rtrv-scrset inconsistency | None |
| 159079 | | 3 | Resolved | Defer | IAR: TST-MSG returns unexpected info when TTR CgPN fails and TTR CdPN is UNMODIFIED (ie neither are Encoded) | The MSU / TST-MSG is processed as it should be. But if there is a CgPN NPP failure (i.e. no CgPN rule was found), the cause of the failure in TST-MSG and ent-trace is shown incorrectly. |
| 159118 | | 3 | Resolved | Defer | IMT VC alignment "HOLE" | The IMT Virtual Circuit (card to card) alignment procedure has a defect that may cause un-necessary retransmissions when Virtual Circuits align. This problem may manifest itself as retransmissions on the IMT bus during an IMT bus ALW command. |
| 159250 | | 3 | Resolved | Defer | STC card inhibited without requiring "FORCE=YES" | No functional impact. The customer can disable monitoring without specifying force=yes. |
| 159292 | | 3 | Resolved | Defer | Telcordia - 41.1 SEAS System Test - SCHED=D_MTCS contains incorrect syntax for register value | Eagle SEAS MTCS has a syntax error per GR-310. The first register value is followed by a colon instead of a comma. |
| 159298 | | 3 | Resolved | Defer | Telcordia - 41.1 SEAS System Test - SCHED=D_MTCS reports incorrect maintenance state for ENTTYPE=LNKSET | SEAS MTCS report will report linksets as 'UAV' if all links are OOS, and will report linksets as 'OOS' if all links are unavailable. |
| 159351 | | 3 | Resolved | Defer | After STC overload/outage test, IP cards did not correctly re-start copy functionality | The customer impact is the alarm status of the monitoring link alarms may not be reported by the UAMs. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Dispo- sition | Title | Customer Impact |
|--------|------|-----|----------|------------------|--|---|
| 159353 | Y | 3 | Resolved | Defer | DBG-DDB command report checksum mismatch while no DDB inconsistencies are reported by the system | The difference between what the OAM is reporting and result from dbg-ddb command could lead the customer to be confused. |
| 159375 | | 3 | Resolved | Defer | IPSG card booted after INIT-SYS with radb_mgr.c module (No DB changes were being made) | The IPSG card that shows the obit will reboot twice instead of once during the init-sys. |
| 159403 | | 3 | Resolved | Defer | IPGW Excess Re-transmit alarms during network impairment testing -- no traffic loss | This alarm is occurring a little earlier than design intent. This means the customer may get an alarm when the network is impaired but still within acceptable operating conditions. |
| 159451 | | 3 | Resolved | Defer | Cannot delete ANSI SID | Customer will not be able to deprovision their ansi sid |
| 159455 | | 3 | Resolved | Defer | scm_oamhc.c Line 627 from warm restart | The standby OAM may not get updates of persistent device states on large system and dual boot of OAM. |
| 159466 | | 3 | Resolved | Defer | Filename for "release" parameter in act-upgrade:action=getrel command should be maximum of 39 characters instead of 30 | No impact. User will have to use a filename with 30 chars or less |
| 159499 | | 3 | Resolved | Defer | E5-ENET card generating Module hw_imtpci_in Line 1424 Class 01bd Severity 1 | The system impact is minimal since the problem only showed up when one of the HIPR2 had capacitor knocked off that a lot of bad packets were generated. Once a while, one of those back packets are passed on to the processor by the FPGA. Even in that case, SW discards it and doesn't pass it up the stack. |
| 159643 | | 3 | Resolved | Defer | After link fluctuation M3UA association may require 2 intis to recover. | In some case after failure association may take slight longer to align. This will occur automatically and in most cases will not be noticable. |
| 159644 | | 3 | Resolved | Defer | BICC MTP conversion from ITUI to ITUN24 generates Error codes:Invalid Stream Identifier & Invalid Param Value | The conversion is failing as expected, but the wrong error message is sent when the number of bytes in the ITUI message is over 4075. This only affect cusotmers using ITUN24 |
| 159681 | | 3 | Resolved | Defer | TRBL Queue is full:elements overwritten Module crc_utl.c Line 523 Class 01b1 Severity 1 | At this point it is believed the card would have to be replaced as only occurrence seems to have been caused by defective HW. |
| 159743 | | 3 | Resolved | Defer | E5-class card obit with hw_ixp1200_c Line 1711 Class 01ce | An E5-class card may boot when a bus is inhibited/allowed. In those cases the system recovers normally. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|---|
| 159848 | | 3 | Resolved | Defer | Certain encoded characters causes serial terminal to lock-up | Certain encoded characters will cause serial terminal to lock-up. This does not affect any of the other serial terminal interfaces, only the one in which the invalid character was entered. For KSR terminals, disconnect the terminal session and re-connect the terminal session. For VT320 terminals, pressing 'F11' re-establishes the terminal. |
| 160001 | | 3 | Resolved | Defer | Upgrade from 62.57.0 to 62.60.1 stops on unprovisioned card that is present | The upgrade command terminates. Upgrade can not be completed until the failing card is manually flash (using the multiple command method) or the THRES= (threshold) parmeter is NOT specified. |
| 160049 | | 3 | Resolved | Defer | Disconnect on password prompt makes terminal unusable | Terminal could become unusable if entering this specific chg-ftp-serv command and then not entering a password and disconnecting. A manual Reset of the terminal(inh/alw) or OAM reset will unblock the terminal. |
| 160204 | | 3 | Resolved | Defer | Telcordia - 40.1 Audit - Incorrect P_MTC/D_MTC/DTH LNKAVAIL and DRDCLFLR Register Values | Due to rounding errors link availability timers could be off a few seconds per day. |
| 160480 | | 3 | Resolved | No-Fix | disc-imt:bus=b:loc=<Active oam> followed by init-mux:bus=a on rapid succession causes Active OAM to boot | The IMT Bus status takes a maximum of 3 seconds to get updated after the disc-imt command. It has been decided to update this behavior in documentation. If the init-mux command is fired after 3 seconds of executing disc-imt command, OAM boot isn't observed. |
| 161029 | | 3 | Resolved | No-Fix | R42_GTT_ACT: Forward and Duplicate Action functionality is not working if a GTT action is changed from Discard to Fwd or Dup. | None |
| 161064 | | 3 | Resolved | Defer | When AMGTT/AMGTT CgPA Upgrade feature is OFF, then command 'rtv-gtt:type=6:cggmod=yes' should be rejected with MTT E4789 | Customer will get output showing empty tables instead of rejecting the command. |
| 161128 | | 3 | Resolved | Defer | Measurements transfer failure UAM with invalid (no) information | An Extraneous UIM with limited debug data displayed after an FTP failure UIM is displayed. There is no impact to the system. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|-------------|-------------|---|---|
| 161155 | | 3 | Resolved | No-Fix | R42_MTPRGTT:With SCCP Conv OFF, when MTP routed message crossing from ITUI->ITUN, NTT is getting updated if MTPRGTT=USEMTPPC. | System impact is none. Marking this PR as no-fix since now NTT parameter is moved to GTMOD table. |
| 161160 | | 3 | Resolved | Defer | Module hpru_mgr.c Line 1532 Class 0075 | The obit extends the time the IMT bus is down. |
| 161526 | | 3 | Resolved | Defer | hundreds of Module dbcdeggt.c Line 25138 Class 01c3 Severity 1 following format-disk on TDM | Streaming ATHs. Unusable standby TDM due to formatted fixed disk. To prevent, use the COPY-DISK command in lieu of the FORMAT-DISK command should be used. Highly unlikely that customer will encounter this issue in the field in normal operation. Most documentation issues a COPY-DISK. |
| 161770 | | 3 | Resolved | Defer | Invalid data cause inconsistent command output for RTRV-GSMOPTS | No operational impact. The user will get inconsistent format of output. |
| 161779 | | 3 | Resolved | Defer | IPSG_PPI:2 severities "ecam_utl.c" and "gpluoam2.c" are observed during upgrade from Rel 41.0.1 to 41.1.1. | Troubles generated during the format-disk portion of the Upgrade when the active MASP was attempting to read the System Release table on the standby. The format and upgrade completed successfully. |
| 161902 | | 3 | ReadyToTest | Active | HIPR2: Contents of EXTSTATS table not initialized properly following upgrade. (Telcordia-FT) | |
| 162021 | | 3 | Resolved | Defer | IMTPCI: Move functionality of C function itx_place_msg_on_rtb to microcode | Implementing this PR would enhance the performance in the COM side (IMTPCI GPL) of the E5 class cards, e.g.: HCMIM, SM4G and EPM in a measurable though not dramatic manner. There is otherwise no impact on the operational software. |
| 162378 | | 3 | Resolved | Defer | E5-OAM Module ath_vxw.c Line 3051 during init-card script (warm boot) | The card may double boot because of this issue. |
| 162500 | | 3 | Resolved | Defer | Provisioning OPC/CgPC of different network domain is allowed in OPC/CgPC GTT sets | The customer is not protected from misprovisioning the GTT tables. However there is no affect as the entry just would not be used. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|---|
| 162571 | | 3 | Resolved | No-Fix | 42.0 Upgrade error "System Release ID table read on 1117 removable failed" | None |
| 162658 | | 3 | Resolved | Defer | CHG-SCR-SIO command takes around 7 mins to complete | Large number of changes to GWS could take extended amount of time. |
| 162819 | | 3 | Resolved | No-Fix | Module sum_mgr_imtp Line 662 Class 0074 Severity 1 | There are no other adverse effects from the trouble, and the problem heals itself automatically. These troubles should not again be observed once all cards are running R42.0 or later GPLs. |
| 162827 | | 3 | Resolved | Defer | uias_oamhc.c Line 685 Obit after format to the inactive partition | Communication between the MCAP and TDM was interrupted for a sufficiently long time to cause a timeout which resulted in the obit. The system recovered. |
| 162830 | | 3 | Resolved | Defer | CGPA/CgPC is not converted when relayed messages crosses the domain. | Currently CgpPC conversion is not perform when a non-GTT Service Relayed MSU does ITUN <-> ITUI or ITU14 <-> ITU214 network domain crossing. |
| 163035 | | 3 | Resolved | Defer | SLAN on E5 based cards | RTx appear and impact troubleshooting but no other confirmed impacts |
| 163079 | | 3 | Resolved | No-Fix | Severity 1 module observed for very large (1 MB) SOIP verification request. (Telcordia) | The SEAS output queue is not sorted and under extreme SEAS congestion scenarios there is a potential to lose higher priority messages from the queue in favor of lower priority messages when discarding. |
| 163141 | | 3 | Resolved | Defer | DAVA not generated correctly by IPGW | If another Application Server (or Servers) is/are connected to the same card when the last ASP in an AS fails, and the only ASP active to the other Application Server is hosted by the same card, the other Application Server will have to begin to audit to find when the failed AS becomes available again (which is generally normal practice anyway). |
| 163200 | | 3 | Resolved | Defer | KSR terminal shows an extra line on the screen when you up arrow sometimes | If the problem occurs, the customer is still able to execute commands. |
| 163395 | Y | 3 | Resolved | Defer | Secondary path of a multihomed association may become restricted | Associations are in restricted status and then traffic failover would not be successful in case of failure on the primary path. |
| 163480 | | 3 | Resolved | Defer | DRMS TBL ID = 8 Checksum mismatch while in mix mode during EOAM transition to E5-OAM | No system impacts were observed after the operation. The database was consistent after the transition procedure. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|---|
| 163554 | | 3 | Resolved | Defer | Two MCP cards become Primary during oam to mcp transition | When both MCP cards become primary, both cards assume collection and reporting roles. This results in a number of Sev 1 ATHs as the two cards attempt to interact. This is fixed by boot either MCP card. When it comes back up, it will assume the secondary role. |
| 163892 | | 3 | Resolved | Defer | Copy-disk failure: Error accessing Active Partition table 364 on active TDM (A) (Telcordia-FT) | This is a low probability scenario. If hit, a work-around can be provided by Tekelec. |
| 163898 | | 3 | Resolved | Defer | CHG-LNPOPTS: NAIV Parameter Entered into CDT as Digit String-should be a number range | This is a format issue. No impact to the customer. |
| 163943 | | 3 | Resolved | Defer | rtrv-srvsel is displaying all the entries without the force and num parameters. | Customer will always get all the entries for srvsel regardless of number requested. |
| 163991 | | 3 | Resolved | Defer | dmshc_lock.c Line 0455 ATH during OAMHC-to-MCP transition | Potential loss of measurements data if a collision occurs between measurements and table copy. |
| 164050 | | 3 | Resolved | Defer | ATM links take greater than 16 min to reactivate | ATM links may take significantly longer to align than they should. |
| 164092 | | 3 | Resolved | Defer | Duplicate Point codes displayed in NPSSP measurement report | The measurements subsystem is not equipped to handle identical point codes that are provisioned as different types (i.e. dpca vs dpcn24). This results in inaccurate reporting of NP and LNP SSP entities. |
| 164119 | | 3 | Resolved | Defer | E5meas_Rel 42.0:Severity 1 mcc_queue.c observed after giving the "init-card" to E5-OAM. | Occasional ATH when one of the E5OAMs is reloading. |
| 164124 | | 3 | Resolved | Defer | E5meas_Rel 42.0:"chg-ip-card:loc=XXXX:rstdoma in=no" resets the domain name to NULL value | Card's domain name gets set to NULL during a chg-ip-card. Execute a second chg-ip-card:domain=xxxx to restore domain name. Note that card has to be rebooted anyway for the ipcard data to take affect. |
| 164136 | | 3 | Resolved | Defer | Incorrect display of number of rules for a screen | Customer can provision more screening rules than will download to cards. |
| 164245 | | 3 | Resolved | No-Fix | meas_dth ATH occured during E5-MASP synching and after oam to mcp transition | None. Since the Meas Subsystem was in transition from OAM to MCP, the ATH is indicative of an anomaly, but not a problem. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|--|
| 164303 | | 3 | Resolved | Defer | R42: AMGTT data should not be applied if PC domain found in CCGTA translation does not matches with PC domain in main GTT. | During CgPA conversion, if PC domain of outgoing message doesn't match that of configured GTT Translation for CgPA GTA then the GTT Translation data should be ignored (as per FD). But currently, this functionality is not correctly implemented. |
| 164342 | | 3 | Resolved | Defer | act-upgrade:action=convertstp command executes 2 hours after command has been entered. | If the upgrade procedure is followed this scenario should not occur. |
| 164353 | | 3 | Resolved | Defer | TERMINAL 1 Terminal failed | This only affects E5-OAM. This is seen in an office where serial terminals are connected with RTS is tied to DCD. This is incorrect wiring. To make the terminals work wire the terminals as required by Tekelec in customer documentation. |
| 164425 | | 3 | Resolved | Defer | R42.0:Checksum Mismatch observed on 63.20.0. | No system impacts were observed and the database restore command was successful. |
| 164440 | | 3 | Resolved | Defer | lb_mgr.c Line 3329 Class 01d8 Severity 1 from SSEDCEM cards | this trouble does not impact the system. |
| 164488 | | 3 | Resolved | Defer | Card 1113 Module ilm_mgr.c Line 592 Class 0001 Severity 1 on 41.1.3-62.71.1 | Self-healing issue that does not have any adverse effect on normal operations. |
| 164500 | | 3 | Resolved | Defer | crc_utl.c Line 520 Class 01b1 Severity 1 -- init-card:appl=oam | This issue may delay standby MASP to return to normal operation due to manual intervention requirement consisting of rebooting the standby MASP to recover this device. |
| 164516 | | 3 | Resolved | No-Fix | R42: Output of "ent-trace" command is displaying incorrect ANSI DPC. | Since ent-trace command is used for debugging purpose, there is no system impact. |
| 164547 | | 3 | Resolved | Defer | HIPR1 activity monitor for the receive side is not working correctly | Should a condition occur that stalls the Rx hardware, the software would not be able to detect the condition and would not boot the card to recover. This defect was discovered during a code inspection and it is not known that any situations that could trigger this problem actually occur. |
| 164685 | | 3 | Resolved | Defer | Threshold value reported in unsolicited SEAS link congestion output is incorrect | The SEAS interface provides buffer usage. The congestion level is correct. However on some link types the buffer usage indicated may be incorrectly reflected. However the user can not look at or change the buffers so there is no impact on operation. |
| 164709 | | 3 | Resolved | Defer | Reference count of Mapset is not getting updated when given with xlat=dpc in GTA commands | Only affect xlat =dpc which means if using SSN from incoming MSU the MAP referenced Set could be deleted. A UIM would print out if MSUs needing this MAP Set were processed. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|---|
| 164713 | | 3 | Resolved | Defer | R42: Severity 1 observed on E5OAM card when restore DB action is performed from Fixed Disk. | There is no impact on the restore operation. The trouble is just output when it should not be. |
| 164803 | | 3 | Resolved | No-Fix | R42:Sev 1 gtt_sel.c observed at E5SM4G card, when sending msg with CGPA GTI as 1,hierarchy FCG. | No system impact. Workaround: Change CGPA GTI in MSU to 0/2/4 |
| 165005 | | 3 | Resolved | Defer | SEND-MSG used in checking Health of the system does not find multiple issues. | If there issues to correct it requires repeated issuing of the SEND-MSG or the ACT-UPGRADE. The system will need to be booted out of upgrade mode in order to make provisioning changes if required |
| 165019 | | 3 | Resolved | Defer | KSR Terminals lockup and show commands from previously run scripts when ^A | This sometimes happens when a script is run on a terminal. If this issue happens then the terminal should be inhibited and allowed to clear this issue out. |
| 165089 | | 3 | Resolved | No-Fix | cmt_rx.ASM Line 825 Class 0001 Severity 1 | no impact impact on the system |
| 165108 | | 3 | Resolved | Defer | On a serial terminal, when entering commands, sometimes, characters go missing | The problem only occurs when executing an obscure combination of left arrow, right arrow and insert key presses when entering a command. the user will just have to reenter the command if they manage to cause this issue. |
| 165129 | | 3 | Resolved | Defer | FLBR ENHANCEMENTS: FALLBACK fails when GTT Table referenced is EMPTY | According to FLOBR whenever no B-tree is found in CdPA GTT set then search function returns database failure. The FALLBACK option is not used in case of the database failure. This is contrary to the basic description of fallback and could cause some confusion. |
| 165181 | | 3 | Resolved | Defer | standby OAM card inhibited flag not reset when active OAM boots | Rept-stat-card will show an inhibited standby E5-OAM as active, after multiple role changes. The card remains inhibited as expected. |
| 165218 | | 3 | Resolved | Defer | 10 minute delay for output of RTRV-ASSOC:ANAME | The command can take up to 10 minutes to finish displaying output. |
| 165263 | | 3 | Resolved | Defer | R42:Help command of chg-sccp-msg displays incorrect supported values for TCAPACN. | Customer will need to read customer documentation to get the correct list of accepted values. |
| 165271 | | 3 | Resolved | Defer | Rtrv-gtt/gta commands displayed inconsistent output values for some of the parameters | No customer impact as the case differences does not make the output unreadable. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|--|
| 165293 | | 3 | Resolved | Defer | IMT MSU retransmission (OAM causing MSU flood) | There is not real system impact to the customer other than the rept-imt-lvl1 command displaying the retransmission counts for each card. Since the messages are retransmitted, they arrive successfully on the OAM card and are processed appropriately. |
| 165295 | | 3 | Resolved | Defer | IMT MSU retransmission (BICC causing MSU flood) | Little real system impact other than clouding IMT debugging |
| 165296 | | 3 | Resolved | Defer | IMT MSU retransmission (Meas. Platform causing MSU flood) | Potential excessive IMT traffic |
| 165298 | | 3 | Resolved | Defer | IMT MSU retransmission (STC cards causing MSU flood) | Only impact is to troubleshooting on IMT. |
| 165327 | | 3 | Resolved | Defer | during start of upgrade standby OAM generated aud_mgr.c severity 1 | The upgrade process is not affected. |
| 165428 | | 3 | Resolved | Defer | f_idpr encoding test fails in certain cases where the TCAP CgPN field decreases in size | This only occurs in the unusual case where the SCCP parameter order is Data-CdPA-CgPA and the TCAP CgPN is reduced in size during IDPR processing. This issue was found during unit testing for PR165012. To date, no customers have been impacted by this issue. Therefore, the priority is low and the fix can be deferred until a subsequent release. |
| 165550 | | 3 | Resolved | No-Fix | OAMHCMEAS: CPU degradation of the Active E5-OAM during collection | The system is working as required and CPU utilization is not a functional issue. |
| 165564 | | 3 | Resolved | Defer | backspace on terminal in KSR mode intermittently blanks the line | The problem is intermittent. If a user encounters the problem, pressing enter followed by 'up-arrow, will allow the user to correct the situation. |
| 165566 | | 3 | Resolved | Defer | tk_smsg.c stack trace data is inadequate | This does not affect operation of the system. The additional data would be used by internal Tekelec resources for determining why the trouble occurred. |
| 165621 | | 3 | Resolved | Defer | act-upgrade:src=server doesn't work with windows ftp server | Customer will not be able to do remote upgrade if the release is retrieved using wftpd server on windows. ftp will work on Solaris/Linux based machines and GuildFTPd on windows. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|---|
| 165651 | | 3 | Resolved | Defer | Code can pass a negative value to API that only access unsigned values | Problem discovered during a code inspection. No adverse effect due to this potential problem is known to exist. |
| 165684 | | 3 | Resolved | Defer | Rel 42.0 E5OAM Meas:Standby OAM card booted randomly with OBITs after reverting form E5-OAM setup. | This should not occur as EOAM shjould not be put in system with E5-OAM |
| 165732 | | 3 | Resolved | Defer | Meas hourly processing not completing properly | Customer is able to retrieve hourly reports after hour ends, i.e. the 0100-0159 report will be available after 0300. The data is complete and accurate, just not available as timely as it should be. |
| 165758 | | 3 | Resolved | Defer | R42:FTRA4.3 - H0 and H1 parameters incorrectly displayed in the retrieved CSV file for rtrv-scr-sio command. | No lost data as there is nothing to display. Since CSV fail customer script should handle |
| 165786 | | 3 | Resolved | Defer | Card Failure: Card 1113 failed to Download BLMCAP, | The flash command may have to be repeated to take effect. |
| 166116 | | 3 | Resolved | Defer | R42: clc_mcap.c trouble observed on E5OAM card when converting EAGLE to duplex mode by inserting E5OAM | Not lilkey to happen as simplex operation of OAM is not normal configuration. Even if it does happen problem is self correcting. |
| 166203 | | 3 | Resolved | Defer | Incremental Upgrade from 41.1.0-62.64.1 to 41.1.4-62.73.1 Fails | Upgrade fails to complete. |
| 166207 | Y | 3 | Resolved | Defer | GLS cards should produce UIM when there is binder failure | In most cases the new screen set just will not load. |
| 166334 | | 3 | Resolved | Defer | during incremental upgrade, ipls_meas severity 1 is generated | E5OAMHC meas application will not able to FTP reports when this problem occurs since it was unable to read the FTPSERV table. This is corrected by booting MASP that generated the ATH. |
| 166335 | | 3 | Resolved | No-Fix | unexpected disk time out alarms generated during upgrade | The disk access message is generated and the system recovers (indicated by the UIM 1106 - IMT GPL reloading 2 of 2 message being displayed.) If the system were not to recover, the TSM GLS cards would double boot in Phase 3 when they were being upgrade. The upgrade command handles this bahavior and continues. |
| 166337 | | 3 | Resolved | Defer | LNP meas: Comma after last register for LNP and SSP hourly and daily reports. | The last meas value printed in a csv report may or may not have a following comma. This does not mean that values were omitted. Meas data accuracy is not affected. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Dispo- sition | Title | Customer Impact |
|--------|------|-----|----------|------------------|---|--|
| 166340 | | 3 | Resolved | No-Fix | D_MTCS LNKSET LSMTCST Error (Telcordia-FT) | No system impact. Reporting issue of missing value when linkset contains Unavailable and inhibited/Out of service link states. |
| 166486 | | 3 | Resolved | Defer | E2508 Cmd Rej: SCMGFID is invalid when issuing chg-scr-cdpa | MTT returned should be that the parm SCMGFID is required to be entered |
| 166498 | | 3 | Resolved | No-Fix | REPT-GTWYACT Not Sent on Legacy OAM (Telcordia-FT) | No system impact as it is a reporting issue only on Legacy OAMs. This is supported on E5-OAMs. |
| 166531 | | 3 | Resolved | Defer | IPSG msucount discrepancies "msucount -l" vs "msucount -a" | The pass command for msucount -a may not be 100% accurate. |
| 166592 | | 3 | Resolved | Defer | R42:FTRA4.3 - Incorrect information in Logs for dlt-dstn using Update Table | Customer sees a "Command not supported" message in their logs when the command is supported and does execute. |
| 166593 | | 3 | Resolved | Defer | R42:FTRA4.3 - Validation fails on FTRA for ent-card but same command is successful through Eagle terminal | The customer may have to use the ent-card on the EAGLE instead of FTRA. |
| 166606 | | 3 | Resolved | Defer | Module trp_tbl.c Line 1133 Class 01c3 Severity 1 | The system impact for this issue is no more than a sev1 ATH generated by TRP module in case Ethernet interface goes down. |
| 166659 | | 3 | Resolved | Defer | Chg-lnp-serv generates dbcd_tts.c #1329 Sev 1 when an existing alias TT is changed. | Trying to change various parameters of an Alias TT entry using chg-lnp-serv command will generate a harmless Sev 1. |
| 166667 | | 3 | Resolved | Defer | FIFO counts reported by rept-imt-lvl1 and rept-imt-info differ | Miminal as TAC noramlly is the only one checking these counts. |
| 166677 | | 3 | Resolved | Defer | E2011 Cmd Rej:Missing mandatory parameter- is missing a space | None expected as the space missing in the output just makes it incosistent with format of other reject messages. . |
| 166710 | | 3 | Resolved | No-Fix | scm_hwvf.c Line 1486 sev 1 output during 40.1.5-62.13.36 upgrade to 63.29 | No impact if proper procedures are followed. |
| 166711 | | 3 | Resolved | No-Fix | During initalization of masp for upgrade UIM 0055 Persistent device state tbl corrupt outpu | UAM will be cleared when both MASPs are running the target GPL. |
| 166930 | | 3 | Resolved | Defer | Command rtrv-dstn:dpc=2-**8-*** is getting accepted. | Invalid data is accepted for the command. No operational impact. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Dispo- sition | Title | Customer Impact |
|--------|------|-----|----------|------------------|--|--|
| 166935 | | 3 | Resolved | Defer | IMT MSU Retransmissions (due to high traffic levels) | The retransmissions (although should not be occurring) are not causing any real issues with messaging traffic as the message that encountered the problem (4ms timeout) was retransmitted and successfully processed. This has no real impact on the system. |
| 166942 | | 3 | Resolved | Defer | Module mcc_queue.c Line 954 Class 01c3 Severity 1 when E5-OAM is coming up. | There is no adverse effect on the E5-OAM card due to this trouble; it appears to be a timing issue: the COM begins reporting that there is no IMT connection even before it accomplished a connection for the first time after the card has booted. |
| 166960 | | 3 | Resolved | Defer | R42: Inconsistent behaviour observed in ent/chg/ rtrv-srvsel commands when DFLFACT is specified as NONE. | none - the error reject command for 2 different commands uses different logic so the reject reason in each case is different. |
| 166975 | | 3 | Resolved | Defer | Sev1: Card 3109 Module tvg_hipr.c Line 1786 Class 01c1 Severity 1 | May be slight delay on bus recovery if this trouble occurs. Delay should be in the order of 250ms. |
| 167114 | | 3 | Resolved | Defer | Module tosil_md.c ATH from HIPR card | The unhandled message is safely discarded and results in no adverse effect to the system. |
| 167138 | | 3 | Resolved | Defer | converted TDM is dropping out of upgrade phase when it becomes active during incremental upgrade | When upgrade fails to continue the workaround ACT-UPGRADE command is re-entered. [Reference 909-1570-001, Procedure 8, Step 1.] must be accomplished. |
| 167173 | | 3 | Resolved | Defer | Extended Bert not running when in simplex OAM mode | BERT test sometime fails when running in Simplex (one OAM only) mode. |
| 167174 | Y | 3 | Resolved | Defer | Customer Docs example shows output in ms when int should be in micro seconds. | There may be minor confusion as the command output does not match the example. |
| 167211 | | 3 | Resolved | Defer | UAM 0012 is assigned to wrong output group | UAM 0012 will display on any terminal with the CARD output group rather than terminal with the MEAS output group. The UAM has a very low probability of occurrence. |
| 167235 | | 3 | Resolved | Defer | HIPR2: Unexpected "H" and "S" in TVG result | Scenario to create this is not part of normal operation. Even in the case where these occurred there appears to be no adverse effect to the operation of the system. |
| 167266 | | 3 | Resolved | Defer | Card 1311 Module im_com.c Line 996 Class 01c3 Severity 1 | The upgrade execution needs to be restarted after the flash images on the affected cards are verified. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|---|
| 167313 | | 3 | Resolved | Defer | HIPR2: extended BERT test should be allowed on IS-ANR bus when other bus is IS-NR | The Extended Bert is a new feature in 42.0. Having it unable to work on IMT IS-ANR may it take longer to trouble shoot an issue on the IMT. |
| 167329 | | 3 | Resolved | Defer | Location range incorrect in CDT for INH-CARD | Possible confusion as documents do not show the correct range |
| 167335 | | 3 | Resolved | Defer | HIPR2: fails to realign at HIGH speed when swapping HIPR with HIPR2 on E5-OAM eagle | When a HIPR2 is re-inserted in its shelf, the bus may not align to the high speed rate. The workaround is to issue the init-mux command. |
| 167395 | | 3 | Resolved | Defer | Incorrect Error Message displayed when HIPR2 is un-plugged/ boots during EXT BERT | Minimal as the primary objective in this case is to terminate the Test and that is getting achieved. The message may casue additional troubleshooting to determine why the failure. |
| 167436 | | 3 | Resolved | Defer | HIPR2: hipr2op_isr ATH/Obits seen in e9010801 overnight run with init-mux script | The HIPR2 card may double boot early in its initialization sequence and recovers normally. The only adverse impact appears to be that the bus takes about 10 seconds longer to come back IS-NR. |
| 167494 | | 3 | Resolved | Defer | SSN range incorrect for rtrv-scr-aftpc and rtrv-scr-cdpa | Possible confusion to to error in documentation. |
| 167496 | Y | 3 | Resolved | Defer | E4440 Cmd Rej: Card running the specified code load not documented | Missing reject command can make recovery take a little more time. |
| 167497 | Y | 3 | Resolved | Defer | Unclear of IP address to use in System managment document | Minor confusion on the cusotmer as how to set up Putty. |
| 167498 | | 3 | Resolved | Defer | Terminal Range Incorrect for rtrv-seculog and rept-imt-info | Customer may not realize that output can be sent to IP terminals. |
| 167500 | | 3 | Resolved | Defer | SCCPTPSCAP range incorrect for chg-th-alm | Customer may not realize the full range they can use. |
| 167502 | | 3 | Resolved | Defer | Optional Parameter Value Incorrect for rept-stat-trbl and rls-alm | The customer may type in the incorrect spelling as that is what is in the manual. |
| 167504 | | 3 | Resolved | Defer | Range incorrect for addtblcnv and deltblcnv in chg-upgrade-config | None as customer should not use these options without direction from Tekelec. |
| 167505 | | 3 | Resolved | Defer | TMRPROV parameter not listed and LPSET should be Mandatory for chg-atm-lps | The terminal will promote for the mandatory parameter but the customer may not realize they can change the other parameter. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|--|
| 167507 | | 3 | Resolved | Defer | Location range incorrect and set to "Optional" for disp-disk-stats | May be confusion as docs do not give correct location. |
| 167508 | | 3 | Resolved | Defer | Location range is incorrect for rept-stat-gpl: missing HIPR locations | Customer may not realize command can be used on HIPR and HIPR2 gpls. |
| 167512 | | 3 | Resolved | Defer | Location range incorrect for rtrv-ip-card and rtrv-ip-lnk | Possible minor confusion as documentation does not match real range. |
| 167516 | | 3 | Resolved | Defer | Incorrect range listed for "mrnset" parameter for chg-map command | Possible confusion as the documentation gives an incorrect range. |
| 167517 | | 3 | Resolved | Defer | Incorrect Max Character Parameter Value for "ttn" for chg-gtt command | Possible confusion as the documentation gives incorrect range. |
| 167534 | | 3 | Resolved | Defer | E5-OAM boots with ath_vxw.c during HIPR2 testing. | IF BERT is executed on an unstable bus the OAM may boot. It will self recover. |
| 167554 | | 3 | Resolved | Defer | HIPR2: hipr2u_mgr.c Line 2210 seen during tst-imtLextbert command issued after init standby OAM. | BERT procedures should not be initiated when the system is not stable (i.e.: before allowing the E5-OAM to stabilize) Since application cards would have already been disconnected from the bus when the event occurs, the impact on the system is essentially negligible. Re-attempt the BERT when cards are not booting and the procedure will likely succeed without any other side effects. |
| 167557 | | 3 | Resolved | Defer | scm_bkgd.c Line 3065 Class 01b3 Severity 1 | The user would only see this ATH once, and there is a variable to ensure it is not re-displayed until the next OAM boot. No other impact on the system. |
| 167560 | | 3 | Resolved | Defer | Card 1113 Module iplk_com.c Line 185 Class 01c3 Severity 1 | no system impact, when the dcb initialization completes no more troubles. |
| 167593 | | 3 | Resolved | Defer | Module e5imt_itx.c Line 402 Class 0001 Severity 1 | Card should not be caused to get on or off the IMT during a test. No adverse effect to the system has been observed. |
| 167594 | Y | 3 | Resolved | Defer | MTT E4758 is missing in the customer documentation and description of MTT 2014 is incorrect | Customer may need to call TAC to determine why the command was rejected. |
| 167607 | | 3 | Resolved | Defer | Command Response Timeout, freeing up Scroll Area when command entered sometimes | A serial terminal is not usable for a while (up to 1 hour). It only follows an init of the OAM and on very rare occasions. Reboot the active card from another terminal. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|---|
| 167642 | | 3 | Resolved | Defer | Location range incorrect for disp-bip, rtrv-bip and tst-bip | No impact as it requires TAC to enter BIP. |
| 167665 | | 3 | Resolved | Defer | HIPR2:LIMs denied STPLAN service during act-flash command on HIPR2 | In a heavily loaded (lots of SLAN traffic system) activating the flash cause a momentary loss of SLAN capacity. It is recommended to only put new cards in the system in times of low activity. |
| 167666 | Y | 3 | Resolved | Defer | tst-t1 command do not provide sufficient information about command results. | Customer may not know how to get results from tst-t1 command. |
| 167679 | Y | 3 | Resolved | Defer | Received mrpg_utl.c sev 1 alarm when deleting the SS7 configuration using SEAS | No system impact. Measurements are being processed (collected / reported) on a link that has been removed, and the Measurements subsystem still attempts to process with this deleted entry. |
| 167760 | | 3 | Resolved | Defer | Second SOIP Connection Automatically Activated (Telcordia - ST) | The SOIP will connect before the terminal is allowed. |
| 167765 | | 3 | Resolved | Defer | REPT-IMT-LVL1 shows incorrect number of MUX cards when a MUX card is unseated | In such a scenario (When MUX card is unseated), number of MUX cards will be reported incorrectly by rept-int-lvl1 command. Actual number of MUX cards can be counted from the output of rept-stat-mux command. |
| 167776 | | 3 | Resolved | Defer | SSP report issue for ITUN PC's form MCP and OAMHC | The MCP and OAMHC SSP reports will differ for the ITUN PC's. The data on the meas table will be same but the for the ITUN PC's representation will be different in the reports. |
| 167815 | | 3 | Resolved | Defer | Location range incorrect for rept-stat-db | Possible confusion as to the correct parameter values for this command. |
| 167833 | Y | 3 | Resolved | Defer | No replacement procedure dedicated to E5ENET card type in the maintenance customer documentation. | Documentation does not provide clear guidance for replacement procedure of E5ENET cards. |
| 167836 | | 3 | Resolved | Defer | HIPR2: HIPR2 card silently double booted after init-mux during gpl flash process | If the card double boots after the init-mux command the side effects are 1) the bus may take 10-15 seconds longer to come IS-NR, and 2) if the card was being booted / init'ed to run a new trial flash load, the card will have to be reflashed since the double boot would have lost the trial image. |
| 167845 | | 3 | Resolved | Defer | dblm_mgr.c Line 623 Class 01c2 Severity 1 & ecam_utl.c Line 536 & 538 Class 01d0 Severity 1 | None, card DB loads correctly. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|--|
| 167869 | Y | 3 | Resolved | Defer | DB admin manual for GTT for ANSI-ITU-China SCCP Conversion Feature needs some additional information. | Customer was not aware that this feature could affect the network indicator bit in CDPA / CGPA fields in an incoming MSU originated from ITU-I(S)/ITU-N(S) domain to ITU-N(S)/ITU-I(S) network domain. |
| 167875 | | 3 | Resolved | Defer | MCPM card generated Module meau.c severity 1 during upgrade | There is a potential for scheduled UI and SEAS reports to be aborted due the failure to read data from the MCP. The reports can be generated manually if needed. This is a timing issue with a very small window of opportunity; thus the number of reports affected would be minimal. |
| 167890 | | 3 | Resolved | Defer | DMS Error during incremental upgrade from 42-63.30 to 42-63.33: dms_utl.c Line 2131 DMS Error | A Sev 1 trouble in generated when the Upgrade command is re-entered during phase 3 on a system under going an incremental upgrade but has never gone through a previous full-DB upgrade. This would only occur if a newly installed system were to upgrade to a Maintenance Build. There is no impact on the execution of the incremental upgrade other then the displaying of this trouble. |
| 167893 | | 3 | Resolved | Defer | rept-imt-lvl2 command: The range of cards not correct | minimal as this is debug command. There are other ways to see the cards on the IMT. |
| 167896 | | 3 | Resolved | Defer | System comes up in simplex mode when both E5-OAMs are present | The customer could enter a command that is allowed before the standby MASP finishes initializing. The command would be allowed then once the standby becomes available a repair would be required. |
| 167899 | | 3 | Resolved | Defer | Numbering Plan values (NP/NPV) in GTTSEL/SRVSEL tables do not match ITU spec | Per the Q.713 ITU spec, NP=private should equal a NP value of 14. The eagle is defining private as a value of 8. To work around this enter the NPV explicitly as 14 instead of "NP=private". |
| 167904 | | 3 | Resolved | Defer | E5-ENET failed to detect loss of connection to the IMT | The card would show as isolated from the OAM. When reseated the card would recover. |
| 167917 | | 3 | Resolved | Defer | HIPR2 testing: Module scm_mux.c Line 1570 Class 01c3 Trouble when bus B is coming up. | The trouble indicates that a HIPR2 card reported an out-of-range value for the IMT bus utilization. The problem self-corrects in a short time. |
| 167990 | | 3 | Resolved | Defer | rept-meas command rejected for FTA reports when oamhameas=off | The customer would be unable to generate hourly or daily reports that would normally go to the FTA. However, the scenario with E5OAM Integrated Meas feature on but oamhameas=off is considered a transition state, so the window during which this problem could occur should be minimal. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------------|-------------|---|---|
| 167994 | | 3 | Resolved | Defer | Minor changes to displayed information and UIM for prepaid IDP query relay | UIMs use enabled and disabled where the options are on and off. |
| 168022 | | 3 | Resolved | Defer | Missing output terminal messages... Missing/Partial echo messages (E5-OAM and Legacy OAM) | Loss of some output on terminal. |
| 168027 | Y | 3 | Resolved | Defer | In certain cases EAGLE outputs UAM 449 when it should output UAM451 | The customer may think the SCCP cards will resynch on their own and will not know reload is required. However, condition can be determined as no updates will be happening on the SCCP cards. Also the oldest level on the EPAP can be checked, and if greater than the SCCP cards then the reload is required. |
| 168069 | | 3 | Resolved | Defer | HIPR2: Master HIPR2 card will not align without clock source on B bus | Not likely to happen as requires reboot of HIPR2 with clock cable disconnected and chanign fak for HIPR2. Fixing the clock cable corrects the issue. |
| 168075 | | 3 | Resolved | Defer | ITU congestion discard thresholds D1/D2 should be same as D3 in MTP2/ATM/IPGW P_BASE meas reports | RBASE report congestion thresholds are inaccurate for some ITU link types. The customer can use reported value for discard level 3 for D1 and D2. |
| 168130 | Y | 3 | Resolved | Defer | RCT Timezone register (RTC_ZONE, stored at address 0x0E) maintained by VxWorks code is not getting updated on E5MASP card | RCT Timezone value is not getting persistent over init-sys. This problem is specific to the E5MASP cards only. Customer can rested the time zone after booting the E5-OAM. |
| 168138 | | 3 | Resolved | Defer | chg-lnpopts Incorrect MTT error 3524 | Some minor confusion since the features are mutually exclusive with LNP. |
| 168138 | | 3 | Resolved | Defer | chg-lnpopts Incorrect MTT error 3524 | Some minor confusion since the features are mutually exclusive with LNP. |
| 168140 | | 3 | Resolved | Defer | E5OAM Int Meas: chg-meas:collect=on rejected if 15 min meas is on | Minor inconvenience. Collection can be turned on by temporarily turning off 15 minute measurements. |
| 168201 | Y | 3 | Pending_Review | Monitor | The rept-stat-alm:display=inhb showing incorrect count of permanent inhibited alarms | Customer confusion as to what alarms are really inhibited. |
| 168244 | | 3 | Resolved | Defer | HIPR2: imte_lvl.c trouble when issuing rept-imt-lvl2 report with sloc/eloc parameters | Miminal as not part of normal operation of EAGLE. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|--|
| 168299 | | 3 | Resolved | Defer | Check for IP route and PVN/FCNA/FCNB conflicts does not work for IP route host address | Due to conflicting IP route entry with PVN/FCNA/FCNB, monitoring session with IMF may get disconnected. As these addresses are used internally between IAS and Eagle side, customers need to be aware of the limitations of auto verification during provisioning. The Conflict between PVN/ FCN and IP link/ route can be resolved through chg-netopts and chg-ip-lnk/ dlt-ip-rte commands. |
| 168301 | | 3 | Resolved | Defer | FCNA/FCNB conflict checks against IP links and routes do not cover entire address space | Due to conflicting IP addresses of STC card and IP links, monitoring session with IMF may get disconnected. As these addresses are used internally between IAS and Eagle side, customers need to be aware of the limitations of auto verification during provisioning. The Conflict between PVN/ FCN, IP link/ route or STC link can be resolved through chg-netopts and chg-ip-lnk/ dlt-ip-rte commands. |
| 168336 | | 3 | Resolved | Defer | MCP Meas:15-min on demand report generated during 2nd and 4th quarter hour LAST period is not correct. | When 15 minute meas feature is on, on demand reports for the xx15 and xx45 periods cannot be generated. The reports are generated correctly when scheduled. Problem is limited to E5OAM Integrated Measurements; MCP is not impacted. |
| 168395 | | 3 | Resolved | Defer | rept-imt-lvl1: IMT level 1 High Speed stats not shown if there are no Eagle cards on a shelf | The High Speed stats can be retrieved using the rept-imt-info with the mux command. |
| 168446 | | 3 | Resolved | Defer | Integrated Meas: UI reports trying to generate in 15 min increments when 15mincollect=on. | The time required to output UI reports every 15 minutes could exceed the capacity of the UI to process the reports. Manually disable scheduled UI reports with chg-meas command, then use Measurement reports generated to FTP server. |
| 168447 | | 3 | Resolved | Defer | lb_mgr.c Line 3337 Class 01d8 Severity 1 from SCCP cards during upgrade | There is no adverse system impact. |
| 168492 | | 3 | Resolved | Defer | EMS is unable to update inventory card Graphics due to the removal of the type parameter in the rtrv-bip command | Customer doc will not match current implementation. |
| 168503 | | 3 | Resolved | Defer | HIPR2: md_hipr2.c Line 379 Class 01cf obit & hw_hipr2_com Line 302 Class 01cf Severity 1 | When inserting HIPR2 on bus card upstream could boot. The IMT is already down at this point so the only affect is it take up to 10 seconds longer to recover. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|---|
| 168529 | | 3 | Resolved | Defer | TST-IMT command is inconsistent across releases & requires multiple interruptions of the bus. | The new test does require that the bus be taken down twice instead of once as with the prior test. The old test is not longer the default. A new parameter for type was added. |
| 168531 | | 3 | Resolved | Defer | restart.c Line 1099 Class 0001 | Not likley to occur in the feild as the system had one IMT down for lab testing. Card does self recover. |
| 168549 | | 3 | Resolved | Defer | MCP DB data transfer enhancement | Lengthy delay in the time required to load an MCP. No impact to data reliability |
| 168566 | | 3 | Resolved | Defer | Module trp.c Line 588 Class 01c3 Severity 1 seen on STC card during normal operation | No observable system impact due to this issue. It is possible that some network element was generating empty broadcast packets occasionally. |
| 168576 | | 3 | Resolved | Defer | IPSG Large MSU Controlled Re-route, minor traffic loss at 80% | Doing Change over and Change back under high traffic with large MSUs may result in some traffic loss. |
| 168579 | | 3 | Resolved | No-Fix | E5-STC cards OBIT during upgrade from 40.1 to 42.0 | The card will not load until the system stablizes. Until the number of network-traffic-producing UAMs is reduced the upgrade can not process or be rolled back. The various health checks and Procudure 1, Steps 16 -17 attempt to identify this condition prior to the start of the upgrade. The system needs to be cleaned up and the bouncing devices need to be stablized. |
| 168592 | | 3 | Resolved | Defer | Pending items for the Reference counts in GTT_MAP and GTT_MRN tables | Customer is not protected from deleting used entries. |
| 168616 | Y | 3 | Resolved | Defer | DB backup is always downloaded to the same E5IPSM without checking if connection to remote server is UP | DB backup is always downloaded to the same E5IPSM without checking if connection to remote server is UP. Hence remote backup transfer via FTP session will fail if connection to the remote server is down on just one E5IPSM. |
| 168652 | | 3 | Resolved | Defer | IPSG card GEI interfaces would not come up | Appears to be switch problem external to EAGLE. Keeping PR open until this can be proved. |
| 168684 | | 3 | Resolved | Defer | R42:FTRA4.3 - Retrieved CSV file incorrectly displays an extra empty line after every entry for rtrv-mtc-measopts command. | This would put extra line in CSV file. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|---|
| 168732 | Y | 3 | Resolved | Defer | When deleting a E5-E1/T1 (T1) port, the port stays in-service at the far-end until card is boots | When a T1 port is deleted (dlt-t1) on an E5-E1T1 card the port stays in-service to the far-end until the card is booted. This makes it confusing to the personnel on the far-end as traffic will not work on this link. |
| 168766 | | 3 | Resolved | Defer | rept-imt-info has duplicate fields in report | No operational impact. Gives bad impression having duplicate entries. |
| 168784 | | 3 | Resolved | Defer | IPGWx: Only 1 AS goes active when a mismatched RC received and assoc is prov in multiple AS'es with no RC | If the customer does not provision the routing context or no routing context to match the far end not all associations will go to in-service state. Provisioning to match far end will address issue. |
| 168809 | | 3 | Resolved | Defer | CSVGENX is displaying incorrectly for rtrv-gttset | The CSV for rtrv-gttset on Unix won't display the actual value of OVERLAPD field. It would always display "No" |
| 168821 | | 3 | Resolved | Defer | E3737 Cmd Rej: Socket connection parameters must be unique," not in the CER Manual | Customer will not know recovery when getting the reject message. |
| 168827 | | 3 | Resolved | Defer | the standby OAM is receiving HIPR maintenance blocks | No system impact. Standby will discard any Maintenance blocks that it receives. |
| 168856 | | 3 | Resolved | Defer | During upgrade (41.0.2 to 42.0) all cards in group failed to flash after one card in group obit'd | If one card does not return to service after the card is inhibited, the card is removed from the upgrade list (works as designed). The code should upgrade all of the other cards in the group and then terminate the upgrade. Instead if the group of cards contains cards that are running different flash. The code only completes flashing on the card running one of the flash. The code should finish the whole set of cards before terminating the upgrade. The workaround is to manually flash the cards the upgrade did not automatically flash. |
| 168858 | | 3 | Resolved | Defer | During upgrade (41.0.2 to 42.0): Module ecam_utl.c reported on Standby TDM | ATHs will occur but these can be safely ignored. |
| 168890 | | 3 | Resolved | Defer | os_utl.c troubles pouring out after chg-db:action=backup command | The backup is not impacted. however if there is another issue it may be masked by the troubles being output for this. |
| 168894 | | 3 | Resolved | Defer | tk_s_md.c pouring out after chg-db:action=backup | The customer may have to boot the OAM to clear issue. |
| 168913 | | 3 | Resolved | Defer | The Eagle has an invalid command of RTRV-PE in its F10 list that should be removed | No system impact and command will not execute. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------------|-------------|--|--|
| 168923 | | 3 | Resolved | No-Fix | adl_load.c obit during full upgrade from 41.2.0-62.69.65 to R42.0.0-64.36.0 | Card will reboot and eventually recover. |
| 168956 | | 3 | Resolved | Defer | CDT Deficiencies regarding rept-imt-lvl1 | Customer will not fully understand stats. As these stats are for Tekelec use this is of little impact. |
| 168958 | | 3 | Resolved | Defer | CDT Deficiencies regarding rept-imt-info | Customer will not fully understand stats. As these stats are for Tekelec use this is of little impact. |
| 168961 | | 3 | Resolved | Defer | smrg_util.c Sev 1 during daily UI reporting | Sev 1 ATH is only impact. No adverse impact to measurements functionality or reliability |
| 168966 | Y | 3 | Resolved | Defer | Command Manual under command rtrv-data-rtdb, it states the entity must be between 5-15 hex digits. | Wrong statement in the documentation regarding entity field may lead the customer to be confused with the use of rtrv-data-rtdb command. |
| 168987 | | 3 | Resolved | No-Fix | 42.0 Upgrade Procedure needs to be updated for 40.4 upgrade path with remote upgrade | This PR only applies to upgrades performed via remote downloads. If the system is running on GPSMs, the workaround is to provide them with an upgrade MO disk. |
| 169046 | | 3 | Resolved | Defer | DB update allowed when in phase 0 of upgrade | This is not an issue if upgrade procedure is correctly followed. If it does occur then Database difference will have to be corrected before the upgrade can continue. |
| 169084 | | 3 | Resolved | No-Fix | Route for cluster point code can be given on A/E Linkset. | This is a legacy issue that has little system impact but is technically a valid issue. |
| 169096 | | 3 | Resolved | No-Fix | Module vcpntry.c Line 176 Class 0001 Sev 1 on DSM after init-sys | Not service affecting |
| 169114 | | 3 | Pending_Review | Monitor | DSM B port connections go unavailable when unplugging ETH2 (DSM A) connection on EPAP | Possible cable faults could affect more than the card using that cable getting updates. The system will alarm if the DB on the DSMs are at different levels. This will allow for troubleshooting to correct the issue. |
| 169146 | | 3 | Resolved | No-Fix | rept-stat-gpl does not display approved and trial version numbers | Until the GPL state is established, the Approved and Trial versions are not displayed on the rept-stat-gpl command. This is expected behavior. |
| 169173 | | 3 | Resolved | Defer | DDB Inconsistent on far-end E5-ATM card after congestion duration run | The DDB inconsistency does not affect traffic. However it does casue a DDB alarm. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|---|
| 169220 | | 3 | Resolved | Defer | meas_dth.c seen during phase 0 of incremental upgrade from 63.35 to 63.38. | No adverse impact to system operation or reliability since standby OAM was begin booted for upgrade anyway. |
| 169221 | | 3 | Resolved | Defer | mrs_mgr.cpp Sev 1 seen during incremental upgrade from 63.35 to 63.38. | No adverse impact to system operation or reliability. |
| 169301 | Y | 3 | Resolved | Defer | Missing description that when CNVCGDA/I/N are enabled =no MSU will be discarded | The customer will not relize the MSU maybe discarded when the option is set this way. |
| 169316 | | 3 | Resolved | Defer | IAR SPORT - DN with no GRN does not give expected UIM | The customer may not realize the GRN is missing. The message will be processed based on this without producing a UIM. |
| 169360 | | 3 | Resolved | Defer | No check for device support of Ethernet before call to iplk_max_ip_links_per_card | No system impact, trouble is displayed when an attempt is made to update IP link LEDs on a card that doesn't support IP links. |
| 169362 | | 3 | Resolved | Defer | Need to update UIMs with the OPC and DPC so we can contact source. | Without this data it is harder for the cusotmer to determine the source of the problem traffic. |
| 169405 | | 3 | Resolved | Defer | CHG-NETOPTS and CHG-EISOPTS not detecting conflict with IPSM IP Link | Properly configure EIS and IPSM networks so there are no IP address conflicts. |
| 169440 | | 3 | Resolved | Defer | UAM 583 with "No error" reported for IPSPG cards and toggling with other monitoring alarms | <p>During IMF fail over scenario, following issues will be observed for Fast Copy enabled IPSPG card.</p> <ul style="list-style-type: none"> - Monitoring alarms keep on toggling on OAM for few minutes and after that alarm toggling stops. - UAM 583 is displayed with wrong reason code (No error). - No impact on the EMP session establishment was observed with the new IMF. <p>i.e. after fail over new IMF was successfully monitoring the links on the IPSPG card.</p> |
| 169476 | | 3 | Resolved | Defer | Standby E5OAM did not return to IS-NR after database maintenance | The E5-OAM comes up on an unusable state as it is unable to load its GPL (OAMHC). The problem appears to have been due to a timing problem when the SATA drives was not ready at the very moment that the code looked for it. Perform workaround:Boot the card, either via init-card:loc=<location> or by re-seating it. The drive will invariably be detected the second time the card boots. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|---|
| 169477 | | 3 | Resolved | Defer | Standby E5 MASP boots with ath_vxw_mgr Obit after Format-Disk Completes | Since it's the Standby that booted and the card came back ok, there is no system impact. |
| 169478 | | 3 | Resolved | Defer | Standby E5 MASP Boots with clc_mcap.c obit after COPY-DISK | MASP will boot again. The card was already booting due to PR 169477 when this additional obit was shown. The card took about a minute longer to get back IS-NR due to this PR. |
| 169496 | | 3 | Resolved | Defer | rept-stat-xxxx commands may display incorrect Fast Copy information after OAM switchover | <p>If FCMODE is updated and an OAM switchover is performed, then rept-stat-mon/rept-stat-card commands will display incorrect Fast Copy related information based on older FCMODE value.</p> <p>No impact on the monitoring of cards as it will be performed correctly (based on the value provisioned in DB).</p> <p>rtrv-eisopts will display the correct FCMODE value. If workaround is required then the Active OAM will need to be re-initialized. After that the Fast Copy DCB will get updated from provisioned FCMODE and correct Fast Copy information will be displayed</p> |
| 169714 | Y | 3 | Resolved | Defer | DURASNEST timer reports 1800 seconds for associations that are up and running normally. | SCTP Measurements are reporting incorrect DURASNET value for some associations after different association is deleted. |
| 169720 | Y | 3 | Resolved | Defer | login via IPSM card to the Eagle is failing. | The telnet session that had this issue can not be reused. All other sessions are usable. The card can be booted to clear the condition. |
| 169901 | Y | 3 | Resolved | Defer | TRP flooding from IMF leads STC/IPSG cards to reboot | FC capable and STC cards reboot and do not come up into service until they are either isolated from network flooding the cards. Or the source of the flooding is corrected. |
| 169902 | Y | 3 | Resolved | Defer | IARNOTAP is used in rept-stat-sccp to compute the failure ratio. | major/critical alarms raised due to high GTT failures |
| 169910 | | 3 | Resolved | Defer | tpim_io.c Line 367 Class 01c3 OBIT while running init-standby script | After being initialized the standby OAM may boot and extra time before coming into service. |
| 169954 | | 3 | Resolved | Defer | gpla.c and gpla_oamhc.c Sev 1s during upgrade from 41.2.0-62.69.65 to 42.0.0-63.38.12 | Upgrade continues without issue. |

Table RN-12. EAGLE 5 42.0 Known PRs (09/02/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|-----------|-------------|---|--|
| 169957 | | 3 | Resolved | Defer | DIFF CONTENTS and DB DIFF after enabling 15 minute measurements following upgrade from 41.2.0-62.69.65 to 42.0.0-63.38.12 | The problem is avoided by not booting the OAM within 30 Minutes or changing the 15 minute measurement option. If this does occur a repair will correct the standby database. |
| 169959 | | 3 | Resolved | Defer | ath_vxw.c Line 3060 Class 0001 Obit during incremental upgrade 63.38.0 to 63.38.12 | This occurs when a card is inhibited while it is in the process of booting. There is no other impact than the obit produced. |
| 170098 | Y | 3 | Resolved | Defer | update required for definition of counter GTTPERFD in customer documentation | Definition of this counter is confusing when some feature like ANSI/ITU SCCP conversion is activated. That is because a single MSU may be counted more than once. |
| 170105 | Y | 3 | Resolved | Defer | ATH upg_mgr.c reported by MASP 1113 during incremental upgrade from 63.38.0 to 63.38.12 | None. The upgrade continues without issue. |
| 170122 | | 3 | Submitted | active | IPSG FastCopy Port A does not work when IPSG cards are used in a MLS linkset with SPC. | Customer will have to connect up both Fast Copy ports to get the A port to work. |
| 192535 | | 3 | Resolved | Defer | EPAP on T1200 with E5-SM4G support of different speed not in Admin Manual | The Customer may have the EPAP and switches set slower than the E5-SM4G cards support. With the alarming in 42.0, the E5-SM4G cards may put out alarms as the conuguration between the switches, EPAP, and E5-SM4G cards do not match. |
| 192688 | Y | 3 | Submitted | active | Module iprh.c Line 2788 due to zero length message | This is a result of zero length messages on IPSM cards simply being dropped. There is no negative system impact. |
| 192986 | Y | 3 | Resolved | Defer | act-file-trns command specifies wrong "loc" parameter in command usage example | Wrong information in example in the customer documentation. |

Table RN-13. EAGLE EMS 42.0 Known PRs (01/28/11)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|-------------|-------------|--|---|
| 169775 | | 2 | ReadyToTest | Active | backup.4mm script does not work with LT-04 tape drive | |
| 124636 | Y | 3 | Resolved | Defer | False alarm of password in Resync - AR 1395978 | False alarm reported for password resynch with Eagle Smart Agent. Issue is not supported by Harris. Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 128487 | | 3 | Resolved | Defer | EMS-Error During Inventory Run | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 129691 | | 3 | Resolved | Defer | EMS - Invalid card-loc allowed in Maintenance through FMS | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 129698 | | 3 | Resolved | Defer | EMS: Misleading error in CMI | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 129942 | | 3 | Resolved | Defer | EMS - Time not specified in the logs | Legacy Harris Smart Agent Issue. With R41.0 additional user and system logs are available thru the CMI to help trace activity. |
| 130187 | | 3 | Resolved | Defer | Memory leak in CMI 1.7 (HSA 6.9) | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 130394 | | 3 | Resolved | Defer | EMS: ARI script execution from cron failed. | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 130633 | | 3 | Resolved | Defer | EMS - Autologout not implemented while switching between CMI pages | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 130797 | | 3 | Resolved | Defer | EMS - Script execution successful with CLLI mismatch | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 130798 | | 3 | Resolved | Defer | EMS - Play Button on Run Script page does not work at times | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 130855 | | 3 | Resolved | Defer | EMS - Manual creation of destination directory for archival of reports | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 130951 | | 3 | Resolved | Defer | EMS - Incorrect Graphical Display on deletion from DB | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131225 | | 3 | Resolved | Defer | EMS - CMI Send Cmd/Script fails if Eagle takes long time to display output | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |

Table RN-13. EAGLE EMS 42.0 Known PRs (01/28/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|--|
| 131233 | | 3 | Resolved | Defer | EMS - Eagle terminal not accessible through Tarantella AR 1445294 | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131256 | | 3 | Resolved | Defer | EMS - Incorrect graphical display after physical card replacement | The results directory folder needs to be manually cleared if the card inventory is changed. Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131486 | | 3 | Resolved | Defer | EMS: Platform Measurement reports. | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131487 | | 3 | Resolved | Defer | EMS: Help link not working. | None. |
| 131616 | | 3 | Resolved | Defer | EMS : Incorrect info in CMI 'view logs'. | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131618 | | 3 | Resolved | Defer | EMS : Incorrect LIM port info on 'view logs' page in CMI. | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131621 | | 3 | Resolved | Defer | EMS: Missing data in 'BoardIDPromReport' in CMI. | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131627 | | 3 | Resolved | Defer | EMS - CMI Script fails on continuous run | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131663 | | 3 | Resolved | Defer | EMS - Wrong path in document for "write_results" function AR 1445298 | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131760 | | 3 | Resolved | Defer | EMS - Incorrect Severity for HSA generated alarm | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131935 | | 3 | Resolved | Defer | EMS - Eagle CLLI not available for CMI login | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131988 | | 3 | Resolved | Defer | EMS - DBInsert alarm does not clear after db comes up | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 131995 | | 3 | Resolved | Defer | EMS - No alarms for Auto Inventory failure | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 132938 | Y | 3 | Resolved | Defer | Measurement HSA loader needs to convert blank fields to null before insertion | Blank entries are causing invalid data to be inserted into the measurements database and corrupts the utilization reports. Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |

Table RN-13. EAGLE EMS 42.0 Known PRs (01/28/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|---|--|
| 134374 | | 3 | Resolved | Defer | installation Packaging- Tekelec EMS-set executable permissions bit in Measurements Platform HSA | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 134402 | | 3 | Resolved | Defer | EMS - No indication to user on click of Play button regarding stopped port | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 134846 | | 3 | Resolved | Defer | EMS - No entry in the EMS_DEVICE_MATE table for mated Eagle pair | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 135720 | | 3 | Resolved | Defer | Change "rack" references to "frame" in EMS | None - not an operational defect |
| 136240 | | 3 | Resolved | Defer | EMS - CMI Hangs During Command Processing | When the user attempts a command then CMI realizes that the connection is missing until the command times out. |
| 137533 | | 3 | Resolved | Defer | EMS : Incorrect OAM measurement data in Db. | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 137534 | | 3 | Resolved | Defer | EMS : OAM .meas data not being inserted to Db. | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 137535 | | 3 | Resolved | Defer | EMS : Multiple entries for report parameters. | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 137890 | | 3 | Resolved | Defer | EMS - Unable to run command for values xy09,ab10 | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 137973 | | 3 | Resolved | Defer | EMS - Display message not updated on Schedule Cron Page | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 138162 | | 3 | Resolved | Defer | EMS : Incorrect and duplicated inventory data in DB. | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 138493 | | 3 | Resolved | Defer | EMS - Coconut prompt password three times | Agent is LA and customer has the implimentation since it is their code base. |
| 139746 | | 3 | Resolved | Defer | EMS : Hourly NP reports(.csv) not getting inserted to the Db. | Legacy PR - works as currently implemented. Tekelec wants to investigate. |
| 139969 | | 3 | Resolved | Defer | EMS : Corba xml result file | Legacy PR - works as currently implemented. Tekelec wants to investigate. |

Table RN-13. EAGLE EMS 42.0 Known PRs (01/28/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|--|
| 139970 | | 3 | Resolved | Defer | EMS: Corba option returns exception. | Legacy PR - works as currently implemented. Tekelec wants to investigate. |
| 140003 | | 3 | Resolved | Defer | EMS - Invalid choice during package installation | Legacy PR - works as currently implemented. Tekelec wants to investigate. |
| 140067 | | 3 | Resolved | Defer | EAGLE EMS: Core Image Configuration Control/Management | No direct customer impact |
| 140315 | | 3 | Resolved | Defer | EMS-Unable to schedule Script in CMI | No impact. The file permissions will be corrected during installation/upgrade by Tekelec personnel. |
| 152420 | | 3 | Resolved | Defer | EMS - CMI hangs when IPSM card is inhibited | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 152905 | | 3 | Resolved | Defer | EMS: CMI hangs on abrupt script stop. | Legacy Harris Smart Agent (SMA) PR. No immediate impact to EMS users. |
| 153130 | | 3 | Resolved | Defer | EMS : Long script execution. | Low. The script works the results are just dropped off. The user can run the script in the background if desired but the display is chopped off. |
| 153562 | | 3 | Resolved | Defer | CMI Command Script Function List Needed | Document will be delivered in a future release. |
| 159604 | | 3 | Resolved | Defer | Netboss Reporter Reports Field Errors | Utilization reports for IP links can return an incorrect utilization value. |
| 159874 | | 3 | Resolved | Defer | Netboss Processes Template File Update | None. This is resolved by PS engineers in a new installation. |
| 160217 | | 3 | Resolved | Defer | EMS CMI Search command history does not search for command as expected | User must perform additional steps to force the search command history list to search for a selected historically sent search parameter. |
| 161640 | | 3 | Resolved | Defer | EMS Golden Image - Debugfiles are not cleaned/moved | The debug files, if enabled, are not removed by the cleanup scripts. This can lead to the possibility of filling of the disk space. |
| 161960 | | 3 | Resolved | No-Fix | Permissions - cm_logs_management.php unexecutable | Cron logs may not be processed for use by customer |
| 162772 | | 3 | Resolved | Defer | EMS CMI Cron Logs do not show Results | No information available in this log file. |

Table RN-13. EAGLE EMS 42.0 Known PRs (01/28/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|---|
| 163059 | Y | 3 | Resolved | Defer | Coconut Alarm put in Maintenance Mode Clears All EV Alarms | A clear alarm from the coconut script clears all alarms from the associated STP. This can mask outstanding alarms from the STP. |
| 164840 | | 3 | Resolved | Defer | EMS Core - cron_log_move and cron_log_delete do not clean up Measurements | Possible disk space issues if the cleanup is not enabled |
| 166776 | | 3 | Resolved | No-Fix | EMS: Problem in start/stop of SNMPNBI sga port | None. The NetBoss NBI uses a command line also so this implementation is consistent. Start and stop can be achieved thru the command line. Removed requirement 90 from FRS (FE006002) since there are too many ways to stop and start the module. The stop/start thru probuilder is unreliable and the effort for repair thru NetBoss Technologies is too expensive since this product is going EOL. With a reliable command line way to stop/start the requirement is redundant and the PR unnecessary if the requirement is removed. |
| 167773 | | 3 | Resolved | No-Fix | EMS - ARI document changes | Documentation is not up to date |
| 168055 | | 3 | Resolved | Defer | EMS : Incorrect parameter range | There may be minor issues in configuring |
| 169223 | Y | 3 | Resolved | Defer | Alarm synchronization does not support inhibited alarms | Alarms on STP are not properly represented in the EMS applications in the case of enabled Inhibited alarms. |
| 169224 | Y | 3 | Resolved | Defer | FaultComm SSH Key processing is automatically accepting new ssh keys from the IPSM cards | The new ssh key is accepted by default. No indication that the key has been changed allowing for the possibility of a security issue |

Table RN-13. EAGLE EMS 42.0 Known PRs (01/28/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------------|----------|-----|----------|-------------|--|---|---------|-------|----------|---------|----------|---------|-------------|----------|-----|----------|-------------|----------|-------------|----------|---------|----------|--------------------|----------|----------------|----------|----------|----------|----------|----------|---------|----------|---------------|----------|-----------------|----------|----------|----------|----------|----------|----------|----------|------------|----------|--------|----------|-----------|----------|--------|----------|-----------|----------|-------------|------|---------------------|----------|----------|----------|---------|--|
| 193267 | Y | 3 | Resolved | Defer | T30108 - NetBoss EMS41 CMI: Missing Eagle Commands | <p>The following commands are not available from the EMS 41 CMI and prevent the customer from creating the desired scripts from the interactive menu.</p> <p>Missing Eagle Commands (R40.1.2) in CMI EMS41 (Netboss)</p> <table> <thead> <tr> <th>Command</th> <th>Class</th> </tr> </thead> <tbody> <tr><td>chg-user</td><td>sa, uca</td></tr> <tr><td>ent-user</td><td>sa, uca</td></tr> <tr><td>act-upgrade</td><td>dbg, sec</td></tr> <tr><td>cdu</td><td>dbg, sec</td></tr> <tr><td>chg-bip-fld</td><td>dbg, sec</td></tr> <tr><td>chg-bip-rec</td><td>dbg, sec</td></tr> <tr><td>chg-tbl</td><td>dbg, cmc</td></tr> <tr><td>chg-upgrade-config</td><td>dbg, oth</td></tr> <tr><td>clr-disk-stats</td><td>dbg, sec</td></tr> <tr><td>copy-tbl</td><td>dbg, sec</td></tr> <tr><td>disp-bip</td><td>dbg, sec</td></tr> <tr><td>disp-bp</td><td>dbg, sec</td></tr> <tr><td>disp-disk-dir</td><td>dbg, sec</td></tr> <tr><td>disp-disk-stats</td><td>dbg, sec</td></tr> <tr><td>disp-lba</td><td>dbg, sec</td></tr> <tr><td>disp-mem</td><td>dbg, sec</td></tr> <tr><td>disp-tbl</td><td>dbg, sec</td></tr> <tr><td>disp-trace</td><td>dbg, sec</td></tr> <tr><td>dlt-bp</td><td>dbg, sec</td></tr> <tr><td>dlt-trace</td><td>dbg, sec</td></tr> <tr><td>ent-bp</td><td>dbg, sec</td></tr> <tr><td>ent-trace</td><td>dbg, sec</td></tr> <tr><td>healthcheck</td><td>dbg,</td></tr> <tr><td>rtrv-upgrade-config</td><td>dbg, oth</td></tr> <tr><td>send-msg</td><td>dbg, roc</td></tr> <tr><td>set-lba</td><td></td></tr> </tbody> </table> | Command | Class | chg-user | sa, uca | ent-user | sa, uca | act-upgrade | dbg, sec | cdu | dbg, sec | chg-bip-fld | dbg, sec | chg-bip-rec | dbg, sec | chg-tbl | dbg, cmc | chg-upgrade-config | dbg, oth | clr-disk-stats | dbg, sec | copy-tbl | dbg, sec | disp-bip | dbg, sec | disp-bp | dbg, sec | disp-disk-dir | dbg, sec | disp-disk-stats | dbg, sec | disp-lba | dbg, sec | disp-mem | dbg, sec | disp-tbl | dbg, sec | disp-trace | dbg, sec | dlt-bp | dbg, sec | dlt-trace | dbg, sec | ent-bp | dbg, sec | ent-trace | dbg, sec | healthcheck | dbg, | rtrv-upgrade-config | dbg, oth | send-msg | dbg, roc | set-lba | |
| Command | Class | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| chg-user | sa, uca | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| ent-user | sa, uca | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| act-upgrade | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| cdu | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| chg-bip-fld | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| chg-bip-rec | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| chg-tbl | dbg, cmc | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| chg-upgrade-config | dbg, oth | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| clr-disk-stats | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| copy-tbl | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| disp-bip | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| disp-bp | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| disp-disk-dir | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| disp-disk-stats | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| disp-lba | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| disp-mem | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| disp-tbl | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| disp-trace | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| dlt-bp | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| dlt-trace | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| ent-bp | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| ent-trace | dbg, sec | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| healthcheck | dbg, | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| rtrv-upgrade-config | dbg, oth | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| send-msg | dbg, roc | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| set-lba | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 195063 | Y | 3 | Resolved | Defer | Documentation for the builtin CMI functions is insufficient. | Customer is unable to properly utilize the CMI for the functions it was designed to provide as the documentation is insufficient to provide guidance how the functions can be utilized. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 195965 | | 3 | Resolved | Defer | EMS: DOS characters in uninstall10rec.sh and uninstallJ2SE10Rec.sh scripts | No customer impact. This only affects the uninstall process for the upgrade. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

Table RN-14. ELAP 9.0 Known PRs (08/05/11)

| PR # | CSR? | Sev | Status | Dispo- sition | Title | Customer Impact |
|--------|------|-----|----------|------------------|--|---|
| 49447 | | 3 | Resolved | Defer | Terminated session login button doesn't work in rare circumstances | If Customer is using IP forwarding, has changed the http port to something other than 80, and allows a GUI session to terminate. Attempts to re-login receive an error rather than the login screen. |
| 129734 | | 3 | Resolved | Defer | Active ELAP reboots when failover | the impact is that in the period of time while server A is rebooting, you will not be able to fail back over from B -> A. This error occurs infrequently. |
| 132527 | | 3 | Resolved | Defer | NPANXX Can Be Deleted from ELAP with TN Data | As stated in the description, if a customer deletes the default gtt entry for which TNs/NPBs exist, the lnp query will fall through to eagle gtt. |
| 164666 | | 3 | Resolved | Defer | ELAP 9.0 [PR122479]:ELAP having incorrect behavior for "User Account Idle timeout". | Idle time is not working correctly so manual check from admin is required. |
| 166078 | | 3 | Resolved | Defer | ELAP9.0_SYSTEM_TEST: localhost IP is getting set in platcfg when we remove NTP server using elapconfig on ELAP | This will not have any impact on the current working of NTP. Only platcfg menu will display localhost (127.0.0.1) IP address corresponding to a deleted NTP server. |
| 166291 | | 3 | Resolved | Defer | ELAP9.0_SYSTEM_TEST: "service network restart" makes database Unknown on ELAP. | The ACTIVE side disk is in a good state and taking updates, no service interruption to the customer. Manual intervention will be required by Tekelec support personnel to properly recover the system to a good disk state. |
| 167357 | | 3 | Resolved | Defer | ELAP9.0_SYSTEM_TEST: ELAP Admin Manual doesnot have Audit, Bulkload alarms | Customer might see an alarm that does not have an explanation in the manual. |
| 160053 | | 3 | Resolved | No-Fix | MMI port connection display has unwanted control characters and no function key capability | The customer will have full VT100 terminal in KSR mode functionality when connected thru the ELAP GUI. There will be a few extra characters in the output. |
| 166051 | | 3 | Resolved | No-Fix | ELAP9.0_SYSTEM_TEST: Different name for Default GTT in Retrieve Records and Local provisioning. | None |
| 166085 | | 3 | Resolved | No-Fix | ELAP9.0_SYSTEM_TEST: Incorrect error message is displayed when TN is specified as a series of 0s in Subscription | None |

Table RN-14. ELAP 9.0 Known PRs (08/05/11) (Continued)

| PR # | CSR? | Sev | Status | Disposition | Title | Customer Impact |
|--------|------|-----|----------|-------------|--|-----------------|
| 166152 | | 3 | Resolved | No-Fix | ELAP9.0_SYSTEM_TEST:ELAP does not show appropriate message after executing "service snmptrapd stop" from elapdev user. | none |
| 166499 | | 3 | Resolved | No-Fix | ELAP9.0_SYSTEM_TEST: : Mingled message content when snmptrapd service is stopped from elapdev or appuser. | none |