

Oracle® Communications
HP Solutions Firmware Upgrade Pack
Software Centric Release Notes
Release 2.2.10
E76846 Revision 01

June 2016

ORACLE®

Oracle Communications, HP Solutions Firmware Upgrade Pack, Release 2.2.10

Copyright ©2010, 2016 Oracle and/or its affiliates. All rights reserved.

This software and related documentation are provided under a license agreement containing restrictions on use and disclosure and are protected by intellectual property laws. Except as expressly permitted in your license agreement or allowed by law, you may not use, copy, reproduce, translate, broadcast, modify, license, transmit, distribute, exhibit, perform, publish, or display any part, in any form, or by any means. Reverse engineering, disassembly, or decompilation of this software, unless required by law for interoperability, is prohibited.

The information contained herein is subject to change without notice and is not warranted to be error-free. If you find any errors, please report them to us in writing.

If this is software or related documentation that is delivered to the U.S. Government or anyone licensing it on behalf of the U.S. Government, the following notice is applicable:

U.S. GOVERNMENT RIGHTS Programs, software, databases, and related documentation and technical data delivered to U.S. Government customers are "commercial computer software" or "commercial technical data" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, the use, duplication, disclosure, modification, and adaptation shall be subject to the restrictions and license terms set forth in the applicable Government contract, and, to the extent applicable by the terms of the Government contract, the additional rights set forth in FAR 52.227-19, Commercial Computer Software License (December 2007). Oracle America, Inc., 500 Oracle Parkway, Redwood City, CA 94065.

This software or hardware is developed for general use in a variety of information management applications. It is not developed or intended for use in any inherently dangerous applications, including applications that may create a risk of personal injury. If you use this software or hardware in dangerous applications, then you shall be responsible to take all appropriate fail-safe, backup, redundancy, and other measures to ensure its safe use. Oracle Corporation and its affiliates disclaim any liability for any damages caused by use of this software or hardware in dangerous applications.

Oracle and Java are registered trademarks of Oracle and/or its affiliates. Other names may be trademarks of their respective owners.

Intel and Intel Xeon are trademarks or registered trademarks of Intel Corporation. All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. AMD, Opteron, the AMD logo, and the AMD Opteron logo are trademarks or registered trademarks of Advanced Micro Devices. UNIX is a registered trademark of The Open Group.

This software or hardware and documentation may provide access to or information on content, products, and services from third parties. Oracle Corporation and its affiliates are not responsible for and expressly disclaim all warranties of any kind with respect to third-party content, products, and services. Oracle Corporation and its affiliates will not be responsible for any loss, costs, or damages incurred due to your access to or use of third-party content, products, or services.

Table of Contents

Table of Contents	3
1 Introduction	4
1.1 Purpose and Scope	4
1.2 Acronyms	4
1.3 Terminology	4
2 Content	6
2.1 Firmware Baselines and Exceptions	6
2.2 HP Solutions Firmware Components Upgraded.....	7
2.2.1 HP ProLiant Server Firmware Components	7
2.2.2 HP Misc Firmware Components	10
3 Upgrade Order	12
3.1 Recommended Order of Firmware Upgrades - Platform 6.5 and Below.....	12
3.2 Recommended Order of Firmware Upgrades - Platform 6.7 to 7.2.....	12
3.3 Important Rules on Simultaneous Firmware Upgrades	13
4 Compatibility	14
4.1 With Previous HP FUP Releases	14
4.2 With Oracle Application Software	14
4.3 Firmware Version Restrictions	14
5 HP SPP Baseline and Changes.....	15
6 Additional Instructions.....	16
6.1 Additional Firmware Installation and Configuration.....	16

1 Introduction

1.1 Purpose and Scope

When a customer buys their HP ProLiant hardware through Oracle we act as the OEM provider of firmware updates through the HP Solutions Firmware Upgrade Pack releases. For Software Centric Customers this is not legally possible.

This document lists the firmware versions approved for this HP Solutions Firmware Upgrade Pack release to assist customers with upgrading their HP hardware. Also, additional instructions and guidance on the firmware upgrades has been provided where possible.

1.2 Acronyms

Table 1. Acronyms

BIOS	Basic Input Output System
FC	Fiber Channel
GPS	Global Product Solutions
HP	Hewlett-Packard Development Company, L.P.
iLO	Integrated Lights-Out
IOS	Internetwork Operating System
IP	Internet Protocol
IPM	Initial Product Manufacture
ISO	ISO 9660 file system (when used in the context of this document)
MOP	Method of Procedure
MSA	Modular Smart Array
OA	Onboard Administrator
POST	Power On Self-Test
PR	Problem Report
RMS	Rack Mount Server
ROM	Read Only Memory
SAN	Storage Area Network
SAS	Serial attached SCSI
SPP	Service Pack for ProLiant
TPD	Telecom Platform Distribution
UI	User Interface

1.3 Terminology

Table 2. Terminology

Firmware	Coded instructions and data programmed directly into the circuitry of read-only memory for controlling the operation of the server or one of its devices.
BladeSystem	The HP c-Class BladeSystem which refers to the c7000 enclosure and all of its contained server and storage blades, including its management software and firmware.
Upgrade	The process of converting an HP hardware component from its current firmware release to a newer release.

Software Centric	Refers to customers who do not buy their HP hardware through Oracle (Software Only Customers).
-------------------------	--

2 Content

2.1 Firmware Baselines and Exceptions

Firmware packages in this document have a specified “Minimum Supported Version”, “Current Supported Version”, and "Maximum Supported Version". The Current Supported Version is the version currently provided by this HP FUP Release. Systems should be upgraded to at least the Minimum Supported Version where the presently-installed firmware is of an earlier version. In some cases versions newer than the Current Supported Version may be available. **Installing these newer versions is typically acceptable. However, check the "Maximum Supported Version" column for restrictions on newer firmware versions.**

2.2 HP Solutions Firmware Components Upgraded

IMPORTANT: For the versions indicated below here are guidelines for reading the table:

- **Minimum Supported FW Version** - If a component has a firmware version older than this it needs to be upgraded.
- **Current Supported FW Version** - This is the version of firmware used this HP FUP release.
- **Maximum Supported FW Version** - If a component has a firmware version newer than this it needs to be downgraded.

2.2.1 HP ProLiant Server Firmware Components

The table below lists the main firmware components relating to Oracle supported HP ProLiant Rack Mount and Blade servers.

Note: System ROM Versions are often interchangeably written with either a "yyyy.mm.dd" format or a "mm/dd/yyyy" format. For example, "05/02/2011" is equivalent to "2011.05.02".

Note: Gen9v1 servers use the Intel E5-XXXX v3 processors. Gen9v2 servers use the Intel E5-XXXX v4 processors.

Component	Minimum Supported FW Version	Current Supported FW Version	Maximum Supported FW Version
System ROM for DL360 G6	2015.08.16	2015.08.16	no maximum
System ROM for DL360 G7	2015.08.16	2015.08.16	no maximum
System ROM for DL360p Gen8 w/ TPD builds 82.29 and lower	2013.09.08	2013.09.08	2013.09.18
System ROM for DL360p Gen8 w/ TPD builds 82.30 and above	2013.09.08	2015.07.01	no maximum
System ROM for DL360 Gen9v1 and Gen9v2	2016.06.02	2016.06.02	no maximum
System ROM for DL380 G6	2015.08.16	2015.08.16	no maximum
System ROM for DL380p Gen8 w/ TPD builds 82.29 and lower	2013.09.08	2013.09.08	2013.09.18
System ROM for DL380p Gen8 w/ TPD builds 82.30 and above	2013.09.08	2015.07.01	no maximum
System ROM for DL380 Gen9v1 and Gen9v2	2016.06.02	2016.06.02	no maximum
System ROM for BL460c G6	2015.08.16	2015.08.16	no maximum
System ROM for BL460c Gen8 w/ TPD builds 82.29 and lower	2013.09.08	2013.09.08	2013.09.18
System ROM for BL460c Gen8 w/ TPD builds 82.30 and above	2013.09.08	2015.06.01	no maximum
System ROM for BL460c Gen9v1 and Gen9v2	2016.05.05	2016.05.05	no maximum
System ROM for BL620c G7	2015.08.16	2015.08.16	no maximum
Power Management Controller for BL460c G6 Servers	3.4	not included ¹	no maximum
Power Management Controller for DL360 G6 and DL380 G6 Servers	2.9	not included ¹	no maximum

¹ Power Management Controller firmware is not included in HP's SPP for ProLiant G6-G7 servers.

Component	Minimum Supported FW Version	Current Supported FW Version	Maximum Supported FW Version
Power Management Controller for DL360 G7 and BL460c G7 Servers	1.6	not included ¹	no maximum
Power Management Controller for BL620c G7 Servers	1.7	not included ¹	no maximum
Power Management Controller for all Gen8 Servers	3.0	3.3	no maximum
Power Management Controller for all Gen9 Servers	1.0.7	1.0.9	no maximum
HP NC532m Broadcom Dual Port 10GbE	6.2.25	6.2.28	no maximum
HP NC532i Broadcom Dual Port 10GbE	6.2.25	6.2.28	no maximum
HP NC382i Broadcom Dual Port 1GbE	5.2.3	5.2.3	no maximum
HP NC365T Intel Quad Port 1GbE	no minimum	not included ²	no maximum
HP NC364T Intel Quad Port 1GbE	no minimum	not included ²	no maximum
HP NC364m Intel Quad Port 1GbE	no minimum	not included ²	no maximum
HP 366M Intel Quad Port 1GbE	1.349.0	1.1200.0	no maximum
HP 331i Broadcom 4-port 1Gb	1.37	1.45	no maximum
HP 331FLR Broadcom 4-port 1Gb	1.37	1.45	no maximum
HP 331T Broadcom 4-port 1Gb	1.37	1.45	no maximum
HP 530FLB Broadcom 2-port 10Gb	7.4.22	7.13.23	no maximum
HP 530M Broadcom 2-port 10Gb	7.4.22	7.13.23	no maximum
HP NC553i Emulex 2-port 10Gb	4.6.247.5	10.7.110.31	no maximum
HP 560FLB Intel 2-port 10Gb	0x8000080b	0x80000872	no maximum
HP 560M Intel 2-port 10Gb	0x8000080b	0x8000083D	no maximum
HP 560SFP+ Intel 2-port 10Gb	0x80000811	0x80000835	no maximum
Smart Array P410i/P411 Controller for DL/BL G6 Servers	6.40	6.64	no maximum
Smart Array P220i/P420i/P420/P421	7.02	7.02	no maximum
Smart Array P244br/P246br/P440ar/P840	3.56	3.56	no maximum
HP 12Gb SAS Expander	2.09	2.09	no maximum
Direct Attached D2700	0070(B)	0150	no maximum

² The NC364m, NC364T, and NC365T NICs do not have firmware on the SPP. HP has never released updated firmware for these NICs. They do not need to be upgraded. The firmware they ship with is approved.

Component	Minimum Supported FW Version	Current Supported FW Version	Maximum Supported FW Version
D2200sb Storage Blade (internal P410i)	6.40	6.64	no maximum
D2220sb Storage Blade (internal P420i)	7.02	7.02	no maximum
QLogic FC Host Adapter for BL460c	2010.05.19	2015.02.01	no maximum
iLO2 for all G5/G6 DL/ML/BL Servers w/ TPD 4.x and greater	2.29	2.29	no maximum
iLO3 for all G7 DL/ML/BL Servers	1.87	1.87	no maximum
iLO4 for all Gen8/Gen9 DL/BL Servers	2.40	2.40	no maximum
SAS Storage Disks (Multiple Part Numbers included)	Various	Various	no maximum

2.2.2 HP Misc Firmware Components

The table below lists various HP and non-HP firmware components.

Component	Minimum Supported FW Version	Current Approved FW Version	Maximum Supported FW Version
OA (Use with PM&C version 5.7 or greater)	4.50	4.50	4.50
OA (Use with PM&C versions 4.x to 5.5)	3.71	3.71	3.71
OA (Use with PM&C versions 2.x to 3.x)	3.31	3.31	3.31
1Gb Ethernet Pass-Thru Module	3.0.3	3.0.3	no maximum
MSA2012fc Disk Controller	J200P50-02	J201R09	no maximum
P2000 G3 MSA Disk Controller	TS201P004	TS201P007	no maximum
P2000 MSA USB Driver (Windows 32bit)	1.0.0.5	1.0.2.8	no maximum
P2000 MSA USB Driver (Windows 64bit)	1.0.2.8	1.0.2.8	no maximum
Cascaded D2700	0070(B)	0147	no maximum
Brocade SAN Switch	6.2.2b	6.2.2b	no maximum
Cisco 4948E-F Switch IOS	12.2(54)WO	12.2(54)WO	12.2(54)WO
Cisco 4948E-F Switch PROM	12.2(44r)SG9	12.2(44r)SG9	no maximum
Cisco 4948E Switch IOS	12.2(54)XO	12.2(54)XO	12.2(54)XO
Cisco 4948E Switch PROM	12.2(44r)SG8	12.2(44r)SG8	no maximum
Cisco 4948 Switch IOS	12.2(53)SG2	12.2(53)SG2	12.2(53)SG2
Cisco 4948 Switch PROM	12.2(31r)SGA1	12.2(31r)SGA1	no maximum
Cisco 3020 Switch IOS (For SwitchConfig Systems Only)	12.2(50)SE3	12.2(50)SE3	12.2(50)SE3
Cisco 3020 Switch IOS (For NetConfig Systems Only)	12.2(58)SE1 ³	12.2(58)SE1 ³	12.2(58)SE1 ³
HP 6120XG Switch	Z.14.51	Z.14.51	Z.14.51

³ This firmware version requires that OA firmware version 3.70 or greater is already installed before a 3020 upgrade.

Component	Minimum Supported FW Version	Current Approved FW Version	Maximum Supported FW Version
HP 6125G Switch	5.20.99, Release 2105	5.20.99, Release 2105	5.20.99, Release 2105
HP 6125XLG Switch	7.1.045, Release 2403	7.1.045, Release 2403	7.1.045, Release 2403
HP 5900 Switch	5900_5920_CMW710_F24 27.ipe ⁴	5900_5920_CMW710_F24 27.ipe ⁴	5900_5920_CMW710_F24 27.ipe ⁴

⁴ This firmware file can only be obtained by opening a HP Support case and specifically requesting it.

3 Upgrade Order

3.1 Recommended Order of Firmware Upgrades - Platform 6.5 and Below

The following is the recommended order of firmware upgrades to reduce possible issues during the process of upgrading a system's firmware.

1. 4948, 4948E, and 4948E-F switches.
2. Onboard Administrator (OA).
3. 1Gb Ethernet Pass-Thru Modules.
4. Cisco 3020, HP 6125G, HP 6120XG, and Brocade SAN enclosure switches.
5. BL460 and BL620 blade servers.
6. P2000 and MSA2012fc external storage controllers.
7. D2700 enclosure cascaded from a P2000.
8. DL380 and DL360 rack mount servers.

NOTE: It is recommended that rack mount servers be upgraded last. If you choose to upgrade them at any other time, please make sure to adhere to the rules in the [Important Rules on Simultaneous Firmware Upgrades](#) section.

NOTE: Mated switches must run the same firmware version. Make sure both switches are running the same firmware version before proceeding with the recommended order of firmware upgrades.

3.2 Recommended Order of Firmware Upgrades - Platform 6.7 to 7.2

The following is the recommended order of firmware upgrades when on or upgrading to Platform 6.7 to 7.2 It is meant to reduce possible issues during the process of upgrading a system's firmware.

1. PM&C host server and PM&C application. (**PM&C 5.7 or greater must be installed before upgrading OA firmware to version 4.50**)
2. 4948, 4948E, and 4948E-F switches.
3. Onboard Administrator (OA).
4. 1Gb Ethernet Pass-Thru Modules.
5. Cisco 3020, HP 6125G, HP 6120XG, 6125XLG and Brocade SAN enclosure switches.
6. BL460 and BL620 blade servers.
7. P2000 and MSA2012fc external storage controllers.
8. D2700 enclosure cascaded from a P2000.
9. DL380 and DL360 rack mount servers.

NOTE: It is recommended that rack mount servers (other than the PM&C host) be upgraded last. If you choose to upgrade them at any other time, please make sure to adhere to the rules in the [Important Rules on Simultaneous Firmware Upgrades](#) section.

NOTE: Mated switches must run the same firmware version. Make sure both switches are running the same firmware version before proceeding with the recommended order of firmware upgrades.

3.3 Important Rules on Simultaneous Firmware Upgrades

Below are important rules to follow when attempting to upgrade more than one type of hardware at a time.

- Do not upgrade an Onboard Administrator to version 4.50 until the associated PM&C is at version 5.7 or greater.
- When upgrading any firmware component do not simultaneously upgrade any network hardware between you and the component being upgraded.
- Do not upgrade anything else when upgrading 4948, 4948E, and 4948E-F switches.
- Do not upgrade anything else within the c7000 enclosure when upgrading Cisco 3020, HP 6125G, HP 6120XG, HP 6125XLG, and Brocade SAN enclosure switches.
- When upgrading an Onboard Administrator (OA) do not upgrade anything else within the c7000 enclosure.

4 Compatibility

4.1 With Previous HP FUP Releases

HP FUP releases are generally compatible with previous HP FUP releases, but previous HP FUP releases may not be compatible with the TPD version being used.

4.2 With Oracle Application Software

Before upgrading the Onboard Administrator to firmware version 4.50, the PM&C must be at version 5.7 or greater.

If using PM&C 5.7 or greater use Onboard Administrator firmware version 4.50.

If using PM&C 4.x to 5.5 use Onboard Administrator firmware version 3.71.

If using PM&C 2.x to 3.x use Onboard Administrator firmware version 3.31.

All HP Gen8 servers require either TPD 5.1.0 or TPD 6.0.0 build 80.20 or higher (eg. TPD 6.0.0-80.20.0) when installing TPD and this firmware release.

Installing TPD and TVOE builds older than 82.30 fails on Gen8 servers when System ROMs newer than 2013.09.18 are used. This problem only occurs during install. After an older, affected version of TPD (build 82.29 and lower) has been installed System ROM versions newer than 2013.09.18 can be installed and run without issue. This problem would only occur if there were some reason to re-install that older version of TPD such as a disaster recovery scenario. This means that before you upgrade to TPD build 82.30 or newer you should upgrade the firmware on the server to the latest approved System ROM version.

4.3 Firmware Version Restrictions

This table includes all conditional restrictions on firmware versions. If a system meets the condition then the listed component must comply with the version restrictions.

Condition	Component	Version	Description
PM&C version \leq 3.2.x	OA	3.31 only	HP OA Firmware version 3.5 or higher is incompatible with older PM&C versions resulting in an inability to IPM enclosure blades.
TPD/TVOE build less than 82.30	Gen8 Blade and RMS System ROMs	2013.09.18 maximum	TPD/TVOE builds before 82.30 will not install with Gen8 System ROMs newer than version 2013.09.18
OA firmware version \geq 4.01	PM&C	5.7 minimum	Before an OA can be upgraded to firmware version 4.01 or later the PM&C must be at version 5.7 or greater.
PM&C version 4.x to 5.4	OA	3.71 only	If a PM&C, version 4.x to 5.5, is being used the OA firmware must be version 3.71.
PM&C version 5.7 or greater	OA	4.50 only	If a PM&C, version 5.7 or greater is being used the OA firmware must be version 4.50.

5 HP SPP Baseline and Changes

This section details the version of the HP SPP ISO used as a baseline for this HP Firmware Upgrade Pack and any firmware versions that differ from it.

The baseline version of the HP SPP ISO used for HP FUP 2.2.10 is SPP 2016.04.0. Windows and VMware components were removed to allow the ISO file size to be below 4GB for compatibility with the OA Enclosure Firmware Management feature and to generally reduce the size of the ISO. Gen9 System ROMs were upgraded from the original versions to the ones indicated in this document. HP QLogic NX2 version 2.15.19 was added in addition to the original version to support the NC532i NIC.

6 Additional Instructions

For firmware issues and concerns please contact HP Support for assistance. If any firmware issue is found to impact Oracle software please contact Oracle Support to notify us of the problem.

6.1 Additional Firmware Installation and Configuration

The following are additional installation and configuration instructions for this release.

- Mated switches of the same model must have the same firmware version(s) as each other.
- When upgrading a Cisco 3020 switch, the OA must first be upgraded to firmware version 3.70 or newer.
- The PM&C must be at version 5.7 or greater before upgrading to OA firmware version 4.50.