

## **Documentation Bulletin**

Severity Level	Info	Bulletin Number	E87284
Issue Date	5/2/2017	Expires	N/A
Title	E5-OAM ROHS-compliant Card Availability		
Product	EAGLE	Release	40.1 and later
Priority	FYI	Related Bugs	N/A
Impacts Compatibility	NO	Impacted Product Line(s):	EAGLE
Markets	ALL	Part No. Affected	870-2903-xx, 870-2900-01
Author and Formal Approvers			
Author	G. Brookins 5/2/2017	Customer Documentation	K. Cook 5/2/2017

## **Problem Description**

A new RoHS E5-OAM (E5-MASP P/N 7346924 and E5-MDAL P/N 7346923) card is available for EAGLE release 40.1 and later. This like-for-like replacement is interchangeable with existing E5-OAM (both E5-MASP and E5-MDAL) cards.

## Impact

The existing E5-MASP (870-2903-xx) can be used in the same EAGLE Control Shelf with the RoHS E5-MASP (7346924) and/or the RoHS E5-MDAL (7346923). The existing E5-MDAL (870-2900-01) can be used in the same EAGLE Control Shelf with the RoHS E5-MASP (7346924).

## **Needed Actions**

Treat the RoHS E5-OAM deployment like the current E5-OAM.

Customers should store this bulletin with their associated EAGLE documentation location for reference.

This notice is provided information to Oracle customers about issues identified with our systems. If you have any questions about this notice, call the My Oracle Support main number at 1-800-223-1711 (toll-free in the US), or call the Oracle Support hotline for your local country from the list at http://www.oracle.com/us/support/contact/index.html.

E87284 Revision 1.0 Page 1 of 1