

Documentation Bulletin

| Severity Level | Info | Bulletin Number | E87285 |
|-----------------------------|--|---------------------------|------------------|
| Issue Date | 5/2/2017 | Expires | N/A |
| Title | HIPR2 RoHS-compliant Card Availability | | |
| Product | EAGLE | Release | 42.0 and later |
| Priority | FYI | Related Bugs | N/A |
| Impacts Compatibility | NO | Impacted Product Line(s): | EAGLE |
| Markets | ALL | Part No. Affected | 870-2872-xx |
| Author and Formal Approvers | | | |
| Author | G. Brookins 5/2/2017 | Customer Documentation | K. Cook 5/2/2017 |

Problem Description

A new RoHS HIPR2 (P/N 7333484) card is available for EAGLE release 42.0 and later. This like-for-like replacement is interchangeable with existing HIPR2 cards.

Impact

An EAGLE Frame can have a mixture of existing HIPR2 cards (870-2872-xx) and RoHS HIPR2 cards (7333484), even within the same shelf.

Needed Actions

Treat the RoHS HIPR2 deployment like the current HIPR2.

Customers should store this bulletin with their associated EAGLE documentation location for reference.

This notice is provided information to Oracle customers about issues identified with our systems. If you have any questions about this notice, call the My Oracle Support main number at 1-800-223-1711 (toll-free in the US), or call the Oracle Support hotline for your local country from the list at http://www.oracle.com/us/support/contact/index.html.

E87285 Revision 1.0 Page 1 of 1