

Severity Level	Info	Bulletin Number	E84899
Issue Date	2/7/2017	Expires	EAGLE 46.5
Title	SLIC Card Deployment Restrictions		
Product	EAGLE	Release	46.4
Priority	FYI	Related Bugs	N/A
Impacts Compatibility	NO	Impacted Product Line(s):	EAGLE
Markets	ALL	Part No. Affected	7094646
Author and Formal Approvers			
Author	G. Brookins	2/7/2017	Customer Documentation B. Chappell 2/7/2017
Problem Description			
SLIC cards provisioned as <i>type=dsm</i> can only be installed in an odd-numbered slot. In addition, the even-numbered slot immediately to the right of the SLIC card cannot be used.			
Impact			
May cause deployment issues.			
Needed Actions			
Treat SLIC card deployment like the E5-SM4G or E5-SM8G-B. Customers should store this bulletin with their associated EAGLE documentation location for reference.			
This notice is provided information to Oracle customers about issues identified with our systems. If you have any questions about this notice, call the My Oracle Support main number at 1-800-223-1711 (toll-free in the US), or call the Oracle Support hotline for your local country from the list at http://www.oracle.com/us/support/contact/index.html .			