Sun Netra™ T6340 Server Module

Product Notes

Part No. 821-0897-10
March 2010, Revision A

Copyright © 2010, Oracle and/or its affiliates. All rights reserved.

This software and related documentation are provided under a license agreement containing restrictions on use and disclosure and are protected by intellectual property laws. Except as expressly permitted in your license agreement or allowed by law, you may not use, copy, reproduce, translate, broadcast, modify, license, transmit, distribute, exhibit, perform, publish, or display any part, in any form, or by any means. Reverse engineering, disassembly, or decompilation of this software, unless required by law for interoperability, is prohibited.

The information contained herein is subject to change without notice and is not warranted to be error-free. If you find any errors, please report them to us in writing.

If this is software or related software documentation that is delivered to the U.S. Government or anyone licensing it on behalf of the U.S. Government, the following notice is applicable:

U.S. GOVERNMENT RIGHTS Programs, software, databases, and related documentation and technical data delivered to U.S. Government customers are "commercial computer software" or "commercial technical data" pursuant to the applicable Federal Acquisition Regulation and agency-specific supplemental regulations. As such, the use, duplication, disclosure, modification, and adaptation shall be subject to the restrictions and license terms set forth in the applicable Government contract, and, to the extent applicable by the terms of the Government contract, the additional rights set forth in FAR 52.227-19, Commercial Computer Software License (December 2007). Oracle USA, Inc., 500 Oracle Parkway, Redwood City, CA 94065.

This software or hardware is developed for general use in a variety of information management applications. It is not developed or intended for use in any inherently dangerous applications, including applications which may create a risk of personal injury. If you use this software or hardware in dangerous applications, then you shall be responsible to take all appropriate fail-safe, backup, redundancy, and other measures to ensure the safe use. Oracle Corporation and its affiliates disclaim any liability for any damages caused by use of this software or hardware in dangerous applications.

Oracle is a registered trademark of Oracle Corporation and/or its affiliates. Oracle and Java are registered trademarks of Oracle and/or its affiliates. Other names may be trademarks of their respective owners.

AMD, Opteron, the AMD logo, and the AMD Opteron logo are trademarks or registered trademarks of Advanced Micro Devices. Intel and Intel Xeon are trademarks or registered trademarks of Intel Corporation. All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. UNIX is a registered trademark licensed through X/Open Company, Ltd.

This software or hardware and documentation may provide access to or information on content, products, and services from third parties. Oracle Corporation and its affiliates are not responsible for and expressly disclaim all warranties of any kind with respect to third-party content, products, and services. Oracle Corporation and its affiliates will not be responsible for any loss, costs, or damages incurred due to your access to or use of third-party content, products, or services.

Please
Recycle

Contents

Late-Breaking Information 1

Supported Versions of the Solaris OS, Firmware, and Software 1

Required Patches 2

Supported Hardware 2

Known Issues 2

Documentation 2

Support and Training 3

Sun Welcomes Your Comments 3

Late-Breaking Information

These product notes provide important and late-breaking information about the Sun Netra T6340 server module.

Supported Versions of the Solaris OS, Firmware, and Software

TABLE 1 lists the minimum required and latest versions of software and firmware for use with Sun Netra T6340 server modules.

TABLE 1 Supported Software and Firmware Versions

Software or Firmware	Minimum and Latest
Solaris Operating System	Solaris 10 10/09 OS
Sun Netra T6340 Server Module firmware (patch ID 139447-xx provides this version)	7.2.7.e (patch ID 139447-01, or later)
Integrated Lights Out Manager (ILOM) software*	ILOM 3.0.9.3.a
Logical Domains Manager (LDoms) Includes Management Information Base (MIB)	1.0.3 MIB 1.0.1 Update 1
Chassis management module (CMM)	CMM ILOM 3.0.6.11.c

* ILOM is a component of the System Firmware. To upgrade your version of ILOM, you must upgrade your System Firmware.

To check for firmware updates, visit:

`http://www.sun.com/bigadmin/patches/firmware`

Required Patches

At this time, there are no mandatory patches required for this server module running the Solaris 10 10/09 OS.

To check for availability of patches, go to:

http://sunsolve.sun.com

Supported Hardware

For details on hardware that is supported for use with the Sun Netra T6340 Server Module, refer to the *Sun Netra 6000 Modular System Product Notes* (821-0929).

Known Issues

There are no known Sun Netra T6340 server module issues.

Documentation

Documentation for the Sun Netra T6340 server module is available at:

http://docs.sun.com/app/docs/prod/nt6340.srvrmod.hic#

Documentation for the Sun Netra 6000 Modular System is available at:

http://docs.sun.com/app/docs/prod/n6000.modsys#hic

Additional Sun documentation is available at:

http://www.sun.com/documentation

Support and Training

Note – Before contacting your authorized service representative for support, ensure that required patches are installed on your server module and related systems.

Sun Function	URL
Support	http://www.sun.com/support/
Training	http://www.sun.com/training/

Sun Welcomes Your Comments

Sun is interested in improving its documentation and welcomes your comments and suggestions. You can submit your comments by clicking the Feedback [+] link at:

http://docs.sun.com

Please include the title and part number of your document with your feedback:

Sun Netra T6340 Server Module Product Notes, part number 821-0897-10.