Tekelec Signaling Products

Master Index

909-1292-01, Revision C
September 2005

TEKELEC

Copyright© 2005 Tekelec.

All Rights Reserved
Printed in U.S.A.

Notice
Information in this documentation is subject to change without notice. Unauthorized use or copying of this documentation can result in civil or criminal penalties.

Any export of Tekelec products is subject to the export controls of the United States and the other countries where Tekelec has operations.

No part of this documentation may be reproduced or transmitted in any form or by any means, electronic or mechanical, including photocopying or recording, for any purpose without the express written permission of an authorized representative of Tekelec.

Other product names used herein are for identification purposes only, and may be trademarks of their respective companies.

Trademarks
The Tekelec logo, EAGLE, G-Flex, G-Port, IP^7, IP^{7}Edge, IP^7 Secure Gateway, and TALI are registered trademarks of Tekelec, Inc. TekServer is a trademark of Tekelec, Inc. All other trademarks are the property of their respective owners.

Patents
This product is covered by one or more of the following U.S. and foreign patents:

U.S. Patent Numbers:

5,008,929, 5,953,404, 6,167,129, 6,324,183, 6,327,350, 6,606,379, 6,639,981, 6,647,113, 6,662,017, 6,735,441, 6,745,041, 6,765,990, 6,795,546, 6,819,932, 6,836,477, 6,839,423, 6,885,872

Ordering Information
Additional copies of this document can be ordered from:

Tekelec Network Signaling Group
Attention: Central Logistics
5200 Paramount Parkway
Morrisville, North Carolina, 27560

Or e-mail your request to *CentralLogistics@tekelec.com*.

Master Index

Eagle 32.0

This section provides an alphabetized index of the Eagle 32.0 documentation set. Each index entry includes the center four digits of the manual part number and the page number where it occurs in that manual. Use Adobe Acrobat Reader 6.0.1 or later.

Symbols

#, 4307:B-22
%full threshold reached - upload required, 4593:3-258
(N)CDSR already exists for specified CGSR, 4801:2-884
(N)CGSR already exists for specified OPNAME, 4801:2-882
(N)SERV must be GPORT/PPSMS/MNPSMS/EIR when (N)SNAI=CCRNDN, 4801:2-786
(N)SERV value is invalid for the specified (N)SNAI, 4801:2-769
(N)SNP must be E164 when (N)SERV=GPORT/PPSMS/MNPSMS, 4801:2-783
(N)SNP must be E164 when NSERV=INPMR, 4801:2-768
(N)SNP/(N)SNAI must not be specified when (N)SERV=INPQ/EIR, 4801:2-770
Single Slot Enhanced DCM, 4318:5-80
.doc file extension, 0008:2-35, 0008:2-72, 0008:2-96, 0008:2-100
.txt file extension, 0008:2-35, 0008:2-72, 0008:2-96, 0008:2-100
<command> command not recognized (C<col>), 4801:2-549
<command> command not supported by this implementation (C<col>), 4801:2-549
<device> is <condition>, 4801:2-417
<parm_desc> is out of range - <parm>, 4801:2-9
<parm_desc> is out of range, <min>...<max> - <parm>, 4801:2-9
<parm_desc> is out of range, <min>...<max>, '<char>' - <parm>, 4801:2-10
<parm_desc> is out of range, <min>...<max>, '<char>', '<char>' - <parm>, 4801:2-10
<parm_desc> num digits incorrect, min <min> max <max> - <parm>, 4801:2-21
<parm_desc> too long, min <min>, max <max>, - <parm>, 4801:2-19
<parm_desc> too short, min <min>, max <max>, - <parm>, 4801:2-18
<parm_desc> value is undefined - <parm>, 4801:2-20
<parm_desc> is out of range, <min>...<max> - <parm>, 4801:2-26
<reserved word> cannot be used in this command <reserved name> = reserved word, 4801:2-443
"Cables", 4626:1-7
"Connectors", 4626:1-7
"Integrated Sentinel", 4626:1-7
"LEDs", 4626:1-7
"Power Cords to Peripherals", 4626:1-7

Numerics

100BASE-T Ethernet network
    ELAP Sync, 4307:2-8
    main DSM, 4307:2-7
10BASE-T Ethernet network
    backup DSM, 4307:2-7
1114 Clock selection mismatch, 4593:3-513

1114 E1/T1 clock requires TDM-GTI, 4593:3-510
1114, 1116 Clock selection mismatch, 4593:3-517
1114, 1116 E1/T1 clock requires TDM-GTI, 4593:3-512
1114-P 1114-S 1116-P clocks failed, 4593:3-257
1114-P 1114-S 1116-S clocks failed, 4593:3-256
1114-P 1114-S clocks failed, 4593:3-255
1114-P 1116-P 1116-S clocks failed, 4593:3-254
1114-P 1116-P clocks failed, 4593:3-253
1114-P 1116-S clock failed, 4593:3-252
1114-P clock failed, 4593:3-251
1114-PHS clock failed, 4593:3-282
1114-PHS, 1114-SHS clocks failed, 4593:3-290
1114-PHS, 1114-SHS, 1116-PHS clocks failed, 4593:3-294
1114-PHS, 1114-SHS, 1116-SHS clocks failed, 4593:3-292
1114-PHS, 1116-PHS clocks failed, 4593:3-286
1114-PHS, 1116-PHS, 1116-SHS clocks failed, 4593:3-288
1114-PHS, 1116-SHS clocks failed, 4593:3-284
1114-S 1116-P 1116-S clocks failed, 4593:3-250
1114-S 1116-P clocks failed, 4593:3-249
1114-S 1116-S clocks failed, 4593:3-248
1114-S clock failed, 4593:3-247
1114-SHS clock failed, 4593:3-274
1114-SHS, 1116-PHS clocks failed, 4593:3-278
1114-SHS, 1116-PHS, 1116-SHS clocks failed, 4593:3-280
1114-SHS, 1116-SHS clocks failed, 4593:3-276
1116 Clock selection mismatch, 4593:3-515
1116 E1/T1 clock requires TDM-GTI, 4593:3-511
1116-P 1116-S clocks failed, 4593:3-246
1116-P clock failed, 4593:3-245
1116-PHS clock failed, 4593:3-270
1116-PHS, 1116-SHS clocks failed, 4593:3-272
1116-S clock failed, 4593:3-244
1116-SHS clock failed, 4593:3-268
14008
    Heading 1
        IETF SCTP for “A” Link Connectivity to SCP/HLR/MGC, 4318:3-69
145C tag, 4601:4-15
15 Minute Measurements Controlled Feature - Eagle
    Activating, 0002:B-26
1500 Signaling Links, 0003:3-110, 4804:3-9
15-minute measurement collection in progress, 4801:2-657
15-minute measurement feature must be on, 4801:2-660
1-800-432-8919, 4626:1-19
18911
    Heading 2
        LSMS/ELAP PING Enhancement, 4307:2-16
18GB to 36GB Hard Drive Upgrade (Release 29.1)(IP7 Release 7.1), 4318:2-1
1900 number portability - PCS, 4802:3-30
2 to 12 million LNP telephone numbers
    enabling, 4802:2-16
20111
    Heading 1

E1/T1 Multi-Channel Interface, 4318:2-112
2500 Routing Keys (IP7 Release 7.1), 4318:2-3
28760
Heading 1
Pre-Paid SMS Intercept - Phase 1, 4318:5-24
30 - Read-only file system, 0008:2-118
30625
Heading 1
EOAP/OAP Support of HSOP Protocol, 4318:2-167
30-minute measurement collection in progress, 4801:2-110
32 - Broken pipe, 0008:2-118
35 - Unsupported value, 0008:2-118
386/486 register cannot be specified, 4801:2-314
40 - A destination address is required, 0008:2-116
40,000 GTT Capacity, 4318:2-7
40,000 GTT Capacity (Release 28.0), 4318:2-7
40,000 GTT Capacity (Release 28.0) (IP7 Release 6.0), 4318:2-7
4000 Routesets (23.0), 4318:2-5
alarms, 4318:2-7
destination commands, 4318:2-6
rtrv-feat, 4318:2-6
41 - Protocol wrong type for socket, 0008:2-116
42 - The protocol is not available, 0008:2-116
42935
Heading 2
Tekelec Customer Services, 4626:1-19
43 - The protocol is not supported, 0008:2-116
44 - The socket type is not supported, 0008:2-116
45 - The operation is not supported on the socket, 0008:2-116
46 - The protocol family is not supported, 0008:2-116
47 - The address family is not supported, 0008:2-116
47123
Heading 1
Network Surveillance Enhancements, 4318:4-183
48 - The address is already in use, 0008:2-116
48 Million Numbers (27.0), 4318:2-7
alarms, 4318:2-14
changed commands, 4318:2-14
hardware requirements, 4318:2-11
new commands, 4318:2-13
system requirements, 4318:2-11
upgrade considerations, 4318:2-12
48 Million Numbers feature
see LNP 48 MIllion Numbers feature
48 Million Numbers feature, LNP, 4307:2-2
49 - The requested address cannot be assigned, 0008:2-116
4-port DS0 monitor applique, 4625:B-6
4-port DSCS monitor applique, 4625:B-8
4-port E1 monitor applique, 4625:B-4
4-port T1 monitor applique, 4625:B-2
4-port V.35 monitor applique, 4625:B-7
5 Minute Linkset Data (25.0), 4318:2-14

changed commands, 4318:2-15
50 - Socket operation on non-socket, 0008:2-116
500 SS7 Links (21.0), 4318:2-19
changed commands, 4318:2-19
5000 Routes, 4804:2-21
5000 Routes (26.1), 4318:2-20
changed commands, 4318:2-20
51 - The network is unreachable, 0008:2-116
52 - The network dropped the connection on reset, 0008:2-116
53 - Software caused the connection to abort, 0008:2-116
54 - The connection was reset by the peer, 0008:2-117
54012
Heading 2
Installation Support, 4626:1-18
55 - No buffer space available, 0008:2-117
56 - The socket is already connected, 0008:2-117
56 Million G-Flex Entries (Release 29.1) (IP7 Release 7.1), 4318:2-3
569 - The file name is already specified, 0008:2-104
57 - The socket is not connected, 0008:2-117
58 - Can't send after socket shutdown, 0008:2-117
5-8 Bit Sequencing Assurance (24.0), 4318:2-16
changed commands, 4318:2-17
signaling link selection conversion, 4318:2-17
59 - Too many references: can't splice, 0008:2-117
595 - File open failed, 0008:2-104
597 - SFTP client packet send failure, 0008:2-104
598 - The SFTP connection is closed, 0008:2-104
599 - SFTP packet read failure, 0008:2-104
5-minute measurement collection in progress, 4801:2-111
60 - The connection timed out, 0008:2-117
600 - SFTP protocol error, 0008:2-105
6000 Routesets, 4804:2-21
6000 Routesets (Release 29.0), 4318:2-21
600-0154-01, 4601:6-22, 4601:6-23
600-0193-01, 4601:6-16, 4601:6-17
600-0934-01, 4601:5-69
601 - Undefined, 0008:2-105
601-0010-01, 4601:6-25
606-0062-01, 4601:5-69, 4601:6-16, 4601:6-17
608 - SFTP received a invalid ID in the response received during a read operation on remote directory, 0008:2-105
609 - SFTP: Handle mismatch error, 0008:2-105
61 - The connection was refused, 0008:2-117
610 - Unexpected SSH2_FXP_ATTRS, 0008:2-105
611 - Unexpected SSH_FXP_NAME, 0008:2-105
612 - SSH_FXP_REALPATH request failure, 0008:2-106
613 - SSH_FXP_READLINK request failure, 0008:2-106
614 - unexpected SSH_FXP_NAME, 0008:2-106
615 - The SFTP client received more data than expected, 0008:2-106
616 - The SFTP client failed to read the data from the file descriptor, 0008:2-106
617 - Excessive identity files, 0008:2-107
62 - The network is down, 0008:2-118

624 - The debug levels allowed for SSH protocol in openSSH is 0-9, 0008:2-107
625 - Failure to read the client configuration file, 0008:2-107
626 - Invalid compression level is specified in the client configuration file, 0008:2-107
627 - SSH failure to setup the IO with the server, 0008:2-107
628 - SSH failure to open the channel for the SSH connection with the server, 0008:2-107
629 - SSH failure to setup the channel for the SSH connection with the server, 0008:2-107
630 - SSH failure to verify the SSH client host key, 0008:2-107
631 - SSH user authentication failure, 0008:2-108
632 - The authentication method is NULL in the client software, 0008:2-108
633 - Permission is denied by the server due to authentication failure, 0008:2-108
633 - User login failure, 0008:2-104
640 - A bad message was received during the SSH authentication, 0008:2-108
641 - Missing authentication context, encountered during the SSH user authorization, 0008:2-109
642 - Failure during the public key read / verification operation, 0008:2-109
643 - Undefined SFTP / SSH error, 0008:2-109
644 - Unexpected SSH_FXP_STATUS error, 0008:2-109
645 - A bad option was specified in the SSH client on the Eagle, 0008:2-109
646 - An unsupported escape character was used in the SSH client on the Eagle, 0008:2-109
647 - An unsupported cipher type was used in the SSH client on the Eagle, 0008:2-109
648 - An unsupported MAC type was used in the SSH client on the Eagle, 0008:2-110
649 - A bad port was used in the SSH client on the Eagle, 0008:2-110
65 - There is no route to the host, 0008:2-118
65,535 Entries per Translation Type (22.0), 4318:2-23
652-0841-01, 4601:6-22, 4601:6-23
652-0954-01, 4601:5-69, 4601:6-16
656 - Bad forwarding was used in the SSH client on the Eagle, 0008:2-110
657 - Bad forwarding ports were specified in the SSH client on the Eagle, 0008:2-110
658 - A bad dynamic port was specified in the SSH client on the Eagle, 0008:2-110
658-0941-01, 4601:5-121
658-0941-02, 4601:5-121
659 - The host was not specified in the SSH client on the Eagle, 0008:2-111
660 - An invalid option or argument was specified in the SSH client on the Eagle, 0008:2-111
661 - The hostname was not specified in the SSH client on the Eagle, 0008:2-111
663 - The SSH client was unable to load the cipher type on the Eagle, 0008:2-111
664 - Asynchronous IO is not supported on IPSM, SSH client error, 0008:2-111
665 - Compression is already enabled in the SSH client on the Eagle, 0008:2-111
666 - Unknown cipher number on the SSH client on the Eagle, 0008:2-111
667 - The SSH client key length is invalid, 0008:2-111
668 - No key is available on the SSH client on the Eagle, 0008:2-112
669 - The secure connection was closed by the remote server, 0008:2-112
67 - The host is down, 0008:2-118
670 - Connection failure due to network outage or the connection was lost due to a faulty SSHD / SFTP server or network, 0008:2-112
671 - An unexpected packet type was received from the SFTP / SSHD server, 0008:2-112
672 - A bad packet length was received from the SSHD / SFTP server, 0008:2-112
673 - A cryptographic attack was detected by the SSH client, 0008:2-112
674 - The SSH / SFTP client on the Eagle failed to read from the remote side, 0008:2-113
675 - Corrupted check bytes were detected on the SSH / SFTP client on the Eagle, 0008:2-113
676 - Corrupted MAC on input was detected by the SSH / SFTP client on the Eagle, 0008:2-113
677 - Corrupted pad on input was detected by the SSH / SFTP client on the Eagle, 0008:2-113
678 - SSH / SFTP tried to close a connection that is already closed, 0008:2-113
679 - The SSH / SFTP client on the Eagle failed to write to the remote side, 0008:2-114

680 - SSH / SFTP tried to set the packet size twice, 0008:2-114
681 - A bad packet size was detected by the SSH / SFTP client on the Eagle, 0008:2-114
682 - The connection timed out when SSH tried to connect to SSHD, 0008:2-115
683 - The SSH connection was refused by the remote server, 0008:2-115
684 - The SSHD server is unreachable, 0008:2-115
685 - The network has reset, 0008:2-115
686 - The SSH / SFTP connection has been aborted, 0008:2-115
687 - The SFTP / SSH connection has been reset by the peer, 0008:2-115
688 - Failed to allocate network buffers, 0008:2-115
689 - The SSH / SFTP socket is already connected, 0008:2-115
690 - The SSH / SFTP socket is not connected, 0008:2-115
691 - The network channel is down, 0008:2-115
692 - The SSHD / SFTP server connection host is down, 0008:2-115
693 - SFTP client channel read failure, 0008:2-115
694 - SFTP client channel write failure, 0008:2-115
695 - SFTP client channel open failure, 0008:2-115
7000 Routesets, 4804:2-21
8000 Routesets, 4804:2-21
804-0176-01, 4601:6-11, 4601:6-48
830-0232-01, 4601:5-86
830-0398-xx, 4601:5-79, 4601:5-89, 4601:5-90, 4601:5-100, 4601:6-10, 4601:6-11, 4601:6-14, 4601:6-15
830-0404-xx, 4601:5-79, 4601:5-89, 4601:5-100, 4601:6-9
830-0528-xx, 4601:6-11, 4601:6-37, 4601:6-48, 4601:6-49, 4601:6-51, 4601:6-72
830-0531-04, 4601:5-107
830-0535-xx, 4601:5-107
830-0605-02, 4601:5-122, 4601:5-129
830-0609-01, 4601:5-64, 4601:5-73
830-0609-xx, 4601:6-11, 4601:6-15, 4601:6-32, 4601:6-38, 4601:6-42, 4601:6-43, 4601:6-53, 4601:6-54
830-0622-xx, 4601:5-119
830-0638-xx, 4601:5-86
830-0657-xx, 4601:6-11, 4601:6-32, 4601:6-36, 4601:6-44, 4601:6-47, 4601:6-53, 4601:6-57, 4601:6-162
830-0699-01, 4601:6-157
830-0699-xx, 4601:6-11, 4601:6-32, 4601:6-35, 4601:6-38, 4601:6-39, 4601:6-41, 4601:6-54, 4601:6-70
830-0708-xx, 4601:6-11, 4601:6-32, 4601:6-37, 4601:6-52, 4601:6-71
830-0709-xx, 4601:6-11, 4601:6-12, 4601:6-32, 4601:6-37, 4601:6-49, 4601:6-51, 4601:6-54, 4601:6-72
830-0710-xx, 4601:6-11, 4601:6-58
830-0772-xx, 4601:5-125
830-0788-xx, 4601:5-25
830-0873-07, 4601:5-104
830-0873-xx, 4601:5-83
830-0894-xx, 4601:5-125
830-0895-01, 4601:5-125, 4601:5-126
840-0016-02, 4601:6-22
840-0064-01, 4625:3-6
840-0089-01, 4625:3-6
850-0330-02 / 03 / 04, 4601:5-13
850-0330-06, 4601:5-11, 4601:5-13, 4601:5-64, 4601:5-73, 4601:5-86, 4601:5-104, 4601:5-105
850-0488-xx, 4601:6-39
870-0774-10, 4601:5-6, 4601:5-91
870-0774-15, 4601:2-5
870-1824-01, 4601:5-63
870-1965-01, 4601:5-6, 4601:5-91

870-1984-02, 4601:5-25
870-1984-03, 4601:5-25
870-1984-04, 4601:5-25
870-1984-xx, 4601:5-25
870-2062-02, 4601:5-133
870-2197-01, 4601:5-25
870-2198-XX, 4601:5-125
870-2238-01, 4625:3-6
870-2278-01, 4625:3-6
870-2360-01, 4601:5-6, 4601:5-91
870-2372-01, 4601:5-25
870-2785-01, 2969:7-2
890-0001-01, 4601:5-54, 4625:3-118
890-1037-01, 4601:5-122, 4601:5-123, 4601:5-128
890-1038-01, 4601:5-68
890-1038-02, 4601:5-68
890-1050-01, 4601:6-22
890-1050-03, 4601:6-22
8-Bit SLS Support (21.0), 4318:2-24
8-Port Connector Box
description, 4625:4-30, 4625:4-38, 4625:4-43
replacement procedure, 4593:6-127
91337
Heading 1
Random SLS Generation, 4318:5-43

A

A bad dynamic port was specified in the SSH client on the Eagle - Error code 658, 0008:2-110
A bad message was received during the SSH authentication - Error code 640, 0008:2-108
A bad option was specified in the SSH client on the Eagle - Error code 645, 0008:2-109
A bad packet length was received from the SSHD / SFTP server - Error code 672, 0008:2-112
A bad packet size was detected by the SSH / SFTP client on the Eagle - Error code 681, 0008:2-114
A bad port was used in the SSH client on the Eagle - Error code 649, 0008:2-110
A CANC-LNP-TNRPT command must not already be in progress, 4801:2-649
A complete point code must be entered, 4801:2-234
A cryptographic attack was detected by the SSH client - Error code 673, 0008:2-112
A destination address is required - Error code 40, 0008:2-116
A mated linkset cannot have more than one link assigned, 4801:2-861
A maximum of 5 LNP 4DIGIT objects may be allocated, 4801:2-647
A maximum of 8 PCs are allowed in a group, 4801:2-353
A problem occurred while trying to access the GWS database, 4801:2-403
A RTRV-LNP-TNRPT command must already be in progress, 4801:2-649
A RTRV-LNP-TNRPT command must not already be in progress, 4801:2-648
A side, 4601:4-23
A specific NIC must be specified in the range (0-3), 4801:2-246
A specific SI must be specified in the range (0-15), 4801:2-407
A specific SSN must be specified in the range (1-255,*), 4801:2-245
A timeout occurred while processing SCSI Debug Command, 4801:2-541
A TTN-reserved service type name only if it matches SERV, 4801:2-527
AAL, 4593:1-17
AAL5, 4593:1-17

AAL5CP, 4593:1-17
AATM, 4593:1-17
Able / Unable states, ELAP, 4307:2-10
aborting
audit, 4751:5-15
bulk load, 4751:6-12
user-initiated resynchronization, 4751:4-11
About FTRA window, 0008:2-11, 0008:2-102
access
configuration menu, 4307:5-14
ACCESS can only be specified with TYPE=P486-DATA, 4801:2-305
accessing
ELAP GUI interface, 2712:A-1
ELAP text interface, 2712:A-6
Account Inactivity, 4307:3-110
ACG, 4593:1-17, 4802:1-12
ACG Node Overload Level Change, 4593:3-811
ACM, 4593:1-17, 4601:2-2, 4601:5-21, 4601:A-4, 4625:3-21, 4625:3-37, 4625:3-95, 4626:1-32
ACM card replacement, 4593:A-43
acronyms, 0002:1-12, 0003:1-12, 4804:1-12
ACT, 4593:1-17
act-alm-trns, 4800:5-2
act-cdl, 4800:5-2
act-dlk, 4800:5-4, 4800:6-2
act-echo, 4800:5-5
act-file-trns, 4800:5-6
act-flash, 4800:5-9
act-ftp-trns, 4800:5-11
act-gpl, 4800:5-13
ACTION and SRCLPSET must be specified together, 4801:2-563
action commands, 4800:4-9
ACTION must be specified as FORWARD, DUPLICATE, or DUPDISC, 4801:2-460
ACTION or FORBID parameter shouldn't be specified, 4801:2-794
Action requires either SAPC or MATELSN, not both, 4801:2-863
Activat, 4593:1-17
Activate, 4800:5-5
Activate Echo to a Terminal
Miscellaneous Command Adjustments (26.0), 4318:4-115
activate signaling link, act-slk
IPGWI, 0003:3-75, 0003:3-133, 0003:3-148, 0003:3-170, 0003:3-182, 0003:3-199, 0003:3-200, 0003:3-214, 0003:3-215, 0003:3-291, 0003:3-293, 0003:3-312, 0003:3-314
IPLIM, 0003:3-75, 0003:3-133, 0003:3-148, 0003:3-170
SS7IPGW, 0003:3-75, 0003:3-133, 0003:3-148, 0003:3-170, 0003:3-182, 0003:3-199, 0003:3-200, 0003:3-214, 0003:3-215, 0003:3-291, 0003:3-293, 0003:3-312, 0003:3-314
Activating
15 Minute Measurements Controlled Feature, 0002:B-26
Command Class Management Controlled Feature, 0002:B-3
Eagle OAM IP Security Enhancements Controlled Feature, 0002:B-12
IP User Interface Controlled Feature, 0002:B-3
LNP Feature on the Eagle, 0007:2-128
LNP Feature Overview, 0007:2-6
LNP Short Message Service Feature, 0007:2-157

Network Security Enhancements Controlled Feature, 0002:B-3
Activating Controlled Features procedure, 0008:2-3
Activating the ANSI-ITU-China SCCP Conversion Feature, 0006:A-36, 0006:A-43, 0006:A-44, 0006:A-45, 0006:A-46
Activating the Eagle OA&M IP Security Enhancements Controlled Feature procedure, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103
Activating the IGTTLS Feature, 0006:A-3
ACTIVE, 4307:3-7
Active device state does not permit database change, 4801:2-675
Active MASP
LNP forced simplex mode, 4593:3-110
Active MASP has become isolated, 4593:3-101
ACTIVE not available for type-enttype combination, 4801:2-116
Active OAM database is incoherent, 4801:2-421
Active OAM must be equipped with E586 hardware, 4801:2-603
Active TDM in unknown upgrade mode, 4801:2-575
Active/Standby
ELAP relation to LSMS connection, 4307:2-10
ELAP roles, 4307:2-5
ELAP switchover, 4307:2-5
Active/Stby GPL versions are not compatible, 4801:2-697
act-lpo, 4800:5-21
ACTNAME already exists in GWS Action Set Table, 4801:2-651
ACTNAME and ACTID cannot both be specified, 4801:2-652
ACTNAME specified must exist in the GWS Stop Action Set table, 4801:2-645
act-oap-config, 4800:5-23
act-oap-config parameters
performance impact, 0002:A-27, 4601:6-114
act-slk, 4800:5-26
act-upgrade, 4800:8-2
act-user, 4800:5-28
Add Authorized PDBA Client IP, 4307:3-105
Add button, 0008:2-1, 0008:2-16, 0008:2-18, 0008:2-22, 0008:2-60
Retrieve Tables, 0008:2-56
Add External NTP Server, 4307:5-26
Add Group screen, 4307:3-99
Add User screen, 4307:3-85
Adding
Command to the Selected Commands Box, 0008:2-60
Multiple Commands to the Selected Commands Box, 0008:2-61
Range of Commands to the Selected Commands Box, 0008:2-61
STP Configuration Record, 0008:2-18, 0008:2-48
adding
card, 0002:4-102, 4804:3-4, 4804:C-31
cluster point code, 4804:2-113
destination point code, 4804:2-162
linkset, 4804:3-5, 4804:3-16
point code, 4804:3-4
remote loopback points, 4804:3-206, 4804:3-212
route, 4804:3-145
shelf, 0002:4-93, 4804:3-3
signaling link, 4804:3-4, 4804:3-5, 4804:3-122, 4804:C-37

user, 0002:4-21
Adding a Blocked DPC Screen, 0005:8-8, 4803:5-42
Adding a Blocked OPC Screen, 0005:11-8, 4803:5-89
Adding a Card, 4802:2-3
Adding a Cluster Point Code, 4803:2-2, 4803:2-12
Adding a Concerned Signaling Point Code, 0006:2-69
Adding a Destination Point Code, 4803:2-18
Adding a DSM, 0007:2-20
Adding a Gateway Linkset, 4803:5-117
Adding a Global Title Translation, 0006:3-17
Adding a GLS Card, 0005:2-46
Adding a GSM MAP Screening Entry, 0004:5-81
Adding a GTT Selector, 0006:4-12
Adding a GTT Set, 0006:4-3
Adding a Mapped SS7 Message Translation Type, 0006:2-61
Adding a Mated Application, 4803:4-2, 4803:6-2
Adding a Route, 4803:3-36
Adding a Screen Set, 0005:13-3
Adding a TCP/IP Data Link, 0004:3-31
Adding a TCP/IP Node, 0004:3-40
Adding a Translation Type, 0006:3-3
Adding ACG Manual Initiated Controls, 4802:4-21
Adding an ACG Node Overload Control Level, 4802:4-13
Adding an Allowed Affected Point Code Screen, 0005:3-4, 4803:5-3
Adding an Allowed Called Party Address Screen, 0005:4-5, 4803:5-8
Adding an Allowed Calling Party Address Screen, 0005:6-6, 4803:5-22
Adding an Allowed DPC Screen, 0005:9-8, 4803:5-56
Adding an Allowed ISUP Message Type Screen, 0005:15-9
Adding an Allowed OPC Screen, 0005:12-8, 4803:5-102
Adding an Allowed SIO Screen, 0005:10-9, 4803:5-71
Adding an Allowed Translation Type Screen, 0005:5-4, 4803:5-16
Adding an Application Socket, 0003:3-195
Adding an IP Host, 0003:3-156
Adding an SCCP Card, 0006:2-48
Adding an SS7 Linkset, 4803:3-2
Adding an SS7 Signaling Link, 4803:3-24
Adding an STP Configuration Record
FTRA 1.0, 0008:2-18, 0008:2-19, 0008:2-20, 0008:2-21, 0008:2-22
FTRA 2.0, 0008:2-18, 0008:2-19, 0008:2-20, 0008:2-21, 0008:2-22
Adding an X.25 Gateway Destination, 0004:2-32
Adding an X.25 Linkset, 0004:2-47
Adding an X.25 Route, 0004:2-101
Adding an X.25 Signaling Link, 0004:2-76
Adding Global Title Address Information, 0006:4-26, 4803:6-10
Adding Security Parameters, 4307:5-7
Additional Integrated Sentinel Support (Release 28.2), 4318:2-25
address
default router, 4307:5-19
netmask, 4307:5-19
Address (MPCx) of mate subsystem must be a full PC, 4801:2-374
Address (PCx) of primary subsystem must be a full PC, 4801:2-374
address mapping

X.25/SS7 Gateway Feature (Eagle 20.0), 4318:5-175
address, Tekelec Technical Services e-mail, 4625:1-15
addresses, IP
see IP addresses
ADDTBLCNV and DELTBLCNV cannot be specified together, 4801:2-890
ADJ DPC, 4593:1-17
ADJ required if MPC/MSSN is given or MULT=DOM or SHR, 4801:2-167
Adjacent Destination Point Code, 4593:1-17
Adjacent Point Code, 4593:1-17
ADMHIPRI - LNP Administration Priority, 4802:3-165
administering point codes
ANSI/ITU MTP Gateway (20.0), 4318:2-37
Administrable SLTMs (20.0), 4318:2-27
administration
Enhanced Bulk Download (25.0), 4318:2-146
EOAP, 1021:8-12
High Speed Master Timing (26.0), 4318:3-59
Nested Cluster Routing (EAGLE 26.0), 4318:4-154
Temporary Alarm Inhibiting and Offline Functions (EAGLE 25.0), 4318:5-119
Administration Manuals, 4601:1-14, 4626:1-13
administration of User IDs and passwords, 4800:4-17
admonishments, documentation, 4307:1-7
Advanced Intelligent Network, 4593:1-17
Advantages, 4318:3-13
advantages
G-Flex C7 Relay (26.3), 4318:3-13
affected commands
Flexible Point Code Formatting (26.0), 4318:3-7
SEAS Enhancements (EAGLE 26.0), 4318:5-61
Aging, 4307:3-112
AI, 4593:1-17
AIN, 4802:3-30
AIN Interval Index, 4802:1-12
AINF Applique (21.0), 4318:2-27
AINTVL, 4802:1-12, 4802:4-3, 4802:4-5, 4802:4-21, 4802:4-22, 4802:4-24, 4802:4-25, 4802:4-28, 4802:4-29, 4802:4-31, 4802:4-32, 4802:4-33
AIPADDR parameter
chg-oap-config, 0002:A-25, 4601:6-112
air filter
part number, 2969:B-3
replace, 2969:7-16
air filter, changing, 4593:2-32
Air filters, 2969:7-2
air management card, 4601:5-63
air supply grille, removing, 4593:2-32
airflow indicator arrows, 4593:2-33
Alarm, 4593:1-17
Alarm 1, 4593:6-4
Alarm 2, 4593:6-4
alarm board (FAP), 4593:2-6
alarm cable installation, 4601:5-86
alarm card, breaker panel

FRU, 4593:6-114
replacement procedure, 4593:6-121
alarm card, MPS Server
description, 1021:6-11, 4625:4-28
replacement procedure, 4593:6-127
Alarm cleared by deleting card, 4593:3-507
Alarm cleared by deleting route, 4593:3-509
Alarm cleared by deleting SLK, 4593:3-508
Alarm cleared for GPL, 4593:3-98
Alarm cleared running non-activated GPL, 4593:3-100
Alarm Clearing Procedures, 4593:3-56
alarm conditions, FAP, 4593:2-7
alarm connectors, 4625:3-26
alarm data strings
contents, 4307:4-3
list using rept-stat-mps command, 4307:4-11
Alarm Enhancements (26.0), 4318:2-27
Alarm in Fuse panel, 4593:3-164
alarm LED, 2712:3-8, 4593:6-3
Alarm LEDs, 4307:3-8
alarm LEDs, 2712:3-8
Alarm LEDs on the Fuse and Alarm Panel (FAP), 4593:3-7
alarm levels, 4800:4-3
alarm system functionality
Temporary Alarm Inhibiting and Offline Functions (EAGLE 25.0), 4318:5-115
Alarm View Window, 4307:3-8
Alarms
Card, 4593:F-3
Clock (Holdover Clock), 4593:F-7
Clock System, 4593:F-7
Customer Defined Trouble (CDT), 4593:F-6
DCM, 4593:F-8
DLK, 4593:F-8
DPC System, 4593:F-10
DSM, 4593:F-11
E1 Port, 4593:F-11
EIR, 4593:F-12
EMAP, 4593:F-12
EMAP (NDC), 4593:F-12
EROUTE, 4593:F-13
Fuse, 4593:F-13
GLS, 4593:F-14
GPL, 4593:F-14
HS Clock System, 4593:F-14
IMT Bus, 4593:F-16
IMT System, 4593:F-16
INP System, 4593:F-16
IP TPS System, 4593:F-17
IP7, 4593:F-17
Linkset, 4593:F-18
LNP System, 4593:F-18
LSMS Connection, 4593:F-18

LSMS System, 4593:F-19
MCPM, 4593:F-19
MEAS System, 4593:F-19
MPS (ELAP/EPAP), 4593:F-20
MPS Alarm Support, 4593:F-20
NDC System, 4593:F-21
routers, 4626:A-17
SCCP System, 4593:F-21
SEAS OAP, 4593:F-22
SEAS System, 4593:F-22
SEAS X25, 4593:F-22
Security Log, 4593:F-23
Security System, 4593:F-23
SLK, 4593:F-24
STPLAN, 4593:F-26
System, 4593:F-26
System GPL, 4593:F-27
T1, 4593:F-27
TAS, 4626:A-20
Terminal, 4593:F-28
X-LIST, 4593:F-28
alarms
4000 Routesets (23.0), 4318:2-7
48 Million Numbers (27.0), 4318:2-14
alarm priorities, 4307:4-4
categories, 4307:4-14
clearing alarm, 4307:4-15
DSM/ELAP in rept-stat-trbl report, 4307:4-12
DSM-ELAP Link status, 4307:4-16
Eagle Application Support for E1 (26.3), 4318:2-106
ELAP application, 4307:4-14
ELAP-DSM UAMs, 4307:4-16
Enhanced Bulk Download (25.0), 4318:2-144
Enhanced GPL Management (25.0), 4318:2-152
EOAP, 0002:A-37, 0002:A-65, 4601:6-124, 4601:6-139
Garrett Magnum Hubs, 4626:A-16
Group Ticket Voucher (23.0), 4318:3-37
GSM MAP Screening (26.1), 4318:3-45
IP Connection Available/Unavailable, 4307:4-16
MPS Available alarm, 4307:4-15
MPS platform, 4307:4-14
MPS platform and ELAP application, 4307:4-15
MPS Server LEDs, 4625:4-32
MTP Restart (EAGLE 21.0), 4318:4-129
multiple alarm conditions, 4307:4-4
rept-stat-mps command to list data strings, 4307:4-11
RTDB Audit, 4307:4-16
Telect Breaker Panel, 4626:A-14
totals in rept-stat-alm report, 4307:4-4, 4307:4-13
Variable Length GTT (Eagle 26.1), 4318:5-166
Weighted SCP Load Balancing (Eagle 27.2), 4318:5-170
Alarms appearing on the system terminal screen, 4593:3-9

Alarms on Application Cards, 4593:3-9
Alarms Reference and User's Manual, 4625:1-13, 4626:1-15
alarms, critical, 4593:2-7
alarms, FAP, 4593:2-8
alarms, fuse, 4593:2-8
alarms, major, 4593:2-7
alarms, minor, 4593:2-7
ALIAS, 4802:3-30, 4802:3-31, 4802:3-32, 4802:3-33, 4802:3-37, 4802:3-41, 4802:3-42, 4802:3-45, 4802:3-48, 4802:3-49, 4802:3-52, 4802:3-87, 4802:3-96, 4802:3-117, 4802:3-125, 4802:3-131, 4802:3-138, 4802:3-149, 4802:3-155, 4802:3-176, 4802:3-180
Alias already in use, 4801:2-189
Alias defined as a destination point code, 4801:2-128
Alias defined as translation type, 4801:2-190
Alias DPCs cannot be a member of a Network or Cluster, 4801:2-380
Alias is not assigned to SERV, 4801:2-501
Alias not assigned to translation name, 4801:2-190
Alias not assigned to translation type, 4801:2-191
Alias not defined, 4801:2-129
Alias PC table is full, 4801:2-887
Alias PCs are not valid for cluster destinations, 4801:2-369
Alias PCs exceed Max allowed for Feature Quantity, 4801:2-878
Alias type matches DPC type, 4801:2-130
Aligning Signaling Links in a fully Restarting Node
MTP Restart (EAGLE 21.0), 4318:4-128
All ASPs with OPEN=YES in AS must use same UAPS, 4801:2-797
ALL cannot be specified with a subsystem, 4801:2-188
All cards on shelf must be unequipped, 4801:2-79
All clocks have failed, 4593:3-209
All entered point code elements must be C if any are C, 4801:2-199
All high speed clocks have failed, 4593:3-296
All IMT System level alarms cleared, 4593:3-194
All links in linkset must have same IPLIML2 setting, 4801:2-536
All links of LSN must use same error correction method, 4801:2-40
All new PC parms must be null if NI, ZONE, MSA or NPC = C, 4801:2-221
All OAP terminals are removed, 4593:3-471
ALL only qualifier allowed with given card type, 4801:2-81
All SEAS UAL sessions unavailable, 4593:3-445
All signaling links serviced by the E1 must be deactivated, 4801:2-805
All signaling links serviced by the T1 must be deactivated, 4801:2-321
All signaling links serviced by this E1/T1 must be deleted, 4801:2-810
All STC Networks Available, 4593:3-573
ALL=YES cannot be specified with a point code, 4801:2-184
ALL=YES must be specified to delete all SSNs for a PC, 4801:2-175
ALL=YES must be specified to delete the entire group, 4801:2-174
alloc-mem, 4800:5-29
Allow a Mated Application to Work as Primary-Secondary and Secondary-Primary (22.0), 4318:2-28
Allow rejected
terminal is not equipped, 4801:2-183
Allowed Affected Destination Field, 0005:2-2
Allowed Affected Destination Field Screen (22.0), 4318:2-31
command, 4318:2-32
Allowed Affected Point Code, 0005:2-2

Allowed Called Party Address, 0005:2-2
Allowed Calling Party Address, 0005:2-2
Allowed CDPA Screen on SCCP Management Format ID (22.0), 4318:2-34
Allowed Destination Point Code, 0005:2-2
Allowed ISUP Message Type, 0005:2-2
Allowed ISUP Message Type Screen Configuration, 0005:15-1
Allowed Originating Point Code, 0005:2-2
Allowed Signaling Information Octet, 0005:2-2
Allowed Translation Type, 0005:2-2
allowing
    DSM, 4751:8-3
    mated application subsystem, 4751:8-4
ALM, 4593:1-17
ALPHA+NUM+PUNC must not be greater than 12, 4801:2-332
Already in nodal isolation, 4801:2-426
Already logged on, 4801:2-12
Alternate bus must be IS-NR, 4801:2-445
Alternate Command Keywords (20.0), 4318:2-34
alternate point code, 4804:2-2
alw, 0003:3-209
alw-card command, 0008:2-43
alw-imt, 4800:5-34
alw-map-ss, 4800:5-35
alw-map-ss command, 4751:8-4
alw-slk, 4800:5-35
alw-trm, 4800:5-37
AMA, 4593:1-17, 4802:1-12
AMA Call Type, 4802:1-12
AMA Feature ID, 4802:1-12
AMA Service Logic ID, 4802:1-12
AMACTYPE, 4802:1-12, 4802:3-169, 4802:3-171
AMAFEATID, 4802:1-12, 4802:3-169, 4802:3-171
AMASLPID, 4802:1-12, 4802:3-169, 4802:3-171
Amem single bit error report, 4593:3-712
American National Standards Institut, 4593:1-17
American Wire Gage, 4601:4-9
An ACTNAME must be specified, 4801:2-652
An invalid option or argument was specified in the SSH client on the Eagle - Error code 660, 0008:2-111
An MIC of TYPE=ALL already exists, 4801:2-453
An MIC with the same service and digits already exists, 4801:2-454
An unexpected packet type was received from the SFTP / SSHD server - Error code 671, 0008:2-112
An unsupported cipher type was used in the SSH client on the Eagle - Error code 647, 0008:2-109
An unsupported escape character was used in the SSH client on the Eagle - Error code 646, 0008:2-109
An unsupported MAC type was used in the SSH client on the Eagle - Error code 648, 0008:2-110
ANAME parameter
    chg-oap-config, 0002:A-25, 4601:6-112
anchor and frame, 4601:3-15
anchor assembly
    for raised floor with support channel, 2969:4-14
    for raised floor with support channel and spring nut, 2969:4-17
    raised floor over concrete, 2969:4-10

slab floor, 2969:4-7
anchor bolt, 4601:3-22
anchor frame
for raised floor with support channel, 2969:4-13
for raised floor with support channel and spring nut, 2969:4-16
to concrete under raised floor, 2969:4-10
to slab floor, 2969:4-6
anchor holes, in raised floor, 2969:4-5
AND, 4802:1-12
AND parameter must be 6 or 10, 4801:2-457
ANMASK parameter
chg-oap-config, 0002:A-25, 4601:6-112
ANSI, 4593:1-17
ANSI Capability Point Code, 4802:1-13
ANSI G-Flex Support at 1700 TPS per DCM (Release 30.3), 4318:2-35
ANSI PC is identical to ANSI CPC, 4801:2-69
ANSI PC parameters are invalid for ITU cards, 4801:2-569
ANSI Point Code, 4802:1-16, 4802:3-85, 4802:3-102, 4802:3-116, 4802:3-130, 4802:3-137, 4802:3-154
ANSI site id not defined, 4801:2-315
ANSI/ITU MTP Gateway (20.0), 4318:2-35
administering point codes, 4318:2-37
changed commands, 4318:2-40
level 3 MSU discrimination, 4318:2-35
local link congestion, 4318:2-37
MSU routing, 4318:2-36
remote link congestion, 4318:2-38
ANSI/ITU point code type mismatch, 4801:2-741
ANSI/ITU SCCP and TCAP Conversion (22.2), 4318:2-39
ANSI/ITU SCCP and TCAP Conversion (24.0), 4318:2-40
changed command, 4318:2-41
ANSI-ITU SCCP Conversion, 4802:2-3, 4802:2-4
ANSI-ITU-China SCCP Conversion, 0006:1-2, 0006:2-3, 0006:2-6, 0006:2-7, 0006:2-16, 0006:2-17, 0006:2-30, 0006:2-33, 0006:2-40, 0006:2-43, 0006:2-44, 0006:2-47, 0006:2-48, 0006:2-49, 0006:2-70, 0006:2-72, 0006:2-83, 0006:2-87, 0006:2-93, 0006:2-118, 0006:2-124, 0006:2-160, 0006:2-161, 0006:2-169, 0006:2-170, 0006:2-177, 0006:2-179, 0006:2-191, 0006:2-192, 0006:3-2, 0006:3-21, 0006:3-23, 0006:3-29, 0006:3-33, 0006:3-54, 0006:3-55, 0006:3-56, 0006:3-59, 0006:3-63, 0006:4-2, 0006:4-27, 0006:4-30, 0006:4-34, 0006:4-38, 0006:4-53, 0006:4-56, 0006:4-59, 0006:4-62, 0006:A-36, 0006:A-37, 0006:A-38, 0006:A-39, 0006:A-41, 0006:A-42
options
changing, 0006:2-191, 0006:2-193
ANSI-ITU-China SCCP Conversion Feature
Activating, 0006:A-36, 0006:A-43, 0006:A-44, 0006:A-45, 0006:A-46
AP, 4593:1-17
APC, 4593:1-17
APC cannot be of a different domain than previous, 4801:2-254
APC cannot be ref. by an X.25 route with LC2NM=YES, 4801:2-280
APC not defined as destination point code, 4801:2-130
APC/SAPC type and group code must match DPC, 4801:2-634
APC/SAPC with specified group code already exists for linkset, 4801:2-835
Appendix A, LEDs, 4601:1-12, 4626:1-13
Appendix B, Connectors, 4601:1-12, 4626:1-13
Appendix C, Cables, 4601:1-12, 4626:1-13

Appendix D, Power Cords to Peripherals, 4601:1-12, 4626:1-13
APPL, 4318:4-85, 4593:1-17, 4802:1-13, 4802:2-19, 4802:3-57, 4802:3-58, 4802:3-63, 4802:3-64, 4802:3-65, 4802:3-66, 4802:3-67, 4802:3-68, 4802:3-71, 4802:3-73, 4802:3-74, 4802:3-90, 4802:3-106, 4802:3-121, 4802:3-133, 4802:3-144, 4802:3-160
appl, 0003:3-4, 0004:2-11
APPL is invalid for report or entity, 4801:2-308
APPL is invalid for specified PERIOD, 4801:2-309
APPL not found in APPLDEFN table on fixed hard disk, 4801:2-668
APPL or LOC parameter must be specified, 4801:2-309
APPL parameter must be specified with CONVERTNET action, 4801:2-670
APPL parameter valid only with CONVERTNET action, 4801:2-679
APPL=ALL can only be selected when SERIAL=YES is specified, 4801:2-697
Application, 4593:1-17
application alarms, ELAP, 4307:4-14
Application already assigned, 4801:2-492
Application Communication Module, 1021:3-9, 4601:5-21, 4625:2-12
Application Communication Module (ACM), 4625:3-19
application communication module (ACM), 4625:3-93
Application Communications Modul, 4593:1-17
Application Communications Module (ACM) measurements, 4593:4-49
Application Communications Modules (ACMs), 4625:3-20
Application Interface (AINF), 4625:3-68
Application Processor, 4593:1-17
Application Processor (AP), 4625:3-62
Application self recovery, 4593:1-14
Application Server, 4593:1-17
Application Server Process, 4593:1-17
Application Service Module, 1021:3-10, 4625:2-14
Application Service Module (ASM), 4625:3-87
application service module (ASM), 4625:3-18
Application Service Module (ASM) measurements, 4593:4-48
Application Services Module, 4593:1-17
Application Sockets on Port B Not Allowed, 4801:2-813
Application Subsystem, 1021:3-7, 4625:2-8
Application Trouble Handler, 4593:1-17
Application type not in LNP database, 4801:2-493
application, detecting problems, 2712:3-8
Application, FTRA
    exiting, 0008:2-4, 0008:2-12
    starting, 0008:2-4
    using, 0008:2-4
Applications, 1021:3-20, 0003:2-3, 0003:2-4
applications
    Types of Routing Strategies Available, 4318:4-167
Application-Specific Integrated Circuits, 4625:4-26
appliques
    4-port DS0 monitor, 4625:B-6
    4-port DSCS monitor, 4625:B-8
    4-port E1 monitor, 4625:B-4
    4-port T1 monitor, 4625:B-2
    4-port V.35 monitor, 4625:B-7
architecture, MPS Server I/O, 4625:4-27

Area Code, 4802:1-16, 4802:4-2
area code
LNP—Automatic Call Gapping (Release 22.0), 4318:4-54
Argument definition error, bad argument type, 4801:2-21
Argument frame overflow, 4801:2-4
AROUTER parameter
chg-oap-config, 0002:A-25, 4601:6-112
arp, 4800:9-2
arrow key operations, terminal, 4800:4-12
AS, 4593:1-17
AS Available, 4593:3-365
AS cannot be deleted while assigned to a routing key, 4801:2-816
AS Restricted, 4593:3-366
AS table is full, 4801:2-829
AS Unavailable, 4593:3-364
AS Unrestricted, 4593:3-367
ASi, 4593:1-17
ASi (Application Specific Interface), 4593:1-17
ASi 4000 SCP, 4625:2-24, 4625:4-3
ASi 4000 Service Control Point, 4625:1-8
ASL8 is only valid for ANSI link sets, 4801:2-366
aslog, 4800:9-5
ASM, 4593:1-17, 4601:2-2, 4601:A-5
ASM with GLS, 4593:1-17
ASM with SCCP, 4593:1-17
ASM, TDM, and MCPM upgrade procedures, 4601:5-28
ASM/TSM-GLS card replacement, 4593:A-38, 4601:5-32
ASM/TSM-SCCP card replacement, 4593:A-34, 4601:5-28
ASM-GLS, 4593:1-17
ASM-SCCP, 4593:1-17
ASM-SCCP card replacement, 4593:A-40
ASP, 4593:1-17
ASP adapter type does not match AS adapter type, 4801:2-820
ASP already in use, 4801:2-819
ASP is still assigned to an AS, 4801:2-815
ASP not supported by specified association's adapter type, 4801:2-592
ASP table is full, 4801:2-816
asplog, 4800:9-6
Assistance
Tekelec Technical Services, 0008:2-3, 0008:2-4, 0008:2-46, 0008:2-103, 0008:2-104, 0008:2-105, 0008:2-106, 0008:2-107, 0008:2-108, 0008:2-109, 0008:2-110, 0008:2-111, 0008:2-112, 0008:2-113, 0008:2-114, 0008:2-115, 0008:2-116, 0008:2-117, 0008:2-118
UK, 0008:2-3
USA, 0008:2-3
Associated State for Maintenance, 4593:1-17
Association connection parameters must be unique, 4801:2-822
Association must have OPEN=NO to change UAPS, 4801:2-797
Association name already exists, 4801:2-823
Association name not found, 4801:2-826
assocrtt, 4800:9-10
assumptions/limitations
Enhanced GTT (26.0), 4318:2-155

assynchronous maintenance modem
Embedded OAP (24.0), 4318:2-137
AST, 4593:1-17
AST possible values, 4800:A-3
Asynchronous IO is not supported on IPSM, SSH client error - Error code 664, 0008:2-111
Asynchronous Transfer Mode, 4593:1-17
At least one MCP card must be IS-NR, 4801:2-661
At least one MCPM card must be configured in system, 4801:2-306
At least one Non-Key parm that is to be changed is required, 4801:2-841
At least one of TIMER, PARM, SRCSET must be entered, 4801:2-691
At least one optional MRGT# parameter must be specified, 4801:2-529
At least one optional parameter is required, 4801:2-46
At least one other optional parameter is required, 4801:2-867
At least one parameter must be changed, 4801:2-35
At least one parameter must be changed(NSNP, NSNAI, NSERV), 4801:2-604
At least TTA, TTI must be specified for a direction of BOTH, 4801:2-801
At least two ports must have security admin authority, 4801:2-339
At most two linksets can be assigned same cost, 4801:2-141
ATH, 4593:1-17
ATM, 4593:1-17, 4593:A-25, 4601:5-81, 4601:5-82, 4601:A-6, 4626:A-3
ATM Adaptation Layer, 4593:1-17
ATM Adaptation Layer Type 5, 4593:1-17
ATM Applique, 4593:1-17
ATM high speed signaling link parameter set
changing, 4804:C-55
ATM LIM, 4601:5-81
ATMANSI, 0004:6-7, 0004:6-21
ATMITU, 0004:6-7, 0004:6-21
attach fan assembly to frame rail, 4593:5-96, 4593:A-81
AUD, 4802:1-13, 4802:3-165, 4802:3-169, 4802:3-171
aud-data, 4800:5-38
Audible Alarms, 4593:3-4
audit
aborting, 4751:5-15
log file, 4751:5-19
managing, 4751:5-9
overview, 4751:5-2
restrictions, 4751:5-6
stages, 4751:5-8
audit and reconcile
from the LSMS GUI, 4751:5-9
options, 4751:2-8, 4751:5-7
stages, 4751:5-8
Audit of LNP backup database completed, 4593:3-753
Audit of LNP database completed, 4593:3-813
Audit, RTDB
alarms, 4307:4-16
auditing OAP database
Support LSMS Disaster Recovery (EAGLE 23.1), 4318:5-108
Auditing the Eagle via High-Speed Audit
Support for LSMS Audit Enhancements (EAGLE 26.1), 4318:5-97
auditing the OAP database

Eagle Initiated OAP User Interface (24.0), 4318:2-117
Aurora serial card driver, 4593:5-23
Authority Violation, 4801:2-3
Authorized IP menu, 4307:3-104, 4307:3-105, 4307:3-106, 4307:3-107, 4307:3-108
Authorized IPs, 4307:3-104
auto-configuration, 4307:5-27
AUTOEXEC.BAT, 0008:2-7
Automatic Call Gapping, 1021:4-5, 4318:4-54, 4593:1-17, 4802:1-12, 4802:4-1, 4802:4-2
Automatic Destination Field Screening, 0005:13-2
Automatic Message Accounting, 4593:1-17, 4802:1-12
automatic resynchronization, 4751:2-4, 4751:2-7, 4751:4-2
availability, 2712:2-19
Availability reports, 4593:4-43
Awaiting LSMS bulk download, 4593:3-967
AWG, 4601:4-9
AXi 1000, 4625:4-19
AXi 2000, 4625:4-19
AXi Application Frame 1, 4625:4-14
AXi Network Frame, 4625:4-14
AXi Systems, 4625:1-10

B

B side, 4601:4-23
back-end check, 4307:3-11
backing up changes, chg-db, 0002:A-47, 0002:A-73, 4601:6-133, 4601:6-148
backplane board (FAP), 4593:2-6
backplane monitor, 4593:5-21
backplane, control shelf, 4601:B-19
backplane, extension shelf, 4601:B-25, 4626:B-9
backpower protection, 4593:2-9
backup
Database Management Command Functions (20.0), 4318:2-82
backup DSM network, 4307:2-7
Backup IP Address - FTRA 2.0, 0008:2-20
Backup IP Address - FTRA 2.0 or greater, 0008:2-16
Backup IP Address Field - FTRA 2.0 or greater, 0008:2-16, 0008:2-20
Backup LNP database corrupted, 4593:3-528
Backup LNP database has been corrected, 4593:3-538
Backup LNP database is inconsistent, 4593:3-534
Backup PDB menu item, 4593:6-18
backup procedures, 0002:2-32
backup database on fixed disk, 0002:2-32
backup database to removable cartridge, 0002:2-35
Backup Provisioning Network Interface (Release 29.0), 4318:2-41
Backup RTDB, 4307:3-38
backups
EPAP PDB database, 4593:6-18, 4593:6-19
frequency for PDB, 4593:6-18, 4593:6-19
procedure for file system, 4593:6-42, 4593:6-52, 4593:6-56
speed for file system, 4593:6-17
tape capacity for file system, 4593:6-17

tape drive for, 4593:6-17
Bad forwarding ports were specified in the SSH client on the Eagle - Error code 657, 0008:2-110
Bad forwarding was used in the SSH client on the Eagle - Error code 656, 0008:2-110
banner format, output, 4800:4-15
banner header section, 4307:3-2
Banner Information Messages, 4307:3-117
banner section, 4307:3-6
banner, displaying error text, 2712:3-10
Batch Mode, 4307:3-60
BC should be less than 2000, 4801:2-314
BEI must be YES if APC domain is X.25, 4801:2-253
Billing Functions, 1021:4-8
BIPADDR parameter
chg-oap-config, 0002:A-25, 4601:6-112
bit rotation
ITU SLS enhancement, 4804:3-28
BITS, 4601:5-85, 4601:5-88, 4601:5-104, 4601:5-115
BITS cable installation, 4601:5-88, 4601:5-104
BITS clock connectors, 4601:B-9
BITS connectors, 4625:3-27
black and white flag, 4601:4-23
blk-slk, 4800:5-42
BLM Applied to LSMS BLM-Based Operations - Removing, 0007:2-29
BLM must be provisioned and IS-NR for an upload, 4801:2-708
BLM/DCM card must be provisioned and IS-NR for bulk download, 4801:2-707
BLM/DCM LNP database must be coherent to do a bulk download, 4801:2-707
Blocked Destination Point Code, 0005:2-2
Blocked Originating Point Code, 0005:2-2
blown fuse, 4593:2-8
blue flag, 4601:4-23
BNAME parameter
chg-oap-config, 0002:A-25, 4601:6-112
BNMASK parameter
chg-oap-config, 0002:A-25, 4601:6-112
boot disk, 4593:5-13
Both DR and DA parameters cannot be entered, 4801:2-81
Both LIMIT and INTRVL must be specified for UIM threshold., 4801:2-670
Both LOC and PORT must be specified, 4801:2-119
Both NP and NAI must be specified if either is present, 4801:2-834
Both NPV and NAIV must be either * or numbers, 4801:2-821
Both OAM cards must be of the same type to update database, 4801:2-461
Both OAM cards must be of type GPSM-II to enable TSCSYNC, 4801:2-334
Both WRNLN and WRNTX must be specified, 4801:2-337
Box
Command List, 0008:2-54, 0008:2-56, 0008:2-58, 0008:2-62, 0008:2-63
Secure Connection - FTRA 2.0 or greater, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-43, 0008:2-48, 0008:2-49
Selected Commands, 0008:2-54, 0008:2-56, 0008:2-60, 0008:2-62, 0008:2-63, 0008:2-64
Adding a Command, 0008:2-60
Adding a Range of Commands, 0008:2-61
Adding Multiple Commands, 0008:2-61
Command Removed, 0008:2-63

Command Selected to be Removed, 0008:2-62
Stop on error
Update Tables, 0008:2-81
Stop on error, Update Tables window, 0008:2-78, 0008:2-81, 0008:2-90, 0008:2-91, 0008:2-92
Use STP and FTP UserNames, Passwords for all STPs, 0008:2-17, 0008:2-18, 0008:2-36, 0008:2-37, 0008:2-38
box, 8-Port Connector
see 8-Port Connector Box
BPDCM GPL, 0004:6-24
BPS must be 1544000 for LIMATM cards, 4801:2-556
BPS must be 4800,9600,19200,56000,64000,1544000 or 2048000, 4801:2-52
BPS must be 56000 for all ports on Multi Port LIM, 4801:2-423
BPS must be 56000 or 64000, 4801:2-38, 4801:2-39
brace bolts, 4601:3-6
brackets, 4601:5-69
Breaker, 4626:A-14
breaker panel
alarm card FRU, 4593:6-114
alarm card replacement procedure, 4593:6-121
FRU, 2712:5-2, 4593:6-114
replacement procedure, 2712:5-5, 4593:6-119
Breaker panels, 4625:4-52
Bridge Amplifier, 4625:B-9
broadcast transfer messages
network routing, 4804:2-148
Broken pipe - Error code 32, 0008:2-118
BROUTER parameter
chg-oap-config, 0002:A-25, 4601:6-112
Browse button
FTP Server Configuration Menu, 0008:2-50, 0008:2-51
Update Tables, 0008:2-78, 0008:2-79
browser connectivity, 0007:2-64, 4307:5-30
browser window, 4307:3-5
browsers, 4307:5-3
Building Integrated Timing System, 4601:5-85, 4601:5-88
Building Integrated Timing System (BITS), 4601:1-6, 4625:3-27, 4625:3-64, 4625:3-68
building requirements, 4625:6-3
Bulk download from LSMS to the BLM card must have completed, 4801:2-708
Bulk Load
Disabling, 0007:2-149
Error Messages, 0007:2-108
Log File, 0007:2-106
Procedure, 0007:2-97
bulk load
aborting, 4751:6-12
from LSMS, 4751:2-5
log file, 4751:6-11, 4751:6-20
managing, 4751:6-4
options, 4751:2-10
overview, 4751:2-9
bus, 4601:4-8
busy icon, 4307:3-6

Button
Add, 0008:2-1, 0008:2-16, 0008:2-18, 0008:2-22, 0008:2-56, 0008:2-60
Browse
FTP Server Configuration Menu, 0008:2-50, 0008:2-51
Update Tables window, 0008:2-78, 0008:2-79
Cancel, 0008:2-34
Print window
Retrieve Tables Log, 0008:2-71
System Log, 0008:2-99
Update Tables Log, 0008:2-95
Save window
Retrieve Tables Log, 0008:2-72
System Log, 0008:2-101
Update Tables Log, 0008:2-96
Select Starting Directory window, 0008:2-52
Select window, 0008:2-79, 0008:2-80
Close, 0008:2-16, 0008:2-25, 0008:2-27, 0008:2-50
Retrieve Tables, 0008:2-56
Update Tables, 0008:2-78
Commit, Update Validation Complete window, 0008:2-83, 0008:2-84
Delete, 0008:2-16, 0008:2-25, 0008:2-27, 0008:2-40
Edit, Update Validation Complete window, 0008:2-83, 0008:2-84, 0008:2-85, 0008:2-86
Load, 0008:2-56, 0008:2-64, 0008:2-73
Modify, 0008:2-16, 0008:2-36, 0008:2-37
Refresh, 0008:2-16, 0008:2-23, 0008:2-25, 0008:2-27, 0008:2-29, 0008:2-39
Remove, 0008:2-56, 0008:2-62
Reset, 0008:2-56, 0008:2-63
Retrieve, 0008:2-54, 0008:2-56, 0008:2-64, 0008:2-65
Retrieve from Local Database, 0008:2-54, 0008:2-56, 0008:2-64
Retrieve from STP, 0008:2-54, 0008:2-56, 0008:2-65
Save
Retrieve Tables Log, 0008:2-72
System Log, 0008:2-101
Update Tables Log, 0008:2-96
Select, 0008:2-16, 0008:2-25, 0008:2-27
Select Starting Directory window, 0008:2-52
Select window, 0008:2-79, 0008:2-80
Set, 0008:2-53
FTP Server Configuration Menu, 0008:2-50
Stop, Update Validation Complete window, 0008:2-83
Store, 0008:2-56, 0008:2-63, 0008:2-73
Test, 0008:2-16, 0008:2-25, 0008:2-27, 0008:2-31
Validate, 0008:2-78, 0008:2-82
Update Tables window, 0008:2-77
BYTE, WORD or DWORD must be entered, 4801:2-82

C

C value not allowed, 4801:2-222
cable
CD-ROM, 4593:5-11
hard drive card, 4593:5-11

Cable Arm, 4601:4-21
Cable Connector, 4601:5-12
cable ends, 4601:4-11
Cable Holes, 4601:3-15
cable holes, in raised floor, 2969:4-5
cable list, 4601:6-11
cable management arms, 2969:3-9
Cable Rack Mounting Kit, 4601:3-16, 4601:3-18
Cable Running List, 4601:5-107
Cables, 4601:4-20
cables
    labeling, 4601:2-8, 4601:C-4, 4626:C-4
Cables, Adapter for -03 and -04 backplanes, 4601:C-49, 4626:C-50
cabling
    additional NE server, 2969:5-14
    frame, 2969:4-20
calculate number of high-speed signaling links in system, 0003:3-88, 0004:2-81, 4804:D-8
calculate number of low-speed signaling links in system, 0003:3-88, 0004:2-81, 4804:D-8
calling name conversion facility, 4802:2-37
Calling Name Conversion Facility (CNCF) (23.1), 4318:2-42, 4318:2-55
    conversion of GN to PIP, 4318:2-49
    conversion of PIP to GN, 4318:2-48
    Gateway Screening Change commands, 4318:2-56
    Gateway Screening Enter commands, 4318:2-55
    Gateway Screening Retrieve commands, 4318:2-56
    Gateway Screening stop action commands, 4318:2-55
    limitations, 4318:2-44
    message conversion, 4318:2-50
    PIP and GN parameters, 4318:2-46
    rtrv-feat, 4318:2-42
    Unsolicited Information Messages, 4318:2-57
Can't switch existing Pfx / Sfx, use RDMOD to reset, 4801:2-843
Can't switch existing Pfx / Sfx, use RMGTT to reset, 4801:2-854
Can’t send after socket shutdown - Error code 58, 0008:2-117
canc-cmd, 4800:5-45
canc-echo, 4800:5-48
cancel
    rtrv-dstn, 0003:3-45, 4804:3-33, 4804:3-148, 4804:3-235
    rtrv-ls, 0003:3-45, 4804:3-33, 4804:3-148, 4804:3-235
    rtrv-rte, 4804:3-148
Cancel button, 0008:2-34
    Print window
        Retrieve Tables Log, 0008:2-71
        System Log, 0008:2-99
        Update Tables Log window, 0008:2-95
    Save window
        Retrieve Tables Log, 0008:2-72
        System Log, 0008:2-101
        Update Tables Log, 0008:2-96
    Select Starting Directory window, 0008:2-52
    Select window, 0008:2-79, 0008:2-80
Cancelling rtrv and rept-stat Commands

Miscellaneous Command Adjustments (26.0), 4318:4-116
canc-lnp-dpcer, 4800:5-49
CANC-LNP-DPCER command is already in progress, 4801:2-644
canc-lnp-tnrpt, 4800:5-50
canc-lpo, 4800:5-50
canc-slk, 4800:5-52
canc-user, 4800:5-53
Cannot add NP and NAI to an entry where GTIXLAT is 22, 4801:2-840
Cannot allow terminal configured as type=none, 4801:2-57
Cannot assign ITU and ANSI LHOST to the same AS, 4801:2-309
Cannot assign LHOST to the B interface, 4801:2-732
Cannot assign LHOST / ALHOST to the B interface, 4801:2-824
Cannot change existing STP True PC if in MAP table, 4801:2-537
Cannot change if existing connection type is PVC, 4801:2-297
Cannot change routing key and attribute values, 4801:2-803
Cannot change terminal authority while user is logged on, 4801:2-338
Cannot change the RC parameter with the ENT command, 4801:2-462
Cannot change TYPE as system requires 2 SA enabled terminals, 4801:2-339
Cannot change TYPE as system requires two SA enabled terminals, 4801:2-344
Cannot decrease PVC below a logical channel in use, 4801:2-300
Cannot decrease SVC below number of SVCs already in use, 4801:2-300
Cannot delete last route to DPC ref. by an X.25 route, 4801:2-279
Cannot delete last route to DPC ref. by redirect func, 4801:2-279
Cannot delete last route to DPC ref. In MAP table, 4801:2-278, 4801:2-878
Cannot delete NPANXX that is in split mode, 4801:2-518
Cannot delete STP self ID if a DPC of same type is defined, 4801:2-73
Cannot delete the last route to a DPC referenced in the MRN table, 4801:2-440
Cannot echo to OAP terminal, 4801:2-733
Cannot enter a wildcard with XLAT=2, Use XLAT=4 for wildcard, 4801:2-887
Cannot enter MTPRSE with SLSOCBIT, SLSRSB parameters, 4801:2-735
Cannot enter MULTCC if STP Options DefCC is NONE, 4801:2-656
Cannot enter the same PC more than once, 4801:2-425
Cannot execute command until table initialization complete, 4801:2-859
Cannot inhibit IMT bus - alternate bus is in abnormal stat, 4801:2-322
Cannot leave a solitary PC in group, 4801:2-424
Cannot provision EMDC card with 15 min coll feature on, 4801:2-660
Cannot read DB Stat Table (<database>, <disk>, <MASP status>), 4801:2-419
Cannot set DefCC to none if a GSM Options MULTCC is defined, 4801:2-638
Cannot specify ALL=YES when command given, 4801:2-7
Cannot specify LC without LOC, 4801:2-298
Cannot specify LSN parameter with ALL=YES, 4801:2-132
Cannot turn on feature with EMDC provisioned, 4801:2-659
Cannot use NEXT if preceding RTRV-LOG command used TYPE=ALL, 4801:2-855
Capability Point Code, 4802:1-13
Capability point code already defined as a route DPC, 4801:2-71
Capability point code is already being used, 4801:2-70
Capability point code matches STP's own point code, 4801:2-71
Capability Point Code Type, 4802:1-13
Capacity, 4601:4-24
Capacity of TDM(s) / TSM(s) insufficient to support request, 4801:2-648
capacity status reporting, DSM memory, 4307:4-7
capacity, file system backup tape, 4593:6-17

Capture Log Files, 4307:3-63
Card
    GPSM-II, 0008:2-3
    IPSM, 0008:2-3
    MCAP, 0008:2-3
    TDM, 0008:2-3
card
    adding, 4804:3-4
    FRU, breaker panel alarm, 4593:6-114
    MPS Server alarm, 1021:6-11, 4625:4-28
    Quad FastEthernet Network Interface, 4625:4-30
    replacement procedure, breaker panel alarm, 4593:6-121
    replacement procedure, MPS Server alarm, 4593:6-127
    replacement procedure, Quad FastEthernet Network Interface, 4593:6-122
    SAI/P, 4625:4-30, 4625:4-43
        replacement procedure, 4593:6-127
Card backup database has been corrected, 4593:3-128
Card backup database is corrupted, 4593:3-130
Card backup database is inconsistent, 4593:3-129
Card database has been corrected, 4593:3-120
Card database is corrupted, 4593:3-125
Card database is inconsistent, 4593:3-121
Card DB is stable, 4593:3-597
Card DB load timeout, check GLS card, 4593:3-596
Card does not exist or is not a LIM (LOC), 4801:2-118
Card does not exist or is not an LPE, 4801:2-107
Card does not support command driven loopback, 4801:2-871
Card does not support more than 2 Links, 4801:2-424
Card GPL of link does not match domain of linkset APC, 4801:2-251
Card GPL type IPGWI requires a link set with IPGWAPC=YES, 4801:2-739
Card GPL type SS7IPGW requires IPGWAPC=YES, 4801:2-717
Card has been reloaded, 4593:3-178
Card has reset, 4593:3-90
Card having link in linkset must first be inhibited, 4801:2-862
Card having link in mate linkset must first be inhibited, 4801:2-863
Card is isolated from the system, 4593:3-107
Card is not a SS7GX25 card, 4801:2-301
Card is not an ACMENET card, 4801:2-259
Card is not in service, 4801:2-160
Card is not running approved GPL, 4593:3-91
Card is present, 4593:3-109
Card is running non-activated GPL, 4593:3-99
Card location already equipped, 4801:2-28
Card location is unequipped, 4801:2-29
Card location must be 1113 or 1115, or APPL=E(OAM), 4801:2-95
Card location must be 1114 or 1116, 4801:2-96
Card location must be 1114, 1116, or 1117, 4801:2-97
Card location not assigned a TCP/IP link, 4801:2-260
Card location specified must be an OAM card, 4801:2-540
Card location specified must be an SCCP card, 4801:2-439
Card location specified must be the standby, 4801:2-58
Card must be inhibited before executing this command, 4801:2-259

Card not using config. SCTP csum method, 4593:3-384
Card Replacement Procedures, 4593:A-1
Card slot location out of range, 4801:2-54
Card slot reserved by system, 4801:2-55
Card successfully loaded with data, 4593:3-210
card type
    signaling link, 4804:3-4
Card type of LIMCH does not support E1PORT = 2, 4801:2-806
Card type of LIMCH does not support T1PORT = 2, 4801:2-324
Card(s) cannot warm restart - FORCE parameter required, 4800:6-367, 4801:2-727
Card(s) not in-service normal - FORCE parameter required, 4801:2-678
Card's A/B interface IP Networks must be unique, 4801:2-607
Carrier Identification Code, 4802:1-13
categories, alarm, 4307:4-14
Cautionary Information, 4601:3-2
Cccmmd table must be accessible, 4801:2-256
Cccnames table must be accessible, 4801:2-257
CCGT and NGTI are mutually exclusive, 4801:2-854
CCGT must be NO when PC is the STP's PC or CPC, 4801:2-622
CCGT must be NO when RI is set to GT, 4801:2-624
CCNC already exists, 4801:2-602
CCNC and MCCMNC parameters must be entered together, 4801:2-601
CCNC cannot be NONE, 4801:2-599
CCP - Charge Number and Charge Party Station, 4802:3-166
CCS7ITU, 0004:6-7, 0004:6-20
CD/DVD, 2969:7-2
CdPA SSN, 4318:5-20
CDPNNAI and SNAI must be specified together, 4801:2-98
CDPNNAI doesn't exist in INPOPTS Table, 4801:2-92
CDPNPFX doesn't exist in INPOPTS Table, 4801:2-90
CDPNPFX must be specified, 4801:2-43
CDPNPFX must not be NONE, 4801:2-88
CD-ROM, 4593:5-9, 4593:5-10, 4625:3-149, 4625:3-151
    description, 4625:4-29
    replacement procedure, 4593:6-123
    specification, 4625:4-27
CD-ROM drive, 0008:2-2, 0008:2-5, 0008:2-7
CD-ROM jumper settings, 4593:5-10
CDSR does not exist in the database, 4801:2-882
CDSR must be specified when NCDSR is specified, 4801:2-883
cdu, 4800:8-8
CDU for DSM (26.05), 4318:2-60
    CDU Port, 4318:2-60
    enhanced commands, 4318:2-61
    new commands, 4318:2-61
    Ping Test, 4318:2-60
    Quick Test, 4318:2-60
CDU Port
    CDU for DSM (26.05), 4318:2-60
central office ground, 2969:6-9, 4601:4-18
CFG parameter
    chg-oap-config, 0002:A-25, 4601:6-112

CGPA entry can't be provisioned, 4801:2-879
CGPA entry is referred by CDPA entries, 4801:2-752
CGSR doesn’t exist for specified OPNAME, 4801:2-754
CGSR must be specified when CDSR is specified, 4801:2-793
CGSR or CDSR shouldn't be specified when SADDR is specified, 4801:2-794
chalk line, 2969:4-4
Change Allowed menu, 4307:3-32
Change Enabled, 4307:3-29
Change Enabled menu, 4307:3-25, 4307:3-26
change features, chg-feat
DCM, 4593:3-390, 4593:5-99, 4593:A-84, 4601:6-74
Change Password, 4307:5-22
Change Password menu, 4307:3-112, 4307:5-22
Change Simplex Mode, 4307:3-20
Change Status, 4307:3-18
changed commands
48 Million Numbers (27.0), 4318:2-14
5 Minute Linkset Data (25.0), 4318:2-15
500 SS7 Links (21.0), 4318:2-19
5000 Routes (26.1), 4318:2-20
5-8 Bit Sequencing Assurance (24.0), 4318:2-17
ANSI/ITU MTP Gateway (20.0), 4318:2-40
ANSI/ITU SCCP and TCAP Conversion (24.0), 4318:2-41
Enhanced Bulk Download (25.0), 4318:2-150
Enhanced GPL Management (25.0), 4318:2-151
Enhanced GTT (26.0), 4318:2-154
Flash Memory Management (23.0), 4318:3-5
Flexible Point Code Formatting (26.0), 4318:3-7
G-Port MNP (26.2), 4318:3-21
GSM MAP Screening (26.1), 4318:3-44
GTT by TT Measurements and GR-376 Enhancements (26.0), 4318:3-51
IP7 Transport Feature (26.1), 4318:3-114
ITU MTP Restart (26.0), 4318:3-152
ITU SLS Enhancements (26.0), 4318:3-154
ITU-TFR Procedure (26.1), 4318:3-156
Large System (27.2), 4318:4-2
LNP AIN Query Enhancement (26.0), 4318:4-47
LRN Table Increase (26.1), 4318:4-92
Miscellaneous Command Adjustments (26.0), 4318:4-115
Multiple LFS Tests (EAGLE 26.0), 4318:4-135
Multi-Port LIM (EAGLE 27.1), 4318:4-145
National Spare Network Indicator Support (EAGLE 22.2), 4318:4-148
National Spare Network Indicator Support (EAGLE 24.0), 4318:4-150
Nested Cluster Routing (EAGLE 26.0), 4318:4-165
Number Pooling (EAGLE 24.0), 4318:4-191
Number Pooling/Efficient Data Representation (EDR) (EAGLE 26.1), 4318:4-196
PCS 1900 LNP Query (EAGLE 26.0), 4318:5-6
Selective Alarm Inhibiting (EAGLE 22.0), 4318:5-75
Simplifying BIP (Board ID PROM) for Eagle STP Boards (EAGLE 23.1), 4318:5-79
STPLAN with Default Router (EAGLE 23.0), 4318:5-90
Temporary Alarm Inhibiting and Offline Functions (EAGLE 25.0), 4318:5-123
TSM Warm Restart and Incremental Loading (EAGLE 26.0), 4318:5-142

Types of Routing Strategies Available, 4318:4-174
Variable Length GTT (Eagle 26.1), 4318:5-165
changed commnands
Group Ticket Voucher for SCCP Cards (27.0), 4318:3-40
changed event log command
Thresholding of UIM Messages (EAGLE 25.0), 4318:5-127
changed files
LNP Measurements Enhancements (25.0), 4318:4-51
Changeover and Changeback Procedure for Processor Outage and LIN (21.0), 4318:2-64
changing
ATM high speed signaling link parameter set, 4804:C-55
cluster point code
attributes, 4804:2-132
destination point code, 4804:2-197
level 2 timers, 4804:3-187
level 3 timers, 4804:3-189
linkset, 4804:3-69
password, 0002:4-48
remote loopback points, 4804:3-215
route, 4804:3-178
security defaults, 0002:4-7
security log characteristics, 0002:4-17
self identification of system, 4804:2-64
signaling link test message, 4804:3-194
terminal characteristics, 0002:4-51
terminal command class assignment, 0002:4-73
user information, 0002:4-35
Changing a Blocked DPC Screen, 0005:8-24, 4803:5-52
Changing a Blocked OPC Screen, 0005:11-24, 4803:5-97
Changing a DCM Parameter Set, 0003:3-227
Changing a Destination Point Code, 4803:2-24
Changing a Gateway Linkset, 4803:5-130
Changing a Global Title Translation, 0006:3-50, 4803:4-18
Changing a GSM MAP Screening Entry, 0004:5-114
Changing a GSM MAP Screening Operation Code, 0004:5-71
Changing a GTT Selector, 0006:4-21
Changing a Linkset, 0004:2-65, 4803:3-13
Changing a Mapped SS7 Message Translation Type, 0006:2-67
Changing a Mated Application, 0006:2-117, 4803:4-8, 4803:6-8
Changing a Route, 4803:3-38
Changing a Screen Set, 0005:13-15
Changing an ACG Node Overload Control Level, 4802:4-19
Changing an Allowed Affected Point Code Screen, 0005:3-15, 4803:5-7
Changing an Allowed Called Party Address Screen, 0005:4-19, 4803:5-14
Changing an Allowed Calling Party Address Screen, 0005:6-21, 4803:5-32
Changing an Allowed DPC Screen, 0005:9-24, 4803:5-66
Changing an Allowed ISUP Message Type Screen, 0005:15-20
Changing an Allowed OPC Screen, 0005:12-23, 4803:5-111
Changing an Allowed SIO Screen, 0005:10-23, 4803:5-82
Changing an Allowed Translation Type Screen, 0005:5-14, 4803:5-20
Changing an Application Socket, 0003:3-209
Changing an IP Card, 0003:3-41, 0003:3-176

Changing an IP Link, 0003:3-161
Changing an IP7 Secure Gateway Option, 0003:3-41
Changing an MRN Group, 0006:2-152
Changing an X.25 Gateway Destination, 0004:2-41
Changing an X.25 Route, 0004:2-119
Changing Global Title Address Information, 0006:4-53, 4803:6-16
changing options
ANSI-ITU-China SCCP Conversion, 0006:2-191, 0006:2-193
SCCP Class 1 Sequencing, 0006:2-20, 0006:2-194, 0006:2-195, 0006:2-196, 0006:2-197
changing passwords, 2969:6-14
Changing the DPC Quantity, 4804:2-21
Changing the Self Identification of the Eagle, 4803:2-16
Changing the X.25 Signaling Link Parameters, 0004:2-134
Channel Card, 4601:5-119
Chapter 1, Introduction, 4601:1-12, 4626:1-13
Chapter 2, General Installation Information, 4601:1-12
Chapter 3, Frames and Shelves, 4601:1-12
Chapter 4, Fuses and Breakers, 4601:1-12
Chapter 4, Sentinel describes the Expanded Services Platform, 4626:1-13
Chapter 5, Eagle STP/IP7 Secure Gateway Assemblies, 4601:1-12
Chapter 7, OAP/EOAP, 4601:1-12
Chapter 8, Integrated Sentinel, 4626:1-13
Charge Number and Charge Party Station - CCP, 4802:3-166
Chassis Dimensions and weight, 2969:3-9
checklist, post-installation, 2969:6-11
checksums and alarms
EOAP, 0002:A-29, 4601:6-115
chg-acg-mic, 4800:5-54
chg-acg-noc, 4800:5-56
chg-appl-rtkey, 4800:5-57
chg-as, 4800:5-69
chg-asp, 4800:5-70
chg-assoc, 4800:5-66
chg-atm-lps, 4800:5-76
chg-attr-seculog, 4800:5-79
chg-bip-fld, 4800:8-14
chg-bip-rec, 4800:8-15
chg-cmdclass, 4800:5-82
chg-ctrl-feat, 4800:5-83
chg-db, 4800:5-87, 4803:2-2, 4803:2-7, 4803:2-12, 4803:2-16, 4803:2-18, 4803:2-21, 4803:2-24, 4803:3-2, 4803:3-11, 4803:3-13, 4803:3-24, 4803:3-33, 4803:3-36, 4803:3-38, 4803:4-2, 4803:4-5, 4803:4-8, 4803:4-10, 4803:4-17, 4803:4-18, 4803:5-3, 4803:5-5, 4803:5-7, 4803:5-8, 4803:5-11, 4803:5-14, 4803:5-16, 4803:5-19, 4803:5-20, 4803:5-22, 4803:5-26, 4803:5-32, 4803:5-35, 4803:5-37, 4803:5-41, 4803:5-42, 4803:5-47, 4803:5-52, 4803:5-56, 4803:5-62, 4803:5-66, 4803:5-71, 4803:5-79, 4803:5-82, 4803:5-89, 4803:5-95, 4803:5-97, 4803:5-102, 4803:5-109, 4803:5-111, 4803:5-117, 4803:5-129, 4803:5-130, 4803:5-141, 4803:5-142, 4803:5-143, 4803:5-145, 4803:5-148, 4803:6-2, 4803:6-5, 4803:6-8, 4803:6-10, 4803:6-15, 4803:6-16
chg-db:action=backup:dest=fixed, 0002:2-33, 4593:3-84
chg-db:action=backup:dest=remove, 0002:2-36, 0002:2-70
chg-db:action=repair, 0002:2-51
chg-db:action=restore:src=fixed, 0002:2-40
chg-db:action=restore:src=remove, 0002:2-44, 0002:2-75
chg-dcmps, 4800:5-85

chg-dstn, 4800:5-98
chg-e1, 4800:5-107
chg-feat, 4800:5-110, 4803:2-2, 4803:2-7, 4803:2-12, 4803:3-4, 4803:3-16, 4803:5-3, 4803:5-8, 4803:5-16, 4803:5-22, 4803:5-35, 4803:5-42, 4803:5-56, 4803:5-71, 4803:5-89, 4803:5-102, 4803:5-117, 4803:5-143
chg-ftp-serv, 0002:4-164, 0002:4-165, 4800:5-120
chg-ftp-serv Eagle command, 0008:2-50
chg-gpl, 4800:5-121
chg-gsmmap-scrn, 4800:5-125
chg-gsmopts, 4800:5-129
chg-gsms-opcode, 4800:5-138
chg-gta, 4800:5-141
chg-gtcnv, 4800:5-148
chg-gtt, 4800:5-151
chg-gttsel, 4800:5-158
chg-gtw-stp, 4800:5-160
chg-gws-actset, 4800:5-161
chg-gws-redirect, 4800:5-164
chg-inpopts, 4800:5-167
chg-ip-card, 0002:4-153, 4800:5-171
chg-ip-lnk, 0002:4-153, 0002:4-173, 4800:5-173
chg-isupvar-attrib, 4800:5-176
chg-l2t, 4800:5-181
chg-l3t, 4800:5-183
chg-lbp, 4800:5-188
chg-lnp-lrn, 4800:5-191
chg-lnp-npanxx, 4800:5-193
chg-lnpopts, 4800:5-203
chg-lnp-refnum, 4800:8-16
chg-lnp-serv, 4800:5-196
chg-lnp-sub, 4800:5-198
chg-lnp-ttmap, 4800:5-201
chg-ls, 4800:5-206
chg-m2pa-tset, 4800:5-218
chg-map, 4800:5-220
chg-meas, 4800:5-226
chg-measopts, 4800:5-228
chg-mrn, 4800:5-236
chg-netopts, 4800:5-243
chg-oap-config, 4800:5-244
chg-pid, 4800:5-249
CHG-PID not allowed while in upgrade mode, 4801:2-416
chg-pstn-pres, 4800:5-250
chg-rte, 4800:5-251
chg-sccpopts command, 0006:2-194, 0006:2-195
chg-scr-blkdpc, 4800:5-260
chg-scr-blkopc, 4800:5-267
chg-scr-cdpa, 4800:5-273
chg-scr-cgpa, 4800:5-279
chg-scr-destfld, 4800:5-285
chg-scr-isup, 4800:5-296
chg-scr-opc, 4800:5-298
chg-scr-sio, 4800:5-304

chg-secu-dflt, 4800:5-313
chg-secu-trm, 4800:5-317
chg-sg-opts, 4800:5-321
chg-sid, 4800:5-327
chg-slt, 4800:5-334
chg-ss7opts command, 4804:3-88, 4804:3-233, 4804:3-237
chg-stpopts, 4800:5-341, 4803:2-2
chg-stpopts command, 0006:2-20, 0006:2-191, 0006:2-194, 0006:2-195
chg-t1, 4800:5-355
chg-tbl, 4800:8-18
chg-th-sccp, 4800:5-356
chg-trm, 4800:5-357
chg-trm command, 0008:2-46
chg-trm:trm=:all=no Eagle command, 0008:2-65
chg-ttmap, 4800:5-367
chg-uaps, 4800:5-368
chg-user, 4800:5-372
chg-x25-dstn, 4800:5-376
chg-x25-rte, 4800:5-378
chg-x25-slk, 4800:5-379
China-ANSI-ITU SCCP Conversion, 0006:1-2, 0006:2-3, 0006:2-6, 0006:2-7, 0006:2-16, 0006:2-17, 0006:2-30, 0006:2-33, 0006:2-40, 0006:2-43, 0006:2-44, 0006:2-47, 0006:2-48, 0006:2-49, 0006:2-70, 0006:2-72, 0006:2-83, 0006:2-87, 0006:2-93, 0006:2-118, 0006:2-124, 0006:2-160, 0006:2-161, 0006:2-169, 0006:2-170, 0006:2-177, 0006:2-179, 0006:2-191, 0006:2-192, 0006:3-2, 0006:3-21, 0006:3-23, 0006:3-29, 0006:3-33, 0006:3-54, 0006:3-55, 0006:3-56, 0006:3-59, 0006:3-63, 0006:4-2, 0006:4-27, 0006:4-30, 0006:4-34, 0006:4-38, 0006:4-53, 0006:4-56, 0006:4-59, 0006:4-62, 0006:A-36, 0006:A-37, 0006:A-38, 0006:A-39, 0006:A-41, 0006:A-42
chk-unref-ent, 4800:5-382
chmod command, 0008:2-50, 0008:2-51
CI, 4601:2-2, 4601:A-7, 4626:1-32
CIC, 4802:1-13
CIC bit
  ITU SLS enhancement, 4804:3-29
CIC outside of valid range for SI, 4801:2-742
CIC Range overlaps an existing routing key, 4801:2-700
cice, 0003:3-233, 0003:3-242, 0003:3-243, 0003:3-250, 0003:3-262
cics, 0003:3-233, 0003:3-242, 0003:3-250, 0003:3-262
CICS must be less than or equal to CICE, 4801:2-700
circular route detection
  configuring, 4804:3-196
circular routing
  network routing, 4804:2-149
CLASS, 4802:3-30
Class name is not an existing command class name, 4801:2-126
Class name is not an existing configurable command class, 4801:2-106
CLASS TT required before OAP update, 4801:2-672
class1seq parameter, 0006:2-20, 0006:2-194
  SCCP Class 1 Sequencing, 0006:2-20, 0006:2-194, 0006:2-195
classes, command, 4800:4-17
Cleaning Printer, 4593:2-34
Cleaning the OAP Fan Filter, 4593:2-32
Clear To Send (CTS), 4625:3-67

Clearing a Temporary FAK alarm, 0002:B-37, 0003:6-7, 0006:A-12
clearing alarm, 4307:4-15
Clearing an FAK alarm, 0007:2-161
Clearing the display
Connectivity Test Log, 0008:2-32, 0008:2-33
Retrieve Tables Log, 0008:2-68, 0008:2-69
System Log, 0008:2-97, 0008:2-98
Update Tables Log, 0008:2-92, 0008:2-93
C-link linkset, 0003:3-7, 4804:3-5
CLLI, 4318:1-8, 4802:1-13
CLLI cannot be specified without Point Code, 4801:2-36
CLLI is already being used by a route, 4801:2-70
CLLI is not identical to that of matching Destination, 4801:2-134
CLLI not defined in route table, 4801:2-131
CLLI used by STP, 4801:2-59
CLLI-based Names Enabled, 4593:4-9
CLOCK, 4601:5-110
Clock
HCMIM, 4625:3-115
clock, 4601:5-85, 4601:5-106, 4601:5-115
Clock A, 4625:3-32
Clock A for card failed, B normal, 4593:3-111
Clock A for card normal, 4593:3-117
Clock alarm(s) cleared, 4593:3-200
Clock B for card failed, A normal, 4593:3-113
Clock B for card normal, 4593:3-118
Clock Cable, 4601:5-104
clock cable, 4601:5-104
Clock Cable Diagram, 4601:5-102
clock cable installation, 4601:5-12
clock cables, 4601:5-101, 4601:5-112
clock connection cable
install, 4601:6-44, 4601:C-36
route, 4601:6-45
clock connectors, 4601:B-5, 4601:B-7, 4601:B-10, 4601:B-12
clock in / out cable
install, 4601:6-43
Clock selection corrected, 4593:3-519
Clock Supply Cables, 4601:5-88
Clock / Alarm, 4601:5-7
Clocks A and B for card failed, 4593:3-115
Clocks A and B for card normal, 4593:3-119
Clocks A and B TSCs are resynchronized, 4593:3-175
Close button
FTP Connection Configuration Menu, 0008:2-50
Retrieve Tables window, 0008:2-56
STP Connection Configuration Menu, 0008:2-16, 0008:2-25, 0008:2-27
Update Tables, 0008:2-78
Closing
Connectivity Test Log window, 0008:2-32, 0008:2-36
Retrieve Tables Log window, 0008:2-68, 0008:2-72
System Log window, 0008:2-97, 0008:2-101

Update Tables Log window, 0008:2-92, 0008:2-96
clr-disk-stats, 4800:8-20
clr-imt-stats, 4800:5-385
cluster destination point code, 4804:2-3
Cluster DPCs are only valid if the CRMD feature is ON, 4801:2-370
Cluster DPCs can't inherit A or E linkset types, 4801:2-877
cluster management
ITU network, 4804:2-97
cluster management when Cluster Routing feature is turned off
Cluster Routing and Management Diversity (21.0), 4318:2-69
cluster point code
adding, 4804:2-113
changing attributes, 4804:2-132
cluster routing
Cluster Routing and Management Diversity (21.0), 4318:2-68
Cluster Routing and Management Diversity feature, 4804:2-91, 4804:2-96
Cluster Routing and Management Diversity (21.0), 4318:2-65
cluster management when Cluster Routing feature is turned off, 4318:2-69
cluster routing, 4318:2-68
compatibility with ITU network and X.25 gateway, 4318:2-69
compatibility with non-cluster routing STPs, 4318:2-68
exception lists, 4318:2-65
Cluster Routing and Management Diversity feature, 4804:2-91
cluster routing, 4804:2-96
compatibility with non-cluster routing systems, 4804:2-96
diversity rules, 4804:2-97
example, 4804:2-100
when feature is turned off, 4804:2-97
CMD parameter is not a valid Eagle command, 4801:2-28
CNAM, 4802:3-30
CNAM TT required before OAP update, 4801:2-673
CNCF, 4802:2-37
Cnvrsn Discard
CGPA PC alias undefined, 4593:3-824
Invalid SCCP element len, 4593:3-829
SCCP MSU too large, 4593:3-822
Cnvrsn Discard - Invalid TCAP element, 4593:3-827
Cnvrsn Discard - Invalid TCAP element len, 4593:3-828
collect=on cannot be specified with 15 min coll operational, 4801:2-659
Combination of SS7 PC/SSNs exists in X.25 route table, 4801:2-294
Combination of X.25 addresses exists in X.25 route table, 4801:2-293
Combination of X.25 addresses not in X.25 route table, 4801:2-288
Combined total baud rate for all ports cannot exceed 168K, 4801:2-156
Comm. attributes cannot be entered for OAP terminal, 4801:2-349
Command
Eagle
alw-card, 0008:2-43
chg-ftp-serv, 0008:2-50
chg-trm, 0008:2-46
chg-trm:trm=:all=no, 0008:2-65
ent-ftp-serv, 0008:2-50
init-card, 0008:2-43, 0008:2-46, 0008:2-47

pass:loc=xxxx
cmd="netstat -p tcp", 0008:2-121
cmd="ping yy.yy.yy.yy", 0008:2-120
rst-card, 0008:2-43
rtrv, 0008:2-56, 0008:2-73, 0008:2-75
rtrv-card, 0008:2-3
rtrv-ctrl-feat, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103
rtrv-feat, 0008:2-54
rtrv-ftp-serv, 0008:2-116
rtrv-gta, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gtt, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gttsel, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gttset, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-ip-lnk, 0008:2-46, 0008:2-47
rtrv-secu-dflt, 0008:2-21
rtrv-trm, 0008:2-45, 0008:2-46, 0008:2-65
rtrv-tt, 0008:2-54, 0008:2-59, 0008:2-65
FTRA
ftra -c, 0008:2-73, 0008:2-75
Selecting, 0008:2-58
command
rtrv-oap-config, 0002:A-35, 0002:A-63, 4601:6-122, 4601:6-137
Command aborted
due to system error, 4801:2-258
Command Aborted messages, 4800:4-15
Command Accepted messages, 4800:4-14
Command action is out of phase with expected procedure, 4801:2-65
Command already in progress, 4801:2-170
Command cannot be executed on a Telnet terminal, 4801:2-879
Command cannot be executed on an MGMT terminal, 4801:2-459
Command cannot be executed on an OAP terminal, 4801:2-335
Command Class Management (Release 29.0), 4318:2-70
Command Class Management Controlled Feature
Activating, 0002:B-3
Deactivating, 0002:B-39
Command Class Management feature must be enabled, 4801:2-99
command classes, configuration of, 4800:4-17
Command Complete
Connectivity Test window, 0008:2-32
Retrieve Tables window, 0008:2-54, 0008:2-65, 0008:2-66
Update Tables window, 0008:2-83, 0008:2-84, 0008:2-87
Command Completed messages, 4800:4-14
Command Driven Loopback (CDL), 4593:3-79
Command driven loopback in progress, 4801:2-872
Command driven loopback not in progress, 4801:2-872
Command Executed messages, 4800:4-14
Command Failed messages, 4800:4-14
Command File
Editing, 0008:2-2, 0008:2-85
Editor window, 0008:2-83, 0008:2-85, 0008:2-86, 0008:2-87

File Menu, 0008:2-87

File Menu, 0008:2-87
Invalid Command, 0008:2-86
Field, Update Tables window, 0008:2-79, 0008:2-80, 0008:2-82
Selected, Update Tables window, 0008:2-79
Stop on error box checked, 0008:2-81
Sending to the Selected STP, 0008:2-84
Command files, sending to the Eagle, 0008:2-4
Command In progress, Cannot Close Window message, 0008:2-86
Command is not supported for IPLIM and SS7IPGW links, 4801:2-688
Command is not supported for SS7IPGW links, 4801:2-688
Command Line Interface, 0008:2-1, 0008:2-56, 0008:2-63, 0008:2-64, 0008:2-73
Automatic Start, 0008:2-75
Manual Start, 0008:2-73
UNIX, 0008:2-74
Windows, 0008:2-74
command line interface (lsmsclaa), LSMS, 4751:5-21
command line, connecting to, 2712:A-3
Command List
Box, 0008:2-54, 0008:2-56, 0008:2-58, 0008:2-62, 0008:2-63
Field
Retrieve Tables window, 0008:2-56
Update Tables window, 0008:2-78
Side, 0008:2-62
Command not allowed while in upgrade mode, 4801:2-534
Command Not Found, 4801:2-699
Command not supported for non-IPGWx linksets, 4801:2-660
Command not supported with current IPLIML2 setting, 4801:2-580
Command not valid for IPGWI, 4801:2-740
Command not valid for IPLIM, 4801:2-721
Command not valid for IPLIMI, 4801:2-731
Command not valid for SS7IPGW, 4801:2-722
Command Output Changes (22.0), 4318:2-72
command prompt
DOS, 0008:2-73
shell, 0008:2-73
Command Rejected Messages
description, 4801:2-2, 4801:3-2
Command Rejected messages, summary, 4800:4-14
Command Removed from the Selected Commands Box, 0008:2-63
Command Response messages, 4800:4-15
Command Response Timeout, freeing up scroll area, 4801:2-444
Command Selected to be Removed in the Selected Commands Box, 0008:2-62
Command will cause system clock outage – Use FORCE=YES, 4801:2-606
Commands
Eagle
EGTT
rtrv-gta, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gttsel, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gttset, 0008:2-54, 0008:2-59, 0008:2-65
GTT
rtrv-gtt, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-tt, 0008:2-54, 0008:2-59, 0008:2-65

Eagle STP, 0008:2-1, 0008:2-77, 0008:2-78
Menu, 0008:2-11
Menu window, 0008:2-56, 0008:2-63, 0008:2-78
Selecting a Range, 0008:2-59
Selecting Multiple, 0008:2-60
commands
about, 4800:4-9
Allowed Affected Destination Field Screen (22.0), 4318:2-32
alw-map-ss, 4751:8-4
command classes, 4800:4-17
duplicate parameters in, 4800:4-10
ELAP log viewer navigation, 4307:3-70
GR-376 Interface (26.0), 4318:3-28
inh-map-ss, 4751:8-4
keywords, 4800:4-9
Link Fault Sectionalization (21.0), 4318:4-17
LNP Measurements Enhancements (25.0), 4318:4-51
output banner format, 4800:4-15
parameters, 4800:4-9
reports and output message types generated by, 4800:4-14
rept-stat-alm, 4307:4-4, 4307:4-13
rept-stat-db, 4307:4-10
rept-stat-mps
description, 4307:4-10
report multiple alarm conditions, 4307:4-4
rept-stat-sccp, 4751:8-5
rept-stat-trbl, 4307:4-4, 4307:4-12
rmv-card, 4751:8-3
rst-card, 4751:8-3
Triggerless LNP (EAGLE 24.0), 4318:5-130
Commands Error Recovery Manual, 4601:1-14, 4626:1-13
Commands Manual, 4601:1-14, 4626:1-13
commands, action, 4800:4-9
commands, entering, 4800:4-9
commands, functions performed by, 4800:4-9
Commit button, Update Validation Complete window, 0008:2-83, 0008:2-84
Common Language Location Identifier, 4601:1-19, 4625:1-17, 4626:1-21, 4802:1-13
Common Language Location Identifier (CLLI), 4318:1-8
Communication errors, 4307:B-20
Communication Module (ACM), 4625:3-9
Communication Settings are not allowed on TELNET terminals, 4801:2-128
Communication Subsystem, 1021:3-5, 4625:2-6
Communications Processor (CP), 4625:3-63
communications processor (CP), 4625:3-97
compatibility with ITU network and X.25 gateway
Cluster Routing and Management Diversity (21.0), 4318:2-69
compatibility with non-cluster routing STPs
Cluster Routing and Management Diversity (21.0), 4318:2-68
complex network, 4804:3-7
Complexity, 4307:3-112
complexity checking, 4307:3-110
compliance, regulatory, 2969:2-4

component interaction scenario
Support for LSMS Audit Enhancements (EAGLE 26.1), 4318:5-98
Component Measurements, 4593:4-22
components
steps before you begin replacement, 4593:6-114
Components of OEM-Based Products, 4625:2-30
components, MPS
list of hardware, 1021:6-2
specifications, 1021:6-10
storage, 4625:4-27
composite clock, 4601:5-82
Compression is already enabled in the SSH client on the Eagle - Error code 665, 0008:2-111
Concerned node table for this group is full, 4801:2-171
Concerned Signaling Point Codes, 0006:2-40, 0006:2-44, 0006:3-2, 0006:4-2
concrete floor preparation, 4601:3-20
Concurrent Logins, 4307:3-111
Concurrent User Logins, 4307:3-111
conditions, multiple alarm, 4307:4-4
Config. SCTP csum method alarm cleared, 4593:3-385
Configuration
ELAP, 0007:2-46
ELAP 5.0, 0007:2-51
ELAP Software Overview, 0007:2-38
Menu - ELAP, 0007:2-50, 0007:2-51
Menu - ELAP 2.x, 0007:2-50
Procedure - ELAP, 0007:2-61
Procedure - ELAP 5.0, 0007:2-51
configuration
of command classes, 4800:4-17
of terminals and printers, 4800:4-3
Configuration and Initialization, 4307:5-9
Configuration data checksum alarm cleared, 4593:3-485
Configuration data checksum mismatch, 4593:3-482
Configuration Menu, 4307:5-14
configuration menu
Change Password, 4307:5-22
Configure DSM Networks, 4307:5-20
Configure ELAP Sync Network, 4307:5-19
Configure Provisioning Network, 4307:5-19
description, 4307:5-14
elapconfig login name, 4307:5-14
Exchange Secure Shell Keys, 4307:5-21
Select Time Zone, 4307:5-21
Configuration Menu Conventions, 4307:5-12
Configuration Procedure, 4307:5-27
configuration procedure, 0007:2-64, 4307:5-30
Configuration record, STP, 0008:2-14, 0008:2-15, 0008:2-16, 0008:2-18, 0008:2-23, 0008:2-25, 0008:2-27, 0008:2-28, 0008:2-29, 0008:2-30, 0008:2-31, 0008:2-36, 0008:2-37, 0008:2-38, 0008:2-39, 0008:2-40, 0008:2-42, 0008:2-43, 0008:2-48
FTRA 1.0, 0008:2-29
FTRA 2.0, 0008:2-29, 0008:2-30
Configuration record, STP - FTRA 1.0

Adding, 0008:2-18, 0008:2-19, 0008:2-20, 0008:2-21, 0008:2-22
Configuration record, STP - FTRA 2.0
Adding, 0008:2-18, 0008:2-19, 0008:2-20, 0008:2-21, 0008:2-22
configure
customer (provisioning) network IP addresses, 4307:5-19
customer (provisioning) network netmask, 4307:5-19
customer network default router address, 4307:5-19
DSM network IP addresses, 4307:5-20
ELAP Sync network IP addresses, 4307:5-19
remote dial-in serial port, 4307:2-9
Configure DSM Network menu, 0007:2-53, 4307:5-18, 4307:5-20
Configure DSM Networks, 4307:5-20
Configure ELAP Sync Network, 4307:5-19
Configure NTP Server, 4307:5-25
Configure Provisioning Network, 4307:5-19
Configure Provisioning Network menu, 4307:5-18
Configure Sync Network menu, 4307:5-19
configuring
circular route detection, 4804:3-196
destination tables, 4804:2-1
measurements terminal, 0002:4-134
restore device state option, 0002:4-192
secondary point codes, 4804:2-47
TFA/TFR pacing rate, 4804:3-200
UIM threshold, 0002:4-129
Configuring a Mate IPGWx Linkset, 0003:3-62
Configuring an IPGWx Linkset, 0003:3-41
Configuring for the CNCF Feature, 0005:14-4
Configuring for the DTA Feature, 0004:4-15
Configuring IP Retransmission Parameters, 0003:3-221
Configuring the DSM Ethernet Link to the MPS, 0007:2-31
Configuring the Eagle, 0008:2-3
Configuring the ELAP 5.0 Procedure, 0007:2-61
Configuring the ELAP Procedure, 0007:2-64
Configuring the Frequency of RST Messages on Low Priority Routes (22.0), 4318:2-73
Configuring the Restricted Linkset Option, 4804:3-233, 4804:3-238, 4804:3-239
Configuring Unauthorized Use Warning Message 22.0), 4318:2-75
Conflicting parameters specified, 4801:2-818
conflicts with existing entry, 4801:2-441
Congestion
Copy Function De-activated, 4593:3-581
Congestion Abatement Reporting (21.0), 4318:2-77
Connect to MMI Port, 4307:3-67
connecting to server command line, 2712:A-3
Connection
definition, 0004:2-5, 4318:5-176
connection
DSM to ELAP, 4307:2-7
ELAP Sync network, 4307:2-4, 4307:2-8
ELAP to DSM, 4307:2-4
existing ELAP to LSMS, 4307:2-11
initial ELAP to LSMS, 4307:2-10

LSMS to ELAP, 4307:2-5, 4307:2-10
primary LSMS to ELAP, 4307:2-10
provisioning (customer) network, 4307:2-9
remote Dialup PPP, 4307:2-9
status, ELAP-to-DSM, 4307:4-16
Connection determination, 0004:2-5
connection determination
X.25/SS7 Gateway Feature (Eagle 20.0), 4318:5-176
Connection failure due to network outage or the connection was lost due to a faulty SSHD/SFTP server or network - Error code 670, 0008:2-112
Connection not compatible with SLK IPLIML2 setting, 4801:2-577
Connectivity, 0003:2-20, 0003:2-21
connectivity, 0007:2-64, 4307:5-30
Connectivity Test - I procedure, 0008:2-119
Connectivity Test - II procedure, 0008:2-120
Connectivity Test Log, 0008:2-31, 0008:2-32, 0008:2-33, 0008:2-34, 0008:2-35
Clearing the Display, 0008:2-32, 0008:2-33
closing, 0008:2-32, 0008:2-36
File Menu, 0008:2-32
Print window, 0008:2-34
Printing, 0008:2-32, 0008:2-34
Save window, 0008:2-35
saved file confirmation window, 0008:2-35, 0008:2-36
saving to a file, 0008:2-32, 0008:2-35
window, 0008:2-31, 0008:2-32, 0008:2-33, 0008:2-34, 0008:2-35, 0008:2-36, 0008:2-44, 0008:2-47, 0008:2-48
errors, 0008:2-32
no errors, 0008:2-31
Connectivity Test Log window
File Menu, 0008:2-32, 0008:2-33
Connector Box, 8-Port
see 8-Port Connector Box
conn-imt, 4800:5-387
connmgr, 4800:9-12
Consistent Command Response Conversion (22.2), 4318:2-78
Consistent Command Response Conversion (24.0), 4318:2-79
continual memory validation, DSM daughterboard, 4307:4-7
continuous reload, DSM, 4307:2-18
Control Frame, 4601:4-35
Control frame, 4601:3-27
Control Frame (CF), 4625:3-4
control frame (CF), 4625:3-18
control shelf backplane, 4625:3-21
Controlled Feature
ANSI-ITU-China SCCP Conversion - Activating, 0006:A-36, 0006:A-43, 0006:A-44, 0006:A-45, 0006:A-46
IGTTLS - Activating, 0006:A-3
IGTTLS - Turning off, 0006:A-14
Large System # Links - Enabling, 0003:3-110, 0004:2-138, 4804:3-9
XGTT Table Expansion - Enabling, 0006:A-17
XMAP Table Expansion - Enabling, 0006:A-27
Controlled Feature Activation

15 Minute Measurements, 0002:B-26
Command Class Management, 0002:B-3
Eagle OAM IP Security Enhancements, 0002:B-12
IP User Interface, 0002:B-3
Network Security Enhancements, 0002:B-3
Controlled Feature Deactivation
Command Class Management, 0002:B-39
Eagle OAM IP Security Enhancements, 0002:B-39
IP User Interface, 0002:B-39
Network Security Enhancements, 0002:B-39
Controlled Feature is not enabled, 4801:2-581
controlled features
turn on and off, 4800:5-83
Conv to intl num - Dflt CC not found, 4593:3-888
Conv to intl num - Dflt MCC not found, 4593:3-890
Conv to intl num - Dflt MNC not found, 4593:3-891
Conv to intl num - Dflt NDC not found, 4593:3-889
Conversion Discard
Invalid SCCP msg type, 4593:3-823
conversion of GN to PIP
Calling Name Conversion Facility (CNCF) (23.1), 4318:2-49
Conversion of MGT to IMSI not possible, 4593:3-893
conversion of PIP to GN
Calling Name Conversion Facility (CNCF) (23.1), 4318:2-48
Converting ITU National Point Code Formats, 4800:A-10
Cooling Fan Alarm, 4593:6-9
Cooling fan failure, 4593:3-389
Cooling fan normal, 4593:3-391
Cooling Fans, 2712:3-13, 4593:6-7
copper-plated hardware, 4601:4-16
Copy
RTDB from Remote Mated NE Procedure, 0007:2-120
RTDB from the Mate ELAP Procedure, 0007:2-113
copy disk procedure, 0002:2-54
Copy Function Activated, 4593:3-582
copy GPL
Database Management Command Functions (20.0), 4318:2-83
copy measurements
Database Management Command Functions (20.0), 4318:2-83
COPY must be in ACT1, 4801:2-651
copy RTDB
from ELAP mate, 4751:3-3
from standby ELAP on mated network element, 4751:3-4
copy-disk, 4800:5-388
copy-fta, 4800:5-390
copy-gpl, 4800:5-392
Copying
One RTDB from Another RTDB, 0007:2-109
RTDB from ELAP on Remote Mated NE, 0007:2-110
RTDB from Mated ELAP, 0007:2-109
copying database from active to standby fixed disk, 0002:2-54
copy-meas, 4800:5-395

copyright information, 0008:2-102
copy-seculog, 4800:5-396
copy-tbl, 4800:8-20
corrected errors, 2712:3-11, 4593:6-5, 4593:6-28
Corrective Maintenance, 4593:1-3
Corrupted check bytes were detected on the SSH / SFTP client on the Eagle - Error code 675, 0008:2-113
Corrupted MAC on input was detected by the SSH / SFTP client on the Eagle - Error code 676, 0008:2-113
Corrupted pad on input was detected by the SSH / SFTP client on the Eagle - Error code 677, 0008:2-113
Corrupted RTDB Database Alarm, 4307:2-20
Corruption Cross Correction, 4307:2-21
Cost Factor on Routing (20.0), 4318:2-80
Could not access active fixed disk, 4801:2-356
Could not access removable disk, 4801:2-354, 4801:2-356
Could not access standby fixed disk, 4801:2-355
Could not block link for testing, 4801:2-326
could not locate adapter layer, 4801:2-816
CPC, 4802:1-13, 4804:2-65
CPCA, 4802:1-13, 4804:2-65
CPCI, 4802:1-13, 4804:2-65
CPCN, 4802:1-13, 4804:2-65
CPCTYPE, 4802:1-13, 4804:2-65
CPCTYPE cannot be specified with NCPC, 4801:2-515
CPCTYPE cannot be specified without CPC, 4801:2-514
CPCx has not been provisioned, 4801:2-378
CPCx must be ANSI if CPCTYPE equals LNP, 4801:2-517
CPCx must not be ANSI if CPCTYPE is INP or EIR, 4801:2-767
CPU
    module replacement procedure, 4593:6-123
    MPS Server specifications, 4625:4-27
CPUs, 4593:6-7
Craftsperson, 4318:3-123
Creating an EMS Configuration Component, 0007:2-81
Creating New Java Policy File, 4307:5-8
creation of UIMs
    Thresholding of UIM Messages (EAGLE 25.0), 4318:5-124
crimp, 4601:4-20
crimp the lugs, 4601:4-11
Crimping tool, 4601:4-13
crimping tool, 2969:6-2
CRITALMINH not set trying to inhibit critical alarms, 4801:2-573
Critical Alarm, 4593:3-3, 4625:3-5
critical alarms, 4593:2-7, 4800:4-3
Critical Application Failure(s), 4593:3-490
Critical customer trouble detected, 4593:3-145
Critical holdover clock trouble detected, 4593:3-150
Critical Platform Errors, 2712:4-2, 4593:6-28, 4593:6-29
Critical Platform Failure(s), 4593:3-489
critical problem, 4318:1-7, 4601:1-18, 4626:1-19
CRMD feature must be ON, 4801:2-246
cron, 0008:2-73, 0008:2-75, 0008:2-76

CRON FTRA Wrapper Script, 0008:2-76
crontab, 0008:2-76
Cross-Connect Panel, 4601:5-20
Cross-Reference Index, 4601:1-15, 4626:1-14
CSPC broadcast group already exists, 4801:2-168
CSPC broadcast group table is full, 4801:2-168
CSPC group cannot contain both PCN and PCN24 point codes, 4801:2-889
CSPC group does not exist, 4801:2-169
CSPC group network type does not match PC network type, 4801:2-184
CSV file format, 0008:2-1, 0008:2-54, 0008:2-56, 0008:2-64, 0008:2-73, 0008:2-75
Current actv OAM db is not supported for this upgrade, 4801:2-68
Current database not coherent, 4801:2-357
Current ITU-N site id must be disabled for this assignment, 4801:2-343
Current set of next elog entries have been overwritten, 4801:2-860
Current stdby OAM db is not supported for this upgrade, 4801:2-68
Current STP
  Selected, 0008:2-41
    FTRA 1.0, 0008:2-41
    FTRA 2.0, 0008:2-42
  Selected: field, 0008:2-39
  Selecting, 0008:2-4, 0008:2-40
customer (provisioning) network
  configure IP addresses, 4307:5-19
  description, 4307:2-9
Customer Assistance, 4800:1-6, 4801:1-10
Customer Care Center, 0007:2-4
Customer Contact Center, 4593:1-8
Customer Definable Alarms (20.0), 4318:2-80
Customer Documentation, 4801:1-3
Customer Service Report, 4625:1-17
Customer Service Report (CSR), 4318:1-8, 4601:1-19, 4626:1-21
Customer Service Request, 4318:1-7, 4601:1-18, 4625:1-15
customer support, 0002:1-6, 0003:1-7, 0004:1-8, 0005:1-8, 0006:1-6, 4803:1-9, 4804:1-6
  Tekelec Technical Services, 0002:1-7, 0003:1-7, 0004:1-8, 0006:1-7, 4751:1-11, 4802:1-8, 4803:1-9, 4804:1-7
Customer Support Center, 4307:1-7, 4593:1-8
Customer Support Centers, 4593:1-8
Customer trouble cleared, 4593:3-149
Customer trouble detected, 4593:3-148
CWMIN must be less than or equal 16384 for IPGW associations, 4801:2-534
Cyclic Redundancy Check (CRC), 4625:3-97

D

dact-alm-trns, 4800:6-2
dact-cdl, 4800:6-2
dact-cmd, 4800:6-3
dact-echo, 4800:6-5
dact-rstst, 4800:6-8
dact-slk, 4800:6-9
dact-user, 4800:6-10
Daily Availability Measurements, 4593:4-38

Daily availability reports, 4593:4-38
Daily LNP System Wide Measurements, 4593:4-65
Daily Maintenance Measurements, 4593:4-51
Daily measurement collection in progress, 4801:2-110
Daily Procedures, 4593:2-15
Data audit already in progress, 4801:2-96
DATA can only be specified with P486, 4801:2-304
Data Collection Applications Manual, 4625:1-12, 4626:1-15
Data Collection Details, 4593:4-11
Data Collection Subsystem, Collection and Delivery document, 4625:1-13, 4626:1-16
Data Communication Equipment (DCE), 4625:3-67
Data Communications Module, 4625:3-19
Data missing for <parm> parameter (C<col>), 4801:2-544
data strings, alarm
    see alarm data strings, 4307:4-3
Data Terminal Equipment (DTE), 4625:3-27, 4625:3-67
Data Terminal Ready (DTR), 4625:3-67
database
    copying from active to standby fixed disk, 0002:2-54
    repairing, 0002:2-48
    restoring from backup partition of fixed disk, 0002:2-39
    verifying, 0002:2-10
Database action ended - FAIL, 4593:3-752
Database action ended - OK, 4593:3-751
Database Administration, 4802:1-2
Database Administration Manual, 4601:1-14, 4626:1-13
Database Administration Manual - System Management, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103
Database Archival, 4593:2-15, 4593:2-20, 4593:2-24, 4593:2-37
Database Audit, 1021:4-7
database back-up, 4307:5-27
Database BACKUP started, 4593:3-749
database backups, EPAP PDB, 4593:6-18, 4593:6-19
Database Communications Module, 1021:3-9, 4625:2-12
Database Communications Module (DCM), 4625:3-9
Database consistency violation - maintenance required, 4801:2-35
Database in the BLM card must be coherent for an upload, 4801:2-709
Database Integrity Enhancements (20.0), 4318:2-81
Database is incoherent, 4801:2-427
Database maint. in progress - retry later, 4801:2-78
Database maintenance is required, 4801:2-33
database maintenance required
    notification, 4751:3-3
Database Management Command Functions (20.0), 4318:2-81
    backup, 4318:2-82
    copy GPL, 4318:2-83
    copy measurements, 4318:2-83
    disk directory, 4318:2-83
    restore, 4318:2-82
database management procedures, 0002:2-1
database partitions
    overview, 0002:1-9, 0003:1-9, 4804:1-9

Database repair is required, 4801:2-33
Database RESTORE started, 4593:3-750
Database Service Module (Eagle STP), 1021:3-10, 4625:2-14
Database tables, retrieving from the Eagle, 0008:2-4
database time stamp (DBTS), 4751:4-3
Database Transport Access (DTA)
LNP—Impact of LNP on Other Features (22.0), 4318:4-65
Database Transport Access (DTA) (20.0), 4318:2-83
Database Unsolicited Output Message Group, 4593:D-26
database, DSM
see DSM
Database, STP Connection Configuration, 0008:2-14, 0008:2-16, 0008:2-17, 0008:2-18, 0008:2-22, 0008:2-40
Daughterboard BIP invalid, 4593:3-184
Daughterboard BIP valid, 4593:3-185
daughterboard, DSM
continual memory validation, 4307:4-7
Day is invalid for type-enttype combination, 4801:2-566
Day must be specified when PERIOD=SPECIFIC, 4801:2-568
Day out of range, 4801:2-99
Day-To-Hour Availability Measurements, 4593:4-41
Day-to-hour availabiltiy reports, 4593:4-41
Day-to-Hour Maintenance Measurements, 4593:4-80
Day-to-hour measurement collection in progress, 4801:2-109
Day-to-hour measurement data not yet collected, 4801:2-109
Day-to-hour reports, 4593:4-80
DB, 4802:1-13
DB is incoherent (<database>, <disk>, <MASP status>), 4801:2-419
DB restore has cleared and Disabled PDS, 4593:3-906
DB status is UPG 1 (<database>, <disk>, <MASP status>), 4801:2-419
db=mps, 4307:4-10
DBG, 4802:1-13
DCM, 4601:2-2, 4625:3-18, 4625:3-19, 4625:3-20, 4625:3-21, 4625:3-28, 4625:3-37, 4625:6-9, 4626:1-32
change features, chg-feat, 4593:3-390, 4593:5-99, 4593:A-84, 4601:6-74
dcm, 0003:3-4
DCM Applied to LSMS BLM-Based Operations - Removing, 0007:2-26
DCM card
Enhanced Bulk Download (25.0), 4318:2-147
DCM card replacement, 4593:A-46
DCM LED, 4601:A-8
DCM parameter set, 0003:3-3
dcmps, 0003:3-209
DCMX, 4601:5-25
Deactivating
Command Class Management Controlled Feature, 0002:B-39
Eagle OAM IP Security Enhancements Controlled Feature, 0002:B-39
IP User Interface Controlled Feature, 0002:B-39
Network Security Enhancements Controlled Feature, 0002:B-39
Deactivating the LNP SMS Feature, 0007:2-162
Debug, 4802:1-13
Debug Commands, 4800:8-1
Debug Menu, 4307:3-61

DEBUG must be on, 4801:2-541
Decode Eagle MPS Alarm, 4307:3-23
Decode MPS Alarm Strings Reference Procedure, 2712:3-18, 2712:3-21, 4593:6-62
Def Router IP Addr must be local to this cards A, B network, 4801:2-631
default
DMS network IP addresses, 4307:2-7
ELAP Sync network IP addresses, 4307:2-8
router IP address, 4307:5-19
values for ELAP user interface prompts, 4307:5-12
Default GTT, 4307:3-43
default network values, 0007:2-61, 4307:5-27
default router, 0002:4-153
Default Routing Keys, 0003:2-25
default values, 4307:5-27
Degraded Mode - 1 card failed, 4593:3-590
Degraded Mode - multiple cards failed, 4593:3-591
Degraded Mode, Invalid OAM HW config, 4593:3-543
Delete button, 0008:2-16, 0008:2-25, 0008:2-27, 0008:2-40
Delete Group Profile, 4307:3-102
Delete LNP 10-Digit Telephone Number Subscription, 4307:B-13, 4307:B-14
Delete LNP Location Routing Number, 4307:B-15
Delete LNP Subscription, 4307:3-51
Delete not allowed, associated TN assigned to the NPANXX, 4801:2-500
Delete NPA-NXX Records, 4307:3-54
Delete Override GTT Records, 4307:3-57
Delete Split NPANXX, 4307:B-15
Delete STP Data window, 0008:2-40
Delete User screen, 4307:3-92
Deleting an EMS Configuration Component, 0007:2-91
Deleting an STP Configuration Record, 0008:2-39
dependencies
TSM Warm Restart and Incremental Loading (EAGLE 26.0), 4318:5-145
Derivations for N1 and N2
Preventive Cyclic Retransmission (PCR) (EAGLE 20.0), 4318:5-32
Description
Retrieve Tables window, 0008:2-56
Update Tables window, 0008:2-78
description
G-Flex C7 Relay (26.3), 4318:3-13
INP Number Normalization (26.3), 4318:3-82
design, ELAP overall, 4307:2-4
Dest IP Address already exists for this card, 4801:2-627
Dest IP Address cannot be local to this cards A, B network, 4801:2-627
Dest IP Address does not exist for this card, 4801:2-628
Dest IP Address is invalid, 4801:2-626
destination, 4804:2-2
Destination address must be a full point code, 4801:2-372
Destination card invalid, 4801:2-97
destination commands
4000 Routesets (23.0), 4318:2-6
Destination disk capacity equals 0, 4801:2-357
Destination disk is unformatted, 4801:2-353

Destination element
definition, 0004:2-5, 4318:5-176
Destination location must specify the standby fixed disk, 4801:2-355
Destination location must specify the standby removable disk, 4801:2-355
Destination parameter not supported, 4801:2-67
destination point code, 4804:2-3
adding, 4804:2-162
changing, 4804:2-197
removing, 4804:2-185
destination tables
configuring, 4804:2-1
Destination's alias PCs must be full PCs, 4801:2-374
detecting and reporting problems, 2712:3-8
Determine LIM, MIM, and MPL Changeout Time, 4593:A-18
DEV state does not allow alarms to be inhibited, 4801:2-414
Device alarm inhibit table not accessible, 4801:2-573
DFLTACT can not be ATIERR unless OPCODE=71, 4801:2-753
DFLTACT must be specified as FORWARD, DUPLICATE, or DUPDISC, 4801:2-341
DGTS, 4802:1-13, 4802:4-5, 4802:4-21, 4802:4-24, 4802:4-25, 4802:4-28, 4802:4-29, 4802:4-31, 4802:4-32, 4802:4-33
DGTS parameter must be 3 or 6-10 digits, 4801:2-452
DHCP, 0004:6-6
diagnostic information, 4593:6-3
Dialup PPP network
description, 4307:2-9
IP addresses, 4307:2-9
modem, 4307:2-9
remote dial-in port, 4307:2-9
Different Database Level Alarm Repetition When UAM 34 Has Been Raised
Miscellaneous Command Adjustments (26.1), 4318:4-117
Digits Valid, 4802:1-14, 4802:3-48
Dimensions and Weight, 4625:4-23
diode board (FAP), 4593:2-6
diode boards, removing, 4593:2-9
diode jumper, 4593:2-8
diode testing, 4593:2-8
DIP switch settings, 4601:5-110, 4625:B-9
Direct Memory Access (DMA), 4625:3-68, 4625:3-97
disabled states
National Spare Network Indicator Support (EAGLE 22.2), 4318:4-148
National Spare Network Indicator Support (EAGLE 24.0), 4318:4-150
Disabling Bulk Load, 0007:2-149
Disabling the Gateway Screening Redirect Function, 0004:4-51
Disallow Simultaneous Logins Sessions with the Same User ID (21.0), 4318:2-90
disaster recovery, 2712:2-14
disc-imt, 4800:6-11
disconnect power
fan assembly, 4593:5-93, 4593:A-77
Disk Access, 2712:3-12, 4593:6-6
Disk Access Alarm, 4593:6-7
Disk access error - fixed disk, 4801:2-103
Disk Coherency Tests (20.0), 4318:2-90

Disk Copy Fixed to Fixed (20.0), 4318:2-91
disk directory
Database Management Command Functions (20.0), 4318:2-83
disk drive, replacement procedure, 2712:5-9
disk drive, replacement procedure for internal, 4593:6-123
disk drives, removable cartridge, 4800:4-2
disk measurement status unreadable, 4593:3-709
Disk space, 0008:2-2
disk systems, 1021:4-10
disks, MPS Server SCSI, 4625:4-27
DiskSuite Alarm, 4593:6-8
DiskSuite File System, 4593:6-6
disp-bip, 4800:8-22
disp-bp, 4800:8-23
disp-disk-dir, 4800:8-25
disp-disk-stats, 4800:8-27
disp-fta-dir, 4800:6-12
Display, 0003:3-180
Clearing
Connectivity Test Log, 0008:2-32, 0008:2-33
Retrieve Tables Log, 0008:2-68, 0008:2-69
System Log, 0008:2-97, 0008:2-98
Update Tables Log, 0008:2-92, 0008:2-93
display card status, rept-stat-card
IPGWI, 0003:3-146, 0003:3-166, 0003:3-180
IPLIM, 0003:3-166, 0003:3-180
SS7IPGW, 0003:3-146, 0003:3-166, 0003:3-180
Display Configuration menu, 4307:5-17
Display External NTP Server, 4307:5-25
Display Inhibited Alarms (Release 29.0), 4318:2-91
Display Release Levels, 4307:3-22
display signaling link status, rept-stat-slk
IPGWI, 0003:3-145, 0003:3-148, 0003:3-165, 0003:3-170, 0003:3-178, 0003:3-182, 0003:3-199, 0003:3-214, 0003:3-291, 0003:3-312, 0003:3-381, 0003:3-391
IPLIM, 0003:3-148, 0003:3-165, 0003:3-170, 0003:3-178, 0003:3-381, 0003:3-391
SS7IPGW, 0003:3-145, 0003:3-148, 0003:3-165, 0003:3-170, 0003:3-178, 0003:3-182, 0003:3-200, 0003:3-201, 0003:3-214, 0003:3-215, 0003:3-291, 0003:3-293, 0003:3-312, 0003:3-314, 0003:3-381, 0003:3-391
displaying
LNP services and translation type assignments, rtrv-lnp-serv, 0002:A-41, 0002:A-68, 4601:6-128, 4601:6-142
OAP configuration, 0002:A-35, 0002:A-63, 4601:6-122, 4601:6-137
terminal configuration, rtrv-trm, 0002:A-33, 0002:A-61, 4601:6-120, 4601:6-135
Displaying an Existing STP Configuration Record, 0008:2-23
disp-lba, 4800:8-29
disp-mem, 4800:8-30
Distributing
LNP Database after LSMS-Based Operation or RTDB Copy, 0007:2-144
RTDB LNP Database to DSMs Procedure, 0007:2-145
RTDB, Returning to Normal Service, 0007:2-145
dlt-acg-mic, 4800:6-12
dlt-acg-noc, 4800:6-13

dlt-appl-rtkey, 4800:6-14
dlt-appl-sock, 4800:6-19
dlt-asp, 4800:6-20
dlt-assoc, 4800:6-21
dlt-bp, 4800:8-32
dlt-card, 4800:6-22
dlt-cspc, 4800:6-23
dlt-dstn, 4800:6-26
dlt-e1, 4800:6-30
dlt-fta, 4800:6-31
dlt-ftp-serv, 0002:4-162, 4800:6-32
dlt-gsmmap-scrn, 4800:6-33
dlt-gsms-opcode, 4800:6-34
dlt-gsmssn-scrn, 4800:6-35
dlt-gta, 4800:6-36
dlt-gtcnv, 4800:6-38
dlt-gtt, 4800:6-40
dlt-gttsel, 4800:6-42
dlt-gttset, 4800:6-44
dlt-gws-redirect, 4800:6-45
dlt-homern, 4800:6-46
dlt-home-smsc, 4800:6-46
dlt-ip-host, 4800:6-47
dlt-ip-node, 4800:6-48
dlt-ip-rte, 4800:6-50
dlt-lbp, 4800:6-51
dlt-lnp-lrn, 4800:6-53
dlt-lnp-npanxx, 4800:6-54
dlt-lnp-serv, 4800:6-56
dlt-lnp-sp, 4800:6-57
dlt-lnp-sub, 4800:6-58
dlt-ls, 4800:6-59
dlt-map, 4800:6-60
dlt-mrn, 4800:6-62
DLTPFX must not be specified, when NCDPNPFX is NONE, 4801:2-90
dlt-pstn-pres, 4800:6-69
dlt-rmt-appl, 4800:6-70
dlt-rte, 4800:6-72
dlt-scr-aftpc, 4800:6-76
dlt-scr-blkdpc, 4800:6-79
dlt-scr-blkopc, 4800:6-83
dlt-scr-cdpa, 4800:6-87
dlt-scr-cgpa, 4800:6-90
dlt-scr-destfld, 4800:6-93
dlt-scr-dpc, 4800:6-96
dlt-scr-isup, 4800:6-99
dlt-scr-opc, 4800:6-100
dlt-scrset, 4800:6-107
dlt-scr-sio, 4800:6-103
dlt-scr-tt, 4800:6-106
dlt-slk, 4800:6-108, 4803:3-33
dlt-spc, 4800:6-110

dlt-split-npa, 4800:6-112
dlt-srvsel, 4800:6-113
dlt-ss-appl, 4800:6-114
dlt-t1, 4800:6-115
dlt-tt, 4800:6-116
dlt-uim-acthresh, 4800:6-119
dlt-user, 4800:6-120
dlt-x25-dstn, 4800:6-120
dlt-x25-rte, 4800:6-121
Document Conventions, 0007:2-2
documentation
    admonishments, 2969:1-6, 4307:1-7, 4800:1-7
    delivery, 2969:1-6
    packaging, 2969:1-6, 4307:1-6
    part numbers, 4307:1-6
    updates, 2969:1-6, 4307:1-6
Documentation Admonishments, 0007:2-4
Documentation Bulletins, 4601:1-14, 4626:1-14
Documentation Packaging, Delivery, and Updates, 4625:1-14, 4801:1-10
documentation set, 0002:1-3, 0003:1-3, 0003:1-5, 4593:1-4, 4803:1-6, 4804:1-3
documents
    Alarms Reference and User's Manual, 4625:1-13, 4626:1-15
    Data Collection Applications Manual, 4625:1-12, 4626:1-15
    Feature Notice, 4625:1-12, 4626:1-15
    hardware and installation, 4625:1-13, 4626:1-16
    list of Sentinel, 4625:1-12, 4626:1-15
    Proactive Testing Applications Manual, 4625:1-12
    Release Notice, 4625:1-12, 4626:1-15
    System Administrator's Guide, 4625:1-12, 4626:1-15
    technical reference documents, 4625:1-13, 4626:1-16
    User's Manual, 4625:1-12, 4626:1-15
dollies, 4601:3-9
Dolly Heavy-Duty Frame, 4601:3-7
Domain indicated by GTIx must match that of existing TT, 4801:2-479
Domain must be SS7 if SPC is specified, 4801:2-715
DOS, 0008:2-6
DOS command prompt, 0008:2-73
Double, 4625:3-19
DPADDR cannot be entered with DR/DA, 4801:2-303
DPC, 4593:F-8
dpc, 0003:3-242, 0004:2-32
DPC - SS status changed, 4593:3-431
DPC assigned to SS7 address does not exist in SS7 domain, 4801:2-292
DPC assigned to SS7 address has no SS7 routes, 4801:2-293
DPC assigned to X.25 address has no SS7 routes, 4801:2-292
DPC assigned to X25 address does not exist in X25 domain, 4801:2-291
DPC cannot be defined as a remote application IPC, 4801:2-459
DPC defined as linkset APC, 4801:2-134
DPC is allowed, 4593:3-399
DPC is already being used, 4801:2-133
DPC is assigned a route, 4801:2-644
DPC is prohibited, 4593:3-401

DPC is referenced by SCCP in the MRN table, 4801:2-435
DPC is referenced by SCCP's MAP table, 4801:2-371
DPC is restricted, 4593:3-400
DPC must be a cluster DPC or cluster member, 4801:2-52
DPC must be removed from X.25 route tbl, 4801:2-256
DPC must be specified as wildcard when used with STAT, 4801:2-388
DPC must have at least one route defined, 4801:2-278
DPC must not specify a cluster route for IPGWAPC link set, 4801:2-718
DPC parameter must be specified, 4801:2-571
DPC parameter needed with MODE=FULL, 4801:2-159
DPC Quantity
    Changing, 4804:2-21
DPC subsystem has been deleted, 4593:3-420
DPC Subsystem is Abnormal, 4593:3-428
DPC subsystem is allowed, 4593:3-417
DPC subsystem is blocked, 4593:3-418
DPC Subsystem is Normal, 4593:3-427
DPC subsystem is prohibited, 4593:3-419
DPC Subsystem is prohibited and blocked, 4593:3-426
DRAM, 4625:3-91
DRANAI and DRANAIV must not be specified together, 4801:2-767
DRANP and DRANPV must not be specified together, 4801:2-767
drill bit, masonry, 2969:4-3
drive, tape
    see tape drive
drklog, 4800:9-19
drkq, 0003:3-151
Drop down list
    STP Name, 0008:2-16, 0008:2-23
        FTRA 1.0, 0008:2-23, 0008:2-25
        FTRA 2.0, 0008:2-23, 0008:2-24, 0008:2-25, 0008:2-26
DRTN, 4802:1-13, 4802:4-3, 4802:4-5, 4802:4-13, 4802:4-14, 4802:4-15, 4802:4-17, 4802:4-19, 4802:4-20, 4802:4-21, 4802:4-24, 4802:4-25, 4802:4-28, 4802:4-29, 4802:4-31, 4802:4-32, 4802:4-33
DS0 4-link monitor configuration window, 4625:B-6
DS0 and NEI link elements do not support non-latching tests, 4801:2-391
DS0 monitor applique, 4625:B-6
DS0A, 4625:3-68
DSA Key Fingerprint, 0008:2-46, 0008:2-47
DSCS bridge amplifier
    description, 4625:B-9
    DIP switch settings, 4625:B-9
    front view, 4625:B-9
    installing, 4625:B-10
    limitations, 4625:B-11
    part number, 4625:B-11
    rear view, 4625:B-10
DSM, 4601:2-2, 4601:5-25, 4625:3-21, 4625:3-37, 4626:1-32
    Adding, 0007:2-20
    allowing card, 4751:8-3
    connection to ELAP, 4307:2-7
    continuous reload, 4307:2-18
    database level, 4307:4-5

daughterboard continual memory validation, 4307:4-7
DSM-ELAP Link status alarms, 4307:4-16
Ethernet Link to the MPS - Configuring, 0007:2-31
incremental loading model, 4307:2-17
inhibiting, rmv-card, 4751:8-3
memory capacity status reporting, 4307:4-7
primary, 4307:2-21, 4307:4-3
provisioning description, 4307:2-17
reload, 4307:2-17
status of connection to ELAP, 4307:4-16
Status Requests, 4307:4-5
system hardware verification, 4307:4-6
UAMs, 4307:4-16
unstable loading mode, 4307:4-8
verifying status, 4751:8-5
warm restart, 4307:2-18
DSM LED, 4601:A-8
DSM networks
configure IP addresses, 4307:5-20
description, 4307:2-4, 4307:2-7
IP addresses, 4307:2-7
DSM's are required when LNP and VGTT are ON, 4801:2-790
DSTN address must be a full, network or cluster PC, 4801:2-385
DSTN5000 feature must be enabled, 4801:2-566
DSX, 4601:5-12, 4601:5-18
DUAL OAP configuration is needed for LNP feature, 4801:2-516
dual-slot DCM card, 4318:5-80
dual-slot STC, 0004:6-4, 0004:6-7, 0004:6-8, 0004:6-19, 0004:6-21, 0004:6-23
Duplicate ACTs in different slots are not allowed, 4801:2-650
Duplicate packets, 0008:2-122
duplicate parameters in command, 4800:4-10
DUR=PERM can only be specified with a 486 processor, 4801:2-304
DURAL must be specified within 0..995959 or 999999, 4801:2-335
Duration Index, 4802:1-13, 4802:4-2, 4802:4-3, 4802:4-4, 4802:4-5, 4802:4-13, 4802:4-19, 4802:4-21, 4802:4-22, 4802:4-31, 4802:4-32
DV, 4802:1-14, 4802:3-30, 4802:3-31, 4802:3-32, 4802:3-33, 4802:3-37, 4802:3-42, 4802:3-45, 4802:3-48, 4802:3-49, 4802:3-52, 4802:3-53, 4802:3-89, 4802:3-120, 4802:3-132, 4802:3-142, 4802:3-158, 4802:3-180
DV must be SCCP when SERV is a user defined type, 4801:2-526
DV must be TCAP when SERV is WNP, AIN, PCS, IN or LNPQS, 4801:2-527
DVD-ROM
description, 4625:4-29
replacement procedure, 4593:6-123
specification, 4625:4-27
Dynamic database is inconsistent, 4593:3-606, 4593:3-607
Dynamic Host Configuration Protocol, 0004:6-6
dynamic random access memory (DRAM), 4625:3-91
Dynamic rtkeys + SRKQ exceed max allowed rtkey limit, 4801:2-723
DYNRTK feature must be enabled to perform this operation, 4801:2-725

E

E1, 4593:A-25, 4593:A-26, 4601:5-118, 4601:5-120, 4601:5-121, 4601:5-123, 4601:5-125, 4601:5-129, 4601:A-6, 4601:A-11, 4601:A-12, 4625:3-19, 4625:3-21, 4625:3-104, 4625:3-109, 4626:A-3, 4626:A-5
E1 4-link Monitor Configuration window, 4625:B-5
E1 Administration and Alarms (26.3), 4318:2-102
  E1 Operation within an EAGLE, 4318:2-102
  Eagle Application Support for E1, 4318:2-103
E1 ATM High Speed Link (Release 28.1), 4318:2-108
E1 ATM High Speed Link (Release 28.1) (IP7 Release 6.0), 4318:2-108
E1 backplane, 4601:5-123, 4601:5-128, 4601:5-130, 4625:3-106, 4625:3-110, 4804:A-5, 4804:B-4
E1 Backplanes, 4601:5-121
E1 Card, 4601:5-119
E1 card
  clocking options, 4804:A-7, 4804:B-5
  configured as channel card, 4804:A-4, 4804:B-3
  configured as E1 card, 4804:A-4, 4804:B-3
  determining configuration, 4804:A-5, 4804:B-4
E1 card location is unequipped, 4801:2-817
E1 interface, 4601:5-122
E1 Interface Kit, 4601:5-122
E1 is assigned to card, 4801:2-804
E1 monitor applique, 4625:B-4
E1 Operation within an EAGLE
  E1 Administration and Alarms (26.3), 4318:2-102
E1 Patch Cables, 4601:5-129
E1 patch cables, 4601:5-122
E1 specified by E1LOC/E1PORT is using CAS, TS=16 not allowed, 4801:2-807
E1/T1 Configuration Form, 4601:5-132
E1/T1 MIM, 0004:6-7, 4601:5-81, 4601:5-82, 4601:5-125
E1/T1 Multi-Channel Interface Module (Release 28.0), 4318:2-112
E1/T1 Multi-Channel Interface Module (Release 28.0) (IP7 Release 6.0), 4318:2-112
E1-ATM, 0004:6-7
E1PORT specified by E1LOC is not equipped, 4801:2-806
E1-T1 MIM, 4601:1-11
E5IS must be on, 4801:2-780
EADDR cannot be specified without SADDR, 4801:2-750
EADDR must be greater than SADDR, 4801:2-749
EADDR shouldn't be specified when SADDR = *, 4801:2-881
Eagle
  documentation set, 0002:1-3, 0003:1-3, 4593:1-4, 4803:1-6, 4804:1-3
  Telnet terminals, 0008:2-16, 0008:2-46, 0008:2-65
  UIM - Unsolicited Information Message, 0008:2-46, 0008:2-47, 0008:2-65
EAGLE 5 SAS, 4601:1-6, 4625:1-6
Eagle Agents
  Manually Verifying and Restarting, 0007:2-151
Eagle Application Support for E1
  E1 Administration and Alarms (26.3), 4318:2-103
Eagle Application Support for E1 (26.3)
  alarms, 4318:2-106
  enhanced commands, 4318:2-104
  hardware requirements, 4318:2-104
  limitations, 4318:2-107

new commands, 4318:2-104
upgrade considerations, 4318:2-107
Eagle can only accept messages of 450 or fewer bytes (C<col>), 4801:2-555
Eagle Card
GPSM-II, 0008:2-3
IPSM, 0008:2-3
MCAP, 0008:2-3
TDM, 0008:2-3
Eagle chg-ftp-serv command, 0008:2-50
Eagle chg-trm:trm=:all=no command, 0008:2-65
Eagle command
alw-card, 0008:2-43
chg-ftp-serv, 0008:2-50
chg-trm, 0008:2-46
chg-trm:trm=:all=no, 0008:2-65
ent-ftp-serv, 0008:2-50
init-card, 0008:2-43, 0008:2-46, 0008:2-47
pass:loc=xxxx
cmd="netstat -p tcp", 0008:2-121
cmd="ping yy.yy.yy.yy", 0008:2-120
rst-card, 0008:2-43
rtrv, 0008:2-56, 0008:2-73, 0008:2-75
rtrv-card, 0008:2-3
rtrv-ctrl-feat, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103
rtrv-feat, 0008:2-54
rtrv-ftp-serv, 0008:2-116
rtrv-gta, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gtt, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gttsel, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gttset, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-ip-lnk, 0008:2-46, 0008:2-47
rtrv-secu-dflt, 0008:2-21
rtrv-trm, 0008:2-45, 0008:2-46, 0008:2-65
rtrv-tt, 0008:2-54, 0008:2-59, 0008:2-65
Eagle command files
sending, 0008:2-4
Eagle configuration, 0008:2-3
Eagle database tables
retrieving, 0008:2-4
Eagle DSM Audit of MPS Databases, 4307:2-19
Eagle EGTT commands
rtrv-gta, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gttsel, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gttset, 0008:2-54, 0008:2-59, 0008:2-65
Eagle ent-ftp-serv command, 0008:2-50
Eagle Feature
EGTT, 0008:2-54
FTP Retrieve and Replace, 0008:2-3
GTT, 0008:2-54
IP User Interface, 0008:2-3
Eagle feature
Eagle OA&M IP Security Enhancements, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103

Eagle GTT commands
rtrv-gtt, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-tt, 0008:2-54, 0008:2-59, 0008:2-65
Eagle Initiated OAP User Interface (24.0), 4318:2-115
LNP Service commands, 4318:2-116
OAP commands, 4318:2-115
Eagle Initiated OAP User Interface (24.0)
auditing the OAP database, 4318:2-117
Eagle LNP Application Processor
see ELAP
Eagle LNP Functional Capabilities, 1021:4-4
Eagle Manual, Database Administration Manual - System Management, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103
Eagle Measurement Reports (20.0), 4318:2-117
Eagle OA&M IP Security Enhancements feature, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103
Eagle OAM IP Security Enhancements Controlled Feature
Activating, 0002:B-12
Deactivating, 0002:B-39
Eagle pass:loc=xxxx
cmd="netstat -p tcp" command, 0008:2-121
cmd="ping yy.yy.yy.yy" command, 0008:2-120
Eagle procedure
Activating Controlled Features, 0008:2-3
Activating the Eagle OA&M IP Security Enhancements Controlled Feature, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103
Eagle Provisioning, 0004:6-6
Eagle Public Host Key Fingerprint, 0008:2-43, 0008:2-44, 0008:2-46, 0008:2-48
Eagle Public Key Fingerprint, 0008:2-17, 0008:2-46, 0008:2-47
Eagle release 30.2 or greater, 0008:2-3, 0008:2-17, 0008:2-22
Eagle Release 31.4 UAM / UIM Changes, 4593:3-52
Eagle Release 31.5 UAM / UIM Changes, 4593:3-52
Eagle Release 31.6 UAM / UIM Changes, 4593:3-53
Eagle rtrv-card command, 0008:2-3
Eagle rtrv-ctrl-feat command, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103
Eagle rtrv-feat command, 0008:2-54
Eagle rtrv-ftp-serv command, 0008:2-116
Eagle rtrv-gta command, 0008:2-54, 0008:2-59, 0008:2-65
Eagle rtrv-gtt command, 0008:2-54, 0008:2-59, 0008:2-65
Eagle rtrv-gttsel command, 0008:2-54, 0008:2-59, 0008:2-65
Eagle rtrv-gttset command, 0008:2-54, 0008:2-59, 0008:2-65
Eagle rtrv-secu-dflt command, 0008:2-21
Eagle rtrv-trm command, 0008:2-65
Eagle rtrv-tt command, 0008:2-54, 0008:2-59, 0008:2-65
Eagle STP, 1021:1-4, 4601:1-10, 4601:1-11, 4625:1-6
Eagle STP and IP7 Secure Gateway Systems, 1021:3-2, 4625:2-3
Eagle STP commands, 0008:2-1, 0008:2-77, 0008:2-78
Eagle Support for Integrated Sentinel, 0004:1-3, 0004:6-2, 0004:6-4, 0004:6-10, 0004:6-11, 0004:6-13, 0004:6-14, 0004:6-19, 0004:6-22, 0004:6-27, 4318:2-117
Eagle Support for Integrated Sentinel (Release 28.0), 4318:2-117
EAGLE-Based Products, 4625:1-6
Ear protectors, 4601:3-20
ear protectors, 2969:4-3

earthquake resistance, 2969:2-6, 4625:6-4
EBI, 4625:3-53
Echo capability not applicable on originating terminal, 4801:2-567
Echo is not set for this port, 4801:2-99
Echo not allowed for telnet terminals, 4801:2-161
EDCM, 4601:2-2, 4625:3-19, 4625:3-81, 4626:1-32
Edit button, Update Validation Complete window, 0008:2-83, 0008:2-84, 0008:2-85, 0008:2-86
Edit menu
    FTP-Based Table Retrieve Application, 0008:2-14, 0008:2-78
Editing a Command File, 0008:2-85
Effect of Corrupted record received from MPS, 4307:2-20
EGMS feature requires DSM card with VSCCP APPL or better, 4801:2-751
EGTA cannot be specified without GTA, 4801:2-168
EGTA must be greater than or equal to GTA, 4801:2-174
EGTT cannot be ON if any SCCP card has a 486 processor, 4801:2-623
EGTT commands
    Eagle
        rtrv-gta, 0008:2-54, 0008:2-59, 0008:2-65
        rtrv-gttsel, 0008:2-54, 0008:2-59, 0008:2-65
        rtrv-gttset, 0008:2-54, 0008:2-59, 0008:2-65
EGTT Feature, 0008:2-54
EGTT must be ON before this command can be entered, 4801:2-615
EGTT Set commands
    Enhanced GTT (26.0), 4318:2-154
Eight-Port Connector Box, 4625:4-55
EILA, 0004:6-7, 4625:3-18, 4625:3-19, 4625:3-21, 4625:3-37
EILA (P/N 870-2049-01, 4593:A-25, 4601:2-2, 4601:A-6, 4626:1-32, 4626:A-3
EIR and INP are mutually exclusive, 4801:2-841, 4801:2-845
EIR and LNP are mutually exclusive, 4801:2-845
EIR feature cannot be enabled if ASM/TSM is present, 4801:2-846
EIR feature must be enabled, 4801:2-849
EIR feature must be ON, 4801:2-662
EIR Subsystem is available, 4593:3-562
EIR Subsystem is disabled, 4593:3-560
EIR Subsystem is not available, 4593:3-559
EIR subsystem is offline in database, 4801:2-849
EIR Subsystem is removed, 4593:3-563
EIR Subsystem normal,card(s) abnormal, 4593:3-561
Either ALIASN or ALIASN24, not both, for destination, 4801:2-597
Either BUS or Location (not both) must be specified, 4801:2-799
Either INP or GPORT feature must be ON, 4801:2-789
Either LOC or APPL (not both) must be specified, 4801:2-107
Either LSN or LOC and PORT must be specified, 4801:2-116
Either PLNP or WNP Features must be ON, 4801:2-756
Either TYPE or TTN must be specified, 4801:2-197
Eject CD menu, 4307:3-77, 4307:5-23
ELAP
    Able/Unable states for provisioning, 4307:2-10
    Active/Standby
        relation to LSMS connection, 4307:2-10
        roles, 4307:2-5
        switchover, 4307:2-5

alarms
see also alarms
application, 4307:4-14
DSM-ELAP Link status, 4307:4-16
in rept-stat-mps report, 4307:4-11
RTDB Audit, 4307:4-16
UAMs, 4307:4-14
change login name passwords, 4307:5-22
Configuration and Initialization, 0007:2-46
Configuration feature, 0007:2-1, 0007:2-6, 0007:2-13, 0007:2-129, 0007:2-132, 0007:2-133, 0007:2-137, 0007:2-138
Configuration Menu, 0007:2-50, 0007:2-51
Configuration Procedure, 0007:2-61, 0007:2-64
connection to DSMs, 4307:2-4, 4307:2-7
definition, 4307:2-2
DSM UAMs, 4307:4-16
existing connection to LSMS, 4307:2-11
general description, 4307:2-3
GUI interface, accessing, 2712:A-1
initial connection to LSMS, 4307:2-10
initialization, 4307:5-9
log viewer navigation commands, 4307:3-70
LSMS connection, 4307:2-5
Maintenance Blocks, 4307:4-3
MPS Server memory to support, 4625:4-27
overall design, 4307:2-4
Software Configuration Overview, 0007:2-38
status of connection to DSM, 4307:4-16
supports LNP 48 Million Numbers feature, 1021:6-2
Sync network
configure IP addresses, 4307:5-19
description, 4307:2-4, 4307:2-8
IP addresses, 4307:2-8
text interface, accessing, 2712:A-6
time zone, 4307:5-21
user interface, 4593:6-17, 4593:6-115
error message format, 4307:5-13
list of error messages, 4307:3-114, 4593:6-23
user interface menus
configuration, 4307:5-14
default values for prompts, 4307:5-12
Escape key to exit operations, 4307:5-12
responding to prompts, 4307:5-12
User Interfaces - Overview, 0007:2-38
user login names
access configuration menu, 4307:5-14
elapconfig
for ELAP initialization, 4307:5-9
Workstation - Setting Up, 0007:2-38
ELAP 2.x
Configuration Menu, 0007:2-50
ELAP 5.0

Configuration and Initialization, 0007:2-51
Configuration Procedure, 0007:2-51, 0007:2-61
ELAP application, 4593:6-21
ELAP Areas, 4307:3-6
ELAP Configuration feature, 0007:2-129
ELAP Database Backup Procedures, 4593:6-51
ELAP Error Messages, 4307:3-114
ELAP menu, 4307:3-12
ELAP Normal Output, 4593:6-10
ELAP User Interfaces, 4307:3-2
ELAP Verbose Output, 4593:6-10
ELAP/EPAP Log Files, 4593:6-21
elapconfig, 4307:5-14
elapconfig login name
access configuration menu, 4307:5-14
for ELAP initialization, 4307:5-9
electric shock, 2969:6-2, 4601:4-13
ELEI is only valid for cluster destinations, 4801:2-369
ELEI is only valid if the CRMD feature is ON, 4801:2-370
Element Management System Alarm Monitor (EMSALM), 4800:4-8
elements overwritten, 4593:3-755
elevation requirements, 2969:2-6
ELRN must be greater than LRN, 4801:2-513
e-mail address, Tekelec Technical Services, 4625:1-15
EMAP GPL
change from trial to approved version, 0002:3-116
Embedded OAP (24.0), 4318:2-127, 4318:2-133
assynchronous maintenance modem, 4318:2-137
EOAP Connector, 4318:2-132
EOAP Processor Card, 4318:2-130
EOAP-to-Eagle Interface, 4318:2-139
EOAP-to-LSMS Interface, 4318:2-140
EOAP-to-SEAS Interface, 4318:2-140
fans, 4318:2-138
Hard Drive and CD-ROM Drive, 4318:2-132
hardware requirements, 4318:2-129
Power Supply card, 4318:2-131
Serial card, 4318:2-131
Third-Party software, 4318:2-138
User Console, 4318:2-137
Embedded Operations Applications Processor, 1021:3-18, 4625:2-18
embossing dies, 4601:4-15
Emergency response, 0004:1-8, 0005:1-8, 0006:1-7, 0007:2-5, 4802:1-9, 4803:1-10
emergency response, 4318:1-9, 4601:1-19, 4625:1-17, 4626:1-21
emergency response (Tekelec Technical Services), 0002:1-7, 0003:1-7, 4751:1-11, 4804:1-7
EMS
Configuration Component, 0007:2-81
Configuration Component - Creating, 0007:2-81
Configuration Component - Deleting, 0007:2-91
Configuration Component - Modifying, 0007:2-87
Configuration Component - Viewing, 0007:2-89
Routing, 0007:2-93

Modify, 0007:2-93
View, 0007:2-96
EMS Agent available, 4593:3-478
EMS Agent unavailable, 4593:3-476
EMSALM terminal type, 0002:4-56
EMSALM terminals, 4800:4-8
enable-ctrl-feat, 4800:6-122
enabled states
National Spare Network Indicator Support (EAGLE 22.2), 4318:4-148
National Spare Network Indicator Support (EAGLE 24.0), 4318:4-149
Enabling a Permanent or Temporary Key, 0003:6-3
Enabling the Large System # Links Controlled Feature, 0003:3-110, 0004:2-138, 4804:3-9
Enabling the LNP Feature for 2 to 12 Million Numbers, 4802:2-16
Enabling the XGTT Table Expansion Feature, 0006:A-17
Enabling the XMAP Table Expansion Feature, 0006:A-27
ENCODE = AMI not currently supported, 4801:2-834
encryption keys for secure shell, 4307:5-21
End Cabinet Alarm Indicators, 4593:3-9
End node internal point codes, 0003:3-4
end panels, 4625:3-6
Ending bucket cannot be less than starting bucket, 4801:2-447
Enforce password complexity checking, 4307:3-110
Enhanced Bulk Download (25.0), 4318:2-143
administration, 4318:2-146
alarms, 4318:2-144
changed commands, 4318:2-150
DCM card, 4318:2-147
hardware requirements, 4318:2-143
limitations, 4318:2-150
minimum LSMS/Eagle Ethernet facility, 4318:2-148
new commands, 4318:2-149
new GPLs, 4318:2-146
OAM reboot during bulk download, 4318:2-149
serviceability, 4318:2-146
upgrade considerations, 4318:2-149
Enhanced Bulk Download already in progress, 4801:2-709
Enhanced Bulk Download not in progress, 4801:2-709
Enhanced Commands
Security Log Increase (EAGLE 26.05), 4318:5-71
enhanced commands
CDU for DSM (26.05), 4318:2-61
Eagle Application Support for E1 (26.3), 4318:2-104
INAP-based Number Portability (INP) (26.05), 4318:3-79
INP Number Normalization (26.3), 4318:3-82
ITU Duplicate Point Code Routing (26.05), 4318:3-151
ITU Gateway Measurements Enhancements (26.05), 4318:3-159
Multiple Point Code Support (EAGLE 26.05), 4318:4-142
Stand-alone Eagle G-Flex Relay Function, 4318:3-15
Two-Point IPLIMx (Eagle 27.1), 4318:5-153
Weighted SCP Load Balancing (Eagle 27.2), 4318:5-170
Enhanced Database Status Reports (20.0), 4318:2-150
Enhanced GPL Management (25.0), 4318:2-151

alarms, 4318:2-152
changed commands, 4318:2-151
Upgrade Considerations, 4318:2-151
Enhanced GSM Map Screening feature must be enabled, 4801:2-883
Enhanced GSM Map Screening feature must be ON, 4801:2-880
Enhanced GTT (26.0), 4318:2-152
Assumptions/Limitations, 4318:2-155
Changed Commands, 4318:2-154
EGTT Set Commands, 4318:2-154
GTA Commands, 4318:2-154
new commands, 4318:2-153
protocol details, 4318:2-153
upgrade considerations, 4318:2-153
Enhanced Link Diagnostics (22.0), 4318:2-155
Enhanced Load Distribution (21.0), 4318:2-156
Enhancement to Backup TFR/TCR Procedures (21.0), 4318:2-161
Enhancement to GTT Failure Messages (25.0), 4318:2-162
Enhancements to GWS Reject Messages (25.0), 4318:2-164
SEAS Compliance, 4318:2-164
ENPANXX must be greater than NPANXX, 4801:2-503
Ent-/Chg-GTT Failure Message Shows Overlap
Miscellaneous Command Adjustments (26.1), 4318:4-117
ent-acg-mic, 4800:6-126
ent-acg-noc, 4800:6-128
ent-appl-rtkey, 4800:6-129
ent-appl-sock, 4800:6-134
ent-as, 4800:6-137
ent-asp, 4800:6-138
ent-assoc, 4800:6-139
ent-bp, 4800:8-33
ent-card, 4800:6-142
ent-cspc, 4800:6-150
ent-dlk, 4800:6-152
ent-dstn, 4800:6-154
ent-e1, 4800:6-164
Entering a Global Title Translation to a Non-Mated Application without Adding the Application as Mated Application (22.0), 4318:2-166
Entering an STP Name, 0008:2-27
entering commands, 4800:4-9
Entering forced simplex mode, 4593:3-104
Enterprise 450
servers, 1021:4-10
ent-ftp-serv, 0002:4-159, 4800:6-166
ent-ftp-serv Eagle command, 0008:2-50
ent-gsmmap-scrn, 4800:6-168
ent-gsms-opcode, 4800:6-174
ent-gsmssn-scrn, 4800:6-178
ent-gta, 4800:6-179
ent-gtcnv, 4800:6-185
ent-gtt, 4800:6-188
ent-gttsel, 4800:6-195
ent-gttset, 4800:6-197

ent-gws-redirect, 4800:6-198
ent-homern, 4800:6-202
ent-home-smsc, 4800:6-201
ent-ip-host, 4800:6-203
ent-ip-node, 4800:6-204
ent-ip-rte, 4800:6-206
Entity must be specified when Entity type is specified, 4801:2-876
ent-lbp, 4800:6-208
ent-lnp-lrn, 4800:6-210
ent-lnp-npanxx, 4800:6-212
ent-lnp-serv, 4800:6-215
ent-lnp-sp, 4800:6-217
ent-lnp-sub, 4800:6-218
ent-ls, 4800:6-222
ent-map, 4800:6-230
ent-mrn, 4800:6-237
ent-na, 4800:6-243
ent-pstn-pres, 4800:6-244
Entries in static route key table cannot exceed SRKQ, 4801:2-724
ent-rmt-appl, 4800:6-246
ent-rte, 4800:6-248
Entry already exists for this application at this IP Address, 4801:2-336
Entry already exists for this application at this priority, 4801:2-337
Entry already exists with specified GTII-TT-NP(V)-NAI(V)-SSN, 4801:2-771
Entry already exists with specified GTIN24-TT-NP(V)-NAI(V)-SSN, 4801:2-814
Entry already exists with specified GTIN-TT-NP(V)-NAI(V)-SSN, 4801:2-772
Entry already exists with specified GTI-TT-NP(V)-NAI(V)-SSN, 4801:2-768
Entry being deleted is referenced by a GSM Map Screen entry, 4801:2-749
Entry does not exist with specified GTII-TT-NP(V)-NAI(V)-SSN, 4801:2-772
Entry does not exist with specified GTIN24-TT-NP(V)-NAI(V)-SSN, 4801:2-889
Entry does not exist with specified GTIN-TT-NP(V)-NAI(V)-SSN, 4801:2-773
Entry does not exist with specified GTI-TT-NP(V)-NAI(V)-SSN, 4801:2-768
Entry is already defined as the STP Options DefCC, 4801:2-637
ent-scr-aftpc, 4800:6-251
ent-scr-blkdpc, 4800:6-255
ent-scr-blkopc, 4800:6-260
ent-scr-cdpa, 4800:6-265
ent-scr-cgpa, 4800:6-269
ent-scr-destfld, 4800:6-274
ent-scr-dpc, 4800:6-277
ent-scr-isup, 4800:6-281
ent-scr-opc, 4800:6-283
ent-scrset, 4800:6-293
ent-scr-sio, 4800:6-287
ent-scr-tt, 4800:6-291
ent-serial-num, 4800:6-295
ent-shlf, 4800:6-296
ent-slk, 4800:6-297
ent-spc, 4800:6-311
ent-split-npa, 4800:6-313
ent-srvsel, 4800:6-314
ent-ss-appl, 4800:6-318

ent-t1, 4800:6-319
ent-trace, 4800:8-37
ent-tt, 4800:6-321
ent-ttmap, 4800:6-323
enttype=lsonismt, 4593:4-120
ent-user, 4800:6-324
ent-x25-dstn, 4800:6-328
ent-x25-rte, 4800:6-329
ENUM must be greater or equal to mate parameter SNUM, 4801:2-857
ENUM range does not match SNUM
    1-999 or 1000-1499, 4801:2-857
ENUM requires an SNUM as its mate parameter, 4801:2-856
Environment variable
    FTRA_HOME, 0008:2-1, 0008:2-6, 0008:2-7, 0008:2-8
    JRE_HOME, 0008:2-1, 0008:2-6, 0008:2-7, 0008:2-8
    system, 0008:2-6, 0008:2-8
    user, 0008:2-6, 0008:2-7, 0008:2-8
environmental conditions, 4751:1-7
environmental requirements, 2969:2-5, 4625:6-4
EOAM, 4802:2-19
EOAP, 1021:1-6, 4601:2-3, 4601:6-60, 4601:A-15, 4625:1-7
    administration, 1021:8-12
    alarms, 0002:A-37, 0002:A-65, 4601:6-124, 4601:6-139
    checksums and alarms, 0002:A-29, 4601:6-115
    serial and Ethernet cabling diagram, 4593:5-133
    shelf, 4601:6-23
    update configuration, 0002:A-42, 0002:A-69, 4601:6-129, 4601:6-143
    updating, 0002:A-27, 4601:6-114
EOAP A
    shutting down, 4593:5-65, 4593:5-85, 4593:5-87, 4593:5-126
EOAP connectors
    Embedded OAP (24.0), 4318:2-132
EOAP Hardware Troubleshooting, 4593:5-5
EOAP power cables, 4601:6-39
EOAP Processor Card
    Embedded OAP (24.0), 4318:2-130
EOAP provisioning
    installing UAL software, 0002:A-8
EOAP shelf
    flange, 4593:5-72
    how to remove, 4593:5-71
    mounting brackets, 4593:5-72
    tools and equipment, 4601:6-15, 4601:6-22, 4601:6-60, 4601:6-64, 4601:6-65
EOAP / OAP Support of HSOP Protocol (Release 28.0), 4318:2-167
EOAP-to-Eagle Interface
    Embedded OAP (24.0), 4318:2-139
EOAP-to-LSMS Interface
    Embedded OAP (24.0), 4318:2-140
EOAP-to-SEAS Interface
    Embedded OAP (24.0), 4318:2-140
EPAP, 4318:2-1
    Backup PDB menu item, 4593:6-18

frequency for PDB backups, 4593:6-18, 4593:6-19
Halt MPS menu item, 4593:6-115
MPS Server memory to support, 4625:4-27
Normal Output, 2712:3-14
PDB backups, 4593:6-18, 4593:6-19
support of GSM features, 1021:6-1
user interface, 4593:6-115
EPAP 2.0 Alarm Migration from ELAP, 4318:2-169
EPAP 2.0 Alarm Migration from ELAP (Eagle 28.0), 4318:2-169
EPAP Audit, 4307:2-19
EPAP Database Backup Procedures, 4593:6-41
EPAP Verbose Output, 4593:6-13
EPAP/ELAP 2.0 Security and UI Enhancements, 4318:2-170
EPAP/ELAP 2.0 Security and UI Enhancements (Release 28.0), 4318:2-170
epapconfig, 0007:2-64, 4307:5-27, 4307:5-30
EPRI cannot be less than PRI, 4801:2-200
equipment required
initial installation, 4601:6-23
equipment, MPS hardware, 1021:6-2
EROUTE capacity normal, card(s) abnormal, 4593:3-578
EROUTE is Removed, 4593:3-574
EROUTE not configured, 4801:2-466
EROUTE System Capacity Exceeded, 4593:3-577
EROUTE System is Available, 4593:3-575
EROUTE System threshold Exceeded, 4593:3-576
Error code
30 - Read-only file system, 0008:2-118
32 - Broken pipe, 0008:2-118
35 - Unsupported value, 0008:2-118
40 - A destination address is required, 0008:2-116
41 - Protocol wrong type for socket, 0008:2-116
42 - The protocol is not available, 0008:2-116
43 - The protocol is not supported, 0008:2-116
44 - The socket type is not supported, 0008:2-116
45 - The operation is not supported on the socket, 0008:2-116
46 - The protocol family is not supported, 0008:2-116
47 - The address family is not supported, 0008:2-116
48 - The address is already in use, 0008:2-116
49 - The requested address cannot be assigned, 0008:2-116
50 - Socket operation on non-socket, 0008:2-116
51 - The network is unreachable, 0008:2-116
52 - The network dropped the connection on reset, 0008:2-116
53 - Software caused the connection to abort, 0008:2-116
54 - The connection was reset by the peer, 0008:2-117
55 - No buffer space available, 0008:2-117
56 - The socket is already connected, 0008:2-117
57 - The socket is not connected, 0008:2-117
58 - Can’t send after socket shutdown, 0008:2-117
59 - Too many references: can’t splice, 0008:2-117
595 - File open failed, 0008:2-104
596 - The file name is already specified, 0008:2-104
597 - SFTP client packet send failure, 0008:2-104

598 - The SFTP connection is closed, 0008:2-104
599 - SFTP packet read failure, 0008:2-104
60 - The connection timed out, 0008:2-117
600 - SFTP protocol error, 0008:2-105
601 - Undefined, 0008:2-105
608 - SFTP received a invalid ID in the response received during a read operation on remote directory, 0008:2-105
609 - SFTP: Handle mismatch error, 0008:2-105
61 - The connection was refused, 0008:2-117
610 - Unexpected SSH2_FXP_ATTRS, 0008:2-105
611 - Unexpected SSH_FXP_NAME, 0008:2-105
612 - SSH_FXP_REALPATH request failure, 0008:2-106
613 - SSH_FXP_READLINK request failure, 0008:2-106
614 - unexpected SSH_FXP_NAME, 0008:2-106
615 - The SFTP client received more data than expected, 0008:2-106
616 - The SFTP client failed to read the data from the file descriptor, 0008:2-106
617 - Excessive identity files, 0008:2-107
62 - The network is down, 0008:2-118
624 - The debug levels allowed for SSH protocol in openSSH is 0-9, 0008:2-107
625 - Failure to read the client configuration file, 0008:2-107
626 - Invalid compression level is specified in the client configuration file, 0008:2-107
627 - SSH failure to setup the IO with the server, 0008:2-107
628 - SSH failure to open the channel for the SSH connection with the server, 0008:2-107
629 - SSH failure to setup the channel for the SSH connection with the server, 0008:2-107
630 - SSH failure to verify the SSH client host key, 0008:2-107
631 - SSH user authentication failure, 0008:2-108
632 - The authentication method is NULL in the client software, 0008:2-108
633 - Permission is denied by the server due to authentication failure, 0008:2-108
633 - User login failure, 0008:2-104
640 - A bad message was received during the SSH authentication, 0008:2-108
641 - Missing authentication context, encountered during the SSH user authorization, 0008:2-109
642 - Failure during the public key read / verification operation, 0008:2-109
643 - Undefined SFTP / SSH error, 0008:2-109
644 - Unexpected SSH_FXP_STATUS error, 0008:2-109
645 - A bad option was specified in the SSH client on the Eagle, 0008:2-109
646 - An unsupported escape character was used in the SSH client on the Eagle, 0008:2-109
647 - An unsupported cipher type was used in the SSH client on the Eagle, 0008:2-109
648 - An unsupported MAC type was used in the SSH client on the Eagle, 0008:2-110
649 - A bad port was used in the SSH client on the Eagle, 0008:2-110
65 - There is no route to the host, 0008:2-118
656 - Bad forwarding was used in the SSH client on the Eagle, 0008:2-110
657 - Bad forwarding ports were specified in the SSH client on the Eagle, 0008:2-110
658 - A bad dynamic port was specified in the SSH client on the Eagle, 0008:2-110
659 - The host was not specified in the SSH client on the Eagle, 0008:2-111
660 - An invalid option or argument was specified in the SSH client on the Eagle, 0008:2-111
661 - The hostname was not specified in the SSH client on the Eagle, 0008:2-111
663 - The SSH client was unable to load the cipher type on the Eagle, 0008:2-111
664 - Asynchronous IO is not supported on IPSM, SSH client error, 0008:2-111
665 - Compression is already enabled in the SSH client on the Eagle, 0008:2-111
666 - Unknown cipher number on the SSH client on the Eagle, 0008:2-111
667 - The SSH client key length is invalid, 0008:2-111
668 - No key is available on the SSH client on the Eagle, 0008:2-112

669 - The secure connection was closed by the remote server, 0008:2-112
67 - The host is down, 0008:2-118
670 - Connection failure due to network outage or the connection was lost due to a faulty SSHD / SFTP server or network, 0008:2-112
671 - An unexpected packet type was received from the SFTP / SSHD server, 0008:2-112
672 - A bad packet length was received from the SSHD / SFTP server, 0008:2-112
673 - A cryptographic attack was detected by the SSH client, 0008:2-112
674 - The SSH / SFTP client on the Eagle failed to read from the remote side, 0008:2-113
675 - Corrupted check bytes were detected on the SSH / SFTP client on the Eagle, 0008:2-113
676 - Corrupted MAC on input was detected by the SSH / SFTP client on the Eagle, 0008:2-113
677 - Corrupted pad on input was detected by the SSH / SFTP client on the Eagle, 0008:2-113
678 - SSH / SFTP tried to close a connection that is already closed, 0008:2-113
679 - The SSH / SFTP client on the Eagle failed to write to the remote side, 0008:2-114
680 - SSH / SFTP tried to set the packet size twice, 0008:2-114
681 - A bad packet size was detected by the SSH / SFTP client on the Eagle, 0008:2-114
682 - The connection timed out when SSH tried to connect to SSHD, 0008:2-115
683 - The SSH connection was refused by the remote server, 0008:2-115
684 - The SSHD server is unreachable, 0008:2-115
685 - The network has reset, 0008:2-115
686 - The SSH / SFTP connection has been aborted, 0008:2-115
687 - The SFTP / SSH connection has been reset by the peer, 0008:2-115
688 - Failed to allocate network buffers, 0008:2-115
689 - The SSH / SFTP socket is already connected, 0008:2-115
690 - The SSH / SFTP socket is not connected, 0008:2-115
691 - The network channel is down, 0008:2-115
692 - The SSHD / SFTP server connection host is down, 0008:2-115
693 - SFTP client channel read failure, 0008:2-115
694 - SFTP client channel write failure, 0008:2-115
695 - SFTP client channel open failure, 0008:2-115
Error Codes
FTP, 0008:2-103
Generic Network, 0008:2-116
SFTP, 0008:2-103
SSH, 0008:2-103
error codes, 4307:3-114, 4593:6-23
error conditions, 4593:6-28
error conditions corrected, 2712:3-11, 4593:6-5
Error in FEATCTRL.TBL date, maintenance required, 4801:2-801
Error message
STP Name does not exist, 0008:2-30
Error Message Format, 4307:5-13
Error message format, 4307:B-19
Error Message Reporting Enhancement (21.0), 4318:2-175
Error Messages, 4307:3-114, 4593:6-23
error messages
Logout on Communications Failures (22.0), 4318:4-92
error messages, ELAP
format, 4307:5-13
list of user interface, 4307:3-114, 4593:6-23
Errors
contacting Tekelec Technical Services, 0002:1-7, 0003:1-7, 0004:1-8, 0006:1-7, 4751:1-11, 4802:1-8, 4803:1-9, 4804:1-7

SFTP, 0008:2-104
SFTP Client, 0008:2-104
SSH Client, 0008:2-107
SSH / SFTP Connection / Setup, 0008:2-115
Errors - contacting the Customer Care Center, 0007:2-4
errors, displayed in GUI banner, 2712:3-10
Escape key to exit ELAP user interface operations, 4307:5-12
ESP, 0004:1-3, 0004:6-2, 0004:6-3, 0004:6-4, 0004:6-7, 0004:6-19, 4625:4-39
ESP Servers, 4625:5-15
ESP Subsystem Hardware Components, 4625:5-15
Ethernet, 0002:4-142, 0004:6-7, 4593:5-22
Quad FastEthernet Interface card, 4593:6-122
Quad FastEthernet Network Interface card, 4625:4-30
ethernet applique, 4625:3-95
Ethernet B Interface for IPGWx and IPLIMx, 4318:2-175
Ethernet connection, 0008:2-2
Ethernet hub description, 4626:2-13
Ethernet Link to the MPS - Configuring, 0007:2-31
Ethernet network
100BASE-T, 4307:2-7, 4307:2-8
10BASE-T, 4307:2-7
DSM networks, 4307:2-4, 4307:2-7
ELAP Sync, 4307:2-4, 4307:2-8
Ethernet switch
replace, 2969:7-4
ETN must be greater than TN, 4801:2-504
ETN parameter requires TN parameter, 4801:2-516
ETT already mapped for LSN and IO specified, 4801:2-365
ETT cannot be mapped to MTT with same value, 4801:2-365
ETT not defined for LSN and IO specified, 4801:2-364
eval, 4307:B-22
Event interval argument - not valid (C<col>), 4801:2-548
event reporting
MTP Restart (EAGLE 21.0), 4318:4-129
Example of Basic Error Correction vs. PCR
Preventive Cyclic Retransmission (PCR) (EAGLE 20.0), 4318:5-29
EXAP Banner Informational Messages, 4593:6-26
EXAP Error Messages, 4593:6-23
EXAP Messages, 4593:6-23
exception list, 4804:2-92
exception lists
Cluster Routing and Management Diversity (21.0), 4318:2-65
Excessive identity files - Error code 617, 0008:2-107
Exchange Secure Shell Keys, 4307:5-21
Exchange Secure Shell Keys menu, 4307:5-21
existing commands
MTP Restart (EAGLE 21.0), 4318:4-130
existing ELAP connection to LSMS, 4307:2-11
Exit Confirmation window, 0008:2-12
Exit menu, 0008:2-11, 4307:5-26
exit user interface operations with Escape key, 4307:5-12
Exit window, 0008:2-12, 0008:2-13

Exiting Degraded Mode, 4593:3-544
Exiting the FTRA application, 0008:2-4, 0008:2-12
expansion cabinets, 1021:4-10
expansion shields, 4601:3-16
expired password procedure, 4800:4-21
EXT ALM, 4601:C-20, 4625:3-26, 4626:C-19
EXT not valid with ACTION=RESET, 4801:2-312
Extended Bus Interface (20.0), 4318:2-178
extended services platform, 0004:6-2, 0004:6-19
Extended Services Platform Host Servers, 4625:4-39
extender board (FAP), 4593:2-7
Extension Frame, 4601:4-35
Extension frame, 4601:3-27
Extension Frame (EF), 4625:3-4, 4625:3-9
extension frame (EF), 4625:3-9
Extension frame 01, 4601:3-27
Extension frame 02, 4601:3-27
Extension frame 03, 4601:3-27
Extension frame 04, 4601:3-27
extension shelf, 4625:3-28
extension shelf backplane, 4625:3-31
Extension Shelf Backplane (23.0), 4318:2-178
extension shelf power connectors, 4601:B-61, 4626:B-24
External Alarm (EXT ALM), 4625:3-26
external alarm cable installation, 4601:5-87
external alarm connector, 4601:B-35, 4625:3-26
external interface descriptions
external interface descriptions, 4318:2-133
external tooth washer, 4601:5-69
External/Customer Alarm Interface, 4625:3-52

F

Failed accessing maintenance data, 4801:2-387
Failed accessing the memory equippage table, 4801:2-647
Failed reading ACG MIC table, 4801:2-449
Failed reading ACG NOC table, 4801:2-448
Failed reading GSM Options Table, 4801:2-608
Failed reading GSM SSN Table, 4801:2-609
Failed reading GTT DBMM table, 4801:2-479
Failed reading GTT Selector Table, 4801:2-609
Failed reading GTT Set Table, 4801:2-609
Failed Reading GTT TRANS table, 4801:2-478
Failed reading HOME SMSC ADDRESS table, 4801:2-594
Failed reading HOMERN Table, 4801:2-763
Failed reading INPOPTS Table, 4801:2-763
Failed reading level 2 timer set table, 4801:2-65
Failed reading level 3 timer set table, 4801:2-66, 4801:2-67
Failed reading Link Fault Sectionalization table, 4801:2-388
Failed reading linkset table, 4801:2-40
Failed Reading LNP LRN table, 4801:2-482
Failed Reading LNP MR table, 4801:2-481

Failed Reading LNP NPANXX table, 4801:2-482
Failed reading LNP Options table, 4801:2-511
Failed reading LNP Ported TN table, 4801:2-481
Failed Reading LNP Service Provider table, 4801:2-481
Failed Reading LNP Split NPANXX table, 4801:2-482
Failed Reading LNP SS Appl table, 4801:2-480
Failed Reading LNP TT SERV table, 4801:2-480
Failed reading MAS configuration table, 4801:2-51
Failed reading OAP configuration table, 4801:2-639
Failed reading redirect table, 4801:2-277
Failed reading Secondary Point Code (SPC) table, 4801:2-710
Failed reading SERV Selector Table, 4801:2-610
Failed reading shelf table, 4801:2-30
Failed reading site identification table, 4801:2-379
Failed reading SLTM table, 4801:2-74
Failed Reading SS Appl table, 4801:2-639
Failed reading STP options table, 4801:2-368
Failed reading terminal table, 4801:2-47
Failed reading the ATM link parameter set table, 4801:2-562
Failed reading the E1/T1 table, 4801:2-810
Failed reading the extended link table, 4801:2-257
Failed reading the GWS Stop Action Set table, 4801:2-645
Failed reading the IMT table, 4801:2-29
Failed reading the link table, 4801:2-30
Failed reading the MRN table, 4801:2-433
Failed reading the password table, 4801:2-331, 4801:2-333
Failed reading the route table, 4801:2-281
Failed reading the security log attributes table, 4801:2-437
Failed reading the UIM Threshold Table, 4801:2-696
Failed reading the user identification table, 4801:2-76
Failed reading the X.25 destination table, 4801:2-281
Failed reading the X.25 route table, 4801:2-281
Failed reading trouble text table, 4801:2-542
Failed reading tt map table, 4801:2-362
Failed reading/writing Extended Linkset Table, 4801:2-409
Failed reading/writing Extended STP Options Table, 4801:2-410
Failed to allocate network buffers - Error code 688, 0008:2-115
Failed User Logins, 4307:3-110
Failure during the public key read/verification operation - Error code 642, 0008:2-109
Failure Inhibiting EIR SS, 4593:3-652, 4593:3-653
Failure Inhibiting LNP SS, 4593:3-810
Failure Inhibiting Local SS, 4593:3-820
Failure on both IMT A and IMT B, 4593:3-198
Failure reading the GSM Map SCRN Table, 4801:2-748
Failure reading the GSM OPCODE Table, 4801:2-748
Failure reading the GSM SSN Screening Table, 4801:2-746
Failure to read the client configuration file - Error code 625, 0008:2-107
Failures detected on one IMT bus, 4593:3-195
FAK alarm - Clearing, 0007:2-161
FAK Alarm - Temporary
Clearing, 0002:B-37, 0006:A-12
fall-through case, 4318:5-20

False Link Congestion Management (21.0), 4318:3-1
Fan assemblies, 2969:7-2
Fan Assembly, 4601:5-54
fan assembly
    installed below DCM card, 4593:A-80
    part number label, 2969:B-3, 2969:B-6
    replace, 2969:7-18
Fan Assembly (EAGLE / GR-376 EOAP) Replacement, 4593:A-76
fan door, replacing, 4593:2-33
Fan feature must be enabled, 4801:2-735
fan filter, replacing, 2712:3-6
fan power cables
    install, 4601:6-42
fan replacement procedure, 4593:6-124
fan support, 4601:6-14
fan switch
    set to OFF, 4593:5-100, 4593:A-84, 4601:6-69, 4601:6-75
    set to ON, 4593:5-98, 4593:A-83
Fan Tray, 4625:3-118
fans
    Embedded OAP (24.0), 4318:2-138
FAP, 4593:2-2, 4601:4-8, 4601:5-164
FAP alarm conditions, 4593:2-7
FAP alarms, 4593:2-8
FAP component functions, 4593:2-5
FAP component replacement, 4593:2-6
FAP components, 4593:2-4
FAP components, hot swapping, 4593:2-6
FAP functions, 4593:2-3
FAP Load Balance Verification (PN 870-0243-XX only), 4593:2-25
FAP_JB (Jumper Board), 4601:4-6
Fast Ethernet switch, 1021:4-10
Fault, 4593:6-4
fault tolerance, 2712:2-19
FC, 4802:1-14
Feature
    Eagle OA&M IP Security Enhancements, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103
    EGTT, 0008:2-54
    FTP Retrieve and Replace, 0008:2-3
    GTT, 0008:2-54
    IP User Interface, 0008:2-3
feature
    X.25 Gateway, 0004:1-2
Feature bit configuration requires DSM card with VSCCP appl, 4801:2-626
feature commands
    LNP—Changes to Existing Commands (22.0), 4318:4-58
feature concept
    High Speed Master Timing (26.0), 4318:3-56
Feature corresponding to APPL not ON, 4801:2-247
feature functions
    PCS 1900 LNP Query (EAGLE 26.0), 4318:5-3
Feature Guide

documents
Feature Guide, 4625:1-12, 4626:1-15
Feature Manuals, 4601:1-14, 4626:1-13
Feature Notice, 4625:1-12, 4626:1-15
feature, LNP 48 MIllion Numbers, 4307:2-2
features
fan, 4593:5-99, 4593:A-84, 4601:6-74
G-Flex, 1021:6-1
G-Port, 1021:6-1
GSM, 1021:6-1
INP, 1021:6-1
LNP 48 MIllion Numbers, 1021:6-2
MPS system additional, 1021:6-10, 4625:4-28
MPS system supported, 1021:6-1
multiple point code support, 4804:2-40
Field
Command File, Update Tables window, 0008:2-79, 0008:2-80, 0008:2-82
Command List
Retrieve Tables, 0008:2-56
Update Tables, 0008:2-78
Current STP Selected:, 0008:2-39
File Name:, 0008:2-52
Select Starting Directory window, 0008:2-52
Select window, 0008:2-80
Files of type:
Select Starting Directory window, 0008:2-52
Select window, 0008:2-80
FTP Password, 0008:2-16, 0008:2-22
FTP UserName, 0008:2-16, 0008:2-21
IP Address, 0008:2-50, 0008:2-51
Backup - FTRA 2.0 or greater, 0008:2-16, 0008:2-20
Primary - FTRA 2.0 or greater, 0008:2-15, 0008:2-20
IP Address - FTRA 1.0, 0008:2-15, 0008:2-20
Look in:
Select Staring Directory window, 0008:2-52
Select window, 0008:2-80
Path, 0008:2-50
Selected Commands, Retrieve Tables, 0008:2-56
STP Name, 0008:2-4, 0008:2-15, 0008:2-16, 0008:2-18, 0008:2-23, 0008:2-27
STP name typed
FTRA 1.0, 0008:2-27
FTRA 2.0, 0008:2-27, 0008:2-28
STP Password, 0008:2-16, 0008:2-21
STP UserName, 0008:2-16, 0008:2-20
Subpath, 0008:2-50
Field Replaceable Units
guidelines, 2712:5-1
locating replacement procedures, 2712:5-2
part numbers, 2712:5-2
Field Replaceable Units (FRUs), 2712:5-2
Field Replaceable Units (FRUs), MPS, 2712:5-3, 2712:5-4, 4593:6-114
File already exists, 4801:2-125

file extension
.doc, 0008:2-35, 0008:2-72, 0008:2-96, 0008:2-100
.txt, 0008:2-35, 0008:2-72, 0008:2-96, 0008:2-100
File format
CSV, 0008:2-1, 0008:2-54, 0008:2-56, 0008:2-64, 0008:2-73, 0008:2-75
File menu
Command File Editor window, 0008:2-87
Connectivity Test Log, 0008:2-32, 0008:2-33
FTP-Based Table Retrieve Application window, 0008:2-12
Retrieve Tables Log, 0008:2-68, 0008:2-69
System Log, 0008:2-97, 0008:2-98
Update Tables Log, 0008:2-92, 0008:2-93
file mirrors, 4593:6-8
File Name: Field
Select Starting Directory window, 0008:2-52
Select window, 0008:2-80
File Naming Conventions
CLLI-based Names Disabled, 4593:4-8
CLLI-based Names Enabled, 4593:4-9
File open failed - Error code 595, 0008:2-104
File System, 2712:3-13, 4593:6-6
file system
backup procedure, 4593:6-42, 4593:6-52, 4593:6-56
speed for backups, 4593:6-17
tape capacity for backups, 4593:6-17
File System Alarm, 4593:6-7
File Transfer for LNP Measurements, 4593:2-18
File transfer in progress, 4801:2-90
File Transfer Utility (20.0), 4318:3-3
filelength not valid with ACTION=RENAME, 4801:2-312
FILELENGTH not valid with ACTION=RESET, 4801:2-311
FileManager, 0008:2-7, 0008:2-8
files
UNIX time zone, 4307:1-2, 4307:5-21, 4307:A-1
Files of type: Field
Select Starting Directory window, 0008:2-52
Select window, 0008:2-80
filters, maintenance for MPS Server, 4593:6-17
Fingerprint
Key
DSA, 0008:2-46, 0008:2-47
Public Host Key
Eagle, 0008:2-43, 0008:2-44, 0008:2-46, 0008:2-48
Public Key
Eagle, 0008:2-17, 0008:2-46, 0008:2-47
finish cables
backplane, 4601:6-53
fire protection requirements, 2969:2-5
First octet of IPADDR cannot be 127, 4801:2-260
Fixed connection, 0004:2-7
fixed connection, 4318:5-177
fixed disk

formatting, 0002:2-92
Fixed disk contains Eagle data (use FORCE=YES), 4801:2-59
fixed disk drive
overview, 0002:1-10, 0003:1-10, 4804:1-10
Fixed disk is inaccessible (internal problem), 4801:2-418
Fixed disk is not initialized, 4801:2-418
Fixed disk is not inserted, 4801:2-418
flag - strict host key, 0008:2-44
flange
EOAP shelf, 4593:5-72
Flash Memory Management (23.0), 4318:3-3
Changed Commands, 4318:3-5
IMT Command Changes, 4318:3-6
New Commands, 4318:3-4
Flexible Point Code Formatting (26.0), 4318:3-6
Affected Commands, 4318:3-7
Changed Commands, 4318:3-7
floor
loading, 2969:2-7
mark layout, 2969:4-4
plan, 2969:4-4
preparation
additional for raised floors, 2969:4-5
for heavy duty frame, 2969:4-3
raised
additional preparations, 2969:4-5
anchoring frame to concrete under raised floor, 2969:4-10
anchoring frame using support channel and spring nut, 2969:4-16
anchoring with support channel, 2969:4-13
slab
anchor assembly, 2969:4-7
slab, anchoring frame, 2969:4-6
Floor Layout, 4601:3-12
floor loading, 4625:6-5
floor plan, 4601:3-12
Floor Preparation, 4601:3-14
floor preparation, 4601:3-11, 4601:3-20
Flow Control, 4802:1-14
For Mate Point Code (MPC), MSSN, MateRC, RC must be provided, 4801:2-429
FORBID can not be STATE or LOCATION for the given OPNAME, 4801:2-752
Force Change on Initial Login, 4307:3-112
FORCE parameter
chg-oap-config, 0002:A-26, 4601:6-113
FORCE parameter required, 4801:2-150
FORCE parameter valid only with DATA parameter, 4801:2-727
Force Standby menu, 4307:3-17
FORCE valid only with APPL, DATA or INITCLK parameters, 4801:2-727
FORCE=YES is required to isolate card from IMT, 4801:2-421
FORCE=YES is required when card is allowed, 4801:2-325
FORCE=YES is required when TN range is greater than 50, 4801:2-643
FORCE=YES must be given to inhibit last OAP terminal, 4801:2-318
FORCE=YES must be specified, 4801:2-698

Force=YES must be specified, 4801:2-706
FORCE=YES must be specified for NUM greater than 1000, 4801:2-175
FORCE=YES must be specified if NUM is greater than 50, 4801:2-503
FORCE=YES must be specified to change existing stop action, 4801:2-653
FORCE=YES must be specified to delete entire node, 4801:2-268
FORCE=YES must be specified to initialize the last OAP, 4801:2-351
forced retransmission
    Preventive Cyclic Retransmission (PCR) (EAGLE 20.0), 4318:5-30
FORCED STANDBY, 4307:3-7
foreach, 4307:B-22
format
    ELAP error messages, 4307:5-13
format, output banner, 4800:4-15
format-disk, 4800:6-332
formatting
    fixed disk, 0002:2-92
    removable cartridge, 0002:2-80
frame
    anchoring
        to concrete under raised floor, 2969:4-10
        to raised floor using support channel, 2969:4-13
        to raised floor with support channel and spring nut, 2969:4-16
        to slab floor, 2969:4-6
    floor preparation, 2969:4-3
    layout, 2969:4-4
    template, 2969:4-4
    unpacking, 2969:4-2
Frame Anchoring, 4601:3-16
frame for EOAP shelf, 4601:6-23
Frame ID out of range, 4801:2-53
frame rail, 4593:5-71
Frame Side Panels, 4601:3-33
frame, MPS
    layout, 4625:4-13
FRCSMPLX - Simplex Mode, 4802:3-165
frequency for PDB backups, 4593:6-18, 4593:6-19
front view
    hub, 4625:4-47
    MPS frame layout, 4625:4-13
    MPS Server, 4625:4-25
    MPS Server detail, 4625:4-22, 4625:4-29
    Netra t 1400, 4625:4-25
FRU
    replacement
        tools required, 2969:7-4
FRUs, 2712:5-2
    guidelines, 2712:5-1
    locating replacement procedures, 2712:5-2
    part numbers, 2712:5-2
FRUs, MPS, 2712:5-3, 2712:5-4, 4593:6-114
FTA, wxtracting LNP measurements from, 4800:5-8
FTP Error Codes, 0008:2-103

FTP Password Field, 0008:2-16, 0008:2-22
FTP Retrieve and Replace (Release 29.0) (IP7 Release 7.0), 4318:3-10
FTP Retrieve and Replace Feature, 1021:3-9, 0008:2-3
FTP SERV table must contain one entry with application USER, 4801:2-591
FTP server, 0002:4-150, 0002:4-154, 0002:4-158, 0002:4-159, 0002:4-162, 0002:4-164, 0002:4-165, 0008:2-49, 0008:2-119
    secure, 0008:2-49
FTP Server Configuration, 0008:2-1, 0008:2-4, 0008:2-49
    Menu, 0008:2-11, 0008:2-49
        Browse button, 0008:2-50, 0008:2-51
        Close button, 0008:2-50
        IP Address, 0008:2-49, 0008:2-119
        IP Address Field, 0008:2-50, 0008:2-51
        Path Field, 0008:2-50
        Set button, 0008:2-50, 0008:2-53
        Subpath Field, 0008:2-50
    Menu window, 0008:2-21, 0008:2-49, 0008:2-50, 0008:2-103, 0008:2-106, 0008:2-119, 0008:2-120
FTP Server Data Set window, 0008:2-53
FTP Server password must be 1 - 15 characters in length, 4801:2-464
FTP Server table entry not found for this APP/IPADDR, 4801:2-338
FTP Server table must be accessible, 4801:2-337
FTP Server Verification procedure, 0008:2-119
FTP transfer already in progress, 4801:2-591
FTP UserName Field, 0008:2-16, 0008:2-21
FTP-Based Table Retrieve, 0008:2-12
FTP-Based Table Retrieve Application
    Edit Menu, 0008:2-14, 0008:2-49, 0008:2-78
    Help Menu, 0008:2-102
    View Menu, 0008:2-69, 0008:2-93, 0008:2-98
    window, 0008:2-11, 0008:2-12, 0008:2-18, 0008:2-31, 0008:2-36, 0008:2-39, 0008:2-58, 0008:2-69, 0008:2-70, 0008:2-71, 0008:2-78, 0008:2-93, 0008:2-94, 0008:2-95, 0008:2-98, 0008:2-99, 0008:2-100, 0008:2-102
ftptest, 4800:9-28
FTRA, 1021:3-9
    Command
        ftra -c, 0008:2-73, 0008:2-75
    Initialization, 0008:2-11
    STP IP connection
        secure, 0008:2-17, 0008:2-22
    version level, 0008:2-102
FTRA 1.0
    Current STP Selected, 0008:2-41
    STP Configuration Record, 0008:2-29
        Adding, 0008:2-18, 0008:2-19, 0008:2-20, 0008:2-21, 0008:2-22
    STP Connection Configuration Menu
        IP Address, 0008:2-16, 0008:2-20
        IP Address Field, 0008:2-15
        STP Name drop down list, 0008:2-23, 0008:2-25
        STP name typed, 0008:2-27
FTRA 2.0
    Current STP Selected, 0008:2-42
    FTP Server, 0008:2-49

Secure FTP Server, 0008:2-49
STP Configuration Record, 0008:2-29, 0008:2-30
Adding, 0008:2-18, 0008:2-19, 0008:2-20, 0008:2-21, 0008:2-22
STP Connection Configuration
Menu window, 0008:2-49
STP Connection Configuration Menu
Backup IP Address, 0008:2-16
Backup IP Address Field, 0008:2-20
IP Address
Backup, 0008:2-16, 0008:2-20
Primary, 0008:2-15, 0008:2-20
Primary IP Address, 0008:2-16
Primary IP Address Field, 0008:2-20
Secure Connection Box, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-43, 0008:2-48, 0008:2-49
STP Name drop down list, 0008:2-23, 0008:2-24, 0008:2-25, 0008:2-26
STP name typed, 0008:2-27, 0008:2-28
FTRA application
exiting, 0008:2-4, 0008:2-12
starting, 0008:2-4
using, 0008:2-4
ftra -c command, 0008:2-73, 0008:2-75
ftra file, 0008:2-44
FTRA icon, 0008:2-11
FTRA Requirements
Hardware, 0008:2-2
Unix Workstation, 0008:2-2
Windows Workstation, 0008:2-2
Software, 0008:2-2
Unix Workstation, 0008:2-2
Windows Workstation, 0008:2-2
FTRA software
installing, 0008:2-4
Unix, 0008:2-7
Windows, 0008:2-5
FTRA window
GTT Warning window, 0008:2-54
Retrieve Tables, 0008:2-4, 0008:2-54, 0008:2-55, 0008:2-58, 0008:2-73
description, 0008:2-56
GTT Warning window, 0008:2-54
Update Tables, 0008:2-4, 0008:2-77, 0008:2-78, 0008:2-79, 0008:2-80, 0008:2-81, 0008:2-86, 0008:2-87, 0008:2-90, 0008:2-91, 0008:2-92
description, 0008:2-78
Select, description, 0008:2-80
Update Validation Complete, 0008:2-82, 0008:2-83, 0008:2-84
Update Validation Complete with errors, 0008:2-84
ftra.bat, 0008:2-7, 0008:2-44
FTRA_HOME environment variable, 0008:2-1, 0008:2-6, 0008:2-7, 0008:2-8
Full LNP database reload initiated, 4593:3-883
full point code, 4804:2-3
Full Point Code must be specified, 4801:2-464
Full Routing Keys, 0003:2-24
Fully specified connection required to change OPEN, 4801:2-693

Functional Description, 4307:2-19
fuse, 4601:4-21, 4601:5-142
fuse alarm, 4593:2-8
Fuse Alarm Interface, 4625:3-52
fuse alarm verification, 4601:5-163
Fuse Amp, 4601:4-9
Fuse and Alarm Panel, 4601:4-5, 4625:3-121, 4625:3-131
fuse and alarm panel, 4593:2-2
Fuse and Alarm Panel (FAP), 4625:3-7, 4625:3-14, 4625:3-22, 4625:3-31
fuse and alarm panel (FAP), 4625:3-119
Fuse and alarm panel front items, 4593:3-8
fuse and alarm panel P/N 804-0007-06, 4601:5-144, 4625:3-127, 4625:3-130, 4625:3-136
Fuse and Alarm Panel Rear View, 4625:3-128
Fuse Flag Color, 4601:4-9
fuse holder board (FAP), 4593:2-7
Fuse Holders, 4601:4-7
Fuse Location, 4601:4-24
fuse panel, 4593:5-6
Fuse Panel alarm has cleared, 4593:3-166
fuse panel shelf power connectors, 4601:B-68, 4626:B-28
Fuse Positions, 4601:4-23
fuse positions
    DCM fan assembly, 4593:3-389
    EOAP, 4593:5-6
Fuse Spares Inventory, 4593:2-35
fuse, blown, 4593:2-8
FWORD can only be used with PADDR, 4801:2-302
FWORD is not supported at this time, 4801:2-302

G

Gateway configuration procedure, 0004:2-9
Gateway Measurements, 4593:4-110
Gateway routing, 0004:2-5
gateway routing, 4318:5-175
Gateway Screening
    LNP—Impact of LNP on Other Features (22.0), 4318:4-64
Gateway Screening (GWS), 4625:3-87
Gateway Screening (GWS) Configuration, 0005:2-1, 0005:3-1, 0005:4-1, 0005:5-1, 0005:6-1, 0005:7-1, 0005:8-1, 0005:9-1, 0005:10-1, 0005:11-1, 0005:12-1, 0005:13-1, 0005:14-1, 0005:15-1
Gateway Screening Change commands
    Calling Name Conversion Facility (CNCF) (23.1), 4318:2-56
Gateway Screening Enter commands
    Calling Name Conversion Facility (CNCF) (23.1), 4318:2-55
Gateway Screening Retrieve commands
    Calling Name Conversion Facility (CNCF) (23.1), 4318:2-56
Gateway screening rules table is full, 4801:2-240
Gateway Screening States, 0005:2-5
Gateway Screening stop action commands
    Calling Name Conversion Facility (CNCF) (23.1), 4318:2-55
Gateway STP - GTWYSTP, 4802:3-166
Gateway STP impact

National Spare Network Indicator Support (EAGLE 22.2), 4318:4-148
gateway STP impact
National Spare Network Indicator Support (EAGLE 24.0), 4318:4-150
Gateway Threshold Exceeded Notification (22.0), 4318:3-25
Gbyte, 4802:1-14
general instructions for MPS alarm recovery procedures, 2712:3-18
general purpose relay connector 01, 4601:B-38, 4626:B-10
general purpose relay connector 02, 4601:B-39, 4626:B-11
General Purpose Relay Connectors, 4625:3-28
General Purpose Serial Interface Connector, 4625:3-28
General Purpose Service Module-II (GPSM-II) for MCAP Slot (Release 28.0), 4318:3-31
general requirements
Nested Cluster Routing (EAGLE 26.0), 4318:4-155
Generic Network Error Codes, 0008:2-116
Generic Program Load, 4802:1-14
getcomm, 0003:3-151
G-Flex, 4318:2-1
GFLEX and LNP are mutually exclusive, 4801:2-775
G-Flex C7 Relay (26.3), 4318:3-13
Description, 4318:3-13
G-Flex feature, 1021:6-1
GFLEX feature must be on, 4801:2-598
GFLEX or EIR feature must be on, 4801:2-853
GFLEX or GPORT feature must be ON, 4801:2-868
GFLEX or GPORT feature must be on, 4801:2-786
GFLEX, INP, or GPORT feature must be ON, 4801:2-766
GFLEX/GPORT/EIR feature must be on, 4801:2-852
GFLEX/GPORT/INP must be ON or EIR must be enabled, 4801:2-850
GFLEX/INP/GPORT/EIR/LNP ELAP Config feature must be ON, 4801:2-827
Global Timing Interface, 4601:2-5
Global Title Translation, 0004:5-20, 4318:4-73, 4802:2-2, 4802:3-57, 4802:3-85, 4802:3-86, 4802:3-95, 4802:3-102, 4802:3-103, 4802:3-116, 4802:3-117, 4802:3-125, 4802:3-130, 4802:3-131, 4802:3-137, 4802:3-138, 4802:3-149, 4802:3-154, 4802:3-155, 4802:3-176, 4802:3-177
Global Title Translation (GTT) (20.0), 4318:3-28
Global Title Translation Modification, 0006:1-2, 0006:1-3, 0006:2-6, 0006:2-7, 0006:2-15, 0006:2-43, 0006:2-46, 0006:2-47, 0006:2-48, 0006:2-49, 0006:3-22, 0006:3-23, 0006:3-28, 0006:3-33, 0006:3-35, 0006:3-54, 0006:3-55, 0006:3-58, 0006:3-59, 0006:3-62, 0006:3-65, 0006:4-30, 0006:4-33, 0006:4-34, 0006:4-38, 0006:4-56, 0006:4-58, 0006:4-59, 0006:4-62, 0006:A-39
Global Title Translations, 0006:3-2
GLS have been removed from the system, 4593:3-379
GLS is at minimum service limit, 4593:3-375
GLS is available, 4593:3-374
GLS is not available, 4593:3-377
GMT, 4601:5-117
GMT fuse holders, 4593:3-7
GMT fuses, 4593:3-7
GP01, 4625:3-28
GP02, 4625:3-28
GPL, 4307:1-9, 4802:1-14
GPL has been corrected, 4593:3-131
GPL is corrupted, 4593:3-132
GPL management procedures, 0002:3-1

G-Port, 4318:5-20
G-Port feature, 1021:6-1
GPORT feature must be on, 4801:2-784
GPORT feature must be on when (N)SERV=GPORT, 4801:2-783
GPORT feature requires DSM Cards, 4801:2-782
G-Port MNP (26.2), 4318:3-19
    changed commands, 4318:3-21
    New Commands, 4318:3-20
    Upgrade Considerations, 4318:3-25
G-Port Mobile Number Portability database, 4318:5-19, 4318:5-20
GPSI, 4625:3-28
GPSM-II, 0008:2-3
GPSM-II card IMASP), 4800:4-2
GPSM-II LEDs, 4593:A-13
GPSM-II required to support more than 700 links, 4801:2-468
GR-376 EOAP, 1021:3-18, 4625:2-19
GR-376 Interface (26.0), 4318:3-28
    commands, 4318:3-28
    Limitations, 4318:3-30
Graphical User Interface, 4307:3-2
gray flag, 4601:4-23
green cable, 4601:4-19
grille, removing, 4593:2-32
ground
    main, 2969:6-5
    plane, 2969:6-3
    window, 2969:6-4
ground bar, 4601:4-15
Ground Cable, 4601:4-15
ground cable, 4601:4-15
ground cable installation, 4601:4-19
ground plane, 4601:4-13
Ground Window, 4601:4-14
Grounding, 2969:2-8
grounding, 4601:4-13, 4625:6-5
group administration, 2712:2-19
Group code must be in SID or SPC table, 4801:2-839
Group code not allowed when ITUDUPPC feat is OFF, 4801:2-838
Group code not allowed with ITUI, ANSI, or 24-bit ITU-N, 4801:2-837
Group Code of destination and Secondary PC must match, 4801:2-744
Group Code of DPCN and OPCN must match, 4801:2-788
Group code required for ITUN when ITUDUPPC feat is ON, 4801:2-838
Group Ticket Voucher (23.0), 4318:3-34
    Alarms, 4318:3-37
    Measurements, 4318:3-38
Group Ticket Voucher for SCCP Cards (27.0), 4318:3-39
    Changed Commands, 4318:3-40
    New UAMs/UIMs, 4318:3-41
    Upgrade Considerations, 4318:3-42
groupcode of DPC(s) and APC/SAPC must match when MULTGC=NO, 4801:2-811
Groups menu, 4307:3-98
Grp Code of dstn & True PC must match if no Secondary PC, 4801:2-744

GSM features, 1021:6-1
GSM MAP Screening (26.1), 4318:3-42
alarms, 4318:3-45
Changed Commands, 4318:3-44
Hardware Requirements, 4318:3-43
Limitations, 4318:3-46
New Commands, 4318:3-43
Upgrade Considerations, 4318:3-43
GSM MAP Screening Duplicate / Forward (Release 29.0), 4318:3-46
GSM Map Screening feature must be enabled, 4801:2-751
GSM Map Screening feature must be ON, 4801:2-745
GSM Map Screening rcvd unknown origin, 4593:3-894
GSM Map SCRN entry already exists or overlaps another entry, 4801:2-750
GSM networks, 4318:5-19
GSMOPTS
EIR Global Response is ON, 4593:3-958, 4593:3-959
GT Conversion table is full, 4801:2-841
GT# Translation Type already assigned, 4801:2-498
GT# Translation Type is not allowed to be a LNP alias, 4801:2-501
GT# Translation Type is not reserved for LNP, 4801:2-499
GT# Translation Type must not already be assigned, 4801:2-522
gt1, 4802:3-85, 4802:3-91, 4802:3-106
gt2, 4802:3-85, 4802:3-91
GTA commands
Enhanced GTT (26.0), 4318:2-154
GTA does not exist in any range, 4801:2-166
GTA does not match translation type's number of digits, 4801:2-166
GTA Length does not match GTT Set number of digits, 4801:2-621
GTA length is not defined for GTTSET, 4801:2-792
GTA length is not defined for TT, 4801:2-792
GTA range does not exist, 4801:2-165
GTA range is already assigned, 4801:2-167
GTA range overlaps a current range, 0006:3-22, 0006:3-44, 0006:3-54, 0006:4-28, 0006:4-48, 0006:4-54, 4801:2-164
GTI (A)=4, and GTI (X)=1 and 3 are not supported, 4801:2-612
GTI input clock anomalies detected, 4593:3-830
GTI network domain does not match GTT set, 4801:2-617
GTI / GTIA is invalid for specified (N)SERV, 4801:2-770
GTI / GTIA / GTII / GTIN not within specified range of 1 to 4, 4801:2-812
GTIA / GTI must not be specified when (N)SERV= GPORT, 4801:2-785
GTII must not be specified when (N)SERV = INPQ, 4801:2-769
GTT, 4307:1-9, 4318:5-21
GTT by TT Measurements and GR-376 Enhancements (26.0), 4318:3-48
Changed Commands, 4318:3-51
Upgrade Considerations, 4318:3-50
GTT commands
Eagle
rtrv-gtt, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-tt, 0008:2-54, 0008:2-59, 0008:2-65
GTT DBMM table is full, 4801:2-656
GTT Error Reporting Enhancements (21.0), 4318:3-51
GTT Feature, 0008:2-54

GTT feature must be ON, 4801:2-248
GTT must be on before EGTT can be on, 4801:2-611
GTT must be ON before GPORT can be ON, 4801:2-782
GTT must be ON before INP can be ON, 4801:2-761
GTT must be ON before MGTT can be ON, 4801:2-283
GTT must be ON before VGTT can be ON, 4801:2-737
GTT must be ON before XGTT can be enabled, 4801:2-471
GTT Selector already exists in GTII-TT-NP(V)-NAI(V), 4801:2-758
GTT Selector already exists in GTIN24-TT-NP(V)-NAI(V), 4801:2-597
GTT Selector already exists in GTIN-TT-NP(V)-NAI(V), 4801:2-757
GTT Selector does not exist in GTII-TT-NP(V)-NAI(V), 4801:2-759
GTT Selector does not exist in GTIN24-TT-NP(V)-NAI(V), 4801:2-598
GTT Selector does not exist in GTIN-TT-NP(V)-NAI(V), 4801:2-758
GTT Selector specified by GTI-TT-NP(V)-NAI(V) already exists, 4801:2-615
GTT Selector specified by GTI-TT-NP(V)-NAI(V) does not exist, 4801:2-616
GTT Set specified by GTTSN already exists, 4801:2-616
GTT Set specified by GTTSN does not exist, 4801:2-616
GTT Set specified by GTTSN has GTAs assigned to it, 4801:2-619
GTT Set specified by GTTSN has GTT Selectors assigned to it, 4801:2-618
GTT Set table is full, 4801:2-618
GTT Table Increase (Release 29.0), 4318:3-51
GTT table is full, 4801:2-191
GTT UIM 21 Digit Length Enhancement (Release 29.0), 4318:3-53
GTT Warning window, 0008:2-54
GTTSN must not be specified as NONE, 4801:2-618
Gtwy IP Address is invalid, 4801:2-703
Gtwy IP Address must be local to this cards A, B network, 4801:2-703, 4801:2-704
GTWYSTP - Gateway STP, 4802:3-166
GUI, 4307:1-9, 4307:3-2
GUI Main Screen, 4307:3-5
GWS and LNP must be ON before TLNP can be ON, 4801:2-654
GWS Error Reporting Enhancement (21.0), 4318:3-53
GWS feature must be ON, 4801:2-250
GWS MSU discard threshold exceeded, 4593:3-800
GWS MSU discarded by redirect function, 4593:3-714
GWS MSU too large to be redirected, 4593:3-716
GWS must be ON before CNCF can be ON, 4801:2-641
GWS must be ON if LAN is ON, 4801:2-245
GWS rcvd a priority that is not allowed, 4593:3-624
GWS rcvd AFTPC that could not be CNCFd, 4593:3-854
GWS rcvd AFTPC that could not be RDCTd, 4593:3-765
GWS rcvd CDPA that could not be CNCFd, 4593:3-850
GWS rcvd CDPA that could not be RDCTd, 4593:3-761
GWS rcvd CGPA that could not be CNCFd, 4593:3-852
GWS rcvd CGPA that could not be RDCTd, 4593:3-763
GWS rcvd Cld Party that is not allowed, 4593:3-629
GWS rcvd Clg Party that is not allowed, 4593:3-627
GWS rcvd DPC that is blocked, 4593:3-620
GWS rcvd DPC that is not allowed, 4593:3-616
GWS rcvd H0/H1 that is not allowed, 4593:3-735
GWS rcvd invalid GTI in TT screening, 4593:3-808
GWS rcvd ISUP that is not allowed, 4593:3-805

GWS rcvd nonSCCP msg in CGPA/CDPA screen, 4593:3-807
GWS rcvd nonSNM msg in DESTFLD screening, 4593:3-806
GWS rcvd OPC that is blocked, 4593:3-618
GWS rcvd OPC that is not allowed, 4593:3-614
GWS rcvd RSP, AFTPC not in routing tbl, 4593:3-696
GWS rcvd RSR, AFTPC not in routing tbl, 4593:3-697
GWS rcvd SCMG with not allowed AFTPC, 4593:3-633
GWS rcvd SIO that is not allowed, 4593:3-622
GWS rcvd TFA, AFTPC not in routing tbl, 4593:3-694
GWS rcvd TFC, AFTPC not in routing tbl, 4593:3-626, 4593:3-746, 4593:3-747, 4593:3-748
GWS rcvd TFP, AFTPC not in routing tbl, 4593:3-692
GWS rcvd TFR, AFTPC not in routing tbl, 4593:3-693
GWS rcvd Translation Type not allowed, 4593:3-631
GWS rcvd TT that could not be CNCFd, 4593:3-856
GWS rcvd TT that could not be RDCTd, 4593:3-767
GWS rcvd UPU, AFTPC not in routing tbl, 4593:3-695
GWS/GTT shared table is full, 4801:2-235
GWSA, GWSM, GWSD are invalid without SCRSET specified, 4801:2-134
GX25 cannot make connection, 4593:3-787
GX25 DPC not defined, 4593:3-784
GX25 incorrect X25 address, 4593:3-778
GX25 logical channel cleared, 4593:3-789
GX25 outbound data exceeds packet size, 4593:3-774
GX25 route already connected, 4593:3-777
GX25 route not available, 4593:3-776
GX25 route not found, 4593:3-775
GX25 unexpected restart received, 4593:3-790
GX25 unrecognized X25 called address, 4593:3-786
GX25 unrecognized X25 calling address, 4593:3-785
GX25 unsupported MSU type received, 4593:3-782
GX25 unsupported packet type received, 4593:3-780

H

H0 and H1 cannot be specified for SI greater than 2, 4801:2-202
H0 and H1 must be specified for given SI, 4801:2-201
H0/H1 matches existing H0/H1 in given SR, 4801:2-201
H1 must be wild card if H0 is wild card, 4801:2-203
Halt MPS menu, 4307:5-24
Halt MPS menu item, 4593:6-115
Halt MPS screen, 4307:3-79
Hard Disk Drive, 4625:3-54
hard disk drive
    label, 2969:B-9, 2969:B-11, 2969:B-12, 2969:B-14, 2969:B-17
    part number, 2969:B-9, 2969:B-11, 2969:B-12, 2969:B-14, 2969:B-17
    replace, 2969:7-21
hard drive, 2969:7-2
hard drive and CD-ROM drive
    Embedded OAP (24.0), 4318:2-132
hard drive card
    replace, 4593:5-103
    troubleshoot, 4593:5-8

hard drive jumper settings, 4593:5-11
hard drives, 2969:7-2
hardware
platform, 1021:4-10
platform, MPS, 4307:2-3
verification, DSM system, 4307:4-6
Hardware and Installation Manuals, 4625:1-13, 4626:1-16
hardware configuration
Link Fault Sectionalization (21.0), 4318:4-15
Hardware Configuration Alarm, 4593:6-9
hardware descriptions, 4601:3-1, 4601:4-1, 4601:5-1, 4625:3-1, 4625:4-1
Hardware Manual, 4601:1-14
Hardware Notes, 4625:6-12
Hardware Operational Test Manual, 4601:2-11, 4626:1-35
Hardware Repair and Return, 4625:1-18
hardware required
Large System (27.2), 4318:4-1
Hardware Requirements, 0008:2-2
Unix Workstation, 0008:2-2
Windows Workstation, 0008:2-2
hardware requirements
48 Million Numbers (27.0), 4318:2-11
Eagle Application Support for E1 (26.3), 4318:2-104
Embedded OAP (24.0), 4318:2-129
Enhanced Bulk Download (25.0), 4318:2-143
GSM MAP Screening (26.1), 4318:3-43
High-Speed Multiplexer (HMUX) (27.2), 4318:3-64
INAP-based Number Portability (INP) (26.05), 4318:3-78
INP Number Normalization (26.3), 4318:3-82
Multi-Port LIM (EAGLE 27.1), 4318:4-147
STPLAN Port to DCM (EAGLE 26.0), 4318:5-87
TSM Warm Restart and Incremental Loading (EAGLE 26.0), 4318:5-144
Variable Length GTT (Eagle 26.1), 4318:5-166
Weighted SCP Load Balancing (Eagle 27.2), 4318:5-170
hardware return, 4593:1-10, 4601:1-20, 4625:1-18
hardware, MPS
list of equipment, 1021:6-2
overview, 4625:4-12
hardware, MPS frame
layout, 4625:4-13
hardware, MPS system configuration, 1021:6-4, 2712:2-5
HCMIM, 4625:3-111, 4625:3-112
dependencies, 4625:3-112
description, 4625:3-111
requirements, 4625:3-112
timing, 4625:3-115
header format, 4307:5-12
Heading 1, 4601:5-1
Health Check Procedure - MPS, 0007:2-79
Health Check, System
status and alarm reporting, 4307:4-2
heat-shrink, 4601:4-15

Heat-shrink gun, 4601:4-15
Heat-shrink gun (hot air blower), 4601:4-13
Heavy Duty Frame, 4601:3-27, 4601:3-28
heavy duty frame
anchoring to concrete under raised floor, 2969:4-10
anchoring to raised floor with support channel and spring nut, 2969:4-16
anchoring to slab floor, 2969:4-6
floor preparation, 2969:4-3
installing, recommended tools, 2969:4-3
Heavy-Duty Frame Panels, 4601:3-25
Help - Tekelec Technical Services, 0008:2-3, 0008:2-4, 0008:2-46, 0008:2-103, 0008:2-104, 0008:2-105, 0008:2-106, 0008:2-107, 0008:2-108, 0008:2-109, 0008:2-110, 0008:2-111, 0008:2-112, 0008:2-113, 0008:2-114, 0008:2-115, 0008:2-116, 0008:2-117, 0008:2-118
UK, 0008:2-3
USA, 0008:2-3
Help menu
FTP-Based Table Retrieve Application, 0008:2-102
hexadecimal, 0008:2-46
HH must be specified when PERIOD=SPECIFIC, 4801:2-115
High Density Interconnect (HDI), 4625:3-21, 4625:3-31
High Speed Clock A for card normal, 4593:3-231
High speed clock alarm(s) cleared, 4593:3-297
High Speed Clock B for card normal, 4593:3-232
High Speed Clocks A and B for card failed, 4593:3-229
High Speed Clocks A and B for card normal, 4593:3-243
High speed IMT packet router, 4625:3-38
High Speed Master Timing (26.0), 4318:3-54
administration, 4318:3-59
feature concept, 4318:3-56
maintenance, 4318:3-60
master clock, 4318:3-56
MCAP card, 4318:3-59
system clocks, 4318:3-56
TDM card, 4318:3-58
High Speed Operations Protocol, 1021:4-4
High-Capacity Multichannel Interface Module, 1021:3-11, 4625:3-111
High-Speed IMT Packet Router, 1021:3-6
High-Speed Master Timing, 1021:3-13, 4601:5-81, 4625:2-18
High-Speed Multiplexer, 1021:3-7, 4625:2-8
High-speed Multiplexer, 4601:1-6, 4601:5-6, 4601:5-91, 4601:5-140
High-Speed Multiplexer (HMUX) (27.2), 4318:3-62
Hardware Requirements, 4318:3-64
New / Changed Commands, 4318:3-63
Upgrade Considerations, 4318:3-65
HIPR, 1021:3-6, 4625:3-38
HLR, 4318:5-20
HMUX, 0004:6-7, 0004:6-19, 4601:2-3, 4601:5-83, 4625:3-37, 4625:3-43, 4626:1-32
HMUX not responding Error, 4593:3-498
HMUX responding normally, 4593:3-496
HMUXTVG must be ON before E5IS can be ON, 4801:2-778
HMUXTVG option, 0004:6-7
Holdover BITS Clock Support (21.0), 4318:3-65

holdover clock, 4601:5-112, 4625:3-139
holdover clock BITS clock source cables, 4601:5-115
holdover clock card placement, 4601:5-108
Holdover Clock FAP, 4601:5-112
holdover clock fuses, 4601:5-117
holdover clock installation, 4601:5-108
holdover clock output connections, 4601:5-112
holdover clock output panel frame ground, 4601:5-109
holdover clock power connections, 4601:5-109
holdover clock switch settings, 4601:5-110
Holdover clock trouble cleared, 4593:3-153
holes are drilled, 4601:3-21
Home Location Register (HLR), 4318:5-19
HOME SMSC specific addresses, 4318:5-23
Home SMSC Table is full, 4801:2-595
HOME SMSCADDR table, 4318:5-23
HOMERN Table is full, 4801:2-762
Host assignment to IPLIM/IPLIMI card not supported, 4801:2-830
Host Key - Secure Eagle
    Provisioning, 0008:2-43
host key checking - strict, 0008:2-44
Host Key Fingerprint
    Public
        Eagle, 0008:2-43, 0008:2-44, 0008:2-46, 0008:2-48
host key flag - strict, 0008:2-44
Host Name Referenced by Application Socket or Association, 4801:2-812
Host Name Still Referenced in IP Link Table, 4801:2-732
Host table is full, 4801:2-683
Host table must contain IP link addresses, 4801:2-691
Hostname must be unique, 4801:2-681
hosts.xml, 0008:2-43, 0008:2-44, 0008:2-46, 0008:2-47, 0008:2-48
hot air blower, 4601:4-15
hot-swap, 4318:5-80
hot-swapping FAP components, 4593:2-6
Hourly Maintenance Measurements, 4593:4-93
Hourly measurement collection in progress, 4801:2-117
hourly status message report
    Simplifying BIP (Board ID PROM) for Eagle STP Boards (EAGLE 23.1), 4318:5-79
how to remove EOAP shelf, 4593:5-71
HS Clock A for card failed, B normal, 4593:3-225
HS Clock B for card failed, A normal, 4593:3-227
HS Master Timing, 4601:5-83
HSOP, 1021:4-4
hsopEnabled File from the OAP - Removing from the OAP, 0007:2-150
Htap, 4601:4-9
Htapped, 2969:6-4, 4601:4-14
HTML output, 4307:3-3
http web server, 4307:3-3
hub
    description, 4625:4-47, 4625:4-50, 4626:2-13
    front LEDs, 4625:4-48, 4625:4-50, 4626:A-18
    front view, 4625:4-47

FRU, 2712:5-2, 4593:6-114
overview, 2712:2-5
rear view, 4625:4-48
replacement procedure, 2712:5-6, 4593:6-121
HVAC requirements, 2969:2-6
HW cannot support purchased TPS rate, 4593:3-605
HW limiting TPS rate alarm cleared, 4593:3-604

I

I/O architecture, MPS Server, 4625:4-27
I/O connectors, 4625:3-27, 4625:3-32
I/O devices, 4800:4-2
i2000 Hardware Reference, 4625:1-13, 4626:1-16
i3000, 4625:5-20
I3000 probe, 4625:5-20
Icon, FTRA, 0008:2-11
ID must be specified, 4801:2-414
Idle Port Logout, 4307:3-82
Idle Terminal Port Logout (21.0), 4318:3-65
Idle Timeout, 4307:3-110
IETF M3UA for “A” Link Connectivity (Release 28.1), 4318:3-67
IETF Protocol Update (Release 28.0), 4318:3-68
IETF Protocol Update (Release 28.1) (IP7 Release 6.0), 4318:3-68
If AUTO=yes, then DUPLEX and SPEED are not allowed, 4801:2-683
If DIR=BKWD, SDATE/STIME must be > EDATE/ETIME, 4801:2-859
If Domain name is specified, RSTDOMAIN is not valid, 4801:2-690
If GTIXLAT is 22, NAI and NP cannot be specified, 4801:2-800
If GTIXLAT is 24, NAI and NP must be specifie, 4801:2-800
If GWSA=OFF then GWSD must also be OFF, 4801:2-135
IF IO or ETT specified, BOTH opt. Parms must be specified, 4801:2-365
If IPADDR is specified SUBMASK is required, 4801:2-686
If NDIGITS = 0 then PREFIX parameter is invalid, 4801:2-36
If NGTI is 2, NNP and NNAI cannot be specified, 4801:2-844
If NGTI is 4, NNP and NNAI must be specified, 4801:2-844
If NGTI is 4, PC cannot be ANSI, 4801:2-890
If OAP parameter not specified as ALL, FORCE=YES required, 4801:2-640
If PARM is specified, PVALUE must be specified, 4801:2-684
If SDATE=EDATE, then ETIME after or same as STIME, 4801:2-407
If specified, BPS must be 2048000 for LIME1ATM Card, 4801:2-542
If specified, BPS must be 56000 for Multi Port LIM, 4801:2-423
If TIMER is specified, TVALUE must be specified, 4801:2-684
If you need assistance - Tekelec Technical Services, 0008:2-3, 0008:2-4, 0008:2-46, 0008:2-103, 0008:2-104, 0008:2-105, 0008:2-106, 0008:2-107, 0008:2-108, 0008:2-109, 0008:2-110, 0008:2-111, 0008:2-112, 0008:2-113, 0008:2-114, 0008:2-115, 0008:2-116, 0008:2-117, 0008:2-118
UK, 0008:2-3
USA, 0008:2-3
IGTTLS - Intermediate GTT Load Sharing, 0006:1-2, 0006:1-3, 0006:2-3, 0006:2-16, 0006:2-43, 0006:2-47, 0006:2-137, 0006:A-3, 0006:A-4, 0006:A-6, 0006:A-7, 0006:A-8, 0006:A-9, 0006:A-10, 0006:A-11, 0006:A-14, 0006:A-15, 0006:A-16
IGTTLS Feature
Activating, 0006:A-3

Turning off, 0006:A-14
ILA, 0004:6-7, 4593:A-19, 4593:A-25, 4601:2-3, 4601:A-6, 4625:3-18, 4625:3-19, 4625:3-21, 4625:3-37, 4625:3-56, 4625:3-57, 4626:1-33, 4626:A-3
Illegal Address Error, 4593:3-497
Illegal Address Error has Cleared, 4593:3-495
Illegal attempt to delete yourself, 4801:2-103
impact on other features
Multiple Point Code Support (EAGLE 26.05), 4318:4-140
Improved Routing Management (20.0), 4318:3-76
IMT, 4601:2-3, 4625:3-7, 4625:3-19, 4625:3-28, 4625:3-32, 4625:3-90, 4626:1-32, 4626:1-33, 4802:1-14
IMT allowed, 4593:3-179
IMT Bus alarm cleared, 4593:3-186
IMT Bus States, 4593:3-10
IMT Cables, 4601:5-7
IMT command changes
Flash Memory Management (23.0), 4318:3-6
IMT connectors, 4625:3-28, 4625:3-32
IMT Fault Isolation (22.0), 4318:3-76
IMT fault test in progress, 4801:2-444
IMT inhibited, 4593:3-180
IMT interface circuits, 4625:3-63
IMT statistics collection in progress - Repeat later, 4801:2-448
IMT Subsystem Alarms (20.0), 4318:3-77
IMT System Alarm Level Determination, 4593:3-10
IN, 4802:3-30
in, 0003:3-148, 0003:3-182, 0003:3-381, 0003:3-391
IN Platforms (PPSMS Servers), 4318:5-20
INAP-based Number Portability (INP) (26.05), 4318:3-77
enhanced commands, 4318:3-79
hardware requirements, 4318:3-78
New Commands, 4318:3-78
Incompatible HW for provisioned slot, 4593:3-181
Inconsistent DSM Card Alarm, 4307:2-19
Incorrect DB version (<database>, <disk>, <MASP status>), 4801:2-419
Incorrect information unit, expecting card location - <parm>, 4801:2-26
Incorrect information unit, expecting IP address - <parm>, 4801:2-23
Incorrect information unit, expecting mnemonic - <parm>, 4801:2-24
Incorrect information unit, expecting number - <parm>, 4801:2-23
Incorrect information unit, expecting number or * - <parm>, 4801:2-25
Incorrect information unit, expecting number or none - <parm>, 4801:2-27
Incorrect information unit, expecting number or range - <parm>, 4801:2-23
Incorrect information unit, expecting point code - <parm>, 4801:2-24
Incorrect information unit, expecting string - <parm>, 4801:2-24
Incorrect information unit, translation type - <parm>, 4801:2-25
Incorrect input, expecting number, * or range - <parm>, 4801:2-27
Incorrect Motherboard - CPU, 4593:3-545
Incorrect port configuration, 4593:3-383
Increase Gateway Screening Screen Sets to 255 (22.0), 4318:3-83
Increase the Number of Mated Application Entries (22.0), 4318:3-101
Increased GTT Transactions (21.0), 4318:3-101
Increased Linkset Capacity, 4318:3-81
Increased Linkset Capacity (Release 28.0), 4318:3-81

Increasing
LRN Quantities on the Eagle, 0007:2-153
NPANXX Quantities on the Eagle, 0007:2-153
Increasing the FTA (File Transfer Area)
Security Log Increase (EAGLE 26.05), 4318:5-71
Increasing the Size of the Service Provider ID Table (23.2), 4318:3-101
incremental loading
TSM Warm Restart and Incremental Loading (EAGLE 26.0), 4318:5-133
incremental loading, DSM, 4307:2-17
INCSLP, 4802:3-165, 4802:3-169, 4802:3-171
IND, 4802:1-14, 4802:4-13, 4802:4-14, 4802:4-15, 4802:4-17, 4802:4-19, 4802:4-20
IND cannot be greater than 3, 4801:2-303
IND parameter must be 6 or 10, 4801:2-457
indicator lights
tape drive, 4625:4-21
information messages, 4307:3-117, 4307:3-118
informational banner messages, 4593:6-26
Inh EIR SS request already outstanding, 4593:3-651
Inh LNP SS request already outstanding, 4593:3-809, 4593:3-819
inh-alm, 4800:6-337
inh-card, 4800:6-342
inhfepalm, 0003:3-151
Inhibit rejected, target terminal is not equipped, 4801:2-238
inhibited alarms, 4800:4-3
inhibiting
DSM, rmv-card, 4751:8-3
mated application subsystem, 4751:8-4
inh-imt, 4800:6-343
inh-map-ss, 4800:6-344
inh-map-ss command, 4751:8-4
inh-slk, 4800:6-347
inh-trm, 4800:6-348
INIT=YES only valid with BID record, 4801:2-98
init-card, 4800:6-349
init-card command, 0008:2-43, 0008:2-46, 0008:2-47
init-flash, 4800:6-355
Initial Command Response Timeout, 4801:2-626
initial configuration steps, 4307:5-27
initial ELAP-LSMS connection, 4307:2-10
initial implementation, 0002:A-4
Initial Platform Manufacture, 4307:5-27
Initialization, 4307:5-9
initialization
ELAP, 4307:5-9
Initialization - ELAP, 0007:2-46
Initialization - ELAP 5.0, 0007:2-51
Initializing the FTRA, 0008:2-11
Initializing window, 0008:2-11
Initiate Upgrade, 4307:5-23
init-imt-gpl, 4800:6-359
init-mux, 4800:6-360
init-network, 4800:6-361

init-oap, 4800:6-364
init-sys, 4800:6-365, 4803:2-16
Init-sys already in progress at another terminal, 4801:2-106
INP and LNP are mutually exclusive, 4801:2-762
INP feature, 1021:6-1
INP feature must be ON, 4801:2-605
INP Number Normalization (26.3), 4318:3-82
    Description, 4318:3-82
    enhanced commands, 4318:3-82
    Hardware Requirements, 4318:3-82
INP or EIR feature must be ON, 4801:2-848
INP subsystem is offline in database, 4801:2-625
Input parameter - use of parameter not supported by this implementation (C<col>), 4801:2-553
Input parameter '<parm>' - missing (C<col>), 4801:2-552
Input parameter argument - flow-thru command string too long (C<col>), 4801:2-551
Input parameter argument - not valid or superfluous (C<col>), 4801:2-554
Input parameter argument - point code range error (C<col>), 4801:2-551
Input parameter argument - range error (C<col>), 4801:2-550, 4801:2-552
Input parameter argument - version range error (C<col>), 4801:2-550
Input syntax
    punctuation error (C<col>), 4801:2-545
inserting removable cartridge, 0002:2-8
Inserting the 2.3 Gbyte Removable Cartridge, 4593:2-13
inspection, post-installation, 2969:6-11
install
    card into EOAP shelf, 4593:5-75
    clock connection cable, 4601:6-44, 4601:C-36
    clock in / out cable, 4601:6-43
    cooling duct, 4601:6-20
    fan power cables, 4601:6-42
    mounting brackets, 4601:6-23
    replacement fan assembly, 4593:5-95, 4593:A-79
    terminal cables, 4601:6-48
Install Replacement Fan Assembly, 4593:A-79
Installation Elements, 4601:3-17
Installation Manuals, 4625:1-13, 4626:1-16
Installation Support, 4601:1-17
installation, MPS, 2712:2-12
Installer's Cable Running List, 4601:2-8, 4601:C-4, 4626:C-4
Installing
    FTRA software, 0008:2-4
        Unix, 0008:2-7
        Windows, 0008:2-5
    Java 2 Runtime Environment software, 0008:2-5, 0008:2-7
installing
    heavy duty frame, 2969:4-2
    Tekelec 1000 chassis in a frame, 2969:5-4
    UAL software, 0002:A-8
Installing Java Policy File, 4307:5-7
InstallShield Wizard, 0008:2-5
Insufficient #SCCP cards to support LIM - use FORCE=YES, 4801:2-669
Insufficient memory for LNP, 4593:3-520

Insufficient memory for provisioning, 4593:3-363
Integer value must be less than 65535, 4801:2-314
Integrated LIM Appliques (ILAs), 4625:3-18
Integrated LIM-AINF Card
    New Hardware (EAGLE 23.1), 4318:4-185
Integrated Sentinel, 1021:5-6, 4625:2-20, 4625:5-8
    Eagle Support, 0004:1-3, 0004:6-2, 0004:6-4, 0004:6-10, 0004:6-11, 0004:6-13, 0004:6-14, 0004:6-19, 0004:6-22, 0004:6-27
Integrated Sentinel (ESP Frame Side), 1021:5-8, 4625:2-23
Integrated Sentinel EAGLE STP Side, 4625:1-6
Integrated Sentinel Hardware Overview, 4625:5-9
Integrated Serial Communications Controller (ISCC), 4625:3-64, 4625:3-65, 4625:3-67, 4625:3-68
Interdependencies, 4601:5-84
Interface, 4625:3-103
interface
    accessing ELAP GUI, 2712:A-1
    accessing ELAP text, 2712:A-6
    ELAP user, 4593:6-17, 4593:6-115
    EPAP user, 4593:6-115
    MPS Server SCSI, 4625:4-27
    Quad FastEthernet Network Interface card, 4625:4-30
    SAI/P card, 4625:4-30, 4625:4-43
Intermed GTT Load sharing feature must be on, 4801:2-432
Intermediate GTT Load Sharing, 0006:1-2, 0006:1-3, 0006:2-3, 0006:2-16, 0006:2-43, 0006:2-47, 0006:2-137, 0006:A-3, 0006:A-4, 0006:A-6, 0006:A-7, 0006:A-8, 0006:A-9, 0006:A-10, 0006:A-11, 0006:A-14, 0006:A-15, 0006:A-16
Intermediate GTT Loadsharing (Release 28.1), 4318:3-102
internal disk drive
    see disk drive
internal point codes, 0003:3-4
International PC is identical to international CPC, 4801:2-72
Internet Explorer, 4307:5-3
Inter-processor Message Transport, 1021:3-5, 4625:2-6
Interprocessor Message Transport, 4601:5-7, 4625:3-97, 4802:1-14
Interprocessor Message Transport (IMT), 4601:5-7, 4625:3-7, 4625:3-9, 4625:3-61
interprocessor message transport (IMT) interface, 4625:3-87, 4625:3-93, 4625:3-100
Interval Index, 4802:1-14, 4802:4-2, 4802:4-3, 4802:4-4, 4802:4-5, 4802:4-13, 4802:4-19, 4802:4-21, 4802:4-22, 4802:4-31, 4802:4-32
Introduction, 0007:2-1, 4625:1-1, 4625:2-2
Intrusion Alert, 4307:3-83
intrusion alert, 4800:4-18
Intrusion Alert (21.0), 4318:3-104
INTVL, 4802:1-14, 4802:4-3, 4802:4-5, 4802:4-13, 4802:4-14, 4802:4-15, 4802:4-17, 4802:4-19, 4802:4-20, 4802:4-21, 4802:4-24, 4802:4-25, 4802:4-28, 4802:4-29, 4802:4-31, 4802:4-32, 4802:4-33
Invalid APPL selection for SERIAL init card command, 4801:2-696
Invalid BAUD value specified, 4801:2-48
Invalid card TYPE and APPL load type combination, 4801:2-31
Invalid card type for this command, 4801:2-82
Invalid character in IP address - <parm>, 4801:2-18
Invalid CLLI, 4801:2-135
Invalid combination - EDATE with STIME, 4801:2-409
Invalid combination of ADDR and PADDR specified, 4801:2-302

Invalid combination of parameters for a default routing key, 4801:2-776
Invalid combination of parameters for a partial routing key, 4801:2-774
Invalid combination of PSTNCAT and PSTNID values, 4801:2-803
Invalid compression level is specified in the client configuration file - Error code 626, 0008:2-107
Invalid destination application ID, 4801:2-80
Invalid destination table, 4801:2-11
Invalid digits in IS41 MAP Digits parm, 4593:3-772, 4593:D-5
Invalid digits in MAP MSISDN parameter, 4593:3-946
Invalid Domain name, 4801:2-685
Invalid drive specified, 4801:2-91
Invalid ENTTYPE for this TYPE, 4801:2-112
Invalid FC value specified, 4801:2-48
Invalid Feature Access Key, 4801:2-583
Invalid file length, 4801:2-126
Invalid filename entered, 4801:2-125
Invalid FTP Password warning window, 0008:2-22
Invalid FTP User Name warning window, 0008:2-21
Invalid GPL type for this command, 4801:2-108
Invalid H0/H1 or NH0/NH1 specified, 4801:2-530
Invalid hardware for EISCOPY to be on, 4801:2-780
Invalid Hostname, 4801:2-679
Invalid INTRVL value specified, 4801:2-410
Invalid IP Address warning window, 0008:2-20, 0008:2-51
Invalid IPADDR, 4801:2-307
Invalid Length for Map IMEI Parameter, 4593:3-737
Invalid length of conditioned digits, 4593:3-892
Invalid length of prefixed digits, 4593:3-949
Invalid link speed combination within linkset, 4801:2-37
Invalid linkset type for card, 4801:2-41
Invalid Loopback selection for LIME1ATM, 4801:2-344
Invalid name for adapter type, 4801:2-817
Invalid NCAI parameter has been entered, 4801:2-375
Invalid OAM card type for TSC sync, 4593:3-138, 4593:3-139
Invalid OAM drive, 4801:2-12
Invalid OAM HW config or an HMUX card is out of service, 4801:2-755
Invalid offset, 4801:2-540
Invalid originating application ID, 4801:2-80
Invalid parameter, 4801:2-310
Invalid parameter combination for SI, 4801:2-718
Invalid parameter combination specified, 4801:2-55
Invalid parameter for CCS7ITU or IPLIMI, 4801:2-570
Invalid parameter for ITU-N 24bit point code, 4801:2-362
Invalid parameter for SCCP, 4801:2-568
Invalid parameter for SS7ANSI, ATMANSI, IPLIM, or SS7IPGW, 4801:2-568
Invalid parameter for VSCCP, 4801:2-570
Invalid parameter specified for report type, 4801:2-445
Invalid parameters for ACTION=COPY, 4801:2-564
Invalid Part Number, 4801:2-581
Invalid password. Keyboard is locked. Enter UNLOCK command, 4801:2-334
Invalid PERIOD for this TYPE, 4801:2-111
Invalid point code, 4801:2-136
Invalid PORT for APPL, 4801:2-250

Invalid PRTY value specified, 4801:2-48
Invalid PVN, 4801:2-779
Invalid PVNMASK, 4801:2-793
Invalid SCSI device syntax, 4801:2-125
Invalid socket / association ratio for card type, 4801:2-468
Invalid source table, 4801:2-11
Invalid STP Name Error Message window, 0008:2-18
Invalid STP Name warning window, 0008:2-18
Invalid STP Password warning window, 0008:2-21
Invalid STP User Name warning window, 0008:2-20
Invalid Subnet Mask, 4801:2-680
Invalid system, 4801:2-12
Invalid System serial number, 4801:2-629
Invalid system serial number in database, 4801:2-583
Invalid table Id, 4801:2-126
Invalid TRM value for SEAS TDM port, 4801:2-318
Invalid TYPE, 4801:2-122
Invalid userID / password combination, 4801:2-331
inventory
    additional server, 2969:5-1
    frame, 2969:4-2
INW Allowed card to DDL crossload, 4593:3-849
INW Card failed to DDL crossload, 4593:3-848
INW Card failed to reset, 4593:3-845
INW Card reset command issued, 4593:3-838
INW Detected card loaded, 4593:3-840
INW Failed to assert DDL inhibition, 4593:3-846
INW Failed to remove DDL inhibition, 4593:3-847
INW MAIN card as last to be reset, 4593:3-836
INW Need to reset / remove / inhibit card, 4593:3-844
INW Removed DDL inhibition, 4593:3-843
INW Waiting for card loading validation, 4593:3-839
IP, 4625:3-19
IP Address, 0008:2-15, 0008:2-16, 0008:2-49, 0008:2-119, 0008:2-120, 0008:2-121
    Backup - FTRA 2.0, 0008:2-20
    Backup - FTRA 2.0 or greater, 0008:2-16
    IPSM, 0008:2-46, 0008:2-47
    Primary - FTRA 2.0, 0008:2-20
    Primary - FTRA 2.0 or greater, 0008:2-16
IP address, 0008:2-16
IP Address - FTRA 1.0, 0008:2-20
IP Address Field, 0008:2-50, 0008:2-51
    Backup - FTRA 2.0 or greater, 0008:2-16, 0008:2-20
    Primary - FTRA 2.0 or greater, 0008:2-15, 0008:2-20
IP Address Field - FTRA 1.0, 0008:2-15, 0008:2-20
IP address must be unique, 4801:2-690
IP Address requires 4 octets in the range 1 . . . 254 - <parm>, 4801:2-13
IP Address still referenced by the Def Router, 4801:2-631
IP Address warning message, 0008:2-43
IP addresses
    configure customer (provisioning) network, 4307:5-19
    configure DSM network, 4307:5-20

configure ELAP Sync network, 4307:5-19
default for DSM networks, 4307:2-7
default for ELAP Sync network, 4307:2-8
default router, 4307:5-19
Dialup PPP network, 4307:2-9
DSM networks, 4307:2-7
ELAP Sync network, 4307:2-8
provisioning (customer) network netmask, 4307:5-19
sample network, 4307:2-7
IP application routing key, 0003:3-3
IP application server processes, 0003:3-4
IP application servers, 0003:3-3
IP application socket, 0003:3-3
IP associations, 0003:3-3
IP card, 0003:3-3
IP communications link
Measurements Platform, 0002:4-150
IP connection
FTRA and STP
secure, 0008:2-17, 0008:2-22
IP connection available, 4593:3-170
IP Connection Available/Unavailable alarms, 4307:4-16
IP Connection Congestion Timeout, 4593:3-831
IP Connection Failed, 4593:3-739
IP Connection manually removed, 4593:3-173
IP Connection Refused, 4593:3-832
IP connection, cannot resolve RHOST, 4593:3-833
IP host, 0002:4-151, 0002:4-172, 0003:3-3
IP link, 0002:4-152, 0002:4-153, 0002:4-172, 0003:3-3
IP Link A is down, 4593:3-598
IP Link A is up, 4593:3-600
IP Link B is down, 4593:3-601
IP Link B is up, 4593:3-603
IP Node Address never entered or Card DB corrupt, 4801:2-307
IP options
drkq, 0003:3-151
getcomm, 0003:3-151
inhfepalm, 0003:3-151
ipgwabate, 0003:3-151
iplimabate, 0003:3-151
sctpcsum, 0003:3-151, 0003:3-376, 0003:3-406
setcomm, 0003:3-151
snmpcont, 0003:3-151
srkq, 0003:3-151
sync, 0003:3-144, 0003:3-151
trapcomm, 0003:3-151
IP protocol option, 0003:3-144
IP Route table full, 4801:2-704
IP routes, 0003:3-3
IP Security Enhancements - Eagle OAM
Activating, 0002:B-12
Deactivating, 0002:B-39

IP Services Module, 0002:4-168, 0002:4-179
IP User Interface
Telnet Support, 4318:3-123
IP User Interface Controlled Feature
Activating, 0002:B-3
Deactivating, 0002:B-39
IP User Interface Feature, 0008:2-3
IP7 connection congested, 4593:3-171
IP7 connection unavailable, 4593:3-167
IP7 Front End, 4625:4-4, 4625:4-5, 4625:4-6, 4625:4-9, 4625:4-44, 4626:A-17
IP7 Secure Gateway, 1021:1-4, 4601:1-10, 4625:1-6
IP7 Secure Gateway Options, 0003:3-3
IP7 Transport Feature (26.1), 4318:3-113
Changed Commands, 4318:3-114
New Features, 4318:3-113
IPADDR already assigned to another TCP/IP link, 4801:2-276
IPADDR and IPRTE cannot be the same address, 4801:2-272
IPADDR assigned to a TCP/IP link, 4801:2-263
IPADDR assigned to a TCP/IP node, 4801:2-261
IPADDR assigned to a TCP/IP router, 4801:2-276
IPADDR not assigned to a TCP/IP link, 4801:2-262
IPADDR not assigned to any TCP/IP link, 4801:2-270
IPADDR not assigned to specified LOC, 4801:2-268
IPADDR w/o IPRTE must match first 2 octets of TCP/IP link, 4801:2-266
IPADDR w/o IPRTE must match first 3 octets of TCP/IP link, 4801:2-266
IPADDR w/o IPRTE must match first octet of TCP/IP link, 4801:2-265
IPAPPL already assigned to specified LOC, 4801:2-267
IPAPPL on Node not assigned to specified LOC, 4801:2-269
IPAPPL on node not connected to any TCP/IP link, 4801:2-271
IPC must be a Private Point Code, 4801:2-877
ipgwabate, 0003:3-151
IPGWI
activate signaling link, act-slk, 0003:3-75, 0003:3-133, 0003:3-148, 0003:3-170, 0003:3-182, 0003:3-199, 0003:3-200, 0003:3-214, 0003:3-215, 0003:3-291, 0003:3-293, 0003:3-312, 0003:3-314
display card status, rept-stat-card, 0003:3-146, 0003:3-166, 0003:3-180
display signaling link status, rept-stat-slk, 0003:3-145, 0003:3-148, 0003:3-165, 0003:3-170, 0003:3-178, 0003:3-182, 0003:3-199, 0003:3-214, 0003:3-291, 0003:3-312, 0003:3-381, 0003:3-391
ipgwi, 1021:3-20, 0003:2-4, 0003:2-21
IPGWI link must be in a single link linkset, 4801:2-738
IPGWx Linkset
Configuring, 0003:3-41
Mate
Configuring, 0003:3-62
IPGWx M3UA connections - migrating IPLIMx M3UA links to, 0003:3-127, 0003:3-138, 0003:3-139, 0003:3-140, 0003:3-141, 0003:3-142, 0003:3-143
IPISUP Feature must be on, 4801:2-700
IPLIM
activate signaling link, act-slk, 0003:3-75, 0003:3-133, 0003:3-148, 0003:3-170
display card status, rept-stat-card, 0003:3-166, 0003:3-180
display signaling link status, rept-stat-slk, 0003:3-148, 0003:3-165, 0003:3-170, 0003:3-178, 0003:3-381, 0003:3-391
iplim, 1021:3-20, 0003:2-3

IPLIM Protocol Support Enhancement (Release 28.1) (IP7 Release 6.0), 4318:3-117
iplimabate, 0003:3-151
iplimi, 1021:3-20, 0003:2-3
IPLIML2 is only valid for IPLIMx SLK, 4801:2-536
IPLIMx ASPs cannot be resident is AS, 4801:2-578
IPLIMx M3UA Signaling Links - Migrating to IPGWx M3UA connections, 0003:3-127, 0003:3-138, 0003:3-139, 0003:3-140, 0003:3-141, 0003:3-142, 0003:3-143
IPLIMx to 8 Points (Release 29.1) (IP7 Release 7.1), 4318:3-118
IPM, 4307:5-27
IPMX, 4626:1-33
IPMX backplane connector, 4626:B-15
IPMX backplane connectors, 4626:B-20
IPMX/HMUX Card Replacement, 4593:A-14
IPPORT already assigned, 4801:2-264
IPPORT can only be specified if IPADDR is specified, 4801:2-264
IPPORT on node not assigned to specified LOC, 4801:2-269
IPPORT on Node not connected to any TCP/IP link, 4801:2-270
IPRTE address assigned to TCP/IP link, 4801:2-274
IPRTE address must use first 2 octets of Class B TCP/IP Link, 4801:2-275
IPRTE address must use first 3 octets of Class C TCP/IP Link, 4801:2-275
IPRTE address must use first octet of Class A TCP/IP Link, 4801:2-274
IPSM, 0002:4-168, 0002:4-179, 0002:4-181, 0008:2-3, 0008:2-43, 0008:2-45, 0008:2-46, 0008:2-47, 0008:2-120, 0008:2-121
IPSM card not equipped, 4801:2-131
IPSM card(s) must be inhibited to enable telnet feature, 4801:2-840
IPSM IP Address, 0008:2-46, 0008:2-47
IPTPS must be divisible by 10, 4801:2-875
IPTPS not allowed for non-IPGWx linksets, 4801:2-874
IPTPS required for IPGWx linksets, 4801:2-873
IS-41 LNP Qry rejected
WNP is OFF, 4593:3-904
IS412GSM must be provisioned before SERVERPFX, 4801:2-887
ISCC Interface Loopback Test (22.0), 4318:3-130
ISCC loopback failed, 4593:3-802
ISCC loopback in progress, 4593:3-804
ISCC loopback success, 4593:3-801
Isolation sheet, 4601:3-20
isolator pad, 2969:4-4
ISUP Normalization, 0003:2-38
ISUP normalization feature must be enabled to set NORM=YES, 4801:2-803
ISUP variant provisioning, 0003:3-4
ISUPMT/TUPMT already exists in given SR, 4801:2-219
ISUPMT/TUPMT does not exist in given SR, 4801:2-219
ISVM, 4802:3-30
ISVM TT required before OAP update, 4801:2-673
ITU ANSI translation not supported, 4593:3-661
ITU Duplicate Point Code Routing (26.05), 4318:3-149
Enhanced Commands, 4318:3-151
ITU entries not allowed when ANSIGFLEX is on, 4801:2-886
ITU Gateway Measurements Enhancements (26.05), 4318:3-157
Enhanced Commands, 4318:3-159
New Measurements Reports, 4318:3-157

ITU GWY
CGB buffer full, 4593:3-732
CPC conversion failure, 4593:3-722
GRS buffer full, 4593:3-730
HOH1 conversion failure, 4593:3-726
Invalid ISUP msg structure, 4593:3-729
OPC conversion failure, 4593:3-724
rcvd msg type cannot convert, 4593:3-727
RSC buffer full, 4593:3-731
ITU International Capability Point Code, 4802:1-13
ITU International Point Code, 4802:1-16
ITU MTP Restart (26.0), 4318:3-151
Changed Commands, 4318:3-152
Limitations, 4318:3-153
Measurements, 4318:3-153
Product Description, 4318:3-151
UIMs, 4318:3-153
Upgrade Considerations, 4318:3-152
ITU National Capability Point Code, 4802:1-13
ITU National Point Code, 4802:1-16
ITU National Point Code must be full point code, 4801:2-761
ITU network
cluster management, 4804:2-97
ITU PC parameters are invalid for ANSI cards, 4801:2-569
ITU point codes are not supported when DOMAIN=X25, 4801:2-145
ITU SLS enhancement
bit rotation, 4804:3-28
CIC bit, 4804:3-29
ITU SLS Enhancements (26.0), 4318:3-154
Changed Commands, 4318:3-154
Restrictions, 4318:3-155
Upgrade Considerations, 4318:3-155
ITU-ANSI SCCP Conversion, 4802:2-3, 4802:2-4
ITU-ANSI-China SCCP Conversion, 0006:1-2, 0006:2-3, 0006:2-6, 0006:2-7, 0006:2-16, 0006:2-17, 0006:2-30, 0006:2-33, 0006:2-40, 0006:2-43, 0006:2-44, 0006:2-47, 0006:2-48, 0006:2-49, 0006:2-70, 0006:2-72, 0006:2-83, 0006:2-87, 0006:2-93, 0006:2-118, 0006:2-124, 0006:2-160, 0006:2-161, 0006:2-169, 0006:2-170, 0006:2-177, 0006:2-179, 0006:2-191, 0006:2-192, 0006:3-2, 0006:3-21, 0006:3-23, 0006:3-29, 0006:3-33, 0006:3-54, 0006:3-55, 0006:3-56, 0006:3-59, 0006:3-63, 0006:4-2, 0006:4-27, 0006:4-30, 0006:4-34, 0006:4-38, 0006:4-53, 0006:4-56, 0006:4-59, 0006:4-62, 0006:A-36, 0006:A-37, 0006:A-38, 0006:A-39, 0006:A-41, 0006:A-42
options
changing, 0006:2-191, 0006:2-193
ITU-INTL site id not defined, 4801:2-316
ITU-NATL site id not defined, 4801:2-316
ITUTFR parameter is only valid for ITU link sets, 4801:2-738
ITU-TFR Procedure (26.1), 4318:3-155
Changed Commands, 4318:3-156
UIMs, 4318:3-156
Upgrade Considerations, 4318:3-156

J

J-8, 4601:5-64, 4601:5-73
J-9, 4601:5-64, 4601:5-73
Java, 4307:5-3
Java 2 Runtime Environment, 0008:2-2, 0008:2-4, 0008:2-5, 0008:2-6, 0008:2-7, 0008:2-8
    software, installing, 0008:2-5, 0008:2-7
Java Plug-In, 4307:5-4
Java Policy File, 4307:5-7
JIPDIGITS - Jurisdiction Information Parameter Digits, 4802:3-165
JIPPRV - Jurisdiction Information Parameter, 4802:3-165
Job Router Service, 4593:6-22
Job Routing Server (JRS)
    description, 4307:2-11
JRE - Java Runtime Environment, 0008:2-2, 0008:2-7
JRE_HOME environment variable, 0008:2-1, 0008:2-6, 0008:2-7, 0008:2-8
jrs.log, 4593:6-22
jumper board, 4601:4-5
jumper board (FAP), 4593:2-7
jumper, diode, 4593:2-8
jumper, P71, 4593:2-8, 4593:2-10
jumper, P72, 4593:2-8, 4593:2-10
Jurisdiction Information Parameter - JIPPRV, 4802:3-165
Jurisdiction Information Parameter Digits - JIPDIGITS, 4802:3-165

K

Key Fingerprint
    DSA, 0008:2-46, 0008:2-47
    Public
        Eagle, 0008:2-17, 0008:2-46, 0008:2-47
key sequences
    KSR terminal, 4800:4-10
    VT320 terminal, 4800:4-10
Key values
    DIR, TTA, TTI, NP, NAI already exist, 4801:2-833
    DIR, TTA, TTI, NP, NAI does not exist, 4801:2-833
keyboard functions, 4800:4-10
Keyboard is locked. Enter UNLOCK command, 4801:2-4
Keyboard is not locked, 4801:2-335
keys, secure shell encryption, 4307:5-21
keywords, command, 4800:4-9
KSR function on VT320 terminals, 4800:4-5
KSR mode, 4318:3-124
KSR Terminal Feature (20.0), 4318:3-160
KSR terminal type, 0002:4-55
KSR terminals
    function on VT320 devices, 4800:4-5
    key sequences, 4800:4-10

L

L parameter cannot be used in combination with LOC, 4801:2-447
L2STATS not valid for IPGWI, 4801:2-740
L2STATS not valid for SS7IPGW, 4801:2-721
L2TSET cannot be specified if card application is SS7GX25, 4801:2-252
l2tset must be 1-10 for ANSI links, 11-20 for ITU, 4801:2-42
label
    cables, 4601:2-8, 4601:C-4, 4626:C-4
    fan assembly, 2969:B-3, 2969:B-6
    hard disk drive
        on part, 2969:B-9, 2969:B-11, 2969:B-12, 2969:B-14, 2969:B-17
    PCI card
        on card, 2969:B-12
Label each cable, 4601:4-20
Label Kit, 4625:3-135
label kit, 4601:2-10
LAN, 4625:4-47, 4625:4-50, 4626:2-13
LAN feature must be ON, 4801:2-248
Large System # Links Controlled Feature
    Enabling, 0003:3-110, 0004:2-138, 4804:3-9
Large System (27.2), 4318:4-1
    Changed Commands, 4318:4-2
    Hardware Required, 4318:4-1
    Limitations, 4318:4-3
    Upgrade Considerations, 4318:4-3
Large System (Phase 3)—1500 Links (Release 29.0), 4318:4-4
Large System—Phase 2 (Release 28.0), 4318:4-3
Last entry in given SR is ref'ed by another screen, 4801:2-206
Last route to DPC in use by GTT, 4801:2-143
Latching versus Non-latching LFS Tests
    Multiple LFS Tests (EAGLE 26.0), 4318:4-133
layered design, 1021:6-3
layout
    memory riser card memory bank, 4593:6-126
    motherboard memory bank, 4593:6-125
    MPS frame, 4625:4-13
layout, frame, 2969:4-4
LBP cannot exceed previously defined NEI LBP value, 4801:2-392
LBP has already been provisioned, 4801:2-390
LBP must have been previously defined in database, 4801:2-394
LBP or ALL parameter must be specified exclusively, 4801:2-394
LC already in use, 4801:2-297
LC can only be specified when TYPE=PVC, 4801:2-289
LC greater than maximum PVCs for link, 4801:2-296
LC must be specified when TYPE=PVC, 4801:2-289
LCA (Logic Cell Array), 4625:3-65
LED
    DCM, 4601:A-8
    DSM, 4601:A-8
LED, alarm, 2712:3-8
LEDs, 4593:5-6, 4601:4-23, 4601:A-1, 4626:A-1
    BM (backplane monitor), 4593:5-21

drive power, 4593:5-8
fan assembly
Active, 4593:5-100, 4593:A-84, 4601:6-70, 4601:6-75
Alarm, 4593:5-100, 4593:A-84, 4601:6-70, 4601:6-75
Minor, 4593:5-100, 4593:A-84, 4601:6-70, 4601:6-75
Garrett Magnum Hubs, 4626:A-16
hub front, 4625:4-48, 4625:4-50, 4626:A-18
MPS Server, 1021:6-11, 4625:4-28, 4625:4-31
MPS Server alarm, 4625:4-32
Netra t 1400, 4625:4-37, 4626:A-15
Telect Braker Panel, 4626:A-14
LEDs, OP/MAINT, 4593:2-7
LEDs, PWR A, 4593:2-7
LEDs, PWR B, 4593:2-7
Length of EGTA must be equal to length of GTA, 4801:2-166
level
DSM database, 4307:4-5
level 2 timers
changing, 4804:3-187
level 3 MSU discrimination
ANSI/ITU MTP Gateway (20.0), 4318:2-35
level 3 timers
changing, 4804:3-189
LFS command in progress, 4801:2-396
LFS data is only valid for OCTET and ALTERNATE patterns, 4801:2-397
LFS feature must be ON, 4801:2-377
LFS must not be running on requested link, 4801:2-401
LFS test is completing, cannot be canceled, 4801:2-396
LFS test terminated with OAM switch over, 4593:3-718
LHOST and ALHOST must refer to different IP addresses, 4801:2-635
LHOST and ALHOST must refer to IP address on the same card, 4801:2-635
LHOST has open socket or association, 4801:2-577, 4801:2-579
LHOST/ALHOST location not found, 4801:2-467
LIDB, 4802:3-30
LIDB TT required before OAP update, 4801:2-672
Lighting, 2969:2-6
lighting, 2969:2-6, 4625:6-3
LIM, 4601:2-3, 4625:3-21, 4626:1-33, 4802:1-15
LIM(s) have been denied EROUTE service, 4593:3-586
LIM(s) have been denied SCCP service, 4593:3-430
LIM(s) have been denied STPLAN service, 4593:3-235
LIM, MIM, and MPL Changeout Time, 4593:A-18
LIM-AINF, 4601:2-3, 4625:3-56, 4626:1-33
LIM-ATM, 0004:6-7, 4601:2-3, 4626:1-33
LIM-ATM-, 4625:3-58, 4625:3-69
LIMATM, 0004:6-7
LIMCH, 0004:6-7
LIM-DS0, 0004:6-7
LIMDS0, 0004:6-7
limds0, 0004:2-11
LIM-DS0A, 4601:2-3, 4626:1-33
LIME1, 0004:6-7

LIME1ATM, 0004:6-7
limitations
Calling Name Conversion Facility (CNCF) (23.1), 4318:2-44
Eagle Application Support for E1 (26.3), 4318:2-107
Enhanced Bulk Download (25.0), 4318:2-150
GR-376 Interface (26.0), 4318:3-30
GSM MAP Screening (26.1), 4318:3-46
ITU MTP Restart (26.0), 4318:3-153
Large System (27.2), 4318:4-3
Multiple LFS Tests (EAGLE 26.0), 4318:4-135
Multiple Point Code Support (EAGLE 26.05), 4318:4-143
Number Pooling / Efficient Data Representation (EDR) (EAGLE 26.1), 4318:4-196
PCS 1900 LNP Query (EAGLE 26.0), 4318:5-8
Security Log Increase (EAGLE 26.05), 4318:5-72
Stand-alone Eagle G-Flex Relay Function, 4318:3-19
Support for LSMS Audit Enhancements (EAGLE 26.1, 4318:5-103
Thresholding of UIM Messages (EAGLE 25.0), 4318:5-128
TSM Warm Restart and Incremental Loading (EAGLE 26.0), 4318:5-145
Weighted SCP Load Balancing (Eagle 27.2), 4318:5-171
LIM-OCU, 0004:6-7
LIMOCU, 0004:6-7
limocu, 0004:2-11
LIMT1, 0004:6-7
LIM-V.35, 0004:6-7, 4625:3-56
LIMV35, 0004:6-7
limv35, 0004:2-11
Link, 4625:3-20
Link assigned to card, 4801:2-32
link diagnostics
Link Fault Sectionalization (21.0), 4318:4-14
Link expected IP TPS threshold exceeded, 4593:3-204
Link Failure Status Information (22.0), 4318:4-8
Link Fault Sectionalization, 4593:3-73
Hardware Configuration, 4593:3-74
Test Details, 4593:3-76
Test Indicators, 4593:3-75
Test Report, 4593:3-75
Link Fault Sectionalization (21.0), 4318:4-12
Commands, 4318:4-17
Hardware Configuration, 4318:4-15
Link Diagnostics, 4318:4-14
Link Fault Sectionalization Test Indicators, 4318:4-16
Remote Loopback Testing for DSOA, 4318:4-14
Remote Loopback Testing for OCU, 4318:4-14
link fault sectionalization test, 4593:3-73
Link Fault Sectionalization Test Indicators
Link Fault Sectionalization (21.0), 4318:4-16
link fault sectionalization test procedure, 4593:3-77
link fault sectionalization test, commands, 4593:3-76
link fault sectionalization test, configuring data, 4593:3-77
link fault sectionalization test, hardware configuration, 4593:3-74
link fault sectionalization test, indicators, 4593:3-75

link fault sectionalization test, report, 4593:3-75
link fault sectionalization test, restrictions, 4593:3-74
link fault sectionalization test, starting, 4593:3-77
link fault sectionalization test, stopping, 4593:3-78
Link Interface Module, 1021:3-8, 4625:2-11, 4802:1-15
Link Interface Module (LIM), 4601:5-81
link interface module (LIM), 4625:3-19
Link Interface Module (LIM) measurements, 4593:4-48
Link Interface Modules (LIMs), 4625:3-9
Link IP TPS normal, 4593:3-208
Link is in test mode, 4801:2-31
Link is unequipped in the database, 4801:2-151
Link Maintenance Commands
    act-cdl, 4593:3-83
    act-lbp, 4593:3-76
    chg-lbp, 4593:3-76
    dact-cdl, 4593:3-83
    dact-lbp, 4593:3-76
    dlt-lbp, 4593:3-76
    ent-lbp, 4593:3-76
    rept-stat-cdl, 4593:3-83
    rept-stat-lfs, 4593:3-76
    rept-stat-tstslk, 4593:3-84
    rtrv-lbp, 4593:3-76
    tst-slk, 4593:3-80, 4593:3-83
Link Maintenance Enhancements, 4593:3-78
    Command Driven Loopback, 4593:3-79
    Commands, 4593:3-83
    Test Indicators, 4593:3-79, 4593:3-81
    Test Signaling Link, 4593:3-80
    tst-slk Loopback Test Details, 4593:3-81
Link Maintenance Unsolicited Output Message Group, 4593:D-6
Link must be cancelled before executing this command, 4801:2-272
Link must be removed from X.25 route(s), 4801:2-252
Link must be SAAL to execute command, 4801:2-401
Link must be SS7 to display Level 2 stats, 4801:2-400
Link must be SS7 to execute command, 4801:2-400
Link must not be active to execute command, 4801:2-399
Link not assigned to SS7-X.25 card, 4801:2-296
Link not equipped, 4801:2-295
Link not Monitored, 4593:3-583
Link set argument - not valid (C<col>), 4801:2-546
Link set is not equipped, 4801:2-158
Link set with IPGWAPC=YES requires SS7IPGW / IPGWI GPL, 4801:2-717
Link Status alarms, DSM-ELAP, 4307:4-16
Link Status Reporting (21.0), 4318:4-20
Link test command in progress, 4801:2-870
Link test command not in progress, 4801:2-871
Link test must not be running on requested link, 4801:2-869
linkinfo, 4800:9-30
Links assigned to linkset, 4801:2-138
Links on specified linkset are in-service, 4801:2-40

Linkset
IPGWx
Configuring, 0003:3-41
Mate IPGWx
Configuring, 0003:3-62
linkset
adding, 4804:3-5, 4804:3-16
changing, 4804:3-69
removing, 4804:3-58
route, 4804:3-6
Linkset already assigned to route, 4801:2-142
Linkset already defined, 4801:2-139
Linkset APC/SAPC is already being used, 4801:2-138
Linkset assigned to route must have at least one link, 4801:2-42
Linkset cannot be the mate of another linkset, 4801:2-860
Linkset cannot reference self as mate, 4801:2-861
Linkset does not reference MATELSN, 4801:2-873
Linkset IP TPS normal, 4593:3-207
Linkset IP TPS threshold exceeded, 4593:3-202
Linkset is unequipped, 4801:2-143
Linkset not assigned in route table, 4801:2-141
Linkset not defined, 4801:2-139
Linkset referenced by route, 4801:2-140
Linkset SAPC referenced by route, 4801:2-257
Linkset SLK requires ITUN APC/SAPC to be 14bit or 24bit only, 4801:2-608
Linkset table full, 4801:2-139
Linkset Type used for cluster route cannot be A or E, 4801:2-140
linkset with MULTGC=YES requires IPGWI/IPLIMI GPL, 4801:2-804
linksets, 4804:3-2
list alarms data strings, 4307:4-11
List All Running Processes, 4307:3-75
List ELAP Software Processes, 4307:3-66
LMC connector, 4601:B-53, 4626:B-23
LNP, 4802:1-15
Database after LSMS-Based Operation or RTDB Copy - Distributing, 0007:2-144
ELAP Configuration feature, 0007:2-1, 0007:2-6, 0007:2-13, 0007:2-129, 0007:2-132, 0007:2-133, 0007:2-137, 0007:2-138
Feature Activation Overview, 0007:2-6
Feature on the Eagle - Activating, 0007:2-128
measurements, 1021:4-8
option - WSMSC10DIG, 0007:2-157
provisioning, 4307:2-10
provisioning data collection sources, 4307:2-11
Service - WSMSC, 0007:2-157
Short Message Service (SMS) - Activation, 0007:2-157
SMS Feature - Deactivating, 0007:2-162
LNP 48 Million Numbers feature, 1021:6-2
LNP ACG node overload, 4593:3-541
LNP Administration Priority - ADMHIPRI, 4802:3-165
LNP AIN Query Enhancement (26.0), 4318:4-47
Changed Commands, 4318:4-47
LNP and GPORT features are mutually exclusive, 4801:2-781

LNP audit
TSM Warm Restart and Incremental Loading (EAGLE 26.0), 4318:5-140
LNP Basic, 0002:4-23, 0002:4-37, 4802:1-2, 4802:1-15
LNP Configuration, 4802:2-1
LNP data, overview, 4751:1-1, 4751:2-3
LNP Database, 1021:4-6, 4802:1-15
LNP database
alarms, 4751:8-3
LNP Database Administration, 0002:4-23, 0002:4-37, 4802:1-2, 4802:1-15
LNP database audit - internal error, 4593:3-754
LNP database audit is disabled, 4593:3-812
LNP database corrupted, 4593:3-525, 4593:3-606, 4593:3-607
LNP database has been corrected, 4593:3-537
LNP Database IMPORT started, 4593:3-760
LNP database is inconsistent, 4593:3-530
LNP Database Unsolicited Output Message Group, 4593:D-24
LNP Day Meas. Discarded for NPANXX, 4593:3-881
LNP DB Audit — End of Audit Report
Support 12 Million Ported Numbers (EAGLE 24.0), 4318:5-92
LNP DTH Measurements Discarded for DPC, 4593:3-834
LNP ELAP CFG = ON, all LNP commands are available on LSMS, 4801:2-828
LNP ELAP CFG feat incompatible with SCCP/EBDADCM/EBDABLM appl, 4801:2-827
LNP ELAP Configuration and WNP features must be ON, 4801:2-632
LNP ELAP Configuration feature
enable, 4800:6-124
turn off, 4800:5-84
LNP ELAP Configuration feature must be ON, 4801:2-585
LNP Feature Enabling
2 to 12 million numbers, 4802:2-16
LNP feature must be ON, 4801:2-438
LNP feature must be on before LNP ELAP Config can be on, 4801:2-826
LNP feature, how to turn on, 4800:6-122
LNP Incremental Loading, 4593:3-887
LNP LRN table is full, 4801:2-485
LNP Maintenance, 1021:4-7
LNP Measurements Enhancements (25.0), 4318:4-47
Changed Files, 4318:4-51
Commands, 4318:4-51
Message Relay Measurements per SSP, 4318:4-47
Upgrade Considerations, 4318:4-51
LNP measurements, extracting from FTA, 4800:5-8
LNP MR table is full, 4801:2-484
LNP NPANXX table is full, 4801:2-486
LNP Option
ADMHIPRI, 4802:3-165
CCP, 4802:3-166
FRCSMPLX, 4802:3-165
GTWYSTP, 4802:3-166
JIPPDIGTS, 4802:3-165
JIPPRV, 4802:3-165
SERVPORT, 4802:3-166
WQREDRCT, 4802:3-166

WSMSC10DIG, 4802:3-167
LNP or EIR must be enabled or INP must be ON, 4801:2-851
LNP or INP feature must be ON, 4801:2-764
LNP ported LRNs 150K Qty Feat Requires at least DSM2GB, 4801:2-705
LNP Ported LRNs Capacity Normal, 4593:3-371
LNP Ported LRNs exceeds Feat. Capacity, 4593:3-370
LNP ported NPANXXs 300K Qty Feat Requires at least DSM2GB, 4801:2-705
LNP Ported NPAs Capacity Normal, 4593:3-373
LNP Ported NPAs exceeds Feat. Capacity, 4593:3-372
LNP Ported TN table is full, 4801:2-485
LNP ported TNs 12million Qty Feat Req at least TSM / DSM1GB, 4801:2-588
LNP ported TNs 24million Qty Feat Require at least DSM2GB, 4801:2-588
LNP ported TNs 36million Qty Feat Require at least DSM3GB, 4801:2-589
LNP ported TNs 48 to 96million Qty Feat Req at least DSM4GB, 4801:2-589
LNP ported TNs 4million Qty Feat Require at least TSM512MB, 4801:2-587
LNP ported TNs 6million Qty Feat Require at least TSM768MB, 4801:2-587
LNP ported TNs 8million Qty Feat Require at least TSM1GB, 4801:2-588
LNP Ported TNs Capacity Normal, 4593:3-369
LNP Ported TNs exceeds Feat. Capacity, 4593:3-368
LNP Query PC must exist in the Route table or as SID true PC, 4801:2-528
LNP Query Service (LNPQS), 1021:4-4
LNP rcvd query with Message Relay TT, 4593:3-759
LNP rcvd query with undefined TT / SERV, 4593:3-757
LNP received query from unknown CGPA PC, 4593:3-756
LNP Response to STPLAN (26.0), 4318:4-53
LNP self-ID commands
LNP—Changes to Existing Commands (22.0), 4318:4-57
LNP Service, 4307:3-42, 4307:3-44, 4307:3-45, 4802:1-17, 4802:3-30, 4802:3-31, 4802:3-33, 4802:3-38, 4802:3-39, 4802:3-40, 4802:3-41, 4802:3-42, 4802:3-46, 4802:3-47, 4802:3-48, 4802:3-49, 4802:3-52, 4802:3-54, 4802:3-55, 4802:3-56, 4802:3-95, 4802:3-103, 4802:3-117, 4802:3-138, 4802:3-176
LNP Service commands
Eagle Initiated OAP User Interface (24.0), 4318:2-116
LNP Service Provider table is full, 4801:2-484
LNP services and translation type assignments
displaying, rtrv-lnp-serv, 0002:A-41, 0002:A-68, 4601:6-128, 4601:6-142
LNP Services Configuration, 4802:3-1
LNP Short Message Service (Release 28.2), 4318:4-87
LNP Split NPANXX table is full, 4801:2-486
LNP SS Appl table is full, 4801:2-483
LNP Subscription, 0002:4-23, 0002:4-37, 4802:1-15
LNP Subscription Ref's DPC with 0 routes, 4593:3-821
LNP Subscription Unsolicited Output Message Group, 4593:D-25
LNP subsystem alarms
LNP—Auto Inhibit / Uninhibit Alarms, 4318:4-72
LNP Subsystem Application, 4318:4-85, 4802:3-63, 4802:3-64, 4802:3-67, 4802:3-68, 4802:3-73, 4802:3-74
LNP Subsystem is available, 4593:3-524
LNP Subsystem is disabled, 4593:3-540
LNP Subsystem is not available, 4593:3-522
LNP subsystem is offline in database, 4801:2-439
LNP Subsystem is removed, 4593:3-539
LNP Subsystem normal, card(s) abnormal, 4593:3-523
LNP telephone number subscription, 4802:3-2

LNP telephone numbers - enabling, 4802:2-16
LNP Translation Type, 4318:4-84, 4802:3-30, 4802:3-41, 4802:3-48, 4802:3-95, 4802:3-176, 4802:3-180, 4802:3-181, 4802:3-183, 4802:3-184
LNP TT SERV table is full, 4801:2-483
LNP updates allowed
    loading mode stability, 4593:3-886
LNP updates inhibited
    loading mode stability, 4593:3-885
LNP—10 Digit Telephone Number Subscription Commands (22.0), 4318:4-53
LNP—Allow Subsystem Command (22.0), 4318:4-54
LNP—Auto Inhibit / Uninhibit Alarms
    LNP Subsystem Alarms, 4318:4-72
    LNP—New Unsolicited Alarm Messages (UAMs) (22.0), 4318:4-71
LNP—Automatic Call Gapping (22.0), 4318:4-54
LNP—Automatic Call Gapping (Release 22.0)
    Area Code, 4318:4-54
LNP—Automatic Call Gapping Commands (22.0), 4318:4-55
LNPBAS, 4802:1-15
LNP—Call Completion to Ported Number (CCPN) (22.0), 4318:4-56
LNP—Changes to Existing Commands (22.0), 4318:4-57
    LNP—chg-feat and rtrv-feat Commands, 4318:4-58
    LNP—Mated Application Commands, 4318:4-57
    LNP—Self ID Commands, 4318:4-57
LNP—clr-disk-stats Command (Release 22.0), 4318:4-58
LNPDB, 4802:1-15
LNP—Degraded Mode (22.0), 4318:4-58
LNP—Destination Point Code Exception Report (23.1), 4318:4-60
LNP—disp-disk-stats Command (22.0), 4318:4-60
LNP—Eagle LNP Configuration (22.0), 4318:4-61
LNP—Impact of LNP on Other Features (22.0), 4318:4-64
    Database Transport Access (DTA), 4318:4-65
    Gateway Screening, 4318:4-64
    STPLAN, 4318:4-65
    Translation Type Mapping, 4318:4-65
LNP—Inhibit Subsystem Command (22.0), 4318:4-65
LNP—Location Routing Number Commands (22.0), 4318:4-66
LNP—LRN Measurements
    LNP—Measurements (22.0), 4318:4-68
LNP—Mapping LNP Translation Type Commands (22.0), 4318:4-66
LNP—Measurements (22.0), 4318:4-67
    LNP—LRN Measurements, 4318:4-68
    LNP—System Wide Measurements, 4318:4-67
    NPANXX Measurements, 4318:4-68
    SSP Measurements, 4318:4-68
LNP—Message Relay (22.0), 4318:4-69
LNP—MSU Trap and Trace Command (22.0), 4318:4-70
LNP—MTP and SCCP Management to Support LNP (22.0), 4318:4-70
LNP—New LNP Input and Output Groups (22.0), 4318:4-71
LNP—New Unsolicited Alarm Messages (UAMs) (22.0), 4318:4-71
    LNP—Auto Inhibit / Uninhibit Alarms, 4318:4-71
LNP—New Unsolicited Information Messages (UIMs) (22.0), 4318:4-72
LNP—NPANXX Commands (22.0), 4318:4-73

LNP—Query Routed as Final Global Title Translation (22.0), 4318:4-73
LNP—Query Routed as Non-Final Global Title Translation (22.0), 4318:4-79
LNP—Report LNP Status Command (22.0), 4318:4-81
LNP—Rerouting Messages for the Local Subsystem (22.0), 4318:4-81
LNP—Service Commands (22.0), 4318:4-84
LNP—Service Provider Commands (22.0), 4318:4-84
LNP—Split NPA Commands (22.0), 4318:4-85
LNPSUB, 4802:1-15
LNP—Subsystem Application Commands (22.0), 4318:4-85
LNP—System Options Commands (22.0), 4318:4-86
LNP—System Wide Measurements
    LNP—Measurements (22.0), 4318:4-67
Load button, 0008:2-56, 0008:2-64, 0008:2-73
loading
    DSM incremental, 4307:2-17
    mode, DSM unstable loading, 4307:4-8
Loading failed
    bad checksum returned, 4593:3-214
    data load timeout, 4593:3-216
    data read Error, 4593:3-212
    disk read failed, 4593:3-221
    disk read prep error, 4593:3-219
    disk read response error, 4593:3-220
    GPL format error, 4593:3-218
    GPL load timeout, 4593:3-215
    invalid GPL, 4593:3-217
    table not found, 4593:3-211
Loading Mode unstable due to maint. baseline not established, 4801:2-475
Loading Mode unstable due to SCCP service is deficient, 4801:2-476
Loading mode unstable. System's LIM service is unavailable, 4801:2-475
LOC and CLASS cannot be specified together, 4801:2-564
LOC and PORT must be specified to display Level2 stats, 4801:2-400
LOC and PORT must be specified when PERIOD=ALL, 4801:2-116
LOC and PORT parameter combination must be specified, 4801:2-394
LOC has maximum number of LFS Tests already in progress, 4801:2-403
LOC is invalid for specified report TYPE, 4801:2-308
LOC is not LFS capable, 4801:2-389
LOC must be LIMDS0 or LIMOCU with SS7ANSI or CCS7ITU, 4801:2-398
LOC must be specified, 4801:2-147
LOC must be specified when TYPE=PVC or SVCA, 4801:2-290
LOC must not be specified when TYPE=SVCR, 4801:2-290
LOC not allowed with MODE=STATIC, 4801:2-725
LOC not assigned an X.25 signaling link, 4801:2-301
LOC parameter not valid for this ENTTYPE, 4801:2-120
local ELAP, 0007:2-62, 4307:5-28
local link congestion
    ANSI/ITU MTP Gateway (20.0), 4318:2-37
    network routing, 4804:2-148
Local Maintenance Center (LMC), 4625:3-26
local maintenance center (LMC) alarm connector, 4625:3-26
local maintenance center cable installation, 4601:5-87
Local Number Portability, 4802:1-15

Local Number Portability (LNP 48 Million Numbers feature, 4307:2-2
local number portability (LNP), 4751:2-2
Local Provisioning menu, 4307:3-48
Local Provisioning Utility, 4307:3-48
Local Service Management System, 4802:1-15
Local Subsystem is available, 4593:3-501
Local Subsystem is disabled, 4593:3-503
Local Subsystem is not available, 4593:3-502
Local Subsystem is removed, 4593:3-504
Local Subsystem normal, card(s) abnormal, 4593:3-505
Local Subsystems (LNP and Toll-Free)
    Multiple Point Code Support (EAGLE 26.05), 4318:4-140
Location invalid for hardware configuration, 4801:2-50
Location Routing Number, 4318:4-54, 4802:1-15, 4802:3-116, 4802:3-118, 4802:3-123, 4802:3-124, 4802:3-125, 4802:3-129, 4802:3-130, 4802:3-135, 4802:3-136, 4802:3-137, 4802:3-138, 4802:3-140, 4802:3-149, 4802:3-150, 4802:3-154, 4802:3-155, 4802:3-156, 4802:3-176, 4802:3-179, 4802:4-2
Location type cannot receive messages, 4801:2-80
lock, 4800:6-370
LOCREQ rcvd - IS412GSM not provisioned, 4593:3-770
Log
    Connectivity Test, 0008:2-31, 0008:2-32, 0008:2-33, 0008:2-34, 0008:2-35
        window, File Menu, 0008:2-32, 0008:2-33
    Retrieve Tables, 0008:2-11, 0008:2-54, 0008:2-65, 0008:2-66, 0008:2-67, 0008:2-68, 0008:2-70, 0008:2-71
        window, File Menu, 0008:2-68, 0008:2-69
    System, 0008:2-11, 0008:2-97, 0008:2-98, 0008:2-99, 0008:2-100, 0008:2-101
        closing, 0008:2-97, 0008:2-101
        window, 0008:2-97, 0008:2-98, 0008:2-99, 0008:2-100, 0008:2-101
            File menu, 0008:2-97, 0008:2-98
    Update Tables, 0008:2-11, 0008:2-77, 0008:2-78, 0008:2-81, 0008:2-82, 0008:2-83, 0008:2-84, 0008:2-87, 0008:2-88, 0008:2-89, 0008:2-90, 0008:2-91, 0008:2-92, 0008:2-93, 0008:2-94, 0008:2-95
        window, 0008:2-82, 0008:2-88, 0008:2-92, 0008:2-93, 0008:2-94, 0008:2-95, 0008:2-96
            Commit Command Completed, 0008:2-88
            File Menu, 0008:2-92, 0008:2-93
log file
    audit, 4751:5-19
    bulk load, 4751:6-20
    used for automatic resynchronization, 4751:4-2
    user-initiated resynchronization, 4751:4-19
Log Viewer, 4307:3-69
log viewer navigation commands, 4307:3-70
LOGBUFROVFL-SECULOG - upload required, 4593:3-259
Logic Cell Array (LCA), 4625:3-68
LOGIC GROUND, 4601:4-19
Logic Ground, 4601:4-13, 4601:4-16
Logic ground, 4601:5-7
logic ground, 4601:4-17, 4601:4-19
logic ground cable, 4601:4-18
logic grounds, 4601:4-18
Logical Channel to Network Management Mapping
    X.25/SS7 Gateway Feature (Eagle 20.0), 4318:5-178
login, 4800:6-371

procedure for password expired, 4800:4-21
procedure for User ID-password already being used, 4800:4-22
procedure for User ID-password not accepted, 4800:4-20
procedure to change password at first login, 4800:4-20
procedure to log into system, 4800:4-19
security checks, 4800:4-17
Login Failure Message (21.0), 4318:4-89
Login Message Text, 4307:3-111
login names
change passwords for, 4307:5-22
login screen, 4307:3-4
Login Success or Failure Tracking (21.0), 4318:4-90
Login Tracking, 4307:3-83
logout, 4800:6-372
Logout menu, 4307:3-113
Logout on Communications Failures (22.0), 4318:4-91
Error Messages, 4318:4-92
logout procedure, 4800:4-23
logs
log viewer navigation commands, 4307:3-70
Look in: Field
Select Starting Directory window, 0008:2-52
Select window, 0008:2-80
Loopback in progress, 4801:2-401
Loopback invalid, 4593:3-816
Loopback prevented, 4593:3-815
Lower bound exceeds upper bound of range - %, 4801:2-22
Lower bound exceeds upper bound of range - <parm>, 4801:2-26
LPU, 4307:3-48
LPU Commands, 4307:B-2
LRN, 4802:1-15, 4802:3-44, 4802:3-82, 4802:3-97, 4802:3-126, 4802:3-127, 4802:3-137, 4802:3-139, 4802:3-141, 4802:3-145, 4802:3-149, 4802:3-151, 4802:3-154, 4802:3-156, 4802:3-157, 4802:3-161, 4802:3-177, 4802:3-179, 4802:3-180, 4802:4-2
LRN already assigned, 4801:2-505
LRN cannot be deleted if referenced in LNP database, 4801:2-512
LRN does not exist, 4801:2-531
LRN must be specified or assigned when RGTA=Yes, 4801:2-504
LRN must be specified when ELRN is specified, 4801:2-526
LRN Quantities on the Eagle - Increasing, 0007:2-153
LRN SP does not match TN SP, 4801:2-477
LRN Table Increase (26.1), 4318:4-92
Changed Commands, 4318:4-92
Upgrade Considerations, 4318:4-108
LRN, or GT# parameter must be specified, 4801:2-520
LSL parameters not valid for card type, 4801:2-556, 4801:2-557
LSMS, 4802:1-15
command line interface (lsmsclaa), 4751:5-21
connection to ELAP for provisioning, 4307:2-5, 4307:2-10, 4307:2-11
Creating an EMS Configuration Component, 0007:2-81
data, 4751:1-1, 4751:2-3
Deleting an EMS Configuration Component, 0007:2-91
ELAP connection for provisioning, 4307:2-10

EMS Configuration Component, 0007:2-81
EMS Routing, 0007:2-93
existing connection to ELAP, 4307:2-11
hardware platform, 1021:4-10
initial ELAP connection to, 4307:2-10
Manually Verifying and Restarting the Eagle Agents, 0007:2-151
Modify EMS Routing, 0007:2-93, 0007:2-96
Modifying an EMS Configuration Component, 0007:2-87
primary connection to ELAP, 4307:2-10
Viewing an EMS Configuration Component, 0007:2-89
LSMS BLM-Based Operations
Removing the BLM, 0007:2-29
Removing the DCM, 0007:2-26
LSMS bulk download cancelled at LSMS, 4593:3-970
LSMS bulk download complete, 4593:3-969
LSMS bulk download in progress, 4593:3-968
LSMS bulk load complete, 4593:3-134
LSMS bulk load required, 4593:3-133
LSMS Connection, 4307:3-8
LSMS Connection menu, 4307:3-31
LSMS HS Audit menu, 4307:3-25
LSMS HS Bulk Download, 4307:3-28
LSMS is at min. service limit, 4593:3-479
LSMS is available, 4593:3-467
LSMS is unavailable, 4593:3-468
LSMS parameter
chg-oap-config, 0002:A-25, 4601:6-112
LSMS parameter requires LNP feature, 4801:2-666
LSMS Q.3 association available, 4593:3-475
LSMS Q.3 association unavailable, 4593:3-472
LSMS subsystem has not been provisioned, 4801:2-320
LSMS-Based Operation - Distributing the LNP Database, 0007:2-144
LSN and LOC cannot be specified together, 4801:2-118
LSN and PORT parms cannot be specified together, 4801:2-119
LSN must be provided with ALL=NO, 4801:2-132
LSN must be specified, 4801:2-121, 4801:2-413
LSN parameter not valid for type-enttype combination, 4801:2-121
LSRESTRICT Option, 4804:3-88, 4804:3-233, 4804:3-234, 4804:3-235, 4804:3-236, 4804:3-237
LSS
No Map IMEI Parameter present, 4593:3-738
LSUSEALM not allowed for non-IPGWx linksets, 4801:2-874, 4801:2-875
LVL, 4802:1-15, 4802:4-13, 4802:4-15, 4802:4-17, 4802:4-19, 4802:4-20
Lvl 1 Removable detected during upgrade, 4801:2-574

M

M2PA on IPLIMx (Release 29.1) (IP7 Release 7.1), 4318:4-93
M2PATSET requires M2PA adapter type, 4801:2-591
M3UA signaling links - migrating IPLIMx to IPGWx, 0003:3-127, 0003:3-138, 0003:3-139, 0003:3-140, 0003:3-141, 0003:3-142, 0003:3-143
main DSM network, 4307:2-7
main ground, 2969:6-5

Main Ground Bar, 4601:4-15
main power feeds, checking, 2712:3-13
maintenance
    High Speed Master Timing (26.0), 4318:3-60
    monthly, 2712:3-2, 2712:3-6
    overview, 2712:3-1
    periodic
        tape drive, 4593:6-17
    periodic MPS Server filter, 4593:6-17
    Temporary Alarm Inhibiting and Offline Functions (EAGLE 25.0), 4318:5-121
    TSM Warm Restart and Incremental Loading (EAGLE 26.0), 4318:5-134
Maintenance and Administration Subsystem, 1021:3-4, 4625:2-4
maintenance and administration subsystem
    overview, 0002:1-8, 0003:1-8, 4804:1-8
Maintenance and Administration Subsystem (MAS), 4625:3-18
Maintenance and Administration Subsystem Processor, 4802:1-15
Maintenance and Administration Subsystem Processor (MASP), 4601:5-81
Maintenance and Administration Subsystem Processors See MASP cards, 4800:4-2
Maintenance Blocks, ELAP
    contents of, 4307:4-3
    description, 4307:4-3
Maintenance Disk and Alarm (MDAL) Card Replacement, 4593:A-3
Maintenance Disk and Alarm Card, 4802:1-15
maintenance disk and alarm card (MDAL), 4625:3-46
Maintenance Disk and Alarm card See MDAL card, 4800:4-2
Maintenance Interface System (MIS), 4625:3-141
Maintenance Log, 4307:3-62
Maintenance Manual, 4601:1-7, 4601:1-14, 4626:1-14
Maintenance Menu, 4307:3-16
maintenance process log file, 4593:6-20
Maintenance software, 4593:1-14
Maintenance Status Reports, 4593:4-129
Maintenance strategy, 4593:1-13, 4593:1-14
maintenance task, 4307:3-7
Major Alarm, 4593:3-4, 4625:3-5
major alarms, 4593:2-7, 4800:4-3
Major Application Errors, 2712:4-3, 4593:6-30
Major Application Failure(s), 4593:3-492
Major customer trouble detected, 4593:3-146
Major failures detected on both IMTs, 4593:3-199
Major holdover clock trouble detected, 4593:3-151
Major IMT failure detected, 4593:3-190
Major Platform Errors, 2712:4-2, 4593:6-29
Major Platform Failure(s), 4593:3-491
major problem, 4318:1-8, 4601:1-18, 4626:1-20
Making a Backup of the Database to the Removable Cartridge, 4593:2-15
Manage Log Files, 4307:3-64
Manage Unused UserIDs, 4307:3-83
Management of Unused User IDs (21.0), 4318:4-108
managing
    audit, 4751:5-9
    bulk load, 4751:6-4

resynchronization, 4751:4-2, 4751:6-2
user-initiated resynchronization, 4751:4-6
manual
admonishments, 0002:1-6, 0003:1-6, 4804:1-6
organization, 0002:1-2, 0003:1-2, 4625:3-44, 4804:1-2
related publications, 0002:1-3, 0003:1-3, 2712:1-4, 4593:1-4, 4804:1-3
Manual Deactivation of SRST Message (21.0), 4318:4-109
Manually Verifying and Restarting the Eagle Agents on the LSMS, 0007:2-151
manuals
Alarms Reference and User's Manual, 4625:1-13, 4626:1-15
Data Collection Applications Manual, 4625:1-12, 4626:1-15
Feature Guide, 4625:1-12, 4626:1-15
Feature Notice, 4625:1-12, 4626:1-15
hardware and installation manuals, 4625:1-13, 4626:1-16
list of Sentinel, 4625:1-12, 4626:1-15
Proactive Testing Applications Manual, 4625:1-12
Release Notice, 4625:1-12, 4626:1-15
System Administrator's Guide, 4625:1-12, 4626:1-15
technical reference documents, 4625:1-13, 4626:1-16
User's Manual, 4625:1-12, 4626:1-15
Map entry must be solitary, 4801:2-431
MAP Operation Code, 4318:5-19
Map Screening cannot Duplicate MSU, 4593:3-909
Map Screening cannot forward MSU, 4593:3-688, 4593:3-907
MAP Table Increase (Release 29.0), 4318:4-109
Map with STP True PC has LNP/INP/EIR SS-APPL assigned, 4801:2-538
mapping, memory bank, 4593:6-127
marking
cable holes, 2969:4-5
frame layout, 2969:4-4
MAS, 4625:3-18
MAS Communication Application Processor (MCAP) Card Replacement, 4593:A-5
MAS communications application processor (MCAP), 4601:5-81
Masking tape, 4601:3-20
masking tape, 2969:4-3
masonry drill-bit, 2969:4-3, 4601:3-20
MASP, 1021:3-4, 4601:5-84, 4625:2-5, 4625:3-19, 4802:1-15
MASP became active, 4593:3-102
MASP became standby, 4593:3-103
MASP cards, 4800:4-2
master clockt
High Speed Master Timing (26.0), 4318:3-56
Master Glossary, 4601:1-15, 4626:1-14
Master Timing, 4601:5-81
Matching routing key already entered for AS, 4801:2-813
Mate already exists for linkset, 4801:2-864
Mate Applications, 0006:2-44, 0006:3-2, 0006:4-2
Mate IPGWx Linkset
Configuring, 0003:3-62
Mate linkset not defined, 4801:2-873
Mate parameters
MPC, MSSN, MateRC are required together, 4801:2-430

Mate PC/SSN cannot be given when MULT=SOL, 4801:2-173
Mate PC/SSN cannot be same as PC/SSN, 4801:2-176
Mate Relative Cost (MateRC) required if MPC/MSSN is entered, 4801:2-428
mated application commands
    LNP—Changes to Existing Commands (22.0), 4318:4-57
mated application subsystem
    allowing, alw-map-ss, 4751:8-4
    inhibiting, inh-map-ss, 4751:8-4
Mated Applications, 0006:2-40
mated gateways, 0003:3-7, 4804:3-5
Mated linksets must contain only SS7IPGW or IPGWI links, 4801:2-861
Mated linksets must have APCs of same network type, 4801:2-862
Mated STPs
    X.25 gateway routing, 0004:2-9
Matrix Controller Automatic, 4625:3-144
MAU, 4601:5-21, 4601:5-23, 4601:5-142, 4625:3-96
MAU (Media Access Unit), 4601:2-13, 4626:1-6
Max IP connections exceeded, 4801:2-687
Max number combined LSLs and ATM HSLs already entered, 4801:2-557
Max number of cards of application type already exist, 4801:2-675
Max number of DEFINED MSGCODEs per variant is exceeded, 4801:2-348
Max number of DEFINED PARMCODEs per variant is exceeded, 4801:2-348
Max number of entries exist in FTP Server table, 4801:2-340
Max number of FTPSERV table entries exist for this APP, 4801:2-341
Max number of STC cards per shelf is entered, 4801:2-779
Max Packet Size must be 128 when N1 is equal to 1080, 4801:2-282
Max sockets per routing key exceeded, 4801:2-687
Maximum Account Inactivity, 4307:3-110
Maximum Concurrent Logins, 4307:3-111
Maximum Concurrent User Logins, 4307:3-111
Maximum Failed User Logins, 4307:3-110
Maximum number of applications already assigned, 4801:2-491
Maximum number of ASPs already associated to AS, 4801:2-819
Maximum Number of CDPNNAIs already provisioned, 4801:2-92
Maximum number of CDPNPFXs already provisioned, 4801:2-82
Maximum number of CPCs defined (96), 4801:2-383
Maximum number of link tests already in progress, 4801:2-402
Maximum number of links are assigned to this linkset, 4801:2-43
Maximum number of Mated Applications (MAP) exceeded, 4801:2-429
Maximum number of PPSMSGTAs already provisioned, 4801:2-470
Maximum number of rules exceeded in screen set, 4801:2-208
Maximum number of screen sets exceeded, 4801:2-208
Maximum of 10 unique CCNCs allowed, 4801:2-601
Maximum Password Age, 4307:3-110
maximum SAPC entries exceeded, 4801:2-835
Maximum SVCAs already defined for link, 4801:2-288
May not change adjacent point code type, 4801:2-137
May not modify both T21 and IT23 timers, 4801:2-67
May not specify both LOC and STAT, 4801:2-148
May not specify both LSN and PST, 4801:2-158
May not specify Filename when ALL=YES, 4801:2-94
MCA, 4625:3-144

MCAP, 0008:2-3, 4593:A-5
MCAP card
High Speed Master Timing (26.0), 4318:3-59
MCP card must be IS-ANR Restrict to enable measplatform, 4801:2-157
MCPM, 0002:2-57, 0002:2-63, 0002:2-83, 0002:2-86, 0002:2-94, 0002:2-98, 0002:3-50, 0002:3-70, 0002:4-141, 0002:4-143, 0002:4-146, 0002:4-147, 0002:4-148, 0002:4-151, 0002:4-152, 0002:4-153, 0002:4-170, 0002:4-181, 0002:B-30
MDAL, 4625:3-19, 4625:3-21, 4625:3-37, 4802:1-15
MDAL alarm cleared, 4593:3-177
MDAL backplane connectors, 4601:B-57
MDAL card
function of, 4800:4-2
removable cartridge drive, 4800:4-2
MDAL LEDs, 4593:3-5
MDAL not responding, 4593:3-176
MEAS Checksum Failure, 4593:3-594
Meas for Enh GSM MAP Screening not supported on EOAM, 4801:2-885
Meas Platform feature must be ON, 4801:2-305
MEAS Platform must be enabled, 4801:2-463
Meas sync not allowed from old version, 4593:3-689
MEAS Synchronization Successful, 4593:3-595
Measurement Collection & Polling Module, 0002:4-141, 0002:4-146
Measurement collection in progress, Retry later, 4801:2-831
Measurement Preparation in progress, Retry later, 4801:2-706
Measurement Reports
Availability, 4593:4-43
Component, 4593:4-22
Daily Availability, 4593:4-38
Daily Maintenance, 4593:4-51
Day-To-Hour Availability, 4593:4-41
Day-to-Hour Maintenance, 4593:4-80
Gateway, 4593:4-110
Hourly Maintenance, 4593:4-93
Maintenance Status, 4593:4-129
Network Management, 4593:4-31
Record Base, 4593:4-122
STP System Totals, 4593:4-14
Measurements
OAM Based, 4593:4-5
Optional 15-Minute, 4593:4-10
Platform, 4593:4-5
measurements
Group Ticket Voucher (23.0), 4318:3-38
ITU MTP Restart (26.0), 4318:3-153
MTP Restart (EAGLE 21.0), 4318:4-129
Multiple Point Code Support (EAGLE 26.05), 4318:4-141
Measurements data copy failure, 4593:3-900
Measurements Enhancements (22.0), 4318:4-110
Measurements not inhibited, 4801:2-58
Measurements Platform, 0002:2-57, 0002:2-82, 0002:2-94, 0002:4-143, 0002:4-145, 0002:4-146, 0002:4-154, 0002:4-158, 0002:4-162, 0002:4-164, 0002:4-179, 0002:B-29, 4593:4-5
Measurements Platform IP Security, 4625:2-13

Measurements Platform option, 0002:2-57, 0002:2-82, 0002:2-94, 0002:4-150, 0002:4-154, 0002:B-29
Measurements Platform—Phase 1 (Release 28.0), 4318:4-111
Measurements subsystem available, 4593:3-593
Measurements subsystem unavailable, 4593:3-592
measurements terminal
    configuring, 0002:4-134
measurements, extracting LNP from FTA, 4800:5-8
Media Access Unit, 4625:3-96
Media Access Unit (MAU), 4601:2-13, 4625:3-95, 4626:1-6
Memory, 2712:3-13, 4593:6-7
memory
    module replacement procedure, 4593:6-124
    MPS Server for ELAP support, 4625:4-27
    MPS Server for EPAP support, 4625:4-27
Memory Alarm, 4593:6-8
Memory Applique, 4625:3-91
memory bank
    mapping, 4593:6-127
    memory riser card layout, 4593:6-126
    motherboard layout, 4593:6-125
memory riser card memory bank layout, 4593:6-126
memory, DSM
    capacity status reporting, 4307:4-7
    daughterboard continual validation, 4307:4-7
Menu
    Commands, 0008:2-11
    Connectivity Test Log
        File, 0008:2-32
    Edit
        FTP-Based Table Retrieve Application, 0008:2-14, 0008:2-78
    Exit, 0008:2-11
    File
        Command File Editor window, 0008:2-87
        Connectivity Test Log window, 0008:2-32, 0008:2-33
        FTP-Based Table Retrieve Application window, 0008:2-12
        Retrieve Tables Log window, 0008:2-68, 0008:2-69
        System Log window, 0008:2-97, 0008:2-98
        Update Tables Log window, 0008:2-92, 0008:2-93
    FTP Server Configuration, 0008:2-11, 0008:2-49
        Browse button, 0008:2-50, 0008:2-51
        Set button, 0008:2-50
    FTP-Based Table Retrieve Application, 0008:2-49
    Help
        FTP-Based Table Retrieve Application, 0008:2-102
    Retrieve Tables Log
        File, 0008:2-68
    STP Connection Configuration, 0008:2-11, 0008:2-14
    View
        FTP-Based Table Retrieve Application, 0008:2-69, 0008:2-93, 0008:2-98
Menu Format, 4307:5-12
menu item, ELAP user interface
    Halt MPS, 4593:6-115

menu item, EPAP user interface
Backup PDB, 4593:6-18
Halt MPS, 4593:6-115
menu section, 4307:3-2, 4307:3-9
menus, ELAP user interface
configuration, 4307:5-14
see also configuration menu
default values for prompts, 4307:5-12
Escape key to exit operations, 4307:5-12
responding to prompts, 4307:5-12
Message
Command In Progress, Cannot Close Window, 0008:2-86
IP Address warning, 0008:2-43
Must Enter Command Script File Name, 0008:2-82
Processing Validate Request, Please Wait, 0008:2-82, 0008:2-88
Update Tables processing completed without errors, 0008:2-87
message box, 4307:3-8
message conversion
Calling Name Conversion Facility (CNCF) (23.1), 4318:2-50
X.25/SS7 Gateway Feature (Eagle 20.0), 4318:5-174
Message History, 4307:3-9
Message Relay, 4802:1-15, 4802:3-85, 4802:3-102
Message Relay (MR) Function, 1021:4-5
Message Relay Global Title Translation, 4802:1-15, 4802:3-57, 4802:3-116, 4802:3-117, 4802:3-130, 4802:3-131, 4802:3-138, 4802:3-155, 4802:3-176, 4802:3-177
Message Relay Measurements per SSP
LNP Measurements Enhancements (25.0), 4318:4-47
message routing
MTP Restart (EAGLE 21.0), 4318:4-128
Message threshold argument - not valid (C<col>), 4801:2-547
Message Transfer Part, 4802:1-15
messages, 4307:3-117, 4307:3-118
messages, ELAP user interface error
format, 4307:5-13
list of, 4307:3-114, 4593:6-23
metadb, 4593:6-8
metastat, 4593:6-8
Method A
update EOAP, 0002:A-42, 0002:A-69, 4601:6-129, 4601:6-144
Method B
update EOAP, 0002:A-45, 0002:A-72, 4601:6-132, 4601:6-147
MF or MV parms must be kept in an ordered list starting at 1, 4801:2-347
MGMT terminal type, 0002:4-55
MGTT - Global Title Translation Modification, 0006:1-2, 0006:1-3, 0006:2-6, 0006:2-7, 0006:2-15, 0006:2-43, 0006:2-46, 0006:2-47, 0006:2-48, 0006:2-49, 0006:3-22, 0006:3-23, 0006:3-28, 0006:3-33, 0006:3-35, 0006:3-54, 0006:3-55, 0006:3-58, 0006:3-59, 0006:3-62, 0006:3-65, 0006:4-30, 0006:4-33, 0006:4-34, 0006:4-38, 0006:4-56, 0006:4-58, 0006:4-59, 0006:4-62, 0006:A-39
MGTT cannot be ON if any SCCP card less than 586 processor, 4801:2-317
Migrating IPLIMx M3UA signaling links to IPGWx M3UA connections, 0003:3-127, 0003:3-138, 0003:3-139, 0003:3-140, 0003:3-141, 0003:3-142, 0003:3-143
MIM
E1T1, 0004:6-7

minimum LSMS/Eagle Ethernet facility
Enhanced Bulk Download (25.0), 4318:2-148
Minor Alarm, 4593:3-4, 4625:3-5
minor alarms, 4593:2-7, 4800:4-3
Minor Application Errors, 2712:4-4, 4593:6-31
Minor Application Failure(s), 4593:3-494
Minor customer trouble detected, 4593:3-147
Minor holdover clock trouble detected, 4593:3-152
Minor IMT failure detected, 4593:3-187
Minor Platform Errors, 2712:4-3, 4593:6-30
Minor Platform Failure(s), 4593:3-493
minor problem, 4318:1-8, 4601:1-19, 4626:1-20
Minutes argument - not valid (C<col>), 4801:2-549
Minutes out of range, 4801:2-100
MIS, 4601:A-24, 4625:3-139
Miscellaneous Command Adjustments (26.0), 4318:4-115
Activate Echo to a Terminal, 4318:4-115
Cancelling rtrv and rept-stat Commands, 4318:4-116
Changed Commands, 4318:4-115
Miscellaneous Command Adjustments (26.1), 4318:4-117
Different Database Level Alarm Repetition When UAM 34 Has Been Raised, 4318:4-117
Ent-/Chg-GTT Failure Message Shows Overlap, 4318:4-117
Miscellaneous Frame, 4625:3-127
Miscellaneous frame, 4601:3-27
Miscellaneous Frame (MF), 4625:3-4
miscellaneous frame (MF), 4625:3-14
Miscellenous Commands, 4307:B-17
Missing argument assignment operator, 4801:2-8
Missing authentication context, encountered during the SSH user authorization - Error code 641, 0008:2-109
Missing command identifier, 4801:2-6
Missing information unit separator, 4801:2-21
Missing mandatory parameter, 4307:B-19
Missing mandatory parameter - <parm>, 4801:2-7
Missing modifier separator, 4801:2-6
Missing parameter, 4801:2-155
Missing parameter - BC, 4801:2-87
Missing parameter - CARD, LOC or IMT, 4801:2-87
Missing parameter - DA or DR, 4801:2-88
Missing parameter - DPADDR or DR, 4801:2-306
Missing parameter block separator, 4801:2-5
Missing parameter identifier, 4801:2-9
Mixed Networks Using the ANSI/ITU Gateway Feature
Point-to-Point Connectivity for ITU Point Codes, 4318:5-12
Mixed point code types are not allowed, 4801:2-209
Mnemonic argument is undefined, 4801:2-176
MNP Circular Route Detected, 4593:3-905
MNPSMS feature, 4318:5-20
MNSAP parameter
chg-oap-config, 0002:A-25, 4601:6-113
MO drive, 1021:4-10
MO Forward Short Message (MO FSM), 4318:5-19

MO Removable Cartridge, 4593:2-11
MO Removable Cartridge Description, 4593:2-10
MO SMS feature must be activated, 4801:2-593, 4801:2-595
Mobile Originated Short Message Service message (MO SMS), 4318:5-19
Mobile Subscriber Integrated Services Digital Network (MSISDN), 4318:5-19, 4318:5-20
Mobile Subscriber Integrated Services Digital Network (MSISDN) number (i.e. phone number), 4318:5-20
Mobile Switching Center (MSC), 4318:5-19
mode
    DSM unstable loading, 4307:4-8
modem, 4601:5-107
modem for PPP connection, 4307:2-9
Modem Not Working, 4593:3-70, 4593:3-71
modems, 1021:4-10
modems, verifying, 2712:3-7
Modification of security log not allowed, 4801:2-436
Modify button, 0008:2-16, 0008:2-36, 0008:2-37
Modify EMS Routing, 0007:2-93
Modify Group menu, 4307:3-100
Modify System Defaults menu, 4307:3-110
Modify User screen, 4307:3-86
Modify Warning window, 0008:2-39
Modifying an EMS Configuration Component, 0007:2-87
Modifying an Existing STP Configuration Record, 0008:2-36, 0008:2-43, 0008:2-48
Month out of range, 4801:2-101
monthly maintenance, 2712:3-2, 2712:3-6
Monthly Procedures, 4593:2-24
More than one of CARD, LOC and IMT specified, 4801:2-88
Motherboard BIP invalid, 4593:3-182
Motherboard BIP valid, 4593:3-183
motherboard memory bank layout, 4593:6-125
mounting bracket
    8-Port Connector Box, 4625:4-12
mounting brackets
    EOAP shelf, 4593:5-72
mouse-over check, 4307:3-11
MPC and MSSN must be defined for new MULT val, 4801:2-181
MPC does not exist in routing table, 4801:2-177
MPC entered, MSSN must also be given, 4801:2-177
MPC feature must be enabled, 4801:2-736
MPC network type does not match PC network type, 4801:2-178
MPC/MSSN pair already exists, 4801:2-179
MPL, 0004:6-7, 4625:3-21, 4625:3-37
MPS
    definition, 4307:2-2
    hardware platform, 4307:2-3
    installation, 2712:2-12
    introduction, 2712:2-2
    overview
        layered design, 1021:6-3
        terminology, 2712:2-3
    platform alarms, 4307:4-14

system hardware configuration, 1021:6-4, 2712:2-5
system software configuration, 1021:6-5, 2712:2-10
upgrade, 2712:2-12
MPS alarms, general recovery procedure instructions, 2712:3-18
MPS application software, 4593:6-3
MPS available, 4593:3-349
MPS Available alarm, 4307:4-15
MPS Disaster Recovery, 4593:6-129
MPS frame
front view, 4625:4-13
rear view, 4625:4-13
MPS hardware
Field Replaceable Units (FRUs), 2712:5-2, 2712:5-3, 2712:5-4, 4593:6-114
frame layout, 4625:4-13
list of equipment, 1021:6-2
overview, 4625:4-12
MPS Health Check Procedure, 0007:2-79
MPS Host Servers, 4625:4-25
MPS LEDs, 4593:6-4
MPS must be either 128 or 256, 4801:2-299
MPS on Netra, 1021:6-9
MPS on TekServer, 1021:6-2
MPS Platform, 2712:3-14
MPS platform, 4593:6-3
MPS Platform Alarm, 4593:6-10
MPS RTDB Audit, 4307:2-19
MPS Server
see also MPS system
alarm card
description, 1021:6-11, 4625:4-28
alarm card replacement procedure, 4593:6-127
CD-ROM, 4593:6-123, 4625:4-27, 4625:4-29
component specifications, 1021:6-10
CPU, 4593:6-123
CPU specifications, 4625:4-27
DVD-ROM, 4593:6-123, 4625:4-27, 4625:4-29
file system backups, 4593:6-19, 4593:6-56
front detail view, 4625:4-22, 4625:4-29
front view, 4625:4-25
I/O architecture, 4625:4-27
LEDs, 1021:6-11, 4625:4-28, 4625:4-31
memory to support EPAP and ELAP, 4625:4-27
Netra t 1400, 4625:4-25
networking ports, 4625:4-28
operating system, 4625:4-28
overview, 1021:6-9, 4625:4-25
parallel ports, 4625:4-27
periodic filter maintenance, 4593:6-17
power down procedure, 4593:6-115
Quad FastEthernet Network Interface card, 4625:4-30
rear detail view, 4593:6-123, 4625:4-22, 4625:4-30
rear view, 4625:4-26

replacement procedure, 4593:6-117
SCSI disks, 4625:4-27
SCSI interface, 4625:4-27
serial ports, 4625:4-27
serial ports SAI/P card, 4625:4-30, 4625:4-43
storage components, 4625:4-27
tape drive, 4625:4-27, 4625:4-29
MPS server, 4318:2-1, 4593:6-3
MPS Server, power down procedure, 2712:5-7
MPS system
see also MPS Server
additional features, 1021:6-10, 4625:4-28
component specifications, 1021:6-10
Ethernet hub description, 4625:4-47, 4625:4-50
list of hardware components, 1021:6-2
supported features, 1021:6-1
MPS unavailable, 4593:3-350
MPS/EPAP 4.0, 1021:1-6, 4625:1-8, 4625:4-11
MPSEL parameter
chg-oap-config, 0002:A-26, 4601:6-113
MPS-to-DSM Data Validation, 4307:2-19
MR, 4802:1-15, 4802:3-42, 4802:3-85, 4802:3-86, 4802:3-87, 4802:3-88, 4802:3-91, 4802:3-92, 4802:3-96, 4802:3-98, 4802:3-103, 4802:3-104, 4802:3-107, 4802:3-111, 4802:3-179
MRGT, 4802:1-15, 4802:3-116
MRGT# Translation Type already assigned, 4801:2-504
MRGT# translation Type is not allowed to be a LNP alias, 4801:2-509
MRGT# Translation Type is not reserved for LNP, 4801:2-505
MRGT# Translation Type value is not reserved for LNP, 4801:2-502
mrgt1, 4802:3-116, 4802:3-121, 4802:3-130, 4802:3-137, 4802:3-138, 4802:3-139, 4802:3-155
mrgt2, 4802:3-116, 4802:3-121, 4802:3-130, 4802:3-137, 4802:3-138, 4802:3-139, 4802:3-155
MRN table is full, 4801:2-352
MSAR=ONLY must be specified exclusively, 4801:2-383
Msg Relay PC must exist in the route table, 4801:2-528
MSGCODE and PARMCODE must both be DEFINED, 4801:2-347
MSRNNAI and MSRNNP parameters must be entered together, 4801:2-786
MSSEL parameter
chg-oap-config, 0002:A-25, 4601:6-113
MSSN or MATERC entered, MPC must also be given, 4801:2-179
MSU reception threshold exceeded, 4593:3-799
MSU routing
ANSI/ITU MTP Gateway (20.0), 4318:2-36
msucount, 4800:9-35
msuroute, 4800:9-66
msutrace, 4800:9-71
MTP, 4802:1-15
Changeback T5 timeout, 4593:3-711
link bypassed SLT phase, 4593:3-703
MTP Adj PC not in routing table, 4593:3-635
MTP and other MRN Message Format Improvements (21.0), 4318:4-119
MTP Circular Route Detection (21.0), 4318:4-124
MTP envelopes, 0004:2-4, 4318:5-174
MTP Invalid TFA received, 4593:3-792

MTP Invalid TFR received, 4593:3-793
MTP Message Received for Network 255, 4593:3-636
MTP rcvd invalid H0/H1 code, 4593:3-612
MTP rcvd invalid TFC - status 0, 4593:3-611
MTP rcvd Transfer Controlled (TFC), 4593:3-610
MTP rcvd unknown DPC, 4593:3-613
MTP rcvd UPU - User SCCP, Cause invalid, 4593:3-957
MTP rcvd User Part Unavailable, 4593:3-608, 4593:3-957
MTP requirements
    Types of Routing Strategies Available, 4318:4-168
MTP Restart (EAGLE 21.0), 4318:4-126
    Alarms, 4318:4-129
    Aligning Signaling Links in a fully Restarting Node, 4318:4-128
    Event Reporting, 4318:4-129
    Existing Commands, 4318:4-130
    Measurements, 4318:4-129
    Message Routing, 4318:4-128
    New Commands, 4318:4-131
MTP Restart Indicator must be off to execute this command, 4801:2-576
MTP restart option not valid for IPGWAPC linksets, 4801:2-699
MTP RSTRT rcvd unexpected user traffic, 4593:3-719
MTP Screening, 0005:2-2
MTPDPCQ cannot be increased while x-list storage is full, 4801:2-383
MTPDPCQ cannot be less than no. of destinations provisioned, 4801:2-387
MTPDPCQ cannot exceed available space in the dstn table, 4801:2-382
MTPRSE parameter is only valid if ITUMTPRS feature is ON, 4801:2-729
MTPRSE parameter is only valid if MTPRS feature is ON, 4801:2-359
MTPRSI is only valid if MTPRS or ITUMTPRS feature is ON, 4801:2-358
MTPRSIT parameter is only valid if MTPRS feature is ON, 4801:2-359
MTPT10ALT cannot be less than level-3 timer T10, 4801:2-399
MTPXLQ cannot exceed available space in the dstn table, 4801:2-367
MTPXLxx parameters are only valid if CRMD feature is ON, 4801:2-367
MULTCC entry already exists in the GSM Options CC list, 4801:2-596
MULTCC entry cannot be NONE, 4801:2-442
MULTCC entry does not exist, 4801:2-637
MULTCC list is full, 4801:2-637
MULTGC=YES not allowed if ITUDUPPC feature is OFF, 4801:2-802
MULTGC=YES requires IPGWI or IPLIMI links, 4801:2-789
MULTGC=YES requires ITU-N or ITU-I point code, 4801:2-811
Multi, 4625:3-19
Multi-Platform Server (MPS) Systems, 1021:6-1, 4625:2-24
multiple alarm conditions, 4307:4-4
Multiple Capability Point Codes (EAGLE 21.0), 4318:4-131
Multiple Flash Download (Release 29.0), 4318:4-132
Multiple LFS Tests (EAGLE 26.0), 4318:4-132
    Changed Commands, 4318:4-135
    Latching versus Non-latching LFS Tests, 4318:4-133
    Limitations, 4318:4-135
    New Commands, 4318:4-135
Multiple Linksets between Two Nodes
    Multiple Point Code Support (EAGLE 26.05), 4318:4-138
multiple point code support, 4804:2-40

Local Number Portability, 4804:2-44
Multiple Point Code Support (EAGLE 26.05), 4318:4-135
Enhanced Commands, 4318:4-142
Impact on Other Features, 4318:4-140
Limitations, 4318:4-143
Local Subsystems (LNP and Toll-Free), 4318:4-140
Measurements, 4318:4-141
Multiple Linksets between Two Nodes, 4318:4-138
New Commands, 4318:4-142
Provisioning Multiple Point Codes, 4318:4-143
Replacing Two STP Pairs with One Eagle Pair, 4318:4-136
UIMs, 4318:4-143
Upgrade Considerations, 4318:4-143
Multiple Sessions per User, 4307:3-82
Multi-Port LIM, 0002:3-63
Multi-Port LIM (EAGLE 27.1)
Changed Commands, 4318:4-145
Hardware Requirements, 4318:4-147
Upgrade Considerations, 4318:4-147
Multi-Port LIM (Release 27.1) (IP7 Release 6.0), 4318:4-144
Multi-Port LIM(EAGLE 27.1), 4318:4-144
Multi-Purpose Server, 1021:1-6, 4625:1-8, 4625:4-11, 4626:1-12
Multi-Purpose Server (MPS)
New Hardware (EAGLE 26.05), 4318:4-186
Must be in upgrade phase 3 or full function mode, 4801:2-426
Must enter at least one PC/RC pair, 4801:2-463
Must Enter Command Script File Name message, 0008:2-82
Must specify ALL=YES to delete all files, 4801:2-95
Must specify application and version, 4801:2-96
Must specify either
ENTRY or ROW with COLUMN, 4801:2-540
Must specify either SNAME or ASNAME, 4801:2-814
Must specify NC when NI is specified for ORIGNINC, 4801:2-539
MySQL Backup menu, 4307:5-24

N

N1 must be either 1080 or 2104, 4801:2-298
NA entry already equipped, 4801:2-839
NA entry not found, 4801:2-839
NACTION must be specified (FORWARD, DUPLICATE, or DUPDISC), 4801:2-461
NACTION parameter must be FORWARD, DUPLICATE, or DUPDISC, 4801:2-460
Nagle's Algorithm, 0003:2-37
NAI and NAIV must not be specified together, 4801:2-612
NAI entries per TT-NP combination has reached allowed max, 4801:2-617
Name field, 4307:3-7
NAME not valid with ACTION=RESET, 4801:2-311
National PC is identical to national CPC, 4801:2-72
National Spare Network Indicator Support (EAGLE 22.2), 4318:4-147
Changed Commands, 4318:4-148
Disabled States, 4318:4-148
Enabled States, 4318:4-148

Gateway STP Impact, 4318:4-148
National Spare Network Indicator Support (EAGLE 24.0), 4318:4-149
Changed Commands, 4318:4-150
Disabled States, 4318:4-150
Enabled States, 4318:4-149
Gateway STP Impact, 4318:4-150
navigation commands, ELAP log viewer, 4307:3-70
NC cannot be zero when NI is less than 6, 4801:2-210
NC is invalid, 4801:2-215
NC is invalid for type-enttype combo, 4801:2-565
NCAI param is only valid if both feat CRMD and NCR are ON, 4801:2-376
NCAI required if cluster members have different route set, 4801:2-380
NCDPNPFX already exists in INPOPTS Table, 4801:2-75
NCGSR shouldn't be specified when CDSR is specified, 4801:2-882
ncice, 0003:3-250, 0003:3-263
NCICE unspecified, NCICS must be less than or equal to CICE, 4801:2-720
ncics, 0003:3-250, 0003:3-263
NCICS must be less than or equal to NCICE, 4801:2-716
NCICS unspecified, NCICE must be greater than or equal to CICS, 4801:2-730
NCM is invalid, 4801:2-216
NCM must be * when using Network Routing, 4801:2-416
NCPC, 4802:1-15, 4804:2-65
NCPCA, 4802:1-15, 4804:2-65
NCPCI, 4802:1-15, 4804:2-65
NCPCN, 4802:1-15, 4804:2-65
NCPCx and CPCx type must match, 4801:2-377
NCPCx cannot be specified without CPCx, 4801:2-378
NCR must be enabled to enter NCAI param, 4801:2-360
ND, 4802:1-15, 4802:4-5, 4802:4-21, 4802:4-24, 4802:4-25, 4802:4-28, 4802:4-29, 4802:4-31, 4802:4-32, 4802:4-33
ND parameter must be 3 or 6-10, 4801:2-453
NDC Q.3 association is available, 4593:3-264
NDC Q.3 association is unavailable, 4593:3-263
NDC Subsystem is available, 4593:3-267
NDC Subsystem is not available, 4593:3-265
NDC System not configured, 4801:2-702
NDFLTACT must be specified (FORWARD, DUPLICATE, or DUPDISC), 4801:2-461
NDFLTACT parameter must be FORWARD, DUPLICATE, or DUPDISC, 4801:2-342
NDGT parameter is invalid for VGTT, 4801:2-793
NDGT parameter not permitted with ALIAS, 4801:2-194
NDIGITS parameter mandatory with PREFIX parameter, 4801:2-36
NEBS, 4601:3-33, 4751:1-7
NEBS Compliance (EAGLE 20.0), 4318:4-151
NEI LBP has already been defined for the CCS7 link, 4801:2-392
NEI LBP must be defined as the last link element, 4801:2-393
Nested Cluster Routing (EAGLE 26.0), 4318:4-152
Administration, 4318:4-154
Changed Commands, 4318:4-165
General Requirements, 4318:4-155
Nested Clusters and Cluster Members, 4318:4-152
Upgrade Considerations, 4318:4-165
Nested Clusters and Cluster Members

Nested Cluster Routing (EAGLE 26.0), 4318:4-152
netmask IP address, 4307:5-19
Netra t 1400
see also MPS Server
front view, 4625:4-25
LEDs, 4625:4-31
rear view, 4625:4-26
netstat, 4800:9-83
netstat -a | grep 21, 0008:2-119
Network, 4593:6-6, 4626:A-13
network, 4593:5-22
complex, 4804:3-7
configuration, 1021:6-7, 2712:2-14
interfaces, 1021:6-7, 2712:2-15
MPS Server ports, 4625:4-28
Quad FastEthernet Interface card, 4593:6-122
Quad FastEthernet Network Interface card, 4625:4-30
syscheck, 2712:3-13
types, 4804:2-2
Network Alarm, 4593:6-8
Network appearances, 0003:3-4
network element data
automatic resynchronization of, 4751:4-2
Network Equipment Building System, 4751:1-7
Network latency, 0008:2-122
Network Management Measurements, 4593:4-31
network routing, 4804:2-145
administration, 4804:2-151
broadcast transfer messages, 4804:2-148
circular routing, 4804:2-149
local link congestion, 4804:2-148
point code availability, 4804:2-147
reception of an RCx message, 4804:2-151
reception of an RSx message, 4804:2-150
reception of transfer messages, 4804:2-150
remote congestion, 4804:2-148
response method transfer messages, 4804:2-148
route availability, 4804:2-147
route management, 4804:2-148
routing strategies, 4804:2-145
Network Routing (EAGLE 26.0)
Types of Routing Strategies Available, 4318:4-167
Network Routing is only valid if the NRT feature is ON, 4801:2-415
network routing point code, 4804:2-3
Network Security Enhancements (Release 29.0), 4318:4-175
Network Security Enhancements Controlled Feature
Activating, 0002:B-3
Deactivating, 0002:B-39
Network Security Enhancements feature must be ON, 4801:2-542
Network Surveillance Enhancements (Release 28.0), 4318:4-183
network time protocol
configuring, 2712:2-17

in Tekelec 1100 AS platforms, 2712:2-17
in TekServer platforms, 1021:6-8
overview, 2712:2-17
network values, 0007:2-61, 4307:5-27
network, customer (provisioning)
configure IP addresses, 4307:5-19
description, 4307:2-9
network, Dialup PPP
description, 4307:2-9
IP addresses, 4307:2-9
modem for, 4307:2-9
remote dial-in serial port configuration, 4307:2-9
network, ELAP Sync
configure IP addresses, 4307:5-19
description, 4307:2-4, 4307:2-8
IP addresses, 4307:2-8
network, Ethernet
100BASE-T, 4307:2-7, 4307:2-8
10BASE-T, 4307:2-7
DSM networks, 4307:2-4, 4307:2-7
ELAP Sync network, 4307:2-8
Network / Cluster cannot have alias DPC members, 4801:2-379
Network / Cluster DSTNs are not supported in the X.25 domain, 4801:2-373
networks
RFC 1587 standard, 0007:2-32, 4307:2-7
sample IP addresses for, 4307:2-7
networks, DSM
configure IP addresses, 4307:5-20
description, 4307:2-4, 4307:2-7
IP addresses, 4307:2-7
new administration commands
Thresholding of UIM Messages (EAGLE 25.0), 4318:5-127
New ANSI Capability Point Code, 4802:1-15
New Capability Point Code, 4802:1-15
New CIC range overlaps an existing routing key, 4801:2-715
New class name cannot be the same as an existing class name, 4801:2-127
new commands
48 Million Numbers (27.0), 4318:2-13
CDU for DSM (26.05), 4318:2-61
Eagle Application Support for E1 (26.3), 4318:2-104
Enhanced Bulk Download (25.0), 4318:2-149
Enhanced GTT (26.0), 4318:2-153
Flash Memory Management (23.0), 4318:3-4
G-Port MNP (26.2), 4318:3-20
GSM MAP Screening (26.1), 4318:3-43
INAP-based Number Portability (INP) (26.05), 4318:3-78
MTP Restart (EAGLE 21.0), 4318:4-131
Multiple LFS Tests (EAGLE 26.0), 4318:4-135
Multiple Point Code Support (EAGLE 26.05), 4318:4-142
Selective Alarm Inhibiting (EAGLE 22.0), 4318:5-74
Stand-alone Eagle G-Flex Relay Function, 4318:3-13
Support for LSMS Audit Enhancements (EAGLE 26.1), 4318:5-98, 4318:5-102

Translation Type Mapping (EAGLE 21.0), 4318:5-130
New connection type must be different from existing, 4801:2-298
New Control Shelf Backplane (EAGLE 23.0), 4318:4-184
New digits valid (DV) must not match old DV indication, 4801:2-519
new features
IP7 Transport Feature (26.1), 4318:3-113
New Global Title Translation Type, 4802:1-15, 4802:3-85, 4802:3-87, 4802:3-102, 4802:3-103, 4802:3-116, 4802:3-117, 4802:3-130, 4802:3-137, 4802:3-139, 4802:3-154, 4802:3-155
new GPLs
Enhanced Bulk Download (25.0), 4318:2-146
New GTT matches old GTT, 4801:2-515
New H0/H1 matches existing wild carded H0/H1 in given SR, 4801:2-211
New Hardware (EAGLE 23.1)
Integrated LIM-AINF Card, 4318:4-185
New Hardware (EAGLE 26.05), 4318:4-186
Multi-Purpose Server (MPS), 4318:4-186
New ITU International Capability Point Code, 4802:1-15
New ITU National Capability Point Code, 4802:1-15
new measurement reports
ITU Gateway Measurements Enhancements (26.05), 4318:3-157
New Message Relay Global Title Translation, 4802:1-16
New PC and RC must be entered as a pair, 4801:2-462
New PC does not exist in the routing table, 4801:2-181
New Service Provider is already assigned, 4801:2-495
New Translation Type already in LNP database, 4801:2-488
New Translation Type Name already in LNP database, 4801:2-489
new UAMs/UIMs
Group Ticket Voucher for SCCP Cards (27.0), 4318:3-41
new UIMs
TSM Warm Restart and Incremental Loading (EAGLE 26.0), 4318:5-142
New User Default Groups, 4307:3-111
new/changed commands
High-Speed Multiplexer (HMUX) (27.2), 4318:3-63
New/existing NSFI=AFTPC requires new/existing SSN=1, 4801:2-211
New/existing PC does not exist in the remote PC table, 4801:2-180
New/existing RI must be GT for new/existing XLAT=DPCNGT, 4801:2-180
NEXT requires this term issued last valid RTRV-LOG command, 4801:2-858
NGT, 4802:1-15, 4802:3-42, 4802:3-44, 4802:3-82, 4802:3-85, 4802:3-87, 4802:3-88, 4802:3-91, 4802:3-92, 4802:3-96, 4802:3-97, 4802:3-98, 4802:3-102, 4802:3-104, 4802:3-107, 4802:3-111, 4802:3-116, 4802:3-118, 4802:3-126, 4802:3-127, 4802:3-130, 4802:3-137, 4802:3-139, 4802:3-141, 4802:3-145, 4802:3-151, 4802:3-154, 4802:3-156, 4802:3-157, 4802:3-161, 4802:3-176, 4802:3-178, 4802:3-179, 4802:3-180, 4802:3-182
NGT can only be specified when XLAT=DPC or DPCNGT, 4801:2-865
NGT can only be specified when XLAT=DPCNGT, 4801:2-182
NGT must be 0 when XLAT is not DPCNGT, 4801:2-497
NGT must be specified for new values of XLAT/RI, 4801:2-182
NGT must be specified when XLAT=DPCNGT, 4801:2-198
NGT# Translation Type is not allowed to be a LNP alias, 4801:2-517
NGT# Translation Type is not reserved for LNP, 4801:2-511
NGT# Translation Type must already be assigned, 4801:2-509
ngt1, 4802:3-102
ngt2, 4802:3-102

NGTI only valid when PC and GTTSN are different domains, 4801:2-844
NGTI only valid when PC and TYPE are different domains, 4801:2-855
NH0 and NH1 cannot be specified for NSI greater than 2, 4801:2-202
NH0 and NH1 cannot be specified for SI greater than 2, 4801:2-212
NH0 and NH1 must be specified for given NSI, 4801:2-211
NH1 must be wild card if NH0 is wild card, 4801:2-213
NI is invalid, 4801:2-214
NI is invalid for type-enttype combo, 4801:2-564
NI parameter may not be specified for ITU linksets, 4801:2-624
NI required, 4801:2-124
NI, ZONE, MSA or NPC cannot be C - more than one exists, 4801:2-205
NI, ZONE, MSA or NPC cannot be C for existing blocked SR, 4801:2-206
NI, ZONE, MSA or NPC must be C when creating new blocked SR, 4801:2-221
NIC and SI must be specified for given H0 and H1, 4801:2-243
NIC does not exist for given SR, 4801:2-220
NIC must be specified for given SI, 4801:2-220
NIC, SI, and H0/H1 entry already exists in given SR, 4801:2-242
NIC, SI, H0/H1,& PRI entry already exist in given SR, 4801:2-533
NLRN must be specified when RGTA=YES, 4801:2-510
NLRN, or NGT# must be specified, 4801:2-522
NMR, 4802:3-102
NMRGT, 4802:1-16
NMRGT# is not assigned, 4801:2-513
NMRGT# Translation Type is not a reserved service for LNP, 4801:2-529
NMRGT# Translation Type is not allowed to be a LNP alias, 4801:2-508
nmrgt1, 4802:3-130, 4802:3-134, 4802:3-154, 4802:3-155
nmrgt2, 4802:3-130, 4802:3-154, 4802:3-155
NMULTCC and MULTCC parameters must be entered together, 4801:2-102
NMULTCC entry already exists in the GSM Options MULTCC list, 4801:2-607
NNGT, 4802:3-176, 4802:3-177, 4802:3-181
NNIC, NSI, and NH0/NH1 entry already exists in given SR, 4801:2-218
NNP,NNAI,NPDD/S,NSDD/S,NGTI,RMGTT invalid if MGTT is OFF, 4801:2-345
NNPANXX already exists, 4801:2-514
No active LFS Test on the specified link, 4801:2-396
No available primary MCP, 4801:2-478
No buffer space available - Error code 55, 0008:2-117
No change requested, 4801:2-716
No Entry found, 4801:2-683
No File Transfer Area on removable cartridge, 4801:2-97
No key is available on the SSH client on the Eagle - Error code 668, 0008:2-112
No match on ACTNAME parameter during retrieve, 4801:2-653
No match on AREA or SSA parameter during retrieve, 4801:2-222
No match on DESTFLD parameter during retrieve, 4801:2-411
No match on EPRI parameter during retrieve, 4801:2-222
No match on H0 parameter during retrieve, 4801:2-223
No match on H1 parameter during retrieve, 4801:2-223
No match on ID or SP parameter during retrieve, 4801:2-223
No match on NC parameter during retrieve, 4801:2-224
No match on NCM parameter during retrieve, 4801:2-224
No match on NI parameter during retrieve, 4801:2-225
No match on NIC parameter during retrieve, 4801:2-225
No match on NPC parameter during retrieve, 4801:2-226

No match on NSFI parameter during retrieve, 4801:2-226
No match on NSR parameter during retrieve, 4801:2-226
No match on PRI parameter during retrieve, 4801:2-227
No match on REDIRECT parameter during retrieve, 4801:2-313
No match on RI parameter during retrieve, 4801:2-227
No match on SCCPMT parameter during retrieve, 4801:2-411
No match on SCMGFID parameter during retrieve, 4801:2-412
No match on SI parameter during retrieve, 4801:2-227
No match on SSN parameter during retrieve, 4801:2-228
No match on TYPE parameter during retrieve, 4801:2-228
No match on ZONE or MSA parameter during retrieve, 4801:2-228
No MIC of TYPE=ALL exists, 4801:2-456
No MIC with the same service and digits exists, 4801:2-456
No obits to display, 4801:2-161
No optional parameters may be specified if FORCE=YES, 4801:2-268
No other optional parameters may be specified with “ALL”, 4801:2-649
No other optional parms can be entered with SRCSET, 4801:2-685
No other parameters are permitted with the NEXT parameter, 4801:2-858
No Reportable Downtime on Network Restart
Upgrade Procedure Enhancements (Eagle 22.0), 4318:5-157
No test link message is sent, 4801:2-153
No troubles to display, 4801:2-161
No user associated with OAP terminal, 4801:2-388
No value expected for ‘<parm>’ parameter (C<col>), 4801:2-553
Node is no longer isolated, 4593:3-398
Node isolated due to SLK failures, 4593:3-396
non oxidizing grease, 4601:4-15, 4601:4-17
Non-ANSI Point Code Support (EAGLE 20.0), 4318:4-186
NONE is a reserved name and cannot be used for a TTN, 4801:2-519
None terminal type, 0002:4-55
Non-Generation of Duplicate SEAS Autonomous Messages (EAGLE 22.0), 4318:4-186
Non-Integrated Sentinel Solutions, 4625:2-29
NORM=YES not supported for specified PSTNCAT/PSTNID values, 4801:2-802
Normal GTT processin, 4318:5-20
normal retransmission
Preventive Cyclic Retransmission (PCR) (EAGLE 20.0), 4318:5-28
Not compatible with SCCP Conversion feature, 4801:2-843
Notification of Congestion Level Increase (EAGLE 22.0), 4318:4-187
Notification of Inability to Perform a Global Title Translation (EAGLE 22.0), 4318:4-188
Notification of Link Set Outage (EAGLE 22.0), 4318:4-188
Notification of Link Set Recovery (EAGLE 22.0), 4318:4-188
Notification of Locally Initiated Database Copy (EAGLE 22.0), 4318:4-189
Notification of MTP-Level Routing Error (EAGLE 22.0), 4318:4-190
Notification of Recovery from Link Congestion (EAGLE 22.0), 4318:4-190
notification, database maintenance required, 4751:3-3
notifications, 4751:4-2, 4751:4-3
NP and NAI must be specified as DFLT together, 4801:2-624
NP and NPV must not be specified together, 4801:2-612
NP ported TNs 2million Qty Feat Requires at least TSM256MB, 4801:2-705
NP(V) and NAI(V) must be specified for given GTI value, 4801:2-613
NP(V) and NAI(V) must not be specified for given GTI value, 4801:2-613
NPA, 4802:1-16

NPANXX, 4318:4-73, 4318:4-85, 4802:1-16, 4802:3-42, 4802:3-44, 4802:3-82, 4802:3-85, 4802:3-86, 4802:3-87, 4802:3-88, 4802:3-91, 4802:3-92, 4802:3-93, 4802:3-94, 4802:3-95, 4802:3-96, 4802:3-97, 4802:3-98, 4802:3-99, 4802:3-100, 4802:3-101, 4802:3-102, 4802:3-103, 4802:3-104, 4802:3-107, 4802:3-108, 4802:3-109, 4802:3-110, 4802:3-111, 4802:3-112, 4802:3-113, 4802:3-114, 4802:3-115, 4802:3-126, 4802:3-127, 4802:3-138, 4802:3-141, 4802:3-145, 4802:3-151, 4802:3-155, 4802:3-157, 4802:3-161, 4802:3-179, 4802:3-180
NPANXX already Split, 4801:2-514
NPANXX does not exist, 4801:2-499
NPANXX Measurements
LNP—Measurements (22.0), 4318:4-68
NPANXX must already be split, 4801:2-517
NPANXX must be specified when ENPANXX is specified, 4801:2-520
NPANXX Quantities on the Eagle - Increasing, 0007:2-153
NPANXX requires TT also be entered, 4801:2-518
NPA-NXX Split / Delete, 4307:3-59
NPA-NXX Split menu, 4307:3-58
NPA-NXX Split screen, 4307:3-46
NPPSMSGTA already exists in GSMOPTS Table, 4801:2-471
NRGTA, 4802:3-176, 4802:3-177, 4802:3-179, 4802:3-181
NSAP parameter requires LNP feature, 4801:2-664
NSD Systems, 4625:1-5
NSFI / NSR cannot be specified, 4801:2-230
NSFI and NSR do not reference an existing screen, 4801:2-231
NSFI is invalid, 4801:2-531
NSFI must be FAIL, 4801:2-230
NSFI must be specified, 4801:2-229
NSFI must be STOP, 4801:2-230
NSFI must be STOP if ACTNAME is specified, 4801:2-646
NSFI must be STOP if COPY or REDIRECT are specified, 4801:2-200
NSFI must not be FAIL, 4801:2-229
NSI must be specified for given NNIC, 4801:2-231
nslookup, 4800:9-94
NSNAI = NONE only allowed when NSERV = INPQ, 4801:2-787
NSNAI must be specified when NSERV = INPMR, 4801:2-774
NSNAME or attributes required, 4801:2-723
NSR cannot be specified if ACTNAME is specified, 4801:2-645
NSR cannot be specified if COPY or REDIRECT are specified, 4801:2-210
NSR cannot be specified when NSFI is STOP or FAIL, 4801:2-233
NSR must be specified for given NSFI, 4801:2-232
NSTAT, 4802:3-67, 4802:3-71, 4802:3-74
NTP
configuring, 2712:2-17
in Tekelec 1100 AS platforms, 2712:2-17
in TekServer platforms, 1021:6-8
overview, 2712:2-17
NTP server, 4307:5-27
NTP Time Available, 4593:3-580
NTP Time Unavailable, 4593:3-579
NTT can only be specified when XLAT=DPC or DPCNGT, 4801:2-866
NTT can only be specified when XLAT=DPCNGT, 4801:2-619
NTT must be specified for new values of XLAT/RI, 4801:2-622
NTT must be specified when XLAT=DPCNGT, 4801:2-620

NUM exceeds maximum table size, 4801:2-184
Number of PREFIX digits cannot exceed NDIGITS parameter, 4801:2-37
Number out of range, 4801:2-163
Number Pooling (EAGLE 24.0), 4318:4-191
  Changed Commands, 4318:4-191
Number Pooling / Efficient Data Representation (EDR) (EAGLE 26.1), 4318:4-192
  Changed Commands, 4318:4-196
  Limitations, 4318:4-196
  Overview, 4318:4-193
  Upgrade Considerations, 4318:4-195
Number Portability Administration Center (NPAC), 4307:2-11, 4751:1-1, 4751:2-2
Numbering Plan Area, 4802:1-16
NZO is not valid for this TYPE, 4801:2-124

O

OA&M IP Security feature disabled, 4593:3-298
OA&M IP Security feature is OFF, 4593:3-499
OA&M IP Security feature is ON, 4593:3-500
OAM IP Security Enhancements Controlled Feature - Eagle
  Activating, 0002:B-12
  Deactivating, 0002:B-39
OAM reboot during bulk download
  Enhanced Bulk Download (25.0), 4318:2-149
OAM switchove, 4318:5-10
OAP, 4601:6-5, 4625:3-26, 4802:1-16
OAP - Removing the hsopEnabled File, 0007:2-150
OAP Alarm (OAPALM), 4625:3-26
OAP alarm installation, 4601:5-87
OAP CFG required before OAP update, 4801:2-667
OAP commands
  Eagle Initiated OAP User Interface (24.0), 4318:2-115
OAP filesystem full, 4593:3-481
OAP frame, 4601:3-27
OAP GPL
  change trial to approved version, 0002:3-111
OAP Hostname required before OAP update, 4801:2-667
OAP IP Address required before OAP update, 4801:2-668
OAP is available, 4593:3-463
OAP parameter
  chg-oap-config, 0002:A-26, 4601:6-113
OAP terminal type, 0002:4-55
OAP terminals available, 4593:3-463
OAP terminals inhibited, 4593:3-458
OAP Unavailable, 4593:3-436
OAP Upgrade Enhancement (EAGLE 27.2), 4318:4-196
OAP Year 2000 Compliance
  Year 2000 Compliance (Eagle 23.1), 4318:5-188
OAPALM, 4625:3-26
OAPF, 4625:3-146, 4625:4-46
Obituaries, 4593:3-65
Occurrence argument - not valid (C<col>), 4801:2-548

Octet 1 is out of range, 1 . . . 223 - <parm>, 4801:2-13
Octet 1 missing - <parm>, 4801:2-16
Octet 2 is out of range, 1 . . . 254 - <parm>, 4801:2-13
Octet 2 missing - <parm>, 4801:2-16
Octet 3 is out of range, 1 . . . 254 - <parm>, 4801:2-15
Octet 3 missing - <parm>, 4801:2-17
Octet 4 is out of range, 1 . . . 254 - <parm>, 4801:2-15
Octet 4 missing - <parm>, 4801:2-17
OCTET and ALTERNATE are not valid for non-latching test, 4801:2-398
octets
changing ELAP Sync network IP address third, 4307:5-19
DSM network IP address, 4307:2-7
ELAP Sync network IP address, 4307:2-8
OCU, 4625:3-68
OEM-Based Network Elements, 4625:2-30
OEM-Based Peripheral Components, 4625:2-31
OEM-Based Products, 4625:1-8
OEM-Based Products and Elements, 4625:2-24
OEM-Based Servers, 4625:2-30
Office Channel Unit (OCU), 4625:3-65
Office Prefix, 4802:1-16
On-demand report currently being printed, 4801:2-123
One SEAS TDM Port unavailable, 4593:3-464
one-inch diameter hole, 2969:4-5, 4601:3-15
Online Cartridge Formatting (EAGLE 20.0), 4318:4-197
Only 4 ports with sys maint. output group ON are allowed, 4801:2-156
Only 6 message relay services can be assigned, 4801:2-530
only one ITU-I APC/SAPC allowed per linkset, 4801:2-835, 4801:2-836
Only one of BYTE, WORD or DWORD may be entered, 4801:2-89
Only one of IPADDR, IPAPPL, IPRTE, or LOC can be specified, 4801:2-271
Only one of IPAPPL or IPPORT may be specified, 4801:2-267
Only one of NCPC/A, NCPCI, or NCPCN/N24 may be specified, 4801:2-69
Only one of PPCN or PCN24 may be specified, 4801:2-280
Only one optional parameter may be specified, 4801:2-262
Only one Source and Destination may be specified, 4801:2-91
Only one SS7IPGW or IPGWI link allowed in mated linkset, 4801:2-695
Only PARMCODE=0 (EOP) can have MINLEN=0, 4801:2-346
Only SNAME, ASNAME or RCONTEXT allowed for default rtkey, 4801:2-814
on-site MPS, 0007:2-62, 4307:5-28
OOS-MT-DSBLD, 4802:1-16, 4802:3-67, 4802:3-73, 4802:3-74
OOS-MT-DSBLD (out of service maintenance disabled), 4318:3-124
OOS-MT-DSBLD state, 0002:A-19, 0002:A-35, 0002:A-63, 4601:6-109, 4601:6-121, 4601:6-136
OP/MAINT LED, 4593:2-7
OPC, CICS, CICE are not allowed with SI unless SI is 4, 5, or 13, 4801:2-702
OPC, CICS, CICE are required if SI is 4, 5, or 13, 4801:2-701
opc/opca, 0003:3-233, 0003:3-242, 0003:3-250, 0003:3-262
OPCODE already exists, 4801:2-747
OPCODE and OPNAME shouldn't be specified together, 4801:2-795
open, 0003:3-209
OPEN must be NO to change an Association or its ASP/A, 4801:2-824
OPEN must be NO to change or delete socket, 4801:2-689
Open sockets cannot have same lhost/lport, 4801:2-737

openSSH 3.0.2p1, 0008:2-105, 0008:2-106, 0008:2-107, 0008:2-108, 0008:2-109, 0008:2-110, 0008:2-111, 0008:2-112, 0008:2-113, 0008:2-114, 0008:2-115, 0008:2-119
Operating system, 0008:2-2
Windows 2000, 0008:2-6
Windows 98, 0008:2-7
Windows NT, 0008:2-6
operating system, Solaris 7, 4625:4-28
Operations Support System Application Processor frame (OAPF), 4625:3-4
Operations Support System Application Processors (OAP), 4625:3-3
Operations Support System Applications Processor, 4625:1-9, 4625:2-25
Operations System Support Applications Processor, 4802:1-16
operations system support applications processor frame (OAPF), 4625:3-16
operations, Escape key to exit user interface, 4307:5-12
OPNAME already used, 4801:2-747
OPNAME does not exist in the database, 4801:2-748
optical disk drives, 1021:4-10
Option
LSRESTRICT, 4804:3-88, 4804:3-233, 4804:3-234, 4804:3-235, 4804:3-236, 4804:3-237
Restricted Linkset - Configuring, 4804:3-233, 4804:3-238, 4804:3-239
Option for Subsystem Prohibit (Release 29.0), 4318:4-197
Optional 15-Minute Measurements, 4593:4-10
options
changing
SCCP Class 1 Sequencing, 0006:2-20, 0006:2-194, 0006:2-195, 0006:2-196, 0006:2-197
options, audit and reconcile, 4751:5-7
orange flag, 4601:4-23
Ordered routes cannot be assigned to cluster members, 4801:2-380
Ordered routes cannot be changed for cluster members, 4801:2-384
Ordered routes cannot be deleted from cluster members, 4801:2-381
originating MSC, 4318:5-19
OUTGRP and SNUM/ENUM combination invalid, 4801:2-858
output banner format, 4800:4-15
output groups, unsolicited messages, 4800:4-15
Output Message Format, 4593:3-37
output messages, types of, 4800:4-14
overhead rack support, attaching, 2969:4-19
Override GTT, 4307:3-44
Override GTT menu, 4307:3-55
Overview, 4625:1-3, 4625:3-43
Activating the LNP Feature, 0007:2-6
ELAP Software Configuration, 0007:2-38
ELAP User Interfaces, 0007:2-38
overview
database partitions, 0002:1-9, 0003:1-9, 4804:1-9
fixed disk drive, 0002:1-10, 0003:1-10, 4804:1-10
maintenance and administration subsystem, 0002:1-8, 0003:1-8, 4804:1-8
Number Pooling/Efficient Data Representation (EDR) (EAGLE 26.1), 4318:4-193
removable cartridge, 0002:1-11, 0003:1-11, 4804:1-11
Overview of ELAP UI, 4307:5-2
Overview of LSMS Hardware Components, 1021:4-11
Overview Sentinel Products, 4625:5-3
overview, Tekelec 1100 AS platform software, 2712:2-1

P

P, 4601:B-51, 4601:C-49, 4626:B-22, 4626:C-50
P Address still referenced by static IP Routes, 4801:2-632
P / N 000-0028-01, 4601:A-21
P / N 502-0040-01, 4601:6-27
P / N 502-0085-01, 4601:4-19
P / N 551-0022-02, 2969:7-2
P / N 551-0022-03, 2969:7-2
P / N 654-0075-01 gray tinted Lexan rear covers (with round holes), 4601:3-37
P / N 658-0374-01 (Label - General Purpose Frame), 4601:3-28
P / N 658-0604-01, 4601:2-10
P / N 658-0604-02, 4601:2-10
P / N 658-0604-03, 4601:2-10
P / N 690-0108-07, 4601:4-15
P / N 690-0131-01, 2969:6-8, 4601:4-19
P / N 803-0229-01, 4601:C-7, 4626:C-7
P / N 804-0165-01, 4601:A-7
P / N 804-0166-01, 4601:A-32
P / N 804-0173-01, 4601:A-28
P / N 804-0175-01, 4601:A-24
P / N 804-0219-01, 4601:3-16, 4601:3-18, 4601:3-19
P / N 804-0228-01, 2969:6-3, 2969:6-8, 4601:4-19
P / N 804-0229-01 window clear heat shrink, 4601:4-15
P / N 804-0817-02, 2969:6-8, 4601:4-8, 4601:4-18, 4601:4-19, 4601:4-20
P / N 804-0977-01 long barrel lug, 4601:4-15
P / N 804-1671-02, 4626:2-64
P / N 830-0226-xx, 4601:5-83
P / N 830-0425-01, 4625:3-96
P / N 830-0543-01, 4601:5-113, 4601:C-20, 4626:C-19
P / N 830-0609-01, 4601:C-29
P / N 830-0657-xx, 4601:6-44
P / N 830-0709-xx, 4601:6-32
P / N 830-0846-01, 4601:5-83
P / N 830-0873-xx), 4601:5-83
P / N 840-0017-02, 4601:3-33
P / N 840-1125-03, 2969:7-2
P / N 840-1133-01, 2969:7-2
P / N 850-0188-01, 4601:A-20
P / N 850-0330-03, 4601:B-3, 4601:B-4, 4601:B-18, 4625:3-21, 4625:3-22, 4625:3-26, 4625:3-27, 4625:3-43, 4626:B-2, 4626:B-3
P / N 850-0330-03 / 04, 4601:B-3, 4626:B-2
P / N 850-0330-05, 4601:5-22, 4601:B-3, 4601:B-4, 4601:B-19, 4626:B-2, 4626:B-3
P / N 850-0330-05 / 06, 4601:B-3, 4601:B-19, 4601:C-29, 4626:B-2
P / N 850-0356-01, 4601:B-25, 4601:B-61, 4626:B-9, 4626:B-24
P / N 850-0356-03, 4601:B-26, 4601:B-27, 4601:B-61, 4626:B-24
P / N 850-0356-03 Extension Shelf Back Plane, 4625:3-14
P / N 850-0488-xx, 4601:6-44
P / N 870-0243-08, 4601:B-37
P / N 870-0259-02, 4601:3-33
P / N 870-0773-XX, 4601:A-23, 4626:A-10
P / N 870-0774-10, 4601:1-6
P / N 870-0774-xx, 4601:A-29, 4601:A-31

P / N 870-1008-xx, 4601:A-4, 4625:3-93
P / N 870-1009-xx, 4593:A-24, 4593:A-28, 4593:A-29, 4601:5-134, 4601:A-9, 4601:A-25, 4601:A-26, 4626:A-11, 4626:A-12
P / N 870-1010-xx, 4601:A-27
P / N 870-1011-xx, 4601:A-5
P / N 870-1012-xx, 4601:A-33
P / N 870-1013-xx, 4601:A-22, 4626:A-9
P / N 870-1014-xx, 4593:A-25, 4601:A-6, 4626:A-3
P / N 870-1171-03, 4601:A-20
P / N 870-1293-xx, 4593:A-25, 4601:A-6, 4626:A-3
P / N 870-1307-04, 4601:A-22, 4626:A-9
P / N 870-1379-xx, 4593:A-25, 4593:A-26, 4601:5-120, 4601:A-6, 4601:A-11, 4601:A-12, 4626:A-3, 4626:A-5
P / N 870-1484-xx, 4593:A-25, 4601:A-6, 4626:A-3
P / N 870-1488-xx, 4593:A-25, 4626:A-3
P / N 870-1606-01, 4601:2-10, 4601:5-154, 4601:5-155, 4625:3-119, 4625:3-130
P / N 870-1824-01, 4601:5-63
P / N 870-1915-01, 4601:2-10
P / N 870-1965-04, 4601:1-6
P / N 870-1984-01, 4601:5-25
P / N 870-2049-01, 4593:A-25, 4601:A-6, 4626:A-3
P / N 870-2320, 4601:4-34
P / N 870-2320-01, 4601:2-10, 4601:4-5, 4601:4-8
P / N 870-2360-01, 4601:1-6
P / N 870-2594-01, 4626:2-64
P / N 870-2595-01, 4626:2-64
P / N 870-2706-02, 2969:7-2
P / N 870-2707-01, 2969:7-2
P / N 870-2708-01, 2969:7-2
P / N 870-2754-01, 2969:7-3
P / N 870-2754-02, 2969:7-3
P / N 870-2785-01, 2969:7-2
P / N 870-2787-01, 2969:7-2
P / N 870-2790-01, 2969:7-2
P / N 870-2795-01, 2969:7-2
P / N 870-2795-02, 2969:7-2
P / N 870-2798-01, 2969:7-2
P / N 870-2799-01, 2969:7-2
P / N 890-1037-01, 4625:3-104
P / N 890-1038-01, 4601:5-68
packaging, documentation, 4307:1-6
Packet drop, 0008:2-122
PAGE, 4802:1-16
parallel ports, MPS Server, 4625:4-27
parameter
    AIPADDR
        chg-oap-config, 0002:A-25, 4601:6-112
    ANAME
        chg-oap-config, 0002:A-25, 4601:6-112
    ANMASK
        chg-oap-config, 0002:A-25, 4601:6-112
    AROUTER

chg-oap-config, 0002:A-25, 4601:6-112
BIPADDR
chg-oap-config, 0002:A-25, 4601:6-112
BNAME
chg-oap-config, 0002:A-25, 4601:6-112
BNMASK
chg-oap-config, 0002:A-25, 4601:6-112
BROUTER
chg-oap-config, 0002:A-25, 4601:6-112
CFG
chg-oap-config, 0002:A-25, 4601:6-112
FORCE
chg-oap-config, 0002:A-26, 4601:6-113
LSMS
chg-oap-config, 0002:A-25, 4601:6-112
MNSAP
chg-oap-config, 0002:A-25, 4601:6-113
MPSEL
chg-oap-config, 0002:A-26, 4601:6-113
MSSEL
chg-oap-config, 0002:A-25, 4601:6-113
OAP
chg-oap-config, 0002:A-26, 4601:6-113
SNSAP
chg-oap-config, 0002:A-26, 4601:6-113
SPSEL
chg-oap-config, 0002:A-26, 4601:6-113
SSSEL
chg-oap-config, 0002:A-26, 4601:6-113
TRM
chg-trm, 0002:A-15
TYPE
chg-trm, 0002:A-15
Parameter AINTVL is not allowed, 4801:2-452
Parameter AINTVL is required, 4801:2-451
Parameter combination invalid, 4801:2-446
Parameter DRTN or AINTVL is required, 4801:2-455
Parameter DRTN or INTVL is required, 4801:2-455
Parameter INTVL is not allowed, 4801:2-451
Parameter INTVL is required, 4801:2-452
Parameter ND is not allowed, 4801:2-450
Parameter ND, DRTN, INTVL, or AINTVL is required, 4801:2-454
parameters for DCM signaling links, 4804:3-6
Parameters inconsistent on re-entering of command, 4801:2-729
Parameters ND, INTVL, and AINTVL are required, 4801:2-449
Parameters not valid for card type, 4801:2-44
Parameters SERV and DGTS are not allowed for TYPE=ALL, 4801:2-450
Parameters SERV and DGTS are required, 4801:2-450
parameters, command, 4800:4-9
Parity, 4802:1-16
PARMCODE is supported in a message, cannot be NOTDEFINED, 4801:2-348
part number

air filter, 2969:B-3
fan assembly, 2969:B-3, 2969:B-6
hard disk drive, 2969:B-9, 2969:B-11, 2969:B-12, 2969:B-14, 2969:B-17
locating, 2969:B-2
PCI card, 2969:B-12
Part Number does not belong to an On/Off Feature, 4801:2-630
Part numbers
air filters, 2969:7-2
fan assemblies, 2969:7-2
Hard drives, 2969:7-2
part numbers, 2712:5-2
part numbers, documentation, 4307:1-6
Partial point codes are not allowed, 4801:2-61
Partial Routing Keys, 0003:2-25
Partition specified invalid for target disk, 4801:2-149
pass, 4800:6-373
pass command, 4318:3-29
pass:loc=xxxx
cmd="netstat -p tcp" Eagle command, 0008:2-121
cmd="ping yy.yy.yy.yy" Eagle command, 0008:2-120
Pass-Through Commands, 4800:2-9, 4800:9-1
password
change at first login, 4800:4-20
change expired at login, 4800:4-21
changing, 0002:4-48
Password Age, 4307:3-110
Password Aging (EAGLE 21.0), 4318:5-1
Password cannot contain userID, 4801:2-333
password complexity checking, 4307:3-110
Password does not contain enough alphabetic characters, 4801:2-328
Password does not contain enough characters, 4801:2-104
Password does not contain enough numeric characters, 4801:2-329
Password does not contain enough punctuation characters, 4801:2-330
Password Encryption (EAGLE 21.0), 4318:5-2
Password operations not allowed on a non-secure terminal, 4801:2-315
Password Requirements (EAGLE 21.0), 4318:5-2
Password Reuse, 4307:3-113
Password Reuse Limit, 4307:3-110
Password too long, 12 maximum, 4801:2-104
Password verification failed, 4801:2-105
passwords
change for ELAP login names, 4307:5-22
passwords, changing, 2969:6-14
passwords, rules for administering, 4800:4-17
Path Field, 0008:2-50
path parameter, 0008:2-50
Pattern contains invalid characters, 4801:2-74
Pattern has odd number of characters, 4801:2-75
PC, 4802:1-16, 4802:3-85, 4802:3-102, 4802:3-116, 4802:3-130, 4802:3-137, 4802:3-154, 4802:3-176, 4802:3-181
PC already exists in CSPC group, 4801:2-170
PC already exists in the MRN entity set, 4801:2-352

PC and RC must be entered as a pair, 4801:2-352
PC cannot match the SID, 4801:2-433
PC does not exist in CSPC group, 4801:2-171
PC does not match existing entry in given SR, 4801:2-533
PC must already exist in the MRN table, 4801:2-366
PC must be ANSI, 4801:2-528
PC must match NPCFMTI set in CHG-STPOPTS, 4801:2-432
PC network type does not match existing PC network type, 4801:2-344
PC/CLLI does not match current PC/CLLI of the STP, 4801:2-135
PC/SSN already exists in given SR, 4801:2-238
PC/SSN does not exist as a mated application, 4801:2-185
PC/SSN does not exist in given SR, 4801:2-237
PC/SSN must be given with Action FORWARD, DUPLICATE, DUPDISC, 4801:2-465
PC/SSN must be specified if FORCE is specified, 4801:2-466
PC/SSN/RI/SCCPMT already exists in given SR, 4801:2-216
PC/SSN/RI/SCCPMT does not exist in given SR, 4801:2-217
PC/SSN/SCMG already exists in given SR, 4801:2-217
PC/SSN/SCMGFID does not exist in given SR, 4801:2-218
PCA, 4802:1-16, 4802:3-42, 4802:3-43, 4802:3-44, 4802:3-57, 4802:3-81, 4802:3-82, 4802:3-87, 4802:3-88, 4802:3-91, 4802:3-92, 4802:3-96, 4802:3-97, 4802:3-98, 4802:3-104, 4802:3-107, 4802:3-111, 4802:3-118, 4802:3-119, 4802:3-122, 4802:3-126, 4802:3-127, 4802:3-132, 4802:3-134, 4802:3-139, 4802:3-141, 4802:3-143, 4802:3-145, 4802:3-151, 4802:3-156, 4802:3-157, 4802:3-159, 4802:3-161, 4802:3-176, 4802:3-178, 4802:3-179, 4802:3-180, 4802:3-182
PCI, 4802:1-16
PCI card
  label, 2969:B-12
  part number, 2969:B-12
  replace, 2969:7-36
PCI cards
  Quad FastEthernet Network Interface card, 4625:4-30
  replacement procedure, 4593:6-122
  SAI/P, 4625:4-30, 4625:4-43
PCI slots, 4625:4-35
PCN, 4802:1-16
PCRN1 and PCRN2 parameters are invalid if ECM=BASIC, 4801:2-39
PCS 1900 LNP Query (EAGLE 26.0), 4318:5-2
  Changed Commands, 4318:5-6
  Feature Functions, 4318:5-3
  Limitations, 4318:5-8
  PLNPQS Details, 4318:5-3
PCS 1900 number portability, 4802:3-30
PCTYPE, 4802:1-16
PCx, CPCx or NCPCx must not be equal, 4801:2-384
PDB Backup Procedure, 4593:6-46
PDB, EPAP
  Backup PDB menu item, 4593:6-18
  backups, 4593:6-18, 4593:6-19
  frequency for backups, 4593:6-18, 4593:6-19
PDB/DN table, 4318:5-20
PDBA, restarting, 4593:6-68
PDS, 4804:2-64
PDS data, 4318:5-11

performance impact
act-oap-config parameters, 0002:A-27, 4601:6-114
PERIOD must be 1 hour boundary for report type, 4801:2-117
PERIOD must be 1/2 hour boundary, 4801:2-122
Period must be 1/4 hour boundary, 4801:2-658
Perl errors, 4307:B-21
Perl Statements and Functions, 4307:B-22
Perm feature key cannot be turned off for the feature, 4801:2-586
Permanently On controlled features, list of, 4800:5-84
Permission is denied by the server due to authentication failure - Error code 633, 0008:2-108
Persisten Device States, 4804:2-64
Persistent device state tbl corrupt, 4593:3-142
Persistent device state tbl diff version, 4593:3-143
Persistent Device States (Release 29.0), 4318:5-10
ping, 4800:9-97
ping -s zz.zz.zz.zz command, 0008:2-120
Ping Test
CDU for DSM (26.05), 4318:2-60
pink lug, 4601:4-15
PIP and GN parameters
Calling Name Conversion Facility (CNCF) (23.1), 4318:2-46
platform, 1021:4-10
alarms, MPS, 4307:4-14
MPS hardware, 4307:2-3
platform alarms, 4593:6-4
Platform Menu, 4307:3-72, 4307:5-23
Platform Menu Exit, 4307:5-25
platform software, 4593:6-4
PLNP feature must be ON, 4801:2-524
PLNPQS details
PCS 1900 LNP Query (EAGLE 26.0), 4318:5-3
PLXO, 4625:3-143
Point Code, 4802:1-16, 4802:2-2, 4802:3-57, 4802:3-59, 4802:3-85, 4802:3-86, 4802:3-102, 4802:3-116, 4802:3-130, 4802:3-137, 4802:3-139, 4802:3-154, 4802:3-176, 4802:3-177
point code
adding, 4804:3-4
alternate, 4804:2-2
cluster destination, 4804:2-3
destination, 4804:2-3
formats, 4804:2-4
full, 4804:2-3
network routing, 4804:2-3
true, 4804:2-2
Point code already exists in given SR, 4801:2-236
point code availability
network routing, 4804:2-147
Point code defined as an alias, 4801:2-133
Point code does not exist in given SR, 4801:2-233
Point code does not exist in the remote point code table, 4801:2-173
Point code does not exist in the routing table, 4801:2-172
Point code matches a STP capability point code, 4801:2-62
Point code matches a STP point code, 4801:2-63

Point code matches a STP secondary point code., 4801:2-867
Point Code must be the STP True point code, 4801:2-523
Point code must exist within the group, 4801:2-261
Point code network type does not match TT network type, 4801:2-194
Point code not defined, 4801:2-283
Point code not equipped, 4801:2-160
Point code out of range, 4801:2-64, 4801:2-239
Point Code Type, 4802:1-16
Point Code type does not match GTT Set network domain, 4801:2-620
Point codes contain invalid wild card combinations, 4801:2-204
Point-to-Multipoint, 0003:2-21
Point-to-Point, 0003:2-20
Point-to-Point Connectivity for ITU Point Codes, 4318:5-12
    Mixed Networks Using the ANSI/ITU Gateway Feature, 4318:5-12
Point-to-Point Protocol (PPP)
    for Dialup PPP network, 4307:2-9
    modem for, 4307:2-9
Policy File, 4307:5-7
pop-up check, 4307:3-11
PORT A LSET, 4802:2-19
PORT B LSET, 4802:2-19
Port B not supported for device, 4801:2-694
port labels and functions, 4601:6-32
PORT must be A if card type is LIMATM or LIME1ATM, 4801:2-555
Port must be inhibited to change comm. attributes, 4801:2-47
PORT must be specified, 4801:2-414
PORT must not be specified when TYPE=SVCR, 4801:2-290
Port not valid for card or application type, 4801:2-733
PORT parameter invalid for DEV selected, 4801:2-413
PORT parameter valid only when ENTTYPE=LINK, 4801:2-120
port Parameter, Summary of Range Values for, 4800:A-2
port, remote dial-in, 4307:2-9
Portability Check for Mobile Originated SMS (MNP SMS), 4318:5-19
Portability Check for Mobile Originated SMS (Release 29.1), 4318:5-19
Ported subscriber SMSC matches Home SMSC Addr, 4593:3-769
ported-out subscriber, 4318:5-19
ports
    8-Port Connector Box, serial, 4625:4-30, 4625:4-38, 4625:4-43
    MPS Server networking, 4625:4-28
    MPS Server parallel, 4625:4-27
    MPS Server serial, 4625:4-27
    SAI/P card, 4625:4-30, 4625:4-43
post-installation inspection, 2969:6-11
Power, 4601:4-8
power
    MPS Server power down procedure, 4593:6-115
power cable, 4601:4-8
    CD-ROM drive
        troubleshoot, 4593:5-8
    hard drive
        troubleshoot, 4593:5-8
power cable installation, 4601:5-7

power cables, 4601:4-12
power connectors, 4601:B-62, 4626:B-25
Power Converter Unit, 4625:3-54, 4625:3-63, 4625:3-98
Power Distribution, 4625:3-31
Power Down of In-Service Eagle System, 4593:3-84
Power Feed Relay Monitor Alarm, 4593:6-9
Power Relay Unit, 2712:3-13, 4593:6-7
power requirements, 2969:2-9, 4625:6-7
power sequencers, 1021:4-10
power source verification, 4601:5-162
Power Supply card
    Embedded OAP (24.0), 4318:2-131
power supply card
    troubleshoot, 4593:5-7, 4593:5-18
Power Supply Unit, 4593:6-7
Power Supply Unit Alarm, 4593:6-9
power up
    EOAP, 4593:5-84
Power Up of the Eagle System, 4593:3-88
power up procedure, 4601:5-163
power, checking main feeds, 2712:3-13
PPSMS feature, 4318:5-20
PPSMSGTA doesn't exist in GSMOPTS Table, 4801:2-470
PPSMSGTA must be specified when NPPSMSGTA is specified, 4801:2-469
PPSMSGTA must not be NONE, 4801:2-469
PREFIX parameter mandatory with NDIGITS parameter, 4801:2-37
pre-installation requirements, 2969:2-5
Prepaid SMS Intercept Ph1 feature must be ON, 4801:2-600
preparing
    floor for heavy duty frame, 2969:4-3
Preventing Dust Buildups, 4593:2-39
Preventive Cyclic Retransmission (PCR) (EAGLE 20.0)
    Derivations for N1 and N2, 4318:5-32
    Example of Basic Error Correction vs. PCR, 4318:5-29
    Forced Retransmission, 4318:5-30
    Normal Retransmission, 4318:5-28
Preventive Maintenance, 4593:1-3
preventive maintenance, 2712:3-2
    MPS Server filters, 4593:6-17
    tape drive, 4593:6-17
primary
    DSM, 4307:2-21, 4307:4-3
    LSMS to ELAP connection, 4307:2-10
Primary IP Address - FTRA 2.0, 0008:2-20
Primary IP Address - FTRA 2.0 or greater, 0008:2-16
Primary IP Address Field - FTRA 2.0 or greater, 0008:2-15, 0008:2-20
Primary PC/SSN pair already exists, 4801:2-181
Primary remote PC does not exist in routing table, 4801:2-186
print, 4307:B-22
Print window
    Cancel button
        Update Tables Log, 0008:2-95

Connectivity Test Log, 0008:2-34
Retrieve Tables Log, 0008:2-70, 0008:2-71
System Log, 0008:2-99
Update Tables Log, 0008:2-94
Printer Inspection, 4593:2-22
Printer Not Working, 4593:3-67
Printer terminal type, 0002:4-55
printers
configuration of, 4800:4-3
connection to TDM, 4800:4-5
directing, 4800:4-15
Printing
Connectivity Test Log, 0008:2-32, 0008:2-34
Retrieve Tables Log, 0008:2-68, 0008:2-70
System Log, 0008:2-97, 0008:2-99
Update Tables Log, 0008:2-92, 0008:2-94
priorities, alarm, 4307:4-4
Priority Processing of Network Management Messages (EAGLE 21.0), 4318:5-34
private virtual network, 0004:6-8, 0004:6-13
Proactive Testing Applications Manual, 4625:1-12
probe-scsi, 4593:5-13
Problem-Major, 4625:1-16
Problem-Minor, 4625:1-16
problems
critical, 4318:1-7, 4601:1-18, 4626:1-19
major, 4318:1-8, 4601:1-18, 4626:1-20
minor, 4318:1-8, 4601:1-19, 4626:1-20
power source
no cPCI power, 4593:5-7
no drive power, 4593:5-8
no fan power, 4593:5-7
processor card
LEDs normal but no Ethernet access, 4593:5-22
RUN LED is GREEN but ports not functioning, 4593:5-21
scsi / drive, 4593:5-9
drives detected but system will not boot, 4593:5-13
system has power but will not boot, 4593:5-9
serial card, 4593:5-22
ports 1 or 2 not working, 4593:5-24
ports 3,4,5, or 6 not working, 4593:5-22
ports 7,8,9, or 10 not working, 4593:5-24
Problems - contacting the Customer Care Center, 0007:2-4
problems, detecting and reporting, 2712:3-8
Probless Solution, 4625:5-8
probless Solution, 4625:5-8
Procedure
Activating Controlled Features, 0008:2-3
Activating the Eagle OA&M IP Security Enhancements Controlled Feature, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103
Activating the LNP Feature on the Eagle, 0007:2-128
Activating the LNP Short Message Service (SMS) Feature, 0007:2-157
Adding a DSM, 0007:2-20

Bulk Load, 0007:2-97
Configuring ELAP, 0007:2-64
Configuring ELAP 5.0, 0007:2-61
Configuring the DSM Ethernet Link to the MPS, 0007:2-31
Connectivity Test - I, 0008:2-119
Connectivity Test - II, 0008:2-120
Copy an RTDB from the Mate ELAP, 0007:2-113
Copy RTDB from Remote Mated NE, 0007:2-120
Creating an EMS Configuration Component, 0007:2-81
Deleting an EMS Configuration Component, 0007:2-91
Disabling Bulk Load, 0007:2-149
Distributing an RTDB LNP Database to DSMs, 0007:2-145
Distributing the LNP Database after LSMS-Based Operation or RTDB Copy, 0007:2-144
ELAP 5.0 Configuration, 0007:2-51
ELAP Configuration, 0007:2-61
FTP Server Verification, 0008:2-119
Increasing the LRN and NPANXX Quantities on the Eagle, 0007:2-153
Modify EMS Routing, 0007:2-93
Modifying an EMS Configuration Component, 0007:2-87
MPS Health Check, 0007:2-79
Removing the hsopEnabled File from the OAP, 0007:2-150
SFTP Server Verification, 0008:2-119
SSHD Server Verification, 0008:2-119
View EMS Routing, 0007:2-96
Viewing an EMS Configuration Component, 0007:2-89
procedure
8-Port Connector Box replacement, 4593:6-127
breaker panel alarm card replacement, 4593:6-121
breaker panel replacement, 2712:5-5, 4593:6-119
CD-ROM replacement, 4593:6-123
Configuring the EOAP from the System Terminal, 0002:A-25, 4601:6-104, 4601:6-112
CPU
module replacement, 4593:6-123
disk drive replacement, 2712:5-9
DVD replacement, 4593:6-123
fan replacement, 4593:6-124
file system backup, 4593:6-42, 4593:6-52, 4593:6-56
hub replacement, 2712:5-6, 4593:6-121
internal disk drive replacement, 4593:6-123
memory module replacement, 4593:6-124
MPS Server alarm card replacement, 4593:6-127
MPS Server Power Down, 2712:5-7, 4593:6-115
MPS Server replacement, 4593:6-117
PCI cards replacement, 4593:6-122
Quad FastEthernet Network Interface card replacement, 4593:6-122
SAI/P card replacement, 4593:6-122, 4593:6-127
tape drive replacement, 4593:6-124
Tekelec 1100 AS main unit replacement, 2712:5-10
procedures
Extracting LNP Measuremens from the FTA, 4800:5-8
log into system, 4800:4-19
logout, 4800:4-23

procedures, login
change password at first login, 4800:4-20
password expired, 4800:4-21
User ID-password already being used, 4800:4-22
User ID-password not accepted, 4800:4-20
Process, 4593:6-7
Process Alarm, 4593:6-8
Process Control menu, 4307:3-14
Processing Retrieve Request
Update Tables Log window, 0008:2-82
Processing Validate Request, Please Wait message, 0008:2-82, 0008:2-88
processor card, 4593:5-22
troubleshoot, 4593:5-7, 4593:5-20
Processor speed, 0008:2-2
Processor timeout error, 4801:2-731
processor, MPS Server CPU, 4625:4-27
product description
ITU MTP Restart (26.0), 4318:3-151
Production Control, 4601:1-17, 4601:3-4, 4626:1-18
Program Update, 4802:1-16
Program Update Unsolicited Output Message Group, 4593:D-25
Prohibit Removing the Last Route to a Destination if that Destination is being Referenced by Mated Applications or Concerned Signaling Point Code Groups (EAGLE 22.0), 4318:5-35
Prohibit the Assigning of a Linkset with Linkset Types A or E to a Cluster Route (EAGLE 22.0), 4318:5-36
prompts
default value format, 4307:5-12
ELAP user interface menus, 4307:5-12
Escape key to exit operations, 4307:5-12
Prompts and Default Values, 4307:5-12
protocol details
Enhanced GTT (26.0), 4318:2-153
Protocol Troubleshooting, 0008:2-122
Protocol wrong type for socket - Error code 41, 0008:2-116
Protocol, Point-to-Point (PPP), 4307:2-9
provisioning
ELAP Able/Unable status, 4307:2-10
ELAP-to-DSM description, 4307:2-17
LNP, 4307:2-10
LSMS-ELAP connection, 4307:2-5, 4307:2-10
NPAC and local data collection at LSMS, 4307:2-11
Provisioning a Mated Application, 0006:2-79
Provisioning an MRN Group, 0006:2-136
Provisioning Multiple Point Codes
Multiple Point Code Support (EAGLE 26.05), 4318:4-143
Provisioning Range for Gateway Screening (EAGLE 22.0), 4318:5-36
Provisioning the Secure Eagle Host Key, 0008:2-43
provisioning values, 4307:5-27
PRTY, 4802:1-16
ps, 0008:2-119
ps -ef|grep sshd, 0008:2-103
ps -f|grep sshd, 0008:2-119

PSEL parameter requires LNP feature, 4801:2-665
PST/AST/SST possible values, 4800:A-3
PSTN is not defined, 4801:2-346
PSTN presentation data, 0003:3-4
PSTNCAT=0 requires PSTNID=0, 4801:2-788
PSTNCAT=1 requires ITU-I or ITU-N point code, 4801:2-789
PU, 4802:1-16
Public Host Key Fingerprint
Eagle, 0008:2-43, 0008:2-44, 0008:2-46, 0008:2-48
Public Key Fingerprint
Eagle, 0008:2-17, 0008:2-46, 0008:2-47
publications, Sentinel, 4625:1-12, 4626:1-15
PVC, 0004:2-4, 4318:5-173
PVC plus SVC cannot be greater than 255, 4801:2-299
PVC plus SVC must be at least 1, 4801:2-299
PVN, 0004:6-8, 0004:6-13, 0004:6-14, 0004:6-15
PVN and PVNMASK must be specified together, 4801:2-777
PVN and PVNMASK must not be the same, 4801:2-777
PVN subnet mask, 0004:6-14, 0004:6-15
PWR A LED, 4593:2-7
PWR B LED, 4593:2-7

Q

QH and HH cannot be specified together, 4801:2-659
QH cannot be specified unless 15 min meas is turned on, 4801:2-658
QH or HH is not valid for this TYPE, 4801:2-124
QH or HH must be specified when PERIOD=SPECIFIC‘, 4801:2-115
QH, HH, or DAY cannot be specified when PERIOD=ACTIVE, 4801:2-114
QH, HH, or DAY cannot be specified when PERIOD=ALL, 4801:2-115
QH, HH, or DAY cannot be specified when PERIOD=LAST, 4801:2-114
QR, 4802:1-16, 4802:4-13, 4802:4-14, 4802:4-15, 4802:4-17, 4802:4-19, 4802:4-20
Quad FastEthernet card, 4625:4-35
Quad FastEthernet Network Interface card
description, 4625:4-30
replacement procedure, 4593:6-122
Quantity control feature capacity exceeded, 4801:2-346
Quarterly Procedures, 4593:2-37
Query Rate, 4802:1-16
Quick Test
CDU for DSM (26.05), 4318:2-60
Quoted string too long (C<col>), 4801:2-552

R

Rack Alarm (RALMx), 4625:3-26
rack alarm and row alarm cable routing, 4601:5-11
rack alarm cable installation, 4601:5-87
rack alarm connectors, 4601:B-64
rack and row alarm connector, 4625:3-26
rack horns, 4601:4-16
rack, overhead, 2969:4-19

Radio Frequency Interference (RFI), 4625:3-31
Raised Floor, 4601:3-14
Raised floor, 4601:3-24
raised floor, 4601:3-16
    additional preparations, 2969:4-5
    anchor assembly
        for anchoring to slab, 2969:4-10
        for use with support channel, 2969:4-14
    anchor assembly for use with support channel and spring nut, 2969:4-17
    anchor with support channel, 2969:4-13
    anchor with support channel and spring nut, 2969:4-16
    create cable and anchor holes, 2969:4-5
RAM, 0008:2-2, 4593:6-6
ramp, 4601:3-5
Random SLS Generation (Release 28.0), 4318:5-43
RC is required if no other optional parameters are provided, 4801:2-425
RCVRY-LINK-CGST
    congestion has cleared, 4593:3-356
    congestion level 2 to 1, 4593:3-355
    congestion level 3 to 2, 4593:3-354
    discard has cleared, 4593:3-362
    discard level 2 to 1, 4593:3-361
    discard level 3 to 2, 4593:3-360
RCVRY-LKF
    link available, 4593:3-299
RCVRY-LKSTO
    Alarm clr'd by deleting SLK, 4593:3-506
    Link set allowed, 4593:3-407
RCVRY-MTPLP-RST
    Circ rte status cleared, 4593:3-435
RCVRY-MTP-RSTRT MTP Restart completed, 4593:3-721
RDCT must be in lowest priority action slot, 4801:2-651
Read NETOPTS table failed, 4801:2-781
Read-only file system - Error code 30, 0008:2-118
rear covers, 4601:3-26, 4601:3-37
rear view
    hub, 4625:4-48
    MPS frame layout, 4625:4-13
    MPS Server, 4625:4-26
    MPS Server detail, 4593:6-123, 4625:4-22, 4625:4-30
Reboot MPS menu, 4307:3-78, 4307:5-24
Received wrong display mode, 4801:2-162
Receiving, 4601:3-4
reception of an RCx message
    network routing, 4804:2-151
reception of an RSx message
    network routing, 4804:2-150
reception of transfer messages
    network routing, 4804:2-150
Recommended Tools, 4601:3-11, 4601:3-14, 4601:5-7, 4601:5-21, 4601:5-85, 4601:5-108, 4601:5-121
recommended tools
    installing heavy duty frame, 2969:4-3

Recommended Tools and Materials, 4601:4-13
reconcile
    stages, 4751:5-8
reconnect cables to EOAP shelf, 4593:5-77
Record Base Measurements, 4593:4-122
Record, STP configuration, 0008:2-14
recovery, overview, 2712:3-18
Rectifier Voltage Inspection/Recording, 4593:2-40
RECVY-NMTSK-DSCD
    SNM Discard Abated, 4593:3-393
red and white flag, 4601:4-23
REDIRECT can only be specified with ANSI point codes, 4801:2-313
Redirect function data has already been entered, 4801:2-277
Redirect function data has not been entered, 4801:2-277
References, 4800:1-3
Refnum entered does not match refnum in table, 4801:2-570
Refresh button, 0008:2-16, 0008:2-23, 0008:2-25, 0008:2-27, 0008:2-29, 0008:2-39
regulatory compliance, 2969:2-4
Rejection threshold argument - not valid (C<col>), 4801:2-547
Related Publications, 0007:2-3, 4625:1-12
Relative Cost (RC) is required for PC/SSN and MPC/MSSN, 4801:2-428
Relative Cost (RC) of true MPC must be less than RC of mate, 4801:2-430
Relative Cost (RC) of true PC must be less than RC of mate, 4801:2-430
relative humidity, 2969:2-6
release 30.2 or greater - Eagle, 0008:2-3, 0008:2-17, 0008:2-22
Release Documentation, 4601:1-14, 4626:1-14
Release Not Compatible Error - Retrieve Tables Log window, 0008:2-57
Release Notice, 4601:1-14, 4625:1-12, 4626:1-14, 4626:1-15
reload
    DSM, 4307:2-17
    DSM continuous, 4307:2-18
Reload RTDB from Remote, 4307:3-37
remote access, 1021:6-6, 2712:2-11
remote application not found, 4801:2-442
remote congestion
    network routing, 4804:2-148
remote dial-in port, 4307:2-9
remote ELAP, 0007:2-62, 4307:5-28
remote link congestion
    ANSI/ITU MTP Gateway (20.0), 4318:2-38
remote loopback points
    adding, 4804:3-206, 4804:3-212
    changing, 4804:3-215
Remote Loopback Testing for DSOA
    Link Fault Sectionalization (21.0), 4318:4-14
Remote Loopback Testing for DSOA (EAGLE 21.0), 4318:5-43
Remote Loopback Testing for OCU
    Link Fault Sectionalization (21.0), 4318:4-14
Remote Loopback Testing for OCU (EAGLE 21.0), 4318:5-44
Remote Maintenance Center (RMC) - Appendix B, page B-3, 4601:5-87
remote maintenance center (RMC) alarm connector, 4625:3-26
remote maintenance center cable installation, 4601:5-87

Remote point code does not exist in MAP table, 4801:2-186
Remote point code table is full, 4801:2-187
removable cartridge, 0002:2-5
formatting, 0002:2-80
inserting, 0002:2-8
overview, 0002:1-11, 0003:1-11, 4804:1-11
removing, 0002:2-9
restoring system data, 0002:2-74
write enabling, 0002:2-7
write protecting, 0002:2-6
Removable cartridge contains Eagle data (use FORCE=YES), 4801:2-59
Removable cartridge database level is not compatible, 4801:2-674
removable cartridge disk drives, 4800:4-2
Removable cartridge is inaccessible (internal problem), 4801:2-418
Removable cartridge is not a MEAS disk, 4801:2-418
Removable cartridge is not a system disk, 4801:2-417
Removable cartridge is not inserted, 4801:2-417
Removable cartridge not inserted, 4801:2-60
Removable in unknown upgrade mode, 4801:2-575
Removable is from previously aborted upgrade, 4801:2-575
Removable media drives assembly, 2969:7-2
remove
cables from EOAP shelf, 4593:5-67
cards from EOAP shelf, 4593:5-70
EOAP card cage, 4593:5-71
fan assembly, 4593:5-93, 4593:A-77
grill and filter, 4601:6-17
Remove button, 0008:2-56, 0008:2-62
Remove External NTP Server, 4307:5-26
Remove Fan Assembly, 4593:A-77
Removing
BLM Applied to LSMS BLM-Based Operations, 0007:2-29
DCM Applied to LSMS BLM-Based Operations, 0007:2-26
hsopEnabled File from the OAP, 0007:2-150
SCCP Card, 0007:2-24
removing
destination point code, 4804:2-185
IPSM, 0002:4-179
linkset containing SS7 signaling links, 4804:3-58
MCPM, 0002:4-146
removable cartridge, 0002:2-9
route, 4804:3-160
shelf, 0002:4-95
signaling link, 0003:3-117, 4804:3-137
SS7 LIM, 0002:4-117, 0004:6-27
user, 0002:4-33
Removing a Blocked DPC Screen, 0005:8-19, 4803:5-47
Removing a Blocked OPC Screen, 0005:11-20, 4803:5-95
Removing a Destination Point Code, 4803:2-21
Removing a Gateway Linkset, 4803:5-129
Removing a Global Title Translation, 0006:3-44, 4803:4-17
Removing a GLS Card, 0005:2-50

Removing a GSM MAP Screening Entry, 0004:5-104
Removing a GSM MAP Screening Operation Code, 0004:5-67
Removing a GTT Selector, 0006:4-17
Removing a GTT Set, 0006:4-8
Removing a Linkset Containing SS7 Signaling Links, 4803:3-11
Removing a Linkset Containing X.25 Signaling Links, 0004:2-58
Removing a Mapped SS7 Message Translation Type, 0006:2-65
Removing a Mated Application, 0006:2-108, 4803:4-5, 4803:6-5
Removing a Screen Set, 0005:13-12
Removing a TCP/IP Data Link, 0004:3-36
Removing a TCP/IP Node, 0004:3-44
Removing a Translation Type, 0006:3-12
Removing ACG Manual Initiated Controls, 4802:4-28
Removing an ACG Node Overload Control Level, 4802:4-17
Removing an ACM, 0004:3-27
Removing an Allowed Affected Point Code Screen, 0005:3-12, 4803:5-5
Removing an Allowed Called Party Address, 0005:4-15
Removing an Allowed Called Party Address Screen, 4803:5-11
Removing an Allowed Calling Party Address Screen, 0005:6-16, 4803:5-26
Removing an Allowed DPC Screen, 0005:9-20, 4803:5-62
Removing an Allowed ISUP Message Type Screen, 0005:15-16
Removing an Allowed OPC Screen, 0005:12-20, 4803:5-109
Removing an Allowed SIO Screen, 0005:10-20, 4803:5-79
Removing an Allowed Translation Type Screen, 0005:5-11, 4803:5-19
Removing an Application Socket, 0003:3-205
Removing an DCM, 0003:3-32, 0003:3-191
Removing an IP Card, 0003:3-32, 0003:3-191
Removing an MRN Group or MRN Group Entry, 0006:2-147
Removing an SCCP Card, 0006:2-59, 4802:2-13
Removing an SS7 Signaling Link, 4803:3-33
Removing an X.25 Gateway Destination, 0004:2-38
Removing an X.25 LIM, 0004:2-25
Removing an X.25 Route, 0004:2-117
Removing an X.25 Signaling Link, 0004:2-94
Removing Concerned Signaling Point Codes, 0006:2-76
removing diode boards, 4593:2-9
Removing Global Title Address Information, 0006:4-48, 4803:6-15
Removing the 2.3 Gbyte Removable Cartridge, 4593:2-14
REP cannot be specified when DUR=PERM, 4801:2-303
REP is only valid if LFST is defined as LLT, 4801:2-391
REP must be greater than prev. and less than subsequent REP, 4801:2-389
REP must be zero if link element to be tested is NEI, 4801:2-390
REP parameter must be specified, 4801:2-398
Repair and Return Shipping Instructions, 4601:1-23, 4625:1-21
repairing database, 0002:2-48
replace
- air filter, 2969:7-16
- Ethernet switch, 2969:7-4
- fan assembly, 2969:7-18, 4593:5-92, 4593:A-76
- fan filter and grill, 4593:5-97, 4593:A-82
- hard disk drive, 2969:7-21
- hard drive card, 4593:5-102, 4593:5-103

PCI card, 2969:7-36
power supply card, 4593:5-117
processor card, 4593:5-124
Replace tiles, 4601:3-15
replacement
8-Port Connector Box, 4593:6-127
breaker panel, 2712:5-5, 4593:6-119
breaker panel alarm card, 4593:6-121
CD-ROM, 4593:6-123
CPU module, 4593:6-123
disk drive, 2712:5-9
DVD, 4593:6-123
fan, 4593:6-124
hub, 2712:5-6, 4593:6-121
internal disk drive, 4593:6-123
memory module, 4593:6-124
MPS Server, 4593:6-117
MPS Server alarm card, 4593:6-127
PCI cards, 4593:6-122
Quad FastEthernet Network Interface card, 4593:6-122
SAI/P card, 4593:6-122, 4593:6-127
steps before you begin component, 4593:6-114
tape drive, 4593:6-124
Tekelec 1100 AS main unit, 2712:5-10
Replacement cables list, 4593:A-91
Replacement parts list, 4593:A-87
replacing
serial I/O card (EOAP), 4593:5-134
two STP pairs with one pair, 4804:2-41
replacing FAP components, 4593:2-6
Replacing Two STP Pairs with One Eagle Pair
Multiple Point Code Support (EAGLE 26.05), 4318:4-136
Report generation failure, 4593:3-901
Report Parameters, 4593:4-12
Report parameters, 4593:4-12
Report transfer failure FTP Server, 4593:3-902
reporting
DSM memory capacity status, 4307:4-7
DSM/ELAP IP link alarm totals, 4307:4-13
DSM/ELAP link alarms, 4307:4-12
RTDB level and status, 4307:4-10
Reporting Functions, 1021:4-7
Reports, 4593:4-13
REPT COND
IMT GPL reloading, 4593:3-741
system alive, 4593:3-713
REPT EVT
IMT GPL reloading, 4593:3-740
Incremental Loading, 4593:3-952
REPT-ALMINH
alarm output enabled, 4593:3-381
alarm output PERM inhibited, 4593:3-380

alarm output TEMP inhibited, 4593:3-382
REPT-E1F
FAC-E1 Port 1 10E-3 BER failed, 4593:3-329
FAC-E1 Port 1 AIS detected, 4593:3-326
FAC-E1 Port 1 available, 4593:3-330
FAC-E1 Port 1 Far End Failure, 4593:3-325
FAC-E1 Port 1 LOF failure, 4593:3-327
FAC-E1 Port 1 LOS failure, 4593:3-328, 4593:3-567
FAC-E1 Port 2 10E-3 BER failed, 4593:3-568
FAC-E1 Port 2 AIS detected, 4593:3-565
FAC-E1 Port 2 available, 4593:3-569
FAC-E1 Port 2 Far End Failure, 4593:3-564
FAC-E1 Port 2 LOF failure, 4593:3-566
rept-ftp-meas, 4800:7-2
rept-imt-lvl1, 4800:7-20
rept-imt-lvl2, 4800:7-32
REPT-LFK
LM Timer NO-CREDIT expired, 4593:3-337
REPT-LINK-CGST
congestion level 0 to 1, 4593:3-351
congestion level 1 to 2, 4593:3-352
congestion level 2 to 3, 4593:3-353
discard level 0 to 1, 4593:3-357
discard level 1 to 2, 4593:3-358
discard level 2 to 3, 4593:3-359
REPT-LINK-MANUAV
local blocked, 4593:3-332
REPT-LKF
ABN - rcvd 2 of 3 invalid BSN, 4593:3-313
ABN - rcvd 2 of 3 invalid FIB, 4593:3-314
APF - failed proving period, 4593:3-308
APF - lvl-2 T1 expd (not ready), 4593:3-305
APF - lvl-2 T1 expd (ready), 4593:3-304
APF - lvl-2 T2 expired, 4593:3-307
APF - lvl-2 T3 expired, 4593:3-306
COO - rcvd changeover order, 4593:3-317
FAC - DS1 LCD failure, 4593:3-346
FAC - DS1 LOF failure, 4593:3-345
false congestion restart, 4593:3-318
HWP -too many link interrupts, 4593:3-301
link test failed, 4593:3-324
lost data, 4593:3-302
MTP link restart delayed, 4593:3-319
not aligned, 4593:3-335
OSA - received SIE, 4593:3-311
OSA - received SIN, 4593:3-310
OSA - received SIO, 4593:3-309
OSA - received SIOS, 4593:3-312
rcvd SSCOP END-mgmnt initiated, 4593:3-343
rcvd SSCOP END-out of service, 4593:3-341
rcvd SSCOP END-protocol error, 4593:3-342
remote blocked, 4593:3-331

remote congestion timeout, 4593:3-315
remote FE loopback, 4593:3-322
remote NE loopback, 4593:3-300, 4593:3-323
RMI remote inhibited, 4593:3-333
Unable to connect, 4593:3-348
X25 link unavailable, 4593:3-320
XDA - excess acknowledge delay, 4593:3-316
XDA-Timer NO-RESPONSE expired, 4593:3-338, 4593:3-345, 4593:3-346
XER - ISERM threshold exceeded, 4593:3-347
XER - SUERM threshold exceeded, 4593:3-303
REPT-LKSTO
Link set prohibited, 4593:3-408
rept-meas, 4800:7-36
REPT-MTPERR
MTP rcvd invalid SIO, 4593:3-637
REPT-MTPLP-DET
Circ rte det(cong), 4593:3-410
REPT-MTPLP-SUST
Sustained circ rte(cong), 4593:3-412
REPT-MTP-RSTRT MTP Restart started, 4593:3-720
REPT-NMTSK-DSCD
SNM Discard Onset, 4593:3-392
REPT-OVSZMSG
MTP MSU too large to route, 4593:3-817
SCCP MSU too large to rte, 4593:3-818
rept-stat-alm, 4800:7-50
rept-stat-alm command, 4307:4-4, 4307:4-13
rept-stat-applsock, 4800:7-55
rept-stat-as, 4800:7-56
rept-stat-asp, 4800:7-57
rept-stat-assoc, 4800:7-58
rept-stat-card, 4800:7-59
rept-stat-card command, 4318:3-30
rept-stat-cdl, 4800:7-76
rept-stat-cdt, 4800:7-78
rept-stat-clk, 4800:7-79
REPT-STAT-CLK Enhancements for Clocking (Release 28.2), 4318:5-45
rept-stat-cluster, 4800:7-84
rept-stat-db, 4800:7-90
rept-stat-db command, 4307:4-10
rept-stat-dlk, 4800:7-107
rept-stat-dstn, 4800:7-108
rept-stat-eroute, 4800:7-117
rept-stat-gpl, 4800:7-121
rept-stat-imt, 4800:7-129
rept-stat-iptps, 4800:7-131
rept-stat-lfs, 4800:7-135
rept-stat-lnp, 4800:7-137
rept-stat-ls, 4800:7-142
rept-stat-lsms, 4593:5-65, 4593:5-85, 4593:5-124, 4593:5-126, 4800:7-145
rept-stat-meas, 0002:2-57, 0002:2-63, 0002:2-83, 0002:2-86, 0002:2-94, 0002:2-98, 0002:3-50, 0002:3-70, 0002:4-152, 0002:4-153, 4800:7-146

rept-stat-mps, 4800:7-148
rept-stat-mps command
    description, 4307:4-10
    DSM memory capacity status reporting, 4307:4-8
    list alarm categories and data strings, 4307:4-11
    list multiple alarm conditions, 4307:4-4
rept-stat-ndc, 4800:7-157
rept-stat-ndc command, 4318:3-29
rept-stat-rte, 4800:7-158, 4803:3-36
rept-stat-rtkey, 4800:7-166
rept-stat-sccp, 4800:7-167
rept-stat-sccp command, 4751:8-5
rept-stat-seas, 4593:5-65, 4593:5-85, 4593:5-124, 4593:5-126, 4800:7-181
rept-stat-seculog, 4800:7-182
rept-stat-slan, 4800:7-185
rept-stat-slk, 4800:7-188, 4803:3-33
rept-stat-sys, 4800:7-197
rept-stat-trbl, 4800:7-201
rept-stat-trbl command, 4307:4-4, 4307:4-12
REPT-STAT-TRBL Enhancement (Release 29.0), 4318:5-46
rept-stat-trm, 4800:7-205
rept-stat-trstslk, 4800:7-207
rept-stat-user, 4800:7-209
rept-stat-xlist, 4800:7-210
REPT-T1F
    FAC-T1 Port 1 Alarm, 4593:3-157
    FAC-T1 Port 1 available, 4593:3-158
    FAC-T1 Port 1 LOF failure, 4593:3-155
    FAC-T1 Port 1 LOS failure, 4593:3-154
    FAC-T1 Port 1 Remote Alarm, 4593:3-156
    FAC-T1 Port 2 Alarm, 4593:3-162
    FAC-T1 Port 2 available, 4593:3-163
    FAC-T1 Port 2 LOF failure, 4593:3-160
    FAC-T1 Port 2 LOS failure, 4593:3-159
    FAC-T1 Port 2 Remote Alarm, 4593:3-161
rept-x25-meas, 4800:7-211
REPT-XLST-TIMO
    X-LIST entry expired, 4593:3-791
Request To Send (RTS), 4625:3-67
Requested link must not be in command driven loopback, 4801:2-869
required data
    EOAP update, 0002:A-30
Required Network Address Information, 0007:2-47, 4307:5-10
Requirements
    ATM or E1 LIM card(s), 4601:5-83
    backplane (P/N 850-0330-04), 4601:5-83
    backplane (P/N 850-0330-05), 4601:5-83
    Feature Matrix, 4601:5-83
    Hardware, 0008:2-2
        Unix Workstation, 0008:2-2
        Windows Workstation, 0008:2-2
    Software, 0008:2-2

Unix Workstation, 0008:2-2
Windows Workstation, 0008:2-2
software release 26.0 or later, 4601:5-83
T1 or E1 clock source (RS 422), 4601:5-83
TDM card 870-0774-06 or 870-0774-08 or later, 4601:5-83
requirements
pre-installation, 2969:2-5
Requires C-linksets parameter tfatcabmlq to be set to 0, 4801:2-888
rerouting global title translation traffic to mate, 4751:8-4
Reset button, 0008:2-56, 0008:2-63
Reset User Password, 4307:3-96
RESETCHAR not valid with ACTION=CREATE, 4801:2-311
RESETCHAR not valid with ACTION=RENAME, 4801:2-312
Response, 4625:1-17
Response Messages, 4800:4-15
response method transfer messages
network routing, 4804:2-148
Response to Commands Issued Prior to Login (EAGLE 21.0), 4318:5-48
restart signaling link alignment delay, 4804:3-23
restart, DSM warm, 4307:2-18
restarting PDBA, 4593:6-68
Restarting the Eagle Agents on the LSMS, 0007:2-151
restore
Database Management Command Functions (20.0), 4318:2-82
restore device state option
configuring, 0002:4-192
Restore RTDB, 4307:3-39
restoring
database
from backup partition of fixed disk, 0002:2-39
from removable cartridge, 0002:2-43
system data, 0002:2-74
system data from removable cartridge, 0002:2-74
restoring the database, 0002:2-39
Restricted Linkset Option
Configuring, 4804:3-233, 4804:3-238, 4804:3-239
restrictions
ITU SLS Enhancements (26.0), 4318:3-155
resynchronization
automatic, 4751:2-4, 4751:2-7, 4751:4-2
basic phases, 4751:2-10
LSMS and network element, 4751:2-6
managing, 4751:4-2, 4751:6-2
procedures, basic phases, 4751:3-7
user-initiated, 4751:2-4, 4751:2-7, 4751:4-2
after bulk load, 4751:6-10
user-initiated resynchronization
aborting, 4751:4-11
Retrieve button, 0008:2-54, 0008:2-56, 0008:2-64, 0008:2-65
Retrieve Database Tables from an STP, 0008:2-54
Retrieve from Local Database button, 0008:2-54, 0008:2-56, 0008:2-64
Retrieve from STP button, 0008:2-54, 0008:2-56, 0008:2-65

Retrieve Group screen, 4307:3-103
Retrieve LNP 10-digit Subscription, 4307:B-16
Retrieve LNP Subscription, 4307:3-52
Retrieve RTDB Records, 4307:3-41
Retrieve Tables
  Command List Box, 0008:2-54, 0008:2-56, 0008:2-58, 0008:2-62, 0008:2-63
  Selected Commands Box, 0008:2-54, 0008:2-56, 0008:2-60, 0008:2-62, 0008:2-63, 0008:2-64
Retrieve Tables Log, 0008:2-11, 0008:2-54, 0008:2-65, 0008:2-66, 0008:2-67, 0008:2-68, 0008:2-70, 0008:2-71
  Clearing the Display, 0008:2-68, 0008:2-69
  closing, 0008:2-68, 0008:2-72
  File Menu, 0008:2-68
  Print window, 0008:2-70, 0008:2-71
  Printing, 0008:2-68, 0008:2-70
  Save window, 0008:2-71, 0008:2-72
  saved file confirmation window, 0008:2-72
  saving to a file, 0008:2-68, 0008:2-71
Retrieve Tables Log window, 0008:2-65, 0008:2-66, 0008:2-67, 0008:2-68, 0008:2-69, 0008:2-70, 0008:2-71, 0008:2-72
  File Menu, 0008:2-68, 0008:2-69
  Processing Retrieve Request, 0008:2-65
  Release Not Compatible Error, 0008:2-57
  with Errors, 0008:2-68
  without Errors, 0008:2-67
Retrieve Tables window, 0008:2-4, 0008:2-54, 0008:2-55, 0008:2-58, 0008:2-73
  Add button, 0008:2-56, 0008:2-60
  Close button, 0008:2-56
  description, 0008:2-56
  GTT Warning window, 0008:2-54
  Load button, 0008:2-56, 0008:2-64, 0008:2-73
  Remove button, 0008:2-56, 0008:2-62
  Reset button, 0008:2-56, 0008:2-63
  Retrieve button, 0008:2-54, 0008:2-56, 0008:2-64, 0008:2-65
  Retrieve from Local Database button, 0008:2-54, 0008:2-56, 0008:2-64
  Retrieve from STP button, 0008:2-54, 0008:2-56, 0008:2-65
  Store button, 0008:2-56, 0008:2-63, 0008:2-73
Retrieve Trouble Report, 4593:3-57
Retrieve User screen, 4307:3-93
Retrieving Eagle database tables, 0008:2-1, 0008:2-4
return cables, 4601:4-11
Return key, 4307:5-27
Return Material Authorization, 2969:B-1
return shipment, 2969:7-21, 2969:7-34, 2969:B-20, 4601:1-24, 4601:3-10, 4625:1-22, 4626:1-23
return shipping instructions, 2969:B-19
Returning a Crate, 4601:1-23, 4625:1-22
Reuse Limit, 4307:3-110
Revocation of security admin userID not allowed, 4801:2-332
Revoke Failed User, 4307:3-83
Revoke/Restore User, 4307:3-82
Revoking a User ID (EAGLE 21.0), 4318:5-48
RFC 1587 network standard, 0007:2-32, 4307:2-7

RGTA, 4802:3-44, 4802:3-82, 4802:3-97, 4802:3-116, 4802:3-118, 4802:3-126, 4802:3-127, 4802:3-130, 4802:3-137, 4802:3-139, 4802:3-141, 4802:3-145, 4802:3-149, 4802:3-151, 4802:3-154, 4802:3-155, 4802:3-156, 4802:3-157, 4802:3-161, 4802:3-176, 4802:3-178, 4802:3-179, 4802:3-180, 4802:3-182
RI, 4802:1-16, 4802:3-42, 4802:3-43, 4802:3-44, 4802:3-81, 4802:3-82, 4802:3-85, 4802:3-87, 4802:3-88, 4802:3-91, 4802:3-92, 4802:3-96, 4802:3-97, 4802:3-98, 4802:3-102, 4802:3-104, 4802:3-107, 4802:3-111, 4802:3-116, 4802:3-118, 4802:3-119, 4802:3-122, 4802:3-126, 4802:3-127, 4802:3-130, 4802:3-132, 4802:3-134, 4802:3-137, 4802:3-139, 4802:3-141, 4802:3-143, 4802:3-145, 4802:3-151, 4802:3-154, 4802:3-156, 4802:3-157, 4802:3-159, 4802:3-161, 4802:3-177, 4802:3-179, 4802:3-180
RI must be GT when specifying NGT, 4801:2-865
RI must be GT when specifying NTT, 4801:2-866
RI must be SSN when CCGT is YES, 4801:2-622
RI=GT must be specified when XLAT=DPCNGT, 4801:2-198, 4801:2-498
risk of electric shock, 2969:6-2, 4601:4-13
RLE and LFST must be specified when database is not used, 4801:2-397
rls-alm, 4800:7-213
RMA, obtaining, 2969:B-1
RMC connector, 4601:B-65, 4626:B-26
RMIN must be less than or equal to RMAX, 4801:2-534
rmv, 4802:1-16, 4802:3-95, 4802:3-98, 4802:3-149
rmv-card, 4800:7-214, 4803:3-11, 4803:3-33
rmv-card command, 4751:8-3
rmv-imt, 4800:7-215
rmv-trm, 4800:7-217
RN already exists in HOMERN Table, 4801:2-765
RN does not exist in HOMERN Table, 4801:2-765
roles, ELAP
  Active/Standby, 4307:2-5
  Active/Standby switchover, 4307:2-5
root, 0008:2-8
Rotary impact drill, 4601:3-20
rotary impact drill, 2969:4-3
route
  adding, 4804:3-145
  changing, 4804:3-178
  clock connection cable, 4601:6-45
  removing, 4804:3-160
  terminal cable, 4601:6-49
route availability
  network routing, 4804:2-147
Route is allowed, 4593:3-402
Route is prohibited, 4593:3-404
Route is restricted, 4593:3-403
route management
  network routing, 4804:2-148
Route table is full, 4801:2-144
router IP address, default, 4307:5-19
routers, 4625:4-48, 4626:A-17
Routes
  5000, 4804:2-21
Routes of equal cost cannot exist for X.25 destinations, 4801:2-375
Routeset is empty, 4801:2-144
Routeset is full, 4801:2-141

Routeset must be empty, 4801:2-142
Routesets
6000, 4804:2-21
7000, 4804:2-21
8000, 4804:2-21
Routesets Feature Quantity must be increased, 4801:2-584
Routing Indicator, 4802:1-16, 4802:3-85, 4802:3-87, 4802:3-102, 4802:3-104, 4802:3-116, 4802:3-117, 4802:3-130, 4802:3-131, 4802:3-137, 4802:3-139, 4802:3-154, 4802:3-155
Routing Key Lookup Hierarchy, 0003:2-27
Routing key not found, 4801:2-693
Routing Key table full, 4801:2-692
Routing Key Tables, 0003:2-25
Row Alarm (ROW ALM), 4625:3-26
row alarm cable installation, 4601:5-87
ROW ALM, 4625:3-26
RS232 terminal ports, 4318:3-123
RS-485, 4625:3-106
rst-card, 4800:7-218
rst-card command, 0008:2-43, 4751:8-3
rst-dstn, 4800:7-220
rst-imt, 4800:7-221
rst-trm, 4800:7-222
RTDB
Audit alarms, 4307:4-16
Copy - Distributing the LNP Database, 0007:2-144
Copy from Remote Mated NE Procedure, 0007:2-120
Copy from the Mate ELAP Procedure, 0007:2-113
Copying, 0007:2-109
Copying from ELAP on Remote Mated NE, 0007:2-110
Copying from Mated ELAP, 0007:2-109
Distributing, LNP Database to DSMs, 0007:2-145
Distributing, Returning to Normal Service, 0007:2-145
rept-stat-db command to view database level and status, 4307:4-10
Verifying Status, 0007:2-111
Verifying Status at the Eagle Terminal, 0007:2-111
Verifying Status at the ELAP User Interface, 0007:2-112
RTDB / Maintenance menu, 4307:3-36
RTDB Audit menu, 4307:3-24
RTDB Backup menu, 4307:5-25
RTDB Backup Procedure, 4593:6-41, 4593:6-51
RTDB database capacity alarm cleared, 4593:3-553
RTDB database capacity is 100% full, 4593:3-546
RTDB database capacity is 80 full%, 4593:3-552
RTDB database corrupted, 4593:3-547
RTDB database has been corrected, 4593:3-551
RTDB database incoherent, 4593:3-554
RTDB database is inconsistent, 4593:3-549
RTDB Menu, 4307:3-34
RTDB reload complete, 4593:3-558
RTDB reload required, 4593:3-557
RTDB resynchronization in progress, 4593:3-556
rtrv commands, 0008:2-56, 0008:2-73, 0008:2-75

rtrv-acg-mic, 4800:7-223
rtrv-acg-noc, 4800:7-225
rtrv-appl-rtkey, 4800:7-226
rtrv-appl-sock, 4800:7-233
rtrv-as, 4800:7-236
rtrv-asp, 4800:7-237
rtrv-assoc, 4800:7-238
rtrv-atm-lps, 4800:7-242
rtrv-atm-prm, 4800:7-247
rtrv-attr-seculog, 4800:7-248
rtrv-bip, 4800:7-249
rtrv-card, 4800:7-253, 4803:3-24
rtrv-card Eagle command, 0008:2-3
rtrv-cmd, 4800:7-258
rtrv-cmdclass, 4800:7-261
rtrv-cspc, 4800:7-262
rtrv-ctrl-feat, 4800:7-264, 4803:2-2, 4803:2-12, 4803:2-18, 4803:4-2, 4803:4-10, 4803:6-2
rtrv-ctrl-feat Eagle command, 0008:2-3, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-103
rtrv-data-rtdb, 4800:8-45
rtrv-dcmps, 4800:7-267
rtrv-dlk, 4800:7-268
rtrv-dstn, 4800:7-270, 4803:2-2, 4803:2-12, 4803:2-18
rtrv-e1, 4800:7-285
rtrv-eisopts, 4800:7-288
rtrv-feat, 4800:7-288, 4803:2-2, 4803:2-7, 4803:2-12, 4803:2-18, 4803:5-3, 4803:5-8, 4803:5-16, 4803:5-22, 4803:5-35, 4803:5-42, 4803:5-56, 4803:5-71, 4803:5-89, 4803:5-102, 4803:5-117, 4803:5-143
4000 Routesets (23.0), 4318:2-6
Calling Name Conversion Facility (CNCF) (23.1), 4318:2-42
rtrv-feat Eagle command, 0008:2-54
rtrv-ftp-serv, 0002:4-154, 4800:7-290
rtrv-ftp-serv Eagle command, 0008:2-116
rtrv-gpl, 4800:7-293
rtrv-gsmmap-scrn, 4800:7-299
rtrv-gsmopts, 4800:7-303
rtrv-gsms-opcode, 4800:7-307
rtrv-gsmssn-scrn, 4800:7-309
rtrv-gta, 4800:7-311
rtrv-gta Eagle command, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gtt, 4800:7-317, 4800:7-319, 4803:4-10
rtrv-gtt Eagle command, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gttsel, 4800:7-328, 4803:6-10, 4803:6-16
rtrv-gttsel Eagle command, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gttset, 4800:7-332
rtrv-gttset Eagle command, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-gtw-stp, 4800:7-334
rtrv-gtwy-acthresh, 4800:7-334
rtrv-gtwy-prmtrs, 4800:7-336
rtrv-gws-actset, 4800:7-336
rtrv-gws-redirect, 4800:7-338
rtrv-homern, 4800:7-340
rtrv-home-smsc, 4800:7-339
rtrv-inpopts, 4800:7-341

rtrv-ip-card, 4800:7-342
rtrv-ip-host, 4800:7-344
rtrv-ip-lnk, 0002:4-153, 0002:4-172, 0002:4-173, 4800:7-345
rtrv-ip-lnk command, 0008:2-46, 0008:2-47
rtrv-ip-node, 4800:7-347, 4800:7-351
rtrv-ip-rte, 4800:7-350
rtrv-isupvar-attrib, 4800:7-351
rtrv-l2t, 4800:7-354
rtrv-l3t, 4800:7-355
rtrv-lbp, 4800:7-358
rtrv-lnp-dbts, 4800:7-360
rtrv-lnp-dpcer, 4800:7-362
RTRV-LNP-DPCER command is already in progress, 4801:2-643
RTRV-LNP-DPCER command must be in progress, 4801:2-644
rtrv-lnp-lrn, 4800:7-365
rtrv-lnp-npanxx, 4800:7-368
rtrv-lnpopts, 4800:7-383
rtrv-lnp-serv, 4800:7-371
rtrv-lnp-sp, 4800:7-372
rtrv-lnp-sub, 4800:7-374
rtrv-lnp-tnrpt, 4800:7-379
rtrv-lnp-ttmap, 4800:7-381
rtrv-log, 4800:7-385
rtrv-log command, 4593:3-63
RTRV-LOG command already in progress, 4801:2-408
rtrv-ls, 4800:7-395
rtrv-m2pa-tset, 4800:7-412
rtrv-map, 4800:7-413, 4803:4-2, 4803:6-2
rtrv-measopts, 4800:7-419
rtrv-meas-sched, 4800:7-417
rtrv-mem, 4800:7-422
rtrv-mrn, 4800:7-423
rtrv-na, 4800:7-425
rtrv-netopts, 4800:7-426
rtrv-oap-config, 4800:7-426
rtrv-oap-config command, 0002:A-35, 0002:A-63, 4601:6-122, 4601:6-137
rtrv-pstn-pres, 4800:7-430
rtrv-rmt-appl, 4800:7-431
rtrv-rte, 4800:7-432
rtrv-scr-aftpc, 4800:7-437
rtrv-scr-blkdpc, 4800:7-442
rtrv-scr-blkopc, 4800:7-447
rtrv-scr-cdpa, 4800:7-452
rtrv-scr-cgpa, 4800:7-457
rtrv-scr-destfld, 4800:7-463
rtrv-scr-dpc, 4800:7-467
rtrv-scr-isup, 4800:7-472
rtrv-scr-opc, 4800:7-476
rtrv-scrset, 4800:7-488
rtrv-scr-sio, 4800:7-481
rtrv-scr-tt, 4800:7-485
rtrv-secu-dflt, 4800:7-492

rtrv-secu-dflt Eagle command, 0008:2-21
rtrv-seculog, 4800:7-500
rtrv-secu-trm, 4800:7-494
rtrv-secu-user, 4800:7-496
rtrv-serial-num, 4800:7-506
rtrv-sg-opts, 4800:7-506
rtrv-shlf, 4800:7-508
rtrv-sid, 4800:7-509, 4803:2-12, 4803:2-16
rtrv-slt, 4800:7-518
rtrv-spc, 4800:7-520
rtrv-split-npa, 4800:7-523
rtrv-srvsel, 4800:7-525
rtrv-ss-appl, 4800:7-530
rtrv-stpopts, 4800:7-532, 4803:2-2
rtrv-t1, 4800:7-537
rtrv-tbl-capacity, 4800:7-539
RTRV-TBL-CAPACITY Enhancement (Release 29.0), 4318:5-47
rtrv-th-sccp, 4800:7-541
rtrv-trbl, 4800:7-541
rtrv-trbltx, 4800:7-543
rtrv-trbltx command, 4593:3-64
rtrv-trbltx report, 4593:3-64
rtrv-trm, 4800:7-549
rtrv-trm command, 0008:2-45, 0008:2-46
rtrv-trm Eagle command, 0008:2-65
rtrv-tt, 4800:7-564, 4803:4-10, 4803:4-18
rtrv-tt Eagle command, 0008:2-54, 0008:2-59, 0008:2-65
rtrv-ttmap, 4800:7-567
rtrv-uaps, 4800:7-569
rtrv-uim-acthresh, 4800:7-573
rtrv-user, 4800:7-574
rtrv-x25-dstn, 4800:7-576
rtrv-x25-rte, 4800:7-578
rtrv-x25-slk, 4800:7-581
Run Health Check menu, 4307:3-73

S

S/ESHELF can only be entered, when report = hmuxerr is set, 4801:2-799
SA, 4802:1-16
SADDR and EADDR must have the same number of digits, 4801:2-749
SADDR must be specified when EGMS feature is OFF, 4801:2-884
SADDR, NPV and NAIV must be specified together, 4801:2-794
safety, 2969:2-1
Safety glasses, 4601:3-20
safety glasses, 2969:4-3
SAI/P card
    description, 4625:4-30, 4625:4-43
    replacement procedure, 4593:6-122, 4593:6-127
Same link management, 0004:2-8
same link management
    X.25/SS7 Gateway Feature (Eagle 20.0), 4318:5-178

SAP
technical reference documents, 4625:1-13, 4626:1-16
SAPC allowed for ITU-I or ITU-N linkset only, 4801:2-836
SAPC entry not found for the linkset, 4801:2-834
SAPC entry preset for the linkset, 4801:2-836
SATA hard drives, 2969:7-2
Save button
Retrieve Tables Log
Save window, 0008:2-72
System Log Save window, 0008:2-101
Update Tables Log Save window, 0008:2-96
Save window
Cancel button
System Log, 0008:2-101
Update Tables Log, 0008:2-96
Connectivity Test Log, 0008:2-35
Retrieve Tables Log, 0008:2-71, 0008:2-72
System Log, 0008:2-100, 0008:2-101
Update Tables Log, 0008:2-95, 0008:2-96
Saved File Confirmation window
Connectivity Test Log, 0008:2-35, 0008:2-36
Retrieve Tables Log, 0008:2-72
System Log, 0008:2-101
Update Tables Log, 0008:2-96
savelogs, 2712:A-9
Savelogs Procedure, 2712:A-9
Saving to a file
Connectivity Test Log, 0008:2-32, 0008:2-35
Retrieve Tables Log, 0008:2-68, 0008:2-71
System Log, 0008:2-97, 0008:2-100
Update Tables Log, 0008:2-92, 0008:2-95
SB, 4802:1-16
scalar localtime, 4307:B-22
SCCP, 0006:2-26, 0006:2-59
SCCP appl provisioned with ASM card type, 4801:2-602
SCCP capacity normal, card(s) abnormal, 4593:3-422
SCCP Card - Removing, 0007:2-24
SCCP card must have at least 586 processor, 4801:2-440
SCCP CdPA, 4318:5-19
SCCP Class 1 Sequencing
class1seq parameter, 0006:2-20, 0006:2-194, 0006:2-195
options
changing, 0006:2-20, 0006:2-194, 0006:2-195, 0006:2-196, 0006:2-197
SCCP Conversion
ANSI-ITU, 4802:2-3, 4802:2-4
ANSI-ITU-China, 0006:1-2, 0006:2-3, 0006:2-6, 0006:2-7, 0006:2-16, 0006:2-17, 0006:2-30, 0006:2-33, 0006:2-40, 0006:2-43, 0006:2-44, 0006:2-47, 0006:2-48, 0006:2-49, 0006:2-70, 0006:2-72, 0006:2-83, 0006:2-87, 0006:2-93, 0006:2-118, 0006:2-124, 0006:2-160, 0006:2-161, 0006:2-169, 0006:2-170, 0006:2-177, 0006:2-179, 0006:2-191, 0006:2-192, 0006:3-2, 0006:3-21, 0006:3-23, 0006:3-29, 0006:3-33, 0006:3-54, 0006:3-55, 0006:3-56, 0006:3-59, 0006:3-63, 0006:4-2, 0006:4-27, 0006:4-30, 0006:4-34, 0006:4-38, 0006:4-53, 0006:4-56, 0006:4-59, 0006:4-62, 0006:A-36, 0006:A-37, 0006:A-38, 0006:A-39, 0006:A-41, 0006:A-42

changing options, 0006:2-191, 0006:2-193
SCCP Conversion Feature
ANSI-ITU-China
Activating, 0006:A-36, 0006:A-43, 0006:A-44, 0006:A-45, 0006:A-46
SCCP Conversion feature must be enabled, 4801:2-842
SCCP Conversion feature requires at least TSM Hardware, 4801:2-856
SCCP Database Download in Progress, 4801:2-488
SCCP did not route - bad translation, 4593:3-664, 4593:3-863
SCCP did not route - DPC congested, 4593:3-668, 4593:3-869
SCCP did not route - DPC not in MAP tbl, 4593:3-669, 4593:3-871
SCCP did not route - DPC OOS, 4593:3-665, 4593:3-866
SCCP did not route - SS congested, 4593:3-671, 4593:3-874
SCCP did not route - SS not in MAP tbl, 4593:3-672, 4593:3-876
SCCP did not route - SS OOS, 4593:3-670, 4593:3-873
SCCP Encode Failure, 4593:3-878, 4593:3-879
SCCP envelopes, 0004:2-4, 4318:5-174
SCCP is available, 4593:3-421
SCCP is not available, 4593:3-425
SCCP is removed, 4593:3-429
SCCP Message Type Screening (EAGLE 22.0), 4318:5-51
SCCP not configured, 4801:2-152
SCCP rcvd GSM Map Opcode w/forbid param, 4593:3-896
SCCP rcvd inv Cld Party - bad GT ind, 4593:3-650, 4593:3-858
SCCP rcvd inv Cld Party - bad network, 4593:3-654, 4593:3-859
SCCP rcvd inv Cld Party - no SSN, 4593:3-655, 4593:3-860
SCCP rcvd inv GT - bad Translation Type, 4593:3-663
SCCP rcvd inv GT - invalid selectors, 4593:3-861
SCCP rcvd inv LSS - bad SSN, 4593:3-681, 4593:3-865
SCCP rcvd inv msg class, 4593:3-646
SCCP rcvd inv msg length, 4593:3-645
SCCP rcvd inv SCMG - bad AFTPC, 4593:3-682
SCCP rcvd inv SCMG - bad length, 4593:3-685
SCCP rcvd inv SCMG - bad msg type, 4593:3-686
SCCP rcvd inv SCMG - bad subsystem, 4593:3-684
SCCP rcvd inv SCMG - invalid SOR, 4593:3-702
SCCP rcvd invalid UDTS msg, 4593:3-638
SCCP rcvd invalid XUDT msg, 4593:3-640
SCCP rcvd invalid XUDTS/LUDTS msg, 4593:3-641
SCCP rcvd undefined Map Op-Code, 4593:3-898
SCCP rcvd unknown msg type, 4593:3-644
SCCP rsp did not route - bad Selectors, 4593:3-660
SCCP rsp did not route - bad Xlation, 4593:3-658
SCCP rsp did not route - invalid GTI, 4593:3-656
SCCP rsp did not route - invalid TT, 4593:3-657
SCCP rsp did not route - no SSN in msg or DB, 4593:3-662
SCCP rsp did not route - SSP not True PC, 4593:3-659
SCCP screen set is too large, 4593:3-691
SCCP Screening, 0005:2-2
SCCP Subsystem Management, 1021:4-6
SCCP XUDT(S) msg
inv segmentation parm, 4593:3-744
SCCP XUDT/LUDT msg

Hop Counter violation, 4593:3-742
inv opt portion len, 4593:3-743
SCCP-CNV
Unable to convert ANSI CDPA GT, 4593:3-673
Unable to convert ANSI CGPA GT, 4593:3-675
Unable to convert ITU CDPA GT, 4593:3-677
Unable to convert ITU CGPA GT, 4593:3-679
SCCPCNV must be ON before TCAPCNV can be ON, 4801:2-571
SCCPCNV, TCAPCNV must be disabled, 4801:2-855
SCCPMT must be specified as 9, 10, 17, 18, or *, 4801:2-183
SCCS Interface Support (EAGLE 21.0), 4318:5-53
Scheduled transfer failure, 4593:3-903
SCMGFID is invalid, 4801:2-212
Scope and Audience, 1021:1-1, 4625:1-4, 4625:3-44
Screen Resolution, 4307:5-3
Screen set name already exists, 4801:2-241
Screen set name is referenced by a link set, 4801:2-241
Screen set name not defined, 4801:2-144
screen workspace, 4307:3-4
Screening action can not be ATIERR for the given OPNAME, 4801:2-753
screws, 4601:5-69
scroll by messages, 4307:3-117, 4593:6-26
SCSI
disks, MPS Server, 4625:4-27
MPS Server interface, 4625:4-27
sctp, 4800:9-101
SCTP Association or SLK provisioned
Card supports 2 links, 4801:2-585
SCTP checksum algorithm option, 0003:3-376, 0003:3-406
SCTP Retransmission Control (Release 28.1), 4318:5-59
SCTP Retransmission Control (Release 28.1) (IP7 Release 6.0), 4318:5-59
sctpcsum, 0003:3-151, 0003:3-376, 0003:3-406
SDATE must be earlier or equal to EDATE, 4801:2-435
SDATE+STIME must be before current date-time, 4801:2-408
SEAC, 4802:1-17
SEAC CLLI parameter requires SEAS feature, 4801:2-663
SEAC CLLI required before OAP update, 4801:2-670
SEAS compliance
Enhancements to GWS Reject Messages (25.0), 4318:2-164
SEAS Enhancements (EAGLE 26.0), 4318:5-61
Affected Commands, 4318:5-61
SEAS Enhancements, Autonomous Messages (EAGLE 22.0), 4318:5-66
SEAS Error Messages Index, 4801:3-1
SEAS feature or LNP feature is not configured, 4801:2-350
SEAS Gateway Audit Command (CHK-UNREF-ENT) (EAGLE 22.0), 4318:5-67
SEAS Gateway Linksets cannot be deleted locally, 4801:2-406
SEAS Gateway Screen Set Names cannot be changed locally, 4801:2-406
SEAS Interface Support (EAGLE 21.0), 4318:5-68
SEAS is at min service limit, 4593:3-450
SEAS is available, 4593:3-461
SEAS is removed, 4593:3-462
SEAS PVC unavailable, 4593:3-443

SEAS Subsystem has not been provisioned, 4801:2-318
SEAS UAL session unavailable, 4593:3-447
SEAS UAL unavailable, 4593:3-439
SEAS unavailable, 4593:3-454
SEAS Verify Signaling Route-Set Status and SCCP Application Status Command (VFY-SRSAPST) (EAGLE 22.0), 4318:5-71
SEAS X.25 Link is available, 4593:3-449
SEAS X.25 Link unavailable, 4593:3-441
SEAS X.25 mode required before OAP update, 4801:2-671
SEAS X.25 packet size required before OAP update, 4801:2-671
SECMTPMATE - rcvd mate PC on non C-link, 4593:3-953
SECMTPSID - rcvd MSU with OPC = SID, 4593:3-954
SECMTPSNM - no rte to OPC / AFTPC, 4593:3-955
secondary point codes, 4804:2-3
  configuring, 4804:2-47
Seconds out of range, 4801:2-108
SECSCCPSCMG - no rte to AFTPC, 4593:3-956
secure connection, 0008:2-3, 0008:2-17, 0008:2-43
Secure Connection Box - FTRA 2.0 or greater, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-43, 0008:2-48, 0008:2-49
Secure Eagle Host Key Provisioning, 0008:2-43
Secure FTP server, 0008:2-49
Secure Host Key - Eagle
  Provisioning, 0008:2-43
secure IP connection between FTRA and STP, 0008:2-17, 0008:2-22
secure shell encryption key exchange, 4307:5-21
security, 2712:2-14
Security Administration, 0008:2-46, 4802:1-16
Security Administration Unsolicited Output Message Group, 4593:D-25
security defaults
  changing, 0002:4-7
security log characteristics
  changing, 0002:4-17
Security log command already in progress, 4801:2-437
Security log exception cleared, 4593:3-261
Security log failed, 4593:3-262
Security Log Increase (EAGLE 26.05), 4318:5-71
  Enhanced Commands, 4318:5-71
  Increasing the FTA (File Transfer Area), 4318:5-71
  limitations, 4318:5-72
  Upgrade Considerations, 4318:5-72
Security tables may not be altered, 4801:2-541
Seismic Frame, 4601:3-24
Select button, 0008:2-16, 0008:2-25, 0008:2-27
  Select Starting Directory window, 0008:2-52
  Select window, 0008:2-79, 0008:2-80
Select Mate menu, 4307:3-13
Select Starting Directory window, 0008:2-50, 0008:2-51, 0008:2-52
  Cancel button, 0008:2-52
  Select button, 0008:2-52
Select Time Zone, 4307:5-21
Select Time Zone menu, 4307:5-21

Select window
Cancel button, 0008:2-79, 0008:2-80
description, 0008:2-80
Select button, 0008:2-79, 0008:2-80
Update Tables, 0008:2-77, 0008:2-78, 0008:2-79, 0008:2-80
Selected Commands
Box, 0008:2-54, 0008:2-56, 0008:2-60, 0008:2-62, 0008:2-63, 0008:2-64
Adding a Command, 0008:2-60
Adding a Range of Commands, 0008:2-61
Adding Multiple Commands, 0008:2-61
Command Selected Removed, 0008:2-63
Command Selected to be Removed, 0008:2-62
Field, Retrieve Tables window, 0008:2-56
Selected STP, 0008:2-1, 0008:2-4, 0008:2-41, 0008:2-54, 0008:2-56, 0008:2-63, 0008:2-64, 0008:2-65, 0008:2-77, 0008:2-78, 0008:2-83, 0008:2-84, 0008:2-85, 0008:2-87
Sending a Command File, 0008:2-84
Selecting
Command, 0008:2-58
Current STP, 0008:2-4, 0008:2-40
Multiple Commands, 0008:2-60
Range of Commands, 0008:2-59
Selective Alarm Inhibiting (EAGLE 22.0), 4318:5-72
Changed Commands, 4318:5-75
New Commands, 4318:5-74
Selective Homing of EPAP RTDBs (Release 29.0), 4318:5-76
self identification of system
changing, 4804:2-64
Semi-Annual Procedures, 4593:2-41
Sending a Command File to the Selected STP, 0008:2-84
Sending Eagle command files, 0008:2-4
send-msg, 4800:8-50
sense errors, 4593:6-5
Sentinel Data Collection Subsystem, ANSI ISUP CDR Data Feed document, 4625:1-13, 4626:1-16
Sentinel Data Collection Subsystem, ITU ISUP CDR Data Feed document, 4625:1-14, 4626:1-16
Sentinel Data Collection Subsystem, LIDB TDR Data Feed document, 4625:1-14, 4626:1-17
Sentinel Data Collection Subsystem, Peg Counter Data Feed File Format document, 4625:1-14, 4626:1-17
Sentinel Frames, 1021:5-4, 4625:5-4
Sentinel Products, 4625:5-1
Sentinel publications, 4625:1-12, 4626:1-15
Sentinel Server Frames, 1021:5-5
Sentinel Site Collector Frame with Flight Recorders, 4625:1-9
Sentinel Transport Card, 0004:6-3, 0004:6-4, 0004:6-5, 0004:6-6, 0004:6-7, 0004:6-8, 0004:6-9, 0004:6-10, 0004:6-11, 0004:6-15, 0004:6-16, 0004:6-19, 0004:6-20, 0004:6-23, 0004:6-24, 0004:6-25, 0004:6-26, 0004:6-27, 0004:6-28, 0004:6-29, 0004:6-30
dual-slot, 0004:6-4, 0004:6-7, 0004:6-8, 0004:6-19, 0004:6-21, 0004:6-23
single-slot, 0004:6-4, 0004:6-7, 0004:6-8, 0004:6-19, 0004:6-21, 0004:6-23
Sentinel Transport Cards, 1021:5-8, 4625:2-22
Serial card
Embedded OAP (24.0), 4318:2-131
serial card, 4593:5-22
serial communication, 1021:6-6, 2712:2-10

serial I/O card (EOAP), 4593:5-134
    replacement, 4593:5-134
SERIAL param valid only with APPL param, 4801:2-696
serial port connectors, 4625:3-27
serial ports
    8-Port Connector Box, 4625:4-30, 4625:4-38, 4625:4-43
    MPS Server, 4625:4-27
    SAI/P card, 4625:4-30, 4625:4-43
SERV, 4802:1-17, 4802:3-30, 4802:3-31, 4802:3-32, 4802:3-33, 4802:3-37, 4802:3-41, 4802:3-42, 4802:3-45, 4802:3-48, 4802:3-49, 4802:3-52, 4802:3-53, 4802:3-89, 4802:3-120, 4802:3-132, 4802:3-142, 4802:3-158, 4802:3-176, 4802:3-180, 4802:4-5, 4802:4-21, 4802:4-24, 4802:4-25, 4802:4-28, 4802:4-29, 4802:4-31, 4802:4-32, 4802:4-33
SERV has not been assigned a true TT, 4801:2-480
SERV must not be GFLEX when SNAI = RNIDN/RNNDN/RNSDN, 4801:2-771
Server
    FTP - FTRA 2.0, 0008:2-49
    FTP, Configuration, 0008:2-4
    Secure FTP - FTRA 2.0, 0008:2-49
server, 1021:4-10, 0003:3-209
    command line, connecting to, 2712:A-3
Server, MPS
    see MPS Server
Service parameters within error messages, 4307:B-19
Service Provider, 4318:4-84, 4802:1-17, 4802:3-44, 4802:3-77, 4802:3-79, 4802:3-80, 4802:3-82, 4802:3-84, 4802:3-97, 4802:3-116, 4802:3-118, 4802:3-125, 4802:3-126, 4802:3-127, 4802:3-131, 4802:3-137, 4802:3-140, 4802:3-145, 4802:3-150, 4802:3-156, 4802:3-165, 4802:3-180
Service Provider already assigned, 4801:2-494
Service Provider does not exist, 4801:2-495
Service Provider ID, 4802:3-165
Service Provider referenced in LNP database, 4801:2-495
Service Providers, 4307:3-47
Service Request, 4626:1-19
Service Selector Table is full, 4801:2-604
Service Type is already in LNP database, 4801:2-487
Service type is not in LNP database, 4801:2-490
serviceability
    Enhanced Bulk Download (25.0), 4318:2-146
services, technical
    see also Tekelec Technical Services
    e-mail address, 4625:1-15
    telephone numbers, 4625:1-15
SERVPORT, 4802:3-166
Session Idle Timeout, 4307:3-110
session inactivity, 4307:3-5
Set button, 0008:2-53
    FTP Server Configuration Menu, 0008:2-50
Set SERVERPFX to NONE before disabling IS412GSM, 4801:2-888
setcomm, 0003:3-151
set-date, 4800:7-583
set-gtwy-actthresh, 4800:7-584
set-mem, 4800:8-53
set-scrrej-prmtrs, 4800:7-585

set-time, 4800:7-586
setting
system clock and date, 0002:4-3
Setting the Maximum Number of Gateway Screening Rejected Messages, 4803:5-142
Setting the Threshold for Reporting Gateway Screening Activity, 4803:5-141
Setting Up an ELAP Workstation, 0007:2-38, 4307:5-3
Setting Up Workstation, 4307:5-3
set-uim-acthresh, 4800:7-588
SFTP client channel open failure - Error code 695, 0008:2-115
SFTP client channel read failure - Error code 693, 0008:2-115
SFTP client channel write failure - Error code 694, 0008:2-115
SFTP Client Errors, 0008:2-104
SFTP client packet send failure - Error code 597, 0008:2-104
SFTP Connection Errors, 0008:2-115
SFTP Error Codes, 0008:2-103
SFTP Errors, 0008:2-104
SFTP packet read failure - Error code 599, 0008:2-104
SFTP protocol error - Error code 600, 0008:2-105
SFTP received a invalid ID in the response received during a read operation on remote directory - Error code 608, 0008:2-105
SFTP Server, 0008:2-112, 0008:2-115, 0008:2-119
SFTP Server Verification procedure, 0008:2-119
SFTP Setup Errors, 0008:2-115
SFTP / SSH Error Codes, 0008:2-103
SFTP: Handle mismatch error - Error code 609, 0008:2-105
shelf
adding, 0002:4-93, 4804:3-3
removing, 0002:4-95
Shelf Clock Connectors, 4625:3-28
Shelf ID out of range, 4801:2-53
Shelf location 1100 is reserved for the control shelf, 4801:2-78
Shelf location already equipped, 4801:2-79
Shelf location not equipped, 4801:2-33
Shell command prompt, 0008:2-73
Shipping Container, 4626:1-23
shipping container, 4601:1-17, 4601:3-4, 4601:3-5, 4601:3-6, 4601:3-7, 4626:1-18
Shipping Manager, 4601:1-17, 4601:3-10, 4626:1-18
shipping, return instructions, 2969:B-19
Short Message Service (SMS) - LNP - Activation, 0007:2-157
Short Message Service Center (SMSC), 4318:5-19
short synchronization, 4751:4-2
si, 0003:3-242
SI does not exist for given SR, 4801:2-242
side panel, 4601:3-33
Signaling Engineering and Administration Center, 4802:1-17
signaling link
adding, 4804:3-4, 4804:3-5, 4804:3-122, 4804:C-37
card types, 4804:3-4
configure for E1 card, 4804:A-8
parameters for DCMs, 4804:3-6
removing, 0003:3-117, 4804:3-137
verify, 4804:3-5

Signaling link is not provisioned for the card, 4801:2-805
signaling link selection conversion
5-8 Bit Sequencing Assurance (24.0), 4318:2-17
signaling link test message
changing, 4804:3-194
signaling links, 1500, 0003:3-110, 4804:3-9
Signaling Network Control Center, 4802:1-17
Signaling System #7, 4751:1-7
Signaling Transfer Point, Local Area Network (SLAN), 4625:6-9
Signaling / Cellular Generic Hardware Reference, 4625:1-13, 4626:1-16
Simplex Mode
FRCSMPLX, 4802:3-165
Simplex Mode Menu, 4307:3-19
Simplifying BIP (Board ID PROM) for Eagle STP Boards (EAGLE 23.1), 4318:5-78
Changed Commands, 4318:5-79
Hourly Status Message Report, 4318:5-79
Single Slot EDCM (SSEDCM), 4318:5-81
single slot EDCM card, 4318:5-80
single-slot STC, 0004:6-4, 0004:6-7, 0004:6-8, 0004:6-19, 0004:6-21, 0004:6-23
SIO does not exist in given SR, 4801:2-241
Site Collector Frames, 1021:5-4, 4625:5-6
site engineering, 4625:6-1
Site PC, CPCs and NCPCs must be full point codes, 4801:2-373
Site point code is already being used, 4801:2-73
Site SPC must be a full point code, 4801:2-714
slab floor
anchor assembly, 2969:4-7
slab floor, anchoring frame, 2969:4-6
SLAN DLK ping test completed, 4593:3-773
SLK Inhibit Denied, 4593:3-795
SLK Inhibit Response Timeout, 4593:3-796
SLK IPLIML2 requires linkset MTPRSE setting to be no, 4801:2-535
SLK Level-3 T19 timer expired, 4593:3-794
SLK Uninhibit Denied, 4593:3-797
SLK Uninhibit Response Timeout, 4593:3-798
SLKUSEALM not allowed for non-IPGWx linksets, 4801:2-874
SLSCI is only valid for ANSI link sets, 4801:2-371
SLSOCBIT parameter is only valid for ITU link sets, 4801:2-734
SLSOCBIT parameter not permitted if SLSOCB feature is off, 4801:2-734
SLSRSB parameter is only valid for ITU Link Sets, 4801:2-735
SLTC aborted
unable to perform the test, 4593:3-708
SLTC failure
bad data pattern, 4593:3-701
failed link, 4593:3-706
invalid Point Code (DPC), 4593:3-705
invalid Point Code (OPC), 4593:3-698
invalid SLC, 4593:3-699
no response, 4593:3-700
SLTC success
manual test passed, 4593:3-707
SLTSET and ENABLED cannot be specified together, 4801:2-75

Small Computer System Interface Buses, 1021:3-5, 4625:2-6
SMS (Short Message Service) - LNP - Activation, 0007:2-157
SMS Feature - LNP - Deactivating, 0007:2-162
SMSC ADDR to be deleted does not exist in database, 4801:2-594
SMSC Address already exists, 4801:2-595
SNAI & SNP must be specified when SERV is not INPQ/EIR, 4801:2-771
sname, 0003:3-242
SNAME must be specified, 4801:2-412
SNCC, 4802:1-17
SNM Overload Abated, 4593:3-395
SNM Overload Onset, 4593:3-394
snmpcont, 0003:3-151
SNSAP parameter
    chg-oap-config, 0002:A-26, 4601:6-113
Socket connection parameters must be unique, 4801:2-682
Socket name already exists, 4801:2-681
Socket Name not defined, 4801:2-693
Socket name not found, 4801:2-680
Socket operation on non-socket - Error code 50, 0008:2-116
Socket Table full, 4801:2-686
sockrtt, 4800:9-110
sockstate, 4800:9-112
Software
    FTRA
        Installing, 0008:2-4
            Unix, 0008:2-7
            Windows, 0008:2-5
    Java 2 Runtime Environment
        installing, 0008:2-5, 0008:2-7
Software caused the connection to abort - Error code 53, 0008:2-116
Software Configuration, 4307:5-1
Software Configuration Alarm, 4593:6-9
Software Requirements, 0008:2-2
    Unix Workstation, 0008:2-2
    Windows Workstation, 0008:2-2
software, MPS system configuration, 1021:6-5, 2712:2-10
Solaris 7 operating system, 4625:4-28
Source address/location must be specified, 4801:2-447
Source and destination combination is not allowed, 4801:2-653
Source and destination disks not compatible, 4801:2-356
Source database version is not compatible, 4801:2-410
Source drive not coherent, 4801:2-357
Source location must specify the active fixed disk, 4801:2-354
Source parameter not supported, 4801:2-68
SP, 4318:4-84, 4802:1-17, 4802:3-43, 4802:3-44, 4802:3-78, 4802:3-79, 4802:3-80, 4802:3-81, 4802:3-82, 4802:3-83, 4802:3-97, 4802:3-116, 4802:3-118, 4802:3-119, 4802:3-122, 4802:3-125, 4802:3-126, 4802:3-127, 4802:3-131, 4802:3-132, 4802:3-134, 4802:3-137, 4802:3-139, 4802:3-141, 4802:3-143, 4802:3-145, 4802:3-151, 4802:3-157, 4802:3-159, 4802:3-161, 4802:3-165, 4802:3-168, 4802:3-169, 4802:3-171, 4802:3-179, 4802:3-180
SP must be specified if not already assigned, 4801:2-506
SP specified does not match SP already assigned, 4801:2-506
space requirements, 2969:2-7, 4625:6-3

spare card storage shelf, 4625:3-14
Spare Inventory Rotation, 4593:2-41
SPC & DPC must be the same network type, 4801:2-714
SPC and NSPC may not be equal, 4801:2-710
SPC does not exist, 4801:2-712
SPC may not be referenced in the STP's route table, 4801:2-713
SPC may not exist as a TPC or CPC in the SID table, 4801:2-711
SPC may not exist as a TPC, CPC, or DPC in the route table, 4801:2-712
SPC may not exist in the STP's route table, 4801:2-711
SPC must be a full point code, 4801:2-715
Specific SSN already exists, 4801:2-847
specifications
    MPS Server component, 1021:6-10
    MPS Server CPU, 4625:4-27
    tape drive, 4625:4-27
Specified APPL or LOC not supported with DATA parameter, 4801:2-730
Specified AS name not found, 4801:2-818
Specified ASP name not found, 4801:2-821
Specified association already assigned to an ASP, 4801:2-815
Specified BC exceeds max allowed (96), 4801:2-89
Specified BPS is invalid, 4801:2-565
Specified card cannot be the Active MASP, 4801:2-773
Specified cards A, B interface IP Address must be assigned, 4801:2-628
Specified LOC is invalid, 4801:2-153
Specified LPSET contains default values and not configurable, 4801:2-563
Specified OAP does not exist, 4801:2-641
Specified OAP not available, 4801:2-639
Specified Port is not valid for Card and APPL Type, 4801:2-423
Specified SP does not match LRN SP, 4801:2-477
Specified UID is reserved for system use, 4801:2-437
speed, file system tape backup, 4593:6-17
split, 0003:3-250, 0003:3-263
Split Allowed CGPA Table (EAGLE 22.0), 4318:5-81
SPLIT must be greater than CICS, 4801:2-719
SPLIT must be less than or equal to CICE, 4801:2-720
Split NPANXX, 4318:4-85, 4802:3-110, 4802:3-113, 4802:3-114, 4802:3-115
Split of Allowed SIO Table (Release 22.0), 4318:5-82
SPLIT, NCICS, NCICE are not allowed with SI unless SI is 4, 5, or 13, 4801:2-722
SPLIT, NSNAME, NCICS, NCICE or attributes required, 4801:2-722
SPSEL parameter
    chg-oap-config, 0002:A-26, 4601:6-113
SR or NSR does not reference an existing SR, 4801:2-243
SRAM, 4625:3-91
SRC and DEST must be specified, 4801:2-91
SRCLPSET and LPSET cannot be equal, 4801:2-563
SRCSET and SET cannot be equal, 4801:2-798
SRCTSET and TSET cannot be equal, 4801:2-592
SRFADDR, SRFNAI & SRFNP parameters must be entered together, 4801:2-785
srkq, 0003:3-151
SRKQ + DRKQ exceed max allowed rtkey limit, 4801:2-725
SRM or MRC cannot be entered for a solitary entry, 4801:2-427
SRM=YES cannot be entered with ITU point code types, 4801:2-176

SRVSEL of ITU found, but not allowed with ANSIGFLEX, 4801:2-886
SS7, 4751:1-7
SS7 address does not exist in X.25 destination table, 4801:2-291
SS7 and IP7, LIM, MIM, and MPL Card Replacement, 4593:A-19
SS7 Destination assigned to non-SS7 linkset, 4801:2-255
SS7 LIM, MIM, and MPL Card Replacement, 4593:A-19
SS7 linksets, 4804:3-2
SS7 Message Rejection Due to Screening (EAGLE 22.0), 4318:5-83
SS7 over High-Speed Signaling Link (EAGLE 23.0), 4318:5-83
SS7 parameters cannot be specified for IP7 link, 4801:2-695
SS7 signaling links, 0004:6-4, 0004:6-7, 0004:6-21
SS7ANSI, 0004:6-7, 0004:6-20
ss7gx25, 0004:2-11
SS7IPGW
activate signaling link, act-slk, 0003:3-75, 0003:3-133, 0003:3-148, 0003:3-170, 0003:3-182, 0003:3-199, 0003:3-200, 0003:3-214, 0003:3-215, 0003:3-291, 0003:3-293, 0003:3-312, 0003:3-314
display card status, rept-stat-card, 0003:3-146, 0003:3-166, 0003:3-180
display signaling link status, rept-stat-slk, 0003:3-145, 0003:3-148, 0003:3-165, 0003:3-170, 0003:3-178, 0003:3-182, 0003:3-200, 0003:3-201, 0003:3-214, 0003:3-215, 0003:3-291, 0003:3-293, 0003:3-312, 0003:3-314, 0003:3-381, 0003:3-391
ss7ipgw, 1021:3-20, 0003:2-4, 0003:2-21
SS7IPGW / IPGWI cards must be inhibited to change SYNC, 4801:2-730
SS7-Over-IP Gateway for Point-to-Point Links (EAGLE 1.0), 4318:5-84
SSEL parameter requires LNP feature, 4801:2-665
SSH Client Errors, 0008:2-107
SSH Connection Errors, 0008:2-115
SSH Error Codes, 0008:2-103
SSH failure to open the channel for the SSH connection with the server - Error code 628, 0008:2-107
SSH failure to setup the channel for the SSH connection with the server - Error code 629, 0008:2-107
SSH failure to setup the IO with the server - Error code 627, 0008:2-107
SSH failure to verify the SSH client host key - Error code 630, 0008:2-107
SSH Host Keys Loaded, 4593:3-966
SSH Host Keys Regenerated, 4593:3-965
SSH Setup Errors, 0008:2-115
SSH user authentication failure - Error code 631, 0008:2-108
SSH, the Secure Shell: The Definitive Guide, 0008:2-122
SSH / SFTP Error Codes, 0008:2-103
SSH / SFTP tried to close a connection that is already closed - Error code 678, 0008:2-113
SSH / SFTP tried to set the packet size twice - Error code 680, 0008:2-114
SSH_FXP_READLINK request failure - Error code 613, 0008:2-106
SSH_FXP_REALPATH request failure - Error code 612, 0008:2-106
SSHD Server, 0008:2-112, 0008:2-115, 0008:2-119
SSHD Server Verification procedure, 0008:2-119
sshtools.xml, 0008:2-113
SSN, 0006:2-91, 0006:2-112, 0006:3-30, 0006:3-60, 0006:4-35, 0006:4-60, 4802:1-17, 4802:3-42, 4802:3-43, 4802:3-44, 4802:3-57, 4802:3-58, 4802:3-60, 4802:3-64, 4802:3-66, 4802:3-68, 4802:3-71, 4802:3-73, 4802:3-74, 4802:3-81, 4802:3-82, 4802:3-85, 4802:3-87, 4802:3-88, 4802:3-90, 4802:3-91, 4802:3-92, 4802:3-96, 4802:3-97, 4802:3-98, 4802:3-102, 4802:3-104, 4802:3-106, 4802:3-107, 4802:3-111, 4802:3-116, 4802:3-118, 4802:3-119, 4802:3-121, 4802:3-122, 4802:3-126, 4802:3-127, 4802:3-130, 4802:3-132, 4802:3-133, 4802:3-134, 4802:3-137, 4802:3-139, 4802:3-141, 4802:3-143, 4802:3-144, 4802:3-145, 4802:3-151, 4802:3-154, 4802:3-156, 4802:3-157, 4802:3-159, 4802:3-160, 4802:3-161, 4802:3-179
ssn, 0003:3-242, 0004:2-32

SSN can only be specified when XLAT=DPCSSN, 4801:2-189
SSN cannot be specified without a point code, 4801:2-189
SSN does not exist for given remote point code, 4801:2-188
SSN for ITU-I and ITU-N True Point Codes must be the same, 4801:2-852
SSN is not allowed unless SI is 3, 4801:2-689
SSN must be 0 when XLAT is not DPCSSN, 4801:2-497
SSN must be 1 if NSFI=AFTPC, 4801:2-199
SSN must be in SS-APPL table when PC is true point code, 4801:2-633
SSN must be non-zero when XLAT=DPCSSN, 4801:2-496
SSN must be specified for new values of XLAT/RI, 4801:2-182
SSN must be specified when XLAT=DPCSSN, 4801:2-198
SSN not allowed with OPC, CICS, and CICE, 4801:2-701
SSN required if SI is 3, 4801:2-684
SSN value must be LNP SSN or INP SSN, 4801:2-625
SSN/TYPE combination already exists, 4801:2-746
SSN/TYPE combination does not exist, 4801:2-746
SSNE should be greater than SSN, 4801:2-441
SSNs, 4318:5-20
SSO parameter is not compatible with True PC, 4801:2-590
SSP measurements
    LNP—Measurements (22.0), 4318:4-68
SSSEL parameter
    chg-oap-config, 0002:A-26, 4601:6-113
SST possible values, 4800:A-3
ST3, 4601:A-28
Stand-alone Eagle G-Flex Relay Function
    enhanced commands, 4318:3-15
    limitations, 4318:3-19
    new commands, 4318:3-13
    upgrade considerations, 4318:3-18
standard, RFC 1587 network, 0007:2-32, 4307:2-7
STANDBY, 4307:3-7
Standby ELAP
    see Active/Standby
standby MASP, 4318:5-11
Standby MASP allowed, 4593:3-589
Standby MASP has not finished initializing, 4801:2-164
Standby MASP inhibited, 4593:3-588
Standby MASP is inhibited, 4801:2-773
Standby MASP is isolated, 4801:2-163
Standby MASP is not available, 4801:2-409
Standby OAM must be equipped with E586 hardware, 4801:2-603
Standby PDBA Falling Behind, 4593:6-112
Standby TDM failure, 4593:3-140
Standby TDM failure cleared, 4593:3-141
Standby TDM in unknown upgrade mode, 4801:2-574
Start ELAP Software, 4307:3-14
Starting address/location must be specified, 4801:2-446
starting bulk load, 4751:6-9
Starting the FTRA application, 0008:2-4

STAT, 0006:2-91, 0006:2-112, 0006:3-30, 0006:3-60, 0006:4-35, 0006:4-60, 4802:3-57, 4802:3-58, 4802:3-60, 4802:3-64, 4802:3-66, 4802:3-67, 4802:3-68, 4802:3-71, 4802:3-73, 4802:3-74, 4802:3-90, 4802:3-106, 4802:3-121, 4802:3-133, 4802:3-144, 4802:3-160
status
DSM memory capacity, 4307:4-7
DSM Status Requests, 4307:4-5
DSM-ELAP Link alarms, 4307:4-16
ELAP Able / Unable, 4307:2-10
ELAP-to-DSM connection, 4307:4-16
Status field, 4307:3-7
Status Indicators (SI), 4625:3-142
STC, 0004:6-3, 0004:6-4, 0004:6-5, 0004:6-6, 0004:6-7, 0004:6-8, 0004:6-9, 0004:6-10, 0004:6-11, 0004:6-15, 0004:6-16, 0004:6-19, 0004:6-20, 0004:6-23, 0004:6-24, 0004:6-25, 0004:6-26, 0004:6-27, 0004:6-28, 0004:6-29, 0004:6-30
dual-slot, 0004:6-4, 0004:6-7, 0004:6-8, 0004:6-19, 0004:6-21, 0004:6-23
single-slot, 0004:6-4, 0004:6-7, 0004:6-8, 0004:6-19, 0004:6-21, 0004:6-23
STC Network Available, 4593:3-571
STC Network Unavailable, 4593:3-570
Stdby security log - upload required, 4593:3-260
steps before you begin component replacement, 4593:6-114
STIME must be earlier or equal to ETIME, 4801:2-435
Stop Bits, 4802:1-16
stop bits, 0002:A-19, 4593:5-64, 4601:6-108
Stop button, Update Validation Complete window, 0008:2-83
Stop ELAP Software, 4307:3-15
Stop on error box
Update Tables window, 0008:2-78, 0008:2-81, 0008:2-90, 0008:2-91, 0008:2-92
Stop on error box Checked
Command File Selected
Update Tables window, 0008:2-81
Stop Without Sending or Editing a Command File, 0008:2-85
storage components, MPS Server, 4625:4-27
Store button, 0008:2-56, 0008:2-63, 0008:2-73
STP
FTRA IP connection
secure, 0008:2-17, 0008:2-22
Retrieve Database Tables, 0008:2-54
selecting current, 0008:2-4
STP Added window, 0008:2-22
STP Configuration Record, 0008:2-14, 0008:2-15, 0008:2-16, 0008:2-18, 0008:2-23, 0008:2-25, 0008:2-27, 0008:2-28, 0008:2-29, 0008:2-30, 0008:2-31, 0008:2-36, 0008:2-37, 0008:2-38, 0008:2-39, 0008:2-40, 0008:2-42, 0008:2-43, 0008:2-48
Adding, 0008:2-18, 0008:2-48
Deleting, 0008:2-39
Displaying, 0008:2-23
FTRA 1.0, 0008:2-29
FTRA 2.0, 0008:2-29, 0008:2-30
Modifying, 0008:2-36, 0008:2-43, 0008:2-48
testing, 0008:2-31
STP Configuration Record - FTRA 1.0
Adding, 0008:2-18, 0008:2-19, 0008:2-20, 0008:2-21, 0008:2-22
STP Configuration Record - FTRA 2.0

Adding, 0008:2-18, 0008:2-19, 0008:2-20, 0008:2-21, 0008:2-22
STP Connection Configuration, 0008:2-1
Database, 0008:2-14, 0008:2-16, 0008:2-17, 0008:2-18, 0008:2-22, 0008:2-40
Menu, 0008:2-11, 0008:2-14
Menu window, 0008:2-14, 0008:2-15, 0008:2-16, 0008:2-18, 0008:2-23, 0008:2-27, 0008:2-31, 0008:2-36, 0008:2-39, 0008:2-40, 0008:2-41, 0008:2-104, 0008:2-120, 0008:2-121
FTRA 1.0, 0008:2-14
FTRA 2.0, 0008:2-49
FTRA 2.0 or greater, 0008:2-14, 0008:2-15
STP Connection Configuration Menu
Add button, 0008:2-1, 0008:2-16, 0008:2-18, 0008:2-22
Close button, 0008:2-16, 0008:2-25, 0008:2-27
Delete button, 0008:2-16, 0008:2-25, 0008:2-27, 0008:2-40
FTP Password Field, 0008:2-16, 0008:2-22
FTP UserName Field, 0008:2-16, 0008:2-21
IP Address, 0008:2-16, 0008:2-120, 0008:2-121
Backup - FTRA 2.0, 0008:2-20
Backup - FTRA 2.0 or greater, 0008:2-16
Primary - FTRA 2.0, 0008:2-20
Primary - FTRA 2.0 or greater, 0008:2-16
IP Address - FTRA 1.0, 0008:2-20
IP Address Field
Backup - FTRA 2.0 or greater, 0008:2-16, 0008:2-20
Primary - FTRA 2.0 or greater, 0008:2-15, 0008:2-20
IP Address Field - FTRA 1.0, 0008:2-15, 0008:2-20
Modify button, 0008:2-16, 0008:2-36, 0008:2-37
Refresh button, 0008:2-16, 0008:2-23, 0008:2-25, 0008:2-27, 0008:2-29, 0008:2-39
Secure Connection Box - FTRA 2.0 or greater, 0008:2-17, 0008:2-22, 0008:2-38, 0008:2-43, 0008:2-48, 0008:2-49
Select button, 0008:2-16, 0008:2-27
STP Name drop down list, 0008:2-16, 0008:2-23
FTRA 1.0, 0008:2-23, 0008:2-25
FTRA 2.0, 0008:2-23, 0008:2-24, 0008:2-25, 0008:2-26
STP Name Field, 0008:2-4, 0008:2-15, 0008:2-16, 0008:2-18, 0008:2-23, 0008:2-27
STP name typed
FTRA 1.0, 0008:2-27
FTRA 2.0, 0008:2-27, 0008:2-28
STP Password Field, 0008:2-16, 0008:2-21
STP UserName Field, 0008:2-16, 0008:2-20
Test button, 0008:2-16, 0008:2-25, 0008:2-27, 0008:2-31
Use STP and FTP UserNames, Passwords for all STPs Box, 0008:2-17, 0008:2-18, 0008:2-36, 0008:2-37, 0008:2-38
STP Connectivity Test, 0008:2-1
STP Data Modified window, 0008:2-37, 0008:2-39
STP LAN, 4802:1-17
STP LAN Feature (EAGLE 20.0), 4318:5-85
STP Name, 0008:2-15, 0008:2-16, 0008:2-17, 0008:2-18, 0008:2-22, 0008:2-23, 0008:2-24, 0008:2-25, 0008:2-27, 0008:2-30, 0008:2-36, 0008:2-40, 0008:2-41, 0008:2-42
entering, 0008:2-27
STP Name does not exist error message, 0008:2-30
STP Name drop down list, 0008:2-16, 0008:2-23
FTRA 1.0, 0008:2-23, 0008:2-25

FTRA 2.0, 0008:2-23, 0008:2-24, 0008:2-25, 0008:2-26
STP Name Field, 0008:2-4, 0008:2-15, 0008:2-16, 0008:2-18, 0008:2-23, 0008:2-27
STP name typed
FTRA 1.0, 0008:2-27
FTRA 2.0, 0008:2-27, 0008:2-28
STP options HMUXABUS or HMUXBBUS must be set=yes, 4801:2-798
STP pair replacement
multiple point code support, 4804:2-41
STP Password Field, 0008:2-16, 0008:2-21
STP Selection Change window, 0008:2-16, 0008:2-41, 0008:2-42
STP System Totals (SYSTOT) Measurements, 4593:4-14
STP True PC and EIR subsystem do not exist in MAP table, 4801:2-847
STP True PC and INP SSN do not exist in MAP table, 4801:2-764
STP True PC and LNP SSN do not exist in MAP table, 4801:2-538
STP True PC does not exist in MAP table, 4801:2-537
STP UserName Field, 0008:2-16, 0008:2-20
STPLAN
LNP—Impact of LNP on Other Features (22.0), 4318:4-65
STPLAN capacity normal, card(s) abnormal, 4593:3-234
STPLAN connection available, 4593:3-240
STPLAN connection unavailable, 4593:3-238
STPLAN is available, 4593:3-233
STPLAN is removed, 4593:3-237
STPLAN not available, 4593:3-236
STPLAN Port to DCM (EAGLE 26.0), 4318:5-87
hardware requirements, 4318:5-87
STPLAN with Default Router (EAGLE 23.0), 4318:5-88
changed commands, 4318:5-90
STPOPTS HMUXTVG must be turned on for this feature, 4801:2-590
Stratum-3 (ST3), 4625:3-139, 4625:3-143
strict host key checking, 0008:2-44
strict host key flag, 0008:2-44
String Data Dump, 4593:3-690, 4593:3-734
String pattern nonconformance, alphabetic - <parm>, 4801:2-19
String pattern nonconformance, alphanumeric - <parm>, 4801:2-19
String pattern nonconformance, numeric - <parm>, 4801:2-20
Subpath Field, 0008:2-50
subscription version, 4751:5-7
Subscriptions menu, 4307:3-41, 4307:3-49
Subsystem Application, 4802:3-57, 4802:3-61, 4802:3-62, 4802:3-63, 4802:3-64, 4802:3-66, 4802:3-67, 4802:3-68, 4802:3-73, 4802:3-74
Subsystem must be in opposite state of change, 4801:2-493
Subsystem must be inhibited before it can be deleted, 4801:2-494
Subsystem must be inhibited before it can be OFFLINE, 4801:2-493
Subsystem Number, 4318:4-85, 4802:1-17, 4802:3-57, 4802:3-58, 4802:3-64, 4802:3-85, 4802:3-86, 4802:3-102, 4802:3-103, 4802:3-116, 4802:3-117, 4802:3-130, 4802:3-137, 4802:3-139, 4802:3-154, 4802:3-155
Subsystem number not in LNP database, 4801:2-492
Subsystem Relative Cost (RC) must be less than its mate, 4801:2-428
Subsystem table for MPC is full, 4801:2-178
Subsystem table for primary remote point code is full, 4801:2-187
Success message, 4307:B-19
Sun Microsystem, 0008:2-7

Sun Microsystems, 0008:2-4, 0008:2-7
Sun StorEdge
D1000 Disk Systems, 1021:4-10
Sun Ultra
Enterprise 450 servers, 1021:4-10
Sun Ultra 5
standard hardware component, 1021:4-10
Support - contacting the Customer Care Center, 0007:2-4
Support 12 Million Ported Numbers (EAGLE 24.0), 4318:5-91
LNP DB Audit — End of Audit Report, 4318:5-92
Support 12 Million Ported Numbers (EAGLE 25.0), 4318:5-92
Support Changing the Linkset Name, 4318:5-94
Support for LSMS Audit Enhancements (EAGLE 26.1
limitations, 4318:5-103
Support for LSMS Audit Enhancements (EAGLE 26.1), 4318:5-96, 4318:5-102
Auditing the Eagle via High-Speed Audit, 4318:5-97
component interaction scenario, 4318:5-98
new commands, 4318:5-98, 4318:5-102
over OAP serial channel, 4318:5-102
via enhanced bulk download, 4318:5-102
Support for Matching Self-ID Rule in SEAS CHG-SID (EAGLE 22.0), 4318:5-103
Support for Provisioning Multiple EPAPs (Release 29.0), 4318:5-105
Support for Secure Gateway Functionality through IP7 7.0 (Release 29.0), 4318:5-105
Support for the CLLI Parameter for Adding or Changing Linksets (EAGLE 22.0), 4318:5-106
Support for the New Linkset Name Parameter for Changing the Attributes of a Route (EAGLE 22.0), 4318:5-106
Support for Up to 41 IPLIMx DCMs (IP7 2.2), 4318:5-107
Support LSMS Disaster Recovery (EAGLE 23.1), 4318:5-108
auditing OAP database, 4318:5-108
Support of E1 Interface for SS7 Signaling Links (Optional) (EAGLE 22.2), 4318:5-108
Support of E1 Interface for SS7 Signaling Links (Optional) (EAGLE 24.0), 4318:5-109
upgrade considerations, 4318:5-109
Support of E1 Master Clock Interface for SS7 Signaling Links (Optional) EAGLE 22.2), 4318:5-109
support, technical
e-mail address, 4625:1-15
telephone numbers, 4625:1-15
Suppression of Gateway Measurements on Non-Gateway Linksets (EAGLE 25.0), 4318:5-109
SVC-Automatic, 0004:2-4, 4318:5-173
SVC-Incoming, 0004:2-4
SVCR, 4318:5-173
Swap Space, 2712:3-13, 4593:6-6
Swap Space Alarm, 4593:6-8
switch
replace, 2969:7-4
switchover operation, 4318:5-11
switchover, ELAP
Active/Standby, 4307:2-5
sync, 0003:3-144, 0003:3-151
Sync network, ELAP
configure IP addresses, 4307:5-19
description, 4307:2-4, 4307:2-8
IP addresses, 4307:2-8

syntax checking, 4307:3-11
Syntax Error Found, 4801:2-698
SYS, 4802:1-17
syscheck, 2712:3-8, 4593:6-3
    running
        using the GUI, 2712:A-6
        using the syscheck login, 2712:A-8, 4593:6-38
syscheck log files, 4593:6-20, 4593:6-21
syscheck, overview, 2712:3-12
system administration procedures, 0002:4-1
System Administrator's Guide, 4625:1-12, 4626:1-15
System Alarm Levels, 4593:3-3
System busy - Repeat later, 4801:2-422
System busy - try again later, 4801:2-148
System Clock, 1021:3-12, 4625:2-15
system clock and date
    setting, 0002:4-3
system clock connectors, 4625:3-26, 4625:3-32
system clocks
    High Speed Master Timing (26.0), 4318:3-56
system environment variable, 0008:2-6
System error - revert to mandatory in-pattern specification, 4801:2-20
System error - software - an attempted buffer overrun has been detected by the SEAS UPL parser (C<col>), 4801:2-554
system fan replacement procedure, 4593:6-124
System Ground, 4601:4-16
system hardware verification, DSM, 4307:4-6
System Health Check
    status and alarm reporting, 4307:4-2
System Health Check Log Files, 4593:6-21
System Health Check Procedure, 4593:6-36
System IP TPS normal, 4593:3-206
System IP TPS threshold exceeded, 4593:3-201
System Log, 0008:2-11, 0008:2-97, 0008:2-98, 0008:2-99, 0008:2-100, 0008:2-101
    Clearing the Display, 0008:2-97, 0008:2-98
    closing, 0008:2-97, 0008:2-101
    Print window, 0008:2-99
    Printing, 0008:2-97, 0008:2-99
    Save window, 0008:2-100, 0008:2-101
    saved file confirmation window, 0008:2-101
    saving to a file, 0008:2-97, 0008:2-100
System Log window, 0008:2-97, 0008:2-98, 0008:2-99, 0008:2-100, 0008:2-101
    Cancel button, 0008:2-99
    File menu, 0008:2-97, 0008:2-98
System Maintenance, 4802:1-17
System maintenance log, 4593:1-15
System Maintenance Unsolicited Output Message Group, 4593:D-2
System Meas limit exceeded for LSONISMT, 4593:3-643
System Meas. Limit exceeded for LRN, 4593:3-960
System Meas. Limit exceeded for LSDESTNI, 4593:3-648
System Meas. Limit exceeded for LSORIGNI, 4593:3-647
System Meas. Limit exceeded for NPANXX, 4593:3-961

System Meas. Limit exceeded for ORIGNI / NINC, 4593:3-649
system operation, 4593:6-3
System Overview, 4601:1-14, 4626:1-14
system problems, 4593:6-3
System release alarm cleared, 4593:3-222
System release GPL(s) not approved, 4593:3-223
System release version unknown, 4593:3-224
System Reports Analysis, 4593:2-17
system requirements
    48 Million Numbers (27.0), 4318:2-11
System SCCP TPS Capacity Exceeded, 4593:3-542
System SCCP TPS Threshold exceeded, 4593:3-423
system security
    command classes, 4800:4-17
    intrusion alert, 4800:4-18
    login security checks, 4800:4-17
System serial number entered is invalid, 4801:2-610
system serial number has not be locked, 4801:2-521
System serial number is already locked in database, 4801:2-611, 4801:2-630
System total reports, 4593:4-14
system unit
    front view, 4625:4-37

T

T<#> (domain) must be between <min> and <max>, 4801:2-416
T1 4-link monitor configuration window, 4625:B-3
T1 card location is unequipped, 4801:2-322
T1 is assigned to card, 4801:2-323
T1 MIM, 0004:6-7
T1 monitor applique, 4625:B-2
T1 TS value must be specified in the range (0-23), 4801:2-326
T-1000, 1021:5-1, 4625:5-3
T1100
    specifications, 2969:3-9
T1PORT specified by T1LOC is not equipped, 4801:2-324
Table copy command already in process, 4801:2-11
Table Expansion
    XGTT, 0006:2-43, 0006:2-47, 0006:2-48, 0006:2-49, 0006:3-27, 0006:4-32, 0006:4-33, 0006:A-17, 0006:A-18, 0006:A-19, 0006:A-20, 0006:A-21, 0006:A-23, 0006:A-24, 0006:A-25, 0006:A-26, 0006:A-39
    XGTT - Enabling, 0006:A-17
    XMAP, 0006:2-43, 0006:2-46, 0006:2-48, 0006:2-49, 0006:2-85, 0006:2-121, 0006:A-27, 0006:A-28, 0006:A-29, 0006:A-30, 0006:A-31, 0006:A-33, 0006:A-34, 0006:A-35, 0006:A-39
    XMAP - Enabling, 0006:A-27
Table full - a maximum of 256 TYPE=SD MICs are allowed, 4801:2-454
Table is full, no more entries allowed, 4801:2-345
TALI “A” Link Connectivit, 4318:5-110
TALON Development Kit, Release 2.0 (IP7 2.0), 4318:5-114
Tape, 4625:4-35
tape drive
    capacity for file system backups, 4593:6-17

description, 4625:4-29
for database and file system backups, 4593:6-17
periodic maintenance, 4593:6-17
replacement procedure, 4593:6-124
specification, 4625:4-27
speed for file system backups, 4593:6-17
Target bus must be inhibited, 4801:2-445
Target card is not a DSM card with VSCCP appl, 4801:2-876
Target card is not in Active state, 4801:2-876
Target drive capacity must be sufficient to perform request, 4801:2-646
Targeted Boards, 4626:1-23
Task Scheduler
Windows, 0008:2-73, 0008:2-75
TCAP, 0004:1-2, 0004:2-2
TCOA, 4601:A-32
TCP Out of Order, 0008:2-122
TCP Packet Delay, 0008:2-122
TCP Packet Error, 0008:2-122
TCP Packet Errors, 0008:2-122
TCP Packet Loss, 0008:2-122
TCP/IP data link, 4318:5-10
TCP/IP link assigned to card, 4801:2-271
TCP/IP Link Provisioning, 0004:6-5
TCP/IP parameters, 0002:4-152
TDM, 0002:A-15, 0008:2-3, 4601:2-5, 4625:3-18, 4625:3-21, 4625:3-37, 4626:1-34, 4802:1-18, 4802:2-19, 4802:2-26
TDM card
as part of MASP, 4800:4-2
connection of terminals and printers to, 4800:4-5
TDM does not support Global Timing Interface, 4801:2-317
TDM technical specifications, 4625:3-54
TDM-GTI, 4601:2-5
Technical Assistance - contacting the Customer Care Center, 0007:2-4
Technical Assistance Centers, 4593:1-8
Technical Bulletins, 4601:1-14, 4626:1-14
Technical Reference Documents, 4625:1-13, 4626:1-16
Technical Services, 4601:1-18, 4625:1-15
Technical services, 4751:1-11, 4802:1-8
technical services, 0002:1-6, 0003:1-7, 0004:1-8, 0005:1-8, 0006:1-6, 4803:1-9, 4804:1-6
Technical Services - Tekelec, 0008:2-3, 0008:2-4, 0008:2-46, 0008:2-103, 0008:2-104, 0008:2-105, 0008:2-106, 0008:2-107, 0008:2-108, 0008:2-109, 0008:2-110, 0008:2-111, 0008:2-112, 0008:2-113, 0008:2-114, 0008:2-115, 0008:2-116, 0008:2-117, 0008:2-118
UK, 0008:2-3
USA, 0008:2-3
technical services and support, 2969:1-7
Technical Support, 4626:1-19
Tekelec 1000, 1021:1-6, 4625:4-11
Tekelec 1000 Applications Server, 1021:1-6, 1021:5-1, 4625:5-3
Tekelec 1000 APS, 4625:1-8, 4625:1-13
Tekelec 1100 AS main unit, replacement procedure, 2712:5-10
Tekelec Signaling Producsts Hardware Manual, 4625:1-13, 4626:1-16
Tekelec Signaling Products Installation-Eagle, 4601:1-14

Tekelec Signaling Products Integrated Applications Installation Manual, 4625:1-13, 4626:1-16
Tekelec Signalling Products Systems, 1021:1-2
Tekelec Technical Services, 0002:1-6, 0003:1-7, 0004:1-8, 0005:1-8, 0006:1-6, 0008:2-3, 0008:2-4, 0008:2-46, 0008:2-103, 0008:2-104, 0008:2-105, 0008:2-106, 0008:2-107, 0008:2-108, 0008:2-109, 0008:2-110, 0008:2-111, 0008:2-112, 0008:2-113, 0008:2-114, 0008:2-115, 0008:2-116, 0008:2-117, 0008:2-118, 4601:1-19, 4625:1-17, 4803:1-9, 4804:1-6
  e-mail address, 4625:1-15
  emergency response, 0002:1-7, 0003:1-7, 4318:1-9, 4626:1-21, 4751:1-11, 4804:1-7
  telephone numbers, 4625:1-15
  UK, 0008:2-3
  USA, 0008:2-3
TekServer, 1021:1-6
  Manual, 4626:1-10
TekServer Fan Orientation Wiring Diagram, 4626:C-83
TekServer Platform Services Hardware Manual, 4626:1-10
TekServer Services Platform, 4626:1-16
Telephone Number, 4318:4-85, 4802:1-18, 4802:3-110, 4802:3-137, 4802:3-138, 4802:3-139, 4802:3-146, 4802:3-147, 4802:3-148, 4802:3-149, 4802:3-153, 4802:3-154, 4802:3-156, 4802:3-162, 4802:3-163, 4802:3-164, 4802:3-176, 4802:4-2, 4802:4-4
TELNET cannot be specified unless the IPSM card is equipped, 4801:2-146
telnet client, 4318:3-123
TELNET Feature must be activated first, 4801:2-146
telnet server, 0008:2-43
telnet session, 4318:3-123
Telnet terminal connection successful, 4593:3-687, 4593:3-962
Telnet terminal type, 0002:4-55
Telnet terminal TYPE can only be set to TELNET or NONE, 4801:2-127
Telnet terminals, 0008:2-16, 0008:2-46, 0008:2-65
telnet terminals, 4800:4-6
Telnet to MPS, 4307:3-81
Temp Key(s) expiration alarm cleared, 4593:3-486
Temp Key(s) expiring soon, 4593:3-487
Temp Key(s) have expired, 4593:3-488
temperature requirements, 2969:2-6
temperature, checking, 2712:3-14
template, frame, 2969:4-4
Temporary Alarm Inhibiting and Offline Functions (EAGLE 25.0), 4318:5-114
  administration, 4318:5-119
  alarm system functionality, 4318:5-115
  changed commands, 4318:5-123
  customer use scenario, 4318:5-116
  maintenance, 4318:5-121
Temporary FAK Alarm
  Clearing, 0002:B-37, 0006:A-12
Temporary feature key is not allowed for the feature, 4801:2-474
temporary key is un-available, 4801:2-629
Ten GTA Lengths are supported per GTTSET, 4801:2-791
Ten GTA Lengths are supported per TT, 4801:2-791
Terminal already echoing to specified terminal, 4801:2-103
Terminal Authority Violation, 4801:2-3
terminal cable installation, 4601:5-107
Terminal Cables, 4601:5-107

terminal cables
    install, 4601:6-48
    route, 4601:6-49
terminal characteristics
    changing, 0002:4-51
terminal command class assignment
    changing, 0002:4-73
terminal configuration
    displaying, rtrv-trm, 0002:A-33, 0002:A-61, 4601:6-120, 4601:6-135
Terminal Disk Module, 4802:1-18
terminal disk module, 4802:2-26
Terminal Disk Module (TDM), 4593:A-51, 4601:5-81
terminal disk module See TDM card, 4800:4-2
Terminal enabled, 4593:3-135, 4593:3-963
Terminal failed, 4593:3-137, 4593:3-964
Terminal Id not entered, 4801:2-150
Terminal is currently inhibited, 4801:2-101
Terminal is currently out of service, 4801:2-102
Terminal is not equipped, 4801:2-151, 4801:2-162
Terminal Not Responding, 4593:3-65
Terminal Processor, 4625:3-52
Terminal temporarily disabled. Excessive LOGIN failures, 4801:2-333
Terminal temporarily disabled. Excessive UNLOCK failures, 4801:2-336
Terminal type
    EMSALM, 0002:4-56
    KSR, 0002:4-55
    MGMT, 0002:4-55
    None, 0002:4-55
    OAP, 0002:4-55
    Printer, 0002:4-55
    Telnet, 0002:4-55
    VT320, 0002:4-55
Terminals
    Eagle
        Telnet, 0008:2-16, 0008:2-46, 0008:2-65
terminals
    arrow key operations, 4800:4-12
    configuration of, 4800:4-3
    connection to TDM, 4800:4-5
    directing unsolicited messages to, 4800:4-15
    EMSALM, 4800:4-8
    telnet, 4800:4-6
    VT320, 4800:4-3
Terminals 1-16 cannot be set to TYPE=TELNET, 4801:2-129
Terminate Active Sessions, 4307:3-109
Termination of Alarm, 4601:5-85
terminology
    MPS, 2712:2-3
    Tekelec 1100 AS core platform, 2712:2-4
test
    fan operation, 4593:5-99, 4601:6-74
    fan operation (GR-376 EOAP), 4593:A-83

Test and Maintenance Features, 4625:3-98
Test button, 0008:2-16, 0008:2-25, 0008:2-27, 0008:2-31
Test Fan Operation and Fan Alarm, 4593:A-83
test mode, 4593:3-89
Testing an STP Configuration Record, 0008:2-31
testing diodes, 4593:2-8
text-based configuration, 4307:5-27
text-based UI, 4307:3-2, 4307:5-27
TFA/TFR pacing rate
  configuring, 4804:3-200
TFATCABMLQ is invalid for C-link sets, 4801:2-375
tfatcabmlq parameter, 4803:3-16, 4804:3-20, 4804:3-70, 4804:3-71, 4804:3-90, 4804:3-233, 4804:3-234, 4804:3-236
TFATCABMLQ value exceeds number of links in link set, 4801:2-372
TFATFRPR must be in increments of 100 msec, 4801:2-395
The address family is not supported - Error code 47, 0008:2-116
The address is already in use - Error code 48, 0008:2-116
The alarms are already inhibited for this device, 4801:2-572
The authentication method is NULL in the client software - Error code 632, 0008:2-108
The Channel card must be on the same shelf as its E1 card., 4801:2-810
The Channel card must be on the same shelf as its T1 card., 4801:2-319
The CNCF feature must be on if CNCF is specified, 4801:2-650
The connection timed out - Error code 60, 0008:2-117
The connection timed out when SSH tried to connect to SSHD - Error code 682, 0008:2-115
The connection was refused - Error code 61, 0008:2-117
The connection was reset by the peer - Error code 54, 0008:2-117
The current LSMS and the associated NSAP, PSEL and SSEL required, 4801:2-640
The debug levels allowed for SSH protocol in openSSH is 0-9 - Error code 624, 0008:2-107
The E1PORT at the specified location is already equipped, 4801:2-808
The E1PORT at the specified location is not equipped, 4801:2-808
The FEATURE / ANSIGFLEX option combination is invalid, 4801:2-885
The file name is already specified - Error code 596, 0008:2-104
The Gateway Linkset specified already exists, 4801:2-405
The Gateway Linkset table is full, 4801:2-403
The GSM MAP Screening table is full, 4801:2-755
The host is down - Error code 67, 0008:2-118
The host was not specified in the SSH client on the Eagle - Error code 659, 0008:2-111
The hostname was not specified in the SSH client on the Eagle - Error code 661, 0008:2-111
The last active serial port cannot be inhibited, 4801:2-593
The linkset is provisioned locally, 4801:2-404
The linkset specified does not exist in the linkset table, 4801:2-405
The linkset specified is not a Gateway Linkset, 4801:2-404
The maximum number of optional tables has been allocated, 4801:2-795
The maximum number of SPCs has already been defined, 4801:2-713
The maximum number of users is already defined, 4801:2-77
The MIM only supports SLTC loopbacks, 4801:2-323
The MPC feature must be ON before ITUDUPPC can be ON, 4801:2-743
The network channel is down - Error code 691, 0008:2-115
The network dropped the connection on reset - Error code 52, 0008:2-116
The network has reset - Error code 685, 0008:2-115
The network is down - Error code 62, 0008:2-118
The network is unreachable - Error code 51, 0008:2-116

The NONE value is not allowed in this case, 4801:2-599
The NSFI / RI combination is invalid, 4801:2-202
The NSFI is invalid for this screen type, 4801:2-204
The operation is not supported on the socket - Error code 45, 0008:2-116
The protocol family is not supported - Error code 46, 0008:2-116
The protocol is not available - Error code 42, 0008:2-116
The protocol is not supported - Error code 43l, 0008:2-116
The requested address cannot be assigned - Error code 49, 0008:2-116
The secure connection was closed by the remote server - Error code 669, 0008:2-112
The SFTP client failed to read the data from the file descriptor - Error code 616, 0008:2-106
The SFTP client received more data than expected - Error code 615, 0008:2-106
The SFTP connection is closed - Error code 598, 0008:2-104
The SFTP / SSH connection has been reset by the peer - Error code 687, 0008:2-115
The socket is already connected - Error code 56, 0008:2-117
The socket is not connected - Error code 57, 0008:2-117
The socket type is not supported - Error code 44, 0008:2-116
The SPC already exists, 4801:2-712
The specified card cannot be inhibited, 4801:2-154
The specified NPANXX is defined as a new split NPANXX, 4801:2-518
The specified overload level has already been defined, 4801:2-458
The specified overload level is not defined, 4801:2-448
The specified SLC is in use, 4801:2-45
The specified user identification is already defined, 4801:2-76
The specified user identification is not defined, 4801:2-77
The SSH client key length is invalid - Error code 667, 0008:2-111
The SSH client was unable to load the cipher type on the Eagle - Error code 663, 0008:2-111
The SSH connection was refused by the remote server - Error code 683, 0008:2-115
The SSH / SFTP client on the Eagle failed to read from the remote side - Error code 674, 0008:2-113
The SSH / SFTP client on the Eagle failed to write to the remote side - Error code 679, 0008:2-114
The SSH / SFTP connection has been aborted - Error code 686, 0008:2-115
The SSH / SFTP socket is already connected - Error code 689, 0008:2-115
The SSH / SFTP socket is not connected - Error code 690, 0008:2-115
The SSHD server is unreachable - Error code 684, 0008:2-115
The SSHD / SFTP server connection host is down - Error code 692, 0008:2-115
The sum of the values for NPCFMTI must be equal to 14, 4801:2-623
The T1PORT at the specified location is already equipped, 4801:2-319
The T1PORT at the specified location is not equipped, 4801:2-321
The terminal state request was unanswered, 4801:2-49
Theory of Operation, 1021:3-14
There is a link already assigned to this port, 4801:2-45
There is no route to the host - Error code 65, 0008:2-118
third-party software
    Embedded OAP (24.0), 4318:2-138
This command is not valid when EGTT is ON, 4801:2-614
This function is not yet supported, 4801:2-197
THRES parameter valid only with CONVERTNET / CONVERTSTP, 4801:2-576
Thresholding of UIM Messages (EAGLE 25.0), 4318:5-124
    Changed Event Log Command, 4318:5-127
    creation of UIMs, 4318:5-124
    limitations, 4318:5-128
    new database administration commands, 4318:5-127
    upgrade considerations, 4318:5-127

Tie-wrap, 4601:4-16
Time Slot Counter, 0004:6-6
Time Slot Counter Synchronization, 1021:3-14, 0004:6-6, 0004:6-10, 0004:6-11, 4625:2-18
Time Stamping, 0004:6-6
time zone
    select for ELAP, 4307:5-21
    UNIX files, 4307:1-2, 4307:5-21, 4307:A-1
Timeout, 4801:2-443
timers
    default values, 4804:3-23
Timeslot 16 on the E1 is in use, CAS = ON not allowed, 4801:2-809
Timestamp Invalid, 4593:3-584
Timestamp Valid, 4593:3-585
Timing, 4625:3-115
Timing Systems Eagle STP / IP7 SG, 1021:3-12, 4625:2-15
tinned ground, 4601:4-16
TLNP and CNCF cannot be in the same action set, 4801:2-656
TLNP and RDCT cannot be in the same action set, 4801:2-655
TLNP feature must be ON, 4801:2-655
TM Adaptation Layer Type 5 Common Part, 4593:1-17
TMOUT, 4802:1-18
TN, 4802:1-18, 4802:3-44, 4802:3-82, 4802:3-97, 4802:3-126, 4802:3-127, 4802:3-137, 4802:3-139, 4802:3-141, 4802:3-145, 4802:3-149, 4802:3-151, 4802:3-154, 4802:3-156, 4802:3-157, 4802:3-161, 4802:3-179, 4802:3-180
TN does not exist, 4801:2-522
TN range must not cross an NPANXX boundary, 4801:2-520
TN range must not overlap existing TN or TN ranges, 4801:2-521
TN ranges are not currently supported, 4801:2-478
To change or delete SERV, it must have no LNP aliases, 4801:2-511
To disable CRITALMINH, critical alarms cannot be inhibited, 4801:2-572
TOCA, 4601:2-5, 4601:5-109, 4625:3-139, 4625:3-143, 4626:1-34
TOCA Card, 4625:3-144
TOLA Card, 4601:5-109
Too many associations per card, 4801:2-823
Too many associations per SLK, 4801:2-822
Too many errors in this command, 4801:2-5
Too many IP connections per card, 4801:2-686
Too many nested cluster dstn entered, 4801:2-360
Too many octets specified, only require 4 - <parm>, 4801:2-17
too many parameters entered, 4801:2-419
Too many parameters specified for <parm> block (C<col>), 4801:2-546
Too many references: can’t splice - Error code 59, 0008:2-117
Too many sockets per SLK, 4801:2-694
tools and equipment
    EOAP shelf, 4601:6-15, 4601:6-22, 4601:6-60, 4601:6-64, 4601:6-65
tools required for FRU replacement, 2969:7-4
tools, recommended
    installing heavy duty frame, 2969:4-3
    to install heavy duty frame, 2969:4-3
Total Ethernet Capacity is greater than 100% for IP Node, 4801:2-264
Total IPTPS for all linksets can't exceed system TPS limit, 4801:2-875
traceroute, 4800:9-115

Traffic Measurements
Measurement periods, 4593:4-13
Transaction Services Module (TSM), 4625:3-99
transition card, 4593:5-24
Translate Indicator, 4802:1-18, 4802:3-85, 4802:3-87, 4802:3-102, 4802:3-103, 4802:3-116, 4802:3-117, 4802:3-130, 4802:3-137, 4802:3-139, 4802:3-154, 4802:3-155
Translation, 4625:3-20
Translation PC is Eagle's, 4593:3-947
Translation PC type is ANSI, 4593:3-948
Translation Service Module (TSM), 4625:3-19
Translation Service Modules (TSMs), 4625:3-9, 4625:3-18, 4625:3-28
Translation Services Module, 1021:3-10, 4625:2-14
translation services module, 4802:2-26
Translation Type, 4318:4-84, 4802:1-18, 4802:3-30, 4802:3-31, 4802:3-33, 4802:3-41, 4802:3-42, 4802:3-48, 4802:3-49, 4802:3-85, 4802:3-87, 4802:3-95, 4802:3-96, 4802:3-102, 4802:3-103, 4802:3-116, 4802:3-117, 4802:3-125, 4802:3-130, 4802:3-131, 4802:3-137, 4802:3-139, 4802:3-140, 4802:3-149, 4802:3-150, 4802:3-154, 4802:3-155, 4802:3-156, 4802:3-176, 4802:3-177
Translation TYPE already exists, 4801:2-192
Translation TYPE defined as an alias, 4801:2-192
Translation TYPE has an alias, 4801:2-195
Translation Type is already in LNP database, 4801:2-487
Translation Type is not in LNP database, 4801:2-489
Translation Type is not reserved for LNP, 4801:2-502
Translation TYPE is referenced by GTT entry, 4801:2-195
Translation type mapping, 0006:2-40, 0006:2-44, 0006:3-2, 0006:4-2
translation type mapping
LNP—Impact of LNP on Other Features (22.0), 4318:4-65
Translation Type Mapping (EAGLE 21.0), 4318:5-128
new commands, 4318:5-130
Translation TYPE must be specified, 4801:2-196
Translation Type Name, 4802:1-18, 4802:3-30, 4802:3-31, 4802:3-48
Translation Type Name is not in the LNP database, 4801:2-491
Translation Type referenced in LNP database, 4801:2-490
Translation TYPE specified does not exist, 4801:2-193
Translation Type value specified more than once, 4801:2-496
Translation TYPEI already exists, 4801:2-757
Translation TYPEI specified does not exist, 4801:2-760
Translation TYPEN already exists, 4801:2-757
Translation TYPEN specified does not exist, 4801:2-759
Translation TYPEN24 already exists, 4801:2-600
Translation TYPEN24 specified does not exist, 4801:2-756
Translation Types, 0006:3-2
trapcomm, 0003:3-151
TRBL Queue is full, 4593:3-755
Triggerless LNP (EAGLE 24.0), 4318:5-130
commands, 4318:5-130
TRM must be specified, 4801:2-420
TRM parameter
chg-trm, 0002:A-15
TRM parameter not valid for type-enttype combo, 4801:2-118
Trouble Detection, 4593:3-4
troubleshoot

CD-ROM drive
power cable, 4593:5-8
hard drive card, 4593:5-8
power cable
hard drive, 4593:5-8
power supply card, 4593:5-7, 4593:5-18
processor card, 4593:5-7, 4593:5-20
troubleshooting, 4593:6-3
Troubleshooting Log Files, 4593:6-20
Troubleshooting Procedures, 0008:2-119
True PC already exists in MAP table, 4801:2-539
true point code, 4804:2-2
True Point Code can only have one mate, 4801:2-431
True Point Code may not be routed to self, 4801:2-431
Try Double Quoting Parameter with '_', 4801:2-28
TS value on the E1 already in use by a signaling link, 4801:2-807
TS value on the T1 already in use by a signaling link, 4801:2-325
TSC, 0004:6-6
TSC Synchronization, 0004:6-6
TSCSYNC must be ON before E5IS can be ON, 4801:2-778
TSET parameter only valid if MODE = DCE, 4801:2-46
TSM, 4318:4-58, 4601:2-5, 4601:B-20, 4625:3-21, 4625:3-37, 4626:1-34, 4626:B-4, 4802:2-26
TSM Warm Restart and Incremental Loading (EAGLE 26.0), 4318:5-131
changed commands, 4318:5-142
dependencies, 4318:5-145
hardware requirements, 4318:5-144
incremental loading, 4318:5-133
limitations, 4318:5-145
LNP audit, 4318:5-140
maintenance, 4318:5-134
new UIMs, 4318:5-142
upgrade considerations, 4318:5-144
warm restart, 4318:5-132
tst-bip, 4800:7-589
tst-disk, 4800:7-590
tst-dlk, 4800:7-594
tst-imt, 4800:7-595
tst-slk, 4800:7-597
tst-slk command, 4593:3-80
tst-slk Support, 4593:3-80
TT, 4802:1-18, 4802:3-30, 4802:3-32, 4802:3-33, 4802:3-37, 4802:3-41, 4802:3-42, 4802:3-43, 4802:3-44, 4802:3-45, 4802:3-48, 4802:3-49, 4802:3-52, 4802:3-53, 4802:3-81, 4802:3-82, 4802:3-85, 4802:3-87, 4802:3-88, 4802:3-89, 4802:3-91, 4802:3-92, 4802:3-95, 4802:3-96, 4802:3-97, 4802:3-98, 4802:3-102, 4802:3-104, 4802:3-107, 4802:3-111, 4802:3-116, 4802:3-118, 4802:3-119, 4802:3-120, 4802:3-122, 4802:3-125, 4802:3-126, 4802:3-127, 4802:3-130, 4802:3-132, 4802:3-134, 4802:3-137, 4802:3-139, 4802:3-141, 4802:3-142, 4802:3-143, 4802:3-145, 4802:3-149, 4802:3-151, 4802:3-154, 4802:3-156, 4802:3-157, 4802:3-158, 4802:3-159, 4802:3-161, 4802:3-176, 4802:3-178, 4802:3-179, 4802:3-180, 4802:3-182
TT and RMV parameters are not compatible, 4801:2-507
TT is not assigned, 4801:2-500
TT is not assigned to the LRN, 4801:2-512
tt map table full for LSN specified, 4801:2-363

tt map table is full, 4801:2-363
TT Mapping is not provisioned for this link set, 4801:2-364
TT must be specified if PC is specified, 4801:2-458
TT must be specified when enttype=tt, 4801:2-109
TT or RMV parameter is required when GTT exists, 4801:2-507
TT parameter valid only when ENTTYPE=TT, 4801:2-119
TT service must be assigned to the TN, 4801:2-508
TT values for AIN or IN LNP Query services are not allowed, 4801:2-526
TT values for AIN, IN, PCS or WNP Query service are not allowed, 4801:2-652
TT values for PCS Query services are not allowed, 4801:2-525, 4801:2-799
TT values for WNP Query services are not allowed, 4801:2-525
TT, TTN, & DV parameters are not allowed with ALIAS, 4801:2-507
TTA cannot be specified for a direction of ITOA, 4801:2-831
TTA must be specified for a direction of ATOI, 4801:2-801
TTDM card
  High Speed Master Timing (26.0), 4318:3-58
TTI must be specified for a direction of ITOA, 4801:2-832
TTI, NP, NAI cannot be specified for a direction of ATOI, 4801:2-889
TTN, 4802:1-18, 4802:3-30, 4802:3-31, 4802:3-32, 4802:3-33, 4802:3-37, 4802:3-42, 4802:3-45, 4802:3-49, 4802:3-52, 4802:3-53, 4802:3-89, 4802:3-120, 4802:3-132, 4802:3-142, 4802:3-158, 4802:3-180
TTN already in use, 4801:2-193
TTN and TYPE do not correspond to each other, 4801:2-196
TTN specified does not exist, 4801:2-193
TUP must use DPC/SI route key if DPC is ANSI, 4801:2-739
turn off
  controlled features, 4800:5-83
  LNP ELAP Configuration feature, 4800:5-84
Turn off EISCOPY before changing PVN and PVNMask, 4801:2-636, 4801:2-811
turn on
  controlled features, 4800:5-83
  LNP ELAP Configuration feature, 4800:5-84
  LNP feature, 4800:6-122
Turning Off the IGTTLS Feature, 0006:A-14
turning On and Off Controlled Features, 0003:6-10
TVG granter failed, 4593:3-386
TVG granter recovered (Eagle system), 4593:3-388
two hole lug, 4601:4-8
Two OAP terminals are already configured, 4801:2-349
Two-Point IPLIMx (Eagle 27.1), 4318:5-153
  enhanced commands, 4318:5-153
TXCO, 4625:3-143
TYPE, 4802:2-19, 4802:4-5, 4802:4-21, 4802:4-22, 4802:4-24, 4802:4-25, 4802:4-28, 4802:4-29, 4802:4-31, 4802:4-32, 4802:4-33
TYPE = SCCS and PRTY=NONE combination not allowed, 4801:2-53
TYPE = VT320 and PRTY=NONE combination not allowed, 4801:2-49
TYPE and SNUM/ENUM combination invalid, 4801:2-859
TYPE does not exist in given SR, 4801:2-244
TYPE matches existing TYPE in given SR, 4801:2-244
Type of Service, 0003:2-37
TYPE parameter
  chg-trm, 0002:A-15
types of networks, 4804:2-2

Types of Routing Strategies Available
Applications, 4318:4-167
Changed Commands, 4318:4-174
MTP Requirements, 4318:4-168
Network Routing (EAGLE 26.0), 4318:4-167

U

UAM 0368, 0007:2-161
UAM 0429, 4751:8-4
UAM 0431, 4751:8-4
UAM Troubleshooting Procedures, 4593:3-89
UAMs
alarm categories, 4307:4-15
clearing alarm, 4307:4-15
ELAP application, 4307:4-15
ELAP-DSM, 4307:4-16
MPS platform, 4307:4-15
RTDB Audit, 4307:4-16
ublk-slk, 4800:7-602
UDP echo, 0004:3-14
UDT message, 4318:5-20
UID, 4802:1-18
UIM, 4318:5-20
UIM - Unsolicited Information Message
Eagle, 0008:2-46, 0008:2-47, 0008:2-65
UIM 1493, 0008:2-46, 0008:2-47
UIM 1494, 0008:2-46, 0008:2-47
UIM number does not exist in STP Trouble Text Table, 4801:2-638
UIM number does not exist in UIM Threshold table, 4801:2-523
UIM Redirect Unsolicited Output Message Group, 4593:D-26
UIM threshold
configuring, 0002:4-129
UIM Troubleshooting Procedures, 4593:3-89
UIMs
ITU MTP Restart (26.0), 4318:3-153
ITU-TFR Procedure (26.1), 4318:3-156
Multiple Point Code Support (EAGLE 26.05), 4318:4-143
Unable to access database. Severe database failure, 4801:2-172
Unable to access DB level, 4801:2-35
Unable to change adapter when already associated to an ASP, 4801:2-821
Unable to change Network/Cluster dstn NCAI param, 4801:2-361
Unable to communicate with card at location, 4801:2-106
Unable to determine current connect status of card <card>, 4801:2-422
Unable to read the selected log, 4801:2-408
Undefined, 4801:2-890
Undefined - Error code 601, 0008:2-105
Undefined SFTP/SSH error - Error code 643, 0008:2-109
Unexpected character(s) <data> after <parm> (C<col>), 4801:2-545
Unexpected disk access timeout, 4593:3-733
Unexpected response message error, 4801:2-732
Unexpected SSH_FXP_NAME - Error code 611, 0008:2-105

unexpected SSH_FXP_NAME - Error code 614, 0008:2-106
Unexpected SSH_FXP_STATUS error - Error code 644, 0008:2-109
Unexpected SSH2_FXP_ATTRS - Error code 610, 0008:2-105
unhb-alm, 4800:7-604
unhb-slk, 4800:7-608
Unistrut, 4601:3-19
Unistrut Overhead, 4601:3-24
unit separator bracket, 4601:3-26
universal time coordinated, 2712:2-17
UNIX
    time zone files, 4307:1-2, 4307:5-21, 4307:A-1
Unix Workstation Requirements, 0008:2-2
Unknown cipher number on the SSH client on the Eagle - Error code 666, 0008:2-111
Unknown command, 4801:2-152
Unknown hardware configuration, 4801:2-523
Unknown LSN, 4801:2-122
unlock, 4800:7-609
Unneeded information found, 4801:2-22
unpacking, 4601:3-4
unpacking frame, 2969:4-2
Unrecognized command, 4801:2-6
Unrecognized parameter identifier, 4801:2-8
Unsolicited Alarm Messages, 4593:3-12
Unsolicited Information Messages, 4307:4-14, 4593:3-27
    Calling Name Conversion Facility (CNCF) (23.1), 4318:2-57
unsolicited messages
    definition, 4800:4-15
    output groups, 4800:4-15
Unsolicited Output Message Groups
    Application Subsystem, 4593:D-15
    Card, 4593:D-12
    Clock, 4593:D-22
    Database, 4593:D-26
    GTT, 4593:D-18
    GWS, 4593:D-20
    Link Maintenance, 4593:D-6
    LNP Database, 4593:D-24
    LNP Subscription, 4593:D-25
    Measurements Maintenance, 4593:D-23
    Monitor, 4593:D-27
    MPS, 4593:D-26
    Program Update, 4593:D-25
    SEAS Maintenance, 4593:D-28
    Security Administration, 4593:D-25
    SLAN, 4593:D-28
    System Maintenance, 4593:D-2
    UIM Redirect, 4593:D-26
unstable loading mode, DSM, 4307:4-8
Unsupported value - Error code 35, 0008:2-118
Un-uploaded security log entries exist on standby fixed disk, 4801:2-436
UOUT, 4802:1-18
Up to 8 SS7IPGW or IPGWI links allowed in un-mated linkset, 4801:2-864

Update Commands, 4307:B-2
Update EOAP
Method A, 0002:A-42, 0002:A-69, 4601:6-129, 4601:6-144
Method B, 0002:A-45, 0002:A-72, 4601:6-132, 4601:6-147
update EOAP configuration, 0002:A-42, 0002:A-69, 4601:6-129, 4601:6-143
Update LNP 10-Digit Subscription, 4307:B-2
Update LNP Location Routing Number, 4307:B-8
Update LNP NPANXX, 4307:B-5
Update LNP Subscription, 4307:3-49
Update NPA-NXX Records, 4307:3-53
Update NPA-NXX Split Records, 4307:3-58
Update Override GTT Records, 4307:3-55
Update Split NPANXX, 4307:B-12
Update Tables Log, 0008:2-11, 0008:2-77, 0008:2-78, 0008:2-81, 0008:2-82, 0008:2-83, 0008:2-84, 0008:2-87, 0008:2-88, 0008:2-89, 0008:2-90, 0008:2-91, 0008:2-92, 0008:2-93, 0008:2-94, 0008:2-95
Clearing the Display, 0008:2-92, 0008:2-93
closing, 0008:2-92, 0008:2-96
Print window, 0008:2-94
Printing, 0008:2-92, 0008:2-94
Save window, 0008:2-95, 0008:2-96
saved file confirmation window, 0008:2-96
saving to a file, 0008:2-92, 0008:2-95
Update Tables Log window, 0008:2-82, 0008:2-88, 0008:2-92, 0008:2-93, 0008:2-94, 0008:2-95, 0008:2-96
Commit Command Completed, 0008:2-88
File Menu, 0008:2-92
File menu, 0008:2-92, 0008:2-93
Processing Retrieve Request, 0008:2-82
Update Tables processing completed without errors message, 0008:2-87
Update Tables window, 0008:2-4, 0008:2-77, 0008:2-78, 0008:2-79, 0008:2-80, 0008:2-81, 0008:2-86, 0008:2-87, 0008:2-90, 0008:2-91, 0008:2-92
Browse button, 0008:2-78, 0008:2-79
Close button, 0008:2-78
Command File, 0008:2-81
Command File field, 0008:2-79, 0008:2-80, 0008:2-82
Command File Selected, 0008:2-79
description, 0008:2-78
Select window, description, 0008:2-80
Update Validation Complete window, 0008:2-77, 0008:2-82, 0008:2-83, 0008:2-84, 0008:2-85, 0008:2-86
with errors, 0008:2-84
Validate button, 0008:2-77, 0008:2-78, 0008:2-82
Update Validation Complete window, 0008:2-77, 0008:2-82, 0008:2-83, 0008:2-84, 0008:2-85, 0008:2-86
description, 0008:2-83
with errors, 0008:2-84
without errors, 0008:2-84
Updates, 4601:1-16
Updates allowed
loading stability, 4593:3-951
Updates inhibited
loading stability, 4593:3-950
updates, documentation, 4307:1-6
updating

EOAP, 0002:A-27, 4601:6-114
Updating Database Tables in the Selected STP, 0008:2-77
Updating the EOAP, 4601:6-117
upgrade, 2712:2-12
upgrade considerations
, 4318:2-151
48 Million Numbers (27.0), 4318:2-12
Eagle Application Support for E1 (26.3), 4318:2-107
Enhanced Bulk Download (25.0), 4318:2-149
Enhanced GTT (26.0), 4318:2-153
G-Port MNP (26.2), 4318:3-25
Group Ticket Voucher for SCCP Cards (27.0), 4318:3-42
GSM MAP Screening (26.1), 4318:3-43
GTT by TT Measurements and GR-376 Enhancements (26.0), 4318:3-50
ITU MTP Restart (26.0), 4318:3-152
ITU SLS Enhancements (26.0), 4318:3-155
ITU-TFR Procedure (26.1), 4318:3-156
Large System (27.2), 4318:4-3
LNP Measurements Enhancements (25.0), 4318:4-51
LRN Table Increase (26.1), 4318:4-108
Multiple Point Code Support (EAGLE 26.05), 4318:4-143
Multi-Port LIM (EAGLE 27.1), 4318:4-147
Nested Cluster Routing (EAGLE 26.0), 4318:4-165
Number Pooling/Efficient Data Representation (EDR) (EAGLE 26.1), 4318:4-195
Security Log Increase (EAGLE 26.05), 4318:5-72
Stand-alone Eagle G-Flex Relay Function, 4318:3-18
Support of E1 Interface for SS7 Signaling Links (Optional) (EAGLE 24.0), 4318:5-109
Thresholding of UIM Messages (EAGLE 25.0), 4318:5-127
TSM Warm Restart and Incremental Loading (EAGLE 26.0), 4318:5-144
Variable Length GTT (Eagle 26.1), 4318:5-165
Weighted SCP Load Balancing (Eagle 27.2), 4318:5-170
upgrade procedure
High-Speed Multiplexer (HMUX) (27.2), 4318:3-65
Upgrade Procedure Enhancements (Eagle 22.0), 4318:5-156
No Reportable Downtime on Network Restart, 4318:5-157
Upgrade Procedures, 4601:1-14, 4626:1-14
Upgrading the Application Processor of the Main Assemblies from the Intel 286/386 to the Intel 486 Microprocessor (Eagle 20.0), 4318:5-159
Use DFILE when specifying STBL, 4801:2-93
Use DTBL when specifying SFILE, 4801:2-93
Use IMT Bus Instead of MBUS (Eagle 23.0), 4318:5-160
Use REPT-STAT-MPS when LNP ELAP Configuration is ON, 4801:2-829
Use SFILE when specifying DTBL, 4801:2-93
Use STBL when specifying DFILE, 4801:2-94
Use STP and FTP UserNames, Passwords for all STPs Box, 0008:2-17, 0008:2-18, 0008:2-36, 0008:2-37, 0008:2-38
user
adding, 0002:4-21
removing, 0002:4-33
user administration, 2712:2-19
User Administration menu, 4307:3-82
user console

Embedded OAP (24.0), 4318:2-137
User currently logged on, 4801:2-105
User Default Groups, 4307:3-111
user environment variables, 0008:2-6
User Guide Conventions, 0008:2-1
USER ID, 4802:1-18
User ID, 4802:1-18
User IDs
already in use at login, 4800:4-22
not accepted at login, 4800:4-20
rules for administering, 4800:4-17
user information
changing, 0002:4-35
user interface, ELAP
error message format, 4307:5-13
Escape key to exit operations, 4307:5-12
file system backups, 4593:6-17
Halt MPS menu item, 4593:6-115
list of error messages, 4307:3-114, 4593:6-23
user interface, EPAP
Backup PDB menu item, 4593:6-18
Halt MPS menu item, 4593:6-115
User Interfaces, 4307:3-2
User Login, 4307:5-14
User login failure - Error code 633, 0008:2-104
User Logins, 4307:3-111
User Names See User IDs, 4800:4-16
user session, log into system for, 4800:4-19
User's Manual, 4625:1-12, 4626:1-15
user-defined LNP services, 4802:3-30
UserID already logged on (or is logging on) another terminal, 4801:2-327
UserID has become obsolete and cannot be used, 4801:2-327
UserID has been revoked, 4801:2-327
user-initiated
aborting, 4751:4-11
User-Initiated Keyboard Locking (Eagle 22.0), 4318:5-160
user-initiated resynchronization, 4751:4-2
log file, 4751:4-18, 4751:4-19
managing, 4751:4-6
overview, 4751:2-4, 4751:2-7
procedure, 4751:4-6
timeline, 4751:4-4
Users menu, 4307:3-83
Using the DPC/SSN Parameters and GTA Range in Displaying Global Title Translations (Eagle 22.0), 4318:5-163
Using the FTRA application, 0008:2-4
UTC, 2712:2-17
utility GPL
change trial to approved version, 0002:3-108

V

V.35, 4601:5-12, 4625:3-68
V.35 4-link monitor configuration window, 4625:B-7
V.35 applique, 4625:3-66, 4625:3-67
V.35 monitor applique, 4625:B-7
Vacuum cleaner, 4601:3-20
vacuum cleaner, 2969:4-3
Validate button
    Update Tables, 0008:2-78, 0008:2-82
    Update Tables window, 0008:2-77
Validating command files, 0008:2-2
validation
    DSM daughterboard continual memory, 4307:4-7
Value <data> for <parm> parameter is not valid (C<col>), 4801:2-544
Value <data> for <parm> parameter not consistent with a previous parameter (C<col>), 4801:2-543
Value <data> not supported for <parm> parameter in this implementation (C<col>), 4801:2-543
Value <data> out of range for <parm> parameter (C<col>), 4801:2-546
Variable
    environment
        FTRA_HOME, 0008:2-1, 0008:2-6, 0008:2-7, 0008:2-8
        JRE_HOME, 0008:2-1, 0008:2-6, 0008:2-7, 0008:2-8
    system environment, 0008:2-6, 0008:2-8
    user environment, 0008:2-6, 0008:2-7, 0008:2-8
Variable Length GTT (Eagle 26.1), 4318:5-163
    alarms, 4318:5-166
    changed commands, 4318:5-165
    hardware requirements, 4318:5-166
    upgrade consideration, 4318:5-165
Variable-Length Global Title Translation, 0006:1-2, 0006:2-3, 0006:2-6, 0006:2-7, 0006:2-12, 0006:2-13, 0006:2-14, 0006:2-15, 0006:2-34, 0006:2-42, 0006:2-44, 0006:2-48, 0006:2-49, 0006:3-4, 0006:3-5, 0006:3-6, 0006:3-7, 0006:3-21, 0006:3-22, 0006:3-32, 0006:3-33, 0006:3-45, 0006:3-46, 0006:3-53, 0006:3-55, 0006:3-62, 0006:4-4, 0006:4-5, 0006:4-7, 0006:4-8, 0006:4-14, 0006:4-23, 0006:4-27, 0006:4-37, 0006:4-49, 0006:4-53, 0006:4-54, 0006:4-62, 0006:A-39
VCI values 0...4 and 6...31 are reserved, 4801:2-555
VCXO, 4625:3-143
Verbose Output, 2712:3-14, 4593:6-15
verification, 4601:4-21
verification, DSM system hardware, 4307:4-6
Verifying
    RTDB Status, 0007:2-111
    RTDB Status at the Eagle Terminal, 0007:2-111
    RTDB Status at the ELAP User Interface, 0007:2-112
verifying
    DSM card status, 4751:8-5
verifying database, 0002:2-10
verifying modems, 2712:3-7
Version, 4593:6-7
Version level, 0008:2-102
Version not supported, 4801:2-837
Version parameter not supported for either SUA or M2PA, 4801:2-837
vfy-lnp-refnum, 4800:8-55

VGTT - Variable-Length Global Title Translation, 0006:1-2, 0006:2-3, 0006:2-6, 0006:2-7, 0006:2-12, 0006:2-13, 0006:2-14, 0006:2-15, 0006:2-34, 0006:2-42, 0006:2-44, 0006:2-48, 0006:2-49, 0006:3-4, 0006:3-5, 0006:3-6, 0006:3-7, 0006:3-21, 0006:3-22, 0006:3-32, 0006:3-33, 0006:3-45, 0006:3-46, 0006:3-53, 0006:3-55, 0006:3-62, 0006:4-4, 0006:4-5, 0006:4-7, 0006:4-8, 0006:4-14, 0006:4-23, 0006:4-27, 0006:4-37, 0006:4-49, 0006:4-53, 0006:4-54, 0006:4-62, 0006:A-39
VGTT cannot be On if any SCCP card has a 486 processor, 4801:2-760
view
hub front, 4625:4-47
hub rear, 4625:4-48
MPS frame front, 4625:4-13
MPS frame rear, 4625:4-13
MPS Server front, 4625:4-25
MPS Server front detail, 4625:4-22, 4625:4-29
MPS Server rear, 4625:4-26
MPS Server rear detail, 4593:6-123, 4625:4-22, 4625:4-30
Netra t 1400 front, 4625:4-25
Netra t 1400 rear, 4625:4-26
View Allowed menu, 4307:3-31
View Any File menu, 4307:3-65
View EMS Routing, 0007:2-96
View Enabled, 4307:3-28
View Enabled menu, 4307:3-24, 4307:3-26
View LNP QTY, 4307:3-36
view logs files, 4307:3-62
View Logs menu, 4307:3-61
View menu
FTP-Based Table Retrieve Application, 0008:2-69, 0008:2-93, 0008:2-98
View RTDB Status, 4307:3-35
View Simplex Mode, 4307:3-20
View Status screen, 4307:3-17
View System Log, 4307:3-76
View Window viewer, 4307:3-62
Viewing an EMS Configuration Component, 0007:2-89
Viewing log files, 0008:2-2
VIOL, 4307:3-7
Visual Alarms, 4593:3-4
voltages, checking, 2712:3-13
VPN Systems, 4625:4-17
VSCCP cards have insufficient extended memory, 4801:2-603
VT320 terminal type, 0002:4-55
VT320 terminals, 4800:4-3
key sequences, 4800:4-10
KSR function on, 4800:4-5
VT-520, 4593:5-22

W

Waiting for duplex mode in provisioning subsystem, 4801:2-79
WAN connection, 4318:3-123
warm restart
TSM Warm Restart and Incremental Loading (EAGLE 26.0), 4318:5-132
Warm Restart capable Feature must be enabled, 4801:2-254

warm restart, DSM, 4307:2-18
Warning Message When LIMs Added with Insufficient TSMs (Eagle 25.0), 4318:5-168
web-based user interface, 4307:3-2
Weekly Procedures, 4593:2-20
weight, 2969:3-9
Weighted SCP Load Balancing (Eagle 27.2), 4318:5-169
    alarms, 4318:5-170
    enhanced commands, 4318:5-170
    hardware requirements, 4318:5-170
    limitations, 4318:5-171
    upgrade considerations, 4318:5-170
When REXMIT=BSD is specified, an RTT cannot be assigned, 4801:2-342
When REXMIT=FIXED or MOD is specified, an RTT must be assigned, 4801:2-343
When RGTA=YES exists, the LRN cannot be removed, 4801:2-510
When RMV=ALLTT is specified, a TT must be assigned, 4801:2-515
When RMV=LRN, LRN must be assigned to the TN, 4801:2-508
When type=DEFAULT, other allowed parameters are SNAME/LOC, 4801:2-777
When type=full, DPC and SI must be specified, 4801:2-788
When type=partial or default, specify NSNAME or attributes, 4801:2-775
When type=partial or default, SPLIT/ RESIZE are not supported, 4801:2-776
Wild card entries are not allowed in this command, 4801:2-197
Wildcard SSN already exists, 4801:2-846
Wildcard / Asterisk combination invalid for direction, 4801:2-832
Wildcard / Asterisk invalid for direction of BOTH, 4801:2-832
Wildcard / Asterisk required for TTI, NP, NAI if DIR is ITOA, 4801:2-833
Window
    About FTRA, 0008:2-11, 0008:2-102
    Command Complete Connectivity Test, 0008:2-32
    Command File Editor, 0008:2-83, 0008:2-85, 0008:2-86, 0008:2-87
        File Menu, 0008:2-87
        Invalid Command, 0008:2-86
    Command File Editor window
        File Menu, 0008:2-87
    Commands Menu, 0008:2-56, 0008:2-63, 0008:2-78
    Connectivity Test Log, 0008:2-31, 0008:2-32, 0008:2-33, 0008:2-34, 0008:2-35, 0008:2-36, 0008:2-44, 0008:2-47, 0008:2-48
        closing, 0008:2-32, 0008:2-36
        File Menu, 0008:2-32, 0008:2-33
        Print, 0008:2-34
        Save, 0008:2-35
        Saved file confirmation, 0008:2-35, 0008:2-36
        with errors, 0008:2-32
        with no errors, 0008:2-31
    Exit, 0008:2-12, 0008:2-13
    Exit Confirmation, 0008:2-12
    FTP Server Configuration Menu, 0008:2-21, 0008:2-49, 0008:2-50, 0008:2-103, 0008:2-106, 0008:2-119, 0008:2-120
    FTP Server Data Set, 0008:2-53
    FTP-Based Table Retrieve Application, 0008:2-11, 0008:2-12, 0008:2-18, 0008:2-31, 0008:2-36, 0008:2-39, 0008:2-58, 0008:2-69, 0008:2-70, 0008:2-71, 0008:2-78, 0008:2-93, 0008:2-94, 0008:2-95, 0008:2-98, 0008:2-99, 0008:2-100, 0008:2-102
    GTT Warning, 0008:2-54

Initializing, 0008:2-11
Invalid FTP Password warning, 0008:2-22
Invalid FTP User Name warning, 0008:2-21
Invalid IP Address warning, 0008:2-20, 0008:2-51
Invalid STP Name Error Message, 0008:2-18
Invalid STP Name warning, 0008:2-18
Invalid STP Password warning, 0008:2-21
Invalid STP User Name warning, 0008:2-20
Modify Warning, 0008:2-39
Print
    Retrieve Tables Log, 0008:2-71
    Update Tables Log, 0008:2-95
Retrieve Tables, 0008:2-4, 0008:2-54, 0008:2-55, 0008:2-58, 0008:2-73
    Add button, 0008:2-56, 0008:2-60
    Close button, 0008:2-56
    Command Complete, 0008:2-54, 0008:2-65, 0008:2-66
    Command List Field, 0008:2-56
    description, 0008:2-56
    GTT Warning, 0008:2-54
    Load button, 0008:2-56, 0008:2-64, 0008:2-73
    Remove button, 0008:2-56, 0008:2-62
    Reset button, 0008:2-56, 0008:2-63
    Retrieve button, 0008:2-54, 0008:2-56, 0008:2-64, 0008:2-65
    Retrieve from Local Database button, 0008:2-54, 0008:2-56, 0008:2-64
    Retrieve from STP button, 0008:2-54, 0008:2-56, 0008:2-65
    Selected Commands Field, 0008:2-56
    Store button, 0008:2-56, 0008:2-63, 0008:2-73
Retrieve Tables Log, 0008:2-65, 0008:2-66, 0008:2-67, 0008:2-68, 0008:2-69, 0008:2-70, 0008:2-71, 0008:2-72
    closing, 0008:2-68, 0008:2-72
    File Menu, 0008:2-68, 0008:2-69
    Print, 0008:2-70, 0008:2-71
    Processing Retrieve Request, 0008:2-65
    Release Not Compatible Error, 0008:2-57
    Save, 0008:2-71, 0008:2-72
    Saved file confirmation, 0008:2-72
    with Errors, 0008:2-68
    without Errors, 0008:2-67
Save
    Retrieve Tables window, 0008:2-72
Select
    File Name: Field, 0008:2-80
    Files of type: Field, 0008:2-80
    Look in: Field, 0008:2-80
    Update Tables, 0008:2-77, 0008:2-78, 0008:2-79, 0008:2-80
Select Starting Directory, 0008:2-50, 0008:2-51, 0008:2-52
    File Name: Field, 0008:2-52
    Files of type: Field, 0008:2-52
    Look in: Field, 0008:2-52
Select, description, 0008:2-80
STP Added, 0008:2-22
STP Connection Configuration Menu, 0008:2-14, 0008:2-15, 0008:2-16, 0008:2-18, 0008:2-23, 0008:2-

27, 0008:2-31, 0008:2-36, 0008:2-39, 0008:2-40, 0008:2-41, 0008:2-104, 0008:2-120, 0008:2-121
FTRA 1.0, 0008:2-14
FTRA 2.0, 0008:2-49
FTRA 2.0 or greater, 0008:2-14, 0008:2-15
STP Data Deleted, 0008:2-40
STP Data Modified, 0008:2-37, 0008:2-39
STP Selection Change, 0008:2-16, 0008:2-41, 0008:2-42
System Log, 0008:2-97, 0008:2-98, 0008:2-99, 0008:2-100, 0008:2-101
closing, 0008:2-97, 0008:2-101
File Menu, 0008:2-97, 0008:2-98
Print, 0008:2-99
Print window
Cancel button, 0008:2-99
Save, 0008:2-100, 0008:2-101
Saved file confirmation, 0008:2-101
Update Tables, 0008:2-4, 0008:2-77, 0008:2-78, 0008:2-79, 0008:2-80, 0008:2-81, 0008:2-86, 0008:2-87, 0008:2-90, 0008:2-91, 0008:2-92
Browse button, 0008:2-78, 0008:2-79
Close button, 0008:2-78
Command Complete, 0008:2-83, 0008:2-84, 0008:2-87
Command File field, 0008:2-79, 0008:2-80, 0008:2-82
Command File Selected, 0008:2-79
Command List Field, 0008:2-78
description, 0008:2-78
Select, description, 0008:2-80
Stop on error box, 0008:2-78, 0008:2-81, 0008:2-90, 0008:2-91, 0008:2-92
Update Validation Complete, 0008:2-83
Validate button, 0008:2-77, 0008:2-78, 0008:2-82
Update Tables Log, 0008:2-82, 0008:2-88, 0008:2-92, 0008:2-93, 0008:2-94, 0008:2-95, 0008:2-96
closing, 0008:2-92, 0008:2-96
Commit Command Completed, 0008:2-88
File Menu, 0008:2-92, 0008:2-93
Print, 0008:2-94
Processing Retrieve Request, 0008:2-82
Save, 0008:2-95, 0008:2-96
Saved file confirmation, 0008:2-96
Update Validation Complete, 0008:2-77, 0008:2-82, 0008:2-83, 0008:2-84, 0008:2-85, 0008:2-86
Commit button, 0008:2-83, 0008:2-84
description, 0008:2-83
Edit button, 0008:2-83, 0008:2-84, 0008:2-85, 0008:2-86
Stop button, 0008:2-83
with errors, 0008:2-84
without errors, 0008:2-84
Windows 2000 operating system, 0008:2-6
Windows 98 operating system, 0008:2-7
Windows Explorer, 0008:2-5
Windows NT operating system, 0008:2-6
Windows Task Scheduler, 0008:2-73, 0008:2-75
Windows Workstation Requirements, 0008:2-2
Wireless number portability - WNP, 4802:3-30
Wireless Query Redirect - WQREDRCT, 4802:3-166
Wireless short message service center - WSMSC, 4802:3-30

Wireless Short Message Service Center 10 Digits - WSMSC10DIG, 4802:3-167
WNP - Wireless number portability, 4802:3-30
WNP feature must be ON, 4801:2-642
work area section, 4307:3-2
workspace section, 4307:3-10
WQREDRCT - Wireless Query Redirect, 4802:3-166
Wrist Strap Test, 4593:2-36
write enabling removable cartridge, 0002:2-7
write protecting removable cartridge, 0002:2-6
WSMSC - Wireless short message service center, 4802:3-30
WSMSC feature must be Activated, 4801:2-633
WSMSC LNP service, 0007:2-157
WSMSC10DIG - Wireless Short Message Service Center 10 Digits, 4802:3-167
WSMSC10DIG LNP option, 0007:2-157

X

X.25
    Connectivity, 0004:2-3
X.25 address already exists in X.25 destination table, 4801:2-285
X.25 address cannot be referenced by route, 4801:2-285
X.25 address does not exist in X.25 destination table, 4801:2-286
X.25 Address must contain at least four digits, 4801:2-282
X.25 connection control, 0004:2-7
    X.25/SS7 Gateway Feature (Eagle 20.0), 4318:5-177
X.25 Destination assigned to non-X.25 linkset, 4801:2-255
X.25 destination table is full, 4801:2-286
X.25 Gateway Destinations, 0004:2-9
X.25 Gateway feature, 0004:1-2
X.25 gateway routing
    X.25/SS7 Gateway Feature (Eagle 20.0), 4318:5-175
X.25 LIM replacement, 4593:A-30
X.25 LIMs, 0004:2-9
X.25 linksets, 0004:2-9
X.25 message conversion
    SS7 to X.25, 4593:B-4
    X.25 to SS7, 4593:B-2
X.25 mode parameter requires SEAS feature, 4801:2-664
X.25 packet size parameter requires SEAS feature, 4801:2-663
X.25 route table is full, 4801:2-295
X.25 Routes, 0004:2-9
X.25 Signaling Link Parameters, 0004:2-9
X.25 signaling links, 0004:2-9
X.25/SS7 Gateway Feature (Eagle 20.0), 4318:5-172
    Address Mapping, 4318:5-175
    Connection Determination, 4318:5-176
    Logical Channel to Network Management Mapping, 4318:5-178
    Message Conversion, 4318:5-174
    same link management, 4318:5-178
    X.25 Connection Control, 4318:5-177
    X.25 Gateway Routing, 4318:5-175
X.25/SS7 IS41 Rev. A Gateway

Overview, 0004:2-2
X.25/SS7 Message Conversion, 4593:B-1, 4593:D-1, 4593:E-1, 4593:F-1
X25 logical channels available, 4593:3-241
X25 no logical channels available, 4593:3-242
X252000, 0004:2-32
X25G, 0004:2-32
X25G Feature must be ON before X252000 can be ON, 4801:2-726
xaddr, 0004:2-32
XGTT requires at least a 586 processor for SCCP GPLs, 4801:2-472
XGTT requires both OAMs running on GPSMII cards, 4801:2-472
XGTT Table Expansion, 0006:2-43, 0006:2-47, 0006:2-48, 0006:2-49, 0006:3-27, 0006:4-32, 0006:4-33, 0006:A-17, 0006:A-18, 0006:A-19, 0006:A-20, 0006:A-21, 0006:A-23, 0006:A-24, 0006:A-25, 0006:A-26, 0006:A-39
XGTT Table Expansion Feature
Enabling, 0006:A-17
XGTT with 1 million entries requires DSM cards for SCCP GPLs, 4801:2-473
XLAT, 4802:1-18, 4802:3-42, 4802:3-43, 4802:3-44, 4802:3-81, 4802:3-82, 4802:3-85, 4802:3-87, 4802:3-88, 4802:3-91, 4802:3-92, 4802:3-96, 4802:3-97, 4802:3-98, 4802:3-102, 4802:3-104, 4802:3-107, 4802:3-111, 4802:3-116, 4802:3-118, 4802:3-119, 4802:3-122, 4802:3-126, 4802:3-127, 4802:3-130, 4802:3-132, 4802:3-134, 4802:3-137, 4802:3-139, 4802:3-141, 4802:3-143, 4802:3-145, 4802:3-151, 4802:3-154, 4802:3-156, 4802:3-157, 4802:3-159, 4802:3-161, 4802:3-177, 4802:3-179, 4802:3-180
XLAT must be DPCSSN and RI must be SSN if PC is the True PC, 4801:2-642
X-LIST DPC is not allowed, 4801:2-52
X-LIST occupancy below threshold, 4593:3-416
X-LIST occupancy threshold exceeded, 4593:3-414
X-LIST space full condition abated, 4593:3-434
X-LIST space full-entry(s) discarded, 4593:3-432
XMAP requires at least a 586 processor for SCCP GPLs, 4801:2-473
XMAP requires both OAMs running on GPSMII cards, 4801:2-474
XMAP Table Expansion, 0006:2-43, 0006:2-46, 0006:2-48, 0006:2-49, 0006:2-85, 0006:2-121, 0006:A-27, 0006:A-28, 0006:A-29, 0006:A-30, 0006:A-31, 0006:A-33, 0006:A-34, 0006:A-35, 0006:A-39
XMAP Table Expansion Feature
Enabling, 0006:A-27

Y

Year 2000 Compliance (Eagle 23.1)
OAP Year 2000 Compliance, 4318:5-188