

<b>Severity Level</b>	<b>Caution</b>	<b>Bulletin Number</b>	<b>F10943-01</b>
<b>Issue Date</b>	10/5/2018	<b>Expires</b>	N/A
<b>Title</b>	Configuring the SLIC Card as an E1T1 Link Card		
<b>Product</b>	EAGLE	<b>Release</b>	46.5
<b>Priority</b>	Medium	<b>Related Bugs</b>	N/A
<b>Impacts Compatibility</b>	NO	<b>Impacted Product Line(s):</b>	EAGLE
<b>Markets</b>	ALL	<b>Part No. Affected</b>	7094646 7352578
<b>Author and Formal Approvers</b>			
<b>Author</b>	G. Brookins	10/4/2018	<b>Customer Documentation</b> B. Chappell 10/4/2018
<b>Problem Description</b>			
<p>The SLIC card is a hot swappable replacement for HC-MIM and E5-E1T1 cards. The same configurations for HC-MIM and E5-E1T1 cards can be used for configuring a SLIC card as an E1T1 Link Card.</p> <p><b>Note:</b> Channel bridging is not supported on SLIC cards. Channel bridging for the location (if any) should be removed by the operator before hot swapping an HC-MIM with a SLIC card.</p> <p>See <i>Release Notes</i> for full information on supported hardware.</p>			
<b>Impact</b>			
Missing information in customer documentation for configuring SLIC as an E1T1 Link Card may cause some confusion for customers.			
<b>Needed Actions</b>			
<p>Customers should follow same HCMIM/E5-E1T1 configurations (except for channel bridging) for SLIC cards in R46.5. Customers should store this bulletin with their associated EAGLE documentation location for reference.</p>			
<p>This notice is provided information to Oracle customers about issues identified with our systems. If you have any questions about this notice, call the My Oracle Support main number at 1-800-223-1711 (toll-free in the US), or call the Oracle Support hotline for your local country from the list at <a href="http://www.oracle.com/us/support/contact/index.html">http://www.oracle.com/us/support/contact/index.html</a>.</p>			