

Severity Level	Info	Bulletin Number	F12588-01
Issue Date	11/27/2018	Expires	EAGLE 46.7 Documentation Set
Title	EAGLE 46.6 Database Administration – GTT User’s Guide Table 2-35. SCCP Throughput Capacity		
Product	EAGLE	Release	46.6
Priority	FYI	Related Bugs	28973222
Impacts Compatibility	No	Impacted Product Line(s):	N/A
Author	J. Carlino	Part No. Affected	E93315-03
Markets	All		
Approved By/Date	Bryan Chappell 11/27/2018		

Problem Description

Replace current Table 2-35 in EAGLE 46.6 Database Administration – GTT User’s Guide with this one:

SCCP Throughput Capacity Feature Activated	E5-SM8G-B TPS	SLIC TPS
SCCP Throughput Capacity 13.6K TPS (P/N: 893019104)	13600	13600 TPS if all below conditions are true: <ol style="list-style-type: none"> EGMS feature is not activated EPAP240M option in STPOPTS is OFF or SM card is provisioned as data=DN/IMSI/ELAP/GTT No UAM 548 or 549 present in the system
SCCP Throughput Capacity 10K TPS (P/N: 893019103)	10000	10000 TPS if any of the below conditions are true: <ol style="list-style-type: none"> EGMS feature is activated EPAP240M option in STPOPTS is ON and SM card is not provisioned as data=DN/IMSI/ELAP/GTT UAM 548 or 549 is present in the system
SCCP Throughput Capacity 6.8K TPS (P/N: 893019102)	6800	6800
SCCP Throughput Capacity 5K TPS (P/N: 893019101)	5000	5000

Impact

None

Needed Actions

No action needed.

Customers should store this bulletin with their associated EAGLE documentation location for reference.

This notice is provided information to Oracle customers about issues identified with our systems. If you have any questions about this notice, call the My Oracle Support main number at 1-800-223-1711 (toll-free in the US), or call the Oracle Support hotline for your local country from the list at <http://www.oracle.com/us/support/contact/index.html>.