

Policy Management

Wireless Release 10.0.2

Maintenance Release Notice

910-6905-001 Revision A

October 2013



Tekelec

Policy Server - Policy Charging and Rules Function (PCRF) Copyright, Notice, Trademarks, and Patents

© 2013 Tekelec

All Rights Reserved

Printed in U.S.A.

Notice

Information in this documentation is subject to change without notice. Unauthorized use, copying, or translation of this documentation can result in civil or criminal penalties.

Any export of Tekelec products is subject to the export controls of the United States and the other countries where Tekelec has operations.

No part of this documentation may be reproduced, translated, or transmitted in any form or by any means, electronic or mechanical, including photocopying or recording, for any purpose without the express written permission of an authorized representative of Tekelec.

Other product names used herein are for identification purposes only, and may be trademarks of their respective companies.

RoHS 5/6 - As of July 1, 2006, all products that comprise new installations shipped to European Union member countries will comply with the EU Directive 2002/95/EC "RoHS" (Restriction of Hazardous Substances). The exemption for lead-based solder described in the Annex will be exercised. RoHS 5/6 compliant components will have unique part numbers as reflected in the associated hardware and installation manuals.

WEEE - All products shipped to European Union member countries comply with the EU Directive 2002/96/EC, Waste Electronic and Electrical Equipment. All components that are WEEE compliant will be appropriately marked. For more information regarding Tekelec's WEEE program, contact your sales representative.

Trademarks

TEKELEC, the Tekelec Logo, EAGLE, G-Flex, G-Port, TEKSERVER, and CAMIANT are registered trademarks of Tekelec. EAGLE 5, EAGLE 5 ISS, TEKELEC LTE DIAMETER SIGNALING INDEX, THINKWORKS, and Subscriber Data Server (SDS) are trademarks of Tekelec. All other trademarks are the property of their respective owners.

Patents

This product may be covered by one or more of the following U.S. and foreign patents:

U.S. Patent Numbers:

Legal Information

7,738,440; 7,788,357; 7,805,515; 8,254,551; US 7961623; US 8073444;

Foreign Patent Numbers:

AU 2004247256; AU 2004247251; AU 2005208846; AU 2005208847; AU 2005286941; EP 1631917; EP 1997276; EP 2049909; JP 4395662; JP 4582346; JP 4652345; JP 4843610; ZL 200680049126.1;

Maintenance Release Notice

Policy Management 10.0.2

This release notice lists the PRs that have been fixed, and those that are known to exist, in Policy Management 10.0.2, a Maintenance Release for 10.0.0.
This release notice also describes how to obtain Tekelec customer documentation.

Contents

PR Severity Definitions.....	2
Customer Fixed PRs.....	2
Customer Known PRs.....	3
Upgrade Paths.....	4
Accessing Customer Support Documentation	5

PR Severity Definitions

The following sections refer to PR severity levels. Definitions of these levels can be found in the following publication:

TL 9000 Quality Management System Measurement Handbook

Customer Fixed PRs

Table RN-1 on page RN-2, "Policy Management 10.0.2 Customer Fixed PRs Report Table," lists fixed severity 1, 2, 3 and enhancements for Policy Management Maintenance Release 10.0.2.

Table RN-1. Policy Management 10.0.1 Customer Fixed PRs Report Table

PR#	SEVERITY	DESCRIPTION
232349	Minor	WLAN Handoff caching issue
231446	Minor	One way Video Issue
231446	Minor	One way audio during PRBT setup
231801	Minor	MPE failover resulting from X2 thread hang in the rc: Thread X2Adaptor0 is dead

Customer Known PRs

Table RN-2. Policy Management 10.0.2 Customer Known PRs Table

PR#	CSR#	SEVERITY	TITLE	CUSTOMER IMPACT
222749	N/A	Minor	MRA Failover on G8 perf demo system caused MPE's to go TOO BUSY for short period of time	After an MRA failover by physically removing the active MRA in a cluster, when the standby blade recovers, the resync of the Bindings can take up to a minute. During this time the some MPE's will report "Too Busy" for a very brief period of time (less than a second).
230268	1012856	Minor	Resource allocation notification enabled for all flows	When applying traffic profiles to Rx flows in Policy rules, it is possible to enable resource allocation notification on the traffic profile. If there are multiple flows in a Rx request(for example, audio and video), and resource allocation notification is only enabled on one of the flow(for example the audio flow) by application of a traffic profile to that flow, the resulting Gx RAR enables the resource allocation notification on all the charging rules. It should enable resource allocation notification only on rule related to the flow on which the traffic profile is applied.

Upgrade Paths

10.02 supports the following upgrade paths for C-Class blades and Rack Mount servers

	From	To
MPE-LI	10.0.1_5.1.0	10.0.2_4.1.0

NOTE:

- Any upgrade other than listed above is not recommended or supported.
- 10.0.2 is supported as a new/fresh installation.
- It is recommended to upgrade in the following order
 - MPE-LI

Platform baseline versions included

TPD version: 5.1.1-73.5.1

COMCOL version: 6.0p224.8237

Part Numbers:

Policy 10.0.2

MPE-LI: 895-1597-203 DVD

895-1597-303 USB

895-1597-403 ESWD

Accessing Customer Support Documentation

1. Go to the [Tekelec Customer Support](#) site.
2. **NOTE: If you have not registered for this new site, click the Register Here link. Have your customer number available. The response time for registration requests is 24 to 48 hours.**
3. Enter your assigned username and chosen password, then click **Login**.
4. **NOTE: After 20 minutes of inactivity, you will be logged off, and you must repeat this step to regain access.**
5. Click the Product Support tab.
6. Use the Search field to locate a document by its part number, release number, document name, or document type. The Search field accepts both full and partial entries.
7. Click a subject folder to browse through a list of related files.
8. To download a file to your location, right-click the file name and select Save Target As.
9. **NOTE: Customers may print a reasonable number of each manual for their own use.**