

## **Tekelec 1100 AS Power Requirements**

Each T1100 AS server requires redundant power feeds with 30 Amp breakers; the power feed is 1000W and 24 Amps at 42V.

For additional information for a frame, click on it:

[DC ELAP](#)

[DC LSMS](#)

[AC LSMS](#)

[Sentinel](#)

[DC PMF](#)

[AC PMF](#)

[DC ENUM](#)